



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

DOT Auto Safety Hotline  
**Vehicle Owner's Questionnaire**  
To Report Vehicle Safety Defects  
1-888-DASH-2-DOT  
(1-888-327-4236)  
INTERNET [www.nhtsa.dot.gov/hotline](http://www.nhtsa.dot.gov/hotline)

FOR AGENCY USE ONLY 100161

Date Received

Repository

2003 JAN 16 PM 1:21

Reference No.  
10047836

OWNER INFORMATION (Type or Print)

Name: [Redacted]  
Address: [Redacted]  
City: TAMPA State: FL Zip Code: [Redacted]

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.  
Signature of Owner: \_\_\_\_\_ Date: 1/1

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: KM-JF25F5- [Redacted]  
Make: HYUNDAI Model: ELANTRA Model Year: 1999  
Date Purchased: July, 1999 Dealer's Name and Telephone Number: Mit/Hyundai on West Hillsborough  
Original Owner:  Dealer's City: Tampa State: FL Zip Code: 33615 Engine: No. Cylinders: 4 Fuel Type: Unleaded  
Transmission Type: AUTOMATIC  Antilock Brakes  Cruise Control Powertrain: \_\_\_\_\_  
Vehicle Component Code: 071100 FUEL SYSTEM, GASOLINE-STORAGE-TANK ASSEMBLY  
Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s): 10/2003 to current Failure Mileage: 65000 Failure Speed: Constant

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make: \_\_\_\_\_ Tire Model (Name or Number): \_\_\_\_\_ Tire Size (Example P215/65R15): \_\_\_\_\_  
DOT No. (Example: DOTM19ABC036): \_\_\_\_\_  Original Equipment  Prior Repair Failure Location: \_\_\_\_\_  
Tire Component Code: \_\_\_\_\_ Tire Failure Type: \_\_\_\_\_

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: \_\_\_\_\_ Date Manufactured: \_\_\_\_\_ Model No./Name: \_\_\_\_\_  
Seat Type: \_\_\_\_\_ Installation System: \_\_\_\_\_  
Child Seat Component Code: \_\_\_\_\_ Failed Part: \_\_\_\_\_

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash:  Yes  No Fire:  Yes  No  
Number of Persons Injured: 0 Number of Deaths: 0 Reported to Police: N

Narrative Description of Incident(s), Crash(es), and Injury(ies).  
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure. List parts repaired or replaced (and if old part is available).

WHEN FUELING, THE PUMP SHUTS OFF APPROXIMATELY EVERY FIFTY CENTS OF GASOLINE. AN INDEPENDENT MECHANIC AT A REPAIR SHOP DETERMINED THAT THE FUEL TANK MUST BE REPLACED. PLEASE PROVIDE FURTHER DETAILS. \*PH

Check Engine light came on. Car would not allow me to pump gas normally. Since car was just over 60k miles, I took car to Firestone to evaluate. They found an Article (copy attached) identifying the problem with my car which also notes this issue being commonly known to occur in my type of vehicle. As a result, the car jerks upon acceleration and stalls frequently. I strongly feel that a recall on my vehicle is necessary & justified. (back)

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

I did nothing to cause my car to actup. The issues have been increasing since the onset of the incident of the check engine light coming on triggered. The car is not old, is just outside 100k miles and has already had the windows motors replaced within the past 2 months. Since the manufacturer is aware of this happening with their cars - correcting the problems should be covered at their expense.

by <sup>the</sup> ~~the~~ <sup>check</sup> ~~check~~ <sup>engine</sup> ~~engine~~ <sup>light</sup> ~~light~~ <sup>issue</sup> ~~issue~~.

Note: This is my second Hyundai Elantra and my other one never had this problem, nor any other car I've owned.

Please feel free to contact me if you have any questions or would like to know more.

Three ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department of Transportation

National Highway Traffic Safety Administration

400 Seventh St., S.W. Washington, D.C. 20590

Official Business Penalty for Private Use \$300



NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

**BUSINESS REPLY MAIL**

FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.



U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation, NVS-216  
400 7th Street, SW  
Washington, DC 20590

**VEHICLE  
OWNER'S  
QUESTIONNAIRE**

**DOT AUTO SAFETY HOTLINE**

TO REPORT VEHICLE SAFETY DEFECTS  
COMPLETE THIS FORM  
OR

**DASH2DOT**

and dial toll free at

**1-888-DASH-2-DOT**

1-888-327-4236

DOT Auto Safety Hotline

(DASH) 2 DOT



U.S. Department of Transportation  
National Highway Traffic Safety Administration  
<http://www.safercar.gov>

# GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK

Entire Article  
2000 HYUNDAI Elantra

## ARTICLE BEGINNING

## TECHNICAL SERVICE BULLETIN

### GENERAL DIAGNOSTIC PROCEDURES: HARD-TO-FILL FUEL TANK

Model(s): 1999 Hyundai, All Models  
Group: Fuel System  
Bulletin No.: 99-30-002  
Date: August, 1999

## DESCRIPTION

All 1999 and later Hyundai vehicles incorporate a new emission control system known as On-Board Refueling Vapor Recovery (ORVR). A general schematic of the system is provided in Fig. 1.

Some owners may experience difficulty filling their vehicle with gasoline and a premature shut off condition as a result of the gas pump nozzles installed at their gas stations. The nozzles at these stations are in the process of being retrofitted or replaced by the nozzle manufacturers. In the meantime, owners should follow instructions posted near the gas pump, and/or try filling the vehicle at a different gas station.

If the refueling difficulty continues, verify that the 1/2" vapor path from the fill vent valve on the gas tank to the air filter on the charcoal canister (see schematic below) is completely free and clear. To perform the procedure below, make sure the fuel tank is below 1/4 tank full.

To quickly determine the general location of a possible vapor path restriction:

- 1) Disconnect the hose connected to the canister side of the liquid-vapor separator. See Fig. 1.
- 2) Take the vehicle to a known "good" or major brand gas station.
  - A) If the vehicle readily accepts fuel, the restriction is located between the liquid-vapor separator and the air filter.
  - B) If the vehicle does not easily accept fuel, the restriction is located between the liquid-vapor separator and the fuel tank.

The following components are contained in the ORVR system:

- Vapor hoses
- Liquid-Vapor Separator(s)
- Fuel Fill Vent Valve

*Hyundai  
No recall  
Risk*

*NAC Hyundai Advisor  
888-327-4230  
Rhonda*

*File 793196*

*File Impairment  
Request reimbursement*

## GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK

Entire Article  
2000 HYUNDAI Elantra

- Fuel Cut Valve (anti-spitback)
- Canister Close Valve
- Air Filter
- Charcoal Canister

After the restriction has been isolated to either half of the system, inspect each component to make sure it is free and clear of any restrictions. See Figs. 2 and 3. Verify that no back pressure can be felt anywhere between the fill vent valve and the air filter at the canister.

**NOTE:** 1999 Accents have two (2) liquid-vapor separators: one located on top of the fuel tank, the other located along side the filler neck.

When checking the liquid-vapor separator, blow through one end of the pipe using lung pressure. See Fig. 4. No back pressure should be felt.

Verify that the Fill Vent Valve is open by carefully removing the valve and confirming that the white plastic shut-off plunger moves freely inside its cage. See Fig. 5.

If the fuel cut valve plunger is stuck closed, a hard-to-fill condition may result. Verify that the plunger moves up and down freely allowing fuel to enter the tank, but does not allow fuel to travel up the neck (under pressure). See Fig. 6. The plunger should be "up" (closed) in its free state.

**IMPORTANT:** When working with the Fill Vent Valve and associated plumbing, be sure to replace the hoses into the proper hose clips to prevent fuel from getting trapped/puddled in the vapor hose. Return fuel from the liquid-vapor separator must have a clear path to drain back to the tank.

### FOUR WAY VALVE

See Fig. 7.

**Purpose:** The Four Way Valve provides an additional vapor path to the canister during refueling.

**NOTE:** 1999 Sonatas have a Four Way Valve located between the liquid-vapor separator and fuel tank.

Proper operation of the valve is as follows:

Refer to Fig. 8.

1). Air flows freely in either direction through the 1/2" ports.


# GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK

Entire Article  
2000 HYUNDAI Elantra

- 2) Air flows freely in either direction through the 1/4" ports.
- 3) Air flows from 1/2" port to the 1/4" port when blowing into one of the 1/2" ports while plugging the other 1/2" port.
- 4) Air does not flow from 1/4" port to the 1/2" port when blowing into one of the 1/4" ports while plugging the other 1/4" port.

## WARRANTY INFORMATION


Normal warranty operation codes and times apply.



On-Board Refueling Vapor Recovery (ORVR) Schematic

600024069

Fig. 1: On-Board Refueling Vapor Recovery (ORVR) Schematic




G00024069

Fig. 2: Inner Layer Separation Causing Restriction

**GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK**

Entire Article  
2000 HYUNDAI Elentra



G00024070

Fig. 3: Kinked Hose Causing Restriction





Fig. 4: Checking Liquid-Vapor Separator


# GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK

Entire Article  
2000 HYUNDAI Elantra



G00024072

Fig. 5: Verifying Fill Vent Valve Is Open




Fuel cut valve and close up of shut-off plunger being pushed open.

G00024072

Fig. 6: Shut-Off Plunger Pushed Open

# GENERAL DIAGNOSTIC PROCEDURE: HARD-TO-FILL FUEL TANK


Entire Article  
2000 HYUNDAI Elantra



**4-WAY VALVE**

G00024074

Fig. 7: Four Way Valve



G00024075

Fig. 8: Proper Operation Of Four Way Valve

**END OF ARTICLE**

THE ATTACHMENTS TO THIS  
DOCUMENT HAVE BEEN REMOVED  
TO PROTECT UNWARRANTED  
INVASION OF PERSONAL PRIVACY  
PURSUANT TO EXEMPTION 6 OF  
THE FREEDOM OF INFORMATION  
ACT (FOIA), 5 U.S.C. 552(b)(6).