



DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
 TO REPORT VEHICLE SAFETY DEFECTS
 1-888-DASH-2-DOT
 (1-888-327-4236)
 INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

Date Received: **2004 JUL 30 PM 6:20**
 10083911
 Reference No. _____
 Od_or _____
 rt_dt _____
 od_rt _____
 up_ltr _____

OWNER INFORMATION (Type or Print)

Name: _____
 Street No. _____ Apt. No. _____
 City: **HOUSTON** State: **TX** Zip Code: _____
 Daytime Telephone Number: _____

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
 In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner: _____ Date: / /

PRODUCT INFORMATION

Vehicle Identification No. (VIN) (17 Digits) *(Located at bottom of windshield on driver's side)*: **1G8ZG5289S1Z**
 Make: **9 SATURN** Model: **SL1** Year: **1995**

Purchased Date: **Dec 1994** Dealer's Name: **SATURN 45 NORTH HOUSTON** Engine Size (CID/OCL): _____
 Dealer's City: _____ State: **HOUSTON** Zip Code: _____ No. Cylinders: **4**
 New Used Turbo Diesel Gas Fuel Injection

Manufacture Date (on driver's door or pillar): **12/94**
 Transmission Type: Manual Automatic
 Restraint System: Driver's Side Air Bag Motor Belt Passenger's Side Air Bag 2-Point Belt 3-Point Belt
 Cruise Control: Yes No
 Drivetrain: Front Rear 4-Wheel
 Vehicle Type: Car Sport Utility Truck Minivan Motorcycle Other
 Body Style: 2-Door 4-Door Station Wagon Pick Up Truck Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Part Name(s): **IGNITION SWITCH** } *Connects to Key & Lock in Steering Column*
 Location: Left Right Front Rear
 Failed Part(s): Original Replacement
 Handicap Adaptive Equip: Yes No

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Brand: _____ Tire Name: _____
 Complete Tire Size: _____ DOT No.: _____
 No. of Failures: _____ Date(s) of Failure(s): _____
 Mileage at Failure(s): _____ Vehicle Speed at Failure(s): _____
 Failed Part(s) Available? Yes No
 NHTSA Previously Contacted? Yes No

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies). Attach photos if available.)

Crash: Yes No
 Fire (Smoke): Yes No
 Number of Persons Injured: **0**
 Number of Fatalities: **0**
 Reported to Manufacturer: Yes No *Attempted - Not Friendly*

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies):

Driver: _____ PASSENGERS: **Front**
START CAR - SMOKE FROM DRIVERS SIDE DASH immediately after starting - Turn OFF.
CALL Dealer - they wanted to tow car & replace wire harness for about \$1000.
Removed PAGES from under Steering Column - CABLE HARNES from ignition switch module (connects to Key/Lock Assembly) is burned/burnt. The black wire has no insulation. The insulation burned off - all the way to the grounding point at the Fire wall. The Black wire is not connected to the gas chassis - it also burned off.

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to 49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

- IGNITION SWITCH FAILED + Shorted BATTERY to BLACK WIRE (CHASSIS)
- IGNITION SWITCH - MANUFACTURED BY LUCAS # 21022170 COE 522073.
I shorted
- I checked the SWITCH with a meter + the switch has failed - shorting inside - Referenced HAYNES SCHEMATICS AS A REFERENCE.
- Replace Ignition Switch (Also Added Fuses for unfused wires)
Add - vehicle works after replacing switch + repairing harness
- ALL POWER FOR VEHICLE IS SENT THROUGH THE IGNITION SWITCH - WHEN SWITCH FAILS ALL UNFUSED LINES ARE VULNERABLE.
- I have SWITCH if needed.
- PICTURES AT

(Lower Case)

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department of Transportation

National Highway Traffic Safety Administration

400 Seventh St., S.W. Washington, D.C. 20590

Official Business Penalty for Private Use \$300



NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES



BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NSA-10.01
400 7th Street, SW
Washington, DC 20590

Complete and return or place in your car manual for future use



VEHICLE OWNER'S QUESTIONNAIRE (VOQ)

DOT AUTO SAFETY HOTLINE

TO REPORT VEHICLE SAFETY DEFECTS
COMPLETE THIS FORM
OR

DASH 2 DOT

and dial toll free at

1-888-DASH-2-DOT

1-888-327-4236

DOT Auto Safety Hotline
(DASH) 2 DOT



U.S. Department of Transportation
National Highway Traffic Safety Administration

www.nhtsa.dot.gov/hotline

Saturn 95 SL1 - BURNS RUBBER

Ignition Switch has a design flaw. All the current used to power the vehicle (lights, starter, etc) passes through the ignition switch. The Positive battery cables (2 of them) are connected to this switch. Each of these connections has a 30 amp fuse. There are 6 other wires connected to the switch. None of these wires are sized to handle 30 amps of current. If the switch fails then one of these 6 small wires will burn before the 30 amp fuse blows.

In our case the insulation burned off the black (chassis) wire and the wire (copper) melted at the crimp to the grounding connector.

These are pictures of the failed part and the damaged wire harness. The part does not look damaged but the failure is that the wrong pins are connected together inside the part. There are numerous shorts in every position of the switch but the most significant is that the Pink wire (+12V) connects to the black wire and Lt Grn wire in every key switch position. This is completely wrong when compared to the Haynes Schematic (E-7 page 12-15)

Part IgnSwitch_01 IgnSwitch_02 IgnSwitch_03

We attempted to call the dealer and GM. Without a recall notice from NHTSA they could care less. Unless I wanted to pay a couple of \$1000, which of course meant that we would be "better off" buying a new car, then do not waste their time.

THE AMAZING ISSUE: - all GM cars are built like this - most cars may be built like this. It saves the vehicle manufacturers a few dozen feet of wire and a couple of relays by running all the power through the ignition switch.

I added an inline fuse to the wire that burned, reused the crimp in the connector and ran a new wire to an accessible chassis ground.

I have more and higher resolution pictures. Any one needing information about this issue or the fix (material cost less than \$5) please contact me at

Pictures @ 2



