

1010 9250

24 Dec '04

NVS-200

To: The Administrator

In accordance with the letter I received, (Attachment 1) I purchased the Camshaft Position Sensor (See Attachment 1) had the part installed (see Attachment 2) and forwarded the bill to Daewoo in September 2004. I have not received any re-imbusement from Daewoo. Please advise me how to receive re-imbusement from Daewoo.

Sincerely Yours

Columbus, Ms

EXECUTIVE SECRETARIAT
2005 JAN -4 P 3 44
NATIONAL HIGHWAY
TRAFFIC SAFETY ADM.

Margaret
1/13/05



Attachment A

Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-9709

September, 2004
(II)

**Safety Recall Notice
Lanos, Nubira, Leganza**

Dear Lanos, Nubira, and Leganza Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daewoo has decided that a defect which relates to motor vehicle safety exists in certain Lanos, Nubira and Leganza model vehicles.

The problem is with the Camshaft Position (CMP) Sensor that may be installed in your Daewoo vehicle. The CMP sensor sends a CMP sensor signal to the engine control module (ECM). The ECM uses this signal as "sync pulse" to trigger the fuel injectors in the proper sequence. In rare instances, due to a possible crack in the C2 capacitor attached to the CMP Sensor PC board, CMP Sensor may malfunction, which will cause the check engine warning light in your instrument panel to illuminate. Additionally, the Camshaft Position Sensor and wiring may melt resulting in a burning smell and/or visible smoke and possibly an underhood fire.

If you have taken your Daewoo in for service since October 2001 because the Check Engine Warning Light was illuminated on your instrument panel, contact your Daewoo Dealer or Authorized Service Center (ASC) immediately to arrange for your vehicle to be inspected, because your CMP Sensor may have been replaced with one that is subject to this recall. Your dealer or ASC will inspect your vehicle and, if your CMP Sensor needs to be replaced, will replace the sensor and add an in-line fuse to the CMP Sensor wiring. If you are not the first owner of your Daewoo vehicle and/or are not sure if your vehicle has been serviced because of an illuminated Check Engine Warning Light, you should also immediately contact your Daewoo Dealer or Authorized Service Center (ASC) to arrange for your vehicle to be inspected.

If your vehicle has not been serviced since October of 2001 to address an illuminated Check Engine Light, or your vehicle's VIN* is not within the following VIN range, your vehicle is not subject to this recall campaign, and you need take no further action at this time.

- Lanos (VIN* numbers: 158465 to 715060)
- Nubira (VIN* numbers: 157058 to 778128, 998142 to 998146)
- Leganza (VIN* numbers: 105594 to 331911)

*VIN=Vehicle Identification Number

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**