



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 10014B

Date Received
21 FEB 28 AM 9:
21-FEB-2008

Repository
Reference No.
10150759

OWNER INFORMATION (Type or Print)

Name
Address
City BURLINGAME State CA Zip Code

Daytime Telephone Number
Evening Telephone Number
E-mail Address

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?
In the absence of an authorized name or address to the vehicle manufacturer.
Signature of Owner Date 5/11/08 YES NO

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield or driver's side
1M6SM1
Make MERCURY Model TRACER Model Year 1985
Date Purchased 01-OCT-85 Dealer's Name and Telephone Number
Engine: No: Cylinders 4 Fuel Type: Gas
Original Owner Dealer's City State Zip Code
Transmission Type AUTOMATIC Antilock Brakes Cruise Control Powertrain UNKNOWN
Vehicle Component Code 061000 ENGINE AND ENGINE COOLING:ENGINE
Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 07-FEB-2008 Failure Mileage 60430 Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)
DOT No. (Example: DOTM4LSABC036) Original Equipment Prior Repair Failure Location:
Tire Component Code Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
Seat Type: Installation System:
Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), condition, and circumstances.)

Crash Yes No Fire Yes No Number of Persons Injured Number of Deaths Reported to Police N

Narrative Description of Incident(s), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure;
i.e., parts repaired or replaced (and if old part is available).

DT*: THE CONTACT STATED WHILE ATTEMPTING TO START THE VEHICLE, THE ENGINE MADE A LOUD KNOCKING NOISE. THE CONTACT IMMEDIATELY TURNED OFF THE ENGINE AND THE NOISE STOPPED. THE VEHICLE WAS TOWED TO AN INDEPENDENT REPAIR SHOP FOR INSPECTION. THE MECHANIC REPLACED THE ENGINE SEAT, CYLINDER HEAD, AND HEAD GASKET WHICH CORRECTED THE PROBLEM.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.


AUTO NOW PARTS

RptHeadingLine3 - Change this text in "SETUP"

RptHeadingLine3 - Change this text in "SETUP"

RptHeadingLine4 - Change this text in "SETUP"

RptHeadingLine5 - Change this text in "SETUP"

TECHNICAL BULLETIN		Make: FORD
	September 1999	Model: No Model
	TB 1726	Liter: 1.9L
		VIN: J
		Year: 95-96

Valve Seat Breakage On 1991-96 Ford 1.9L VIN J Engines

The AERA Technical Committee offers the following information regarding valve seat breakage on 1991-96 Ford 1.9L VIN J engines. Most of the breakage reported has been with the intake valve seat on cylinder heads with the casting number of F0EE-B7A. Three-center valve cover mounting bolts can also identify those heads.

When the intake valve seat breaks, the valve seat shatters into tiny debris. The intake valve seats are made of a metal that shatters somewhat easily. When a valve job is to be performed, it is common procedure for the mechanic to just pull the intake and exhaust manifolds back to provide just enough room to get the cylinder head off of the engine. Replacement of all the intake seats is required to prevent the possible repeat failure to reoccur at the other locations. Once the valve job has been completed using a hardened seat, proceed with the installation of the cylinder head as outlined in a service manual.

When a seat shatters, debris from the valve seat goes into the intake and exhaust manifolds. In addition to the cylinder head from the engine, the manifolds should also be removed from the engine and thoroughly cleaned out of all debris. Failure to clean out the intake and exhaust manifolds could result in a repeated engine failure.

The AERA Technical Committee

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2005



Reference:

Page 1 of 1

Please note: this bulletin was given to me by the mgr of the garage

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**