



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Vehicle Owner's Questionnaire

TO REPORT VEHICLE SAFETY DEFECTS

888-327-4236

www.safercar.gov

FOR AGENCY USE ONLY

Date Received

21 JULY 2006

Repository ☐

Reference No.

10163101

OWNER INFORMATION (Type or Print)

Name

Street No.

Apt. No.

City

MANCHESTER

State

N.H.

Zip Code

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle?

In the absence of authorization, this report will be made available to the vehicle manufacturer only during a defect investigation or when you make a complaint about recall performance on your vehicle.

☒ YES ☐ NO

Signature of Owner

Date

8/10/06

VEHICLE INFORMATION

17 digit Vehicle Identification number located at bottom of windshield on driver's side

WDBW675JXA

Make

MERCEDES
BENZ

Model

S 500

Year

2001

Current Mileage

103,200

Date Purchased

4/02

Dealer's Name and Telephone Number

DREHER-HOLLOWAY 603 431-8585

Engine:

No. Cylinders 8

Fuel Type:

☐ Diesel ☐ Hybrid
☒ Gas ☐ Other

☐ Original Owner

Dealer's City

GREENLAND

State

N.H.

Zip Code

03840

Transmission Type

☐ Manual
☒ Automatic

☒ Antilock Brakes

☒ Cruise Control

Powertrain

☐ All-Wheel Drive
☐ Front-Wheel Drive

☒ Rear-Wheel Drive
☐ Four-Wheel Drive

FAILED COMPONENT(S)/PART(S) INFORMATION

Component Name

117000 DIGITAL INSTRUMENT PANEL

Incident Date(s)

17 JULY 2006

Failure Mileage

103,200

Failure Speed

0

Failure Location

☐ Driver ☐ Passenger
☐ Front ☐ Rear

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make/Brand

Tire Model/Line

Tire Name

Tire Size (Example: P215/65R1105)

Failed Structure

☐ Tread ☐ Sidewall ☐ Bead

DOT No. (Example: DOT MAL9ABC036 on sidewall)

☐ Original Equipment
☐ Prior Repair

Failure Type:

☐ Blowout ☐ Blister ☐ Crack ☐ Torn ☐ Tread Separation ☐ Road Hazard ☐ Out of Round

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make

Date Manufactured

Model Number and Name

Seat Type

☐ Infant ☐ Booster ☐ Integrated ☐ Convertible ☐ Other

Installed in Vehicle using the:

☐ Vehicle safety belt
☐ LATCH system*

Failed Part. Describe Failure Below

☐ Base ☐ Harness/Buckle ☐ LATCH Connector ☐ Shell ☐ Handle ☐ Other

*Vehicle info required

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the Incident(s), Failure(s), Crash(es), and Injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

0

Number of Deaths

0

Police Report No.

N

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies).

ENGINE CLUSTER WENT BLACK. UNABLE TO DETERMINE SPEED, DIRECTION
LIGHT FUNCTION, GAS GAUGE, TEMP GAUGE, RPM'S. FUSES BLOWN.
HIGH BEAM WOULD NOT WORK, TRUNK WOULD NOT OPEN, ALL DASH BOARD
AND DOOR LIGHTS FAILED, RADIO AND OTHER CONTROLS ON STEERING WHEEL
FAILED TO FUNCTION. DIRECTION LIGHTS ON MIRRORS CEASED TO FUNCTION.

Continue on back.

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to a49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administration enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Mail postage free or fax to 202-366-7882

Aug 10, 2006

Dear Sir,

Enclosed is the form you sent me in response to my filing a verbal complaint about the safety of my automobile. I have filled out the NHTSA form to correct some inaccuracies and included a copy of the VOP you had filled out. Also, I'm included copies of the invoices I have paid so far to correct the problems resulting from the defective instrument cluster. They total \$2029.06. Additionally I need to replace the two outside mirrors because the direction lights stopped functioning. The dealer estimates a cost of \$150 each, plus labor at \$99.00/hour. These have to be replaced for the car to pass inspection in New Hampshire.

Included also, is a copy of a NHTSA Recall Bulletin 06V028000. It describes the precise problem I had with my car. I hope you are successful getting this recall extended to include my VIN.

For your information, I bought the car from Chambers Motor Car of Boston. They are at 259 Mc Gath Highway, Somerville, MA. 02143 877 832-1461.

Please let me know if you need
further information. My daytime phone
number is [REDACTED] My E-mail
address is [REDACTED]
I look forward to hearing from you.

Best regards,
[REDACTED]

P.S. The dealer in New Hampshire, Holloway
Mercedes Benz, 309 Portsmouth Ave,
Greenland, N.H. 03840, (603-431-8585)
is the one which has been servicing
this car.



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects

1-888-DASH-2-DOT

(1-888-327-4236)

INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

21-JUL-2006

Repository ☐

Reference No.
10163101

OWNER INFORMATION (Type or Print)

Name

Address

City

MANCHESTER

State NH

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner

Date / /

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

WDBNG75JX1A

Make

MERCEDES BENZ

Model

S CLASS

Model Year

2001

Date Purchased
09-JUN-02

Dealer's Name and Telephone Number
HOLLOWAY MERCEDES BENZ 603 431 8585

Engine:

No: Cylinders 8

Fuel Type:

Gas

Original Owner

☐

Dealer's City

GRANDY GREENLAND

State

VT N.H.

Zip Code

05640

Transmission Type

AUTOMATIC

☒ Antilock Brakes

☒ Cruise Control

Powertrain

REAR WHEEL DRIVE

Vehicle Component Code

117000 DIGITAL INSTRUMENT PANEL

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
17-JUL-2006

Failure Mileage
103200

Failure Speed
0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

DT*: THE CONTACT STATED WHILE STARTING THE ENGINE THE CLUSTER INSTRUMENT PANEL DARKENED. AFTER THIS INCIDENT OTHER ELECTRICAL PROBLEMS OCCURRED; FUSES BECAME BLOWN, THE HIGH BEAM, RADIO AND INTERIOR LIGHTS FAILED. THE MANUFACTURER DECLARED THERE IS A RECALL FOR S MODELS AND PROVIDED THE CAMPAIGN NUMBER 06V08000. THE VEHICLE VIN# WAS NOT INCLUDED IN THE RECALL.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

INTERIOR LIGHTING**NHTSA RECALL BULLETIN**

Reference Number(s): 06V028000

VEHICLE DESCRIPTION

Model(s): 2000 MERCEDES BENZ CL CLASS

2000 MERCEDES BENZ S CLASS

2001 MERCEDES BENZ CL CLASS

2001 MERCEDES BENZ S CLASS

2002 MERCEDES BENZ CL CLASS

2002 MERCEDES BENZ S CLASS

2004 MERCEDES BENZ CL CLASS

2004 MERCEDES BENZ S CLASS

2005 MERCEDES BENZ CL CLASS

2005 MERCEDES BENZ S CLASS

Campaign No: 06V028000

Number of Affected Vehicles: 36911

Beginning Date of Manufacture: 2000 JUN

Ending Date of Manufacture: 2004 SEP

SYSTEM

INTERIOR LIGHTING

DESCRIPTION OF DEFECT

ON CERTAIN VEHICLES, THE INSTRUMENT CLUSTER IS EXPERIENCING ELECTRICAL MALFUNCTIONS. THE INSTRUMENT CLUSTER CONTAINS GAUGES AND INDICATORS THAT MUST BE ILLUMINATED WHENEVER THE VEHICLE IS IN OPERATION.

CONSEQUENCE OF DEFECT

DUE TO INADEQUATE ILLUMINATION, THE DRIVER WILL BE UNABLE TO READ THE GAUGES AND INDICATORS, SUCH AS THE SPEEDOMETER, WHICH COULD INCREASE THE RISK OF A CRASH.

CORRECTIVE ACTION

DEALERS WILL REPLACE THE INSTRUMENT CLUSTER MODULES. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT MERCEDES-BENZ AT 1-800-367-6372.

ADDITIONAL INFORMATION

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.

THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).