

1045 10105874

Date: July 31st, 2006

Address: Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W. , Washington, D.C. 20590

Subject: Engine Check Sign

To whom it may concern:

This is a complaint regarding the Daewoo Corporation that advised me to rectify the fault in the engine of my car which was found by the Daewoo Company as a manufacturing fault. They requested me to take my car to a repair shop: Brooklyn Dodge Repair Shop. They were unable to fix the problem which still causes the check engine prompt to appear in my car which is hazardous and irritating as well. Therefore I have enclosed a copy of the receipt at the Brooklyn Dodge Repair Shop and a copy of the Daewoo Corporation letter which are self-explanatory and prove my statement.

Thanking you in anticipation and in seeking your advice accordingly.

[Redacted signature block]

Richmond Hill, NY [Redacted]

Contact number [Redacted]

Info AS STATED

10/10/06



Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-9709

May, 2006
(II)

Safety Recall Notice Lanos, Nubira, Leganza

SECOND NOTICE

Dear Lanos, Nubira, and Leganza Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. We are writing as a follow-up to an earlier communication regarding this important subject. Our records indicate that you have not yet made your Daewoo vehicle available to your Daewoo Dealer or Authorized Service Center (ASC) allowing them to perform this important inspection procedure.

Daewoo has decided that a defect which relates to motor vehicle safety exists in certain Lanos, Nubira and Leganza model vehicles.

The problem is with the Camshaft Position (CMP) Sensor that may be installed in your Daewoo vehicle. The CMP sensor sends a CMP sensor signal to the engine control module (ECM). The ECM uses this signal as "sync pulse" to trigger the fuel injectors in the proper sequence. In rare instances, due to a possible crack in the C2 capacitor attached to the CMP Sensor PC board, CMP Sensor may malfunction, which will cause the check engine warning light in your instrument panel to illuminate. Additionally, the Camshaft Position Sensor and wiring may melt resulting in a burning smell and/or visible smoke and possibly an underhood fire.

If you have taken your Daewoo in for service since October 2001 because the Check Engine Warning Light was illuminated on your instrument panel, contact your Daewoo Dealer or Authorized Service Center (ASC) immediately to arrange for your vehicle to be inspected, because your CMP Sensor may have been replaced with one that is subject to this recall. Your dealer or ASC will inspect your vehicle and, if your CMP Sensor needs to be replaced, will replace the sensor and add an in-line fuse to the CMP Sensor wiring. If you are not the first owner of your Daewoo vehicle and/or are not sure if your vehicle has been serviced because of an illuminated Check Engine Warning Light, you should also immediately contact your Daewoo Dealer or Authorized Service Center (ASC) to arrange for your vehicle to be inspected.

If your vehicle has not been serviced since October of 2001 to address an illuminated Check Engine Light, or your vehicle's VIN* is not within the following VIN range, your vehicle is not subject to this recall campaign, and you need take no further action at this time.

- Lanos (VIN* numbers: 158465 to 715060)
- Nubira (VIN* numbers: 157058 to 778128, 998142 to 998146)
- Leganza (VIN* numbers: 105594 to 331911)

*VIN=Vehicle Identification Number

If you are the owner of the subject vehicle, but have leased it to another person, you are required by federal law to forward a copy of this notice to your lessee by first class mail within ten days of your receipt of this letter. See 49 C.F.R. 577.7(a)(2)(iv).

If you believe that Daewoo has failed or is unable to remedy the defect described in this letter without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at (888) 327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Because your safety is very important to Daewoo, we urge you to have your vehicle inspected and repaired immediately. Your Daewoo Dealer or Authorized Service Center (ASC) inspect your vehicle and determine if it is involved in this recall. If your Daewoo is involved in this recall, your dealer will replace the Camshaft Position Sensor and add an in-line fuse to the Camshaft Position Sensor wiring.

This service will be performed for you at no charge and should take about one hour. Thus, to minimize waiting time, you are advised to make an appointment with your Daewoo dealer or Authorized Service Center (ASC), in advance. For assistance in locating a Daewoo Dealer or Authorized Service Center (ASC) in your area, please visit the Daewoo website at www.daewoo.com and click on the "Service/Part Locator" link. Additionally, the Daewoo website provides information on other recall actions that may be applicable to your Daewoo vehicle. Simply click on the "Owners" link and follow the prompts.

If, however you take your vehicle to your Daewoo dealer or Authorized Service Center (ASC) on the scheduled service date and you have a problem with obtaining the corrective service on that date, please contact the Daewoo Customer Assistance Center toll-free at (877) 362-1234, option 6. A Daewoo representative will assist you with arranging prompt service for your vehicle.

The enclosed Owner Reply Card identifies your vehicle. Presenting the card at the time of your service will assist your Daewoo Dealer in completing this procedure in the shortest time possible. If you have sold or traded your vehicle, please let us know by completing the enclosed postage-paid reply card and returning it to us.

We apologize for any inconvenience this may cause you. We have taken this initiative in the interest of your safety and continued satisfaction with your Daewoo vehicle.

Sincerely,

Daewoo Customer Relations Department

6/8/06

516-358-9500
250-80 Service
TPK
718 434-6000
718 299-6300

THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).