

[REDACTED] <NHTSA>

From: [REDACTED] <NHTSA>
Sent: Thursday, January 19, 2006 5:58 PM
To: [REDACTED] <NHTSA>
Subject: RE: 99 Hyundai Recall - ATRANS Slip

[REDACTED] I tried to call you, but the number listed isn't yours. And, tomorrow's my RDO, so you may not be able to reach me then.


It's possible that your vehicle is not covered by this recall. The database does not list the effected VIN's. If you called the dealer, gave them your VIN, and they said that you are not effected by it, then you probably are not.

You have the customer notification letter. You can take it, and your vehicle to a dealer and ask them to do the repair. There are a few possibilities for why they may not.

1. A previous owner already took the car in for this remedy.
2. Your vehicle was not built during the months that there was a defect. (They may have addressed it in the plant before your vehicle was built.)
3. They believe that the recall has expired, or that for some other reason you are not entitled.

If it's 1 or 2, there is little that we can do. If it is 3, call me. Good luck.

[REDACTED]
NHTSA/DOT
400 7th Street SW
Washington, DC 20590



-----Original Message-----

From: [REDACTED] <Contractor>
Sent: Thursday, January 19, 2006 4:06 PM
To: [REDACTED]
Subject: RE: 99 Hyundai Recall - ATRANS Slip

TODAY I CALL LIKE YOU SAID DO AND THEY TOLD ME THAT MY CAR ISN'T INCLUDED IN THAT RECALL BUT YESTODAY THE PERSON I TALK TO TOLD ME THAT MY VEHICLE WAS COVERED UNDER THAT RECALL BUT NOW THERE TELLING ME SOMETHING DIFFERENT. SO WHAT DO I DO NOW?

-----Original Message-----

From: [REDACTED]
Sent: Thursday, January 19, 2006 2:02 PM
To: [REDACTED] <Contractor>
Subject: RE: 99 Hyundai Recall - ATRANS Slip

Hi [REDACTED]

If your vehicle is covered by recall 99V-178, and it has not already received its remedy, you are entitled.

You should contact a Hyundai dealer. Ask them if they have a record of your vehicle (VIN KMHVF24N2XU [REDACTED] being serviced for this recall. If it has not received the remedy, make an appointment with them to do so.

Hyundai may know the recall as campaign number 99-01-002. See attached recall notification.

<< File: RCDNN-99V178-4747.pdf >>

[REDACTED]
NHTSA/DOT
400 7th Street SW
Washington, DC 20590
[REDACTED]

-----Original Message-----

From: [REDACTED] <Contractor>
Sent: Thursday, January 19, 2006 12:00 PM
To: [REDACTED]
Subject:

Hi my name is [REDACTED] i am a contractor for dot I was online and i found out that my car has a recall on it so i contact the traffic safety adminstration auto safety hotline 1-888-dash-2-dot and the person on the phone give me a file [REDACTED] then she gave me a number to call to found out if my vehicle was one of the one effected that number was [REDACTED] then from there i was told that the recall expired 2 years ago and so i was like that mean i would have to pay to get this problem fix with me car i was told yes. My car is doing what the recall said. Here is the recall that came on the computer. I was told by Co-worker that safety recalls don't expire and if that indeed is true i would like to know what i have to do to get my car fix i only had the car sent NOV. 2005. Thanks for your time hope to hear from you soon.

Repor
t Date
:
NHT
SA
Camp
aign
ID
numb
er :

January 19,
2006 at 11:20
AM
99V178000

<< OLE Object: Picture
(Metafile) >>

<< OLE Object: Picture
(Metafile) >>

<<
OLE
Object
: Pictur
e (Met
afile)
>>

Make	Model/Bui
/ Mod	ld Years:
els :	
HYU	1999
NDAI	
/ AC	
CEN	
T	
HYU	1999
NDAI	
/ ELA	
NTR	
A	
HYU	1999
NDAI	
/ TIB	
URO	
N	
Manu	
factur	
er :	
HYU	
NDAI	
MOT	
OR	
COM	
PAN	
Y	
NHT	Mfg's
SA	Report
CAM	Date :
PAIG	JUL 06,
N ID	1999
Numb	
er :	
99V1	
78000	
Comp	
onent:	
POW	
ER	
TRAI	
N:AU	
TOM	
ATIC	
TRA	
NSMI	
SSIO	
N	

Potent
ial
Numb
er Of
Units
Affect
ed :
11530

Sum
mary:
<<
OLE
Object
: Picture (Metafile)
>>
VEHICLE
DESCRIPTION:
PASSENGER
VEHICLES
EQUIPPED
WITH
AUTOMATIC
TRANSMISSION.
THE
AUTOMATIC
TRANSMISSION
PRESSURE
RELEASE
CONTROL
SOLENOID
VALVE
SEALS
DO NOT
REMAIN
SUFFICIENTLY
ASTI

Consequence:
<<
OLE
Object
: Picture (Metafile)
>>
SUCH SLIPPAGE
CAN CAUSE
PREMATURE
DETERRIORATION
OF THE FRICTION
ELEMENT SURFACES
AND COULD CAUSE
THE VEHICLE
NOT TO ACCELERATE,
OR NOT ACCELERATE
AS EXPECTED,
WHEN THE DRI

Reme

dy:

<<

OLE

Object

: Pictur

e (Met

afile)

>>

DEA

TERS

WILL

REPL

ACE

THE

PRES

SURE

CON

TRO

L SO

LEN

OID

VAL

VE.

Notes

: <<

OLE

Object

: Picture

e (Metafile)

>>

OWNER

NOTI

FICA

TION

BEG

AN

JULY

14,

1999.

OWN

ERS

WHO

TAK

E TH

EIR

VEHI

CLES

TO

AN

AUT

HORI

ZED

DEA

LER

ON

AN

AGR

EED

UPO

N SE

RVIC

E DA

TE

AND

DO

NOT

RECE

IVE

THE

FREE

REM

EDY

WIT

HIN

ARE

ASO

NAR

[REDACTED]
TranTech, Inc., NHTSA

[REDACTED]
Washington, DC [REDACTED]



HYUNDAI AMERICA TECHNICAL CENTER, INC.

A Subsidiary of
Hyundai Motor Company (Korea)

5075 Venture Drive
Ann Arbor, MI 48108

RECEIVED

99 JUL -7 PM 2:16

Tel: (313) 747-6600
Fax: (313) 747-6699

July 6, 1999 OFFICE
DEFECTS INVESTIGATION

Ms. Kathleen C. Demeter
Director
Office of Defects Investigation
Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

99V-178 (01)

RE: Defect Information Report

Dear Ms. Demeter:

Pursuant to Part 573 of Title 49 of the Code of Federal Regulations, Hyundai Motor Company is submitting information concerning a recall that is being voluntarily initiated. Specific information as required by Section 573.5 is as follows:

573.5(c)(1)

Manufacturer - Hyundai Motor Company
Distributor - Hyundai Motor America

573.5(c)(2)

1999 model year Hyundai Accent, Elantra and Tiburon vehicles produced beginning March 25, 1999 through April 30, 1999 that are equipped with automatic transmissions.

573.5(c)(3)

Approximately 11,530 total vehicles, consisting of:

3,672 Accents
7,199 Elantras
659 Tiburons

573.5(c)(4)

Hyundai estimates that 10% of the vehicles may experience automatic transmission slippage as a result of this defect.

573.5(c)(5)

During the production period provided in response to 573.5(c)(2), the supplier's pressure control solenoid valve seals did not remain sufficiently elastic. The inelasticity results in automatic transmission fluid leakage at the pressure control solenoid valve interface to the valve body.

The automatic transmission fluid leakage results in reduced pressure application to the transmission clutches, brake and kickdown servo, which allows them to slip. Such slippage can cause premature deterioration of the friction element surfaces and may cause the vehicle to not accelerate, or to not accelerate as expected, when the driver presses the accelerator pedal.

573.5(c)(6)

Hyundai first became aware of this condition during the week of June 21, 1999 when customers contacted Hyundai dealers about transmission slipping.

573.5(c)(8)

All owners of record of affected vehicles will be contacted by first class mail and will be asked to bring their vehicles to Hyundai Dealers to have the pressure control solenoid valve replaced. It is anticipated that owner notification will begin during July, 1999.

573.5(c)(9)

The Technical Service Bulletin containing the pressure control solenoid valve replacement procedure is enclosed.

573.5(c)(10)

The draft owner notification letter is enclosed.

573.5(c)(11)

Hyundai has assigned "Campaign 033" as the designation for this campaign.

Sincerely,

Robert Babcock
Manager, Government Affairs

Attachments: 2

DRAFT

MOTOR VEHICLE RECALL

99V-178 (03)

Dear 1999 Accent, Elantra or Tiburon Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act:

Hyundai has determined that a defect, which relates to motor vehicle safety, exists in certain 1999 model year Accent, Elantra and Tiburon vehicles produced beginning March 25, 1999 through April 30, 1999 that are equipped with automatic transmissions.

What is the problem?

- **Some automatic transmission pressure control solenoid valve seals in this production range of vehicles were improperly manufactured. This can result in reduced pressure to the transmission friction elements. This reduced pressure allows the friction elements to slip, which can cause premature deterioration of the transmission. Slippage also can cause the vehicle to not accelerate, or to not accelerate as expected, when the accelerator pedal is depressed.**

Inability to accelerate when the driver presses the accelerator pedal could increase the risk of a vehicle crash.

What will Hyundai do?

- **In order to ensure that your vehicle does not experience transmission slippage relating to this condition, we are asking you to schedule an appointment as soon as possible to take your vehicle to your Hyundai dealer. The Hyundai dealer will replace the pressure control solenoid valve seal in your vehicle's automatic transmission. You should plan to leave your vehicle at your Hyundai dealer for a half day to have this service performed. This operation will be performed at no charge to you.**

What should you do?

- **We urge you to call your Hyundai dealer to schedule an appointment to have this work performed as soon as possible.**


What if you have other questions?

- **If you have any difficulty having this service repair performed, we recommend that you call the Hyundai Customer Assistance Center at 1-800-633-5151. If you are still not satisfied that we have remedied this situation without charge, and within a reasonable amount of time, you may wish to write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D.C. 20590 or call their toll-free Auto Safety Hotline at 1-800-424-9393 (Washington, D.C. residents may call 202-366-0123).**


We urge your prompt attention to this important safety matter.

Hyundai Motor America


4. Using two blade screwdrivers, push the tabs of the solenoid valve grommet inward and push the grommet into the transaxle case.



5. Remove the oil filter from the valve body.
6. Remove the oil temperature sensor installation bolt, then remove the sensor from the bracket.
7. Remove the 10 valve body bolts. Remove the valve body.



8. Remove the two bolts that secure the PCSV.






HYUNDAI Technical Service Bulletin


DRAFT

Group	CAMPAIGN
Number	99-01-002
	99V-178 (06)

9. Remove the black rubber seal and discard. Install a new seal (P/N 46341-34010).




10. Carefully align the cut-out notches on the seal to the flange.



11. Reinstall the solenoid valve and torque to specification of 3-4 lb.ft (40-60 kg.cm)

12. Confirm the O-ring is installed on the top center of the valve body and the valve body pipe is installed on the top of the valve body.



13. Push the solenoid connector through the hole in the case and push the solenoid valve grommet into the hole until the tabs click into position.

14. Carefully align the manual valve on the valve body to the manual control shaft and reinstall the valve body.
15. Reinstall the ten bolts and torque to specification of 7-9 lb.ft (100-120 kg.cm).
16. Reinstall the oil temperature sensor to the bracket.
17. Install a new oil pan gasket and reinstall the oil pan. Tighten the bolts to specification of 7-9 lb.ft (100-120 kg.cm).
18. Reconnect the solenoid connector to the engine harness.
19. Reinstall the battery tray, battery and air cleaner.
20. Add SP-II ATF (approximately 4 1/2 quarts for Accent, 5 quarts for Elantra/Tiburon) and check the level with the engine idling in Neutral.
21. Test drive the vehicle and confirm the shifting is correct. When the ATF is at normal operating temperature (70-100°C, 159-212°F), recheck the ATF level.
22. Reset the customer's radio stations and clock.





HYUNDAI Technical Service Bulletin

DRAFT

Group

CAMPAIGN

Number

99-01-002

PARTS INFORMATION:

99V-178 (08)

MODEL	PART NAME	PART NUMBER
1999 Elantra, Tiburon & Accent	Seal - packing	46341-34010
1999 Elantra, Tiburon & Accent	SP-II ATF	00230-18000
1999 Elantra/Tiburon	Oil pan gasket	45265-28010
1999 Accent	Oil pan gasket	45265-22010

CAMPAIGN CLAIM INFORMATION:

MODEL	OP CODE	OPERATION	OP TIME	OP QTY
Accent	91A043R0	Remove and Reinstall PCSV Rubber Seal and Oil Pan Gasket	1.2	1
	91A043R1	Remove & Reinstall Transaxle and Flush Cooler Lines	3.6	1
Elantra, Tiburon	91A043R0	Remove and Reinstall PCSV Rubber Seal and Oil Pan Gasket	1.2	1
	91A043R2	Remove & Reinstall Transaxle and Flush Cooler Lines	3.9	1

SUBMIT CLAIMS FOR THE ABOVE APPLICABLE CAMPAIGN OPERATION CODE USING THE CAMPAIGN SCREEN.

NOTE: IN THE RARE CASE WHEN THE ATM REQUIRES REPLACEMENT UNDER THIS CAMPAIGN, PRIOR AUTHORIZATION IS REQUIRED FROM YOUR DPSM.