



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects

1-888-DASH-2-DOT

(1-888-327-4236)

INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository ☐

03-AUG-2007

2007 DEC 12 AM 11:13

Reference No.

10198405

OWNER INFORMATION (Type or Print)

Name

Address

City

BUENA-PARK Santa Fe Springs

State CA

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

Make

FORD

Model

EXPEDITION

Model Year

1997

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Gas

Original Owner

☐

Dealer's City

State

Zip Code

Transmission Type

AUTOMATIC

☒ Antilock Brakes

☒ Cruise Control

Powertrain

UNKNOWN

Vehicle Component Code

110000 ELECTRICAL SYSTEM

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)

25-JUL-2007

Failure Mileage

Failure Speed

0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment

☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☒ Yes ☐ No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

He heard smoke after alarm

TL*THE CONTACT OWNS A 1997 FORD EXPEDITION. WHILE PARKED OVER NIGHT A FRIEND SMELLED SMOKE AND NOTICED THERE WAS SMOKE COMING FROM THE VEHICLE. HE LATER NOTICED THE VEHICLE WAS ENGULFED IN FLAMES. THE FIRE DEPARTMENT EXTINGUISHED THE FIRE HOWEVER; THE FIRE DESTROYED THE VEHICLE, OFFICE FURNITURE AND PERSONAL ITEMS. AS OF AUGUST 3, 2007, THE CAUSE OF THE FIRE HAS NOT BEEN DETERMINED. THE VIN, ENGINE SIZE, NUMBER OF CYLINDERS AND MILEAGE INFORMATION WERE UNAVAILABLE.

On August 30th a forensics expert determined the cause of fire was a defect from the manufacturer, due to a recalled cruise control switch. The owner never received a recall notice and was unaware of the defect. The owner lost the bulk of his company's assets due to the fire.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

BARNETT AUTOMOTIVE ENGINEERING



3065 Hayes Ave. ♦ Costa Mesa, California, 92627
Phone (714) 444-3224 ♦ Fax (714) 444-3064

September 3, 2007



Santa Fe Springs, CA



File Name: [REDACTED] Ford Motor Company
Claim Number: Not Filed

VEHICLE INSPECTION

ASSIGNMENT:

Gregory J. Barnett, Consultant, was retained to inspect the subject vehicle specifically to perform a fire cause and origin investigation on the subject vehicle, a 1997 Ford Expedition, for the primary failed part that caused the fire.

CONCLUSION:

It is the conclusion of this expert that the fire that occurred on the date of loss was due to a latent defect in the cruise control deceleration switch. The switch wires show signs of high electrical heat and arc beading. The subject vehicle also has safety recall NHTSA Number 05V388000 open. The cruise control deceleration switch is known to cause fires even when vehicle is off and parked. The recall is attached to this report labeled as "EXHIBIT A".

DISCUSSION:

Vehicle Make: Ford
Model: Expedition
Year: 1997
VIN: 1FMFU18L6VI [REDACTED]
Miles: Not Available [REDACTED]

On 8/30/07 this expert proceeded to [REDACTED], Santa Fe Springs, CA where he contacted [REDACTED] who produced the subject vehicle for inspection.

When this expert interviewed [REDACTED] the case facts were related as follows: [REDACTED] was in another part of the industrial unit where the subject vehicle was parked. The subject vehicle had been parked at least one hour. [REDACTED] smelled smoke/something burning. When he walked into the area where the subject vehicle was parked, he observed flaming combustion under the hood of the subject vehicle. [REDACTED] stated he observed drips of flaming combustion dropping down onto the floor on the left side of the vehicle. An ABC fire extinguisher was used by [REDACTED] in an attempt to extinguish the flames. However, the fire grew out of control and burned or caused smoke damage to most of the industrial unit where the fire occurred.

This expert examined the exterior, interior, and underside of the subject vehicle. There was a distinct burn pattern that moved from left-to-right inside the engine compartment, front-to-rear and top-downward on the remainder of the subject vehicle.

Since the subject vehicle had been parked at least one hour prior to the fire starting, auto ignition of a flammable or combustible liquid on a hot exhaust component was ruled out. Given the fire description by [REDACTED] electrical fire was determined to be the most likely cause. Additionally, this model vehicle is a known fire hazard from the cruise control deceleration switch.

The electrical system and the components in the engine compartment were inspected carefully for signs of electrical heat. The wires that feed the cruise control deceleration switch were examined. There was evidence of high electrical heat in the wiring. This is evidenced by the brittle copper wire with an arc bead on the end of one of the wires. The wire with the arc bead broke off when touched. It was photographed by this expert. However, [REDACTED] retained custody of the wire. This expert recommended to [REDACTED] that the wire be preserved carefully in a safe place.



