

INFORMATION Redacted PURSUANT TO THE FREEDOM OF

INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)



U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

111 2 8 2010
 15 JUN 2010

Repository

Reference No.
 10336463

OWNER INFORMATION (Type or Print)

Name [REDACTED]
 Address [REDACTED]
 City REDFORD State MS Zip Code [REDACTED]

Daytime Telephone Number [REDACTED] E-mail Address [REDACTED]
 Evening Telephone Number [REDACTED]

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: **I FTNX21S3YE [REDACTED]** Make FORD Model F250 Model Year 2000
 Date Purchased **2000** Dealer's Name and Telephone Number **VANITY FORD 734-996-2300** Engine: No: Cylinders **10** Fuel Type: **GAS**
 Original Owner Dealer's City **ANN ARBOR** State **MI** Zip Code **48106**
 Transmission Type **Auto** Antilock Brakes Cruise Control Powertrain Multiple Failure: Incident Date(s) **12-JUN-2010**

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 060000 ENGINE AND ENGINE COOLING Failure Mileage 207000 Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)
 DOT No. (Example: DOTM9ABC036) Original Equipment Prior Repair Failure Location:
 Tire Component Code Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
 Seat Type: Installation System:
 Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash Yes No Fire Yes No Number of Persons Injured Number of Deaths Reported to Police
 N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 2000 FORD F250. THE CONTACT STATED THE VEHICLE CAUGHT FIRE WHILE PARKED AND THE FIRE SPREAD TO THE CAB AND TIRES. THE FIRE DEPARTMENT STATED THAT THE FIRE ORIGINATED UNDER THE HOOD. THE VIN WAS UNAVAILABLE AT THE TIME OF THE COMPLAINT. THE CONTACT PLANNED TO SPEAK WITH THE MANUFACTURER. THE CURRENT AND FAILURE MILEAGES WERE APPROXIMATELY 207,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

User: ENORMAN

REDFORD POLICE DEPARTMENT

07/09/2010 14:20

Supplements - Case #: 10-04133

Fire Inspector Garland and I looked at the F-250 at the N Redford Tow Yard on this date. Listed are the observations noted about the vehicle fire. Pictures of the vehicle are attached to the report.

The vehicle is a 2000 Ford F-250

The fire originated in the engine compartment and spread to the passenger compartment.

The upper portion of the engine on the driver side of the vehicle sustained the most extensive damage. This included the cowl and hood.

The cruise control switch and the plastic master cylinder reservoir were completely consumed.

The upper edge of the radiator on the driver side was consumed

The lower portions of the engine still had significant amounts of combustibles present

The valve cover on the driver side showed significantly more flame impingement damage than the passenger side valve cover

The front driver tire was partially consumed while the front passenger tire was primarily intact

The driver side view mirror was primarily consumed while the passenger side mirror was intact

The windshield on the driver side was consumed along the A-pillar while the passenger side windshield still had pieces of glass in place along the A-pillar

This model year Ford fell under the vehicle recall for the cruise control switch. It is unknown if the recall work was performed on this vehicle.

[06/25/2010 16:56, KCRITTENDEN, 1993, RTPD] [06/25/2010 17:03, KCRITTENDEN, 1993, RTPD] [06/25/2010 17:05, KCRITTENDEN, 1993, RTPD]

July 6, 2010

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]



www.herndon-assoc.com

36135 Schoolcraft
Livonia, Michigan 48150
FAX: 734 591 0140

100 Ouellette Ave, Suite 901
Windsor, Ontario N9A 6T3
1 800 961 2909

P.O. Box 27
Boyer City, Michigan 49712
231 582 5543

P.O. Box 520
Coloma, Michigan 49038
269 468 3418

Licensed in Michigan, Ohio,
Illinois, Indiana, Arizona
Florida & Ontario, Canada

PREDICATION:

This case is predicated upon the request of [REDACTED] with special reference to the fire loss of a 2000 Ford F-250.

TITLE INFORMATION:

A review of the title information indicates that the 2000 Ford pickup SRW super duty, was transferred into the name of [REDACTED] and [REDACTED] of [REDACTED] in Redford Township, Michigan, [REDACTED] on February 23, 2006, at which time the odometer read 169,193 actual miles. First Catholic Federal Credit Union is the secured interest. Michigan license plate the [REDACTED] registered to the vehicle, expires September 18, 2010. The driver's license number listed on the registration is [REDACTED] (See Enclosed Document)

VINQUERY:

Vinquery decoded the Vehicle Identification Number as a 2000 Ford F-250, super duty, 4 wheel drive, equipped with a 6.8 liter, V-10 gasoline engine and was assembled in the United States. (See enclosed document)

INSPECTION:

On June 29, 2010, at 8:15 a.m., this Investigator arrived at North Redford Towing in Redford, Michigan, to conduct an investigation into the fire loss of a 2000 Ford F-250.

Once at the scene, a close inspection provided the following information:

SEE ENCLOSED INVESTIGATION REPORT

Prior to leaving the inspection location, several digital photographs were taken, are stored on a server off site, and are enclosed for your review.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010

July 6, 2010
Page 2

ORIGIN AND CAUSE INVESTIGATION:

On June 29, 2010, at 8:15 a.m., this Investigator arrived at North Redford Towing in Redford, Michigan, to conduct an origin and cause investigation into the fire loss of a 2000 Ford F-250, white in color, Vehicle Identification Number 1FTNX21S3YE [REDACTED]. Upon arrival at the facility, the vehicle is located in the secured parking lot and identified by the public Vehicle Identification Number in the area of the windshield and dashboard. Initial observations reveal evidence of a fire to have originated within the engine compartment which extended to both front tires, partially consuming and deflating same. The fire has further extended, partially consuming the grille and headlight assemblies, melting and cracking the windshield, and entering the passenger compartment, where there is high burning lessening in degree extending towards the rear. Further, there is blistering to the painted surfaces of the front clip, driver door, and roof of the vehicle with the rear of the vehicle intact, to include both rear tires which are still intact and inflated.

The examination is now focused to the fuel tank, fill tube, and fuel cap, where all are found to be intact and are free of any fuel leakage or fire origin. cursory inspection of the undercarriage reveals it is intact, however the spare tire is missing. The examination continues and is focused to the rear, where there is a trailer hitch and evidence of aftermarket wiring having been connected to the factory trailer wiring, however all of the wiring is intact and undamaged by fire.

The inspection is now focused to the bed of the truck, where there is a plastic Ford bed liner, which is intact. Contents include screwdrivers, a CD, a box of nails, and a lunch pail.

At this time the inspection is focused to the cab area, where it is determined that all four doors were closed during the fire and all windows were in the up/closed position. Inspection reveals that the passenger door window was broken in during the course of fire fighting, and the windshield has melted and cracked during the course of the fire.

The inspection continues and is focused to the seating, where there is high burning noted to the rear seat where there is a child seat on the passenger side. Inspection further reveals high burning to the front seats, drop down is noted on the bottom seat cushions but no evidence of any fire origin. Inspection of the flooring reveals the carpeting still intact, there are baseball caps, rolls of tape, water bottles, towels, an umbrella, and papers noted, but no evidence of any fire origin. Further inspection of the passenger floor area reveals the remains of the glove box door which has melted and fallen into the floor area during the course of the fire.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010

July 6, 2010
Page 3

At this time the investigation is focused to the dashboard, where there is exposure fire damage extending from the engine compartment with much of the combustible dashboard panel remaining on the side closest the driver and passenger. Inspection reveals exposure fire damage within the dashboard and to the associated wiring, where the fire has extended through openings in the bulkhead on the right or passenger side. At this time having completed an inspection of the cab area to include the dashboard, no evidence of any fire origin is found.

The examination is now focused to the engine compartment, where a subsequent check of the fluid levels reveals the brake fluid, power steering fluid and coolant have drained during the course of the fire. The transmission fluid is full and the oil is overfull and can be attributed to water entering the engine compartment during fire extinguishment.

The inspection is focused to the right or passenger side, where the damage is much less pronounced to the right front tire versus the left or driver's side front tire. The examination of the battery in the right front reveals plastic casing and lead posts remaining and no evidence of any fire origin. Inspection of the battery cables reveal they are partially void of insulation but reveal no evidence of any electrical faulting or fire origin. Further, there is still wiring insulation intact on the positive cable traveling down to the starter.

The investigation continues and is focused to the alternator located on the top center of the engine, where the housing is not melted. Inspection of the main alternator cable reveals it is void of insulation but maintains integrity, the fusible link is still intact traveling to the solenoid, and there is no evidence of any fire origin.

The examination is now focused to the radiator and air conditioning condenser, where melting is noted to the air conditioning condenser and melting is noted to the inside of the radiator, most pronounced on the left or driver's side and is high in nature. The examination continues and the front lower section of the engine compartment reveals the remains of combustible transmission cooler hoses, lower radiator hose and combustible power steering cooler hoses and no evidence of any fire origin.

The investigation is focused to the top of the engine, where there are still combustible hoses remaining and combustibles in the area of the coil packs. Inspection of the fuel rails reveal combustibles remaining and the fuel lines still connected to the fuel rails at the rear, and no evidence of any fire origin due to fuel leakage.

At this time, the inspection is focused to the main wiring harness at the rear of the engine compartment, where the wiring is void of insulation traveling to the left or driver's side to

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]

July 6, 2010
Page 4

include the main lead traveling to the fuse relay center, but there is no evidence of any electrical faulting. Inspection of the fuse relay center reveals charred combustibles remaining and no evidence of any fire origin. Further inspection of the windshield wiper motor at the cowl reveals exposure fire damage and no evidence of any fire origin within this area.

The examination is now focused to the brake booster. Inspection reveals the paint has been consumed and the alloy master cylinder has been almost totally consumed by the fire, with the steel brake lines having melted out of same. Upon searching the suspension components and undercarriage, no remains of the vehicle speed control deactivation switch can be found. The examination is now focused to the valve covers, where the fire damage to the driver's side valve cover, coupled with the fire damage to the inside of the driver's front tire, is all consistent with the fire having originated within the engine compartment on the driver's side in the immediate area of the master cylinder.

At this time the vehicle is elevated into the air by a forklift truck, where the oil pan and transmission pan are intact and the fuel lines and fuel filter are intact and there is no evidence of any fire origin within the undercarriage.

At this time having completed the above inspection and examination, it is the opinion of this Investigator that the fire originated within the rear of the engine compartment on the left or driver's side and at this time the investigation continues.

NATIONAL HIGHWAY TRAFFIC AND SAFETY ADMINISTRATION:

A search of the National Highway Traffic and Safety Administration for 2000 Ford F-250 super duty trucks produced three recalls. Of interest is NHTSA Safety Campaign I.D. No. 09V399000. The manufacturer report date is October 9, 2009. The NHTSA Action Number is EA08021. The component is vehicle speed control. There are 4,500,000 potential units affected. The summary states Ford is recalling models to include 1999 through 2000 F-250 super duty trucks equipped with Texas instruments speed control deactivation switch. The switch may leak internally and then overheat, smoke or burn. The consequence states a vehicle fire could occur with or without the engine running. Ford will notify owners that dealers will install a fused wiring harness in line with the speed control deactivation switch. Repairs will be completed free of charge. Safety recall began October 27, 2009. The Ford Recall Campaign Number is 09S09.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]

July 6, 2010
Page 5

A further search of the National Highway Traffic and Safety Administration Defects Investigation Database produced three records, to include EA05005, pertaining to the vehicle speed control system. (See enclosed documents)

ALLDATA SYSTEM:

A search of the Alldata System for 2000 Ford F-250 4 wheel drive trucks equipped with 6.8 liter, 10 cylinder gasoline engines produced four general campaigns, 13 safety related recalls, and a number of technical service bulletins. Of interest are recall 05S28S15, dated April 10, 2008, cruise control deactivation switch inspection; 09S09 dated October 13, 2009, cruise control deactivation switch overheating; and NHTSA recalls 06V286000 dated July 27, 2006, cruise control switch fire hazard; 07V336000 dated August 2, 2007, cruise control fire hazard; and 09V399000 dated October 9, 2009, cruise control deactivation switch. (See enclosed documents.)

OPEN RECALL CHECK:

This Investigator contacted the Service Department of North Brothers Ford in Westland, Michigan. Upon providing the Vehicle Identification Number, it was ascertained there is an open recall on the speed control deactivation switch.

INTERVIEW [REDACTED]

On June 29, 2010, at 2:50 p.m., Investigator Randy List conducted a telephone interview with [REDACTED] named insured and co-titleholder with [REDACTED] [REDACTED] indicated that she and [REDACTED] both operate the vehicle. [REDACTED] was the last operator of the vehicle of before the fire, and was alone.

The fire was discovered on June 12, 2010, between 2:00 and 2:30 a.m., and the weather conditions were clear. The vehicle was parked in the driveway of their home at 8848 Sarasota Street in Redford Township, Michigan. Subsequently, [REDACTED] called 911 from the home phone, at which time the Redford Township Fire Department responded and extinguished the fire involving the 2000 Ford F-250 equipped with a gasoline operated engine.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]

July 6, 2010
Page 6

The vehicle was purchased new in 2000 from Varsity Ford in Ann Arbor, Michigan. Since the purchase, they have not received any recall notices, campaigns, or correspondence from the manufacturer.

At the time of purchase a factory warranty was in effect. Since the purchase, no warranty or service work was performed, excluding routine maintenance to include brakes and fluid changes, etc.

The vehicle was last refueled earlier that evening and the tank was full. [REDACTED] indicates that [REDACTED] checks the fluid levels in the vehicle and that oil changes are done between 3,000 and 4,000 miles. In between oil changes there is no need to add any fluids.

Prior to the fire, there were no mechanical or electrical problems experienced. The mileage at the time of the purchase was new and the mileage at the time of the fire loss was approximately 207,000 miles.

Since the purchase, no aftermarket electrical accessories have been added and nothing was plugged into the cigarette lighter or auxiliary power port. It was learned that the vehicle is equipped with a factory keyless entry system.

In a short scenario, it was learned that the vehicle was driven home by [REDACTED], parked in the driveway and at approximately 2:00 a.m. they were awakened by a glow outside and when they came out the engine compartment was on fire.

The firefighters indicated it was not arson and believe it was electrical. [REDACTED] believes the fire is electrical.

As a result of the fire there was fire damage to the exterior of the home and to the neighbor's home. At this time no further information was obtained, the interview was terminated.

INTERVIEW [REDACTED]

On June 29, 2010, at 3:40 p.m., Investigator Randy List conducted a telephone interview with [REDACTED] who last operated the vehicle. [REDACTED] confirmed that he was alone prior to parking the vehicle and experienced no mechanical or electrical problems prior to parking same.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]

July 6, 2010
Page 7

When asked if he is a smoker, he stated he is but had not been smoking on his way home.

[REDACTED] reiterated that no aftermarket electrical items were added to the vehicle. He further reiterated that nothing was plugged into the cigarette lighter or auxiliary power port.

According to [REDACTED] there was minor damage when the vehicle was rear-ended in 2008 and was not repaired. This was the only accident involving the vehicle.

The last drive was approximately 30 to 45 minutes, during which time the headlights and radio were being utilized and were functioning properly. Prior to parking the vehicle, he was not pulling a trailer. It was further learned the trailer hitch was on the vehicle when purchased.

Prior to parking the vehicle no fluid leakage problems were experienced, no operability problems, no warning lights illuminated, there were no changes in the gauges and no unusual odors or noises were detected.

In a short scenario [REDACTED] stated the vehicle was driven home with no problems. The vehicle was parked in the driveway between the houses. At approximately 2:00 a.m., he awoke to use the restroom and saw a glow out the window. Looking out, he saw flames coming from under the hood. He awoke his family, 911 was notified, at which time he went out and sprayed the house with a garden hose until the fire department responded and extinguished the fire.

The smoke and flames were first observed under the hood. At the time of the fire the hood was closed, all doors were closed, the vehicle was locked and the windows were up.

[REDACTED] believes the fire was electrical. Further, he has not spoken to any other fire investigators, public or private, regarding the fire.

Since the fire, no items were removed from the engine compartment. Further, there were no flammable or ignitable liquids being stored within the vehicle.

When questioned regarding the operation of the cruise control, it was learned that the cruise control is not used often. It was used possibly one to two times in the last six months. The last time it was used, no problems were experienced with same.

At this time no further information was obtained, the interview was terminated.

IN RE: H&A File No. 10-1067VF
Date Received: June 29, 2010
[REDACTED]

July 6, 2010
Page 8

REDFORD TOWNSHIP FIRE DEPARTMENT:


This office was not requested to obtain a copy of the Redford Township Fire Report pertaining to the fire in question.

CONCLUSION:

Having completed an examination of the vehicle, reviewed an interview obtained from [REDACTED] and [REDACTED] who last operated and discovered the fire, conducted research pertaining to the vehicle, and based upon all of the information known at the time of the preparation of this report, it is the opinion of this Investigator that the fire originated within the left or driver's side rear of the engine compartment, in the immediate area of the master cylinder and brake fluid reservoir, with the fire extending upward and outward from this location causing the damage present. The fire is classified as an accidental fire, electrical in nature. It should be noted that the speed control deactivation switch is located within this area and has been recalled due to the potential for an engine compartment fire and the fire is consistent with this recall. Further, the recall is open/has not been satisfied on this vehicle.

At this time no further investigation is forthcoming, we are closing our file and forwarding our report and photographs for your review.

Conclusions and opinions expressed in the report were developed utilizing the Investigator's training, education, experience and standard investigative techniques.



Devin C. Jordan, CFI

DCJ/dkh

PAINTING INC
REDFORD, MI 48239-1549

1008
74-7154/272A 50
1883620968

Date 6-28-10

Pay to the Order of Herbon + Associates
Five Hundred ⁰⁰/₁₀₀

\$ 500⁰⁰



Dollars



FOR _____



HERNDON
IA
ASSOCIATES
800.961.2909

10-1067 VF

VEHICLE FIRE INVESTIGATION 2

Passenger Compartment (Interior) Cont.

17	Overhead Console	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>	N/A <input type="checkbox"/>
	DVD Player/Monitor(s)	Intact <input type="checkbox"/>	Partially Consumed <input type="checkbox"/>	Consumed <input type="checkbox"/>	N/A <input checked="" type="checkbox"/>
18	Air Bags:				
	Steering Wheel:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/> N/A <input type="checkbox"/>
	Passenger Side Dash:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/> N/A <input type="checkbox"/>
	Right Rear:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>
	Left Rear:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>
	Side Air Bags (Driver):	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>
	Side Air Bags (Pass):	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>
	Headliner/Curtain:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Deployed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>
19	Odometer Reading: _____ Removed <input type="checkbox"/>				
	Analog <input type="checkbox"/> Digital <input type="checkbox"/> Destroyed By Fire <input checked="" type="checkbox"/> Vandalized <input type="checkbox"/>				
	Oil Change Sticker <input type="checkbox"/> Date: _____ Mileage: _____				
20	Title Information: (Date Of Transfer To Current Owner/Mileage) <i>2-23-2004 / 1169193 Actual Miles</i>				
21	Ashtray Smoking Materials Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unk Cigar Lighter Used <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unk				
22	Personal Effects In Passenger Compartment <i>car seat, rolls of tape, plastic drink bottles, hats, sandwiches</i>				

Engine Compartment

23	Engine Accessibility	Limited (Hood Jammed) <input type="checkbox"/>	Open <input checked="" type="checkbox"/>	Forced Or Unbolted By Investigator <input type="checkbox"/>
		Consumed <input type="checkbox"/>		
24	Engine	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Partially Stripped <input type="checkbox"/> Fire Damaged <input checked="" type="checkbox"/>
25	Battery	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/> After-Mkt wiring/conn <input type="checkbox"/>
26	Aux Battery	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/> N/A <input checked="" type="checkbox"/>
27	Fuse/ Relay Center	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/>
28	ECM/PCM	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/>
29	Radiator	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/>
30	AC Condenser	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/> N/A <input type="checkbox"/>
	Fluid Levels - NOTE: D.B.F. = DRAINED BY FIRE			
31	Oil	Transmission	Coolant	Brake
	D.B.F. <input type="checkbox"/> <i>over full / checked</i>	D.B.F. Full <input type="checkbox"/>	D.B.F. <input checked="" type="checkbox"/>	D.B.F. <input checked="" type="checkbox"/>
		Dealers Access <input type="checkbox"/>		Power Steering D.B.F. <input checked="" type="checkbox"/> Electric <input type="checkbox"/>
32	Belts:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
33	Upper Hose:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
34	Lower Hose:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
35	Engine Parts Missing: <i>Ø</i>			
36	Additional Information:			

Exterior Examination

37	Tires: (Brand)	OEM or <u>Aftermarket</u>	32 nd of Tread Remaining	No. Of Lugs	Missing	Switched
	<i>Pirelli</i>	<u>Wheels</u> / Wheel Covers				
LF						
LR	<i>4</i>	<i>4</i>	<i>3-4</i>	<i>All</i>		
RR						
RF						

VEHICLE FIRE INVESTIGATION **3**

Door Handle/Cylinder

38	Driver Door	Intact <input checked="" type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
39	Left Rear (sliding/cargo) Door(s)	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
40	Rear Cargo Door (s)	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
41	Right Rear (sliding/cargo) Door(s)	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
42	Passenger Door	Intact <input checked="" type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>

Trunk/Cargo/Bed Compartment Examination

43	Pickup <input checked="" type="checkbox"/>	Van <input type="checkbox"/>	Utility Vehicle <input type="checkbox"/>	Other <input type="checkbox"/>		
44	Trunk Lock	Intact <input type="checkbox"/>	Locked <input type="checkbox"/>	Forced Open <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
45	Trunk Release	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Electric <input type="checkbox"/>	Manual <input type="checkbox"/>	Unknown <input type="checkbox"/>
46	Entry To Trunk	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Through Deck <input type="checkbox"/>	Rear Seat <input type="checkbox"/>	

Trunk/Cargo/Bed Contents

47	Spare Tire	Intact <input type="checkbox"/>	Missing <input checked="" type="checkbox"/>	On Vehicle <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
48	Tire Change Equipment	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>			
49	CD Changer in Cargo Area or Trunk	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Hybrid Batteries <input type="checkbox"/>		
50	Aftermarket Wiring for Audio/Video System i.e. Power Cable, Speaker Wiring, RCA Connectors	Other Contents/Personal Effects In Trunk Compartment/Cargo Area: <i>box of nails, lunch pail, screwdrivers</i>				
51	Trailer Hitch	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Factory <input type="checkbox"/>	Non-Factory <input type="checkbox"/>	Unknown <input type="checkbox"/>
	Trailer Wiring	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Factory <input checked="" type="checkbox"/>	Non-Factory <input checked="" type="checkbox"/>	Unknown <input type="checkbox"/>

Glass Condition

52	Windshield:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input checked="" type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>		
53	Electric Windows:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>						
54	Driver's Window:	Intact <input checked="" type="checkbox"/>	Up <input checked="" type="checkbox"/>	Down <input type="checkbox"/>	Missing <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	
	Position:	In <input type="checkbox"/>	Out <input type="checkbox"/>						
55	Left Rear Window:	Intact <input checked="" type="checkbox"/>	Up/Closed <input checked="" type="checkbox"/>	Down/Open <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input checked="" type="checkbox"/>		
	Position:	In <input type="checkbox"/>	Out <input type="checkbox"/>						
56	Vent/Triangle Position:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>		
57	Left Rear 3 rd Window:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>		
	Position:	In <input type="checkbox"/>	Out <input type="checkbox"/>	Open <input type="checkbox"/>	Closed <input type="checkbox"/>				
58	Rear Window Position:	Intact <input checked="" type="checkbox"/>	Open <input type="checkbox"/>	Closed <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input checked="" type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>
59	Right Rear 3 rd Window:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>		
	Position:	In <input type="checkbox"/>	Out <input type="checkbox"/>	Open <input type="checkbox"/>	Closed <input type="checkbox"/>				
60	Vent/Triangle Position:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input type="checkbox"/>		
61	Right Rear Window:	Intact <input checked="" type="checkbox"/>	Up/Closed <input checked="" type="checkbox"/>	Down/Open <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input checked="" type="checkbox"/>		
	Position:	In <input type="checkbox"/>	Out <input type="checkbox"/>						

VEHICLE FIRE INVESTIGATION 4

62	Passenger Window:	Intact <input type="checkbox"/>	Up <input checked="" type="checkbox"/>	Down <input type="checkbox"/>	Missing <input type="checkbox"/>	Stationary <input type="checkbox"/>	Moveable <input type="checkbox"/>	Cracked <input type="checkbox"/>	Broken <input checked="" type="checkbox"/>
	Position:	Melted/Cracked By Heat <input type="checkbox"/>							
		In <input checked="" type="checkbox"/>		Out <input type="checkbox"/>					
63	Sun Roof:	Open <input type="checkbox"/>	Closed <input type="checkbox"/>		Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>			
64	Convertible	Up <input type="checkbox"/>	Down <input type="checkbox"/>		Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>			
65	T-Top	On <input type="checkbox"/>	Missing <input type="checkbox"/>		Fire Damaged <input type="checkbox"/>				
66	Hard/Soft Top	On <input type="checkbox"/>	Missing <input type="checkbox"/>		Fire Damaged <input type="checkbox"/>				
67	Tonneau Cover/Fiberglass Cap	On <input type="checkbox"/>	Missing <input type="checkbox"/>		Fire Damaged <input type="checkbox"/>				

Under Vehicle

68	Gasoline <input checked="" type="checkbox"/>	Diesel <input type="checkbox"/>	Natural Gas <input type="checkbox"/>	Electric <input type="checkbox"/>	Hybrid <input type="checkbox"/>
69	1. Fuel Tank	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
70	1. Fill Pipe	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
71	1. Fuel Cap	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
72	2. Fuel Tank	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
73	2. Fill Pipe	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
74	2. Fuel Cap	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	
75	Transmission Pan	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Leakage Noted <input type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
76	Oil Pan	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Leakage Noted <input type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

NOTE: For Damage/Rust * L = Light M = Medium H = Heavy

Areas	Open	Closed	Missing	Rust*	Damage *	Vandalized	Consumed
77	Front Bumper						
78	Hood						
79	Grille		X				
80	Head Lights						+
81	Left Fender						X
82	Driver's Door						
83	Left Rear(sliding/cargo)Door(s)		X				
84	Left Quarter Panel		X				
85	Trunk Lid/Tail Gate						
86	Rear Cargo Door(s)		X				
87	Tail Lights						
88	Rear Bumper						
89	Roof						
90	Right Quarter Panel						
91	Right Rear(sliding/cargo)Door(s)						
92	Passenger Door		X				
93	Right Fender		X				
94	Running Boards/Step Bars						
95	Exterior Mirrors						

96 Body Condition: Excellent Good Fair Poor *dur. partially*

97 Plate on vehicle Yes No Plate Number _____

98 Evidence Confiscated: Yes No

Completed By: Devin Jackson

A SOS 11 06/29/2010 15:33:58 CCF/JAVAP1999/69_198_118_3/1.

53;1;1FTNX21S3YEA [REDACTED]

TITLE INFORMATION:

TITLE MAILED TO SECURED INTEREST HOLDER

2000 FORD	1FTNX21S3YE [REDACTED]	29 PICKUP	S TRANSFER
02/23/2006	128T0530773	SRW SUPER DUTY	169193 A

[REDACTED] N AND

REDFORD TWP [REDACTED]

FIRST CATHOLIC FCU
 9300 COOPER 02/22/2006
 TAYLOR 48146

** 06/12/2010 ABANDONED - CONFIRM WITH ENTERING JURISDICTION MI8269300 **

REGISTRATION INFORMATION:

[REDACTED]
 09/18/2010
 MI SOS

PC-RENEWAL
 H-630-603-085-724

VINquery.com Report - 6/29/2010

VIN #	1FTNX21S3YE [REDACTED]
VINquery.com Vehicle ID	21854
Model Year	2000
Make	Ford
Model	F-250 SD
Trim	Lariat SuperCab Long Bed 4WD
Manufactured In	UNITED STATES
Production Seq. Number	A27799
Specifications - General	
Body Style	EXTENDED CAB PICKUP 4-DR
Engine Type	6.8L V10 SOHC 20V
Transmission	4-Speed Automatic 5-Speed Manual 6-Speed Manual
Driveline	4WD
Tank(gallon)	38.00
Fuel Economy(City, miles/gallon)	No data
Fuel Economy(Highway, miles/gallon)	No data
Specifications - Chassis	
Anti-Brake System	2-Wheel ABS
Steering Type	Recirc
Brake Type(front)	Disc
Brake Type(rear)	Disc
Turning Diameter(in.)	50.40
Suspension(front)	Live
Suspension(rear)	Live
Spring Type(front)	Torsion Bar
Spring Type(rear)	Leaf
Tires	235/85R16
Specifications - Interior Dimensions	
Headroom(front, in.)	41.40
Headroom(rear, in.)	38.50
Legroom(front, in.)	40.70
Legroom(rear, in.)	32.40
Shoulder Room(front, in.)	68.00
Shoulder Room(rear, in.)	68.00
Hip Room(front, in.)	67.40
Hip Room(rear, in.)	67.30
Specifications - Colors	
Interior Trim	Medium Parchment Leather
Exterior Color	Black Clearcoat Black Clearcoat/Harvest Gold Clearcoat Metallic Bright Amber Clearcoat Metallic Bright Amber Clearcoat Metallic/Black Clearcoat Dark Toreador Red Clearcoat Metallic Dark Toreador Red Met/Black Clearcoat Deep Wedgewood Blue Clearcoat Metallic Deep Wedgewood Blue Met/Harvest Gold Clearcoat Metallic Harvest Gold Clearcoat Metallic Harvest Gold Clearcoat Metallic/Black Clearcoat Island Blue Island Blue/Harvest Gold Clearcoat Metallic Oxford White Clearcoat Oxford White Clearcoat/Harvest Gold Clearcoat Metallic Red Clearcoat Woodland Green Clearcoat Metallic Woodland Green Met/Harvest Gold Clearcoat Metallic
Specifications - Exterior Dimensions & Weight	
Curb Weight(automatic, lbs.)	5981
Curb Weight(manual, lbs.)	5935
Length(in.)	247.60
Width(in.)	79.90

Height(in.)	80.20
Wheelbase(in.)	158.00
Ground Clearance(in.)	8.30
Track(front, in.)	No data
Track(rear, in.)	No data

Specifications - Cargo Bed Dimensions

Length(in.)	98.60
Width at Wheelwell(in.)	50.90
Width at Wall(in.)	64.60
Depth(in.)	20.00

Specifications - Capacities

Seating(standard)	6
Seating(optional)	5
Volume(passenger, cu.ft.)	No data
Volume(cargo, cu.ft.)	No data
Towing(standard, lbs)	7400
Towing(maximum, lbs)	13700
Payload(standard, lbs)	2865
Payload(maximum, lbs)	2865
GVWR(standard, lbs)	8800
GVWR(maximum, lbs)	8800

Specifications - Warranty

Basic(duration, months)	36
Basic(distance, miles)	36,000
Powertrain(duration, months)	36
Powertrain(distance, miles)	36,000
Rust(duration, months)	60
Rust(distance, miles)	Unlimited

Specifications - Pricing

MSRP(USD)	\$29,895
Dealer Invoice(USD)	\$26,016
Destination Charge(USD)	No data

Equipment - Anti-Theft & Locks

Child Safety Door Locks	N/A
Locking Pickup Truck Tailgate	N/A
Power Door Locks	Std.
Vehicle Anti-Theft	N/A

Equipment - Braking & Traction

4WD/AWD	Std.
ABS(2-Wheel/4-Wheel)	Std.
Automatic Load-Leveling	N/A
Electronic Brake Assistance	N/A
Limited Slip Differential	Opt.
Locking Differential	N/A
Traction Control	N/A
Vehicle Stability Control System	N/A

Equipment - Safety

Driver Airbag	Std.
Front Side Airbag	N/A
Front Side Airbag with Head Protection	N/A
Passenger Airbag	Std.
Side Head Curtain Airbag	N/A
Second Row Side Airbag	N/A

Electronic Parking Aid	N/A
First Aid Kit	N/A
Trunk Anti-Trap Device	N/A
Equipment - Remote Controls & Release	
Keyless Entry	Opt.
Remote Ignition	N/A
Equipment - Climate Control	
Air Conditioning	Std.
Separate Driver/Front Passenger Climate Controls	N/A
Equipment - Interior Features	
Cruise Control	Std.
Tachometer	Std.
Tilt Steering Wheel	Std.
Tilt Steering Column	N/A
Heated Steering Wheel	N/A
Leather Steering Wheel	Opt.
Steering Wheel Mounted Controls	N/A
Telescopic Steering Column	N/A
Adjustable Foot Pedals	N/A
Genuine Wood Trim	N/A
Tire Inflation/Pressure Monitor	N/A
Trip Computer	N/A
Equipment - Storage	
Cargo Area Cover	Opt.
Cargo Area Tiedowns	N/A
Cargo Net	Opt.
Load Bearing Exterior Rack	Opt.
Pickup Truck Bed Liner	Opt.
Equipment - Roof	
Power Sunroof/Moonroof	N/A
Manual Sunroof/Moonroof	N/A
Removable/Convertible Top	N/A
Equipment - Entertainment, Communication & Navigation	
AM/FM Radio	Std.
Cassette Player	Std.
CD Player	Opt.
CD Changer	Opt.
DVD Player	N/A
Hands Free/Voice Activated Telephone	N/A
Navigation Aid	N/A
Second Row Sound Controls or Accessories	N/A
Subwoofer	N/A
Telematic Systems	N/A
Equipment - Seat	
Driver Multi-Adjustable Power Seat	Std.
Front Cooled Seat	N/A
Front Heated Seat	N/A
Front Power Lumbar Support	N/A
Front Power Memory Seat	N/A
Front Split Bench Seat	N/A
Leather Seat	Std.

Second Row Folding Seat	N/A
Second Row Heated Seat	N/A
Second Row Multi-Adjustable Power Seat	N/A
Second Row Removable Seat	N/A
Third Row Removable Seat	N/A

Equipment - Exterior Lighting

Automatic Headlights	N/A
Daytime Running Lights	Opt.
Fog Lights	Opt.
High Intensity Discharge Headlights	N/A
Pickup Truck Cargo Box Light	N/A

Equipment - Exterior Features

Bodyside/Cab Step or Running Board	Opt.
Front Air Dam	N/A
Rear Spoiler	N/A
Skid Plate or Underbody Protection	N/A
Splash Guards	Opt.
Wind Deflector or Buffer for Convertible	N/A
Power Sliding Side Van Door	N/A
Power Trunk Lid	N/A

Equipment - Wheels

Alloy Wheels	Std.
Chrome Wheels	N/A
Steel Wheels	Opt.

Equipment - Tires

Full Size Spare Tire	Std.
Run Flat Tires	N/A

Equipment - Windows

Power Windows	Std.
Glass Rear Window on Convertible	N/A
Sliding Rear Pickup Truck Window	Opt.
Privacy Glass or Deep Tinted Glass	Opt.

Equipment - Mirrors

Electrochromic Exterior Rearview Mirror	N/A
Heated Exterior Mirror	N/A
Electrochromic Interior Rearview Mirror	N/A
Power Adjustable Exterior Mirror	Opt.

Equipment - Wipers

Interval Wipers	N/A
Rain Sensing Wipers	N/A
Rear Wiper	N/A
Rear Window Defogger	N/A

Equipment - Towing

Tow Hitch Receiver	Opt.
Towing Preparation Package	N/A

Legends

Std. - Standard: indicates a manufacturer-installed feature that comes standard.
 Opt. - Optional: indicates a manufacturer-installed feature that does not come standard.
 N/A - Not Available: Indicates a feature that is not available as a manufacturer-installed item.

Disclaimer

ALTHOUGH VINQUERY.COM CHECKS REGULARLY WITH ITS DATA SOURCES TO CONFIRM THE ACCURACY AND COMPLETENESS OF THE DATA, IT MAKES NO GUARANTY OR WARRANTY, EITHER EXPRESS OR IMPLIED, INCLUDING

WITHOUT LIMITATION ANY WARRANTY OR MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE, WITH RESPECT TO THE DATA PRESENTED IN THIS REPORT. USER ASSUMES ALL RISKS IN USING ANY DATA IN THIS REPORT FOR HIS OR HER OWN APPLICATIONS. ALL DATA IN THIS REPORT ARE SUBJECT TO CHANGE WITHOUT NOTICE.

© 2006 - 2010 VINquery.com - Auto Databank, Inc. All rights reserved.



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

3 Record(s) Displayed.

Report Date : July 1, 2010 at 10:16 AM
 Search Type : VEHICLE
 Make: FORD
 Model or Model No.: F-250 SD
 Model Year: 2000

Make: FORD **Model:** F-250 SD
Model Year: 2000
Manufacturer: PRO-A MOTORS, INC. **Mfr's Report Date:** MAR 21, 2006
NHTSA CAMPAIGN ID Number: 06E026000 **NHTSA Action Number:** N/A
Component: EXTERIOR LIGHTING
Potential Number of Units Affected: 61944

Summary:

CERTAIN PRO-A MOTORS CORNER LAMPS, TURN SIGNALS, AND HEADLIGHTS SOLD AS REPLACEMENT LAMPS FOR USE ON CERTAIN PASSENGER VEHICLES LISTED ABOVE. SOME COMBINATION LAMPS THAT ARE NOT EQUIPPED WITH AMBER SIDE REFLECTORS FAIL TO CONFORM TO FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT.

Consequence:

WITHOUT THE AMBER REFLECTORS, THE VEHICLE WILL BE POORLY ILLUMINATED, POSSIBLY RESULTING IN A VEHICLE CRASH WITHOUT WARNING.

Remedy:

PRO-A MOTORS WILL NOTIFY OWNERS AND OFFER TO REPURCHASE THE LAMPS. THE RECALL BEGAN ON APRIL 3, 2006. OWNERS MAY CONTACT PRO-A MOTORS AT 323-838-2988.

Notes:

THIS RECALL ONLY PERTAINS TO PRO-A MOTORS AFTERMARKET LAMPS AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON THE LISTED PASSENGER VEHICLES. FOR MORE INFORMATION ON THE LAMP MODEL NUMBERS, CLICK ON DOCUMENT SEARCH AND VIEW DOCUMENT TITLED "LAMP MODEL NUMBERS." CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Make: FORD **Model:** F-250 SD
Model Year: 2000
Manufacturer: FORD MOTOR COMPANY **Mfr's Report Date:** DEC 03, 2007
NHTSA CAMPAIGN ID Number: 07V553000 **NHTSA Action Number:** EA06012
Component: ENGINE AND ENGINE COOLING:ENGINE:DIESEL
Potential Number of Units Affected: 1176000

Summary:

ON CERTAIN HEAVY DUTY TRUCKS EQUIPPED WITH 7.3L DIESEL ENGINES, THE CAMSHAFT POSITION SENSOR LOCATED ON THE ENGINE OF THE VEHICLE MAY FUNCTION INTERMITTENTLY, POSSIBLY RESULTING IN AN ENGINE STALL.

Consequence:

IN THE EVENT OF AN ENGINE STALL, A CRASH COULD RESULT WITHOUT WARNING.

Remedy:

DEALERS WILL INSPECT THE SENSOR AND REPLACE IT WITH AN IMPROVED CAMSHAFT POSITION SENSOR FREE OF CHARGE. THE RECALL BEGAN ON DECEMBER 29, 2007. OWNERS MAY CONTACT FORD AT 1-866-436-7332.

Notes:

FORD RECALL NO. 07S57. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Make: FORD

Model: F-250 SD

Model Year: 2000

Manufacturer: FORD MOTOR COMPANY

Mfr's Report Date: OCT 09, 2009

NHTSA CAMPAIGN ID Number: 09V399000

NHTSA Action Number: EA08021

Component: VEHICLE SPEED CONTROL

Potential Number of Units Affected: 4500000

Summary:

FORD IS RECALLING MODEL YEARS 1995-2003 WINDSTAR, 2000-2003 EXCURSION DIESEL, 1993-1997 AND 1999-2003 F-250 SD THROUGH F-550 SD DIESEL, 1992-2003 E-150 THROUGH E-550, 1995-2002 EXPLORER, 1997 AND 2002 MERCURY MOUNTAINEER, 1995-1997 AND 2001-2003 RANGER, AND 1994 F53 VEHICLES EQUIPPED WITH THE TEXAS INSTRUMENTS SPEED CONTROL DEACTIVATION SWITCH (SCDS). THE SCDS MAY LEAK INTERNALLY AND THEN OVERHEAT, SMOKE, OR BURN.

Consequence:

A VEHICLE FIRE COULD OCCUR WITH OR WITHOUT THE ENGINE RUNNING.

Remedy:

FORD WILL NOTIFY OWNERS THAT DEALERS WILL INSTALL A FUSED WIRING HARNESS IN LINE WITH THE SCDS. ON 1999-2003 WINDSTAR VEHICLES WITH A LEAKING SCDS, DEALERS WILL ALSO INSPECT THE ABS CONTROL MODULE CONNECTOR AND REPAIR AS NECESSARY. REPAIRS WILL BE COMPLETED FREE OF CHARGE. THE SAFETY RECALL BEGAN ON OCTOBER 27, 2009. OWNERS MAY CONTACT FORD AT 1-888-222-2751.

Notes:

FORD'S RECALL CAMPAIGN NUMBER IS 09S09. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).



OFFICE OF DEFECTS INVESTIGATION (ODI)

Defects - Search Results

3 Record(s) Displayed.

<p>Report Date : July 1, 2010 at 10:17 AM Search Type : VEHICLE Year : 2000 Make : FORD Model : F-250 SD</p>
--

NHTSA Action Number:

EA05005

NHTSA Recall Campaign Number:

7 recalls found

Make: FORD

Model: F-250 SD

Manufacturer : FORD MOTOR COMPANY

Year : 2000

Component :

VEHICLE SPEED CONTROL:CRUISE CONTROL
 ELECTRICAL SYSTEM:WIRING:FRONT UNDERHOOD

Date Investigation Opened : March 22, 2005

Date Investigation Closed : August 2, 2006

Summary:

EA05-005 IS CLOSED WITH FORD'S ACTIONS IN RECALLS 05V-017, 05V-388, AND 06V-286, RECALLING APPROXIMATELY 6.7 MILLION VEHICLES EQUIPPED WITH TEXAS INSTRUMENTS SPEED CONTROL DEACTIVATION SWITCHES (SCDS). THE BRAKE SYSTEMS IN THESE RECALLED VEHICLES GENERATE A VACUUM THAT CAN POTENTIALLY CAUSE THE SCDS TO FAIL AND, IN CERTAIN SWITCH INSTALLATION ORIENTATIONS, CATCH FIRE. FORD IS ALSO INCLUDING THE ENTIRE POPULATION OF 1998 EXPLORERS. FORD HAS INFORMED ODI THAT TESTING TO DETERMINE THE CAUSE OF FAILURES IN THE 1998 EXPLORERS WILL CONTINUE AFTER THIS INVESTIGATION IS CLOSED. ODI BELIEVES THAT THE VEHICLES EXHIBITING THE FACTORS CAUSING SCDS FAILURE DESCRIBED IN THIS REPORT CORRELATE WELL WITH THE OBSERVED FAILURE RATES ON THESE VEHICLES BY MODEL AND MODEL YEAR. THE CLOSING OF THIS INVESTIGATION DOES NOT CONSTITUTE A FINDING BY NHTSA THAT A SAFETY-RELATED DEFECT DOES NOT EXIST IN THE NON-RECALLED VEHICLES MANUFACTURED WITH SCDS THAT ARE NOT INCLUDED IN FORD'S RECALLS. ODI WILL CONTINUE TO MONITOR THE NON-RECALLED POPULATION FOR INCIDENCE OF ENGINE COMPARTMENT FIRES. THE AGENCY RESERVES THE RIGHT TO TAKE FURTHER ACTION IF WARRANTED BY THE CIRCUMSTANCES. SEE ATTACHED CLOSING REPORT FOR DETAILS.

NHTSA Action Number:

PE06011

NHTSA Recall Campaign Number:

N/A

Make: FORD

Model: F-250 SD

Manufacturer : FORD MOTOR COMPANY

Year : 2000

Component :

ENGINE AND ENGINE COOLING:ENGINE:DIESEL

Date Investigation Opened : February 27, 2006

Date Investigation Closed : June 23, 2006

Summary:

THE CAM POSITION SENSOR (CPS) PROVIDES A CRITICAL SIGNAL TO THE SUBJECT VEHICLE (SV) ENGINE MANAGEMENT SYSTEM, THE LOSS OF WHICH RESULTS IN AN ENGINE STALL. DURING PE06-011, FORD STATED IN THEIR RESPONSE TO ODI THAT IT IS CONTINUING TO INVESTIGATE ALLEGATIONS OF CPS

THESE PRODUCTS WERE NOT FORMALLY WITHIN SCOPE OF THE INVESTIGATION WHEN FAILURE INFORMATION WAS REQUESTED. WARRANTY DATA ANALYSIS INDICATES THAT ABOUT HALF THE CLAIMS INVOLVED A STALL WHILE DRIVING EVENT (FORD'S ASSESSMENT) AND THAT POOR CPS DURABILITY WAS A LONGSTANDING CONCERN. FORD REPORTED THAT THE NEW CPS DESIGN SHOULD MEET OR EXCEED THEIR 10 YEAR, 150K MILE LIFE EXPECTANCY DESIGN REQUIREMENT.



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

[Vehicle Level](#) → [Technical Service Bulletins](#) → [Recalls](#) → [Generals](#) ←

Generals
Information

<u>Number</u>	<u>Date</u>	<u>▼ Title</u>
99B28	12/01/1999	Campaign - Engine Oil Cooler Inspection/Replacement
00B53	10/01/2000	Campaign - Front Driveshaft Replacement
98B29	01/01/1999	Campaign - GEM Module Replacement
02L08	02/01/2002	Campaign - Missing Engine Information label

© 2010 ALLDATA LLC. All rights reserved.
[Terms of Use](#)



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference | Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

Vehicle Level → Technical Service Bulletins → Recalls → Safety ←

Safety

Information

<u>Number</u>	<u>Date</u>	<u>Title</u>
<u>05S28S15</u>	<u>04/10/2008</u>	<u>Recall - Cruise Control Deactivation Switch Inspection</u>
<u>09S09</u>	<u>10/13/2009</u>	<u>Recall - Cruise Control Deactivation Switch Overheating</u>
<u>01S24</u>	<u>08/01/2001</u>	<u>Recall - Defective Wiper Motor Switch/Gear Cover</u>
<u>99S32</u>	<u>11/01/1999</u>	<u>Recall - Fuel System Integrity</u>
<u>02L11</u>	<u>10/01/2002</u>	<u>Recall - Lug Nut Procedure and Torque Specification</u>
<u>00S21</u>	<u>10/01/2000</u>	<u>Recall - Seat Belt Buckle Inspection/Replacement</u>
<u>NHTSA00V170000</u>	<u>06/15/2000</u>	<u>Recall 00V170000: Master Cylinder Pushrod Retaining Clip</u>
<u>NHTSA00V228001</u>	<u>08/11/2000</u>	<u>Recall 00V228001: Seat Belt Buckle Defect</u>
<u>NHTSA01V258000</u>	<u>08/03/2001</u>	<u>Recall 01V258000: Wiper Motor Gear Case Cover</u>
<u>NHTSA 06V286000</u>	<u>07/27/2006</u>	<u>Recall 06V286000: Cruise Control Switch Fire Hazard</u>
<u>NHTSA07V336000</u>	<u>08/02/2007</u>	<u>Recall 07V336000: Cruise Control Fire Hazard</u>
<u>NHTSA09V399000</u>	<u>10/09/2009</u>	<u>Recall 09V399000: Cruise Control Deactivation Switch</u>
<u>NHTSA99V265000</u>	<u>09/16/2000</u>	<u>Recall 99V265000: Accelerator Cable and Throttle Body</u>

© 2010 ALLDATA LLC. All rights reserved.
[Terms of Use](#)



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference | Component Search:



▼ Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

[Vehicle Level](#) → [Technical Service Bulletins](#) → [All Technical Service Bulletins](#) ←

All Technical Service Bulletins

Information

<u>Number</u>	<u>Date</u>	<u>Title</u>
04-18-5	09/20/2004	4X4 System - Front Hubs Won't Lock/Disengage
06-21-19	10/30/2006	A/C - Heater Core Electrolysis/Leakage
99-19-6	09/20/1999	A/C - Identification of Non Approved Refrigerants
99-24-6	11/29/1999	A/C - Thumping Noise On Cold Engine Start-up
02-20-8	10/14/2002	A/C System - Diagnosis and Service Tips
00-24-4	11/27/2000	A/T - (4R100) Fluid Overheats, Updated Cooler
99-21-11	10/18/1999	A/T - 4R100 Orange Service Tag Service Procedure
03-26-1	01/12/2004	A/T - 4R70W Needle Bearing/Race Kit Service Tip
03-14-8	07/21/2003	A/T - Cooler Flushing Service Tips
00-23-10	11/13/2000	A/T - In Line Fluid Filter Kit
02-17-6	09/02/2002	A/T - Inadvertent Shift Interlock Disabling
06-14-4	07/24/2006	A/T - Mercon V ATF Usage
02-21-1	10/28/2002	A/T - Torque Converter Access Plug Dislodges
00-9-1	05/01/2000	A/T Cooler - Fluid Leaks at Radiator
02-11-4	06/10/2002	Aluminum Engine - New Cleaners/Service Tips
02-16-4	08/19/2002	Audio System - Whining/Buzzing Noise From Speakers
07-5-8	03/19/2007	Battery - Battery Eye Function/Charging/Service
01-10-11	05/28/2001	Bi Fuel System - Component Identification
01-21-4	10/29/2001	Bi-Fuel - Lock Off Solenoid/Tank Valve Coil Resistance
01-10-6	05/28/2001	Bi-Fuel System - Compuvalve Replacement

<u>04-18-11</u>	<u>09/20/2004</u>	<u>Body - Corrosion At Bottom of Door or Tailgate</u>
<u>03-23-2</u>	<u>11/24/2003</u>	<u>Body - Exterior Mirror Glass/Motor Service Tips</u>
<u>06-26-5</u>	<u>01/08/2007</u>	<u>Body - Running Board Corrosion</u>
<u>04-23-9</u>	<u>11/29/2004</u>	<u>Body - Water Leaks From Roof Flange Area</u>
<u>99-25-6</u>	<u>12/13/1999</u>	<u>Brake Rotor - Incorrect Discard Thickness Specification</u>
<u>03-19-10</u>	<u>09/29/2003</u>	<u>Brakes - Vehicle Pulls Left/Right on Braking</u>
<u>99-19-4</u>	<u>09/20/1999</u>	<u>Brakes - Vibration/Inspection Service Tips</u>
<u>99B28</u>	<u>12/01/1999</u>	<u>Campaign - Engine Oil Cooler Inspection/Replacement</u>
<u>00B53</u>	<u>10/01/2000</u>	<u>Campaign - Front Driveshaft Replacement</u>
<u>98B29</u>	<u>01/01/1999</u>	<u>Campaign - GEM Module Replacement</u>
<u>02L08</u>	<u>02/01/2002</u>	<u>Campaign - Missing Engine Information label</u>
<u>06-8-5</u>	<u>05/01/2006</u>	<u>Cruise Control - Diagnostic Updates</u>
<u>01-20-5</u>	<u>10/15/2001</u>	<u>Driveability - Vacuum Leak Detection</u>
<u>03-14-3</u>	<u>07/21/2003</u>	<u>Drivetrain - 4X4 Hub Non-Engagement/Disengagement</u>
<u>06-23-4</u>	<u>12/06/2006</u>	<u>Drivetrain - Drive-Away Shudder/Vibration</u>
<u>03-4-1</u>	<u>03/03/2003</u>	<u>Drivetrain - Front Locking Hub Service Tips</u>
<u>03-11-2</u>	<u>06/09/2003</u>	<u>Drivetrain - Hub/Bearing Rocking End-Play Measurement</u>
<u>99-23-4</u>	<u>11/15/1999</u>	<u>EVAP - DTC's P0442/P0455/MIL ON/No Driveability Concerns</u>
<u>05-18-7</u>	<u>09/22/2005</u>	<u>Electrical - Wiring Soldering/Crimping Service Tips</u>
<u>03-20-3</u>	<u>10/13/2003</u>	<u>Emissions - MIL ON/DTC's Stored/Check Fuel Cap Lamp ON</u>
<u>01-9-7</u>	<u>05/14/2001</u>	<u>Emissions/Engine Controls - Driveability Diagnosis</u>
<u>02-2-3</u>	<u>02/04/2002</u>	<u>Engine - Aluminum Block/Head Machining</u>
<u>07-15-2</u>	<u>08/06/2007</u>	<u>Engine - Cylinder Head Spark Plug Thread Repair</u>
<u>02-21-13</u>	<u>10/28/2002</u>	<u>Engine - Cylinder Head Straightedge Surface Check</u>
<u>01-24-6</u>	<u>12/10/2001</u>	<u>Engine - Oil System Priming Procedures</u>
<u>06-18-16</u>	<u>09/18/2006</u>	<u>Engine - Reman Engine Head Gasket Identification</u>

- 00-26-1 12/25/2000 Engine - Rough Idle/Noise When Cold
- 07-21-2 10/29/2007 Engine - Spark Plug Hole Thread Repair Procedure
- 04-24-14 12/13/2004 Engine Controls - General PCM Programming Procedures
- 04-17-4 09/06/2004 Engine Controls - MIL ON/Lean DTC Service Tips
- 03-9-11 05/12/2003 Engine Controls - Rough Idle/Hesitation
- 01-23-6 11/26/2001 Engine Coolant - Propylene Glycol Recommendations
- 02-1-4 01/21/2002 Engine Head Gasket - Approved Replacement Procedures
- 02-1-9 01/21/2002 Engine Oil - Oil Recommendations/Applications
- 01-1-3 01/22/2001 Exhaust System - 'Miss' Sound From Exhaust
- 01-4-9 03/05/2001 Front Brakes - Pad/Caliper Rattle on Bumps
- 99-26-9 12/27/1999 Fuel Economy - Customer Expectation vs. Vehicle Usage
- 01-7-3 04/16/2001 Fuel Pump - Whine Heard Through Radio Speakers
- 01-19-4 10/01/2001 Hood Lamp Switch - Updated Replacement Part
- 01-21-13 10/29/2001 Ignition Switch - High Turning Effort/MIL ON/DTC's Set
- 05-22-8 11/14/2005 Ignition System - Coil-On-Plug Misfire Diagnostic Tips
- 07-4-3 03/05/2007 Interior - Leather Wrapping On Steering Wheel Is Loose
- 06-15-8 08/07/2006 Keyless Entry - Keypad Diagnostics
- 03-18-1 09/15/2003 Keyless Entry System - Service Tips
- 01-10-1 05/28/2001 LPG - Parameter Identification Data Input and Output
- 06-17-7 09/04/2006 Lighting - Addition of Bulbs to Turn/Hazard Flashers
- 99-24-2 11/29/1999 Locks - Lock Service Packages Available
- 06-26-1 01/08/2007 M/T - Mercon(R) V ATF Usage Information
- 02-2-1 02/04/2002 PCM - Low Power In Reverse Gear
- 01-1-6 01/22/2001 PCM - MIL ON, DTC's P0350/P0360 Set
- 05S28S15 04/10/2008 Recall - Cruise Control Deactivation Switch Inspection

- 09S09 10/13/2009 Recall - Cruise Control Deactivation Switch Overheating
- 01S24 08/01/2001 Recall - Defective Wiper Motor Switch/Gear Cover
- 99S32 11/01/1999 Recall - Fuel System Integrity
- 02L11 10/01/2002 Recall - Lug Nut Procedure and Torque Specification
- 00S21 10/01/2000 Recall - Seat Belt Buckle Inspection/Replacement
- NHTSA00V170000 06/15/2000 Recall 00V170000: Master Cylinder Pushrod Retaining Clip
- NHTSA00V228001 08/11/2000 Recall 00V228001: Seat Belt Buckle Defect
- NHTSA01V258000 08/03/2001 Recall 01V258000: Wiper Motor Gear Case Cover
- NHTSA 06V286000 07/27/2006 Recall 06V286000: Cruise Control Switch Fire Hazard
- NHTSA07V336000 08/02/2007 Recall 07V336000: Cruise Control Fire Hazard
- NHTSA09V399000 10/09/2009 Recall 09V399000: Cruise Control Deactivation Switch
- NHTSA99V265000 09/16/2000 Recall 99V265000: Accelerator Cable and Throttle Body
- 05-3-10 02/21/2005 Restraints - Seat Belt Stop Button Service
- 05-16-11 08/22/2005 Restraints - Seat Belts Slow to Retract
- 00-14-2 07/10/2000 Speedometer Defective., 4X4 Lamp ON, DTCs P1635/P1639
- 03-20-5 10/13/2003 Starting System - No Start/Repeat Starter Failure
- 06-19-14 10/02/2006 Starting System- No Crank Condition
- 07-1-7 01/22/2007 Steering - Mercon V(R) Fluid Usage
- 07-11-10 06/11/2007 Steering/Brakes - Brake Pedal Kick-Back/Grabbing
- 01-3-2 02/19/2001 Steering/Suspension - Stiff, Wandering
- 04-23-6 11/29/2004 Suspension - Vehicle Leans/Sags To One Side
- 02-3-5 02/18/2002 Tailgate - Squeaking/Binding Condition
- 01-5-3 03/19/2001 Trailer Tow Wiring - Difficult To Locate
- 02-1-6 01/21/2002 Wheels/Tires - Road Force Measurement Equipment
- 01-10-12 05/28/2001 Wire Harness - Terminal Repair Kit

© 2010 ALldata LLC. All rights reserved.
Terms of Use

Select Vehicle | New TSBs | Technician's Reference Component Search: 

 Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

Vehicle Level → Technical Service Bulletins → Superceded Bulletins ←

Superceded Bulletins

Information

<u>Number</u>	<u>Date</u>	<u>Title</u>
<u>05S28S11</u>	<u>08/03/2007</u>	<u>05S28S11 - 08/03/07</u>
<u>05S28S12</u>	<u>08/20/2007</u>	<u>05S28S12 - 08/20/07</u>
<u>00-3-8</u>	<u>02/07/2000</u>	<u>A/T - E4OD/4R100 Fluid In-Line Filter Kit</u>
<u>00-2-2</u>	<u>01/24/2000</u>	<u>A/T - E4OD/4R100 In Line Filter Kit Tips</u>
<u>01-15-7</u>	<u>08/06/2001</u>	<u>A/T - Fluid Application Charts</u>
<u>00-1-5</u>	<u>01/10/2000</u>	<u>A/T - New Transmission Cooler Flusher/Service Tip</u>
<u>06-4-2</u>	<u>03/06/2006</u>	<u>Battery - Battery EYE Function/Charging Service Tips</u>
<u>02-4-5</u>	<u>02/15/2002</u>	<u>Battery - Charging Tips and Guidelines</u>
<u>05-9-18</u>	<u>05/16/2005</u>	<u>Battery - Service/Charging Tips</u>
<u>05-17-6</u>	<u>09/05/2005</u>	<u>Drivetrain - Drive Away Shudder/Vibration</u>
<u>04-22-7</u>	<u>11/15/2004</u>	<u>Drivetrain - Driveaway Shudder or Vibration</u>
<u>04-11-6</u>	<u>06/08/2004</u>	<u>Drivetrain - Front Hubs Won't Engage/Stay Engaged</u>
<u>01-7-8</u>	<u>04/16/2001</u>	<u>EVAP System - MIL ON Multiple DTC's Set</u>
<u>03-11-6</u>	<u>06/09/2003</u>	<u>Electrical - Wiring Soldering/Crimping Tips</u>
<u>03-9-8</u>	<u>05/12/2003</u>	<u>Emissions - MIL ON/EVAP System DTC's Set</u>
<u>02-20-2</u>	<u>10/14/2002</u>	<u>Engine - Cylinder Head Straightedge Flatness Check</u>
<u>01-4-7</u>	<u>03/05/2001</u>	<u>Engine - Oil Recommendations/Applications</u>
<u>04-21-7</u>	<u>11/01/2004</u>	<u>Engine Controls - General PCM Reprogramming Procedures</u>
<u>99-22-4</u>	<u>11/01/1999</u>	<u>Front Wipers - Operate While Switch Is In Off Position</u>
<u>99-24-3</u>	<u>11/29/1999</u>	<u>Front Wipers - Operate While Switch is in OFF Position</u>

- 01-15-6 08/06/2001 Heater Core - Repeated Failure
- 03-14-4 07/21/2003 Ignition System - Engine Misfire Diagnostic Tips
- 04-16-1 08/23/2004 Ignition System - Engine Misfire Diagnostics Tips
- 06-14-12 07/24/2006 Lighting - Adding Additional Turn Signal/Hazard Bulbs
- 04-18-15 09/20/2004 Lighting - Addition of Hazard/Turn Signal Bulbs
- 02-21-9 10/28/2002 Lighting - Additional Turn Signal/Hazard Flasher Bulbs
- 00-8-6 04/17/2000 Locking Hubs - Service Tip
- 04-26-2 12/31/2004 Parking Assist System - False Tone Activation
- 99-26-6 12/27/1999 Passive Antitheft System (PATS) - Diagnostics Tips
- 05S28S8 08/03/2006 Recall - Cruise Control Deactivation Switch Defects
- 05S28S10 03/02/2007 Recall - Cruise Control Deactivation Switch/Fire Hazard
- 05S28S13 09/05/2007 Recall - Cruise Control Switch Circuit Defect
- 05S28S14 01/28/2008 Recall - Speed Control Deactivation Switch Defects
- 05S28S9 08/28/2006 Recall - Speed Control System Modification
- 04-24-21 12/13/2004 Restraint System - Seat Belts Slow to retract
- 01-18-1 09/17/2001 Shift Interlock (BRAKE) - Inadvertent Disabling
- 02-19-4 09/30/2002 Starting System - Starter Failure/Ignition Lock Sticking
- 04-24-3 12/13/2004 Steering - Leather Coming Loose From Steering Wheel
- 01-16-8 08/20/2001 Turn Signals/Hazard Flashers - Bulb Addition
- 99-22-2 11/01/1999 Wire Harness - Terminal Repair Kit/Wire Splice Procedure

© 2010 ALLDATA LLC. All rights reserved.
Terms of Use



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN 5

[Vehicle Level](#) → [Technical Service Bulletins](#) → [Recalls](#) → [Safety](#) → [Recall - Cruise Control Deactivation Switch Inspection](#) → [Important Reminder Customer Letter - Truck](#) ←

Important Reminder Customer Letter - Truck

Recall - Cruise Control Deactivation Switch Inspection

Safety Recall 05S28-S15 - Truck Vehicle Owners

April 2008

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

******* IMPORTANT REMINDER *******

Service parts are now available to perform the necessary repairs to your vehicle.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has previously sent you letters indicating that a defect which relates to motor vehicle safety exists in your speed control equipped vehicle. This condition may result in a vehicle fire, even if the vehicle is parked, even if you have never used your speed control. We apologize for this situation and for our previous lack of repair parts and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support.

What is the issue? Ford cannot be confident that over many years in service, the type of Speed Control Deactivation Switch (SCDS) installed on your vehicle will not leak, posing the risk of an underhood fire. This condition may occur either when the vehicle is parked or when it is being operated, even if the speed control is not in use.

What will Ford and your dealer do? Ford Motor Company has authorized your dealer to perform the repairs under this program free of charge (parts and labor). If you had the Interim Repair (Speed Control System disconnect) performed, the final repair will restore operation of the speed control system. If your dealer has recently completed the final repair on your vehicle for this recall, please disregard this letter.

How long will it take? Your dealer may be able to perform this repair while you wait; however, due to scheduling requirements, your dealer may need your vehicle for a longer period of time.

What are we asking you to do? We urge you to contact your dealer as soon as possible to schedule an appointment to have this service performed. Provide the dealer with the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed near your name at the beginning of this letter.

Zoom

Sized for Print



© 2010 ALLDATA LLC. All rights reserved.
[Terms of Use](#)



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference

Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

[Vehicle Level](#) → [Technical Service Bulletins](#) → [Recalls](#) → [Safety](#) → [Recall - Cruise Control Deactivation Switch Inspection](#) → [Owner Letter](#) ←

Owner Letter

Recall - Cruise Control Deactivation Switch Inspection

August 2, 2007

Mr. Daniel C. Smith
Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Mr. Smith:

Subject: Ford Recall No. 06S28

Summary

- **Ford Action** - Ford is recalling certain 1998-2002 model year Ford Ranger, 1992-1998 Ford Crown Victoria, Mercury Grand Marquis and Lincoln Town Car, 1993-1998 Lincoln Mark VIII, 1993-1995 Ford Taurus SHO with automatic transmission, 1994 Mercury Capri, 1999-2001 Ford Explorer and Mercury Mountaineer, 2001-2002 Ford Explorer Sport and Explorer Sport Trac, 1992-1993 and 1997-2003 Ford E-150-360 gasoline or natural gas vehicles, 2003 E-450 gasoline or natural gas vehicles, 1993 Ford Bronco, 1993 Ford F-Series gasoline or natural gas vehicles, 1995-2002 Ford F63 Motorhome chassis, and 2003-2004 Ford F-150 Lightning vehicles equipped with speed control.
- **Number of Vehicles Involved** - Ford estimates that there are approximately 3.6 million vehicles currently registered in the United States and Federalized Territories.
- **Effect on Vehicle Operation** - The speed control deactivation switch may, under certain conditions, leak internally and then overheat, smoke, or burn.
- **Service Procedure** - Owners of the trucks and SUV's included in the action will be instructed to return their vehicles to dealers for installation of a fused wiring harness to eliminate the potential risk of fire. Owners of the passenger cars included in this action will be instructed to return their vehicles to their dealers to have the speed control deactivation switch disconnected as an interim repair. As soon as repair parts are available (expected October, 2007) owners will be instructed to return to the dealers for installation of a fused wiring harness.

Attached is the detailed information required by the applicable portions of 49 CFR Part 573 - Defect and Non-Compliance Information Report.

Sincerely,

James P. Vondale
Attachment

Zoom

Sized for Print

ATTACHMENT

49 CFR Part 573 -- DEFECT INFORMATION REPORT -- FORD RECALL 05S28

Pursuant to Part 573 of Title 49 of the Code of Federal Regulations, Defect and Noncompliance Reports, Ford Motor Company (Ford) submits the following information concerning a safety recall action that it is voluntarily initiating.

573.6 (c) (2) - Potentially Affected Vehicles

Approximately 3.6 million potentially affected vehicles are currently registered in the U.S. and Federalized Territories. Those vehicles are certain 1993-2002 model year Ford Ranger, 1992-1998 Ford Crown Victoria, Mercury Grand Marquis and Lincoln Town Car, 1993-1998 Lincoln Mark VIII, 1993-1995 Ford Taurus SHO with automatic transmission, 1994 Mercury Capri, 1999-2001 Ford Explorer and Mercury Mountaineer, 2001-2002 Ford Explorer Sport and Explorer Sport Trac, 1992-1993 and 1997-2003 Ford E-150-350 gasoline or natural gas vehicles, 2003 E-450 gasoline or natural gas vehicles, 1993 Ford Bronco, 1993 Ford F-Series gasoline or natural gas vehicles, 1995-2002 Ford F53 Motorhome chassis, and 2003-2004 Ford F-150 Lightning vehicles equipped with speed control.

Vehicles	MY	Assembly Plant	Beginning	End
Ranger	1993-2002	Twin Cities	5/7/1997	8/10/2002
Ranger	1993-2002	Edison	4/8/1997	8/27/2002
Ranger	1993-1999	Louisville	4/25/1997	4/1/1999
Town Car	1992-1998	Wixom	11/5/1991	2/28/1998
Crown Victoria	1992-1998	St. Thomas	2/5/1992	2/28/1998
Grand Marquis	1992-1998	St. Thomas	2/5/1992	2/28/1998
Mark VIII	1993-1998	Wixom	6/18/1992	6/26/1998
Taurus SHO A/T	1993-1995	Atlanta	4/23/1992	6/15/1995
Explorer/Mountaineer	1999-2001	Louisville	6/16/1998	9/27/2000
Explorer/Mountaineer	1999-2001	St. Louis	6/23/1998	12/24/2000
Explorer Sport	2001-2002	Louisville	9/24/1999	8/18/2002
Explorer Sport Trac	2001-2002	Louisville	9/24/1999	8/16/2002
E150-E350	1992-1993	Lorain	4/22/1991	8/31/1993
E150-E350	1997-2002	Lorain	4/9/1996	8/2/2002
E150-E450	2003	Lorain	8/5/2002	12/31/2002
F-Series	1993	Ontario	8/24/1992	8/24/1993
F-Series	1993	Kansas City	8/8/1992	8/21/1993
F-Series	1993	Michigan	5/29/1992	8/13/1993
F-Series	1993	Norfolk	7/27/1992	8/2/1993
Bronco	1993	Michigan	5/28/1992	8/13/1993
F-53 Motorhome (TY1)	1995-1997	Monterrey/Immsa	7/12/1994	12/19/1997
F-53 Motorhome (P131)	1998-2000	Monterrey/Immsa	10/6/1997	12/17/1999
F-53 Motorhome (P131)	2001-2002	Detroit Chassis	11/8/1999	12/27/2002
Capri	1994	Broad Meadows Plant 2	6/11/1993	7/13/1994
F-150 Lightning	2003-2004	Ontario	11/5/2002	5/18/2004

Zoom

Sized for Print

Because these vehicles are not produced in VIN order, information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-800-392-3873) or by contacting a local Ford dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

573.6 (c) (3) - Estimated Population of Vehicles Potentially Affected

Ford estimates that there are approximately 3.6 million potentially affected vehicles currently registered in the United States and Federalized Territories.

573.6 (c) (4) - Estimated Percentage of Affected Vehicles with the Defect Condition

Unknown.

573.6 (c) (5) - Description of the Defect

Ford has previously recalled vehicles that were equipped with the Texas Instruments speed control deactivation switch. The vehicles previously recalled contain a specific combination of factors that may cause a switch that is powered at all times to be more likely to leak and develop increased electrical resistance and potential for fire.

Vehicles addressed by this action are not affected by the combination of factors that were in vehicles previously recalled. Rather, the reports appear to relate to leakage in the switch due to long term durability performance issues. Although the rate of alleged speed control deactivation switch fires on these vehicles is extremely low, customers continue to be concerned about the safety of their vehicles. Therefore, Ford is initiating a recall on these remaining vehicles to address ongoing customer concerns even though the vehicles included in this action are not affected by the combination of factors related to the previous actions.

573.8 (c) (6) - Chronology of Events

In February, 2007 Ford began investigating reports of underhood fires in the affected vehicles as a result of an increasing number of reports. Ford was also contacted by the National Highway Traffic Safety Administration (NHTSA) in March, 2007 regarding some of these reports. These reports involved vehicles with more than 13 years in service indicating that a long term durability issue may be affecting the speed control switch. Our investigation found these vehicles do not contain the established combination of factors that can result in a Texas Instruments switch being susceptible to developing a leak. Rather, the reports appear to relate to long term durability performance of the Texas Instruments switch which may result in leakage causing increased electrical resistance within the leaking switch, and the potential for an unattended vehicle fire.

Ford currently lacks the experience and data concerning the longer term durability of the speed control deactivation switch in vehicles with more than 15 years in service. Accordingly, to address ongoing customer concerns with the switch, Ford is taking this action to add a two amp fuse in the speed control deactivation switch circuit or replace the switch with a new generation switch if the previous switch was leaking to protect against extremely long term durability issues.

A

This action will be taken on all remaining vehicles that use a previous generation speed control deactivation switch that is powered at all times.

Zoom

Sized for Print

Select Vehicle | New TSBs | Technician's Reference Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

Vehicle Level → Technical Service Bulletins → Recalls → Safety → Recall - Cruise Control Deactivation Switch Overheating → Dealer Letter ←

Dealer Letter

Recall - Cruise Control Deactivation Switch Overheating

TO: All U.S. Ford and Lincoln Mercury Dealers

October 13, 2009

SUBJECT: Safety Recall 09S09
Certain 1992-2003 Model Year Vehicle Lines
Speed Control System Modification

AFFECTED VEHICLES

Due to the complexity and the number of vehicles involved, please refer to Attachment IV for Affected Vehicle Applications. Affected vehicles are identified in OASIS. In addition, for a list of vehicles assigned to your dealership, visit <https://web.fsavinlists.dealerconnection.com>. This information will be available by October 15, 2009.

REASON FOR THIS SAFETY RECALL

In some of the affected Windstar vehicles, the Speed Control Deactivation Switch (SCDS) may overheat, smoke, or burn, which could result in an underhood fire. The potential for a switch fire exists in these vehicles regardless of whether speed control is being used. In addition, on 1999-2003 Windstar vehicles only, brake fluid may migrate from a leaking SCDS to the anti-lock brake system (ABS) module, creating the potential for melting or fire at the ABS module regardless of whether the engine is running or power is present.

As a result of the Windstar investigation, Ford reviewed all remaining Texas Instruments Speed Control Deactivation Switches in vehicles not previously recalled. These other vehicles use the Texas Instrument SCDS as a redundant speed control device, ABS signal input, or for parts commonality. All of these vehicles have been in service for many years and most continue to have no fire allegations. However, Ford is taking action on all of these vehicles to address customers' lack of confidence in the perceived long term durability of their vehicles.

SERVICE ACTION

Dealers are to inspect the Speed Control Deactivation Switch (SCDS) harness connector for the presence of brake fluid contamination. If no brake fluid is present, dealers are to install the universal fused jumper harness. If brake fluid is present, dealers are to replace the SCDS and check for related damage as instructed in Attachment III - Technical Information. This service must be performed on all affected vehicles at no charge to the vehicle owner. Owners are being advised to park their vehicle outdoors away from structures until the recall service is performed to prevent a potential fire from spreading.

OWNER NOTIFICATION MAILING SCHEDULE

Owners of affected vehicles will be notified by mail beginning late October 2009 and ending early December 2009. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

Zoom

Sized for Print

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$6,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Affected Vehicle Applications
Attachment V: Dealer Q & A
Owner Notification Letter
Recall Reimbursement Plan

QUESTIONS & ASSISTANCE

Special Service Support Center (Dealer Only)

Sincerely,



Michael A. Berardi

Zoom

Sized for Print



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

[Vehicle Level](#) → [Technical Service Bulletins](#) → [Recalls](#) → [Safety](#) → [Recall 06V286000: Cruise Control Switch Fire Hazard](#) ←

Recall 06V286000: Cruise Control Switch Fire Hazard

MAKE/MODELS: MODEL/BUILD YEARS:

Ford/E450 1996-2002

Ford/Econoline 1994-1996

Ford/Excursion 2000-2002

Ford/Explorer 1998

Ford/F250 1994-2002

Ford/F350 1994-2002

Ford/F450 1994-2002

Ford/F550 1994-2002

Ford/Mountaineer 1998

MANUFACTURER: Ford Motor Company

NHTSA CAMPAIGN ID NUMBER: 06V286000 MFG'S REPORT DATE: July 27, 2006

COMPONENT: Vehicle Speed Control

POTENTIAL NUMBER OF UNITS AFFECTED: 1200000

SUMMARY:

On certain trucks equipped with speed control, gasoline or natural gas engines, the speed control deactivation switch may overheat.

CONSEQUENCE:

Overheat could result in smoke, or burn and in an underhood fire.

REMEDY:

Dealers will install a fused wiring harness into the speed control system free of charge. The recall is expected to begin on August 7, 2006. Owners may contact Ford at 1-866-436-7332.

NOTES:

Ford recall No. 05S28. Customers may also contact The National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.



[Home](#) | [Account](#) | [Contact ALLDATA](#) | [Log Out](#) | [Help](#)

HERNDON & ASSOCIATES

Select Vehicle | New TSBs | Technician's Reference Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

[Vehicle Level](#) → [Technical Service Bulletins](#) → [Recalls](#) → [Safety](#) → [Recall 06V286000: Cruise Control Switch Fire Hazard](#) ←

Recall 06V286000: Cruise Control Switch Fire Hazard

MAKE/MODELS: MODEL/BUILD YEARS:

Ford/E450 1996-2002

Ford/Econoline 1994-1996

Ford/Excursion 2000-2002

Ford/Explorer 1998

Ford/F250 1994-2002

Ford/F350 1994-2002

Ford/F450 1994-2002

Ford/F550 1994-2002

Ford/Mountaineer 1998

MANUFACTURER: Ford Motor Company

NHTSA CAMPAIGN ID NUMBER: 06V286000 MFG'S REPORT DATE: July 27, 2006

COMPONENT: Vehicle Speed Control

POTENTIAL NUMBER OF UNITS AFFECTED: 1200000

SUMMARY:

On certain trucks equipped with speed control, gasoline or natural gas engines, the speed control deactivation switch may overheat.

CONSEQUENCE:

Overheat could result in smoke, or burn and in an underhood fire.

REMEDY:

Dealers will install a fused wiring harness into the speed control system free of charge. The recall is expected to begin on August 7, 2006. Owners may contact Ford at 1-866-436-7332.

NOTES:

Ford recall No. 05S28. Customers may also contact The National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.

© 2010 ALldata LLC. All rights reserved.
[Terms of Use](#)

Select Vehicle | New TSBs | Technician's Reference | Component Search:



Conversion Calculator

2000 Ford Truck F 250 4WD Super Duty V10-6.8L VIN S

Vehicle Level → [Technical Service Bulletins](#) → [Recalls](#) → [Safety](#) → [Recall 07V336000: Cruise Control Fire Hazard](#) ←

Recall 07V336000: Cruise Control Fire Hazard

MAKE/MODELS: MODEL/BUILD YEARS:

Ford/Bronco 1993

Ford/Crown Victoria 1992-1998

Ford/E-150 1997-2002

Ford/E-250 1997-2002

Ford/E-350 1997-2002

Ford/E150 1992-1993 2003

Ford/E250 1992-1993 2003

Ford/E350 1992-1993 2003

Ford/E450 2003

Ford/Explorer 1999-2001

Ford/Explorer Sport 2001-2002

Ford/Explorer Sport Trac 2001-2002

Ford/F-150 Lightning 2003-2004

Ford/F150 1993

Ford/F250 1993

Ford/F350 1993

Ford/F450 1993

Ford/F53 1995-2002

Ford/Ranger 1998-2002

Ford/Taurus SHO 1993-1995

Lincoln/Mark VIII 1993-1998

Lincoln/Town Car 1992-1998

Mercury/Capri 1994

Mercury/Grand Marquis 1992-1998

Mercury/Mountaineer 1999-2001

MANUFACTURER: Ford Motor Company

NHTSA CAMPAIGN ID NUMBER: 07V336000 MFR'S REPORT DATE: August 02, 2007

COMPONENT: Vehicle Speed Control

POTENTIAL NUMBER OF UNITS AFFECTED: 3600000

SUMMARY:

On certain pickup trucks, passenger vehicles, sport utility vehicles, and motor homes chassis, the speed control deactivation switch may, under certain conditions, leak internally and then overheat, smoke, or burn.

CONSEQUENCE:

This could result in an underhood fire.

REMEDY:

Dealers will install a fused wiring harness. Owners of the passenger cars included in this campaign will be instructed to return their vehicles to their dealers to have the speed control deactivation switch disconnected as an interim repair. As soon as repair parts are available (expected October 2007), owners will be instructed to return to the dealers for installation of a fused wiring harness. The recall is expected to begin on August 13, 2007, and mailing completed by September 19, 2007. Owners may contact Ford at 1-800-392-3673.

NOTES:

Ford recall No. 05S28S11. Customers may also contact The National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.

© 2010 ALldata LLC. All rights reserved.
[Terms of Use](#)

CONSEQUENCE:

A vehicle fire could occur.

REMEDY:

Ford will notify owners and dealers will install a fused wiring harness for the SCDS. Dealers will also inspect the ABS control connector and repair as necessary. Repairs will be completed free of charge. The safety recall is expected to begin on or about October 26, 2009. Owners may contact Ford at 1-800-392-3673.

NOTES:

Ford's recall campaign number is 09S09. Owners may also contact The National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.



1. A view of the public Vehicle Identification Number.

2. A view of the front of the vehicle.





3. A view of the driver's side from the left front.

4. A view of the left front tire and wheel fire damaged.






5. A view of the left rear.


6. A view of the right rear.






7. A view of the aftermarket wiring spliced into the factory trailer wiring.

8. A view of the trailer wiring.





9. A view of the bed of the truck.


10. A view of the passenger's side from the right rear.





13. Another view of the driver's side.


14. A view of the fuel cap intact.





15. A view of the underside from front to rear.

16. Another view of the underside from front to rear.





17. A view of the inside of the right front tire.

18. A view of the inside of the left front tire.






21. A view of the rear passenger compartment from the driver's side.

22. A view of the front passenger compartment from the driver's side.






23. A view of the dashboard from the driver's side.

24. A view of the rear passenger compartment from the passenger's side.






25. A view of the dashboard and front passenger compartment from the passenger's side.


26. A view of the top of the dashboard and cowl area.






29. A view of the engine compartment from the front.


30. A view of the engine compartment from the passenger's side.






31. A view of the passenger's side of the engine compartment from the front.


32. A view of the engine compartment from the driver's side.






33. A view of the driver's side of the engine compartment from the front.

34. A view of the windshield wiper motor assembly.






35. A view of the battery and battery cables in the right front.


36. A view of the solenoid in the inner right fender.





37. A view of the alternator and associated wiring.


38. A view of the lower radiator hose and transmission cooler hoses.






39. A view of the power steering cooler hoses fire damaged in the left front.

40. A view of the inside of the radiator fire damaged.





41. A view of the fuel lines and connections at the rear of the engine.


42. A view of the fuse relay center on the left or driver's side.






45. A view of the left valve cover.


46. A view of the transmission fluid full.





47. A view of the oil overfull on the dipstick.

48. A view of the brake booster with the master cylinder destroyed by the fire.



Redford MF



US Department of Transportation
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382
Official Business
Penalty for Private Use \$300

5155

BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO. 1888 WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

**US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-210
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382**

