

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

23-JUN-2010

Repository ☐

Reference No.
10339771

OWNER INFORMATION (Type or Print)

Name

Address

City

CINCINNATI

State

OH

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1GTGK13U61F

Make

GMC

Model

SIERRA 2500 HD

Model Year

2001

Date Purchased

9/29/01

Dealer's Name and Telephone Number

Holman Motors Inc

Engine:

No: Cylinders

8

Fuel Type:

Reg
Gas

Original Owner

☒

Dealer's City

BATAVIA

State

OH

Zip Code

45103

Transmission Type

Automatic

☒ Antilock Brakes

☒ Cruise Control

Powertrain

Multiple Failure:

Continual
near collision

Incident Date(s)

31-AUG-2009

21 Sept 2010

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Codes: 030000 SERVICE BRAKES, HYDRAULIC, 036000 SERVICE BRAKES, HYDRAULIC: ANTILOCK

Failure Mileage

160000

Failure Speed

0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment

☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2001 GMC SIERRA 2500 HD. THE CONTACT STATED THAT THE VEHICLE WAS PREVIOUSLY SERVICED FOR AN UNKNOWN FRONT WHEEL SPEED SENSOR RECALL BY AN AUTHORIZED DEALER. UPON RECEIVING THE VEHICLE FROM THE AUTHORIZED DEALER THE ABS AND BRAKE LIGHTS CONTINUED TO ILLUMINATE ON THE DASHBOARD. ON A SEPARATE OCCASION, THE ABS AND BRAKE WARNING LIGHTS ILLUMINATED ON THE DASHBOARD AND THE STOPPING DISTANCE OF THE VEHICLE WAS ABNORMALLY INCREASED. ACCORDING TO THE RECALL, THE REPAIR WAS TO DECREASE STOPPING DISTANCE AND CORRECT THE ILLUMINATION OF THE WARNING LIGHTS. THE VEHICLE WAS TAKEN BACK TO THE DEALER WHERE THE BRAKES WERE CHECKED AND LUBRICATED. THE FAILURE CONTINUED TO RECUR AND THE CONTACT STATED WHEN DRIVING ON ROUGH SURFACES, THE STOPPING DISTANCE WAS SEVERELY INCREASED. THE FAILURE MILEAGE WAS 160,000 AND THE CURRENT MILEAGE WAS 183,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Fwd: FW: NHTSA: Follow up to ODI Complaint: 10339771

From: [REDACTED]

To: [REDACTED]

Subject: Fwd: FW: NHTSA: Follow up to ODI Complaint: 10339771

Date: Thu, Oct 28, 2010 6:35 am

Attachments: EVOQEMAILRESPONSE.doc (53K), 10339771.pdf (54K)

From: EVOQ@dot.gov

To: [REDACTED]

Sent: 10/26/2010 8:39:40 A.M. Eastern Daylight Time

Subj: FW: NHTSA: Follow up to ODI Complaint: 10339771

Please see the attached copy of your recent complaint and instructions. Please make any necessary edits and return via email to dataquality@dot.gov or fax to (202) 366-1767. Due to the volume of complaints we receive and our limited resources, we can not respond to every complaint.

NHTSA/Office of Defects Investigation



Dealer: HOLMAN MOTORS, INC.
4337 ELICK LN
BATAVIA OH 45103
(513) 752-3123

1GTGK13U61F [REDACTED]
[REDACTED]
CINCINNATI OH [REDACTED]

THIS SERVICE WILL BE PERFORMED AT **NO CHARGE** TO THE OWNER.



[REDACTED]
AS A VALUED GMC OWNER, WE WANT TO LET YOU
KNOW THAT GM IS COMMITTED TO QUALITY PRODUCTS AND
CUSTOMER SATISFACTION.

ACCORDING TO OUR RECORDS, AS OF MAY 5, 2007, SERVICE
HAS NOT YET BEEN COMPLETED FOR THE FOLLOWING OPEN RECALL(S) FOR
YOUR GMC 1GTGK13U61F [REDACTED]

05068 FRONT WHEEL SPEED SENSOR CORROSION



369294-4444 00000119348

If you no longer own this vehicle for any of the reasons listed on the attached Owner Reply Card, please update the card and drop it into any mailbox.