

INFORMATION Redacted PURSUANT TO THE FREEDOM OF



U.S. Department of Transportation
National Highway Traffic Safety Administration

INFORMATION ACT (FOIA) 5 U.S.C. 552(B)(6)

Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

AGENCY USE ONLY 100148

Date Received: **MAR 23 2012**

Repository:

Reference No.: 10450541

06-MAR-2012

OWNER INFORMATION (Type or Print)

Name: [REDACTED]

Address: [REDACTED]

City: DROVEPORT *Groveport* State: OH Zip Code: [REDACTED]

Daytime Telephone Number: [REDACTED]

Evening Telephone Number: [REDACTED]

E-mail Address: [REDACTED]

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side: 1N6BA06A05N [REDACTED]

Make: NISSAN Model: TITAN Model Year: 2005

Date Purchased: *3-10-07* Dealer's Name and Telephone Number: *Germain Nissan 614-800-914-5103* Engine: No: Cylinders: *8* Fuel Type: *Flex fuel*

Original Owner: Dealer's City: *COLUMBUS* State: *OH* Zip Code: *43230*

Transmission Type: *AUTO* Antilock Brakes Powertrain: Multiple Failure: Incident Date(s): *11-JAN-2012*

Cruise Control

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 110000 ELECTRICAL SYSTEM

This is the date when we were finally given a copy of recall and realized the danger of problem - we knew about recall after purchase.

Failure Mileage: 70959 Failure Speed: [REDACTED]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make: [REDACTED] Tire Model (Name or Number): [REDACTED] Tire Size (Example P215/65R15): [REDACTED]

DOT No. (Example: DOTM19ABC036): [REDACTED] Original Equipment Prior Repair Failure Location: [REDACTED]

Tire Component Code: [REDACTED] Tire Failure Type: [REDACTED]

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: [REDACTED] Date Manufactured: [REDACTED] Model No./Name: [REDACTED]

Seat Type: [REDACTED] Installation System: [REDACTED]

Child Seat Component Code: [REDACTED] Failed Part: [REDACTED]

APPLICABLE INCIDENT INFORMATION
(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash: Yes No Fire: Yes No

Number of Persons Injured: [REDACTED] Number of Deaths: [REDACTED] Reported to Police: N

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2005 NISSAN TITAN. THE CONTACT STATED THAT THE AIRBAG WARNING LIGHT WAS ILLUMINATED. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN ID NUMBER: 06V459000 (ELECTRICAL SYSTEM). THE CONTACT STATED THAT THE FAILURE WAS CAUSED BY THE FAILURE OF THE WIRING HARNESS. THE VEHICLE WAS TAKEN TO AN AUTHORIZED DEALER WHERE THEY ADVISED THAT THE VIN WAS NOT INCLUDED IN THE RECALL. THE CONTACT WAS CONCERNED THAT THE AIRBAGS COULD POSSIBLY DEPLOY WITHOUT WARNING DUE TO THE FAILURE OF THE WIRING HARNESS. THE VEHICLE WAS NOT REPAIRED. THE FAILURE MILEAGE WAS 70,959 AND THE CURRENT MILEAGE WAS 72,006.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Build DATE 10-05

Contact ALLDATA | Log Out | Help

HOFFMAN AUTO REPAIR
HOFFMAN AUTO RE00003

TSBs | Technician's Reference | Component Search:

Conversion Calculator

Truck Titan 2WD V8-5.6L (VK56)

Systems → Air Bag Systems → Technical Service Bulletins → Recalls → Recall

06V459000: Seat Belt Wire Harness Modification

Recall 06V459000: Seat Belt Wire Harness Modification

MAKE/MODELS: MODEL/BUILD YEARS:

Nissan/Titan 2004-2006

MANUFACTURER: Nissan North America, Inc.

NHTSA CAMPAIGN ID NUMBER: 06V459000 MFG'S REPORT DATE: November 22, 2006

COMPONENT: Electrical System

POTENTIAL NUMBER OF UNITS AFFECTED: 96500

SUMMARY:

On certain crew cab trucks, the wires in the harness were routed through the rear doors and into the body. These wires may break due to over bending of the harness as the door is opened and closed. The harness contains wires for the driver seat belt pretensioner and for the front passenger seat belt which is part of the occupant classification system. Wires for the rear audio speakers are also contained in the harness.

CONSEQUENCE:

If the wires for the seat belts and speaker wires break and make contact, there is a possibility that the pretensioner may deploy. If this happens when the seat belt is retracted, it will not be possible to use the seat belt. If one of the wires on the right side harness for the seat belt tension sensor breaks, the passenger side front air bag will not deploy as designed in a frontal collision increasing the risk of a crash and personal injury.

REMEDY:

Dealers will replace the wire harness cover with a different type that prevents over bending of the harness and the harness will be rerouted free of charge. The recall is expected to begin on or about February 19, 2007. owners may contact Nissan at 1-800-647-7261.

NOTES:

Customers may also contact The National Highway Traffic Safety Administration's