


| | | | | | |
|--|---|---|--|--|----------------------------|
|  <p>U.S. Department of Transportation National Highway Traffic Safety Administration</p> | | <p>INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6) DOT Auto Safety Hotline</p> <p>Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline</p> | | <p>FOR AGENCY USE ONLY 100148</p> | |
| <p>OWNER INFORMATION (Type or Print)</p> | | <p>Date Received JUL - 2 2012</p> | | <p>Repository <input type="checkbox"/></p> | |
| <p>Name [REDACTED]</p> | | <p>27-MAR-2012</p> | | <p>Reference No. 10453222</p> | |
| <p>Address [REDACTED]</p> | | <p>Daytime Telephone Number [REDACTED]</p> | | <p>E-mail Address</p> | |
| <p>City ROCKVILLE State MD Zip Code [REDACTED]</p> | | <p>Evening Telephone Number</p> | | | |
| <p><i>The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).</i></p> | | | | | |
| VEHICLE INFORMATION | | | | | |
| <p>17 digit Vehicle Identification Number Located at bottom of windshield on driver's side KMHDN46D35U [REDACTED]</p> | | <p>Make HYUNDAI</p> | <p>Model ELANTRA</p> | <p>Model Year 2005</p> | |
| <p>Date Purchased 8/2005</p> | <p>Dealer's Name and Telephone Number Fitzgerald White Flint, MD</p> | | | <p>Engine: No: Cylinders</p> | <p>Fuel Type:</p> |
| <p>Original Owner <input checked="" type="checkbox"/></p> | <p>Dealer's City Rockville, MD</p> | <p>State</p> | <p>Zip Code 20852</p> | | |
| <p>Transmission Type <input type="checkbox"/> Antilock Brakes <input type="checkbox"/> Cruise Control</p> | <p>Powertrain</p> | <p>Multiple Failure:</p> | | <p>Incident Date(s) 01-FEB-2012</p> | |
| FAILED COMPONENT(S)/PART(S) INFORMATION | | | | | |
| <p>Vehicle Component Code: 140000 AIR BAGS</p> | | | | <p>Failure Mileage 51000</p> | <p>Failure Speed 0</p> |
| ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE | | | | | |
| <p>Tire Make</p> | | <p>Tire Model (Name or Number)</p> | | <p>Tire Size (Example P215/65R15)</p> | |
| <p>DOT No. (Example: DOTM19ABC036)</p> | | <p><input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair</p> | <p>Failure Location:</p> | | |
| <p>Tire Component Code</p> | | | | <p>Tire Failure Type:</p> | |
| ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE | | | | | |
| <p>Make:</p> | | <p>Date Manufactured:</p> | | <p>Model No./Name:</p> | |
| <p>Seat Type:</p> | | <p>Installation System:</p> | | | |
| <p>Child Seat Component Code:</p> | | <p>Failed Part:</p> | | | |
| APPLICABLE INCIDENT INFORMATION | | | | | |
| <i>(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)</i> | | | | | |
| <p>Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> | <p>Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> | <p>Number of Persons Injured</p> | <p>Number of Deaths</p> | <p>Reported to Police N</p> | |
| <p>Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).</p> | | | | | |
| <p>TL* THE CONTACT OWNS A 2005 HYUNDAI ELANTRA. THE CONTACT STATED THAT WHILE PARKED, THE AIR BAG LIGHT ILLUMINATED ON THE INSTRUMENT PANEL. THE VEHICLE WAS TAKEN TO THE DEALER FOR A DIAGNOSTIC TEST. THE TECHNICIAN STATED THAT THE SEAT SENSOR ON THE PASSENGER SIDE WOULD HAVE TO BE REPLACED. THERE WAS A RECALL UNDER NHTSA CAMPAIGN ID NUMBER 11V179000 (AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE), THAT MAY BE RELATED TO THE FAILURE. THE MANUFACTURER STATED THAT THE VEHICLE WAS NOT INCLUDED IN THE RECALL. THE VEHICLE WAS REPAIRED. THE APPROXIMATE FAILURE MILEAGE WAS 51,000.</p> | | | | | |
| <p>Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.</p> | | | <p>ATTACH ADDITIONAL SHEETS IF NECESSARY</p> | | |
| <p>The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.</p> | | | | | |

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

(3/8/12) Auto CENTRO (Attachment I) Air bag sensor failure - Code B1448 - Only Hyundai dealer has equipment to reset. Airbag light once repaired. Must go to dealer (attachment 2) 3/13/12. Called Hyundai (800-633-5151) 3/8/12 & 3/14/12 spoke to supv. Jim ID # 54206, case # 4754203 Consumer Assistance Center. They do not recognize this as a problem for recall. I mentioned to them that based on mileage of 51,000+ & previous recalls of elentra's for the years - 2007-2008, 2009 (attachment 3) for a similar problem, they should have a recall or campaign on the 2005. Furthermore, the web site "About Automobile" shows other consumer complaints on the 2005 elentra airbag failure. Air Bag failure at 51,000 miles should not be happening. ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department of Transportation

National Highway Traffic Safety Administration

1200 New Jersey Avenue SE, Washington, D.C. 20077-9382

Official Business
Penalty for Private Use \$300



NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO. 1888 WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

**US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-210
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382**



Think your vehicle has a safety defect?



**If so:
Use the enclosed form to file a report.**

**or visit:
www.safercar.gov**

**or call:
Vehicle Safety Hotline
888-327-4236**



Vehicle Owner's Questionnaire (VOQ)
U.S. Department of Transportation
National Highway Traffic Safety Administration



113

DUPLICATE

AUTO CENTRO INC.

Import Specialists Sales and Service
7420 Westmore Rd
Rockville MD, 20850
Phone: 301-340-2444
Fax: 301-610-7098

"We are proud to be rated
BEST by Washington Consumer
Check Book" Integrity Since 1977
www.autocentroimports.com
License# 737

Date: Mar 08, 2012 Service Writer: TSW Work Order #: 40,273

Name: [Redacted]
Address: [Redacted]

Make: 2005 HYUNDAI
Model: ELANTRA 2.0L A/T
Engine: 4-1975 2.0L DOHC
Plate: [Redacted]
VIN: KMHDN46D35U [Redacted]
Odometer In/Out: 51,519/51,522

Phone#: [Redacted] Home [Redacted] Work [Redacted]
Driver: [Redacted]

| Status | Tech | Description | Part Number | Qty | Price \$ | Hours | Rate \$ | Total \$ |
|----------|------|--|----------------|------|----------|-------|------------------|----------|
| JC | | Perform Airbag System Mal-Function Diagnostic | | | \$89.98 | | | 44.99 |
| JC | | Code found: B1448 - Needs RF pass occupamcy-sensor | | | | | | |
| | | | | | | | Service Subtotal | 44.99 |
| JC | | Perform Check Engine Light System Diagnostic | | | | | | 89.98 |
| JC | | Code Found: P0172 Performed Intake smoke test- NPF | | | | | | |
| | | | | | | | Service Subtotal | 89.98 |
| Replaced | IRB | 3k Minor Service --- STD | | | | | | 26.99 |
| | | Oil Filter (15400PLMA01) | 3312 | 1.00 | 7.25 | | | 7.25 |
| | | 5W30 Engine Oil | 5W30 | 4.10 | 4.25 | | | 17.42 |
| | | Hazardous Waste Disposal | | 1.00 | 1.50 | | | 1.50 |
| | | Windshield Washer Solvent | WASHER SOLVENT | 1.00 | 2.16 | | | 2.16 |
| | | Drain Plug-Washer | DRAIN PLUG | 1.00 | .95 | | | .95 |
| | | MICRO-EDGE BLADE - left | 40720A | 1.00 | 11.42 | | | 11.42 |
| | | | | | | | Service Subtotal | 67.69 |
| | IRB | Replace a/c belt | | | | .60 | 89.98 | 53.99 |
| | | Multi Rib Belt | 4PKX855 | 1.00 | 18.95 | | | 18.95 |
| | | Shop Supplies | | | 2.04 | | | 2.04 |

Comment: May need check engine light repairs if light returns. RF tire and alignment needed.
Lower center trans. mount has slight crack. Steering rack is leaking. Airbag system needs RF passenger occupancy sensor.

Payments: Total Paid: \$0.00 Balance: \$0.00

213 Fitzgerald AUTO MALLS

FitzMall.com SINCE 1966

FITZGERALD'S LAKEFOREST HYUNDAI-SUBARU
905 N. Frederick Avenue
Gaithersburg, MD 20879
(301) 670-7070



Visit us at our website: www.FitzMall.com

CELL: [REDACTED]

| | | | | | |
|--|---|------------------------------|--------------------------|----------------------------------|----------------------------------|
| CUSTOMER NO. 44019 | ADVISOR JOSHUA KRUMPACH | 524 | TAG NO. 1800 | INVOICE DATE 03/15/12 | INVOICE NO. HYCS308028 |
| [REDACTED] ROCKVILLE, MD [REDACTED] | LABOR RATE | LICENSE NO. | MILEAGE 51,688 | COLOR SILVER/GRAY | STOCK NO. |
| | YEAR / MAKE / MODEL 05/HYUNDAI/ELANTRA/GLS AUTO | | | DELIVERY DATE 08/29/05 | DELIVERY MILES 21 |
| | VEHICLE I.D. NO. K M H D N 4 6 D 3 5 U [REDACTED] | | | SELLING DEALER NO. | PRODUCTION DATE |
| | F. T. E. NO. | | P. O. NO. | | R. O. DATE 03/13/12 |
| RESIDENCE PHONE [REDACTED] | BUSINESS PHONE | COMMENTS E# BPP NO | | | MO: 51688 |

JOB# 1 CHARGES

| | |
|--|---------------|
| LABOR | 285.00 |
| J# 1 440LZ *BODY ELECTRICAL UNITS: TECH(S):0599 | |
| CUSTOMER STATES THE AIR BAG LIGHT IS ON \$114.95 PERFORMED SYSTEM TEST AND FOUND CODE B1448 OCS MAT DEFECT INSPECTED AND FOUND INTERNAL FAILURE IN THE SENSOR REPLACE SEAT BOTTOM | |
| PARTS | |
| QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE- | |
| 1 88200-2D800-FAL CUSHION ASSY-FRON | 420.31 |
| TOTAL - PARTS | 420.31 |
| JOB# 1 TOTALS | |
| LABOR | 285.00 |
| PARTS | 420.31 |
| JOB# 1 JOURNAL PREFIX HYCS JOB# 1 TOTAL | 705.31 |

FOR YOUR INFORMATION AND ACKNOWLEDGEMENT:

TERMS AND CONDITIONS FOR VEHICLE REPAIR ORDERS & INVOICES

PAYMENT TERMS: We only accept cash, check, Visa, Master Card, Discover or American Express Bank Cards for payment. No credit will be extended.

Full payment is due immediately upon completion of work.

We reserve the right to require a reasonable deposit for parts and labor.

We charge interest at .04% per day on amounts past due more than 30 days under this repair order. You agree to pay a storage charge of \$45.00 per day beginning 48 hours after completion of work.

You agree to pay all costs of collecting any amounts due under this repair order including reasonable attorney fees.

Unless full payment is received within 30 days from completion of work your vehicle may be sold under the Uniform Commercial Code of this State to pay any charges due.

You consent to reasonable use of the vehicle for the purpose of inspecting, testing, and repairing it.

NOTICE TO OUR CUSTOMERS

Please note that we are not liable to you for any casualty loss you may sustain when it is in for service should it be stolen or damaged by persons not employed by this dealership.

We commit to you to deliver the highest quality repairs and service to your vehicle and commit to take the required level of care to ensure the safekeeping of your vehicle and protections thereof from the damaging acts of third parties not employed by us. Should your vehicle be damaged despite our best efforts, your resort will be to your own vehicle insurance provider. Should you wish to know the extent of our insurance coverage for these facilities and our repair operations ask your service sales representative or his/her supervisor. You agree to be bound by the Fitzgerald Loaner Car Program Agreement and the Vehicle Use Agreement if you or your agent accepts a Loaner Car to use while we are repairing your vehicle.

We warrant that the parts and labor provided under this Repair Order will be free of defects in material and workmanship for 90 days or 4000 miles from when we return your vehicle to you. Any defects in parts or labor covered by this warranty shall only be corrected at this location and is limited to repair or replacement of the defective parts and labor. No other express warranties are provided.

By signing below you waive the requirement to test drive the vehicle.

Labor is charged by flat rate manual unless you agree that labor will be charged by clock hour.

A charge equivalent to 10% of total repair order is included for environmental, disposal and misc. charges used on your vehicle.

Manufacturer Special Policy Adjustment Programs

Federal law requires manufacturers to furnish the National Highway Traffic Safety Administration (N.H.T.S.A.) with bulletins describing any defects in their vehicles. You may obtain copies of these bulletins from either the Manufacturer or N.H.T.S.A. In addition, certain consumer publications or organizations publish this information, which may be available for a fee or for free.

TOTALS

| | |
|--|---------------------------------------|
| THANK YOU FOR VISITING FITZGERALD AUTOMALL | TOTAL LABOR 285.00 |
| QUESTIONS OR COMMENTS? | TOTAL PARTS 420.31 |
| PLEASE CALL ME DIRECT AT 301-670-4800 | TOTAL SUBLET 0.00 |
| THANK YOU. | TOTAL G.O.G. 0.00 |
| TONY PEARSON, SERVICE MANAGER 301-670-4800 | TOTAL MISC CHG. 0.00 |
| JOHN SARTORI, BODY SHOP MANAGER 301-670-4800 | TOTAL MISC DISC 0.00 |
| | TOTAL TAX 25.22 |
| | TOTAL INVOICE \$ 730.53 |

PLEASE NOTE THAT WHILE YOUR VEHICLE IS ON OUR PREMISES, WE MAY NOT BE RESPONSIBLE FOR ANY DAMAGE TO YOUR VEHICLE UNDER CERTAIN CIRCUMSTANCES. PLEASE ASK ONE OF OUR REPRESENTATIVES ABOUT THE EXTENT OF OUR RESPONSIBILITY, INCLUDING OUR INSURANCE COVERAGE.

CUSTOMER SIGNATURE _____

X

CUSTOMER'S SIGNATURE
NO CLAIMS WITHOUT THIS INVOICE
THANK YOU

CUSTOMER PAYMENT

() CASH () CHECK NO.
() CHARGE () CREDIT CARD

CASHIER SIGNATURE _____

PAYMENT DATE ____ / ____ / ____

CUSTOMER CALLED: BY _____

DATE _____ TIME _____

The Reynolds and Reynolds Company F2001 REV. 11.24.08 C2192980 Q (12/09) ERALZHRNE


[Log in](#) | [Register](#)


373

[Write a Review](#) [Read Reviews](#) [Cars For Sale](#) [Consumer Resources](#) [Dealer Services](#) [About Us](#)

Hyundai ELANTRA Recalls

Recalls for the Hyundai ELANTRA

Listed below are the known recalls for the **Hyundai ELANTRA**.

[Ask a Hyundai Mechanic](#) A Hyundai Mechanic Will Answer Now! Questions Answered Every 9 Seconds. [Hyundai.JustAnswer.com](#)

[2012 Hyundai Accent Deals](#) Find out our Lowest Possible Price on an All-New 2012 Hyundai Accent! [Hyundai.CarPriceSecrets.com](#)

[Buy Used at CarMax](#) Shop Smart. Thousands of Cars to Choose from at No-Haggle Prices! [www.CarMax.com](#)

[All Choices](#)

By Year: [2009](#) | [2008](#) | [2007](#) | [2006](#) | [2005](#) | [2004](#) | [2003](#) | [2002](#) | [2001](#) | [2000](#) | [1999](#) | [1997](#) | [1996](#) | [1995](#) | [1994](#) |

2009 Hyundai ELANTRA Recall

Item Affected: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE
Date Announced: 3/3/2011

Description of Recall:

HYUNDAI IS RECALLING CERTAIN MODEL YEAR 2007-2009 ELANTRA VEHICLES MANUFACTURED FROM JULY 14, 2006, THROUGH NOVEMBER 1, 2008. THE FRONT PASSENGER SEATS IN THE VEHICLES CONTAIN A WEIGHT SENSOR DESIGNED TO DEACTIVATE THE RIGHT FRONTAL AIRBAG WHEN OCCUPANTS OF CERTAIN WEIGHTS OCCUPY THE SEAT. THE ELECTRICAL CONNECTOR FOR THE WEIGHT SENSOR IS LOCATED UNDER THE CENTER CONSOLE, BETWEEN THE FRONT SEATS. UNDER CERTAIN CIRCUMSTANCES THE CONNECTOR COULD BECOME CONTAMINATED AND MALFUNCTION SUCH THAT THE FRONT PASSENGER AIRBAG WILL DEPLOY REGARDLESS OF THE WEIGHT OF THE OCCUPANT.

Action Needed To Fix It:

DEALERS WILL INSTALL A PROTECTIVE COVER OVER THE WEIGHT CLASSIFICATION SYSTEM CONNECTOR TO PREVENT CONTAMINATION. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTING TO BEGIN DURING APRIL 2011. OWNERS MAY CONTACT HYUNDAI'S CUSTOMER ASSISTANCE CENTER AT 1-800-633-5151.

Find your local [Hyundai Dealer](#).

2008 Hyundai ELANTRA Recall

Item Affected: FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP
Date Announced: 8/25/2008

Description of Recall:

HYUNDAI IS RECALLING 65,000 MY 2008 ELANTRA VEHICLES WITH 2.0 LITER BETA ENGINES. THE FUEL PUMP MOTOR MAY NOT HAVE THE PROPER UNIFORM INTERNAL ELECTRICAL SURFACE CONTACT. THIS MAY CAUSE THE FUEL PUMP TO PRODUCE LESS PUMPING PRESSURE THAN REQUIRED TO SUPPLY THE FUEL INJECTION SYSTEM.

Action Needed To Fix It:

DEALERS WILL REPLACE THE FUEL PUMP SUBASSEMBLY FREE OF CHARGE. THE RECALL BEGAN ON SEPTEMBER 15, 2008. OWNERS MAY CONTACT HYUNDAI AT 1-800-633-5151.

Find your local [Hyundai Dealer](#).

2008 Hyundai ELANTRA Recall

Item Affected: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE
Date Announced: 3/3/2011

Description of Recall:

HYUNDAI IS RECALLING CERTAIN MODEL YEAR 2007-2009 ELANTRA VEHICLES MANUFACTURED FROM JULY 14, 2006, THROUGH NOVEMBER 1, 2008. THE FRONT PASSENGER SEATS IN THE VEHICLES CONTAIN A WEIGHT SENSOR DESIGNED TO DEACTIVATE THE RIGHT FRONTAL AIRBAG WHEN OCCUPANTS OF CERTAIN WEIGHTS OCCUPY THE SEAT. THE ELECTRICAL CONNECTOR FOR THE WEIGHT SENSOR IS LOCATED UNDER THE CENTER CONSOLE, BETWEEN THE FRONT SEATS. UNDER CERTAIN CIRCUMSTANCES THE CONNECTOR COULD BECOME CONTAMINATED AND MALFUNCTION SUCH THAT THE FRONT PASSENGER AIRBAG WILL DEPLOY REGARDLESS OF THE WEIGHT OF THE OCCUPANT.

Action Needed To Fix It:

DEALERS WILL INSTALL A PROTECTIVE COVER OVER THE WEIGHT CLASSIFICATION SYSTEM CONNECTOR TO PREVENT CONTAMINATION. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTING TO BEGIN DURING APRIL 2011. OWNERS MAY CONTACT HYUNDAI'S CUSTOMER ASSISTANCE CENTER AT 1-800-633-5151.

Find your local [Hyundai Dealer](#).

2008 Hyundai ELANTRA Recall

Item Affected: FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP
Date Announced: 12/30/2008

Description of Recall:

HYUNDAI DE PUERTO RICO (HPR) IS RECALLING 347 MY 2008 ELANTRA VEHICLES. THE FUEL PUMP MOTOR MAY NOT HAVE THE PROPER, UNIFORM INTERNAL ELECTRICAL SURFACE CONTACT. THIS MAY CAUSE THE FUEL PUMP TO PRODUCE LESS PUMPING PRESSURE THAN REQUIRED TO SUPPLY THE FUEL INJECTION SYSTEM.

Action Needed To Fix It:

DEALERS WILL REPLACE THE VEHICLE'S FUEL PUMP SUBASSEMBLY. THE RECALL BEGAN ON FEBRUARY 9, 2009. OWNERS MAY CONTACT HPR AT 1-800-981-0188.

Find your local [Hyundai Dealer](#).

2008 Hyundai ELANTRA Recall

Item Affected: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE
Date Announced: 3/16/2011

Description of Recall:

HYUNDAI IS RECALLING CERTAIN MODEL YEAR 2007-2008 ELANTRA VEHICLES MANUFACTURED FROM JULY 14, 2006, THROUGH AUGUST 29, 2007. THE DRIVER'S SEAT TRACK POSITION SENSOR DETERMINES THE SEAT'S FORE AND AFT POSITION AND ALLOWS THE DRIVER'S FRONTAL AIR BAG TO DEPLOY AT THE PRESSURE APPROPRIATE FOR THAT SEATING POSITION, WITH A LOWER PRESSURE DEPLOYMENT IN THE MOST FORWARD SEATING POSITIONS. THE AIR BAG CONTROL MODULE MAY RECEIVE AN UNSTABLE ELECTRICAL SIGNAL FROM THE SEAT TRACK POSITION SENSOR SUCH THAT, IN A CRASH THAT REQUIRES DRIVER FRONTAL AIRBAG DEPLOYMENT, THE DRIVER'S AIRBAG MAY DEPLOY AT THE HIGHER PRESSURE THAN INTENDED IF THE SEAT WAS POSITION IN ONE OF THE FORWARD POSITIONS IN WHICH A LOWER PRESSURE DEPLOYMENT IS INTENDED.

Action Needed To Fix It:

DEALERS WILL REPROGRAM THE AIR BAG CONTROL MODULE FREE OF CHARGE. THE SAFETY RECALL IS EXPECTING TO BEGIN DURING APRIL 2011. OWNERS MAY CONTACT HYUNDAI'S CUSTOMER ASSISTANCE CENTER AT 1-800-633-5151.

Find your local [Hyundai Dealer](#).

2007 Hyundai ELANTRA Recall

Item Affected: EXTERIOR LIGHTING
Date Announced: 7/17/2009

Description of Recall:

HYUNDAI IS RECALLING 3,011 MODEL YEAR 2005-2007 ELANTRA, TUCSON, SONATA, AZERA AND ACCENT VEHICLES. A MALFUNCTIONING STOP LAMP SWITCH MAY CAUSE THE BRAKE LIGHTS TO FAIL TO ILLUMINATE WHEN THE BRAKE PEDAL IS DEPRESSED OR MAY CAUSE THE BRAKE LIGHTS TO REMAIN ILLUMINATED WHEN THE BRAKE PEDAL IS RELEASED. A DEFECTIVE STOP LAMP SWITCH MAY ALSO AFFECT THE OPERATION OF THE BRAKE-TRANSMISSION SHIFT INTERLOCK FEATURE SO THE TRANSMISSION WOULD NOT BE ABLE TO BE SHIFT OUT OF THE "PARK" POSITION. IT MAY ALSO CAUSE THE ELECTRONIC STABILITY CONTROL (ESC) MALFUNCTION LIGHT TO ILLUMINATE, AND IT MAY NOT DEACTIVATE THE CRUISE CONTROL WHEN THE BRAKE PEDAL IS DEPRESSED.

Action Needed To Fix It:

DEALERS WILL REPLACE THE STOP LAMP SWITCH FREE OF CHARGE. THE RECALL BEGAN ON SEPTEMBER 2, 2009. OWNERS MAY CONTACT HYUNDAI OF PUERTO RICO CUSTOMER SERVICE AT 1-787-999-4310.

Find your local [Hyundai Dealer](#).

2007 Hyundai ELANTRA Recall

Item Affected: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE
Date Announced: 3/16/2011

Description of Recall:

HYUNDAI IS RECALLING CERTAIN MODEL YEAR 2007-2008 ELANTRA VEHICLES MANUFACTURED FROM JULY 14, 2006, THROUGH AUGUST 29, 2007. THE DRIVER'S SEAT TRACK POSITION SENSOR DETERMINES THE SEAT'S FORE AND AFT POSITION AND ALLOWS THE DRIVER'S FRONTAL AIR BAG TO DEPLOY AT THE PRESSURE APPROPRIATE FOR THAT SEATING POSITION, WITH A LOWER PRESSURE DEPLOYMENT IN THE MOST FORWARD SEATING POSITIONS. THE AIR BAG CONTROL MODULE MAY RECEIVE AN UNSTABLE ELECTRICAL SIGNAL FROM THE SEAT TRACK POSITION SENSOR SUCH THAT, IN A CRASH THAT REQUIRES DRIVER FRONTAL AIRBAG DEPLOYMENT, THE DRIVER'S AIRBAG MAY DEPLOY AT THE HIGHER PRESSURE THAN INTENDED IF THE SEAT WAS POSITION IN ONE OF THE FORWARD POSITIONS IN WHICH A LOWER PRESSURE DEPLOYMENT IS INTENDED.