

INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)				FOR AGENCY USE ONLY 100148	
 U.S. Department of Transportation National Highway Traffic Safety Administration		Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		Date Received DEC - 5 2012 01-OCT-2012	
				Repository ☐ Reference No. 10478125	
OWNER INFORMATION (Type or Print)					
Name				Daytime Telephone Number	
Address					
City		State	Zip Code	Evening Telephone Number	
ORANGEBURG		SC		N/A	
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make		Model	
6MMAP67P92T		MITSUBISHI		DIAMANTE	
Model Year		Engine:		Fuel Type:	
2002		No: Cylinders		UNLEADED	
Date Purchased		Dealer's Name and Telephone Number			
9-14-2005		LUND CADILLAC, LLC			
Original Owner		Dealer's City		State	
☐		PHOENIX		AZ	
		Zip Code		85022	
Transmission Type		Powertrain		Multiple Failure:	
AUTO				SEE BELOW	
☐ Antilock Brakes		☒ Cruise Control		Incident Date(s)	
				-26 JUL 2012 25-JULY-2012	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Codes: ENGINE (PWS), BRAKES (PWS)				Failure Mileage	
CRANK ANGLE, SENSOR WIRING, ELECTRICAL SYSTEM, FUEL PUMP, MISFIRES, EGR VALVE, FUEL INJECTOR				140000	
				Failure Speed	
				75	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM19ABC036)		☐ Original Equipment ☐ Prior Repair		Failure Location:	
Tire Component Code				Tire Failure Type:	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:		Date Manufactured:		Model No./Name:	
Seat Type:		Installation System:			
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION					
(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)					
Crash		Fire		Number of Persons Injured	
☒ Yes ☐ No		☐ Yes ☒ No		0	
				Number of Deaths	
				0	
				Reported to Police	
				2-2-12	
Narrative Description of Incident(s), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).					
OUT OF CONTROL					
TL* THE CONTACT OWNS A 2002 MITSUBISHI DIAMANTE. THE CONTACT STATED THAT WHILE DRIVING AT 75 MPH, THE CONTACT ATTEMPTED TO BRAKE BUT THE BRAKES FAILED TO RESPOND WITHOUT ANY WARNINGS. THE VEHICLE CRASHED INTO A PASSENGER VAN. THE VEHICLE WAS DESTROYED. THE CONTACT MENTIONED THAT TWO MONTHS PRIOR TO THE FAILURE THE CHECK ENGINE LIGHT HAD ILLUMINATED. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC FOR DIAGNOSIS AND WAS INFORMED THAT THE VEHICLE MISFIRES, NEEDED SPARK PLUGS, A FUEL PUMP, A FUEL INJECTOR, AN EGR VALVE, AND THE ENGINE SURGED ERRATICALLY. THE FAILURE AND CURRENT MILEAGE WAS 140,000.					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.					
ATTACH ADDITIONAL SHEETS IF NECESSARY					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

SEE ATTACHED SHEETS. - INCIDENT REPORT.
PICTURE OF CRASH/ACCIDENT: RECALL ID#1267
ELECTRICAL SYSTEM WIRING; QUESTIONNAIRE, NARRATIVE
DESCRIPTION OF INCIDENT.

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382

Official Business
Penalty for Private Use \$300



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



BUSINESS REPLY MAIL

FIRST-CLASS MAIL

PERMIT NO. 1888


WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-210
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382



Think your vehicle
has a safety defect?



If so:

Use the enclosed
form to file a report.

or visit:

www.safercar.gov

or call:

Vehicle Safety Hotline
888-327-4236



November 14, 2012

Orangeburg, SC

Reference No: 10476125

US Dept. of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-210
1200 New Jersey Avenue SE
Washington, DC 20077-9382

Dear US Dept. of Transportation:

- On September 14, 2005 a 2002, Mitsubishi Diamante, was purchased from Lund Cadillac, LLC in Phoenix, Arizona.
- From 2010-2012 the vehicle had multiple problems and defects.
- Several hundred dollars were paid to independent mechanics to address issues with the fuel pump, Heating Coil, Check Engine Light, Spark Plugs, Misfires, Sensor Wiring, EGR Valve, Fuel Injector, causing engine surge and running erratically, often times stopping suddenly.
- After vehicle failed inspection, the owner presented receipts to The North Carolina Division of Motor Vehicle reflecting numerous attempts were made by mechanic to address engine surge issues, but the engine light remained illuminated and cited issues remained unresolved.
- Upon presentation of invoice, the owner then obtained special permission from The North Carolina Division of Motor Vehicle to pass inspection and renew license plate registration, as mechanical defects were addressed with no success.
- After the owner's vehicle crashed into a Chevrolet Van on July, 25, 2012, the owner made the following observations.
- While traveling into the downtown area of Orangeburg, SC the engine surged up to 75 MPH.
- The owner depressed the brakes to avoid a crash, but could not stop or control the vehicle as it slammed into a van and overturned it, destroying the vehicle as pictured with enclosed document.
- After trying to understand the course of events, and losing control of the vehicle, through research, the owner found Recall ID # 1267 - ELECTRICAL SYSTEM: WIRING: FRONT UNDERHOOD, See attached.
- The owner did not receive any notification that the safety issues mentioned were ever addressed or identified when the car was purchased in 2005.
- The owner believes this was one of the 3885 potential units affected by THE CRANK ANGLE SENSOR WIRING, CAUSING THE ENGINE TO RUN ERRATICALLY OR STOP SUDDENLY, INCREASING THE RISK OF A CRASH, as noted in the Recall ID # 1267.

Sincerely,

Enclosures: Incident Report

Picture of crash/accident on July 26, 2012

Recall ID # 1267. ELECTRICAL SYSTEM: WIRING: FRONT UNDERHOOD, Owner's Questionnaire

Main Office: Office of Financial Responsibility SC Department of Public Safety P.O. Box 493, Columbia, SC 29215				SOUTH CAROLINA DEPARTMENT OF PUBLIC SAFETY FR-10 (REV. 07-2011) NOTICE OF REQUIREMENT					
Date: 07-25-2012		Time: 08:15		Class: 38		Collision Location (Rt. #): 178 / BROUGHTON ST		Main Use: 2-Alternate Business	
Failure to comply could result in appropriate action under 56-10-270 and 56-10-520 of the 1976 code of laws of S.C. as amended, if vehicle subject to registration in S.C., and upon conviction thereof, the Department must suspend your driving and/or registration privileges until all compliances have been met under the above sections of law.									
E-293196					E-293197				
Driver/Pedestrian's Full Name					Driver/Pedestrian's Full Name				
01					02				
Sex: F, Race: W, Street/R.F.D.: , Birth Date: , City, State & Zip: DENMARK, SC					Sex: F, Race: B, Street/R.F.D.: , Birth Date: , City, State & Zip: RALEIGH, NC				
State: SC, Driver's License #: , Class: D, Insurance Company: TRAVELERS INSURANCE					State: NC, Driver's License #: , Class: C, Insurance Company: STATE FARM				
Year: 2005, Body: VN, Vehicle Make: CHEV, VIN #: 1GNDV23EX5D					Year: 2002, Body: 4S, Vehicle Make: MITS, VIN #: 6MMAP67P2T				
State: SC, Year: 2012, License Plate #: , Owner's D.L. #:					State: NC, Year: 2012, License Plate #: , Owner's D.L. #:				
Home Telephone: , Owner's Full Name:					Home Telephone: , Owner's Full Name:				
Bus. Telephone: , Street/R.F.D.:					Bus. Telephone: , Street/R.F.D.:				
Contributed To Collision: , City, State & Zip:					Contributed To Collision: , City, State & Zip:				
Driver/Pedestrian's Full Name									
State: , Year: , License Plate #: , Owner's D.L. #:									
Home Telephone: , Owner's Full Name:									
Bus. Telephone: , Street/R.F.D.:									
Contributed To Collision: , City, State & Zip:									
All Units Insurance Information (to be completed by Investigating Officer)									
Accident Insurance Information for Unit # 01									
Company Name: TRAVELERS INSURANCE, Area Code/Phone Number: (800) 252-6333									
Agency Name: LANCASTER AGENCY, Policy Number:									
Accident Insurance Information for Unit # 02									
Company Name: STATE FARM, Area Code/Phone Number:									
Agency Name: , Policy Number:									
Insurance Information									
Notice of Requirement Accepted: Signature: , Y/N Refused to Affix Signature? , Y/N Vehicle Subject to Registration in SC?									
To Be Completed By Insurance Agency, Broker, Or Other Company Representative									
Reference to Unit #: , I hereby affirm that to the best of my knowledge the vehicle described above was insured by the below stated insurance company on the date of the collision.									
Insurance Company: , Policy #: , Signature: , Title:									
Beginning Date: , Ending Date: , Policy Holder: , NA Code (Assigned by S.C. Dept. of Ins.): , Bus. Telephone:									
Notice: Failure to have this form completed by your insurance broker, agent, or representative and returned to the South Carolina Department of Public Safety within 15 days may result in suspension of your driving and/or registration privileges.									
If any of the below are applicable, disregard the above portion.									
Form FR-10 Not Issued: Section 56-10-270, 56-10-520									
Check here if a Form SR-23, Fleet Policy of 25 or more vehicles is on file with the Department covering the vehicle.									
Check here if a certificate of self insurance has been issued by the Department covering the vehicle and indicate the certificate number SI- .									
Check here if liability insurance was not in effect to comply with South Carolina statutory requirements.									
Investigating Officer's Name: KING - N W, Rank: SGT, Badge #: 574, Code: HP07, Date: , Reviewer's Name: , Rank: , Inmate Agency Code: 12BW147749									



DIONNE GLEATON/T&D
The driver of a Chevrolet van was taken to the Regional Medical Center with minor injuries Wednesday after a Mitsubishi slammed into it. The van then overturned. The driver of the Mitsubishi has been charged.

Subject: Electrical Control Harness 2002 Mitsubishi Diamante



2002 Mitsubishi Diamante

Average Resale Value: \$5,063

MPG Range: 25 mpg

Body Style: Sedan



[Safety Features](#)

[Crash Test Ratings](#)

[Recalls](#)

Recall ID # 1267 - ELECTRICAL SYSTEM:WIRING:FRONT UNDERHOOD

☐ [Hide Details](#)

Recall Date:

APR 07, 2002

Model Affected:

2002 Mitsubishi Diamante

Summary:

ON CERTAIN PASSENGER VEHICLES, THE MAIN UNDER HOOD ELECTRICAL WIRING HARNESS MAY HAVE INSUFFICIENT CLEARANCE BETWEEN THE ENGINE CONTROL HARNESS AND THE EXHAUST HEAT SHIELD. AS A RESULT, THE HARNESS COULD COME IN CONTACT WITH THE HEAT SHIELD, WHICH COULD RESULT IN MELTING OF THE HARNESS INSULATION.

Consequences:

THE MELTING OF THE HARNESS INSULATION COULD RESULT IN GROUNDING OF THE CRANK ANGLE SENSOR WIRING, CAUSING THE ENGINE TO RUN ERRATICALLY OR STOP SUDDENLY, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSPECT THE HARNESS FOR DAMAGE AND, IF NONE IS EVIDENT, WILL TIE THE HARNESS BACK TO PREVENT THE HARNESS FROM EVER COMING INTO CONTACT WITH THE HEAT SHIELD. ANY HARNESS THAT SHOWS EVIDENCE OF DAMAGE WILL BE REPAIRED AS NECESSARY AND THEN TIED BACK TO PREVENT FUTURE DAMAGE. OWNER NOTIFICATION BEGAN MAY 13, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT MITSUBISHI AT 1-800-222-0037.

Potential Units Affected:

3885

Notes: MITSUBISHI AMERICA Recall ID # 50010 -
EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL

☐ [Full Details](#)