

JUN 26 2014

DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline				FOR AGENCY USE ONLY 100148	
				Date Received 01-APR-2014	Repository ☐ Reference No. 10576285
OWNER INFORMATION (Type or Print)				Daytime Telephone Number	
Name [REDACTED] Address [REDACTED] City FORT WAYNE State IN Zip Code [REDACTED]				E-mail Address [REDACTED] Evening Telephone Number [REDACTED]	
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1G4HP54K224 [REDACTED]				Make BUICK	Model LESABRE
Date Purchased 7/3/2002		Dealer's Name and Telephone Number Kelley Buick 260-434-4600		Engine: No: Cylinders	Fuel Type:
Original Owner ☒	Dealer's City Fort Wayne	State IN	Zip Code 46825		
Transmission Type automatic	☒ Antilock Brakes ☒ Cruise Control	Powertrain 3800 V 6 L 36	Multiple Failure:	Incident Date(s) 30-MAR-2014	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Codes: FUEL/PROPULSION SYSTEM (PWS), ENGINE (PWS)				Failure Mileage 52213	Failure Speed 0
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM19ABC036)		☐ Original Equipment ☐ Prior Repair		Failure Location:	
Tire Component Code				Tire Failure Type:	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:		Date Manufactured:		Model No./Name:	
Seat Type:		Installation System:			
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION					
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)					
Crash ☐ Yes ☒ No	Fire ☒ Yes ☐ No	Number of Persons Injured 0	Number of Deaths 0	Reported to Police N	
Narrative Description of Incident(s), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).					
TL* THE CONTACT OWNS A 2002 BUICK LESABRE. THE CONTACT STATED THAT UPON INITIAL START-UP, THE VEHICLE HESITATED AND APPEARED TO MISFIRE. THE CONTACT THEN SUDDENLY HEARD A LOUD POP FOLLOWED BY A MASSIVE AMOUNT OF BLACK SMOKE COMING FROM UNDER THE HOOD OF THE VEHICLE. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE DEALER AND THE MANUFACTURER WERE MADE AWARE OF THE FAILURE AND DECLINED TO PROVIDE A REMEDY TO THE CONTACT. THE VEHICLE WAS NOT REPAIRED. THE FAILURE MILEAGE WAS 52,213. UPDATED 05/28/14 MA Incorrect. See attached forms/receipts. Paid in full. #99.32					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

CUSTOMER #: 464770

2014593



INVOICE

Tom Kelley Buick GMC

633 Avenue of Autos Fort Wayne, IN 46804
(260) 434-4600 Fax: (260) 434-4740

www.drivekelley.com

FORT WAYNE, IN

PAGE 1

HOME: [REDACTED]

CONT: [REDACTED]

BUS: [REDACTED]

CELL: [REDACTED]

SERVICE ADVISOR: 159 PAUL COY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
25 BLU	02	BUICK LESABRE	1G4HP54K224		33893/52213	T1889	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
03JUL02 DD			16:00 03APR14		0.00	CASH	08APR14

R.O. OPENED READY OPTIONS: ENG:L36 TRN:A 1)STK#-2B1436

12:39 03APR14 12:42 08APR14

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A C/S THEY WERE TOLD MANIFOLD CRACKED REPORT (COOLANT)

00CDZMISC .INTAKE MANIFOLDBLEW UP / TOW IN

206 CC		369.50	369.50
1 89017272 3265BOPC (S)MANIFOLD KIT			141.94
1 89017554 3270BOPC (S)GASKET KIT			44.17
1 12346290 8800BOPCKT COOLANT			22.81
1 19245529 3330 (S)REGULATOR KIT			128.76
1 FRT FREIGHT	14.77	14.77	14.77
1 12587077 3330BPC F-(S)RAIL KIT			237.13

PARTS: 574.81 LABOR: 369.50 OTHER: 14.77 TOTAL LINE A: 959.08

33893 upper plastic intake blowup bent injector rail 3.50 replace
intake and injector rail and fuel pressure regulator

B NEED CORRECT MILES PLEASE

01 GENERAL CONCERN

206 CC		0.00	0.00
PARTS: 52213	0.00 LABOR: 0.00 OTHER: 0.00	TOTAL LINE B:	0.00

BUICK®

State Tax

40.24

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE
DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF
THIS REPAIR INVOICE.By signing below, you acknowledge that you were notified of and
authorized the Dealership to perform the services/repairs itemized
in this Invoice and that you received (or had the opportunity to
inspect) any replaced parts as requested by you. The vehicle is
being returned to you in exchange for your payment of the Amount
Due.*SHOP SUPPLY COSTS: We
have added a charge equal to
9% of the total cost of labor,
not to exceed \$25.81, to the
Repair Order for shop supplies
used in connection with this
repair.ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	369.50
PARTS AMOUNT	574.81
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	14.77
TOTAL CHARGES	959.08
LESS INSURANCE	0.00
SALES TAX	40.24

PLEASE PAY
THIS AMOUNT

999.32

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE