

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

National Highway Traffic Safety Administration		1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100145	
Name		Date Received		Repository ☐	
Address		15-SEP-2022		Reference No. 11484652	
City		State		E-mail Address	
Columbia Cross Roads		PA			
ZIP Code		Daytime Telephone Number		Evening Telephone Number	
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		MAKE		Model	
2M4HCUAAAD7A1		HYUNDAI		ELANTRA	
Date Purchased		Dealer's Name and Telephone Number		Engine	
04/13/2011		SIMMONS ROCKWELL 607-746-5555		No. Cylinders	
Original Owner		Dealer's City		Fuel Type	
☐		Elmira		GASOLINE	
STATE		ZIP Code		Incident Date(s)	
NY		14903		15-SEP-2013	
Transmission Type		Antilock Brakes		Multiple Failure	
MANUAL		☒ Cruise Control			
Powertrain		Incident Date(s)			
		15-SEP-2013			
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Components Codes: 010000 STEERING				Failure Mileage	
				40000.0	
				Failure Speed	
				60	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM1 9ABC036)		☐ Original Requirement		Failure Location	
		☐ Prior Repair			
Tire Component Code		Tire Failure Type			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make		Date Manufactured		Model No./Name	
Seat Type		Installation System			
Child Seat Component Code		Failed Part			
APPLICABLE INCIDENT INFORMATION					
(Please describe in detail the incident(s), failure(s), crash(es), injury(ies).)					
Crash		Fire		Number of Persons Injured	
☐ Yes ☒ No		☐ Yes ☒ No		Number of Deaths	
				Reported to Police	
				N	
Narrative Description of Incident(s), Crash(es), Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure, i.e., parts repaired or replaced (and if old part is available).					
The contact owns a 2010 Hyundai Elantra. The contact stated while driving 40-50 MPH, the power steering assist warning light illuminated. The contact veered to the side of the road and turned the vehicle. The contact was able to continue driving. However, the failure reoccurred while driving. The vehicle was taken the dealer on two occasions. The dealer updated the Electronic Power Steering (EPS) control unit. However, the failure persisted. The dealer was contacted and informed the contact they no longer had the part to repair the vehicle. The vehicle was not repaired. The contact associated the failure with NHTSA Campaign Number, 15V100000 (Steering). The manufacturer was notified of the failure. The failure mileage was approximately 40,000.					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.					
ATTACH ADDITIONAL SHEETS IF NECESSARY					
The Privacy Act of 1974-Public Law 93-579. This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

January 10, 2023


Vehicle was purchased used from dealer in May 2011 with 60K mile 5 yr warranty. The ESP problem occurred several times during warranty period & was corrected by dealer. The problem reoccurred later but could be corrected by safely stopping vehicle & re-starting engine. This continued to be a dangerous situation. During ownership, problem occurred several more times and was corrected by dealer resetting the ESP module.

I was concerned that if vehicle was sold or traded to someone not aware of steering problem it could cause a catastrophic accident especially to a novice or older driver. Vehicle steering was extremely heavy and hard to control especially when on sharp turns and/or slow speeds.

When last problem occurred, the ESP could not be reset by turning engine off and on again. Took to dealer and was told they no longer had equipment to reset the ESP. That is when I contacted NHTSA.

Was later contacted by dealer and problem was resolved by dealer at no cost to me. Copy of repair invoice enclosed. I appreciate and thank the NHTSA for their help and hoping to finally resolving this dangerous problem.

Sincerely,

A solid black rectangular box used to redact the signature of the sender.

CUSTOMER #: [REDACTED]

*Hyundai
Cust. Service
1-800-
343-
7764*

SIMMONS ROCKWELL HYUNDAI, INC.

784 County Rte 64, Bldg. 3 Elmira, NY 14903

PH: (807) 796-5555 Fax: (807) 795-1453

www.simmons-rockwell.com

INVOICE

Other Locations:

Chevrolet * Buick * GMC * Nissan
Dodge * Chrysler * Jeep * Suzuki * Subaru * Ford * Mercury

NYS Reg # 7063837

PAGE 1

COLUMBIA X RD, PA [REDACTED]

HOME: [REDACTED] CONT: [REDACTED]

BUS: [REDACTED] CELL: [REDACTED]

SERVICE ADVISOR: 712 ROLAND RICHARDSON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
	10	HYUNDAI Elantra	KMH DU4AD0AU [REDACTED]		181557/181557	T060	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN10 IS							
01JAN10 DD		01JAN2010	20:00 17OCT22		150.00	CASH	17OCT22
R.O. OPENED	READY	OPTIONS	DLR:S/R				
07:42 17OCT22	17:06 17OCT22						

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A CUSTOMER STATES VEHICLE HARD TO STEER. SOP HERE FOR REPAIR

CAUSE:

MIS MISC. DESCRIPTION

105 WOLCOTT, ZEBULIN M LIC#: 1QE1

WPH

1 56310-2H250-AS1 COLUMN & SHAFT ASSY-STEERING

2 81919-31000 BOLT-SAFETY LOCK

(N/C)

(N/C)

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

181557 1.70 replace steering column assembly. using gds program sas

WE HOPE YOUR SERVICE VISIT WAS A FIVE STAR
EVENT. ***** IF YOU CAN NOT RECOMMEND US TO
A FRIEND, PLEASE TELL US WHY. THANK YOU FOR
YOUR TIME. 796-5555 EXT.2198 OR 2125

* [] CASH [] CREDIT CARD *
* [] CHECK [] CHARGE *

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE
INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE
SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO
OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE
VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED
UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY
ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS
CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT
NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY
MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER

The factory warranty constitutes all
of the warranties with respect to
the sale of this item/items. The
Seller hereby expressly disclaims all
warranties, either express or
implied, including any implied
warranty of merchantability or
fitness for a particular purpose.
Seller neither assumes nor
authorizes any other person to
assume for it any liability in
connection with the sale of this
item/items.

DESCRIPTION

TOTALS

LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER COPY