



DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
 TO REPORT VEHICLE SAFETY DEFECTS
 1-888-DASH-2-DOT
 (1-888-327-4236)
 INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY
 Date Received: **10/28/00**
 RECEIVED
 10/28/00 11:22
 557078
 Reference No.

OWNER INFORMATION (Type or Print)

[Redacted Owner Information]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
 In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner: [Redacted]

Date: 10/28/00

PRODUCT INFORMATION

| | | | | |
|---|--|--|---|--|
| Vehicle Identification No. (VIN.) (17 Digits) 2FABP43F4FX239322 | | Make Ford | Model CROWN VIC | Year '85 |
| Purchased Date 12/91 | Dealer's Name N/A | Engine Size (CID/CYL) 5.0L | <input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection | |
| <input type="checkbox"/> New <input checked="" type="checkbox"/> Used | Dealer's City South Bend | State IN | Zip Code 46637 | No. Cylinders 8 |
| Manufacture Date (on driver's door or pillar) 7-85 Made in CANADA | Transmission Type <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Automatic | Restraint System <input type="checkbox"/> Driverside Air Bag <input type="checkbox"/> Motorbelt <input type="checkbox"/> Passengerside Air Bag <input type="checkbox"/> 2-Point Belt <input checked="" type="checkbox"/> 3-Point Belt | Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Drivetrain <input type="checkbox"/> Front <input checked="" type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel |
| Vehicle Type <input checked="" type="checkbox"/> Car <input type="checkbox"/> Sport Utility <input type="checkbox"/> Van <input type="checkbox"/> Truck <input type="checkbox"/> Minivan <input type="checkbox"/> Motorcycle <input type="checkbox"/> Other | | Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other | | |

FAILED COMPONENT(S)/PART(S) INFORMATION

| | | | |
|--|---|--|--|
| Part Name(s) IGNITION MODULE, CHOKE THERMOSTAT | Location <input type="checkbox"/> Left <input type="checkbox"/> Right <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear | Failed Part(s) <input checked="" type="checkbox"/> Original <input type="checkbox"/> Replacement | Handicap Adaptive Equip <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
|--|---|--|--|

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

| | | |
|-----------------|-----------------------------|--|
| Tire Brand | Tire Name | Complete Tire Size |
| No. of Failures | Date(s) of Failure(s) | Failed Part(s) Available? |
| | Mileage at Failure(s) | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| | Vehicle Speed at Failure(s) | NHTSA Previously Contacted? |
| | | <input type="checkbox"/> Yes <input type="checkbox"/> No |

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the Incident(s), Failure(s), Crash(es), and Injury(ies). Attach photos if available.)

| | | | | |
|--|---|---------------------------|----------------------|---|
| Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Number of Persons Injured | Number of Fatalities | Reported to Manufacturer <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
|--|---|---------------------------|----------------------|---|

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies). **#1. Ignition Module - Very defective part; Had to replace this part 2 times already due to Failure. Very dangerous when this part fails because the engine will stall. My engine stalled twice after this part failed. I was driving home from work one day, when all of a sudden my car stalled in the middle of the road (cause) failed ignition module. Same thing happened again a couple of years later (cause) failed ignition module. Very expensive to fix this device, plus towing etc. → over**

Continue on back.

The Privacy Act of 1974 • Public Law 93-579 This information is requested pursuant to a49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administration enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

#2. Choke Thermostat - Yet another very defective part. When this part goes bad it creates a very, very, dangerous situation = (The throttle will stick). The gas pedal "stuck" on my car when the choke thermostat became defective. This caused the engine to run wide open creating a very serious, and dangerous situation.

I hope you will investigate these very defective parts.

ATTACH ADDITIONAL SHEETS IF NECESSARY

U.S. Department of Transportation

National Highway Traffic Safety Administration

400 Seventh St., S.W. Washington, D.C. 20590

Official Business Penalty for Private Use \$300



NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NSA-10.01
400 7th Street, SW
Washington, DC 20590



Complete and return or place in your car manual for future use

**VEHICLE
OWNER'S
QUESTIONNAIRE
(VQO)**



DOT AUTO SAFETY HOTLINE

TO REPORT VEHICLE SAFETY DEFECTS
COMPLETE THIS FORM

OR

DASH 2 DOT

and dial toll free at

1-888-DASH-2-DOT

1-888-327-4236

DOT Auto Safety Hotline
(DASH) 2 DOT



U.S. Department of Transportation
National Highway Traffic Safety
Administration

www.nhtsa.dot.gov/hotline

Judge orders Ford recall

By DAVID KRAVETS
Associated Press Writer

OAKLAND, Calif. — A judge took the unprecedented step Wednesday of ordering the recall of as many as 1.7 million Ford cars and trucks sold in California, accusing the automaker of concealing a dangerous design flaw that can cause the vehicles to stall in traffic.

The ruling compounds Ford's troubles as the automaker tries to steer its way out of the Firestone tire recall crisis.

Ford has insisted all along that the ignition module at issue is safe, and it said it will appeal the ruling, arguing that a California state judge has no authority to issue such an order.

Never before has a U.S. judge ordered an automotive recall.

The device was put on 29 models between 1983 and 1995, including the Taurus, LTD, Ranger, Bronco, Mustang and Escort, according to Ford. During that period, Taurus was one of the top-selling cars in America.

Superior Court Judge Michael E. Ballachey said Ford sold as many as 23 million vehicles with the flaw, but his jurisdiction does not extend beyond California. However, similar class-action suits are pending in Alabama, Maryland, Illinois, Tennessee and Washington.

The automaker has settled dozens of wrongful-death and personal-injury lawsuits nationwide in which a Ford vehicle was suspected of stalling. But Ford never admitted any wrongdoing.

The National Highway Traffic Safety Administration conducted three probes into stalling of Ford vehicles between 1984 and 1987 and closed the cases after finding "no defects," agency spokesman Tim Hurd said Wednesday.

See RECALL/Page B9

Recall

Ballachey said that Ford knew since at least 1982 that the vehicles were prone to stalling, especially when the engine was hot, but failed to alert consumers and repeatedly deceived federal regulators by claiming the modules were safe.

"This case was about concealment of a dangerous condition," he said.

Government agencies normally order recalls, but Ballachey said state law gives him that power.

Ford disagreed and argued that a recall is unnecessary.

"The record in this case does not demonstrate a safety problem," Ford attorney Richard Warner said. "These vehicles are safe."

The judge appointed a referee to study three options—ordering Ford to remove the modules and remount them away from the engine, replacing the module with one from 1999-2000 model vehicles, or ordering a vehicle buyback. Ballachey set

Ford said it does not know how much a California recall would cost, but the Center for Auto Safety estimated that it would be at least \$125 million.

The automaker already is involved in the recall of 6.5 million Firestone tires, which were standard equipment on Explorers and other vehicles. NHTSA is investigating more than 100 deaths in connection with the tires.

The judge's ruling was based on a class-action lawsuit filed on behalf of 3.5 million current and former Ford owners in California.

The plaintiffs claim that the TFI module, which regulates electric current to the spark plugs, was wrongly mounted on the distributor near the engine block, exposing it to excessive heat and stress. The plaintiffs say that caused the vehicles to stall.

Ford documents show the automaker was warned by an engineer that high temperatures would cause the device to fail and stall the engine.

Installation Tips Diagnosing Ford TFI Systems

Ford vehicle owners are currently experiencing a high replacement rate of their distributor mounted ignition modules. However, a majority of these modules are not defective and most of the failures are due to other problems in the system.

Module Problems

1. Early O.E. units stamped "Made in France" are prone to premature transistor failure. This is partly due to poor soldering of the heat sink to the power transistor.
2. Premature module failure can result from improper cleaning of the mounting surface and poor application of the heat transfer compound.
3. Water damage to the module may be caused by cooling system leaks or steam cleaning the engine.

Note: When steam cleaning, never aim the cleaner directly at any electric component.

Magnetic Pick-ups and Hall Effect Unit Problems

1. The TFI-I system is equipped with a standard magnetic pick-up, which is subject to the same problems associated with GM's HEI systems.

When the magnetic pick-up has an intermittent problem, check for broken or loose leads. Using an ohmmeter, read the resistance of the magnetic pick-up. The reading should be between 650-1300 ohms. Now, wiggle all wires to detect any variation in ohms. If the reading has varied, the unit is defective. Also, check the magnet in the pick-up for cracks which can cause intermittent problems or a "no-start" condition. Replace the defective unit.

2. The TFI-IV system uses a Hall Effect unit instead of a magnetic pick-up. Ford is experiencing heat related problems with this unit.

The early units, which are black, should be replaced whenever a module is replaced. Newer units, which are blue, should be replaced if signs of heat or burning are present at the plug-in connector.

