

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

22-AUG-2000

Od_or _____
rt_dt _____
od_rt _____
up_ltr _____

Reference No.

728740

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) <small>(located at bottom of windshield or driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GHDX03E3YD105215	OLDSMOBILE TRI	SILHOUETTE	2000	

Purchase Date 01-AUG-1999	Dealer's Name _____	Engine Size (CID/CCL) _____	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injection
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driver Side Airbag <input type="checkbox"/> Passenger Side Airbag <input type="checkbox"/> Inert Inert <input type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other <input type="checkbox"/> Sport Utl <input type="checkbox"/> Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Station Wagon <input type="checkbox"/> Pick Up Truck <input checked="" type="checkbox"/> Other
--	---	--	--	---	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08310000	Part Name(s) ELECTRICAL SYSTEM;WIRING;HARNES;FRONT;UNDERHOOD	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
-----------------------	---	--	---

No. of Failures 2	Date(s) of Failure(s) 18-AUG-2000	Mileage at Failure(s) 10400	Vehicle Speed at Failure(s) 2	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No
----------------------	--------------------------------------	--------------------------------	----------------------------------	---	---

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

MY MINI-VAN IS IDLING AT 2700RPMs AND THE CHECK ENGINE LIGHT IS LIT. THIS HAPPENED AT 4000MILES AND THE DEALER REPLACED THE TPS (THROTTLE POSITION SENSOR) THE FIRST TIME. THE SECOND INCIDENT OCCURED AT 10,400 MILES WITH THE CAR IDLEING AT 2700 RPMs. THIS TIME THE DEALER CALLED THE MANUFACTURER. THE DEALER TECH TOLD ME THAT A TECH AT THE MANUFACTURER SAID THE POSSIBLE CAUSE OF THE TPS IS ELECTROMAGNETIC WAVES EMENATING FROM THE WIRING HARNES IS CAUSING THE TPS TO FOUL SENDING IT INTO THE HIGH RPM REVS. THE TECH ALSO SAID THAT THE MANUFACTURER WOULD DENIE THIS IF ASKED. THE DEALER TECH SIAD TO REMEDY THE PROBLEM FOR NOW, HE WOULD WRAP TAPE AROUND THE HARNES TO KEEP THE WAVES DOWN TO A MINIMUM. I FIND THIS VERY HARD TO BELIEVE THAT TAP

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.