

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

05-SEP-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

730306

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JNKCP01P5NT302098	INFINITI	G20	1992	

Purchase Date 01-JUN-1992	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☒ Motorbell ☐ 2-Point Belt	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Ult ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06400000	Part Name(s) FUEL-THROTTLE LINKAGES AND CONTROL	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) 23-AUG-2000 Mileage at Failure(s) 95000 Vehicle Speed at Failure(s) 65	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE ACCELERATOR CABLE OF THE INFINITI G20 FROM THE FIREWALL TO THE CARBURETOR CONSISTS OF A BRAIDED STEEL CABLE IN A SOFT RUBBER SHEATH. A HARD PLASTIC PIECE CONNECTING THE ACCELERATOR CABLE TO THE FIREWALL INTERFACE FAILED, THUS EXPOSING THE CRITICAL BRAIDED STEEL ACCELERATOR CABLE TO THE SHARP, HARD EDGE OF THE BROKEN HARD PLASTIC PIECE. SUBSEQUENTLY, THREE STRANDS OF THE BRAIDED STEEL WIRE WERE CUT AS THE ACCELERATOR WAS OPERATED. AT THE TIME OF THE ACCIDENT, THE THREE FRAYED STRANDS ACTED AS FISH HOOKS INSIDE THE SOFT RUBBER SHEATH AND PREVENTED RETURN ACTION OF THE ACCELERATOR AS THE GAS PEDAL WAS RELEASED. THE RESULT WAS THAT THE ACCELERATOR JAMMED IN THE FULLY OPEN POSITION AS THE G20 INFINITI WAS BEING DRIVEN IN HEAVY MORNING RUSH HOUR TRAFF

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

05-SEP-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

730306

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JNKCP01P5NT302098	INFINITI	G20	1992	

Purchase Date 01-JUN-1992	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☒ Motorbell ☐ 2-Point Belt	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Ult ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06400000	Part Name(s) FUEL-THROTTLE LINKAGES AND CONTROL	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) 23-AUG-2000 Mileage at Failure(s) 95000 Vehicle Speed at Failure(s) 65	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE ACCELERATOR CABLE OF THE INFINITI G20 FROM THE FIREWALL TO THE CARBURETOR CONSISTS OF A BRAIDED STEEL CABLE IN A SOFT RUBBER SHEATH. A HARD PLASTIC PIECE CONNECTING THE ACCELERATOR CABLE TO THE FIREWALL INTERFACE FAILED, THUS EXPOSING THE CRITICAL BRAIDED STEEL ACCELERATOR CABLE TO THE SHARP, HARD EDGE OF THE BROKEN HARD PLASTIC PIECE. SUBSEQUENTLY, THREE STRANDS OF THE BRAIDED STEEL WIRE WERE CUT AS THE ACCELERATOR WAS OPERATED. AT THE TIME OF THE ACCIDENT, THE THREE FRAYED STRANDS ACTED AS FISH HOOKS INSIDE THE SOFT RUBBER SHEATH AND PREVENTED RETURN ACTION OF THE ACCELERATOR AS THE GAS PEDAL WAS RELEASED. THE RESULT WAS THAT THE ACCELERATOR JAMMED IN THE FULLY OPEN POSITION AS THE G20 INFINITI WAS BEING DRIVEN IN HEAVY MORNING RUSH HOUR TRAFF

CONTINUED ON BACK (SEE INSTRUCTIONS)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.