



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

20-DEC-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

755900

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield and driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FALP67L2WK130120	FORD	CONTOUR	1998	

Purchase Date 01-JUN-1997	Dealer's Name _____	Engine Size (CID/CC/L) <u>2.5 L</u>	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05230000	Part Name(s) ENGINE COOLING SYSTEM:PUMP:WATER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) <u>01-SEP-2001</u> Mileage at Failure(s) <u>61800</u> Vehicle Speed at Failure(s) <u>65</u>	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured C	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

1998 FORD CONTOUR SE, 2.5L V6 - WATER PUMP IMPELLER SHATTERED WHILE DRIVING ON HIGHWAY, CAUSING LOSS OF COOLANT FLOW. ENGINE OVERHEATED. FORTUNATELY THERE WAS A LINCOLN-MERCURY DEALER LESS THAN 1 MILE AWAY FROM THE LOCATION WHERE THE PART FAILED, SO ENGINE DID NOT RUN IN OVERHEATING CONDITION FOR VERY LONG. WATER PUMP WAS REPLACED BY THIS LOCAL DEALER (\$371 TOTAL). THE CAR IS STILL MY DAILY DRIVER, AND NOW APPEARS TO BE OPERATING NORMALLY WITH THE NEW WATER PUMP.

CONTINUED ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.