

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 335

Date Received

22-FEB-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

857339

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side) 1G4HP52K1VH464347	Vehicle Make BUICK	Vehicle Model LESABRE	Vehicle Year 1997	Current Odometer Reading
---	------------------------------	---------------------------------	-----------------------------	--------------------------

Purchase Date	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 01232000	Part Name(s) STEERING:UNKNOWN TYPE:SHAFT SECTOR	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 0	Date(s) of Failure(s) <u>22-FEB-1998</u> Mileage at Failure(s) <u>72260</u> Vehicle Speed at Failure(s) _____	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

AT ANY SPEED CONSUMER WOULD FEEL SLACKNESS IN THE STEERING COLUMN. DEALER SAID SHAFT WAS WORN OUT. DEALER REPLACED BOTTOM AND TOP STEERING. DEALER CLAIMED THAT EVENTUALLY IT WOULD HAVE CAUSED CONSUMER TO LOSE CONTROL. *AK

CONTINUED ON BACK (SEE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 335

Date Received

22-FEB-2000

DEFECTS INVESTIGATION

857339

OWNER INFORMATION (Type or Print)

591905

Work Number

Home Number

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

In the absence

address to the vehicle manufacturer.

☒ YES☐ NO

Signature of Owner

Date 3/24/00

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (Located at bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G4HP52K1VH464347	BUICK	LESABRE	1997	73742

Purchase Date

Dealer's Name Dobbs Buick

Engine Size

(CID/CC/L) 3.8☐ Turbo☐ Diesel☒ Gas☐ Fuel Injection☒ New ☐ UsedCity Memphis State TN Zip CodeNo Cylinders 6

Transmission Type

Antilock Brakes

Restraint System

Cruise Control

Drive Train

Vehicle Type

Body Style

☐ Manual☒ Yes☒ 3-Point Belt☐ Motorbelt☒ Yes☒ Front☒ Car☐ Sport UR☐ 2-Door☒ Automatic☐ No☒ Driverside Airbag☐ 2-Point Belt☒ No☐ Rear☐ Van☐ Truck☒ 4-Door☒ 4-Wheel☐ No☒ Passengerside Airbag☐ Other☐ Other☐ Other☐ Other☐ Other☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 01232000	Part Name(s) STEERING:UNKNOWN TYPE:SHAFT SECTOR	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
-----------------------	--	--	--

No of Failures

0

Date(s) of Failure(s) 22-FEB-1998Mileage at Failure(s) 72268

Vehicle Speed at Failure(s)

Failed Part(s)
Available?☐ Yes ☒ NoNHTSA Previously
Contacted?☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

AT ANY SPEED CONSUMER WOULD FEEL SLACKNESS IN THE STEERING COLUMN. DEALER SAID SHAFT WAS WORN OUT. DEALER REPLACED BOTTOM AND TOP STEERING. DEALER CLAIMED THAT EVENTUALLY IT WOULD HAVE CAUSED CONSUMER TO LOSE CONTROL. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.