

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

436

Date Received

31-MAY-2000

Od_or	_____
rt_dt	_____
od_rt	_____
up_ltr	_____

Reference No.

862777

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? YES NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) <small>(located at bottom of windshield or driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GNEK13K8SJ401707	CHEVROLET TRU	TAHOE	1995	

Purchase Date	Dealer's Name _____	Engine Size (CID/CCL) _____	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection
<input type="checkbox"/> New <input checked="" type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
<input type="checkbox"/> Manual <input type="checkbox"/> Automatic	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driver Side Airbag <input type="checkbox"/> Passenger Side Airbag	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	<input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other	<input type="checkbox"/> Sport Util Truck Motorcycle <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Station Wagon <input type="checkbox"/> Pick Up Truck <input checked="" type="checkbox"/> Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 12310000	Part Name(s) INTERIOR SYSTEMS; SEAT TRACKS AND ANCHORS	Location	Failed Part(s)
		<input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	<input type="checkbox"/> Original <input type="checkbox"/> Replacement

No. of Failures	Date(s) of Failure(s) 27-MAY-2000	Failed Part(s) Available?	NHTSA Previously Contacted?
	Mileage at Failure(s) _____	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No
	Vehicle Speed at Failure(s) _____		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash	Fire	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

DRIVER SEAT BROKE WHILE DRIVING. DEALER WILL REPAIR AT CONSUMER'S COST. AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT
1-888-327-4236
www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 436

Date Received

00 JUL 31 AM 11:52
31-MAY-2000
OFFICE OF INVESTIGATION

Od_or _____
rt_dt _____
od_r1 _____
up_itr _____

Reference No.

862777

OWNER INFORMATION (Type or Print)

611599

Work Number

Home Num

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner Anthony Vincent

Date 5/1/00

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (Located at bottom of windshield on driver's side) **1GNEK13K8SJ401707** Vehicle Make **CHEVROLET TRU** Vehicle Model **TAHOE** Vehicle Year **1995** Current Odometer Reading **79,062**

Purchase Date September 1998 Dealer's Name _____ Engine Size 5.7L Turbo Diesel Gas Fuel Injection
 New Used City _____ State _____ Zip Code _____ No Cylinders 8

Transmission Type Manual Automatic Antilock Brakes Yes No Restraint System 3-Point Belt Motorbelt Driverside Airbag 2-Point Belt Passengerside Airbag Cruise Control Yes No Drive Train Front Rear 4-Wheel Vehicle Type Car Sport Ut Van Truck Minivan Motorcycle Other _____ Body Style 2-Door 4-Door Stationwagon Pick Up Truck Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component **12310000** Part Name(s) **INTERIOR SYSTEMS:SEAT TRACKS AND ANCHORS** Location Left Right Front Rear Failed Part(s) Original Replacement

No of Failures _____ Date(s) of Failure(s) 27-MAY-2000 Mileage at Failure(s) 79,133 Vehicle Speed at Failure(s) 30 mph Failed Part(s) Available? Yes No NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash Yes No Fire Yes No Number of Persons Injured _____ Number of Fatalities _____ Estimated Property Damage \$ 2,34.20 Reported to Police Yes No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

DRIVER SEAT BROKE WHILE DRIVING. DEALER WILL REPAIR AT CONSUMER'S COST.*AK

CONTINUE ON BACK IF NEEDED

*The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

14 July, 2000
Reference: VIN 1GNEK13K8SJ401707

General Motors
PO Box 33170
Detroit, MI 48232-5170

Dear Sir,
Subject: Failed Drivers Seat Frame in 1995 Tahoe, FP-Number, 12472585, Frame 16.716

On 27 May 2000 the drivers seat lower frame failed at the forward left hand side attachment point to the sliding frame attached to the vehicle body. This failure was particularly troubling in that it occurred while driving the vehicle, nearly causing the driver to lose control with two small children seated in the rear.

Taking the vehicle into George White Chevrolet, Ames, IA, their service technicians determined that the entire lower seat frame would require replacement. We were informed that there was not service bulletin on this part. In addition, since the vehicle was no longer under warranty, no repairs would be covered.

Through casual conversation with other Chevrolet/GM Tahoe and Suburban owners of the same vintage all confirmed that they too have had similar seat failures. This is not an isolated event and is due to a fundamental design flaw in this part.

The vehicle I own, VIN 1GNEK13K8SJ401707 had 77,000 miles on the odometer at the time of failure, >99% of all driving is on paved highway. It is reasonable to assume that the average speed of the vehicle is approximately 45 mph. This would suggest that the vehicle has been in operation for nearly 1,700 hours. The two primary operators of the vehicle weight 145 pounds and 185 pounds respectively.

It is reasonable to suggest that as the driver of the vehicle sits in the seat, the vehicle pitching occur at a frequency less than 10 Hz. This would indicate that the seat had fewer than 61,666 cycles of reversing load. See Figure 1 for illustration:




Figure 1. General description of forces and point of failure

Assuming the load distribution is equally distributed between all four attachment points, the average loading would be 46.25 pounds. The metal stamping was measured at a thickness of 0.40 of an inch thick with the spot weld diameter of 0.375 inches. The backing plate is welded at 4 spots. Therefore the static working stresses should be on the order of 2,500 psi in the weld. The reversing stress to cause failure within 61.666 cycles is on the order of 20,000 psi. Knowing that the force at the seat attachment point is 46 pounds, this would indicate an acceleration of 7.6 g's, not exactly positive marketing data for operator comfort and vehicle smoothness. Clearly, there are other design flaws at work for this failure to occur.

Examination of the seat frame at the failure location clearly shows multiple cracks emanating from multiple stress risers in the stamped frame material. The metal stamping had a backing plate spot-welded to the frame. The frame had a stamped hole where a fastener could be run through to the backing plate. The backing plate was formed with a hole where threads would be formed upon insertion of a fastener. The sheet metal stamping also has multiple holes stamped into the surface where various components may be attached or bolt fasteners attached to the nut backing plates. The initial source of the cracking occurred at the hole punched through the sheet metal to form the hole where the fastener from the seat frame attached to the chassis to the seat itself. The yellow arrow highlights the remainder of the stamped hole in the following Figure 2. The red arrows show the initial crack that lead to the ultimate failure.



Figure 2. Frame Point of Failure.

Secondary failure points were located where the backing nut was spot welded to the stamped cross member. The blue arrows in Figure 3 points to two of four spot welds where the crack continued to propagate leading to the ultimate failure of the seat frame. Also visible in Figures 2 and 3 are the multiple cracks that developed during the point of initiation to failure. All of these cracks lead to a dramatic loss in strength of the frame, making for a potentially very dangerous situation for the driver and passengers of the vehicle.

Assuming the load distribution is equally distributed between all four attachment points, the average loading would be 46.25 pounds. The metal stamping was measured at a thickness of 0.40 of an inch thick with the spot weld diameter of 0.375 inches. The backing plate is welded at 4 spots. Therefore the static working stresses should be on the order of 2,500 psi in the weld. The reversing stress to cause failure within 61,600 cycles is on the order of 20,600 psi. Knowing that the force at the seat attachment point is 46 pounds, this would indicate an acceleration of 7.6 g's, not exactly positive marketing data for operator comfort and vehicle smoothness. Clearly, there are other design flaws at work for this failure to occur.

Examination of the seat frame at the failure location clearly shows multiple cracks emanating from multiple stress discs in the stamped frame material. The metal stamping had a backing plate spot-welded to the frame. The frame had a stamped hole where a fastener could be run through to the backing plate. The backing plate was formed with a hole where threads would be formed upon insertion of a fastener. The sheet metal stamping also has multiple holes stamped into the surface where various components may be attached or bolt fasteners attached to the nut backing plates. The initial source of the cracking occurred at the hole punched through the sheet metal to form the hole where the fastener from the seat frame attached to the chassis to the seat itself. The yellow arrow highlights the remainder of the stamped hole in the following Figure 2. The red arrows show the initial crack that lead to the ultimate failure.




Figure 2. Frame Point of Failure.

Secondary failure points were located where the backing nut was spot welded to the stamped cross member. The blue arrows in Figure 3 points to two of four spot welds where the crack continued to propagate leading to the ultimate failure of the seat frame. Also visible in Figures 2 and 3 are the multiple cracks that developed during the point of initiation to failure. All of these cracks lead to a dramatic loss in strength of the frame, making for a potentially very dangerous situation for the driver and passengers of the vehicle.




Figure 3 Secondary Cracks Leading to Ultimate Failure

Figure 4 is a micrograph of the surface of the crack indicated by the upper blue arrow in Figure 3. This crack surface shows fatigue failure by its smooth appearance. This location is where one of the spot welds was made to hold the backing plate/out in place.



Figure 4. Micrograph of Crack Surface at Spot Weld.

Figure 5 shows crack surface one half the distance between the edge of the stamping and the spot weld in Figure 4. This is the surface indicated by the upper blue arrow in Figure 3. The interesting feature of this feature, Figure 5, is that the upper surface is smooth and shiny indicating fatigue failure causing the propagation of the crack. The lower half of the crack surface shows the result of the final failure mode when the material became overstressed and failed.




Figure 5. Crack Surface Showing Upper Fatigue and Lower Overstress Failure

Figure 4 is a micrograph of the surface of the crack indicated by the upper blue arrow in Figure 3. This crack surface shows fatigue failure by its smooth appearance. This location is where one of the spot welds was made to hold the backing plate/nut in place.




Figure 4. Micrograph of Crack Surface at Spot Weld.

Figure 5 shows crack surface one half the distance between the edge of the stamping and the spot weld in Figure 4. This is the surface indicated by the upper blue arrow in Figure 3. The interesting feature of this picture, Figure 5, is that the upper surface is smooth and shiny indicating fatigue failure causing the propagation of the crack. The lower half of the crack surface shows the result of the final failure mode when the material became overstressed and failed.




Figure 5. Crack Surface Showing Upper Fatigue and Lower Overstress Failure.

The body of evidence shows that the seat frame failed due to fatigue. The source of the fatigue failure is due to an improper design or material defect. This problem could have been much more serious. It is however, not reasonable to charge me, the owner of the vehicle to repair what is clearly a design defect. A design defect that could have caused serious loss of life and property.

It is therefore requested that I be reimbursed in the amount of \$234.26, the cost to repair the vehicle. Attached is the invoice CTC528388 from George White of Ames, IA

Sincerely,



cc: NHTSA
Information Management, Staff NSA-10.01
400 7th Street, SW
Washington, DC 20590

