



AMERICAN SUZUKI MOTOR CORPORATION

March 12, 2010

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

RE: 10V-072

Dear Associate Administrator:

This concerns Nissan campaign number 10V-072. Nissan is conducting a recall campaign in the United States and also certain foreign countries. Because Nissan has submitted the attached Part 573 report, Nissan need not submit a Part 579 report for the same issue (49 CFR §579.11(d)(1)).

No Suzuki vehicles are affected domestically or abroad. However, because the 2009-2010 Suzuki Equator is substantially similar to the vehicles affected by this campaign, Suzuki is submitting this report pursuant to §579.11(a).

1. Name of Manufacturer

Nissan North America, Inc.

2. Identification of Motor Vehicles Potentially Involved

Please see Item 2 in the attached defect information report.

No Suzuki vehicles are affected domestically or abroad.

3. Total Number of Motor Vehicles Involved

Please see Item 3 in the attached defect information report. Approximately 25,000 Nissan vehicles outside the United States are also affected.

4. Description of Defect

Please see Item 5 in the attached defect information report.

5. Identification of Campaign Initiator, Campaign Type, and Program for Remedying Defect

Nissan is initiating a recall campaign in the United States and also in certain other affected markets. The NHTSA

campaign ID # is 10V-072. Please see Item 5 in the attached defect information report for the description of the corrective action.

6. Identification of Determination Date, Foreign Countries Involved, and Campaign Commencement Dates

Please see the attached defect information report. Please contact Nissan for additional information.


7. Identification of "Substantially Similar"¹ Vehicles Sold or Offered for Sale in the U.S.

2009-2010 Suzuki Equator.

Note: The reported issue does not affect Suzuki Equator vehicles sold in the U.S. or abroad.

Sincerely,

AMERICAN SUZUKI MOTOR CORPORATION



Kenneth M. Bush
Associate Director
Government Relations

¹ Vehicles identified in this letter as "substantially similar" under the broad definition specified in 49 CFR Part 579 can have significant differences in design, performance, durability, etc. The vehicles may not be "substantially similar" except for purposes of reporting under 49 CFR Part 579.

NISSAN

RECEIVED

By Recall Management Division at 11:03 am, Mar 03, 2010

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000

10V-072
(4 Pages)


February 26, 2010

Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
Room W48-302
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Sir:

We are transmitting the enclosed Defect Information Report in accordance with 49 CFR Part 573. A voluntary recall campaign will be initiated and your office provided with the notices. Nissan plans to notify owners on March 22, 2010. We will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy.

Very truly,



John Gibbons
Senior Manager,
Technical Compliance

Encl.

DEFECT INFORMATION REPORT

1. Manufacturer:

Nissan North America, Inc.

2. Vehicles Potentially Involved:

<u>Model</u>	<u>Dates of Manufacture</u>
MY 2008-2010 Nissan Titan	SOP 2008 through December 14, 2009
MY 2008-2010 Nissan Armada	SOP 2008 through December 14, 2009
MY 2008-2009 Nissan Quest	SOP 2008 through August 31, 2009
MY 2008-2010 Infiniti QX56	SOP 2008 through December 14, 2009

The affected vehicle production range was determined based on the production range of the affected part that may have been manufactured out of specification. Vehicles manufactured prior to and after these dates are not affected.

The brake pedal assembly supplier is:

KSR International
95 Erie Street South
Ridgetown, ON NOP 2C0
519-674-5413

Formerly:

Drivesol Worldwide
Kendalville, IN

3. Total Number of Vehicles Potentially Involved:

Approximately 179,383. The approximate number by Model and Model Year follows:

<u>Model</u>	<u>Number of Vehicles</u>
MY 2008-2010 Nissan Titan	84,729
MY 2008-2010 Nissan Armada	42,973
MY 2008-2009 Nissan Quest	21,794
MY 2008-2010 Infiniti QX56	29,887

4. Percentage of Vehicles Estimated to Actually Contain the Defect:

Nissan believes that the percentage of possible affected vehicles is extremely small. In fact, Nissan found this condition on only one vehicle in the United States, and received one field report from the Middle East related to this issue. Nevertheless, as explained below, out of an abundance of caution, Nissan will inspect potentially affected vehicles to ensure that the brake pedal pivot pin on these vehicles has been manufactured to specification.

5. Description of the Defect:

The brake pedal pivot pin end was not spin-formed to specification during the manufacturing process of the brake pedal assembly. If the pedal pivot pin end is not spin-formed, then the pivot pin may not remain in place. As pressure is applied to the pedal, there is a possibility that the pivot pin could slide and cause the brake pedal to partially disengage from the brake pedal bracket. If this occurs, the driver will experience unusual and noticeable looseness in the pedal and a reduction in braking force. The pedal remains partially attached to the mounting bracket and is still connected to the master cylinder.

6. Chronology of Principal Events:

December 14, 2009: Nissan received a field report of an improperly operating pedal. Nissan immediately instituted a factory and dealer inventory inspection and searched field data for similar issues. In addition, Nissan conducted a thorough inspection of factory parts supply.

January 4, 2010 - February 21, 2010: Nissan's comprehensive inspection of over 6,000 vehicles and parts did not identify any parts that were out of specification. Also, Nissan's search of field data did not find any other pedal pins that were not spun. Subsequently, Nissan was informed of one field report in the Middle East that was potentially related to this issue.

In addition to field investigation and inventory inspection, Nissan carefully reviewed the suppliers' manufacturing process and concluded that some brake pedal assemblies could have missed the final quality inspection.

February 22, 2010: As a precautionary measure, Nissan determined that a potential safety defect may exist. After this decision, an additional field report has been received from the Middle East, bringing the total to three field reports. Nissan is not aware of any reports of crashes or injuries possibly associated with this issue.

7. Description of Corrective Action:

Owners of all potentially affected vehicles will be notified and their brake pedal assembly will be inspected and replaced if necessary.

8. Copy of Notices:

Copies of all notices will be provided to NHTSA as they become available.