

ODI RESUME

INVESTIGATION: RQ98-0 23

DATE OPENED: 11-13-48

SUBJECT: Brake Rotor Disc/Hub Separation

PROMPTED BY: IE98-083

PRINCIPAL ENGINEER: Nha Nguyen

MANUFACTURER: Chrysler Corporation

MODEL(S): Cherokee

MODEL YEAR(S): 1992 through 1995 VEHICLE POPULATION: 200 K (est.)

PROBLEM DESCRIPTION: The brake rotor of the subject vehicles can corrode and separate at the

disc/bub area causing vehicle control problems and increasing braking distance.

FAILURE REPORT SUMMARY

TAILURE REPORT SUMMART			
	ODI	MANUFACTURER	TOTAL
COMPLAINTS:	15	0	15
CRASHES:	0	0	Û
INJ CRASHES:	0	0 1	0
#INJURIES:	0		. 0
FAT CRASHES:	0	O	0
#FATALS:	0	} 0	0
OTHER:		į l	

DESCRIPTION OF OTHER: None

ACTION: Recall Query has been opened.

ENGINEER: VN

DIV CHF:

SUMMARY: Chrysler conducted a safety recall, 98V-005, on January 5, 1998 involving approximately 225,000 1993 Grand Cherokee, 1990-91 Cherokee, Wrangler and Comanchee, and 1989-91 Eagle Premier and Dodge Monaco. The front disc brake rotors of these vehicles may experience severe corrosion if operated for an extensive period in the "salt belt" states. Owners in Connecticut, Illinois, Indiana, Maine, Massachuset, Maryland, Michigan, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Wisconsin, and the District of Columbia will receive replacement rotors that are coated with a corrosion protection. Chrysler began owner notification on March 9, 1998.

ODI has received 15 complaints from owners of model year 1992-95 Jeep Cherokee vehicles alleging that one or both of the front brake rotor disc had separated from its hub, causing the vehicles to severely pull to one side and/or significantly extended its stopping distance. Twelve of 15 complaints originated from within the recalled states.