

MSG NM= 194533 FR=VAOS TO=BB01 SENT=01/14/91 03:15 PM
RM=047 ST=C DIV=0050 CC=00134 BT=VAOS AT=01/14/91 03:15 PM

TO ED KADISEVSKIS MDES
JOHN KOURTESIS MDES

CC: DAVE ZARN ZARN
STAN HOMOL SH2
ED KADISEVSKIS MDES
SCOTT MARTIN MFPC
STEVE OFFILER SSO1
BILL SWEET PCME
ANDRE CHARPENTIER MDES
DICK GRIEPEY MFPC

FR: MATT SELLERS PCME

SUB: CCPS PRESSURE TESTER DISCUSSION MEETING MINUTES

BELOW IS A LIST OF COMMENTS/ACTIONS FROM OUR MEETING TODAY
CONCERNING THE NEW 77PS PRESSURE TESTER. SOME OF THESE ITEMS WILL
THROWN ON THE TABLE FOR FURTHER DISCUSSION AT OUR NEXT SCHEDULED
CCPS MECHANIZATION MEETING.

PLEASE REVIEW EACH ITEM AND PREPARE FOR DISCUSSION.

DO ERNS

MILLIVOLT TESTING

IS A MILLIVOLT DROP TEST BEING INCORPORATED IN THE NEW TESTER. IS
IT A DUPLICATION OF THE CURRENT 52PS/57PS PRESSURE TESTER
CAPABILITY? DESIGN HAS INDICATED THAT A 800ms/200mv/7v TEST IS
DESIRED/REQUIRED. IS THIS A POSSIBLE TEST SCENARIO IN THE 77PS
TESTER?

CREEP DETECTION

IS THE CREEP DETECTION THRESHOLD ADJUSTABLE LIKE THE 52PS/57PS
TESTER.

OVER-PRESSURE PRE-CYCLES

SPECIFIED @ 600PSI MINIMUM, TWO CYCLES REQUIRED. ARE WE LIMITED TO
300 PSI OR CAN WE CHANGE AT WILL UP TO THE SYSTEM PRESSURE. ALSO,
IS THE 1000 PSI MAX ON THE SYSTEM AN ARBITRARY CALL OUT BASED ON
SYSTEM DUPLICATIONS. CAN THIS BE ADJUSTED TO 1100, 1500 ???

HANDLING DAMAGE

IS THERE A RAMPED EJECTION SYSTEM IN PLACE TO MINIMIZE SUBSEQUENT
HANDLING DAMAGE TO THREADS, BASE ETC.

J512 SEAL & LEAK TEST

CONCERNS WERE DISCUSSED OVER THE ABILITY OF THE SYSTEM TO PERFORM
AN ACCURATE LEAK TEST GIVEN THE REDUCTION OF SEALING SURFACE AREA
ON THE J512 HEXPORT END. IS THE SURFACE AREA TOO SMALL?

TI-NHTSA 001656

ARE THERE ACCOMMODATIONS TO ALLOW FOR THE OFFSET KEY ON THE PASS CAR BASE WITHOUT INTERFERENCE IN THE NEST. ALSO, ARE THERE PLANS TO INSTALL A KEY LOCATION SENSING PROBE TO MOVE TO THE TEST.

ACTUATION/RELEASE SPECIFICATIONS

EDITH ROBERTS 5/29/90 SPEC. MEMO STATED 100PSI AS THE MINIMUM ACTUATION, AND 20PSI AS THE MINIMUM RELEASE. THE TRUE REQUIREMENTS ARE AS FOLLOWS:

ACTUATION: 90 PSI MINIMUM - 150 PSI MAXIMUM
RELEASE: 20 PSI MINIMUM - 750 PSI MAXIMUM

IS THIS A CONCERN?

LOW LEVEL LEAK TEST

ARE WE INCLUDING A TEST STATION ON THE OFF LOAD CONVEYOR, OR JUST LEAVING ROOM FOR FUTURE ADDITION.

SYSTEM OUTPUT CAPABILITIES

ARE THERE PLANS TO IMPROVE VISUAL ASPECTS OF THE OUTPUT BEYOND THE CURRENT CAPABILITIES. SUCH THINGS AS HISTOGRAMS, PARETOS, ETC.

LEAK RATE SPECIFICATION

CURRENT SPEC IS 8 PSI/SEC @ 500 PSI OR MAX ACTUATION PLUS 10%. DOES THIS MEAN THAT WE CAN TEST FOR PRESSURE DECAY BELOW 500 PSI, OR IS 500 PSI THE MINIMUM TEST PRESSURE. IF IT IS BELOW 500 PSI, CAN WE AD IT THE PSI/SEC DECAY SPECIFICATION AT WILL.

RAMP RATES

WE HAD TO SHUT OFF THE FAST UP VALVE ON THE 57PS PRESSURE TESTER TO ALLOW TESTING OF 125 AND 250 PSI ACTUATION DEVICES. THE FAST UP VALVE TENDED TO SHOOT THE APPLIED PRESSURE PAST THE ACTUATION TEST RANGE BEFORE THE SYSTEM COULD REACT. THEREFORE VOIDING THE TEST. ARE WE CONSIDERING THIS PROBLEM WITH THE NEW DESIGN.

EXPORT VARIATIONS

PLANS ARE TO POSSIBLY INCLUDE A METRIC HEXPORT IN THE 77PS LINE OF PRODUCTS. THE MAJOR DIAMETER OF THIS THREAD IS ABOUT .017" LARGER THAN THE J512 HEXPORT. WILL THIS CREATE A CONCERN OVER INTERFERENCE.

CATEGORIZATION OF BAD DEVICES

CURRENT PRIORITY IS AS FOLLOWS: B-LEAK, C-CONTINUITY FAIL, D-CREEP ACTUATION, E/F-ACTUATION HIGH OR LOW, G/H-RELEASE HIGH OR LOW, K-DIFFERENTIAL, L-RELEASE CREEP.

ARE THESE PRIORITIES REARRANGED EASY, AND CAN WE CHANGE THE CRITERIA FOR EACH FAILURE MODE.

I WOULD LIKE TO REVIEW THIS MEMO AT THE NEXT CCPS MECHANIZATION MEETING. HOWEVER IF YOU FEEL THAT A SEPERATE MEETING IS APPROPRIATE PLEASE CALL.

REGARDS...MATT

TI-NHTSA 001656

SAMPLE ORDER

ORDER NO: 0091-4
REQUEST DATE: 01/15/91
CREDIT ACCOUNT: 5902
COST CENTER: 131
PRODUCT CODE: 040

CUSTOMER: SURFACES
CUSTOMER P.O. NO: 28218
TI PART NO: 57PSL5-3
CUSTOMER PART NO: FEVC-9F924-AA
QUANTITY: 6

PRICE: \$20.00 EACH

DELIVERY PROMISED: 01/21/91

SPECIAL INSTRUCTIONS: USE OFFSET PLATING TRO

BILL TO:
SURFACES
(ADDRESS ON FILE)

SHIP TO:
SURFACES
(ADDRESS ON FILE)

PRODUCTION SAMPLES

XX ENGINEERING DEVELOPMENT SAMPLES
CC: ENGINEERING: STEVE OFFLER
PRODUCTION CONTROL: MARIE CROSSLAND
SALES ENGINEER: JOE SCHUCK

TI-NHTSA 001657

SAMPLE ORDER

ORDER NO: CD91-5

REQUEST DATE: 01/18/91

CREDIT ACCOUNT: 5902

COST CENTER: 101

PRODUCT CODE: 060

CUSTOMER: BENDIX

CUSTOMER P.O. NO: E179104

T1 PART NO: 77PSL2-1

CUSTOMER PART NO: N/A

QUANTITY: 5

PRICE: \$30.00 EACH

DELIVERY PROMISED: 2 - 1/31/91 (NON-FUNCTIONAL SAMPLES) *shipped 1-21-91*
3 - 2/21/91 (FUNCTIONAL SAMPLES)

SPECIAL INSTRUCTIONS:

BILL TO:
BENDIX AUTOMOTIVE SYSTEMS - NA
ATT'N: ACCOUNTS PAYABLE
P.O. BOX 4001
SOUTH BEND, IN 46634

SHIP TO:
BNA-ENGINEERING
PLANT 9
CORNER KENWOOD & BENDIX DRIVE
SOUTH BEND, IN 46628
ATT'N: ED SCHULTZ

PRODUCTION SAMPLES

XX ENGINEERING DEVELOPMENT SAMPLES

CC: ENGINEERING: STEVE OFFILER

PRODUCTION CONTROL: MARIE CROSSLAND

SALES ENGINEER: JOE SCHUCK

TI-NHTSA 001659

HIGHLIGHTS
Stephen B. Offler
Week Ending 01/18/91

Handwritten initials and date:
JTB
1/18/91



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

HEXPORT: No news from Stan Bragdon of SAE yet. I will recontact him mid-next week if I do not hear from him sooner.

We are looking into the chamfer gaging method using spherical shapes as opposed to cylindrical. I have completed calculations of the geometries involved to determine the best ball sizes to be using and the resolution they will provide. The larger-size ball (9/32") yields a total travel of 3.3 mils when applied to the standard J512 4 mil total tolerance, while the smaller-size ball (7/32") yields travel of 5.5 mils. We are prototyping this idea using ball bearings and a dial indicator. We plan to meet with TDR this morning to discuss the implementation of this concept, and after digesting this meeting we plan to recontact Elco as well. The spherical idea was conceived by Elco, and furthermore it is ultimately their responsibility to control/measure their process. We find ourselves involved because the final gaging technique must meet Ford's approval; that is, if we do not directly measure the chamfer and angle, then we must demonstrate to Ford via our control plan that the technique we use to infer these measurements is appropriate.

The tolerance relaxation experiment is complete. A report is planned ASAP, to be forwarded to interested Ford parties and to Stan Bragdon to support the paper analysis. No evidence of leakage whatsoever from any of the test matrix. Sectioning/disassembly is complete as well. The runout (included purposely) leaves obvious evidence; inspection shows the deformation of the brass seat to be obviously off-center. If both mating parts were similar grades of steel and runout was present, then it is reasonable to assume that significantly higher installation torques would be required to deform the components to the extent required to form a seal. Breakage of the hexport could become a factor in this instance; however we know of no such practices (smut on steel) in automotive brake lining practices. All mating findings pertinent to this program are aluminum or brass.

77PS PROTOTYPES: The model shop has delivered both terminals and spring arms, quantity 200. We have plenty of bases. Matt Sellers and Dave Peripoli are working on riveting and staking fixtures to allow build of completed switches. We expect to start building early next week. Parts will be built for calibrator evaluations, spring arm life testing, movable contact selection, and customer samples. Exact plan TBD soon.

SAMPLES, TESTING, MISC: We have received a request for five 77PS samples from Bendix. They conveyed an immediate need, but Charlie was able to ascertain that the need is for physical samples, with functional samples needed later. We will ship two non-functionals ASAP (clearly labelling them as such) with the balance of three functional devices to be shipped after life testing builds confidence in the design. Also, George Randall has a need for seventy-five 77PS devices in February.

We have missed the ship date for the Ford of Australia parts. The holdup is due to material and a collet required for the CNC lathe in B20 to produce metric hexports.

We are working with Print Control to put together parts lists for this program. We plan to begin with the Pass Car (57PSL5-3) parts list, holding off on the Truck (57PSL5-2) parts list until a hexport decision comes from Ford.

TI-NHTSA 001660

ML MM= 390930 FR=SB01 TO=ZARN SENT=01/22/81 09:15 PM
RW=199 ST=C DIV=0050 CC=00101 BY=SB01 DTG=01/22/81 09:15 PM

DI Tom Charbonneau	TC	Charlie Douglas	CRSC
Dave Czarn	ZARN	Joe Schuch	WMLI
Mike DeMattia	PDCA	Matt Halland	ECME

RI Steve Offiler SMY

J: SAE J512 Update

Ref: MSG #50387 or 846201

have been in contact again with Stan Bragdon. He has read and understood our report of the J512 tolerance startup problem and he related widening of tolerances, and duplicated our results with our own CAD layout. He has informed us that he is in complete agreement with our analysis.

As the plot thickens, however. Before he can stand behind the recommended changes and put forth a ballot, he must first complete similar analysis of all of the rest of the tabulated nominal plugging sizes. (My analysis was only concerned with the size we are using, 3/16". J512 lists eight sizes from 3/16" to 3/4".) Since his time is donated to SAE by his company, Parker-Hannifin, he cannot give this matter high priority, so it'll take some time to complete the analysis for the other seven sizes.

He has yet another concern. He told me that the J512 inverted flare seal system is designed to have a deformable member present (typically double-flared copper tubing, of course). He believes that some type of deformable member is needed for the plug too. He pointed out a copper "flare gasket" (Fig 38 of J513 Refrigeration Fittings) is normally used on J513 flares. He feels the lack of a gasket is an oversight in J512, and will be spending some time looking into this.

He responded with a brief description of the tolerance relaxation experiment and the fact that we've observed no leakage problem to date. Using dissimilar metals, the stronger one will deform the weaker one in absence of a deformable gasket. I plan to copy Stan on the final report of the experiment when it is completed.

Finally, I checked with Stan to make sure he had no objections to being contacted by George Randall to further discuss this issue from George's perspective. TI should initiate this conversation, I participate on a conference call if possible. Hopefully we can convince George with Stan's help.

Ards,
ve G.

TI-NHTSA 001681

-MBG MW- 1905 FR=PCQA TD=PCQA SENT=01/25/91 07117 AM
R#=079 ST=C DIV=0050 CC=00149 BY=CZRN AT=01/24/91 04:30 PM

JANUARY 24, 1991

TO:	BRIAN COUGHLIN	PEC	CC:	TOM CHARBONEAU	TC
	MIKE DeMATTIA	PCQA		JOHN KOURTESIS	MOES
	CHARLIE DOUGLAS	CPPC		STEVE MAJOR	WHLZ
	DICK GARIEPY	MFPC		ANDY McQUIRK	PCQA
	PAUL KOTCH	PRK1		ED O'NEILL	EJON
	JOE LAZARZ	JMLB		JOE SCHUCK	WHLZ
	BTEVE OFFILER	SBO1		GARY SNYDER	CPPC
	MATT SELLERS	PCME		MARTHA SULLIVAN	CPPC
	BILL SWEET	PCME		RAY TOURANGEAU	PCME
	GEORGE LAVOIE	B512		TED BAliARD	AVME
	JOHN HAYNEB	PCQA		DAVE VARNEY	FORM
				SCOTT MARTIN	MFPC
				CLAIRE BALTHAZAR	MFPC
				JOHN WILSON	JWP
FR:	DAVE CZARN	ZARN			

SJ: FORD CRUISE CONTROL PRESSURE SWITCH START-UP MEETING:
01/24/91 MEETING MINUTES

TI-NHTSA 001682

MEETING

=====

THE NEXT MEETING IS SCHEDULED FOR

DATE: 01/31 (THURSDAY)
 TIME: 10:00-11:30 AM
 PLACE: MARKETING CONFERENCE ROOM

* = NEW OR REVISED ITEMS

57 L/T

Hexport:

	WHO	WHEN	
* TOL. RELAXATION TEST REPORT	OFFILER	01/24	ORIG.
		01/24	COMP.
* J512 GAGE SKETCH TO PAUL KOTCH	OFFILER	01/23	DELETED
* J512 GAGE PRINT TO ELCO	SELLERS/ KOTCH	02/07	
* RELEASE GAGE FOR BUILD	SELLERS	02/07	
* TEST J512 GAGE CONCEPT	OFFILER	01/31	ORIG.
		01/24	COMP.
* SHOULD ELCO OR TI BUILD GAGE ?	CZARN	01/24	ORIG.
		01/24	COMP.
* F/U WITH AFCC RE: ELCO BLANKS	CZARN	01/24	ORIG.
		01/24	COMP.
. ELCO CONTROL PLAN (DELAYED DUE TO J512 GAGING DEFINITION)	KOTCH	01/17	ORIG.
		02/28	REV.
* RELEASE PRODUCTION HEXPORT (L/T)	SELLERS	02/08	
. ISIR corrective actions:			
. A. COINED BLADE TIP OVERSIZED - M.C. STUDY FROM AJ KNOTT	KOTCH	01/04	ORIG.
		01/31	REV.
. DISC LIFE TEST FROM EACH LOT	OFFILER/ GRIEPEY	02/14	
. L/T PILOT RUN	SELLERS/ GRIEPEY	01/24	ORIG.
		02/28	REV.
. CREATE L/T EIS PARTS LIST AND B.O.M. (ORIG. DATE WAS INCORRECT)	OFFILER/ WILSON	01/24	ORIG.
		03/07	REV.

57 P/C

* OFFSET POLARITY KEY BASE PRINT	OFFILER	11/16	ORIG.
		01/24	REV.
. P/C PILOT RUN	SELLERS/ GRIEPEY	01/31	ORIG.
		02/28	REV.
* CREATE P/C EIS PARTS LIST AND B.O.M.	OFFILER/ WILSON	01/24	ORIG.
		01/31	REV.
* DISCUSS TERMINAL LEAD-IN ANGLE WITH AJ KNOTT	SELLERS/ LAVOIE	01/31	ORIG.
		01/24	COMP.
* RELEASE P/C HEXPORT (P/N 36900)	SELLERS/ KOTCH	01/31	
. ESTABLISH LEADTIME FOR HEXPORT	KOTCH	01/31	

7PS

DESIGN UPDATE	OFFILER	ONGOING
MFG/MECH UPDATE	SELLERS	ONGOING
REPORT ON TOKICO P.S. RESPONSIBILITY	DOUGLAS	ONGOING
DESIGN FMEA -START	OFFILER	02/12
-COMPLETE		04/10

TI-NHTSA 001863

* PROVIDE START/FINISH DATE FOR FMEA	OFFILER	01/24	COMP.
		01/17	ORIG.
		01/24	REV.
		01/24	COMP.
* BEGIN CALIBRATOR EVALUATION	SELLERS	02/04	
* TEST PLAN FOR PROD. INTENT SWITCHES	OFFILER	01/10	ORIG.
		01/24	REV.
		01/24	COMP.
* CRITICAL PATH DESIGN ITEMS TO TRACK AT S/U MTGS.	OFFILER/	01/10	ORIG.
	CZARN	01/24	REV.
		01/24	COMP.
* "BLANKET PROTOTYPE ORDER" PACKAGE	TEAM	12/20	ORIG.
		01/24	REV.
		01/24	COMP.
* PROD. LINE LAYOUT	SELLERS	03/14	
* PROD. LINE SET-UP (RTE CARDS, ETC)	BALTHAZAR	TBD	
* RESOLVE BASE DELIV. SCHED. W/AFCC	SELLERS	02/07	
* ORDER ADD'L M.S. TERMS AND SPRINGS	OFFILER	02/07	
* PROVIDE DATES FOR COMP. OF 1ST PASS SPRING/CONTACT/PIN WINDOW TESTING	OFFILER	02/07	

IQP'S:

* ALUMINUM CRIMP RING	SELLERS	01/31
* REBUMP CUP	SELLERS	02/21
* MOVABLE TERM.	SELLERS	02/21
* STATIONARY TERM.	SELLERS	03/15
* BASE	SELLERS	02/28

PRODUCTION COMPONENTS:

* ALUMINUM CRIMP RING	LAVOIE	02/11
* REBUMP CUP	LAVOIE	02/27
* MOVABLE TERM.	LAVOIE	03/01
* STATIONARY TERM.	LAVOIE	03/22
* BASE	SELLERS	03/06
* HEXPORT	POTCH	03/22

MANUFACTURING EQUIPMENT:

* FINAL ASM MACHINE BUILD COMPLETION	SELLERS/	04/15
	KOURTESIS	
* PRESSURE TESTER BUILD COMPLETION	SELLERS/	05/01
	KOURTESIS	
* BASE ASM MACHINE BUILD COMPLETION	SELLERS/	05/31
	KOURTESIS	

FORD AUSTRALIA

* FORD AUSTRALIA UPDATE	DOUGLAS	ONGOING	
* SAMPLES FOR VP BUILD	OFFILER	01/17	ORIG.
		02/08	REV.

DISCUSSION

=====

57 L/T

WE MET WITH TDR TO REVIEW A J512 GAGE CONCEPT, USING THE BALL-BEARING MEASUREMENT TECHNIQUE. STEVE HAS EXPERIMENTED WITH THE TECHNIQUE AND IT SHOWS PROMISE. TDR HAS QUOTED \$3200 PER GAGE FOR 2 GAGES; DELIVERY IN 3 WEEKS. WE WILL PROPOSE TO ELCO THAT THEY PURCHASE ONE GAGE FROM US.

ELCO INFORMED US ON 01/23 THAT THE 21 HEXPORTS DUE ON 01/25 WILL BE DELAYED BY A "MINIMUM OF 3 WEEKS". THEIR SUPPORT OF THE PROGRAM CONTINUES TO BE IN QUESTION; HOWEVER, A 3 WEEK DELAY WILL MINIMALLY IMPACT OUR PLANS.

TI-NHTSA 001004

CHARLIE. WE PLAN TO DELIVER STEVE'S TOLERANCE RELAXATION TEST REPORT TO GEORGE ON FRIDAY, AND ALSO INFORM HIM OF OUR RECENT DISCUSSIONS WITH STAN BRAGDON OF THE SAE J512 COMMITTEE.

77 PS

EASTERN AUTOMATION, WHO IS DEVELOPING THE SPRING FORMING/SPRING ATTACHMENT MACHINE, WILL BE DEBUGGING IN MARCH. THEY AND MECHANIZATION HAVE ASKED US TO CONFIRM OUR ANGLE AND FORCE SPECIFICATIONS THAT APPEAR ON THE PRINT. STEVE WILL CONDUCT SOME FORCE-DEFLECTION MEASUREMENTS ON THE MODEL SHOP SPRINGS TO GIVE SOME PRELIMINARY FEEDBACK. EASTERN HAS NOT BUILT IN AN ADJUSTMENT STATION IN THE BENDING STATION, AND WE ARE UNSURE AT THIS POINT IF WE SHOULD MANDATE THIS.

PRODUCTION INTENT SWITCHES ARE CURRENTLY BEING BUILT FOR CALIFORNIA PROVE-OUT AND FOR DESIGN EVALUATION. THE LATTER INCLUDES TEST-TO-FAILURE OF THE SPRING, SUCCESS TESTING OF TWO CONTACT DESIGNS AND PIN WINDOW EVALUATION.

MILESTONES	PLANNED	ACTUAL
57 L/T IBIR	11/21/90	11/21/90
57 L/T JOB 1	07/01/91	
57 P/C IBIR	01/15/91	01/15/91
57 P/C JOB 1	06/03/91	
77PS IBIR	06/01/91	
77PS SOP (T1)	09/01/91	

PRODUCTION PLAN BY MONTH (THOUSANDS)

	P/C 57PSL5-3	L/T 57PSL5-2	P/C 77PSL2-1	L/T 77PSL2-2
FEB	0	0	0	0
MAR	5	0	0	0
APR	5	0	0	0
MAY	10	3	0	0
JUN	*17	4	0	0
JUL	17	*5	0	0
AUG	17	7	4	0
SEP	17	7	10	0
OCT	0	7	**12	5
NOV	0	7	17	7
DEC	0	0	17	**7

NOTE: PLAN FOR AUGUST AND BEYOND IS TENTATIVE.

* = JOB1 FOR 57PS VERSIONS

** = TENTATIVE JOB1 FOR 77PS VERSIONS

REGARDS,
DAVE CZARN 18-FORD

MS00320 - MSG Number 00001905 delivered from PCQA on 01/25/91 at 07:17 AM
The input was from PCQA at terminal LDRO The RECIPIENTS were:
PCQA PCQA PCQA

TI-NHTSA 001665

отв
срн

2225 177 11 1969

1	1000	1000
2	1000	1000
3	1000	1000
4	1000	1000
5	1000	1000
6	1000	1000
7	1000	1000
8	1000	1000
9	1000	1000
10	1000	1000
11	1000	1000
12	1000	1000
13	1000	1000
14	1000	1000
15	1000	1000
16	1000	1000
17	1000	1000
18	1000	1000
19	1000	1000
20	1000	1000
21	1000	1000
22	1000	1000
23	1000	1000
24	1000	1000
25	1000	1000
26	1000	1000
27	1000	1000
28	1000	1000
29	1000	1000
30	1000	1000
31	1000	1000
32	1000	1000
33	1000	1000
34	1000	1000
35	1000	1000
36	1000	1000
37	1000	1000
38	1000	1000
39	1000	1000
40	1000	1000
41	1000	1000
42	1000	1000
43	1000	1000
44	1000	1000
45	1000	1000
46	1000	1000
47	1000	1000
48	1000	1000
49	1000	1000
50	1000	1000
51	1000	1000
52	1000	1000
53	1000	1000
54	1000	1000
55	1000	1000
56	1000	1000
57	1000	1000
58	1000	1000
59	1000	1000
60	1000	1000
61	1000	1000
62	1000	1000
63	1000	1000
64	1000	1000
65	1000	1000
66	1000	1000
67	1000	1000
68	1000	1000
69	1000	1000
70	1000	1000
71	1000	1000
72	1000	1000
73	1000	1000
74	1000	1000
75	1000	1000
76	1000	1000
77	1000	1000
78	1000	1000
79	1000	1000
80	1000	1000
81	1000	1000
82	1000	1000
83	1000	1000
84	1000	1000
85	1000	1000
86	1000	1000
87	1000	1000
88	1000	1000
89	1000	1000
90	1000	1000
91	1000	1000
92	1000	1000
93	1000	1000
94	1000	1000
95	1000	1000
96	1000	1000
97	1000	1000
98	1000	1000
99	1000	1000
100	1000	1000

$\frac{1}{2} \leq \theta \leq 1$ $\frac{1}{2} \leq \theta \leq 1$ $\frac{1}{2} \leq \theta \leq 1$ $\frac{1}{2} \leq \theta \leq 1$

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-11-2015 BY 60322

1. **THEORY**

— 2 2 7 —

DATE 11-17-2000
TIME 1000-1130 AM
PLACE MARKETING CONFERENCE ROOM

PLEASE CALL ME IF YOU ARE NOT ABLE TO ATTEND

* - ITEMS NOT ALL OF WHICH HAVE BEEN REVIEWED BY EMPLOYER
BEFORE ISSUING NOTICE

[illegible]

* A. TERMINAL DIMENSIONS
* M.D. STUDIES FROM AJ KNOTT

[illegible]

Dave concentrating on
 Value - results will come
 in 5 yrs. FRPS.
 She's working this week
 initial exam
 trying to achieve
 charges by 3/21

~~REMOVAL DATE ONLY; CHANGE IN STAKEHOLDERS / ...03/07~~

[illegible]

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

2. Next, gather relevant information and data. This may involve research, consultation with experts, or collecting data from various sources.

3. Once the information is gathered, analyze it to identify patterns, trends, and key factors that influence the outcome.

4. Based on the analysis, develop a hypothesis or a proposed solution. This should be based on the evidence gathered and logical reasoning.

5. Test the hypothesis or solution through experiments, simulations, or practical applications. This step is crucial to validate the proposed solution.

6. Finally, evaluate the results and draw conclusions. This involves comparing the outcomes with the initial hypothesis and identifying any areas for improvement.

[illegible][illegible]

OFFICE	114
OFFICE	114
OFFICE	78
OFFICE	
OFFICE	06/01
OFFICE	07/00
OFFICE	07/15
OFFICE	07/15
OFFICE	08/01
OFFICE	08/01

02/28

- ALL-WEATHER DRIVE SHAFT
- REDUCE OIL
- MOVABLE TERM.
- STATIONARY TERM.
- BAGE
- (AFCD DELIV. DATE PUSH-OUT)
- EXPORT (R/N 26200)

LAVER	03/01	
LAVER	03/02	
LAVER	03/03	
LAVER	03/04	
SELLERS	03/05	CRIG.
	03/06	REV.
WITCH	03/07	

1. DATA ARE MISSING FOR CORRELATION
 2. DATA ARE MISSING FOR CORRELATION
 3. DATA ARE MISSING FOR CORRELATION

1990-1991	1.00
1991-1992	1.00
1992-1993	1.00
1993-1994	1.00
1994-1995	1.00
1995-1996	1.00
1996-1997	1.00
1997-1998	1.00
1998-1999	1.00
1999-2000	1.00
2000-2001	1.00
2001-2002	1.00
2002-2003	1.00
2003-2004	1.00
2004-2005	1.00
2005-2006	1.00
2006-2007	1.00
2007-2008	1.00
2008-2009	1.00
2009-2010	1.00
2010-2011	1.00
2011-2012	1.00
2012-2013	1.00
2013-2014	1.00
2014-2015	1.00
2015-2016	1.00
2016-2017	1.00
2017-2018	1.00
2018-2019	1.00
2019-2020	1.00
2020-2021	1.00
2021-2022	1.00
2022-2023	1.00
2023-2024	1.00
2024-2025	1.00
2025-2026	1.00
2026-2027	1.00
2027-2028	1.00
2028-2029	1.00
2029-2030	1.00
2030-2031	1.00
2031-2032	1.00
2032-2033	1.00
2033-2034	1.00
2034-2035	1.00
2035-2036	1.00
2036-2037	1.00
2037-2038	1.00
2038-2039	1.00
2039-2040	1.00
2040-2041	1.00
2041-2042	1.00
2042-2043	1.00
2043-2044	1.00
2044-2045	1.00
2045-2046	1.00
2046-2047	1.00
2047-2048	1.00
2048-2049	1.00
2049-2050	1.00
2050-2051	1.00
2051-2052	1.00
2052-2053	1.00
2053-2054	1.00
2054-2055	1.00
2055-2056	1.00
2056-2057	1.00
2057-2058	1.00
2058-2059	1.00
2059-2060	1.00
2060-2061	1.00
2061-2062	1.00
2062-2063	1.00
2063-2064	1.00
2064-2065	1.00
2065-2066	1.00
2066-2067	1.00
2067-2068	1.00
2068-2069	1.00
2069-2070	1.00
2070-2071	1.00
2071-2072	1.00
2072-2073	1.00
2073-2074	1.00
2074-2075	1.00
2075-2076	1.00
2076-2077	1.00
2077-2078	1.00
2078-2079	1.00
2079-2080	1.00
2080-2081	1.00
2081-2082	1.00
2082-2083	1.00
2083-2084	1.00
2084-2085	1.00
2085-2086	1.00
2086-2087	1.00
2087-2088	1.00
2088-2089	1.00
2089-2090	1.00
2090-2091	1.00
2091-2092	1.00
2092-2093	1.00
2093-2094	1.00
2094-2095	1.00
2095-2096	1.00
2096-2097	1.00
2097-2098	1.00
2098-2099	1.00
2099-2100	1.00
2100-2101	1.00
2101-2102	1.00
2102-2103	1.00
2103-2104	1.00
2104-2105	1.00
2105-2106	1.00
2106-2107	1.00
2107-2108	1.00
2108-2109	1.00
2109-2110	1.00
2110-2111	1.00
2111-2112	1.00
2112-2113	1.00
2113-2114	1.00
2114-2115	1.00
2115-2116	1.00
2116-2117	1.00
2117-2118	1.00

THE UNIVERSITY OF CHICAGO

522-523 524-525

1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 26

CLAUDE TO WHITT BY TELEPHONE, STATING THAT, "WARRS IS A REVE"
 "CLAUDE TO WHITT BY TELEPHONE, STATING THAT, "WARRS IS A REVE"
 "CLAUDE TO WHITT BY TELEPHONE, STATING THAT, "WARRS IS A REVE"
 "CLAUDE TO WHITT BY TELEPHONE, STATING THAT, "WARRS IS A REVE"

SAINT JOHN'S BAPTIST CHURCH, 1000 WEST 10TH AVENUE, DENVER, COLORADO, ADVISED THAT THE CHURCH HAS A RECORD OF A MEMBER, JOHN J. HARRIS, WHO WAS A MEMBER OF THE CHURCH FROM 1958 TO 1962. HARRIS WAS A MEMBER OF THE CHURCH DURING THE PERIOD OF THE CHURCH'S ACTIVITIES IN THE DENVER AREA. HARRIS WAS A MEMBER OF THE CHURCH DURING THE PERIOD OF THE CHURCH'S ACTIVITIES IN THE DENVER AREA. HARRIS WAS A MEMBER OF THE CHURCH DURING THE PERIOD OF THE CHURCH'S ACTIVITIES IN THE DENVER AREA.

CONTRIBUTION TO THE FACILITIES BEING MADE IS PROVIDED AS COMPENSATION FOR THE LATERAL ELEMENT THAT TAKES PLACE WITH THE SPRING ARMY UNITS. IT PRESENTS MAJOR LONG-TERM CONFLICTS, INCLUDING AND ELSEWHERE, AS WELL AS THE SITUATION FOR INTERVENTION. BEYOND THE AREA OF THE 1950. DURING THE PERIOD OF THE 1950S, INDICATES THE RECENT SITUATION.

The following table shows the results of the regression analysis for the dependent variable "Number of children in the household" (N = 1,000). The independent variables are "Age of the head of household" and "Gender of the head of household". The results are presented in the following table:

[illegible]

PRODUCTION PLAN BY MONTH (THOUSANDS)

	7/2 5798L-2	7/7 5798L-2	7/12 7798L-2-1	7/17 7798L-2-2
FEB	2	1	1	1
MAR	3	1	0	0
APR	3	1	0	1
MAY	10	2	0	1
JUN	*17	1	1	1
JUL	17	*5	0	0
AUG	17	7	4	0
SEP	17	7	10	0
OCT	1	1	*12	1
NOV	1	1	1	1
DEC	0	1	1	*1

1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 26

1. **DATE FOR THE REVIEW**

TI-NHTSA 001662

MSG MSG 1047L FR=JAMES TO=INPN SENT=140511Z 11Z 11Z 11Z 11Z
R0=0000 ST=C DTU=0000 CC=00104 R0=VAGS AT=01 25 11 11Z 11Z 11Z

01 STEPH HOMOL 342
ED LINDSEVSKIS MDEB
BROTHER MARTIN MDEB
STEVE OFFILER SBO1
ANDRE CHARPENTIER MDEB

02 DAVE CZARN ZARN
DICK GRIEPT MDEB
JOHN YOUTEES MDEB
BILL SWEET PCME

03 MATT BELLEPS PCME

04 CCPS PRESSURE TESTER MEETING MINUTES

THE FOLLOWING ARE MINUTES FROM OUR MEETING THIS WEEK CONCERNING THE
CCPS PRESSURE TESTER. DURING THE MEETING WE REVIEWED THE LIST OF
QUESTIONS DEVELOPED BY THE CCPS START-UP TEAM CONCERNING THE CCPS
PRESSURE TESTER.

MILLIVOLT TESTING

THERE WERE NO PLANS TO INCORPORATE A MILLIVOLT TEST BOARD IN THE
CCPS PRESSURE TESTER, AND THE CIRCUIT TYPE IS NOT THE SAME AS THE
57PS TESTER. WE HAVE AGREED THAT THIS WILL CHANGE. WE WILL NOW
INCORPORATE A CIRCUIT IDENTICAL TO THE 57PS TESTER. THE SCREEN
INPUT SELECTION WILL ALSO ALLOW OPERATOR TO MAKE CHANGES TO THE
MILLIVOLT THRESHOLD VALUE.

ACTIONS:

PROVIDE ANDRE C. WITH PROPER CURRENT/VOLTAGE
VALUES FOR THE TEST. STEVE 1/20
INCORPORATE MILLIVOLT CIRCUIT UPGRADE. ANDRE ASAP

CREEP DETECTION

THE CREEP DETECTION MILLISECOND VALUE WILL BE ADJUSTABLE THROUGH
SCREEN INPUT AS IN THE 57PS TESTER.

NO ACTIONS REQUIRED.

OVER-PRESSURE PRE-CYCLES

IT WAS DISCUSSED THAT OVERPRESSURE PRE-CYCLES ARE ADJUSTABLE TO
0.00PS WITHOUT CONCERN OVER SEAL LIFE DEGRADATION.

NO ACTIONS REQUIRED.

HANDLING DAMAGE

IT WAS DISCUSSED THAT HANDLING DAMAGE TO THE TESTER WILL BE

TI-NW7SA 001000

ALL ALREADY BE PROVIDED BY WHAT IS A THREAD ASSEMBLY. IT IS
INSTALLED IN-LINE AFTER PRESSURE TEST PRIOR TO COMPLETION.

ACTIONS:

PROVIDE PUMP SECTION IS PRESENT IN DESIGN.

ED 1/27

712 SEAL & LEAK TEST

7PS TESTED USES A POLYURETHANE BLOCK THAT PRESSES AGAINST THE
EXPORT DOG-POINT END DURING THE TEST CYCLE. THIS SAME METHOD WILL
BE USED FOR CCPS. HOWEVER, MECHANIZATION HAS INDICATED THAT THERE
MAY BE A CONCERN OVER BLOCK LIFE AS A RESULT OF THE SHARPER AREA
IT COMES INTO CONTACT WITH. HIGHER MAINTENANCE FREQUENCY WILL
PROBABLY RESULT. SEAL EFFECTIVENESS CONCERNS AS A RESULT OF THE
SMALL SURFACE AREA ON THE JETIC HAVE BEEN VOIDED. MECHANIZATION
FEELS NO PROBLEMS WOULD BE EXPECTED.

ACTIONS:

PROVIDE BILL/MATT WITH URETHANE BLOCK
PRINT.

ED 1/27

QUOTE OUTSIDE SUPPLIERS.

BILL/MATT 1/28

PASS CAR OFFSET POLARITY KEY

THE OFFSET KEY LOCATION OF THE PASS CAR VERSION WAS NOT
INCORPORATED IN THE ORIGINAL PROPOSAL. MECHANIZATION FEELS THAT THE
ACCOMMODATIONS WILL BE MINOR AT FIRST GLANCE.

ACTIONS:

PROVIDE ED WITH 44515 PRINT.

MATT 1/29

EVALUATE CHANGES REQUIRED AND ADVISE MATT.

ED 2/1

ACTUATION/RELEASE SPECIFICATIONS

THE UPDATE TO THE ORIGINAL ACTUATION/RELEASE SPEC WILL NOT BE A
PROBLEM, AND NO ACCOMMODATIONS ARE REQUIRED. THE NEW SPEC IS:

ACTUATION: 90 PSI MINIMUM - 850 PSI MAXIMUM
RELEASE: 20 PSI MINIMUM - 750 PSI MAXIMUM

ACTIONS:

PROVIDE ED WITH UPDATED ENVELOPE PRINT.

MATT 1/29

0 LEVEL LEAK TEST

THIS WOULD INCREASE CYCLE TIME DRAMATICALLY, AND IS SUBJECT TO
TECHNICAL EVALUATION AS TO THE PROPER METHOD. THE 7PSI RANGE MAY
PRESENT SOME DIFFICULTIES. WE ARE NOT PURSUING THIS TEST ON THE
CCPS PRODUCT.

END OF PAGE

TI-NHTSA 001670

SEA VALVE SPECIFICATION

PLANS TO INCORPORATE AN OPGI SEC DECAY RATE THRESHOLD ON THE CCPS TESTER HAVE BEEN DETERMINED BY DESIGN TO BE INADEQUATE. GIVEN THE LOWER OPERATING PRESSURES OF THE CCPS PRODUCTS WE MAY WANT TO OBTAIN LEAK TESTING UNDER DIFFERENT CONDITIONS. THIS REPRESENTS AN UNUSUAL EFFORT ON THE PART OF THE EQUIPMENT DESIGN. THEREFORE, WE WILL PROVIDE AN ADJUSTABLE LEAK TEST SET-UP THROUGH DESIGN INPUT.

ACTIONS:

SOFTWARE PROVISION THAT WILL ALLOW MANIPULATION OF LEAK TEST CRITERIA.

ANDRE -SEA-

AMP RATES

PROBLEMS ENCOUNTERED WITH THE 57PS TESTER WITH RESPECT TO THE PASS OR VALVE OVER-SHOOT ARE BEING ACCOUNTED FOR IN THE CCPS TESTER DESIGN.

ACTIONS:

VERIFY THAT THIS PROBLEM IS CORRECTED.

ANDRE ASAF

EXPORT VARIATIONS

THE INCORPORATION OF A HEXPORT WITH A MAJOR O.D. INCREASE OF 1.11" IS NOT PRESENT AN INTERFERENCE PROBLEM WITH TESTER MESTING.

NO ACTIONS REQUIRED.

CATEGORIZATION OF BAD DEVICES

WE DISCUSSED THE INCORPORATION OF A NEW FALLOUT CATEGORIZATION METHOD. THE CURRENT TESTER PRESENTS THE OPERATOR WITH A REASON RANK FOR FALLOUT ACCORDING TO A PRIORITY HIERARCHY. IF MULTIPLE PROBLEMS EXIST WITHIN A DEVICE, THE SYSTEM IGNORES PROBLEMS LOWER IN THE HIERARCHY LIST AND DISCARDS THE DATA. AS AN ENGINEERING TOOL, THIS DISCARDED DATA MAY BE USEFUL. WE DISCUSSED SETTING UP A SYSTEM THAT WILL GENERATE A REPORT THAT TRACKS MULTIPLE DISCREPANCIES WITHIN A DEVICE, AND WOULD BE CAPABLE OF SUMMARIZING THE DATA ON A PERIODIC BASIS. SUCH A SYSTEM MAY PROVIDE SOME INSIGHT DURING TROUBLE ANALYSIS.

ACTIONS:

WORK OUT A MATRIX OF REALISTIC MULTIPLE DISCREPANCY SCENARIOS.

STAVE/STAN/
MATT 100

REVIEW PROPOSED MATRIX AND INCORPORATE TESTING PROCESS INTO SOFTWARE.

ANDRE ASAF

END OF PAGE

TLNH78A 001671

-MSG MN= 104533 FR=VAGS TO=SB01 SENT=01/14/91 03:15 PM
RR=067 BT=C DIV=0050 CC=00134 BY=VAGS AT=01/14/91 03:25 PM

TO ED MADISEVSKI MDES
JOHN KOURTESIS MDES

CC: DAVE ZARN ZARN
STAN HOMOL SHC
ED MADISEVSKI MDES
SCOTT MARTIN MFPC
STEVE OFFILER SB01
BILL SWEET PCME
ANDRE CHARPENTIER MDES
DICK GARIEPY MFPC

FR: MATT SELLERS PCME

SUB: CCPS PRESSURE TESTER DISCUSSION MEETING MINUTES

BELOW IS A LIST OF COMMENTS/ACTIONS FROM OUR MEETING TODAY
CONCERNING THE NEW 77PS PRESSURE TESTER. SOME OF THESE ITEMS WILL
THROWN ON THE TABLE FOR FURTHER DISCUSSION AT OUR NEXT SCHEDULED
CCPS MECHANIZATION MEETING.

PLEASE REVIEW EACH ITEM AND PREPARE FOR DISCUSSION.

CD TRNS

MILLIVOLT TESTING

IS A MILLIVOLT DROP TEST BEING INCORPORATED IN THE NEW TESTER. IS
IT A DUPLICATION OF THE CURRENT 52PS/57PS PRESSURE TESTER
CAPABILITY? DESIGN HAS INDICATED THAT A 800ms/200mv/7v TEST IS
DESIRED/REQUIRED. IS THIS A POSSIBLE TEST SCENARIO IN THE 77PS
TESTER?

CREEP DETECTION

IS THE CREEP DETECTION THRESHOLD ADJUSTABLE LIKE THE 52PS/57PS
TESTER.

OVER-PRESSURE PRE-CYCLES

SPECIFIED @ 800PSI MINIMUM, TWO CYCLES REQUIRED. ARE WE LIMITED TO
300 PSI OR CAN WE CHANGE AT WILL UP TO THE SYSTEM PRESSURE. ALSO,
IS THE 1000 PSI MAX ON THE SYSTEM AN ARBITRARY CALL OUT BASED ON
SYSTEM DUPLICATIONS. CAN THIS BE ADJUSTED TO 1100, 1500 ???

HANDLING DAMAGE

IS THERE A RAMPED EJECTION SYSTEM IN PLACE TO MINIMIZE SUBSEQUENT
HANDLING DAMAGE TO THREADS, BASE ETC.

J512 SEAL & LEAK TEST

CONCERNS WERE DISCUSSED OVER THE ABILITY OF THE SYSTEM TO PERFORM
AN ACCURATE LEAK TEST GIVEN THE REDUCTION OF SEALING SURFACE AREA
ON THE J512 HEYPORT END. IS THE SURFACE AREA TOO SMALL?

TI-NHTSA 001672

ARE THERE ACCOMMODATIONS TO ALLOW FOR THE OFFSET 1/8" ON THE PASS CAR BASE WITHOUT INTERFERENCE IN THE NEST. ALSO, ARE THERE PLANS TO INSTALL A KEY LOCATION SENSING PROBE TO POKE FOR THE TEST.

ACTUATION/RELEASE SPECIFICATIONS

JEITH ROBERTS' 5/29/90 SPEC. MEMO STATED 100PSI AS THE MINIMUM ACTUATION, AND 25PSI AS THE MINIMUM RELEASE. THE TRUE REQUIREMENTS ARE AS FOLLOWS:

ACTUATION: 90 PSI MINIMUM - 850 PSI MAXIMUM
RELEASE: 20 PSI MINIMUM - 750 PSI MAXIMUM

IS THIS A CONCERN?

LOW LEVEL LEAK TEST

ARE WE INCLUDING A TEST STATION ON THE OFF LOAD CONVEYOR, OR JUST LEAVING ROOM FOR FUTURE ADDITION.

SYSTEM OUTPUT CAPABILITIES

ARE THERE PLANS TO IMPROVE VISUAL ASPECTS OF THE OUTPUT BEYOND THE CURRENT CAPABILITIES. SUCH THINGS AS HISTOGRAMS, PARETOS, ETC.

LEAK RATE SPECIFICATION

CURRENT SPEC IS 8 PSI/SEC @ 500 PSI OR MAX ACTUATION PLUS 10%. DOES THIS MEAN THAT WE CAN TEST FOR PRESSURE DECAY BELOW 500 PSI, OR IS 500 PSI THE MINIMUM TEST PRESSURE. IF IT IS BELOW 500 PSI, CAN WE ADAPT THE PSI/SEC DECAY SPECIFICATION AT WILL.

RAMP RATES

WE HAD TO SHUT OFF THE FAST UP VALVE ON THE 57PS PRESSURE TESTER TO ALLOW TESTING OF 125 AND 250 PSI ACTUATION DEVICES. THE FAST UP VALVE TENDED TO SHOOT THE APPLIED PRESSURE PAST THE ACTUATION TEST RANGE BEFORE THE SYSTEM COULD REACT. THEREFORE VOIDING THE TEST. ARE WE CONSIDERING THIS PROBLEM WITH THE NEW DESIGN.

EXPORT VARIATIONS

PLANS ARE TO POSSIBLY INCLUDE A METRIC EXPORT IN THE 77PS LINE OF PRODUCTS. THE MAJOR DIAMETER OF THIS THREAD IS ABOUT .017" LARGER THAN THE J512 EXPORT. WILL THIS CREATE A CONCERN OVER INTERFERENCE.

CATEGORIZATION OF BAD DEVICES

CURRENT PRIORITY IS AS FOLLOWS: B-LEAK, C-CONTINUITY FAIL, D-CREEP ACTUATION, E/F-ACTUATION HIGH OR LOW, G/H-RELEASE HIGH OR LOW, V-DIFFERENTIAL, L-RELEASE CREEP.

ARE THESE PRIORITIES REARRANGED EASY, AND CAN WE CHANGE THE CRITERIA FOR EACH FAILURE MODE.

I WOULD LIKE TO REVIEW THIS MEMO AT THE NEXT CCPS MECHANIZATION MEETING. HOWEVER IF YOU FEEL THAT A SEPERATE MEETING IS APPROPRIATE PLEASE CALL.

REGARDS...MATT

MSG MSG- 10470 PP-VAGS TO-ZARN SENT=01/25/91 0712Z AM
RM=000 ST=C DIV=0000 CC=00134 BY=VAGS AT=01/25/91 0712Z AM

01 STAFF MEMORIAL SHQ
ED MACISEVSI IS MDES
GUYE MARTIN MFC
STEVE OFFILER SBD
ANDRE CHARPENTIER MDES

02 DAVE CZARN ZARN
DICK DARIEPY MFC
JOHN FOURTESIS MDES
BILL SWEET PCME

R1 MATT SELLERS PCME

03 CCPS PRESSURE TESTER MEETING MINUTES

THE FOLLOWING ARE MINUTES FROM OUR MEETING THIS WEEK CONCERNING THE
CCPS PRESSURE TESTER. DURING THE MEETING WE REVIEWED THE LIST OF
QUESTIONS DEVELOPED BY THE CCPS START-UP TEAM CONCERNING THE CCPS
PRESSURE TESTER.

MILLIVOLT TESTING

WE WERE NO PLANS TO INCORPORATE A MILLIVOLT TEST BOARD IN THE
CCPS PRESSURE TESTER, AND THE CIRCUIT TYPE IS NOT THE SAME AS THE
57PS TESTER. WE HAVE AGREED THAT THIS WILL CHANGE. WE WILL NOW
INCORPORATE A CIRCUIT IDENTICAL TO THE 57PS TESTER. THE SCREEN
INPUT SELECTION WILL ALSO ALLOW OPERATOR TO MAKE CHANGES TO THE
MILLIVOLT THRESHOLD VALUE.

ACTIONS:

PROVIDE ANDRE C. WITH PROPER CURRENT/VOLTAGE
VALUES FOR THE TEST. STEVE 1/29
INCORPORATE MILLIVOLT CIRCUIT UPGRADE. ANDRE ASAP

CREEP DETECTION

THE CREEP DETECTION MILLISECOND VALUE WILL BE ADJUSTABLE THROUGH
SCREEN INPUT AS IN THE 57PS TESTER.

NO ACTIONS REQUIRED.

OVER-PRESSURE PRE-CYCLES

IT WAS DISCUSSED THAT OVERPRESSURE PRE-CYCLES ARE ADJUSTABLE TO
0.00PSI WITHOUT CONCERN OVER SEAL LIFE DEGRADATION.

NO ACTIONS REQUIRED.

LANDING DAMAGE

WE WILL BE A RAMPED DEJECTION SYSTEM THAT WILL REDUCE THE

TI-NHTSA 001674

LEAK RATE SPECIFICATION

PLANS TO INCORPORATE AN SFBI/SEC DECAY RATE THRESHOLD ON THE CCPS TESTER HAVE BEEN DETERMINED BY DESIGN TO BE INADEQUATE. GIVEN THE LOWER OPERATING PRESSURES OF THE CCPS PRODUCTS WE MAY WANT TO PERFORM LEAK TESTING UNDER DIFFERENT CRITERIA. THIS PRESENTS NO UNORDINARY EFFORT ON THE PART OF THE EQUIPMENT DESIGN. THEREFORE, WE WILL PROVIDE AN ADJUSTABLE LEAK TEST SET-UP THROUGH CRESH INPUT.

ACTIONS:

SOFTWARE PROVISION THAT WILL ALLOW MANIPULATION OF LEAK TEST CRITERIA.

ANDRE AGAP

AMP RATES

PROBLEMS ENCOUNTERED WITH THE STPS TESTER WITH RESPECT TO THE FAST HP VALVE OVER-SHOOT ARE BEING ACCOUNTED FOR IN THE CCPS TESTER DESIGN.

ACTIONS:

VERIFY THAT THIS PROBLEM IS CORRECTED.

ANDRE AGAP

EXPORT VARIATIONS

THE INCORPORATION OF A HEXPORT WITH A MAJOR Q.D. INCREASE OF .019" DI NOT PRESENT AN INTERFERENCE PROBLEM WITH TESTER MESSING.

NO ACTIONS REQUIRED.

CATEGORIZATION OF BAD DEVICES

WE DISCUSSED THE INCORPORATION OF A NEW FALLOUT CATEGORIZATION METHOD. THE CURRENT TESTER PRESENTS THE OPERATOR WITH A 'REASON RAO' FOR FALLOUT ACCORDING TO A PRIORITY HIERARCHY. IF MULTIPLE PROBLEMS EXIST WITHIN A DEVICE, THE SYSTEM IGNORES PROBLEMS LOWER IN THE HIERARCHY LIST AND DISCARDS THE DATA. AS AN ENGINEERING TOOL, THIS DISCARDED DATA MAY BE USEFUL. WE DISCUSSED SETTING UP A SYSTEM THAT WILL GENERATE A REPORT THAT TRACKS MULTIPLE DISCREPANCIES WITHIN A DEVICE, AND WOULD BE CAPABLE OF SUMMARIZING THE DATA ON A PERIODIC BASIS. SUCH A SYSTEM MAY PROVIDE SOME INSIGHT DURING TROUBLE ANALYSIS.

ACTIONS:

WORK OUT A MATRIX OF REALISTIC MULTIPLE DISCREPANCY SCENARIOS.

STAVE/STAN/
MATT 1/30

REVIEW PROPOSED MATRIX AND INCORPORATE REPORTING PROCESS INTO SOFTWARE.

ANDRE AGAP

FRANKS...MATT

TI-NHTSA 001675

HIGHLIGHTS
Stephen B. Offler
Week Ending 01/25/91



FORD MY '92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

HEXPORT: Stan Bragdon of the SAE J512 committee has recontacted us regarding our proposed changes to J512. He agrees with our graphical analysis, and is leaning towards bringing our recommended changes to the committee. However, he must perform similar analyses on each nominal tubing size; our analysis concerned itself only with our particular size. Furthermore, he feels that a deformable element must be present; normally this is the flared brake tubing. Of course, no tubing exists with our plug geometry. Stan referred me to J513f, Refrigeration Fittings, where a "Flare Gasket" is described. He's looking into the possibility that J512 is in error, and that a gasket of this type was originally intended for J512 in the absence of tubing. *Bottom line:* resolution of this issue will come eventually now that the ball is rolling, but it will not be quick enough to be useful in our negotiations with George Randall.

I have completed a 32-page report of the results of our testing of the new, proposed J512 dimensions. All combinations of worst-case tolerance stack-ups passed all tests. We noted that in every case, the steel hexport (plug geometry) deformed the brass seating port in making a seal. This lends credence to Stan's idea of a flare gasket, although it seems application would be required only in the case of steel-on-steel. Dave Cram is hand-delivering copies of this report today to Bruce Pease and George Randall, and I have sent one to Stan as well. Additional copies are available, see me.

We have met with Howard Nelson of T-D-R Co. Inc. regarding a real-world implementation of the J512 chamfer gaging concept using spherical shapes. We brainstormed an approach and developed very rough sketches of the required fixtures. He has responded with a rough quote of \$6400 for design/build of two gages, one for us and one for Elco. We plan to proceed with this. Mfg. Eng. will impose some type of contract with T-D-R which holds them responsible for guaranteeing an acceptable R&R. Elco has tentatively agreed to pick up half of the tab.

SAMPLES, CUSTOMER ISSUES: SREA's (Supplier Request for Engineering Approval) have been written, proposing the removal of the problematic terminal-position tolerance on the envelope prints. Our position on this issue is described in the vantage: the tight tolerance is based on insert-molding process capabilities; none of our present Ford power-steering or brake switches include this tolerance; and we have shipped approx. 100K switches to date with zero terminal-related RMR's. Dave Cram is hand-delivering the SREA's today.

Bruce Pease requested that the latest envelope print iteration include a description of the revisions directly on the print. This is because the latest changes are all J512 related, and he wants absolutely clear documentation. Drafting has added the revision detail in the upper-right corner of the prints. These were omitted to Bruce yesterday. He is releasing these prints, which casts the new, modified J512 tolerances in concrete.

Twenty "Functional Build" Light Truck 57PS's were shipped. These are production-level parts, which assume completion of ISIR, and which are shipped directly to B&A. The required special paperwork was completed, along with a functional build tag affixed to each of the twenty switches.

TI-NHTSA 001676



SAMPLES, CONTINUED: Six Pass-Car samples were shipped to Surface. These are the first parts shipped (other than a few direct to Bruce) to use the offset key bases. We are coloring the keys black (on gray bases) at Bruce's request to help differentiate these parts. This procedure will continue until SOP.

Mike McHugh reports that he is presently building metric hexports for the Ford of Australia samples. Part of the delay has been caused by the need to obtain the correct lathe collet and the correct material. I have informed him that in the future he may use certain alternate materials which are typically available from AFCC Screw Machines. Charlie has contacted F of A to inform them of the delay. These parts originally should have shipped 01/10 for receipt by 01/17.

77PS: The final review of the production 46515 base mold design was held. Various issues such as cavity ID's, tolerances in historically problematic areas, and interference tab details were discussed and will be updated on 46515 as soon as possible.

Dave Pulpoll has completed seal modifications to allow threading and seating of prototype 77PS components. We have built about 30 switch assemblies to date. Most of these will be used by Mechanization in calibrator debug. We are making plans to build more, and to have the model shop create more terminals and springs, to be used for spring life testing, contact testing, pin window experiments, calibrator debug, and customer samples.

A meeting was held with Mechanization to discuss details of the 77PS program later. Highlighted items include: millivolt drop measurement and contact definition; design of the polyurethane seal, recognizing the geometry of the J512 hexport end; leak check runs at the lower 77PS act/rel pressures and the minimum resolution of the transducers; accommodations in fixturing for the offset-key bases; and comparison of failures, recognizing the deficiencies of the present failure prioritization system. STANJ

MISCELLANEOUS: We are presently working with Drafting to set up Parts List for the 57PS Pass-Car devices, which also involves the addition of dash numbers to various established 57 component and subassembly drawings. We are holding off on Light Truck until the end of January when resolution of the hexport issue is expected.

NO-HOLE SPACER, STAN?
AND NOTES W/O HOLE

-3-

AND PART, ONE YEAR...
-2. THE HOLE IN THE

-1 ONLY ONE W/ HOLE

HIGHLIGHTS
Stephen B. Offler
Week Ending 01/25/91

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

HEXPORT: Stan Bragdon of the SAE J512 committee has recontacted us regarding our proposed changes to J512. He agrees with our graphical analysis, and is leaning towards bringing our recommended changes to the committee. However, he must perform similar analyses on each nominal tubing size; our analysis concerned itself only with our particular size. Furthermore, he feels that a deformable element must be present; normally this is the flared brake tubing. Of course, no tubing exists with our plug geometry. Stan referred me to J513f, Refrigeration Fittings, where a "Flare Gasket" is described. He's looking into the possibility that J512 is in error, and that a gasket of this type was originally intended for J512 in the absence of tubing. *Bottom line:* resolution of this issue will come eventually now that the ball is rolling, but it will not be quick enough to be useful in our negotiations with George Randall.

I have completed a 32-page report of the results of our testing of the new, proposed J512 dimensions. All combinations of worst-case tolerance stack-ups passed all tests. We noted that in every case, the steel hexport (plug geometry) deformed the brass mating port in making a seal. This lends credence to Stan's idea of a flare gasket, although it seems application would be required only in the case of steel-on-steel. Dave Czarn is hand-delivering copies of this report today to Bruce Pease and George Randall, and I have sent one to Stan as well. Additional copies are available, see me.

We have met with Howard Nelson of T-D-R Co. Inc. regarding a real-world implementation of the J512 chamfer gaging concept using spherical shapes. We brainstormed an approach and developed very rough sketches of the required fixture. He has responded with a rough quote of \$6400 for design/build of two gages, one for us and one for Elco. We plan to proceed with this. Mfg. Eng. will impose some type of contract with T-D-R which holds them responsible for guaranteeing an acceptable R&R. Elco has tentatively agreed to pick up half of the tab.

SAMPLES. CUSTOMER ISSUES: SREA's (Supplier Request for Engineering Approval) have been written, proposing the removal of the problematic terminal-position tolerance on the envelope prints. Our position on this issue is described in the verbiage: the tight tolerance is based on insert-molding process capabilities; none of our present Ford power-steering or brake switches include this tolerance; and we have shipped approx. 10KK switches to date with zero terminal-related RMR's. Dave Czarn is hand-delivering the SREA's today.

Bruce Pease requested that the latest envelope print iteration include a description of the revisions directly on the print. This is because the latest changes are all J512 related, and he wants absolutely clear documentation. Drafting has added the revision detail in the upper-right corner of the prints. These were overmited to Bruce yesterday. He is releasing these prints, which casts the new, modified J512 tolerances in concrete.

Twenty "Functional Build" Light Truck 57PS's were shipped. These are production-level parts, which assume completion of ISIR, and which are shipped directly to B&A. The required special paperwork was completed, along with a functional build tag affixed to each of the twenty switches.

HIGHLIGHTS 91-01-25

Page 2

SAMPLES, CONTINUED: Six Pass-Car samples were shipped to Surfaces. These are the first parts shipped (other than a few direct to Bruce) to use the offset key bases. We are coloring the keys black (on gray bases) at Bruce's request to help differentiate these parts. This procedure will continue until SOP.

Mike McHugh reports that he is presently building metric hexports for the Ford of Australia samples. Part of the delay has been caused by the need to obtain the correct lathe collet and the correct material. I have informed him that in the future he may use certain alternate materials which are typically available from APCC Screw Machines. Charlie has contacted F of A to inform them of the delay. These parts originally should have shipped 01/10 for receipt by 01/17.

77PS: The final review of the production 46515 base mold design was held. Various items such as cavity ID's, tolerances in historically problematic areas, and interference tab details were discussed and will be updated on 46515 as soon as possible.

Dave Peripoli has completed tool modifications to allow riveting and staking of prototype 77PS components. We have built about 50 switch assemblies to date. Most of these will be used by Mechanization in calibrator debug. We are making plans to build more, and to have the model shop create more terminals and springs, to be used for spring life testing, contact testing, pin window experiments, calibrator debug, and customer samples.

A meeting was held with Mechanization to discuss details of the 77PS pressure tester. Highlighted items include: millivolt drop measurement and continuity definition; design of the polyurethane seal, recognizing the geometry of the J512 hexport end; leak check rates at the lower 77PS act/rel pressures and the minimum resolution of the transducers; accommodations in fixturing for the offset-key bases; and categorization of failures, recognizing the deficiencies of the present failure prioritization system.

MISCELLANEOUS: We are presently working with Drafting to set up Parts Lists for the 57PS Pass-Car devices, which also involves the addition of dash numbers to various established 57 component and subassembly drawings. We are holding off on Light Truck until the end of January when resolution of the hexport issue is expected.

-MSG #6- 62145 FR-CZRN TO-PCOA SENT=01/28/91 11:56 AM
R#-131 ST=C DIV=0050 CC=00101 BY=CZRN AT=01/28/91 11:56 AM

TO: STEVE OFFILER SRO1 CC: TOM CHARBONNEAU TC
CHARLIE DOUGLAS CPFC GARY SNYDER CPFC
MATT SELLERS PCHE MARTHA SULLIVAN CPFC
BILL SWEET PCHE ANDY McGUIRK PCOA
MIKE DEMATTIA PCOA STEVE MAJOR MLT
JOHN HAYNES PCOA ED O'NEILL EJOH
JOE SCHUCK MLT
PAUL KOTCH PRK1
FR: DAVE CZARN ZARN
RE: FORD TRIP REPORT - CRUISE CONTROL PRESSURE SWITCH

MEETING DATE: 01/25/91

ATTENDEES: BRUCE PEASE - RELEASE ENGINEER P/C BRAKE
GEORGE RANDALL - RELEASE ENGINEER L/T NOBC
JOE SCHUCK
DAVE CZARN

OVERVIEW:

- GEORGE AND BRUCE HAVE BOTH AGREED TO REMOVE THE TERMINAL POSITIONAL TOLERANCE FROM THE PRINTS (57 AND 77 STYLE), ALLOWING US FULL IER APPROVAL FOR THE 57PS VERSIONS.
- IT IS LIKELY THAT BOTH L/T AND P/C WILL APPROVE THE RELAXED TOLERANCE JS12 REPORT.
- GEORGE BROUGHT UP THE JS12 PRICING FOR DISCUSSION, AS HE FEARS THE ADDED COST WILL BE CHARGED TO HIM AS ENGINEERING CHANGE RELATED. FI NEEDS TO WORK WITH FORD PURCHASING TO RESOLVE THIS.

NOTES:

THE REMOVAL OF THE TERMINAL POSITIONAL TOLERANCE WILL ENABLE US TO SECURE FULL IER APPROVAL FOR 57PS L/T AND P/C. GEORGE AND BRUCE CONCURRED THAT EVEN A GROSSLY MISALIGNED TERMINAL WOULD ALLOW FOR MATING CONNECTOR FIT-UP. HE ALSO USED OUR 57PS SWITCH HISTORY TO SUPPORT THE CHANGE. THE WAY IN WHICH THE CCPS TEAM PRESENTED THE IER REPORT AND FOLLOW-UP WAS THE KEY TO THE QUICK RESOLUTION OF THIS ISSUE - NICELY DONE!

GEORGE HAS CHANGED HIS OPINION ON THE RELAXED TOLERANCE JS12 SEAL, DUE MOSTLY TO STEVE'S PAPER ANALYSIS, TESTING AND WORK WITH K-H AND THE JS12 COMMITTEE. BOTH WERE PLEASED WITH THE WORK WE'VE DONE TO PROVE OUT THE RELAXED TOLERANCE DESIGN, AND THEY WILL REVISION OUR TEST REPORT THIS WEEK. GEORGE STATED THAT IF HE DID NOT FIND ANY PROBLEM WITH OUR ANALYSIS, AND IF BRUCE APPROVES THE DESIGN, HE WILL ALSO APPROVE IT.

BRUCE WOULD LIKE TO SEE DATA THAT CORRELATES SWITCH ROTATION VS. TORQUE (DURING ASSEMBLY TO THE MATING FITTING). HE WOULD ALSO LIKE US TO SEND A COPY OF THE RELAXED TOLERANCE TEST REPORT TO PITTS AND WEATHERHEAD, ALONG WITH THIS DATA. JOE IS HAND-DELIVERING A COPY OF THE REPORT TO KOLSEY-HAYES, SO WE NEED TO SEND THEM ONLY THE TORQUE DATA.

ACTION:

- SEND TEST REPORTS AND DATA - OFFILER 02/01

BRUCE WOULD LIKE US TO SUBMIT 2 ENVELOPE DRAWINGS, 1 WITH THE REPORT AND BASE DIMENSIONAL CHANGES AND 1 WITH THE TERMINAL POSITIONAL TOLERANCE REMOVED.

ACTION:

- CLOSE WITH BRUCE TO ESTABLISH A COMPLETION DATE - OFFILER 02/01

IN SUMMARY, WE HAD A VERY SUCCESSFUL MEETING WITH BRUCE AND GEORGE AND WE ARE CLOSE TO CLEARING TWO MAJOR HURDLES. HOWEVER, IT WAS THE TEAM'S WORK PRECEDING THE MEETING THAT REALLY MADE THE WAY.

REGARDS,
DAVE CZARN
13-CCPS

TL-NHTSA 001681

180 MM= 62165 FR=CZRN TO=ELB SENT=01/28/91 11:56 AM
RW=105 ST=C DIV=0050 CC=00101 BT=CZRN AT=01/28/91 11:56 AM

1.	STEVE OFFILER	SBO1	CC:	TOM CHARBONEAU	TC
	CHARLIE DOUGLAS	CPFC		GARY SNYDER	CPFC
	MATT BELLERS	PCME		MARTHA SULLIVAN	CPFC
	BILL SWEET	PCME		ANDY McGUIRE	PCGA
	MIKE DEMATTIA	PCGA		STEVE MAJOR	WHLZ
	JOHN HAYNES	PCGA		ED O'NEILL	EJON
	JOE SCHUCK	WHLZ			
	PAUL KOTCH	PRK1			
2.	DAVE CZARN	ZARN			
3.	FORD TRIP REPORT - CRUISE CONTROL PRESSURE SWITCH				

ETING DATE: 01/25/91

TENDERS: BRUCE PEARSE - RELEASE ENGINEER P/C BRAKE
GEORGE RANDALL - RELEASE ENGINEER L/T NOBC
JOE SCHUCK
DAVE CZARN

REVIEW:

GEORGE AND BRUCE HAVE BOTH AGREED TO REMOVE THE TERMINAL
POSITIONAL TOLERANCE FROM THE PRINTS (57 AND 77 STYLE), ALLOWING US
ALL IER APPROVAL FOR THE 57PS VERSIONS.

IT IS LIKELY THAT BOTH L/T AND P/C WILL APPROVE THE RELAXED TOLERANCE
1. EXPORT.

GEORGE BROUGHT UP THE J512 PRICING FOR DISCUSSION, AS HE FEARS THE
ADDED COST WILL BE CHARGED TO HIM AS ENGINEERING CHANGE RELATED. TJ
WENT TO WORK WITH FORD PURCHASING TO RESOLVE THIS.

NOTES:

THE REMOVAL OF THE TERMINAL POSITIONAL TOLERANCE WILL ENABLE US TO
BECOME FULLY IER APPROVED FOR 57PS L/T AND P/C. GEORGE AND BRUCE
INQUIRED THAT EVEN A GROSSLY MISALIGNED TERMINAL WOULD ALLOW FOR
MATING CONNECTOR FIT-UP. WE ALSO USED OUR 57PS SWITCH HISTORY TO
SUPPORT THE CHANGE. THE WAY IN WHICH THE CCPS TEAM PRESENTED THE IER
REPORT AND FOLLOW-UP, WAS THE KEY TO THE QUICK RESOLUTION OF THIS
ISSUE - NICELY DONE!

GEORGE HAS CHANGED HIS OPINION ON THE RELAXED TOLERANCE J512 SEAL,
JE MOSTLY TO STEVE'S PAPER ANALYSIS, TESTING AND WORK WITH K-H AND
JE J512 COMMITTEE. BOTH WERE PLEASED WITH THE WORK WE'VE DONE TO
WORK OUT THE RELAXED TOLERANCE DESIGN, AND THEY WILL REVIEW OUR
3ST REPORT THIS WEEK. GEORGE STATED THAT IF HE DID NOT FIND ANY
ISSUES WITH OUR ANALYSIS, AND IF BRUCE APPROVES THE DESIGN, HE WILL
SO APPROVE IT.

BRUCE WOULD LIKE TO SEE DATA THAT CORRELATES SWITCH ROTATION VS.
TORQUE (DURING ASSEMBLY TO THE MATING FITTING). HE WOULD ALSO LIKE
TO SEND A COPY OF THE RELAXED TOLERANCE TEST REPORT TO PITTS AND
BATHERHEAD, ALONG WITH THIS DATA. JOE IS HAND-DELIVERING A COPY OF
THE REPORT TO KELSEY-HAYES, SO WE NEED TO SEND THEM ONLY THE TORQUE
DATA.

TIDNI
SEND TEST REPORTS AND DATA - OFFILER 02/01

UCE WOULD LIKE US TO SUBMIT 2 ENVELOPE DRAWINGS, 1 WITH THE REPORT
D BASE DIMENSIONAL CHANGES AND 1 WITH THE TERMINAL POSITIONAL
ANCE REMOVED.

TIDNI
CLOSE WITH BRUCE TO ESTABLISH A COMPLETION DATE - OFFILER 02/01

SUMMARY, WE HAD A VERY SUCCESSFUL MEETING WITH BRUCE AND GEORGE
D WE ARE CLOSE TO CLEARING TWO MAJOR HURDLES. HOWEVER, IT WAS THE
AM'S WORK PRECEDING THE MEETING THAT REALLY PAVED THE WAY.

DARDS,
VE CZARN
-CCPS

TI-NHTSA 001683

SAMPLE REPORT

REASON FOR REPORT		VENDOR		P.O.	Part No.	Rev.
NEW PART	☒	Valentine Tool			27713-1	A
REPLACEMENT TOOL	☐	REPORT REQ. BY	DATE	INSPECTED BY	DATE	
CORRECTED TOOL	☐	M. Sellers	1/31/91	Jeanne Gentes	2/2/91	
REPAIRED TOOL	☐	THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQ. REQ. ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.				
REVIEW	☐					
OTHER	☐					
	☐					

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)						DISPOSITION	
	Sample	1	2		Insp. Method		
1	1.065 - 1.069	X 1.0675	1.0669		TM		
		Y 1.0680	1.0676				
2	.835 - .839	X .8382	.8389				
	⊕ .003 ⊕ A ⊕	Y .8379	.8376				
		⊕ .0009	.0002				
		⊕ .0009	.0004				
		⊕ .0025	.0009				
3	.158 - .161	X .1598	.1601				
	⊕ .003 ⊕ A ⊕	Y .1599	.1599				
		⊕ .0007	.0026				
		⊕ .0005	.0003				
		⊕ .0015	.0052				
4	.010 R max.	M .020R	.020R		Unit. Mic.		
	2 places	mt .005R	.005R		Y TM		
5	.028 - .032 R	.025R	.025R		TM		
6	□ .0015	.0005	.0005		Del. Ind.		
7	Note #4	.030R	.030R		TM		
8	.005R max.	.015R	.015R		Unit. Mic.		
		.010R	.010R				
9	.005R max.	.004R	.003R				
10	No burrs allowed.	OK	OK		TM		
11	.910 max.	X .9059	.9047				
		Y .9047	.9056				
12	.795 min. flat	X .8088	.8107				
		Y .8079	.8091				
13	.468 - .472	X .4661	.4654				

REMARKS AND/OR INSTRUCTIONS: .0002-.0004 plating to be applied.

4: Adjacent to the outer radius is a .0052-.0102 rib

15. JICTION: TOOL APPROVED FOR PROD.

RESUBMISSION REQ'D

FG. ENG.: *[Signature]* 2/20/91

ORA ENG.:

PURCH. AGENT:

TI-NHTSA 001684

4575 000000 145442--51570 04701



PAGE 2 OF 2

SAMPLE REPORT

REASON FOR REPORT		VENDOR		P.O.		PART NO.		REV.	
NEW PART						37713-1			
REPLACEMENT TOOL.		REPORT REQ. BY		DATE		INSPECTED BY		DATE	
CORRECTED TOOL.									
REPAIRED TOOL.									
REVIEW									
OTHER									

THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)				DISPOSITION	
				Insp Method	
12	(cont.)	$\sqrt{.4646}$	$.4664$	TM	Re-submission Req
		$\sqrt{.0002}$	$.0026$		
		$\sqrt{.0002}$	$.0009$		
		$\sqrt{.0006}$	$.0054$		" "
14	$\square .003$	$.0004$	$.0007$	Qual Ind	
15	$.003 - .007 A$	$.015 R$	$.016 R$	Unit Mic	" "
16	$.012 - .015$	$.014$	$.014$	Qual Ind	
17	$.050 Ref.$	$.057$	$.056$		
	Note # 3	Maintained	160 Houghton	Aug Gage	
		full length			
18	$11.0015 B$	$.0007$	$.0009$	Qual Ind.	
19	$.090 - .092$	$.091$	$.091$		
20	$.310 - .320$	$.315$	$.316$		
21	Note # 1	LK	OK	TM	
22	$.034 - .041$	$.039$	$.034$	Unit Mic	

REMARKS AND/OR INSTRUCTIONS:

13: measured from inside cup.

13. SITION: TOOL APPROVED FOR PROD.	RESUBMISSION REQ'D
FG. ENG.: <i>[Signature]</i> 2/20/41	QRA ENG.:
	PURCH. AGENT:

DATE: 02/02/91

HIGHLIGHTS
Stephen B. Offler
Week Ending 02/01/91

Jeff
3/10/91



OVERTIME: Jeff DiDomenico, 91-02-02, 4 hrs

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE FS

HEXPORT: The tolerance relaxation report was apparently well-received at Ford. George Randall is very close to accepting the relaxed tolerance part. His primary concern now is that cost deltas associated with 1512 vs. 1514 are not charged to Engineering. Bruce Pease indicates that the Tier-1's should receive copies of the report as well. One concern Bruce had was that our testing was conducted with devices tightened to 1/8 turn (this minimum guideline is per an earlier conversation with Wessheadhead). Bruce wished to correlate this to a torque value. A quick experiment on 3 devices showed 1/8 turn roughly corresponds to 5 ft-lbs. Bruce was pleased with this information, since typical torque values on these fittings are roughly 10-15 ft-lbs. Thus, we have demonstrated a good seal at torques well below those in actual use.

CUSTOMER ISSUES: Both Bruce and George have signed off the SREA's which allow us to remove the very tight terminal positional tolerance from the envelope prints. This resolves the last outstanding issue on the 57FS ISER, clearing the path for full approval. I will be updating the envelope prints to remove this tolerance.

Prototype metric hexports for the Ford of Australia application have been completed by Bld. 20's CNC lathe operation. They look dimensionally excellent. They have been sent to plating, and expected back mid-next week. This will allow us to build and ship the 25 customer samples by late next week.

77FS: The very first prototype 77FS devices have been built. These are supposedly NON-FUNCTIONAL samples, labelled as such, for Bendix. Actually, the devices are functional but have not had extensive testing yet. Jeff manually "calibrated" the devices; that is, he deformed the stationary terminal to obtain a dimension for which we have pins in stock. He also reports no significant differences between the 77 devices and corresponding 57 devices, in terms of pin window, snap sound, and actuation/release values.

Light Truck has requested 77FS samples, quantity 75, for shipment 91-02-22. We will be building more 77 switch assemblies soon for use in testing and for these samples, assuming all testing goes well.

Mechanization has approx. 40 switches in their possession for calibrator debug. Steve McCooney reports that first, they will be doing simple mechanical debug (basically ensuring that all geometry is correct) then moving to the heart of the matter, which is debug of the electrical aspects.

We have begun force-deflection type testing, which will be useful in understanding the nuances of calibration, and also to understand the impact of spring angle on forces which will help determine the range of adjustability needed for the spring forming tool.

DRAFTING: We are presently working to update 57FS component and subassembly drawings to include new dash numbers to cover the 57PSLS-2 and -3 switches. This effort is required prior to completion of the parts lists, which are underway.

TORQUE TEST: TEST 124-15-03 JAD 2-1-91

DEGREES	ELCO CNC PART	MODEL SHOP HIGH END	MODEL SHOP LOW END
45	8.3	3.3	2.9
60	14.2	5.0	4.2
90	19.6	9.2	7.9
135	31.7	14.6	10.4
180	36.3	26.3	12.9
225	45.8	27.9	14.6
270	47.5 <i>W.B.</i>	30.4	17.5
315		33.8	19.2
360		39.6 <i>W.B.</i>	21.3
405			25.0 <i>W.B.</i>
450			25.0
495			25.0
540			25.0
585			25.0
FLUID PASSAGE	0.099 inches	0.092 inches	0.088 inches

- ELCO CNC PART BROKE OFF AT THE O-RING GLAND AT APPROX. 47.5 FT. LBS.
- LOW END MODEL SHOP PART BEGAN TO PULL THE CENTERS OUT OF THE BRASS FEMALE J512 FITTING AT APPROX. 25 FT. LBS.
- HIGH END MODEL SHOP PART WAS ABORTED AT APPROX. 39.6 FT. LBS. BEFORE FAILURE OCCURRED
- MODEL SHOP HEXPORTS USED IN THIS TEST CAN BE FOUND WITH TOLERANCE RELAXATION EXPERIMENT PARTS (TEST 117-07-16).

TI-NHTSA 001087

VALENTINE MTG.

MSG MM# 305742 FR=VAGS TO=SH2 SENT=02/06/91 10:47 AM
 R#176 ST=C DIV=0050 CC=00134 DT=VAGS AT=02/06/91 10:47 AM

TO: GEORGE LAVIE	B512	VALENTINE
STEVE OFFILER	SB01	
JEANNE GENTES	AT02	
JOHN HAYNES	PC0A	
TO: BILL SWEET	WS00	
STAN HOMOL	SH2	
TO: MATT SELLERS	PCME	

TO: 27713-1 CUP / 74797 RING, TOOL IMPROVAL ISSUES

WILL SUMMARIZE THE FINDINGS AT OUR FAI REVIEW WITH VALENTINE
 ELON. PLEASE ENSURE THAT VALENTINE REVIEWS THE ITEMS AND PREPARES
 RESPONSE TO MYSELF AS SOON AS POSSIBLE. IT IS CRUCIAL THAT THESE
 TOOLS ARE PRODUCTION CAPABLE WITHIN THE NEXT FEW WEEKS.

4797-1 ALUMINUM DRIMP RING

THE ONLY DISCREPANCY WITH THIS TOOL IS THE ^{IN} ~~OUT~~ SIDE RADIUS
 SPECIFIED AT .055/.065 R. T.I. FOUND THE RADIUS 2 .050 R. HOWEVER,
 THE CENTRALIZATION OF THE CROSS SECTION WAS IN QUESTION. IT WAS
 NOTED THAT HAVING AN UN-CENTERED CROSS SECTION WOULD IN FACT SHOW
 THE RADIUS HIGHER: WHICH WOULD NOT PROVIDE AN EXPLANATION FOR THE
 HIGH READING.

1. ACTIONS *CONFIRMING DIE (THINNING: CUPLE WKS)*

QUANT/CROSS SECTION ADDITIONAL SAMPLE TO
 PROVIDE PRECISE READING.

GENTES URGENT

VALENTINE ACTIONS

REVIEW TOOLING, PROVIDE RESPONSE ON LEAD TIME
 REQUIRED TO MAKE ADJUSTMENT IF NEEDED.

VALENTINE 2/7

7713-1 CUP

THE MAJORITY OF THE DISCREPANCIES FOUND WITH THE CUP "SEEM" TO BE
 RELATED TO THE CONCENTRICITY BETWEEN THE TOP AND BOTTOM PUNCHES
 THAT FORM THE .472/.468 RING. VISUAL OBSERVATION OF A CROSS
 SECTIONED PART SEEMS TO INDICATE THAT THE RING IS BEING PUSHED
 HORIZONTALLY TO SOME EXTENT TOWARD THE MIDDLE OF THE CUP. ANOTHER
 CRITICAL DIMENSION THAT IS OUT OF SPECIFICATION IS THE .005" MAX
 . CALLOUT FOR INSIDE RADIUS. THEY WERE FOUND RUNNING .010 TO .015
 . THIS IS A FUNCTIONAL SURFACE AND MUST BE MAINTAINED BELOW .005"

IT SHOULD BE NOTED THAT THE Q.C. EQUIPMENT USED BY VALENTINE IS NOT
 SET UP TO MEASURE ODT TOLERANCED PARTS AS ACCURATELY AS T.I. S.

THHTSA 001886

TEM # 1

010" R. MAX 2 PLACES RUNNING .020" R.

AY BE RELATED TO CONCENTRICITY PROBLEM STATED ABOVE.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON REPAIR SCHEDULE.

VALENTINE 2/11

TEM # 2

028/.032" R. RUNNING .025" (JIMMIE MEASURES)

AY BE RELATED TO PROBLEM STATED ABOVE WITH CONCENTRICITY. DESIGN
AS INDICATED THIS WE MAY BE ABLE TO OPEN THE PRINT TO ALLOW A
HARPER RADIUS. HOWEVER, VALENTINE SHOULD REVIEW TOOLING ANYWAY.

.I. ACTION

EVALUATE OPENING RADIUS SPEC. AND ADVISE.

STEVE 2/11

- JIMMIE MEASURES
W/3 "EDWARD"

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON ADJUSTMENT CAPABILITY. VALENTINE 2/11

TEM # 3

OTE # 4 .045" MAX PINCH OFF RADIUS RUNNING .080" R. (JIMMIE MEASURES)

FOUND TO BE SUBJECTIVE IN MEASUREMENT METHOD. RADIUS AS IT EXISTS
IS THE SAME AS IS FOUND ON THE CURRENT 52 AND 57PS CUPS. NO
RIMPING DIFFICULTIES RELATED TO THIS EDGE CONDITION HAVE BEEN
NOTED ON EITHER DEVICE. REVIEW OF THE PRINT CALLOUT WILL BE
DISCUSSED BETWEEN STAN, STEVE, AND MYSELF.

.I. ACTION

REVIEW PRINT CALL OUT.

STEVE 2/11

THINK HE
W/ HIS SEAL -
CHECK IN
HAVE X-SECT?

VALENTINE ACTION

IS THIS DIMENSION ADJUSTED AT ALL WHEN
HANDING BETWEEN 27298 AND 27713?

VALENTINE 2/11

TEM # 4

005" R. MAX RUNNING .010/.015" R (JIMMIE MEAS.)

SERVES AS A SEATING AREA FOR BOTH THE WASHER AND CONVERTER. MUST
BE MAINTAINED AT THE .005" R. SPECIFICATION.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON REPAIR SCHEDULE.

VALENTINE 2/11

TEM # 5

TI-NHTSA 001689

ADDITIONAL TOLERANCE WAS ALSO FOUND OUT OF SPEC. THIS DIMENSION
MUST BE TO SPEC. IT SERVES A VITAL FUNCTION WITH DEVICE OPERATION.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON ADJUSTMENT CAPABILITY. VALENTINE 2:11

ITEM # 6

003/.007 R. RUNNING .015 R. *CHANGE PRINT*

SERVES AS A SEAL DEFORMATION SURFACE. IT IS QUESTIONABLE WHETHER
.015" R. WILL AFFECT THE SEALING FUNCTION. TO BE REVIEWED BY T.I.
HOWEVER, VALENTINE SHOULD REVIEW THE TOOLING IN PARALLEL.

T.I. ACTION

EVALUATE EFFECT ON SEALING FUNCTION. ADVISE. STEVE MATT 2:11

*UP VIA 1646
ATTN MATT*

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON ADJUSTMENT CAPABILITY. VALENTINE 2:11

WOULD LIKE TO MEET ON 2/11/90 AT 3:00PM IN BUILDING 12 CAFETERIA
TO REVIEW COMPLETED ACTIONS. CALL IF YOU CANNOT ATTEND.

EDORGE - PLEASE CLOSE WITH VALENTINE ON THIS MEETING.

REGARDS...MATT
1245

TI-NHTSA 001690

-MSG MR= 305742 FR=VAGS TO=PCOA SENT=02/06/71 10:47 AM
RN=059 ST=C DIV=0050 CC=00134 BY=VAGS APOC/06/71 10:47 AM

TO: GEORGE LAVIOE RS12 VALENTINE
STEVE OFFILER SB01
JEANNE GENTLE ATQC
JOHN HAYNES PCOA
CC: BILL SWEET WSSO
STAN HOMOL SH2
FR: MATT SELLERS PCMF

SUBJ 27713-1 CUP / 74797 RING, TOOL APPROVAL ISSUES

I WILL SUMMARIZE THE FINDINGS AT OUR FAE REVIEW WITH VALENTINE
BELOW. PLEASE ENSURE THAT VALENTINE REVIEWS THE ITEMS AND FORWARDS
A RESPONSE TO MYSELF AS SOON AS POSSIBLE. IT IS CRUCIAL THAT THESE
TOOLS ARE PRODUCTION CAPABLE WITHIN THE NEXT FEW WEEKS.

74797-1 ALUMINUM CRIMP RING

THE ONLY DISCREPANCY WITH THIS TOOL IS THE OUT SIDE RADIUS
SPECIFIED AT .055/.065 R. T.I. FOUND THE RADIUS 2 .050 P. HOWEVER,
THE CENTRALIZATION OF THE CROSS SECTION WAS IN QUESTION. IT WAS
NOTED THAT HAVING AN UN-CENTERED CROSS SECTION WOULD IN FACT SKEW
THE RADIUS HIGHER, WHICH WOULD NOT PROVIDE AN EXPLANATION FOR THE
HIGH READING.

TI-NHTSA 001091

T.I. ACTIONS

MOUNT/CROSS SECTION ADDITIONAL SAMPLE TO
PROVIDE PRECISE READING.

STEVE

VALENTINE ACTIONS

REVIEW TOOLING. PROVIDE RESPONSE ON LEAD TIME
REQUIRED TO MAKE ADJUSTMENT IF NEEDED

VALENTINE

27713-1 CUP

=====

THE MAJORITY OF THE DISCREPANCIES FOUND WITH THE CUP ARE
RELATED TO THE CONCENTRICITY BETWEEN THE TOP AND BOTTOM RINGS
THAT FORM THE .4727/.468 RING. VISUAL OBSERVATION OF THE
SECTIONED PART SEEMS TO INDICATE THAT THE RING IS DEFORMED
HORIZONTALLY TO SOME EXTENT TOWARD THE MIDDLE OF THE CUP. THE
CRITICAL DIMENSION THAT IS OUT OF SPECIFICATION IS THE .0005
R. CALLOUT FOR INSIDE RADIUS. THEY WERE FOUND RUNNING .0005
R. THIS IS A FUNCTIONAL SURFACE AND MUST BE MAINTAINED AT .0005
R.

IT SHOULD BE NOTED THAT THE O.C. EQUIPMENT USED BY THE CUP
SET UP TO MEASURE GDT TOLERANCED PARTS AN ACCURATELY .0001

ITEM # 1

.010" R. MAX 2 PLACES RUNNING .020" W.

MAY BE RELATED TO CONCENTRICITY PROBLEM STATED ABOVE.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON REPAIR SCHEDULE.

VALENTINE

ITEM # 2

.028/.032" R. RUNNING .025"

MAY BE RELATED TO PROBLEM STATED ABOVE WITH CONCENTRICITY. STEVE
HAS INDICATED THIS WE MAY BE ABLE TO OPEN THE PRINT TO ALLOW A
SHARPER RADIUS. HOWEVER, VALENTINE SHOULD REVIEW TOOLING CAPABILITY.

T.I. ACTION

EVALUATE OPENING RADIUS SPEC. AND ADVISE.

STEVE

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON ADJUSTMENT CAPABILITY. VALENTINE

TI-NHTSA 001892

ITEM # 3

NOTE # 4 .045" MAX PINCH OFF RADIUS RUNNING 1.000" R.

FOUND TO BE SUBJECTIVE IN MEASUREMENT. REASON: .002" R. IS THE SAME AS IS FOUND ON THE CURRENTLY USED TOOLING. CRIMPING DIFFICULTIES RELATED TO THE .002" R. DIMENSION NOTED ON EITHER DEVICE. REVIEW OF THE TOOLING SHOULD BE DISCUSSED BETWEEN STAN, STEVE, AND MYSELF.

T.I. ACTION

REVIEW PRINT CALL OUT.

VALENTINE ACTION

IS THIS DIMENSION ADJUSTED AT ALL WHEN CHANGING BETWEEN 27282 AND 27213?

ITEM # 4

.005" R. MAX RUNNING .010/.015" R.

SERVES AS A SEATING AREA FOR BOTH THE CONTACT AND THE SEAL. IT MUST BE MAINTAINED AT THE .005" R. SPECIFICATION.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON REPAIR SCHEDULE. (C) 1971

ITEM # 5

.4687/.472" RUNNING AS LOW AS .4646"

POSITIONAL TOLERANCE WAS ALSO FOUND OUT OF SPEC. THIS DIMENSION MUST BE TO SPEC. IT SERVES A VITAL FUNCTION WITH REGARD TO SEALING.

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON REPAIR SCHEDULE. (C) 1971

ITEM # 6

.003/.007 R. RUNNING .015 R.

SERVES AS A SEAL DEFORMATION SURFACE. IT IS QUESTIONABLE WHETHER A .015" R. WILL AFFECT THE SEALING FUNCTION. TO BE REVIEWED BY STAN. HOWEVER, VALENTINE SHOULD REVIEW THE TOOLING IN PARALLEL.

T.I. ACTION

EVALUATE EFFECT ON SEALING FUNCTION. ADVISE. STAN MAY (C) 1971

VALENTINE ACTION

REVIEW TOOLING. ADVISE ON ADJUSTMENT (C) 1971

(C) 1971

I WOULD LIKE TO MEET ON 2/11/90 AT 3:00PM IN BUILDING 17 CAFE TERRACE
TO REVIEW COMPLETED ACTIONS. CALL IF YOU CANNOT ATTEND.

GEORGE - PLEASE CLOSE WITH VALENTINE ON THIS MEETING.

REGARDS...MATT
X1245

TI-NHTSA 001694

HIGHLIGHTS
Stephen B. Offler
Week Ending 02/08/91

Handwritten signature/initials



FORD MY92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: George Randall has asked for new prints ASAP. He is accepting the new, relaxed J512 tolerances we proposed, 5.58 - 5.85mm (.2197" - .2303"). However, he wanted 5.60 and made a significant issue out of the 0.02mm (.0008") before finally agreeing, then only because Bruce Pease already had.

On the removal of the terminal position tolerance from the print, George misinterpreted the SREA we presented, assuming we meant removal of the true-position GDT callout and replacement with a conventional co-ordinate dimension. Our goal was to take the tolerance off and replace the basic with a reference dimension. This quickly became a major issue. George needed to know what new co-ordinate dimension was going to be used on the next prints. A statistical terminal position study on four different lots of production 57PS's showed our present capability is poor. The better terminal had a Cpk of 0.26. In other words, we are shipping production 57PS's every day that do not meet the customer print. I proposed a tolerance of 0.5mm +/- 0.5, five times the present tolerance. George strongly refused this. Our negotiations finally stalled at 0.5mm +/- 0.2, which is the tolerance George's new print will carry. We must now spend effort to attempt to improve the 57PS staking process.

SAMPLES: The 20 Ford of Australia devices shipped Thursday 02-07. They used custom CNC lathe metric harpoons using M10x1.25 thread and 14mm len. They used O-rings rather than J512, using this opportunity to steer them towards O-rings. We included complete information on the J514 O-ring gland details, the O-rings themselves, and tri-axial compatible materials, all from the Parker O-Ring Handbook. We also included a copy of the Engineering Specification, a set of mating connectors, and a cover letter.

George Randall indicates that he needed/expected his 75 57PS samples before 91-02-22 which is the date on our paperwork. He has very few 57PS's on the shelf, and stock builds are ongoing. We must first do an Impulse test to validate this latest iteration of the prototype switch assembly. This in turn requires that we "mock-calibrate" the bases; that is, as-built uncalibrated they read very short pins, out of range, so we must deflect the stationary terminal to roughly its midpoint so they can be pinned traditionally. I have contacted Wayne Carlson, who indicates the calibrator is at a stage where he can bond to some pre-determined value. It is not capable of a true calibration yet. We plan to mock-calibrate about 100 bases, do an Impulse test ASAP on 12, and use about 20 of the remaining to build expedient parts for George. These will ship after successful completion of the Impulse test, possibly as early as next Thursday. Subsequently we will build and ship the remaining 65 well ahead of the 02-22 date.

HEXPORE: I have received data generated by Hinc, using their version of the ball-gaging method. They included data using two different ball sizes as well as optical TM measurements. I have begun to analyze this data, and preliminarily it looks like their angles were off, my calculations on their data showing 48.75 degrees (spec 42 +/- 1). Also, correlation with the TM readings is not very good. TM readings of the chamber diameter are always lower than the ball readings, by an average of .0042" with SD of .0012". However, we know the difficulties in using optical measurements, and I still tend to trust the ball readings.

TI-NHT8A 001005

**TEXAS
INSTRUMENTS**



2014年12月15日

2011.11.11

	ALUMINUM SPEC	DAVID + 10 ACTUAL	DAVID + 10 ACTUAL	DAVID + 10 ACTUAL	DAVID + 10 ACTUAL	DAVID + 10 ACTUAL	DAVID + 10 ACTUAL	COMMENTS
1	15.45 + 15.51	15.55	15.61	15.71	15.75	15.87	15.87	
2	16.56 + 16.76	16.59/16.58	16.62/16.54	16.62/16.57	16.53/16.54	16.58/16.56	16.59/16.54	
3	17.50 + 17.61	17.574	17.651	17.675	17.43	17.674	17.646	
4	18.40 + 18.60	18.768	18.806	18.775	18.777	18.753	18.758	
5	19.34 + 19.55	19.73	19.71	19.71	19.71	19.71	19.71	
6	20.24 + 20.44	20.357/20.041	20.320/20.020	20.337/20.017	20.367/20.011	20.365/20.015	20.367/20.013	
7	21.16 + 21.32	21.69/21.71	21.67/21.71	21.72/21.61	21.66/21.63	21.69/21.67	21.65/21.63	
8	22.04 + 22.43	22.282	22.280	22.280	22.280	22.280	22.280	
9	22.94 + 23.53	23.902	23.997	23.999	23.999	23.997	23.997	
10	23.85 + 24.04	24.004	23.974	23.969	23.964	23.964	23.964	
11	24.74 + 24.93	24.772	24.691	24.689	24.686	24.686	24.676	
12	25.65 + 25.85/30.05 34.04	29.05 35.04	29.05 35.04	29.05	29.05 35.04	29.05 35.04	29.05 35.04	
13	26.71 + 26.9 27 27.99/27.9	27.99/27.9	27.99/27.9	27.99/27.9	27.99/27.9	27.99/27.9	27.99/27.9	
14	27.53 + 27.75	27.956/27.841	27.840/27.800	27.842/27.821	27.845/27.821	27.840/27.844	27.840/27.827	2" F SPEC.
15	28.01 + 28.26	28.055/28.069	28.074/28.127	28.140/28.176	28.127/28.124	28.125/28.127	28.071/28.111	
16	28.94 + 29.14	29.140/29.147	29.092/29.089	29.086/29.114	29.048/29.061	29.039/29.011	29.137/29.153	
17	29.85/30.01	29.84	29.56/28.57	28.66/28.54	28.56/28.66	28.77/28.61	28.71/28.61	28.67

TEXAS INSTRUMENTS



DIMENSIONAL ANALYSIS ON PART NUMBER

FIG-489A-48

FEATURE	CAVITY # 10	CAVITY # 11	CAVITY # 12	CAVITY # 13	CAVITY # 14	CAVITY # 15	CAVITY # 16	COMMENTS
SPEC	ACTUAL	ACTUAL	ACTUAL	ACTUAL	ACTUAL	ACTUAL	ACTUAL	
11	57.15 MAX	55.57	55.74	55.71	55.70	55.57	55.56	
12	11.75 ± 0.11	11.70/11.56	11.72/11.54	11.72/11.55	11.70/11.57	11.70/11.51	11.70/11.50	
13	11.15 ± 0.17	11.05/11.79	11.25/11.44	11.72/11.79	11.28/11.54	11.72/11.54	11.70/11.56	
14	14.25 MAX	11.56	11.65	11.67	11.65	11.65	11.66	
15	1.50 ± 0.06	1.43/1.61	1.41/1.56	1.57/1.64	1.49/1.62	1.50/1.74	1.55/1.67	OUT OF SPEC.
	1.12 MIN	1.53/1.29	1.13/1.54	1.12/1.11	1.09/1.56	1.14/1.12	1.11/1.14	
16	1.75 ± 0.04	1.740	1.732	1.731	1.727	1.731	1.734	
17	5 7.62-8.03	7.74/7.90	7.94	7.97/7.94	7.97	7.95	7.95	
18	6.60 ± 0.01	6.600	6.600	6.601	6.607	6.605	6.602	
19	PROG 27-208 41	PROG 24MIN	PROG 24MIN	MEASURED	ON A CROSS	SECTIONED	PART	
		PROG 57MIN	PROG 64MIN					
20	1.50-1.214 21	1.54-1.34	1.64-1.34	1.54-1.34	1.34-1.34	1.54-1.34	1.24-1.34	
21	7.12-7.75	7.74	7.52	7.53	7.54	7.51	7.51	
22	NO FLASH OR	OK	OK	FLASH	OK	OK	FLASH	
	PURPS ALLOWED							
	ON SURFACE							
27	1.75-1.41	1.145	1.099	1.160	1.156	1.119	1.107	
28	0.60-1.30	1.115	1.168	1.172	1.140	1.161	1.155	

TEXAS INSTRUMENTS INCORPORATED • 3830 WEST STREET • AUSTIN, TEXAS 78757
505-435-3333 • TELEFAX 512-791-7000 • CABLE TEXINS

TI-NHTSA 001697

2016-2017-2018

TEXAS REGISTERED MAILING CORPORATION • 26 POKESST STREET • AFTERSCHOOL MAIL SERVICE
552-555-3500 • TEL: 51 7708 FAX: 51 345-5555 • CABLE: 51 7708

TI-NHTSA 001696

22. 25. 2014. rok

[illegible]**TI-NHTSA 001899**

F20C-4521-40

TEAR INSTRUMENTS INCORPORATED • 34 FOREST STREET • ATTLEBORO MA 01915
508-252-3826 • TELE 40 7788 TOLL 7-0-3-6-8885 • CABLE 72145

TI-NHTSA 001700

-MSG N#- 378314 FR=PCQA TO=PCQA SENT=02/11/91 07:43 AM
RA=163 ST=C DIV=0050 CC=00149 BY=CERN AT=02/08/91 03:27 PM

FEBRUARY 08, 1991

TO:	RUSTY STRUBEL	JNLS	CC:	TOM CHARBONEAU	TC
	MIKE DeMATTIA	PCQA		JOHN MOUTERIS	NDIS
	CHARLIE DOUGLAS	CPFC		STEVE MAJOR	WHL2
	DICK GARIEPY	NFFC		ANDY McGUIRE	PCQA
	PAUL KOTCH	PRK1		ED O'NEILL	ELON
	JOE LAZARZ	JNLS		JOE SCHUCK	WHL1
	STEVE OFFILER	SB01		GARY SWYDER	CPFC
	MATT SELLERS	PCNE		MARTHA SULLIVAN	CPFC
	BILL SWEET	PCNE		RAY TOURANGEAU	PCNE
	GEORGE LAVOIE	B512		TED BALLARD	AVNE
	JOHN HAYNES /	PCQA		DAVE VARNEY	FORM
				SCOTT MARTIN	NFFC
				CLAIRE BALTHAZAR	NFFC
				BILL CONGDON	NFFC

FR: DAVE CEARN IARN

SJ: FORD CRUISE CONTROL PRESSURE SWITCH START-UP MEETING:
02/08/91 MEETING MINUTES

MEETING

THE NEXT MEETING IS SCHEDULED FOR

DATE: 02/14 (THURSDAY)
TIME: 10:00-11:30 AM
PLACE: MARKETING CONFERENCE ROOM

PLEASE CALL ME IF YOU ARE NOT ABLE TO ATTEND

* - NEW OR REVISED ITEMS

57 L/T

Report:

	WHO	WHEN	
* ELCO APPROVAL OF GAGE CONCEPT	KOTCH	02/04	ORIG.
		02/04	CONF.
* FINAL GAGE REVIEW	SELLERS/	02/09	ORIG.
	OFFILER	02/14	REV.
* RELEASE GAGE FOR BUILD	SELLERS	02/07	ORIG.
		02/14	REV.
. ELCO CONTROL PLAN	KOTCH	01/17	ORIG.
(DELAYED DUE TO J512 GAGING DEFINITION)		02/28	REV.
* RELEASE PRODUCTION REPORT (L/T)	SELLERS	02/08	ORIG.
		02/01	CONF.
. ISIR corrective actions:			
* A. TERMINAL DIMENSIONS			
- M.C. STUDIES FROM AJ KNOTT	KOTCH	01/04	ORIG.
		02/14	REV.
. DISC LIFE TEST FROM EACH LOT	OFFILER/	02/14	
	GARIEPY		
* L/T PILOT RUN	SELLERS/	01/24	ORIG.
	GARIEPY	03/18	REV.
. CREATE L/T BLS PARTS LIST	OFFILER/	01/24	ORIG.

TI-NHTSA 001701

AND B.O.M. (ORIG. DATE WAS INCORRECT)	WILSON	03/07	REV.
37 P/C			
* OFFSET POLARITY KEY BASE PRINT	OFFILER	11/16	ORIG.
		02/14	REV.
* P/C PILOT RUN	SELLERS/	01/31	ORIG.
	GABIEPY	03/18	REV.
* CREATE P/C EIS PARTS LIST	OFFILER/	01/24	ORIG.
AND B.O.M.	WILSON	02/14	REV.
* RELEASE P/C HEXPORT (P/N 36900)	SELLERS/	01/31	ORIG.
	KOTCH	02/04	REV.
		02/05	COMP.
* ESTABLISH LEADTIME FOR HEXPORT	KOTCH	01/31	ORIG.
		02/01	REV.
		02/07	COMP.
* ENV. DWG. WITH NO TERM. POS'N TOLERANCE	OFFILER	02/28	

77PS

* DESIGN UPDATE	OFFILER	ONGOING	
* MFG/MECH UPDATE	SELLERS	ONGOING	
* REPORT ON TOKICO P.S. RESPONSIBILITY	DOUGLAS	ONGOING	
* DESIGN FMEA -START	OFFILER	02/12	
-COMPLETE		04/18	
* BEGIN CALIBRATOR EVALUATION	SELLERS	02/04	ORIG.
		02/04	COMP.
* PROD. LINE LAYOUT	SELLERS	03/14	
* PROD. LINE SET-UP (RTE CARDS, ETC)	BALTHAZAR	TBD	
* PROVIDE DATES FOR COMPLETION OF ABOVE	BALTHAZAR	02/21	
* PROVIDE QUALITY RELATED CRITICAL PATH	HAYNES	02/21	
ITEMS TO TRACK AT S/U MTGS.			
* RESOLVE BASE DELIV. SCHED. W/APCC	SELLERS	02/07	ORIG.
		02/07	COMP.
* ORDER ADD'L M.S. TERM'S AND SPRINGS	OFFILER	02/07	ORIG.
		02/11	REV.
* PROVIDE DATES FOR COMP. OF 1ST PASS	OFFILER	02/07	ORIG.
SPRING/CONTACT/FIM WINDOW TESTING		02/14	COMP.
* DETERMINE IF CLEARANCE SHOULD BE ADDED	OFFILER	02/14	
FOR MOV. ARM IN THE BASE			

IQP'S:

* ALUMINUM CRIMP RING	SELLERS	01/31	ORIG.
		02/08	COMP.
* RESUMP CUP	SELLERS	02/21	ORIG.
		02/08	COMP.
* MOVABLE TERM.	SELLERS	02/21	ORIG.
		02/08	COMP.
* STATIONARY TERM.	SELLERS	03/15	ORIG.
		02/08	COMP.
* BASE	SELLERS	02/28	

PRODUCTION COMPONENTS:

* ALUMINUM CRIMP RING	LAVOIE	02/11	
* RESUMP CUP	LAVOIE	02/27	
* MOVABLE TERM.	LAVOIE	03/01	
* STATIONARY TERM.	LAVOIE	03/22	
* BASE	SELLERS	03/06	ORIG.
(APCC DELIV. DATE PUSH-OUT)		03/15	REV.
* HEXPORT (P/N 36900)	KOTCH	02/04	

(ORIG. DATE INCORRECT)

MANUFACTURING EQUIPMENT:

. FINAL ASM MACHINE BUILD COMPLETION
. BASE ASM MACHINE BUILD COMPLETION
* PRESSURE TESTER BUILD COMPLETION
(ORIG. DATE INCORRECT)

SELLERS/ 04/15
KOURTESIS
SELLERS/ 05/31
KOURTESIS
SELLERS/ 06/06
KOURTESIS

FORD AUSTRALIA

. FORD AUSTRALIA UPDATE
. SAMPLES FOR VP BUILD

DOUGLAS ONGOING
OFFILER 01/17 ORIG.
02/08 REV.
02/08 COMP.

DISCUSSION

57 L/T AND P/C

WE'VE RECEIVED APPROVAL FOR THE RELAXED TOLERANCE J512 FROM BOTH L/T AND P/C! WE ARE WORKING TO QUICKLY PROVIDE REVISED PRINTS TO CEMENT THE DECISION. THESE PRINTS WILL CARRY A REVISED TERMINAL POSITIONAL TOLERANCE AS DESCRIBED BELOW.

L/T HAS REVERSED THEIR DECISION TO REMOVE THE TERMINAL POSITIONAL TOLERANCE FROM THE PRINT. GEORGE RANDALL HAS CONCEDED TO INCREASE THE TOLERANCE FROM +/- .004" TO +/- .008"; HOWEVER, THE CURRENT PROCESS IS CAPABLE TO +/- .020" AT BEST. WE NEED TO MOVE QUICKLY TO IMPROVE OUR CAPABILITY - EITHER BY PROCESS OR POST-STAKE ALIGNMENT - IN ORDER TO SECURE FULL ISIR APPROVAL FOR THE 57PS.

TDR'S J512 GAGE CONCEPT DRAWING HAS BEEN APPROVED BY ELCO. THEY'VE AGREED TO PAY \$3200 FOR 1 GAGE; 2 GAGES WILL BE RELEASED NEXT WEEK AFTER A FINAL REVIEW AT TDR.

ELCO HAS PROVIDED A DELIVERY SCHEDULE THAT WILL MEET OUR NEEDS FOR START-UP. 5000 HEXPORTS (RELAXED TOLERANCE P/N 36900) WILL BE DELIVERED BY 08/04; 45000 MORE WILL BE COMPLETED BY 08/05. ALL PARTS WILL BE FULLY PRODUCTION REPRESENTATIVE, MADE ON THE CHUCKER. PER PAUL'S DISCUSSION WITH ELCO, THEY ARE TAKING NO EXCEPTIONS TO THE 36900 PRINT.

77PS

PRODUCTION INTENT SWITCHES WERE CALIBRATED TODAY USING THE PRODUCTION CALIBRATOR. THE RESULTS OF THE FIRST PASS WERE ENCOURAGING, IN TERMS OF REPEATABILITY OF THE SET CONTACT HEIGHT.

THE PRESSURE TESTER COMPLETION DATE HAS BEEN PUSHED OUT BY 3 WEEKS ACCORDING TO MECHANIZATION'S LATEST UPDATE; JOHN K. WILL ATTEMPT TO BRING THIS BACK ON SCHEDULE. (IT WAS INCORRECTLY REPORTED IN LAST WEEK'S MINUTES THAT THE BASE ASM. MACHINE WAS PUSHED OUT.)

THE P/C AND L/T PILOT RUNS ARE RESCHEDULED FOR MID-MARCH, TO ALLOW FOR USE OF PRODUCTION HEXPORTS.

BASSLER IS CURRENTLY STAMPING INITIAL PARTS OFF THE MOVABLE

TI-NHTSA 001703

TERMINAL TOOL.

FAI REVIEW OF CRIMP RING AND CUP (VALENTINE) DETERMINED AN OUT-OF-SPEC RADIUS AT THE BASE OF THE RING, AN IRREGULARLY FORMED SUPPORT BUMP IN THE CUP, AND SOME CORRELATION ISSUES. A FOLLOW UP MEETING WITH VALENTINE IS SCHEDULED FOR MONDAY.

MILESTONES	PLANNED	ACTUAL
57 L/T ISIR	11/21/90	11/21/90
57 L/T JOB 1	07/01/91	
57 P/C ISIR	01/15/91	01/15/91
57 P/C JOB 1	06/03/91	
77PS ISIR	08/01/91	
77PS SGP (TI)	09/01/91	

PRODUCTION PLAN BY MONTH (THOUSANDS)

	P/C 57PSL5-3	L/T 57PSL5-2	P/C 77PSL2-1	L/T 77PSL2-2
FEB	0	0	0	0
MAR	5	0	0	0
APR	5	0	0	0
MAY	10	3	0	0
JUN	*17	4	0	0
JUL	17	*5	0	0
AUG	17	7	4	0
SEP	17	7	10	0
OCT	0	7	**12	5
NOV	0	7	17	7
DEC	0	0	17	**7

NOTE: PLAN FOR AUGUST AND BEYOND IS TENTATIVE.

* = JOB1 FOR 57PS VERSIONS

** = TENTATIVE JOB1 FOR 77PS VERSIONS

REGARDS,
DAVE CZARN \10-FORD

TI-NHTSA 001704

TEXAS INSTRUMENTS

ATTACHED INSTRUMENTS DETAIL

PAGE 1 OF 1

SAMPLE REPORT

REASON FOR REPORT		VENDOR		P.O.	PART NO.	REV
NEW PART		T.I. Model Shop			27713-1	A
REPLACEMENT TOOL.		REPORT REQ. BY	DATE	INSPECTED BY		DATE
CORRECTED TOOL.		M. Sellers	2/13/91	Jeanne Gentes		2/8/91
REPAIRED TOOL.		THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING TO ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION TO EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.				
REVIEW						
OTHER Eng. Evaluation ☒						

CIRCLE ALL OUT OF TOLERANCE DIMENSIONS!						DISPOSITION	
					Insp. Method		
1	.003-.007 R	.007R			Handwritten		
2	.005R max.	.007R	(see .011 max.)		"		
3	Note # 4 max.	.110R			T.M.		
4	.028-.032 R	.030R			"		
5	.010 R max.	.003R	(outside)		Handwritten		
	(2 pl.)	.003R	(inside)		"		
Note: .0018 wide rib around the .008-.030 R rib inside and outside of the cup. Dimension 1: This radius is deeply intended into the surface. .0017-.0018 step around the ID of the .028-.032 R rib inside the cup.							

REMARKS AND/OR INSTRUCTIONS:

D. POSITION: TOOL APPROVED FOR PROD.

RESUBMISSION REQ'D

MFG. ENG.:

QRA ENG.:

PURCH. AGENT:

27713 →

R.010 MAX @ BASE OF RAMP


CHK TO ✓ FILLET MAX .003



→ APDOR NEXT ITERATION


.028-.032 R ; DOWN TO .026 ?? CIRC M/S PART

27713 talk to Joanne about



VERY HARD TO MEASURE

VALENTINE
ACTIONS



PINCH-OFF → NOTE: "PINCH-OFF RADIUS ALLOWED"
NO MEAS.

PRESSURE SWITCH DATA

FORM 21605

TEST NO. 121-09-15

DEVICE E23413	DATE REQUESTED 3-14-91	REQUESTED BY Steve Off. 1st	REQUESTED COMP. DATE
PERFORMED BY Jeff D. Deane, CO	DATE STARTED 1-28-91	DATE COMPLETED 2/15/91	APPROVED BY

PROJECT TITLE: C-14.50 control pressure switch

CUSTOMER:

PURPOSE OF TEST: Disc 1-50 test of ball PC and LT, both .015" pass-rated and .015" non-pass-rated.

PROCEDURE: Next Pass

Device #	Material	Disc	Initial	Per Pass	Disc #
121-09-01	.0122	304/102	108/47	103/52	203/102
02	.0122	304/102	101/55	102/57	203/102
03	.0122	304/102	101/55	102/57	203/102
04	.0122	304/102	101/55	102/57	203/102
05	.0122	304/102	101/55	102/57	203/102
121-09-06	.0122	304/102	101/55	102/57	203/102
07	.0122	304/102	101/55	102/57	203/102
08	.0122	304/102	101/55	102/57	203/102
09	.0122	304/102	101/55	102/57	203/102
10	.0122	304/102	101/55	102/57	203/102
121-09-11	.0122	304/102	101/55	102/57	203/102
12	.0122	304/102	101/55	102/57	203/102
13	.0122	304/102	101/55	102/57	203/102
14	.0122	304/102	101/55	102/57	203/102
15	.0122	304/102	101/55	102/57	203/102
121-09-16	.0122	304/102	101/55	102/57	203/102
17	.0122	304/102	101/55	102/57	203/102
18	.0122	304/102	101/55	102/57	203/102
19	.0122	304/102	101/55	102/57	203/102
20	.0122	304/102	101/55	102/57	203/102
21	.0122	304/102	101/55	102/57	203/102

TI-NHT8A 001707

-MSG N#- 66425 FR-SBO1 TO-PCQA SEPT-02/15/91 06:44 AM
R#-177 ST-C DIV-0050 CC-00101 BY-SBO1 AT-02/15/91 06:44 AM

TO: Dave Csarn ✓ ZARM CC: Mike DeMattia PCQA
John Haynes ✓ PCQA Charlie Douglas CPFC
Matt Sellers PCME

FR: Steve Offiler SBO1

SJ: 77PS Design FMEA

The purpose of this memo is to explain in greater detail the recent schedule slip on the FMEA start date. According to previously agreed upon dates, the meetings were supposed to start up on Tuesday 91-02-12. They did not.

Today's highlights (91-02-15) will explain the activities given highest priority recently.

Items planned to receive highest priority in the coming few days include:

- ** Final emergency iteration to the 77PS spring (36889). Results of two recent calibration runs show this to be necessary. Steve N. indicates this late change will waste Eastern Automation design time, but fortunately nothing is in steel yet. Furthermore, the model shop is about to produce another 200 springs for us.

- ** Clean up myriad of details to finalize all production component prints and subassembly dwgs. to allow creation of parts lists.

- ** 77PS planning and creation of a detailed schedule.

I'd like to begin work on the DFMEA after the above are completed. I propose that the first meeting take place on Tuesday, 91-02-26, time and place T-B-D. The end date originally given of 91-04-18 will not change at this point.

Regards,
Steve O.

TI-NHTSA 001709

HIGHLIGHTS
Stephen B. Offler
Week Ending 02/15/91

Handwritten signature
HANS



FORD MY '92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: I have forwarded finalized envelope prints to George Randall, including the relaxed J512 tolerance and the widened terminal position tolerance. We also owe Bruce Pease new prints. His already carry the relaxed J512, so it is just a matter of the terminal position tolerance. These are planned within the next couple of weeks; Bruce is not indicating a priority is needed.

We're communicating with Tera Kuzume of TUJ regarding Tokico. Tokico inquired about 57PSL5-2, but we are steering them directly to 77PSL2-3 given their rough schedule which shows SOP 3Q92. Charlie has sent them envelope drawings. Tokico has expressed a concern about zinc plating on the hexport, citing galvanic corrosion. The material of their mating part is an aluminum/copper alloy according to TUJ. Tokico has suggested nickel plate as their preferred hexport finish. They'd like prototypes with nickel plate in four weeks. We have not formulated a response on this yet.

Charlie has received advance notice from Ford for Phase II production switches (Light Truck 57PSL5-2). They need 19 thru the end of March and need additional 106 thru the end of April. These must be built on production equipment.

We have shipped twelve 77PSL2-3 (Rev "A", tight J512) samples to George Randall on a priority basis against his order for 75. These are the first fully functional 77PS devices shipped. They use bases calibrated on the Mechanization calibrator. To confirm that nothing would go wrong with these first-pass 77PS calibrated switch assemblies, we did a full impulse test including 25K powered cycles before samples shipped. All devices passed. We are now preparing the balance of 63.

77PS: We have run two trial lots of 77PS switch assemblies on the Mechanization calibrator. The first lot of 100 is being used for customer samples and in-house testing. A geometry problem was resulting in the calibrator deforming the spring arms, but luckily the calibration operation was still successful and the parts easily passed life testing. The calibrator has been modified, and the second trial run showed no spring deformation. However, there is now a problem with our spring/movable terminal geometry. This problem was originally masked because the calibrator was deforming the spring. The second lot, which was run on 25 parts to collect measurement variation, has shown that the end of the spring which rivets to the movable terminal is too high. This forces the calibrator to deflect the stationary terminal excessively in order to get the t-pin bump to the desired height, and leaves the spring arm at an acute angle at contact transfer rather than perpendicular as intended. Further analysis is required to determine if the rivet hole in the spring or the movable terminal is out of position, and to correct the situation. This will receive high priority because it has immediate impact on Eastern Automation's programs.

PRODUCTION COMPONENTS/ISSUES: We met with representatives of Valenline to discuss discrepancies on FAI's of the rebound cap 27713 and the aluminum creep ring 74797. All issues should be rectified using three approaches: Valenline is reworking the tools, we are refining the prints, and we are resolving differences in measuring techniques.

We visited TDP to tour their facility and discuss details of the J512 ball gage fixturs. I have calculator...s ideal ball sizes, and done some work to show correlation of this

HIGHLIGHTS 91-02-15

Page 2

technique relative to known "standards", using the chamfer blocks Man had built up originally for the optical gage R&R. My results look promising. We explained the concept of gage R&R to TDR, and expect that they will be supportive if R&R problems arise.

We have completed a disc lifetime on production-intent discs using production equipment. We ran .0122" passivated and .013" non-passivated in Pass-Car and Light-Truck ranges. No failures turned up. Free-disc characterizations pre- and post-test showed minuscule drift over life.

TI-NHTSA 001711

TO: Bill Sweet
FM: Matt Sellers
SS: Highlights, w/E 2/15/91

CAN I SEE
Breakdown

Chrysler LH . . . Assumptions are use of G.M. Sensor Component tooling and Assembly tooling. Also use of Ford Pressure tester. Tooling Summary was passed on to marketing outlining the Program Tooling requirements, (\$131K). Component tooling includes two terminals and a base mold.

Terminals

* A.J. Knott	<u>Movable Tool</u> \$14.2K + \$23.56/K	<u>Stationary Tool</u> \$16.3K + \$57.33/K
* Bassler	\$18.8K + \$21.75/K	\$21.0K + \$63.78/K

* Stemmt, Bally, Thomas → In quote cycle still.

Base mold

* AFCC \$38.0K + \$85.63/K

* Nypro, Dumerst, etc. → In quote cycle still

Bassler has indicated that an updated quote is forthcoming. Hopefully will be more in-line with A.J. Knott. Lead time is critical. A.J. Knott says they can finish early June!?? Seems optimistic, but Bassler is into the second week in July; as we predicted.

↓ what are some
defect probs

77PS

Calibrator experiments with 77PS base assemblies have surfaced an additional problem with the spring (terminal) assembly. When calibrated, the spring is at an acute angle rather than horizontal. Impact on Eastern Automation tooling or terminal tooling has yet to be determined.

First 100 devices - 20 measured had a sign of 0.9 mils when measured with the design continuity method.

TI-NHTBA 001712

77PS Cont.

TDR will be released on T.I.'s gauge per a Final design review. The focus of the last design review was to discuss R&R Aspects of the measurement technique. The nesting technique in the gauge is key and TDR will make all efforts to provide consistency.

Production

Efforts to reduce low pin incidence have been concentrated on the pre-crimp Station. Alignment of the bottom plunger, and upgrades to the top plunger delivery system have reduced the defect percentage from 1 1/2 / 2% range to .3%.

77PS Cont.

Valentine is off tweaking the Alum. Ring and low-ratio cup tools per an FAI review meeting last Monday. Repair completion and review will be late next week.

Marketing has requested further breakdown of the CCPS tooling list. Specifically, they are requesting detail on what the T.I. Capital is buying. This request is being driven by Ford in an effort to ensure T.I. is buying re-usable assets. Mechanisms has been tasked to provide a detailed outline on the (4) pieces of automation.

-MSG #= 66425 FR=SB01 TO=PCQA SENT=02/15/91 06:44 AM
R#177 ST=C DIV=0050 CC=00101 BY=SB01 AT=02/15/91 06:44 AM

TO: Dave Czarn ✓ ZARN CC: Mike DeMattia PCQA
John Haynes ✓ PCQA Charlie Douglas CPFC
Matt Sellers PCHE

FR: Steve Offiler SB01

SJ: 77PS Design FMEA

The purpose of this memo is to explain in greater detail the recent schedule slip on the FMEA start date. According to previously agreed upon dates, the meetings were supposed to start up on Tuesday 91-02-12. They did not.

Today's highlights (91-02-15) will explain the activities given highest priority recently.

Items planned to receive highest priority in the coming few days include:

- ** Final emergency iteration to the 77PS spring (36889). Results of two recent calibration runs show this to be necessary. Steve M. indicates this late change will waste Eastern Automation design time, but fortunately nothing is in steel yet. Furthermore, the model shop is about to produce another 200 springs for us.

- ** Clean up myriad of details to finalize all production component prints and subassembly dwgs. to allow creation of parts lists.

- ** 77PS planning and creation of a detailed schedule.

I'd like to begin work on the DFMEA after the above are completed. I propose that the first meeting take place on Tuesday, 91-02-26, time and place T-B-D. The end date originally given of 91-04-18 will not change at this point.

Regards,
Steve O.

TI-NHTSA 001714

-MSG N#- 154568 FR-FRE3 TO-PCQA SENT=02/19/91 03:19 PM
R#-076 ST=C DIV=0050 CC=00484 BY=FRE3 AT=02/19/91 03:19 PM

TEXAS INSTRUMENTS INC.

ATTLEBORO, MASSACHUSETTS

MATERIALS & ELECTRICAL PRODUCTS GROUP

TELEPHONE CONVERSATION RECORD AND CONFIRMATION.

DATE FEB. 19, 1991

CUSTOMER: STEVE OFFILER

INDIVIDUAL: DAN FREEDMAN

I CALLED : 1:30PM (TIME)

OUR JOB # CRUISE CONTROL

PART # 46515 REV C (PENDING)

CONVERSATION NOTES: DISCUSSED DIMENSION 2X.063/.075 RADIUS (BUMP) CENTER VIEW,
WOULD LEFT TOP VIEW (BUMP) MAINTAIN RADIUS ON BOTH ENDS AND .543/.531 LONG.

CONVERSATION SUMMARY: YES, BOTH WOULD BE MAINTAINED IN CURRENT DESIGN AND
CLARIFIED WHEN UPDATING TO REVISION C.

NAME DAN FREEDMAN (MOLD DESIGN)

FRE3 N/S 1-46

EXT. (508) 699-1504

COPY:

RAY TOURANGEAU
BILL ARCHIBALD
NORM ROY
NORM TREMBLAY
STEVE WALTERS
DENNIS BOINOS
ANDY MCQUIRK

PCNE DAVE CSANN
APCO TOM CHARBONNEAU
NLDG NATT SELLERS
NLDG ~~BOB ANGELO~~
NLDG MIKE DEMATTIA
NLDG STEVE OFFILER
PCQA

SARN
TC
PCNE
NLDG
PCQA
SBO1

*Pub-
FYI -
Get m.d.s. Lm*

TI-NHTSA 001710

CCPS QUALITY ASSURANCE START-UP REQUIREMENTS

<u>ACTION</u>	<u>DATE REQUIRED</u>
REVIEW & UPDATE 57PS GAS/CHARACTERISTIC SHEETS	2/20
DESIGN FMEA	
START	???
COMPLETE	4/10
PROCESS FMEA	
START	???
COMPLETE	7/1
DEVELOP 77PS GAS (PRELIMINARY)	7/1
DEVELOP 77PS CHARACTERISTIC SHEETS	7/15
COMPLETE GAGE R&R STUDIES FOR ALL 77PS GAGES	7/15
ESTABLISH 77PS MANUFACTURING CONTROL PLAN	7/15
FINALIZE 77PS GAS	8/1
SUBMIT 77PS ISIR	8/1
ESTABLISH 77PS START-UP INSPECTION REQUIREMENTS	8/15
SET-UP 77PS SPC FILES	8/15

-MSG H#- 154568 FR-FRE3 TO-PCQA SENT-02/19/91 03:19 PM
R#-076 ST-C DIV-0050 CC-00484 BY-FRE3 AT-02/19/91 03:19 PM

TEXAS INSTRUMENTS INC.

ATTLEBORO, MASSACHUSETTS

MATERIALS & ELECTRICAL PRODUCTS GROUP

TELEPHONE CONVERSATION RECORD AND CONFIRMATION. DATE FEB. 19, 1991

CUSTOMER: STEVE OFFILER

INDIVIDUAL: DAN FREEDMAN

I CALLED : 1:30PM (TIME)

OUR JOB # CRUISE CONTROL

PART # 46515 REV C (PENDING)

CONVERSATION NOTES: DISCUSSED DIMENSION 2X.083/.075 RADIUS (BUMP) CENTER VIEW.

WOULD LEFT TOP VIEW (BUMP) MAINTAIN RADIUS ON BOTH ENDS AND .543/.531 LONG.


CONVERSATION SUMMARY: YES, BOTH WOULD BE MAINTAINED IN CURRENT DESIGN AND
CLEARIFIED WHEN UPDATING TO REVISION C.


NAME DAN FREEDMAN (HOLD DESIGN) FRE3 H/S 1-46 EXT. (508) 699-1504

COPY:	RAY TOURANGEAU	PCNE	DAVE CLARK	SAFN
	BILL ARCHIBALD	AFCO	TON CHARBONNEAU	TC
	NORM ROY	NLDG	MATT SELLERS	PCNE
	NORM TREMBLAY	NLDG	BOB ANGELO	NLDG
	STEVE WALTERS	NLDG	MIKE DEMATTIA	PCQA
	DENNIS BOINOS	NLDG	STEVE OFFILER	SBO1
	ANDY MCQUIRK	PCQA		

*Pub -
FUT -
Get mD in L.*

TI-NHTSA 001718





TMHTSA 001720

				Oct 9		Nov 9		Dec 9		Jan 9		Feb 9	
				1	2	3	4	5	6	7	8	9	10
1	ANAL. SUP. TUN. & SEC. TUN.	10/1/91	1/1/92										
2	SUP. ANAL. (10/1)	1/1/92	1/1/92										
3	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
4	SEC. TUN. TUN. TUN. (10/1)	1/1/92	1/1/92										
5	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
6	SUP. ANAL. (10/1)	1/1/92	1/1/92										
7	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
8	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
9	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
10	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
11	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
12	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
13	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
14	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
15	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
16	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
17	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
18	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
19	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
20	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
21	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
22	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
23	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
24	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
25	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
26	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
27	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
28	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
29	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
30	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
31	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
32	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
33	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
34	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
35	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
36	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
37	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
38	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92										
39	ANAL. SUP. TUN. TUN. (10/1)	1/1/92	1/1/92					</					

-MSG #= 176895 FR-CZRN TO-PCQA SENT=02/20/91 11:35 AM
 R#-100 ST-C DIV-0050 CC-00101 BY-CZRN AT=02/20/91 11:35 AM

FEBRUARY 20, 1991

TO: ROSTY STRUBEL	RCS2	CC: TOM CHARBONNEAU	TC
MIKE DeMATTIA	PCQA	JOHN KOURTISIS	NDES
CHARLIE DOUGLAS	CPPC	STEVE MAJOR	WHLE
DICK GARIEPY	MFPC	ANDY MCGUIRK	PCQA
PAUL KOTCH	PRK1	ED O'NEILL	EJON
JOE LASARE	JML8	JOE SCHUCK	NELI
STEVE OFFILER	SBO1	GARY SNYDER	CPPC
MATT SELLERS	PCME	MARTHA SULLIVAN	CPPC
BILL SWEET	PCME	RAY TOURANGEAU	PCME
GEORGE LAVOIE	B512	TED BALLARD	AVNE
JOHN HAYNES	PCQA	DAVE VARNEY	FORM
		SCOTT MARTIN	MFPC
		CLAIRE BALTHAZAR	MFPC
		BILL CONGDON	MFPC

FR: DAVE CZARN ZARN

SJ: FORD CRUISE CONTROL PRESSURE SWITCH START-UP MEETING:
 02/14/91 MEETING MINUTES

MEETING

THE NEXT MEETING IS SCHEDULED FOR

DATE: 02/21 (THURSDAY) **PLEASE NOTE
 TIME: 10:00-11:30 AM ROOM CHANGE**
 PLACE: Q-TIP ROOM

PLEASE CALL ME IF YOU ARE NOT ABLE TO ATTEND

* = NEW OR REVISED ITEMS

57 L/T

Export:

* FINAL GAGE REVIEW

* RELEASE GAGE FOR BUILD

. ELCO CONTROL PLAN
 (DELAYED DUE TO J512 GAGING DEFINITION)

. ISIR corrective actions:

* A. TERMINAL DIMENSIONS
 - M.C. STUDIES FROM AJ KNOTT

* DISC LIFE TEST FROM EACH LOT

. L/T PILOT RUN

. CREATE L/T HIS PARTS LIST
 AND B.O.M. (ORIG. DATE WAS INCORRECT)

* RESOLVE TERMINAL POS'N ISSUE

WHO	WHEN	
SELLERS/	02/05	ORIG.
OFFILER	02/14	REV.
	02/14	COMP.
SELLERS	02/07	ORIG.
	02/14	REV.
	02/18	COMP.
KOTCH	01/17	ORIG.
	02/28	REV.
KOTCH	01/04	ORIG.
	02/21	REV.
OFFILER/	02/14	ORIG.
GARIEPY	02/14	COMP.
SELLERS/	01/24	ORIG.
GARIEPY	03/18	REV.
OFFILER/	01/24	ORIG.
WILSON	03/07	REV.
TEAM	03/21	

TI-NHTSA 001722

57 P/C

* OFFSET POLARITY KEY BASE PRINT	OFFILER	11/16	ORIG.
		02/21	REV.
. P/C PILOT RUN	SELLERS/	01/31	ORIG.
	GARIFFY	03/18	REV.
. CREATE P/C EIS PARTS LIST	OFFILER/	01/24	ORIG.
AND B.O.M.	WILSON	02/21	REV.
. ENV. DWG. WITH REVISED POS'N TERM. TOL.	OFFILER	02/28	

77PS

. DESIGN UPDATE	OFFILER	ONGOING	
. MFG/MECH UPDATE	SELLERS	ONGOING	
. REPORT ON TOKICO P.S. RESPONSIBILITY	DOUGLAS	ONGOING	
. COMPLETE DESIGN FMEA	OFFILER	04/18	
. PROD. LINE LAYOUT	SELLERS	03/14	
. PROD. LINE SET-UP (RTE CARDS, ETC)	BALTHAZAR	TBD	
. PROVIDE DATES FOR COMPLETION OF ABOVE	BALTHAZAR	02/21	
. PROVIDE QUALITY RELATED CRITICAL PATH	HAYNES	02/21	
ITEMS TO TRACK AT S/U MTGS.			
* ORDER ADD'L M.S. TERM'S AND SPRINGS	OFFILER	02/07	ORIG.
		02/13	COMP.
* DETERMINE IF CLEARANCE SHOULD BE ADDED	OFFILER	02/14	ORIG.
FOR MOV. ARM IN THE BASE		02/14	COMP.

IQP'S:

. BASE	SELLERS	02/28	
--------	---------	-------	--

PRODUCTION COMPONENTS:

. ALUMINUM CRIMP RING	LAVOIE	02/11	
. REBUMP CUP	LAVOIE	02/27	
. MOVABLE TERM.	LAVOIE	03/01	
. STATIONARY TERM.	LAVOIE	03/22	
. BASE	SELLERS	03/06	ORIG.
(AFCC DELIV. DATE PUSH-OUT)		03/15	REV.
. HEXPORT (P/N 36900)	KOTCH	03/04	

MANUFACTURING EQUIPMENT:

. FINAL ASM MACHINE BUILD COMPLETION	SELLERS/	04/15	
	KOURTESIS		
. BASE ASM MACHINE BUILD COMPLETION	SELLERS/	05/31	
	KOURTESIS		
. PRESSURE TESTER BUILD COMPLETION	SELLERS/	06/06	
	KOURTESIS		

FORD AUSTRALIA

. FORD AUSTRALIA UPDATE	DOUGLAS	ONGOING	
-------------------------	---------	---------	--

DISCUSSION

57 L/T AND P/C

A BRAINSTORMING SESSION FOR IMPROVING TERMINAL POSITIONING WAS HELD WITH DESIGN/QUALITY/MFG ENG/MECH. MISALIGNMENT IS ALWAYS IN THE SAME DIRECTION; SEVERAL POSSIBLE CAUSES WERE IDENTIFIED. MFG. ENGINEERING WILL EVALUATE A FEW CONCEPTS THAT WERE DISCUSSED TO

IMPROVE POSITIONING.

77PS

CALIBRATOR DEBUG HAS HIGHLIGHTED WHAT APPEARS TO BE A PROBLEM WITH THE SPRING/THERMAL DESIGN. STEVE IS EVALUATING TO DETERMINE IF TOOLING CORRECTIONS ARE NEEDED.

CALIBRATED SWITCHES WERE SUCCESSFULLY IMPULSE TESTED. THE FIRST 77PS PRODUCTION INTENT SWITCHES WERE SHIPPED TO L/T LAST WEEK.

DISC LIFE TESTING CONFIRMED THAT THE PASSIVATED .0122" WILL BE ADEQUATE FOR THE 77PS.

BOTH ANI'S HAVE BEEN DELIVERED.

MILESTONES	PLANNED	ACTUAL
57 L/T ISIR	11/21/90	11/21/90
57 L/T JOB 1	07/01/91	
57 P/C ISIR	01/15/91	01/15/91
57 P/C JOB 1	06/03/91	
77PS ISIR	08/01/91	
77PS SOP (TI)	09/01/91	

PRODUCTION PLAN BY MONTH (THOUSANDS)

	P/C 57PSL3-3	L/T 57PSL3-2	P/C 77PSL2-1	L/T 77PSL2-2
FEB	0	0	0	0
MAR	5	0	0	0
APR	5	0	0	0
MAY	10	3	0	0
JUN	*17	4	0	0
JUL	17	*5	0	0
AUG	17	7	4	0
SEP	17	7	10	0
OCT	0	7	**12	5
NOV	0	7	17	7
DEC	0	0	17	**7

NOTE: PLAN FOR AUGUST AND BEYOND IS TENTATIVE.

* = JOB1 FOR 57PS VERSIONS

** = TENTATIVE JOB1 FOR 77PS VERSIONS

REGARDS,
DAVE CEARN | 11-FORD

TI-NHT8A 001724

HIGHLIGHTS
Stephen B. Offler
Week Ending 02/22/91



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: Communication with TIJ via Chadie Douglas regarding Tokico continues. They've clarified their need for a nickel-plate hexport. The master cylinder itself is made of aluminum (not Al/Cu alloy as reported earlier), but the brake lines are copper. Any zinc entering the system will cause corrosion of the brake tubing and potential failure. They seem quite firm on this issue. Chadie has met with Bob Baboian, who confirmed the above. He further indicated that a nickel-plate hexport, assembled to a zinc-plate cap and an aluminum crimp ring, will not be a problem. We have a verbal sample request for 12 77PS's with nickel-plate hexports, now due in 3 weeks. We will strip and replate hexports to meet this need. Matt Sellers is speaking with Denis Villard regarding a nickel-plating specification. Historically, we have used a chromium-over-nickel plating system on 52PS hexports, which shows excellent salt-spray resistance at a premium price.

We have just received a fax from TIJ showing an assembly of the Tokico master cylinder with pressure switch in place. Immediately apparent are: 1) they are using an O-ring seal; 2) they are allowing about 46mm for overall switch length minus thread, our device is 47.75mm; and 3) they are allowing 30mm max for overall diameter of the crimp ring, our device is 32.5mm. Of these issues, the O-ring is good news, the overall length may not be much of a problem (we may shave 1.75mm of the hex flats) but the diameter is a potential killer. Reducing this means redesign/retooling of the hexport, washer, cap, and connector, and possibly a move to a smaller disc as well.

We have shipped the balance of 63 77PS's to Ford Light Truck to complete their order of 75. Also, we shipped 3 77PS's (Pass-Car spec) to Bendix to complete their order.

77PS ISSUES: A dimensional study of the Model Shop prototype parts has highlighted areas which are contributing to the problems with the spring position. The movable-terminal end of the spring is too high, forcing the calibration operation to push the stationary contact down excessively in order to reach the predetermined bump height. The fact that the end is too high seems to be a stacking of the spring hole too low, the movable-terminal hole too high, and the base too short. We plan to restump the hole in the movable terminal (producing an oval slot) to bring the spring down where it belongs. This will require careful riveting. This is actually a problem related to prototype parts not meeting print; the prints themselves seem correct. A separate issue is the position of the bump, which is drastically off-center. I have updated the production print to correct this. A marking has been delivered to Mechanization to be forwarded to Eastern Automation.

Powered impulse testing of the 77PS contact system, using the 7440S low-current contact, shows acceptable performance but the contacts are obviously nearing the end of life. We plan some more extensive testing and formal analysis of the contacts.

Some analysis of the calibration data taken last week has been completed. The calibrator's reported measurement of each of 25 devices was compared with a manual measurement taken by Jeff DiDomenico. Six devices were also measured separately by the calibrator and Jeff to determine gaging errors. We found the calibrator gage error to be slightly tighter than Jeff's, sigma of roughly 0.12 mils vs 0.15 respectively. The data on the 25 devices shows very good agreement between the calibrator and Jeff; both have sigma's of 0.52 mils. Removing gage errors, it looks like the calibrator is capable of a sigma of about 0.4 mils.

Stephen B. O'Flair
Week Ending 02/22/91

CUSTOMER ISSUES: Communication with TU via Charlie Douglas regarding Tokico continues. They've clarified their need for a nickel-plate hexport. The master cylinder itself is made of aluminum (not A/Cu alloy as reported earlier), but the brake lines are copper. Any zinc entering the system will cause corrosion of the brake tubing and potential failure. They seem quite firm on this issue. Charlie has met with Bob Babolian, who confirmed the above. He further indicated that a nickel-plate hexport, assembled to a zinc-plate cup and an aluminum crimp ring, will not be a problem. We have a verbal sample request for 12 77PS's with nickel-plate hexports, now due in 3 weeks. We will strip and replate hexports to meet this need. Max Sellers is speaking with Denis Villard regarding a nickel-plating specification. Historically, we have used a chromium-over-nickel plating system on 52PS hexports, which shows excellent salt-spray resistance at a premium price.

We have just received a fax from TU showing an assembly of the Tokico master cylinder with pressure switch in place. Immediately apparent are: 1) they are using an O-ring seal; 2) they are allowing about 46mm for overall switch length minus thread, our device is 47.75mm; and 3) they are allowing 30mm max for overall diameter of the crimp ring, our device is 32.5mm. Of these issues, the O-ring is good news, the overall length may not be much of a problem (we may shave 1.75mm of the hex flats) but the diameter is a potential killer. Reducing this means redesign/retooling of the humpport, washer, cap, and converter, and possibly a move to a smaller die as well.

We have shipped the balance of 63 TTPS's to Ford Light Truck to complete their order of 75. Also, we shipped 3 TTPS's (Pass-Car spec) to Bendix to complete their order.

77PS ISSUES: A dimensional study of the Model Shop prototype parts has highlighted areas which are contributing to the problems with the spring position. The movable-terminal end of the spring is too high, forcing the calibration operation to push the stationary contact down excessively in order to reach the predetermined bump height. The fact that the end is too high seems to be a stacking of the spring hole too low, the movable-terminal hole too high, and the base too short. We plan to restamp the hole in the movable terminal (producing an oval slot) to bring the spring down where it belongs. This will require careful riveting. This is actually a problem related to prototype parts not meeting print; the prints themselves seem correct. A supreme issue is the position of the bump, which is drastically off-center. I have updated the production print to correct this. A markup has been delivered to Mechanization to be forwarded to Eastern Automation.

Powered impulse testing of the TTPS contact system, using the 74405 low-current contact, shows acceptable performance but the contacts are obviously nearing the end of life. We plan some more extensive testing and formal analysis of the contacts. DAVE

Some analysis of the calibration data taken last week has been completed. The calibrator's reported measurement of each of 25 devices was compared with a manual measurement taken by Jeff DiDomenico. Six devices were also measured repeatedly by the calibrator and Jeff to determine gaging errors. We found the calibrator gage error to be slightly tighter than Jeff's, sigma of roughly 0.12 mils vs 0.15 respectively. The data on the 25 devices shows very good agreement between the calibrator and Jeff; both have sigma's of 0.52 mils. Removing gage errors, it looks like the calibrator is capable of a sigma of about 0.4 mils.

TO: Bill Sweet
FM: Matt Sellers
SJ: Highlights . w/E 2/22/91

77PS

Mechanization has made up two of the four weeks pushout on the completion of the pressure tester build. They anticipate making up some additional time when an assessment is taken in the tool room.

Valentine has completed fixes on the aluminum crimp ring tool, and have re-submitted this morning. The cup tool is still being tweaked with completion expected by Monday. Valentine and T.I. will then re-convene at the inspection table and work out correlation issues and print issues.

Bassler has lost the "Ahead of schedule" status on the tools, and is currently toying with the original completion date. This was apparently due to problems with the Volvo project terminals. It is imperative that movable terminal samples be provided to Eastern Automation ASAP. Bassler must be on time.

Chrysler LH

Bassler and A.J. Knott are being exercised as the top two terminal supplier candidates. Both indicate a willingness to commit to a June 7 delivery in support of Chrysler's June 23 sample delivery requirement. A trip to A.J. Knott to complete an evaluation is planned for Monday.

TI-NHTSA 001727

AFCC and Nypro are candidates for tooling up the base mold. The issues with Nypro are lead time, no history, and reduced controllability by us. This tool will be the gating item in meeting the June 23 date. AFCC will be

LH Continued

Asked to propose A Single Cavity prototype to ensure timely Availability of bases. It looks like A 6-week delivery @ \$ 15K.

APG

The Ring Feeder upgrade is being delayed two weeks due to the Capital under \$5K Fund driving up A Req. will be cut the First week in March to Automation Devices Inc. A 6-week lead time is Anticipated. The Feeder will handle Alum And Steel

Peripoli / Robichaud are working on tweaks to Allow use of the Aluminum ring on the APG crimp nest are complete. Main dial nest are being done.

AMI

Chromate has consistently been allowing a better crimp than the un-chromated situation. we are still looking at a .005" to .010" shift in crimp diameter. we have not 'centered' the process yet. we are still skewed slightly high. However, the Indexer upgrade may assist in an $\bar{x}$ shift by improving the Alignment - thus reducing out of roundness

The indexer / table ^{has been delayed to 3/16 Installation} ~~change will be done next week~~ ~~to be done~~ due to problems with the indexer supplier.

The low Pin incidence rate has been dropped From 2-3% range to .1-.3% range! This was accomplished by re-design of the hold down probe and also upgrade of the bottom plunger. Bob Robichaud and Bassilier are drawing up A P.M. procedure for the operator to ensure consistent probe force on the disc

318356
8 22234

SALES CODE
502610

HOME, NEW YORK 10010

17713

01000000

DATE	INVOICE NO
07/26/91	02790

VOICE TO: VALENTINE TOOL & STAMPING, INC.
171 W MAIN ST
NORTON, MA 02766

SHIP TO: VALENTINE TOOL & STAMPING, INC.
171 W MAIN ST
NORTON, MA

ATTN: JEANNE LAPLANCHE, O.C. MGR.

ITEM (LINE)	NO. QTY	NO. INDS OR BOLS	UNIT PRICE	SHIPPED BY
177134	040	06	CMP	M S S

REQUIREMENTS OF:
ORDER NO 13428

COLOR CODE

IN NO	C	NR	P	S	ST	NI	CD	NO
466709	07	34	012	006	01			

ITEM	QTY	UNIT	PRICE	DESCRIPTION	DATE	TIME	LOCATION	REMARKS
125-127MM X 50.00MM	04000	Y	2.0000	04000 Y 2.0000				
101 -001 +005 -005				101 -001 +005 -005				
125 -025MM +127 -127MM				125 -025MM +127 -127MM				

CASE	ALUM KILD
NO. 100	C-1006

TEST REPORT




Certificate of Compliance

TEST: 1
2/27/91
Newly Public, Onsite County
My commission expires 2/27/91

I certify that the above figures are a true and correct copy of those contained in the records of this corporation.

O. Zingulini
HOME STEEL CO., INC.

7/20/91



SPECIFICATION: 100% COTTON

1. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 2. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 3. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 4. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 5. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 6. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 7. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 8. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 9. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**
 10. **ՀԱՅԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ՍՈՑԻԱԼԻՍՏԻԿԱՆ ԿՈՄՍՊՈՒԾԱԿԱՆ ԿՈՄԻՏԵ**

© 2005 Blackwell Publishing Ltd *Journal of Internal Medicine* 257: 105–112



DISSEMINATING AND TOLERATING IN
ACCORDANCE WITH 48 CFR 101-11.6

MANUFACTURED TO EXACTLY THE PRODUCT
SPECIFICATIONS APPROVED BY THE

CHINA (in Beijing) CONFIRMS ON
FOLLOWING FROM THE PARTIAL
APPROXIMATE FOR CONSTRUCTION REMAINS
FROM LINDENHURST AIRPORT

FORWARDING APPROVAL TO PRODUCTION
FROM THE NEW YORK OFFICE
IS REQUIRED PRIOR TO SUBMISSION
OF PRODUCTION

DATE MAY 20 1964 BY SP-5 J. W. B. / J. W. B.



TI-NHTSA 001730

DECLASSIFIED BY: 6032 JEP/STW ON: 04-11-2013

METRIC[illegible]

-MSG N#- 307114 FR-SBO1 TO-PCQA SENT-02/26/91 09:44 AM
R#-049 ST-C DIV-0050 CC-00101 BY-SBO1 AT-02/26/91 09:44 AM

TO: John Haynes PCQA CC: Dave Caarn ZARN
Joe Schuck WHLZ Mike DeMattia PCQA
Matt Sellers PCNE Charlie Douglas CPPC
Stan Romol SH2

FR: Steve Offiler SBO1

SJ: Conversation w/ Joe Schuck

Joe called me today in order to prep for his meeting this morning with George Randall and a call later today to Bruce Pease.

We have recently sent revised prints to George, showing the newly negotiated terminal alignment spec of 0.30mm +/- 0.20 and also showing J512 relaxed dimensions that match Bruce's prints. Now, we need to get ISIR approval for the Light Truck device (57PSL5-2) by demonstrating that we can meet the new terminal spec. I briefed Joe on the latest efforts to improve alignment, using 76PS tooling. Once solid improvements are obtained, we need to translate them to the production 57PS tooling. The timetable for this is unclear in my mind.

Joe suggested that we pull out the LF ISIR dimensional data, to determine if we are now in-spec. using the new tolerance. I have done this, and the answer is NO. Four of the six stationary-terminal measurements are outside the new range. All of the six movable-terminal measurements are in spec. Therefore, our only recourse is to make improvements to the 57PS tooling and resubmit dimensional data. We need to understand and communicate to Ford when this will happen.

On the subject of Pass-Car, Bruce Pease has informed us that he cannot use the color gray for his switches, because on certain carlines the CCPS will be located in close proximity to the 57PSL2-2 which is also gray. We can't use black because the truck CCPS is black. We can't use white or blue because of the 57PSF3-3 and -5, which are also Pass-Car brake switches. Ford Powertrain is requesting "dark, subdued" colors for underhood beautification reasons, which rules out green, red, yellow, and purple. We've tentatively arrived upon brown as the best possibility. This applies to both 57PSL3-3 and 77PSL2-1. Please direct any comments on this color choice to me immediately.

Regards,
Steve O.

TI-NHTSA 001731

CCPS QUALITY ASSURANCE START-UP REQUIREMENTS

<u>ACTION</u>	<u>DATE REQUIRED</u>
REVIEW & UPDATE 57PS QAS/CHARACTERISTIC SHEETS	2/28
DESIGN FMEA	
START	----
COMPLETE	4/15
PROCESS FMEA	
START	----
COMPLETE	7/1
DEVELOP 77PS QAS (PRELIMINARY)	7/1
DEVELOP 77PS CHARACTERISTIC SHEETS	7/15
COMPLETE GAGE R&R STUDIES FOR ALL 77PS GAGES	7/15
ESTABLISH 77PS MANUFACTURING CONTROL PLAN	7/15
FINALIZE 77PS QAS	8/1
SUBMIT 77PS ISIR	8/1
ESTABLISH 77PS START-UP INSPECTION REQUIREMENTS	8/15
SET-UP 77PS SPC FILES	8/15

TI-NHTSA 001732



PAGE 1 OF 1

THE DIMENSIONS INDICATED BELOW REPRESENT TEST RESULTS OF THE FINISHED RESASURING. ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DIFFER FROM THE SPECIFIED DIMENSIONS, THE DEVIATION INDICATES THE MEASURED ACTION PER EACH NON-COMPLIANCE IN THE APPROPRIATE COLUMN.

[illegible]

REMARKS AND/OR INSTRUCTIONS:

HIGHLIGHTS

Stephen B. Offler
Week Ending 91-04-05



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

57PS & CUSTOMER ISSUES: 56 production 57PSL5-3's for Pitts' ISIR were expedited on Thursday, 91-04-04. This had been planned for 04-11, but apparently the urgency for these parts was miscommunicated. Several issues arose during the build which required the intervention of many individuals, including Matt Sellers, Jeff DiDomenico, Bob Robichaud, Dave Peripoli, Rusty Struble, and myself. Exactly 62 good parts were ultimately completed: 56 for Pitts and 6 for the Q.A. dimensional check. The major problem encountered was final crimp of the aluminum crimp ring. Serious burrs are still forming, and in general the crimp operation is visually poor and obviously out of control. We are still working to understand why this iteration caused so much difficulty. Mfg. Eng. is working on various angles on the precrimp tool and various heights of the crimp nest. At one point during the build, it was realized that the tools have no preload device to push the switch down onto the sensor; addition of urethane bumpers to perform this function seemed to help. Bob R. is planning to design spring-loaded preload devices into these tools. Also, Jeff has pointed out that in his experience a slotted precrimp tool (as used on Bendix APT to clear the connector key) makes a large improvement. We hypothesize that this is because crimp ring material is not forced to compress as it is moved inward; rather the slot gives material a place to go. We are looking into ways to prototype this concept.

Regarding the Tier-1 hydraulic testing, I have spoken with all three players. Gary Iancuili of Dana-Weatherhead has given me his requirements, and I have requested that Jim Cosina of Kelsey-Hayes and Jack Hutcherson of Pitts give me their requirements by Monday of next week. Our model shop will be building roughly three dozen parts with maximum J512 chamfer runout and another three dozen produced to "ideal" dimensions to represent best and worst case. We plan to charge the three Tier-1's accordingly for these.

We have reached the conclusion of the terminal position issue. Dave P. and Matt have been able to demonstrate significant improvements, and we can now hit 0.50 ± 0.25 with a Cpk approaching 1.33. Ford has recognized our efforts, and granted a tolerance relaxation. We expedited SREA's for all four parts, and I am trying to expedite the 57PSL5-2 envelope print to George Randall because he has not entered it into his system yet, but needs it now. In order to issue the change request for this print, it was necessary to spend time to learn the Electronic Change Notice system.

As part of our efforts on the calibration specification experiment, I have learned that the Valentine 27713 cup and the model shop rebumped 27288 perform very similarly, which means that all our Pitts-Car disc development efforts with rebumps will carry over to production.

77PS ISSUES: We have received the two TDR J512 chamfer gages. Matt and I did another R&R on both gages; results look good. Exercising the equations I've developed (using a Lotus spreadsheet) we've discovered that the latest Elco hexport submission looks good on the chamfer diameter but the angle is low, measuring 40.5 degrees against a spec. of 41-43. Furthermore, I have confirmed the accuracy of the gage readings of the angles by sectioning a part and measuring it myself.

We have finished calibrating all of our prototype 77PS switch assemblies, using the calibrator on the AMI with Mickey-Mouse'd nests and controls. Our results were much worse than the initial iterations with the calibrator stand-alone on a bench. Only about 32% of the parts fell into the target window. We have sorted the remainder, and should be able to use them by pinning individually. We have a total of 170 usable parts. The reasons why this iteration fared so poorly are definitely related to the fact that everything is just slapped together. We will continue with serious iteration when we have production-representative parts available and the calibrator is properly tied into the AMI mechanically and electrically, roughly 2-3 weeks.

We had a meeting with Steve Walters on the 46515 FAI (77PS production base mold). We are down to the point of working out details; making minor tool mod's and/or changing the prints as needed. The parts are looking quite good.

The 77PS test to check the slotted terminal prototypes and to experiment with slow vs. fast powered cycles for contact design reasons is progressing. We should be able to finish the powered cycles over the coming weekend and have results early next week.

HIGHLIGHTS
Stephen B. Offler
Week Ending 91-04-05



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE P5

57PS & CUSTOMER ISSUES: 56 production 57PSL5-3's for Pitts' ISIR were expedited on Thursday, 91-04-04. This had been planned for 04-11, but apparently the urgency for these parts was miscommunicated. Several issues arose during the build which required the intervention of many individuals, including Matt Sellers, Jeff DiDomenico, Bob Rubichand, Dave Peripoli, Rusty Struble, and myself. Exactly 62 good parts were ultimately completed; 56 for Pitts and 6 for the Q.A. dimensional check. The major problem encountered was final crimp of the aluminum crimp ring. Serious burrs are still forming, and in general the crimp operation is visually poor and obviously out of control. We are still working to understand why this iteration caused so much difficulty. Mfg. Eng. is working on various angles on the precrimp tool and various heights of the crimp seat. At one point during the build, it was realized that the tools have no preload device to push the switch down onto the sensor; addition of urethane bumpers to perform this function seemed to help. Bob R. is planning to design spring-loaded preload devices into these tools. Also, Jeff has pointed out that in his experience a slotted precrimp tool (as used on Bendix APT to clear the connector key) makes a large improvement. We hypothesize that this is because crimp ring material is not forced to compress as it is moved inward; rather the slot gives material a place to go. We are looking into ways to prototype this concept.

Regarding the Tier-1 hydraulic testing, I have spoken with all three players. Gary Inanelli of Dana-Weatherhead has given me his requirements, and I have requested that Jim Charles of Kelsey-Hayes and Jack Hachmann of Pitts give me their requirements by Monday of next week. Our model shop will be building roughly three dozen parts with maximum IS12 chamber rimout and another three dozen produced to "ideal" dimensions to represent best and worst case. We plan to charge the three Tier-1's accordingly for these.

We have reached the conclusion of the terminal position issue. Dave P. and Matt have been able to demonstrate significant improvements, and we can now hit 0.50 ± 0.25 with a Cpk approaching 1.33. Ford has recognized our efforts, and granted a telephony relaxation. We expedited SREA's for all four parts, and I am trying to expedite the 57PSL5-2 envelope print to George Randall because he has not entered it into his system yet, but needs it now. In order to issue the change request for this print, it was necessary to spend time to learn the Electronic Change Notice system.

As part of our efforts on the calibration specification experiment, I have learned that the Valentine 27713 cup and the model shop rebumped 27288 perform very similarly, which means that all our Pace-Car disc development efforts with rebumps will carry over to production.

77PS ISSUES: We have received the two TDR IS12 chamber gages. Matt and I did another R&R on both gages; results look good. Exercising the equations I've developed (using a Lotus spreadsheet) we've discovered that the latest Elco handset submission looks good on the chamber diameter but the angle is low, measuring 40.5 degrees against a spec. of 41-43. Furthermore, I have confirmed the accuracy of the gage readings of the angle by sectioning a part and measuring it myself.

TI-NHTSA 001812

We have finished calibrating all of our prototype 77PS switch assemblies, using the calibrator on the AMI with Mickey-Mouse'd nests and controls. Our results were much worse than the initial iterations with the calibrator stand-alone on a bench. Only about 32% of the parts fell into the target window. We have sorted the remainder, and should be able to use them by pinning individually. We have a total of 170 usable parts. The reasons why this iteration fared so poorly are definitely related to the fact that everything is just slapped together. We will continue with serious iteration when we have production-representative parts available and the calibrator is properly tied into the AMI mechanically and electrically, roughly 2-3 weeks.

We had a meeting with Steve Walters on the 46315 FAI (77PS production base mold). We are down to the point of working out details; making minor tool mod's and/or changing the prints as needed. The parts are looking quite good.

The 77PS test to check the slotted terminal prototypes and to experiment with slow vs. fast powered cycles for contact design reasons is progressing. We should be able to finish the powered cycles over the coming weekend and have results early next week.

TI-NHTSA 001813

TO: BILL SWEET
FM: MATT SELLERS
SJ: HIGHLIGHTS FOR W/E 4/05/91

77PS

TERMINAL POSITION UPDATE ... STAKING TOOL RE-DESIGN EFFORTS HAVE NOW BEEN BROUGHT TO A CLOSE WITH INCREMENTAL IMPROVEMENT IN OUR TERMINAL POSITION CAPABILITY WITH ALL 57PS BASED PRODUCTS. LAST UPDATE ON PROGRESS HAD INDICATED THAT SIGMA VARIABILITY HAD BEEN REDUCED, BUT WITHOUT BEING ABLE TO CENTER THE MEAN TO THE SPEC. TOOL ITERATIONS HAVE NOW CENTERED THE MEAN AND MAINTAINED A REDUCED SIGMA VARIABILITY. CURRENT CAPABILITY IS $\pm .010$ ". ORIGINAL CAPABILITY WAS $\pm .0315$ ".

A DETAILED SUMMARIZATION OF THESE EFFORTS WERE PRESENTED TO FORD AND RESULTED IN AUTHORIZATION TO CHANGE THE ENVELOP TO $\pm .010$ ".

THE REVISED TOOL DESIGN HAS BEEN INCORPORATED INTO THE NEW CHRYSLER LH STAKING SYSTEM, AND WILL BE INCORPORATED INTO 77PS, 52PS, AND 76PS.

57PSL5-S FORD PASS CAR ... SHIPPED 56 DEVICES TO PITT'S OF TEXAS THURSDAY AFTERNOON. THIS WAS THE 1ST PRODUCTION LOT OF THESE DEVICES, AND SERVED TO SURFACE SEVERAL IMPROVEMENTS THAT NEED TO BE MADE STILL: ALUMINUM RING CODING, ALUMINUM RING CRIMPING, AND PRESSURE TESTER FIXTURING. ALL NEED TO BE GIVEN TOP PRIORITY DUE TO LARGE UPCOMING PRODUCTION ORDERS.

TDR HEXPORT GAUGES ... TDR DELIVERED BOTH J512 HEXPORT GAUGING SYSTEMS TO T.J. THIS WEEK ALONG WITH HAND WRITTEN PRINTS. THE GAUGES HAVE PROVED TO BE EXCEPTIONAL WITH RESPECT TO CONSTRUCTION AND REPEATABILITY. CORRELATION TO SECTIONING MEASUREMENTS TECHNIQUES IS WITHIN 1/4 DEGREE. ELCO'S GAUGE WILL BE FORWARDED TODAY OR MONDAY.

FORCE DEFLECTION SPC GAUGING ... A SYSTEM TO MONITOR PROCESS VARIATIONS WITH MOVABLE TERMINAL ASSEMBLY FORCE DEFLECTION HAS BEEN CONCEPTUALIZED AND WILL BE BROUGHT INTO USE BY TWO PATHS. ONE WILL BE TO HAVE DAVE P. BUILD A NESTING STATION TO BE USED ON AN EXISTING FORCE DEFLECTION GAUGE. THE OTHER WILL BE TO CONSULT WITH TDR & PRECISION PROD. TO QUOTE A STAND ALONE SYSTEM.

36900-1 J612 HEXPORT ... ELCO SUBMITTED THERE FAI AND MCS DATA ON THIS PART. THE FAI WAS DONE PROPERLY AND IS CURRENTLY BEING CORRELATED. HOWEVER, THE MCS DATA WAS INADVERTENTLY PERFORMED ON UN-PLATED PARTS. ELCO FELT THIS WAS WHAT WE WOULD BE LOOKING FOR. WE HAVE HAD TO SHIP BACK 50 PIECES FROM A RECENT SHIPMENT SO THAT THEY COULD DUPLICATE THE STUDY ON PLATED PARTS.

ELCO REJECTIONS/POULSEN QUOTATIONS ... SEVERAL REJECTIONS FOR CONTAMINATED AND ONLY PARTS HAVE BEEN FOUND RECENTLY. ELCO CORRECTIVE ACTIONS HAVENT BEEN HEARD YET. SOME HAVE BEEN RTS, OTHERS HAVE BEEN US AS IS DUE TO PRODUCTION REQUIREMENTS AND LACK OF FUNCTIONAL CONCERN.

POULSEN HAS BEEN SLOW TO RESPOND TO QUOTATION REQUEST WITH THREE HEXPORTS. THEY ARE QUOTING A 52PS, 57PS AND 77PS HEXPORTS. MAYBE AN ELCO COMPETITOR?

BASE MOLD FAI RESULTS ... AN FAI REVIEW MEETING THIS WEEK ON THE 48515 BASE MOLD RESULTED IN ACTION FOR BOTH PRECISION AND AFCC. A HANDFUL OF ISSUES WITH STEEL SAFE DIMENSIONS HAVE BEEN IDENTIFIED AS NEEDING CORRECTION. ANOTHER COUPLE OF ISSUES WILL BE HANDLED THROUGH PRINT REVISION WHERE ALLOWED BY ENVELOP REQUIREMENTS. RECOVERY SCHEDULE IS COMPLETION IN 1-1/2 WEEKS.

BASSLER TERMINALS ... PROBLEMS WITH BOTH BASSLER TOOLS. THEY CANNOT MEET OUR TERMINAL TIP DIMENSIONAL REQUIREMENTS WITH THE CURRENT TOOL DESIGN. SEVERAL ITERATIONS HAVE BEEN TRIED WITH NO SUCCESS. MATERIAL GEOMETRY AFTER COINING CANT BE ADEQUATELY PREDICTED. A FEW STATION NOW HAVE TO BE ALTERED/REPLACED. ESSENTIALLY THE TIP WILL NOW HAVE TO BE TRIMMED TO DIMENSION. ABOUT \$2000.00 PER TOOL BASSLER WILL EAT. RECOVERY SCHEDULE IS TWO WEEKS FOR THE STATIONARY AND AN ADDITIONAL WEEK BEYOND FOR MOVABLE. BASSLER WAS INSTRUCTED TO RUN OFF ENOUGH TERMINAL PRIOR TO TEAR DOWN TO SUPPORT DE-BUGS.

BASE CALIBRATOR STATUS ... INSTALLED ON THE AMI AND WITH PROTOTYPE NEST AND PARTS THE CALIBRATOR IS BEHAVING TERRIBLE. BASE DIMENSIONS ARE ALL OVER THE PLACE VARYING AS MUCH AS .010". PROBLEM ANALYSIS WILL BE AN IN-DEPTH STUDY. THEREFORE, WE HAVE PUT ADDITION CALIBRATOR EVAL'S ON HOLD UNTIL PRODUCTION MATERIAL IS AVAILABLE, (THREE WEEKS). AT THAT TIME WE WILL SEE IF THE PROBLEMS ARE RELATED TO THE PROTOTYPE SET-UP ALONE.

TERMINAL REEL ORDERS ... BASSLER HAS TRIED OUT THE 6SPS REELS WITH SUCCESS. THE TERMINALS SEEM TO REEL UP NICELY. WE ALSO FOUND OUT THAT ABOUT 16K PARTS CAN BE PUT ON EACH REEL. PREVIOUS PREDICTIONS WERE 4K TO 5K. DUE TO WEIGHT CONCERNS WE WILL HAVE TO LIMIT THE AMOUNT TO SOME QUANTITY.

ORDERS HAVE TO BE PLACED FOR REELS. WE WILL NEED ABOUT 25 REELS TO START. TOTAL BILL WILL BE \$1400.00. CHARGES TO PC093?

EASTERN AUTOMATION PROGRESS ... THEY WILL HAVE TO BE VISITED FOR A TOOLING REVIEW LATER THIS MONTH. MECHANIZATION AND MANUFACTURING ENG. SHOULD BE REPRESENTED. NEED FEEDBACK FROM YOU SO THAT PLANS CAN BE MADE IN ADVANCE.

CHRYSLER LH PROJECT

ALL TOOLS PROGRESSING ON SCHEDULE. DETAILED SCHEDULES WERE RECEIVED ON THE BASE MOLD AND ASSEMBLY TOOLING THIS WEEK, AND ARE SUPPORTING PROJECTED DUE DATES.

TOWNSEND WAS IN THIS WEEK TO REVIEW OUR REQUIREMENTS AND BEGIN THE QUOTE PROCESS. QUOTES ARE DUE NOT LATER THAN MONDAY. VERBAL QUOTE WAS OUT TO LUNCH, (\$10K PER RIVETER), THEY WERE TOLD THAT WE ARE EXPECTING ABOUT \$8K EACH.

MECHANIZATION HAS BEEN ASKED TO MAKE THE RIVETING TOOLS ADAPTABLE TO 52PS RIVETER'S. THIS WILL TAKE THE HEAT OFF PROCURING THE RIVETERS SO FAST. MARKETING SUPPORTS THIS ALSO.

**KELSEY-HAYES GROUP**

April 5, 1991
 Revised April 6, 1991

JAMES COSSINS
 Kelsey-Hayes Group
 38481 Huron River Drive
 Romulus, Michigan 48174

Steve Offiler
 Texas Instruments
 Mail Stop 13-39
 34 Forest Street
 Attleboro, MA 02703

Dear Steve,
 In response to Bruce Pease's letter dated December 21, 1990, samples will be required with specific tolerances. The samples should have dimensions A, B, and C (see attached print) as close to the targets as possible and all other dimensions must be within the specified limits.

Qty.	P/N	Dim A	Dim B	Dim C dia.
I. 7	F2VC-SF924-BA	(.103) 9.44 (.004) 1.10 (.004) 5.85		
II. 7	F2VC-SF924-BA	(.103) 9.45 (.004) 1.40 (.004) 5.85		
III. 7	F2VC-SF924-BA	(.103) 9.39 (.004) 1.40 (.004) 5.85		

When the pressure switches are submitted please serialize the samples and provide list of dimensions A-C for each switch.
 The order will be submitted to Joe Schuck through the Kelsey-Hayes prototype department immediately.

Sincerely,


 James Cossins

TI-NHTSA 001817

**TEXAS INSTRUMENT INCORPORATED
FORD CCPS NY93 L/T PRICE QUOTATION**

INTRODUCTION/PURPOSE

- WITH NY92, FORD BEGINS CONVERSION FROM A VACUUM BASED TO AN ELECTRONIC BASED CRUISE CONTROL SYSTEM.
- TI HAS ALREADY SECURED NY92 BUSINESS.
- THIS PROPOSAL IS IN RESPONSE TO A FORD REQUEST FOR PIECE PRICE ON NY93 L/T (EXPECTED VOLUME 550K - 660K).
- WE EXPECT P/C TO FOLLOW VERY SOON WITH AN RFO OF THEIR OWN FOR NY93.
- TI GOAL IS TO USE THIS PROPOSAL TO SECURE ALL NY93 CCPS BUSINESS.

TI44HTSA 001818

**TEXAS INSTRUMENT, INCORPORATED
FORD CCPS NY93 L/T PRICE QUOTATION**

BACKGROUND/HISTORY

- o TI FIRST ENGAGED WITH FORD ON THIS PROGRAM IN 1987.
- o TI HAS BEEN INVOLVED AS SOLE SUPPLIER IN DEVELOPING PRODUCT WITH FORD ENGINEERING.
- o INITIAL ENGAGEMENT TARGETED THE FOLLOWING COST GOALS (HANDED DOWN BY FORD).
 - PIECE PRICE: \$1.75 - \$1.90
 - TOOLING COST: \$700K - \$900K
- o EVOLUTION OF PRODUCT LED TO TI SECURING NY92 BUSINESS AT THE FOLLOWING COSTS:
 - PIECE PRICE: \$2.21
 - TOOLING COST: \$1320K

TI-NHTSA 001819

11 APR 91 CD/DAA 050-0175

**TEXAS INSTRUMENT, INCORPORATED
FORD CCPS MY93 L/T PRICE QUOTATION**

CURRENT STATUS

- o BECAUSE OF TIMING DELAYS ON PART OF FORD IN RELEASING TOOLING FUNDS, TI WILL START MY92 PRODUCTION WITH MODIFIED VERSION OF 57PS.
- o RUNNING CHANGE WILL BE MADE TO 77PS NO SOONER THAN 3 MONTHS AFTER START OF PRODUCTION (FORD RULES).
- o INTERNAL OBJECTIVE TO BE CAPABLE OF RUNNING 57PSL TYPE DEVICES (POWER STEERING) ON CCPS AUTOMATED TOOLING BY MY93 (CURRENTLY ONLY SEMI-AUTOMATED).

TI-NHTSA 001820

11 APR 91 CD/DAA 050-0175

**TEXAS INSTRUMENT INCORPORATED
FORD CCPS NY93 L/T PRICE QUOTATION**

COMPETITION

o RFQ BEING SENT TO TI ONLY.

- WITH NEW PROGRAMS, WHEN NEW PLATFORMS ARE ADDED, FORD SENDS OUT AN RFQ AS A MATTER OF POLICY.
- EVEN THOUGH WE HAD A NY92 CCPS AGREEMENT, WE STILL RESPONDED TO RFQ'S FOR EACH PLATFORM USING CCPS.

o HYSTAT WILL BE A COMPETITOR IN FUTURE.

- MOST LIKELY NY94/95 TIME FRAME WHEN P/C GROUP MOVES CCPS FROM PROP VALVE TO MASTER CYLINDER.
- PLAN TO BEGIN ADDRESSING THIS ISSUE SERIOUSLY DURING LATE 3091/EARLY 4091 (I.E. ONCE WE HAVE ASSURED A SMOOTH PRODUCTION START).

o AS A RESULT OF PRESSURE SWITCH COMMODITY TEAM, FOLLOWING COMPETITORS WILL BE DROPPED AT FORD (MAAO).

- G.E.
- TOD
- ROBERT SHAW

TI-NHTSA 001821

11 APR 91 CD/DAA 050-0175

**TEXAS INSTRUMENTS INCORPORATED
FORD CCPS NY93 L/T PRICE QUOTATION**

TI STRATEGY/OBJECTIVE

- o **PROVIDE A PIECE PRICE CONSISTENT WITH EXPECTATIONS UNDER CURRENT AUTOMOTIVE ECONOMIC CLIMATE WHILE AT THE SAME TIME MAINTAINING/ IMPROVING LEVEL OF GPN.**
 - **GOAL IS TO SECURE A THREE-YEAR EXTENSION IN AN EXPEDITIOUS MANNER.**
 - **WILL LOCK OUT COMPETITION THROUGH NY95 (HYSTAT OFFERING UNSOLICITED QUOTES).**
- o **IF LONG-TERM AGREEMENT CANNOT BE REACHED AT TERMS FAVORABLE TO TI, WILL FALL BACK TO SECURING NY93 EXTENSION ALONE (AT THE PRESENT TIME).**
 - **CUSTOMIZED FEATURES OF HEXPORT GIVE TI A COMPETITIVE ADVANTAGE.**

TI-MMTSA 001822

11 APR 91 CD/DAA 050-0175

**TEXAS INSTRUMENT INCORPORATED
FORD CCPS MY93 L/T PRICE QUOTATION**

RECOMMENDATIONS

- o MAINTAIN MY92 PIECE PRICE OF \$2.21 FOR MY93.
 - REPRESENTS GPM OF 30+Z DURING SECOND YEAR OF PRODUCT LIFE CYCLE.
 - AVOIDS ANY UNNECESSARY COMPETITION AT THIS POINT IN PROGRAM.
- o USE OPPORTUNITY AS A BASIS FOR QUOTING MULTI-YEAR EXTENSION.
 - ELIMINATE HYSTAT THREAT THROUGH MY95.

TI-NHTSA 001823

11 APR 91 CD/DAA 050-0175

TEXAS INSTRUMENTS INCORPORATED
FORD CCPS NY93 L/T PRICE QUOTATION

ANALYSIS SUMMARY

<u>ITEM</u>	<u>NY93 \$</u>
EAU (K)	550
ASP (\$)	\$2.21
TOTAL COST (\$)	\$1.46
N.R. (\$K)	\$1216
GPH (Z)	33.9Z
D&A (Z)	17.8Z
ORG. PFT. (Z)	16.1Z
GPH (\$K)	\$412
ORG. PFT. (\$K)	\$196
PAT ROA (Z)	14.5Z

TI-NHTSA 001824

11 APR 91 CD/DAA 050-0175

INITIAL SAMPLE WARRANT

No. 22-394

PART INFORMATION

Part Name NEXT GENERATION SPEED CONTROL Part Number F2VC-9F924-AB
 Control Item ☒ Yes ☐ No Engineering Change Level G Date 4-11-91
 Engineering Change Authorization BRICE-PEASE Date _____
 Shown on Drawing No. F2VC-9F924-AB Part Weight 062

Reason for Initial Sample:

☐ Initial Submission ☐ Change in Optional Construction or Material ☐ Process Change
☐ Engineering Change ☐ Additional, Replacement, or Refurbished Testing ☐ Change in Subcontractor or Source
☐ Tooling Transfer ☒ Correction of Discrepancy (Reproduction No. SEE BELOW) ☐ Parts Produced at Additional Location
☐ Other - Please Specify _____

SUPPLIER INFORMATION (Manufacturing Location)

Supplier Name TEXAS INSTRUMENTS Street Address 34 FOREST STREET
 City ATTLEBORO State MA Postal Code 02703 Country USA
 Supplier Mfg. Location Code - DUNS TG97K Customer Assigned FORD MOTOR CO - EED

CUSTOMER INFORMATION

Customer Name FORD MOTOR CO - EED Buyer FRED HENDERSHOT Buyer Code 185
 Purchase Order Number _____ Sample Acceptance Level 2
 Application NEXT GENERATION SPEED CONTROL

RESULTS

The results for dimensional measurements ☒, material tests ☒, and functional (EE) tests ☒ meet all drawing and specification requirements ☒ Yes ☐ No

Submission Checklist

☐ Checked Print ☐ Material Test Results ☐ Control Plan
☐ Auxiliary Drawings/Tables ☐ Certifications ☐ Process Capability Results
☐ Correct Number of Samples ☒ Functional (EE) Test Results ☐ Process Flow Diagram
☒ Engineering Approval ☐ Product Engineering Approval ☐ Size Measurement Results

Supporting data for all requirements are available upon request.

COMMENTS:

ISR SUPPLEMENT WITH ADDITIONAL TESTING TO CLOSE OUT ALERT NO. A1C166193:
ALSO, CORRECTED DIMENSIONS. PART PREVIOUSLY APPROVED ON
ISR # 712384 DATED 9/15/91

DECLARATION

I affirm that the samples submitted by this warrant are representative of our parts and have been made to the applicable customer drawings and specifications from specified material, on regular production testing with no operations other than the regular production process.

Authorized Signature JIM NATT Date 12/20/91
 Title QA ENGINEER Phone No. 508-699-1719

Approval (when required) ☒ Approved ☐ Rejected

Signature _____ Date 1/10/92

Form 202C

TI-NHTSA 001825

TEXAS INSTRUMENTS



Ford Motor Company
17000 Oakwood Blvd.
P.O. Box 1586-D-2015
Dearborn, Michigan 48121

January 10, 1992

Attn: Mr. Mark Scholler

Subj: ISIR Submission (Component Material Change)
Ford Part Number F2VC-9F924-AB
Pass Car Series

Ref: SREA No. 147671

Dear Mark,

Enclosed, please find our ISIR submission to document the environmental seal material change for the NGSC deactivation switch, Ford part number F2VC-9F924-AB. The submission includes a copy of the approved Supplier Request For Engineering Approval (SREA) no. 147671.

Please let me know if you have any questions or if I may be of any further assistance.

Regards,


Jim Watt
URA Engineer
Precision Controls Department
Control Products Division

cc: Dave Czarn, MS 12-29; Charlie Douglas, MS 12-33
Andy McGuirk, MS 12-27
Steve Majors, TI Farmington Hills, Michigan

enc1: ISIR submission

PART INFORMATION

Part Name Next Generation Speed Control Part Number F2VC-9F924-AB
Control Item ☐ Yes ☐ No Engineering Change Level _____ Date _____
Engineering Change Authorization Bruce Page Date _____
Shown on Drawing No. F2VC-9F924-AB Part Weight .062
Reason for Initial Sample:
☐ Initial Submission ☒ Change in Optional Construction or Material ☐ Process Change
☐ Engineering Change(s) ☐ Additional, Replacement, or Returbished Testing ☐ Change in Subcontractor or Source
☐ Tooling Transfer ☐ Correction of Discrepancy (Resubmission No. _____) ☐ Parts Produced at Additional Location
☐ Other - Please Specify _____

SUPPLIER INFORMATION (Manufacturing Location)

Supplier Name Texm Instruments Int. Street Address 34 Forest Street
City Attleboro State Ma Postal Code 01703 Country USA
Supplier Mfg. Location Code - DUNS T097K Customer Assigned Ford Motor Co - EED

CUSTOMER INFORMATION

Customer Name Ford Motor Co. - EED Buyer Fred Henderahot Buyer Code 165
Purchase Order Number _____ Sample Acceptance Level _____
Application Next Generation Speed Control

RESULTS

The results for dimensional measurements ☐, material tests ☐, and functional (ES) tests ☐ meet all drawing and specification requirements ☐ Yes ☐ No

Submission Checklist

☐ Checked Print	☒ Material Test Results	☐ Control Plan
☐ Auxiliary Drawings/Sketches	☐ Certifications	☐ Process Capability Results
☐ Correct Number of Samples	☐ Functional (ES) Test Results	☐ Process Flow Diagram
☐ Dimensional Results	☐ Product Engineering Approval	☐ Gage (Measurement) Studies

Supporting data for all requirements are available upon request.

COMMENTS:

Submission due to change of environmental seal material composition
and copy of area is attached.

DECLARATION

I affirm that the samples represented by this warrant are representative of our parts and have been made to the applicable customer drawings and specifications from specified materials, on regular production tooling with no operations other than the regular production process.

Authorized Signature Jim Watt Date 9 Jan 92
Print Name Jim Watt Title QA Engineer Phone No. 508-699-1719

APPROVAL (when required by customer procedure) ☐ Approved ☐ Rejected

Signature _____ Date _____
B-292C

No. 147671

Supplier Request for Engineering Approval

DATE November 5 1971

SUPPLIER TO COMPLETE

SUPPLIER NAME AND ADDRESS

Texas Instruments Incorporated, 34 Forest Street, Attleboro, MA 02703

FORD AND/OR SUPPLIER PART NAME AND PART NUMBER OF ASSEMBLY AND ITS COMPONENTS

SWITCH AST - SPEED CONTROL DEACTIVATE

(delta) F2VC-9F924-AB

DESIGN	YES	NO
COMPOSITION	YES	NO
PROCESSING	YES	NO
DESCRIPTION	YES	NO

CHANGE: ☐ DESIGN ☒ COMPOSITION ☐ PROCESSING ☐ DESCRIPTION

The proposed change involves use of a blue-colored environmental seal in place of the present seal, which is reddish in color with a black stripe on its outer circumference. The blue seal is identical in dimensions and material, except for pigmentation. Presently, only the black stripe differentiates the pass-car seal, which has slightly different dimensions from other similar seals.

EFFECT OF CHANGE

No effect on device performance or cost. Benefit is reduced possibility of assembly error.

INTERCHANGEABILITY AFFECTED

ASSEMBLY

☐ YES☒ NO

COMPONENTS

☐ YES☒ NO

TOOLING OR FACILITY CHANGES REQUIRED

IF YES, COST EFFECT \$

☐ YES☒ NO

TIME TO INCORPORATE CHANGE AFTER APPROVAL

Approx. 4-6 weeks.

PRICE COST AFFECTED

IF YES, COST EFFECT \$

☐ YES☒ NO

WILL INCORPORATION OF CHANGE AFFECT SHIPPING SCHEDULE

☐ YES☒ NO

SIGNATURE

S. J. Mc... 9/11/05

PRODUCT ENGINEERING TO COMPLETE

PCR IN PROCESS

☒ APPROVED☐ REJECTED

BY

D.F. Pease

DATE

9/11/06

CONCURRED BY

B. J. Mc...

DATE

11/1/71

BLANKET APPROVAL GRANTED FOR SUBSEQUENT CHANGES WHICH ARE SAME AS DESCRIBED ABOVE

☐ YES☒ NO

SAMPLE OF CHANGE COMPONENT REQUIRED

☐ YES☒ NO

REASON FOR REJECTION OR QUALIFYING CONDITIONS OF ACCEPTANCE

* This approval is granted upon the understanding that it is advisory in nature and in no manner changes the Seller's original responsibility for insuring that all characteristics designated in the applicable engineering specifications and/or inherent in samples as originally tested and approved, are maintained. Seller accepts full responsibility for the changes or types of changes listed above, and should such changes result in less satisfactory performance than experienced with the originally approved item, Seller will fully reimburse the Buyer for all expenses incurred to correct the deficiency.

TI-NHTSA 001820

TEXAS INSTRUMENTS



Ford Motor Company
17000 Oakwood Blvd.
P.O. Box 1586-D-2015
Dearborn, Michigan 48121

December 20, 1991

Attn: Mr. Mark Scholler

Subj: Supplemental ISR Submission
Ford Part Number F2VC-9F924-AB
Pass Car Series

Ref: Initial ISR Submission

Dear Mark,

Enclosed, please find our supplemental sample warrant for NGSC deactivation switch, Ford part number F2VC-9F924-AB. The warrant includes reference to the alert no. A10166193 providing conditional approval of switches utilizing manually crimped parts.

A copy of the supplemental ISR testing addressing diaphragm life during impulse testing. PIST information is also enclosed. Finally, (8) samples of bases with the corrected 1.88 - 2.04 base cavity mold dimension are enclosed.

Please let us know if you have any questions or if I may be of any further assistance.

Regards,


Jim Watt
QRA Engineer
Precision Controls Department
Control Products Division

cc: Dave Czarn, MS 12-29; Charlie Douglas, MS 12-33
Andy McGuirk, MS 12-27
Steve Majors, TI Farmington Hills, Michigan

enc: ISR Supplement, ISR Warrant, Sample corrected bases

INITIAL SAMPLE WARRANT

No. 112384

PART INFORMATION

Part Name NEXT GENERATION SPEED CONTROL Part Number F2VC-9F924-ABControl Item ☐ Yes ☐ No Engineering Change Level _____ Date _____Engineering Change Authorization BRUCE PEASE Date _____Shown on Drawing No. F2VC-9F924-AB Part Weight 062 lb

Reason for Initial Sample:

- ☐ Initial Submission ☐ Change in Optional Construction or Material ☐ Process Change
☐ Engineering Change(s) ☐ Additional, Replacement, or Refurbished Tooling ☐ Change in Subcontractor or Source
☐ Tooling Transfer ☒ Correction of Discrepancy (Resubmission No. _____) ☐ Parts Produced at Additional Location
☐ Other - Please Specify SEE BELOW

SUPPLIER INFORMATION (Manufacturing Location)

Supplier Name TEXAS INSTRUMENTS Street Address 34 FOREST STREETCity ATTLEBORO State MA Postal Code 02703 Country USASupplier Mfg. Location Code - DUNS T097K Customer Assigned FORD MOTOR CO - EED

CUSTOMER INFORMATION

Customer Name FORD MOTOR CO - EED Buyer FRED HENDERSHOT Buyer Code 165

Purchase Order Number _____ Sample Acceptance Level _____

Application NEXT GENERATION SPEED CONTROL

RESULTS

The results for dimensional measurements ☐, material tests ☐, and functional (ET) tests ☐ meet all drawing and specification requirements ☐ Yes ☐ No

Submission Checklist

- | | | |
|--|--|---|
| ☐ Checksheet Print | ☐ Material Test Results | ☐ Control Plan |
| ☐ Auxiliary Drawings/Sketches | ☐ Certifications | ☐ Process Capability Results |
| ☐ Correct Number of Samples | ☒ Functional (ET) Test Results | ☐ Process Flow Diagram |
| ☐ Dimensional Results | ☐ Product Engineering Approval | ☐ Gage (Measurement) Studies |

Supporting data for all requirements are available upon request.

COMMENTS:

ISR SUPPLEMENT WITH ADDITIONAL TESTING TO CLOSE OUT ALERT NO. A10166193;ALSO, CORRECTED CASE MOLD DIMENSIONS.

DECLARATION

I affirm that the samples represented by this warrant are representative of our parts and have been made to the applicable customer drawings and specifications from specified materials, on regular production tooling with no operations other than the regular production process.

Authorized Signature Jim Watt Date 12/20/91Name JIM WATT Title QA ENGINEER Phone No. 508-699-1719APPROVAL (when required by customer procedure) ☐ Approved ☐ Rejected

Signature _____ Date _____

Form 2920

TI-NHTSA 001830

CORRECTED MOLD DIMENSIONS

F2VC-9F924-AB

CAVITY #	SPEC. 2.06 - 1.95
A1	1.92
A	1.94
B1	1.985
B	1.99
C1	1.985
C	2.00
D1	1.99
D	1.975

cc = G. H. R.

TEXAS INSTRUMENTS



Ford Motor Company
17000 Oakwood Blvd.
P.O. Box 1586-D-2015
Dearborn, Michigan 48121

December 04, 1991

Attn: Mr. Mark Scholler

Subj: Initial ISR Submission
Ford Part Number F2VC-9F924-AB
Pass Car Series

Ref: My December 04, 1991 Telephone Call

Dear Mark,

Enclosed, please find our subsequent initial sample warrant for NGSC deactivation switch, Ford part number F2VC-9F924-AB. The warrant includes reference to the alert no. A10166193 providing conditional approval of switches utilizing manually crimped parts.

A copy of the referenced alert is also enclosed for your information.

Please let me know if you have any questions or if I may be of any further assistance.

Regards,


Joe Watt
SRA Engineer
Precision Controls Department
Control Products Division

cc: Dave Czarn, MS 12-29; Charlie Douglas, MS 12-33
Andy McQuirk, MS 12-27
Steve Majors, TI Farmington Hills, Michigan

encl: Alert no. A10166193
Initial Sample Warrant

INITIAL SAMPLE WARRANT

No 112384

PART INFORMATION

Part Name NEXT GENERATION SPEED CONTROL Part Number F2VC-9F924-AB
 Control Item ☐ Yes ☐ No Engineering Change Level _____ Date _____
 Engineering Change Authorization Steve Pease Date _____
 Shown on Drawing No. F2VC-9F924-AB Part Weight .062 lb

Reason for Initial Sample:

- ☐ Initial Submission ☐ Change in Optional Construction or Material ☐ Process Change
☐ Engineering Change(s) ☐ Additional, Replacement, or Refurbished Testing ☐ Change in Subcontractor or Source
☐ Tooling Transfer ☐ Correction of Discrepancy (Resubmission No. _____) ☐ Parts Produced at Additional Location
☐ Other - Please Specify _____

SUPPLIER INFORMATION (Manufacturing Location)

Supplier Name Texas Instruments Inc. Street Address 34 Forest Street
 City Attleboro State MA Postal Code 02703 Country USA
 Supplier Mfg. Location Code - DUNS 1097E Customer Assigned Ford Motor Co. EED

CUSTOMER INFORMATION

Customer Name Ford Motor Co. EED Buyer Fred Sandershot Buyer Code 165
 Purchase Order Number _____ Sample Acceptance Level _____
 Application Next Generation Speed Control

RESULTS

The results for dimensional measurements ☐, material tests ☐, and functional (ES) tests ☐ meet all drawing and specification requirements ☐ Yes ☐ No

Submission Checklist

- ☒ Checked Print ☒ Material Test Results ☐ Control Plan
☐ Auxiliary Drawings/Sketches ☒ Certifications ☐ Process Capability Results
☒ Correct Number of Samples ☒ Functional (ES) Test Results ☐ Process Flow Diagram
☒ Dimensional Results ☐ Product Engineering Approval ☐ Gage Measurement Studies

Supporting data for all requirements are available upon request.

COMMENTS:

Condition of parts submitted manually crimped parts as detailed in
STATE-MA-91000000 (attached) Initial ISM Submitted 9/26/91

DECLARATION

I affirm that the samples represented by this warrant are representative of our parts and have been made to the applicable customer drawings and specifications from specified materials, on regular production tooling with no operations other than the regular production process.

Authorized Signature Jim Watt Date 12/4/91
 Print Name Jim Watt Title QA Engineer Phone No. 508-699-1719

APPROVAL (when required by customer procedure) ☐ Approved ☐ Rejected

Signature _____ Date _____

Quality Control **292c**

TI-NHTSA 001833

ALERT DETAIL

PRINT DATE/TIME: 91/10/11 09:39
PAGE:

CORRECTION
FR: J. SINK
TO: JAGM PASSION ALERT

ORIGIN ACTIVITY: NCOB CHASSIS PRO (LHCB)
ORIGINATOR: PEASE, S. F.
CPSC: 000001

TYPE: (U) USE PPM
DATE: 91/10/02
PHONE: 32-37933
NOTICE NO:

ALERT NUMBER
A10166193

STATUS: A
LOCATION: RM 3001, OLDGUY, D
RESOLVING NOTICE:

ALERT DESC:

PERMIT TEXAS INSTRUMENTS TO SHIP SPEED CONTROL REDUNDANT
DEACTIVATION SWITCH, PZVC-PP924-AB, WITH EXCEPTION TO THE
INTENDED MANUFACTURING/ASSEMBLY PROCESS CONSISTING OF
1992 LINCOLN TOWN CAR, CROWN VICTORIA, GRAND
MARQUIS WITH NEW GENERATION SPEED CONTROL,
CVFA CUFM CUVB
NA17

PRODUCTS AFFECTED:

MODEL CODES:
PLANTS AFFECTED:
NFO CONCERN CTRL:
PROGRAM:
MTT:
EST INCRN VAN COST:
EST INCRN VMS COST:
UNIT MEASURE:
SUPP CODE:

-0.92

MODEL YEAR: 92

TIME: 900
EST INCRN TOOL COST:
EST INCRN PAC COST:
APPEARANCE:

END CONCERN CTRL:
EFFECTIVE IN:
UNIQUE CODE: 000
0
0

INVALID:
OUT:
DISP: U
EST INCRN LDR COST: 0.00
UT EFFECT: 0.0000

***** AFFECTED PARTS *****

AFF PART NO:
CPSC:
ACT:

000405
INTER:

AFF PART DESC:
NOTICE:
SUPPLY/LOCAL:
SUPPLIER:

AVAIL:

REL IND: N
FUNC RECD:

***** FURTHER DESCRIPTION/ALERT RESOLUTION/REASON FOR REJECTION ETC. *****

USERID: BPP2400
ALERT DESC: ACTIVITY: NCOB
USING A MANUALLY LOADING CRIMPING MACHINE VERSUS THE
AUTOMATIC IN LINE LOADED CRIMPER. THE AUTOMATIC CRIMPER HAS
BEEN DETERMINED TO HAVE A YET TO BE DEFINED DEFICIENCY THAT
RESULTS IN PART FAILURE TO MEET THE REQUIRED NUMBER OF CYCLES
IN THE IMPULSE TEST. THE SUPPLIER IS GIVEN A 90 DAY PERIOD
TO RESOLVE THE ISSUE. THE MANUALLY CRIMPED PARTS PASS THE
E8 TEST. THIS DEVIATION PERMITS INCORPORATION OF THE .AB
LEVEL SWITCH AND DELETION OF THE INTERIN .00 SWITCH FOR A
COST REDUCTION OF 0.92. THE .AB SWITCH IS PIA TO E80 ITH

ENTRY DATE: 91/10/02

USERID: BPP2400
ALERT DESC: ACTIVITY: NCOB
PROPORTIONING VALVES PZAC-20091-0A, PZVC-20091-0C, AND
JUNCTION BLOCK PZAC-20320-CH.

ENTRY DATE: 91/10/03

USERID: LA20406
ALERT DESC: ACTIVITY: NCOB
OK. SUPVR. APPROVAL REQ'D. IF PZVBS IS AFFECTED. LA2

ENTRY DATE: 91/10/04

USERID: 0JMS146
ALERT DESC: ACTIVITY: NCOB

ENTRY DATE: 91/10/04

TI-NHTSA 001034

TEXAS INSTRUMENTS



Ford Motor Company
17000 Oakwood Blvd.
P.O. Box 1586-D-2015
Dearborn, Michigan 48121

September 27, 1991

Attn: Mr. Mark Scholler

Subj: Initial ISR Submission
Ford Part Number F2VC-9F924-AB
Pass Car Series

Ref: My September 20, 1991 Telephone Call

Dear Mark,

Enclosed, please find our initial ISR submission for the NGSC deactivation switch, Ford part number F2VC-9F924-AB. The submission includes complete product validation testing which is enclosed with the documentation.

We noted one discrepancy during the dimensional analysis. Dimension 1.88 - 2.86 was inadvertently transferred in error from the envelope drawing to the component drawing, resulting in the one out of dimension measurement (2.677). Sample bases with the corrected dimension will be forwarded to you within three weeks.

We noted that the pass car print does not indicate any significant characteristics, and therefore, no PIST/PIPC data is required. However, we intend to provide PIST/PIPC data on actuation, release, and thread specifications similar to what was provided on the F2VC-9F924-AB right valve ISR submission, and forward the data to you.

Please let us know if you have any questions or if I may be of any further assistance.

Regards,


Jim Matt
QRA Engineer
Precision Controls Department
Control Products Division

cc: Dave Czarn, MS 12-29; Charles Douglas, MS 12-33
Andy McQuirk, MS 12-27
Joe Schuck, TI Farmington Hills, Michigan

encl: ISR submission



INITIAL SAMPLE WARRANT

No. 112384

PART INFORMATION

Part Name NEXT GENERATION SPEED CONTROL DEACTIVATION Part Number FZVC-9F924-AB
PRESSURE SWITCHControl Item ☐ Yes ☐ No Engineering Change Level _____ Date _____Engineering Change Authorization Bruce Pease Date _____Shown on Drawing No. FZVC-9F924-AB Part Weight .062 lb

Reason for Initial Sample:

- | | | |
|--|---|--|
| ☒ Initial Submission | ☐ Change in Optional Construction or Material | ☐ Process Change |
| ☐ Engineering Change(s) | ☐ Additional, Replacement, or Refurbished Testing | ☐ Change in Subcontractor or Source |
| ☐ Tooling Transfer | ☐ Correction of Discrepancy (Resubmission No. _____) | ☐ Parts Produced at Additional Location |
| ☐ Other - Please Specify _____ | | |

SUPPLIER INFORMATION (Manufacturing Location)

Supplier Name TEXAS INSTRUMENTS Street Address 34 Forest St.City Attleboro State Mass. Postal Code 02703 Country USASupplier Mfg. Location Code - DUNS T097K Customer Assigned Ford Motor Co. EED

CUSTOMER INFORMATION

Customer Name FORD MOTOR CO. EED Buyer Fred Hendershot Buyer Code 165

Purchase Order Number _____ Sample Acceptance Level _____

Application NEXT GENERATION SPEED CONTROL

RESULTS

The results for dimensional measurements ☐, material tests ☐, and functional (ES) tests ☐ meet all drawing and specification requirements ☐ Yes ☐ No

Submission Checklist

- | | | |
|---|--|--|
| ☒ Checked Print | ☒ Material Test Results | ☒ Control Plan |
| ☐ Auxiliary Drawings/Sketches | ☒ Certifications | ☒ Process Capability Results |
| ☒ Correct Number of Samples | ☒ Functional (ES) Test Results | ☒ Process Flow Diagram |
| ☒ Dimensional Results | ☒ Product Engineering Approval | ☒ Gage (Measurement) Studies |

Supporting data for all requirements are available upon request.

COMMENTS:

DECLARATION

I affirm that the samples represented by this warrant are representative of our parts and have been made to the applicable customer drawings and specifications from special materials, on regular production tooling with no operations other than the regular production process.

Authorized Signature *Jim Watt* Date 9/26/91Print Name JIM WATT Title QRA Eng. Phone No. 508-699-1719APPROVAL (when required by customer procedure) ☐ Approved ☐ Rejected

Signature _____ Date _____

Form 292C

TI-NHTSA 001636

No. 112384

Page 1 of 1

SUPPLIER Texas Instruments, Attleboro, Ma.		LOCATION T097K		Part number F2VC-9F924-AB	
EQUIP CODE Fred Hendershot 165		FROM COMMENTS ON: ESD		NO. OF SAMPLES 6	
REASON FOR SAMPLED NEW PART ☐ CHANGED PART ☐ NEW LOCATION ☐ NEW TOOLS ☐ MULTIPLE QUANTITY ☐		PART NAME Next Generation Speed Control Deactivation Pressure Switch MFG DATE 4/17/91 MODEL YEAR AND PRODUCT LINE AUTHORIZED SIGNATURE NO N/A			
SAMPLE MADE ON PRODUCTION SET-UP AND TOOLS YES ☐ NO ☐		REWORKED, HAND ON TOOL ROOM WORK REQUIRED YES ☐ NO ☐		WE HEREBY CERTIFY THE INFORMATION ABOVE IS TRUE AND CORRECT AND THAT OUR SAMPLES MEET FORD MOTOR COMPANY SPECIFICATIONS	
SAMPLES MADE TO MFG DATED 4/17/91		DATE INSPECTED 9/20/91		MADE BY OR AUTHORIZED SIGNATURE ORA Eng. DATE 9/26/91	

[illegible]

U.S. GOVERNMENT PRINTING OFFICE: 1964 O - 354-101											
DISPOSITION	SERIAL NO.	APPROVED	REJECTED	NOT RECD.	INSPECTION AND TESTS INSTRUCTIONS APPROVED	YES ☐	NO ☐	SPECIAL SALES APPROVED	YES ☐	NO ☐	NOT RECD. ☐
DEVELOPMENTAL BY DATE	XXXX				INITIAL SAMPLE APPROVAL MUST BE MADE IMMEDIATELY BY APPROVAL OF FIRST PRODUCTION SAMPLE	YES ☐	NO ☐	CONTROL PLAN APPROVED	YES ☐	NO ☐	NOT RECD. ☐
INTERNAL TEST 378a FORM					APPROVED BY SUTURE	YES ☐	NOT RECD. ☐	APPROVED BY FORM (Subsidiary)	YES ☐	NO ☐	NOT RECD. ☐
ES TEST 844 FORM					DESIGN	AUTHORIZED SIGNATURE			DATE		

Prod. Code: 292a

DESIGNATED CHARACTERISTIC CLASS
▽ - CONTROL ITEM

COPY 1

T1-NHTSA 001837



HIGHLIGHTS
Stephen B. Offler
Week Ending 91-04-12



VACATION: Steve, Monday 91-04-15
Jeff, Friday 91-04-19

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: The audible noise problem from switch snap on WIN35 was experienced by George Randall, alerting him to a potential problem on his vehicles (VAN35 van, F-series trucks). He has discovered a couple of related issues: a "feel" in the brake pedal, and a audible resonance from the brake booster diaphragm, which are occurring simultaneously with our switch's actuation. I have had a couple of conversations with George, and at present we're leaning towards an incipient disc to address these issues. George has asked us for anything we can come up with (i.e. characteristics not necessarily within his spec.) so he can do some quickie testing. Jeff DiDomenico is presently working on an incipient disc, and after several iterations he is making very good progress. We are, of course, shooting for a disc that will yield a device within the truck spec. When we have a disc (mid-next week at the present rate) we plan characterizations and life-testing before shipping anything to George.

We plan to ship 100 samples of 77PSL2-3 (Truck) today. These use prototype switches from the AMI calibration iteration, which were Impulse, Powered Impulse, and Thermal Cycle tested to verify the functionality of this kluged design. Jeff has built sensors using the Elco CNC lathe hexports built to the original J512 spec. Production aluminum crimp rings and the production crimp equipment will be used. Final testing must be done in the lab; 77PS switches are too short to fit the production 57 tester.

We have received requests for engineering samples from Weatherhead and Kelsey-Hayes for the Ford-required verification of the modified J512 seal. We planned to get all three Tier-1's requirements before sending hexport jobs to the Model Shop, however Pitt is dragging their feet. When they finally give us their needs, they will be charged a higher piece-price.

Regarding the SREA's to relax terminal position from 0.30-0.70 to 0.25-0.75, George has signed off but Bruce's supervisor (a new individual, not Frank Janosi)

Also, along with the SREA's, Bruce has asked for updated prints. The ECN for these has been filed.

PRODUCTION ISSUES: Elco's latest submission of 36900-1 hexports has been rejected for threads. We met with Mark Godbout in R.I. who demonstrated that the "go" gage required greater than the spec. of 4.5 in-lbs torque, but the tri-roll PD gages showed the parts near nominal. Careful inspection using an optical comparator with a thread template showed the initial threads to be damaged. With Stan Homol's input, we have determined that these threads were most likely damaged during planing. It looks like the same re-rolling operation that has become necessary on other 52/57 hexports will be needed here.

I have completed a set of tables for use with the TDR chamfer gages. Since the calculation of chamfer diameter and angle is very sensitive to gage ball diameter, separate tables were created for each anticipated ball diameter. For a given set of gage ball sizes, the tables

HIGHLIGHTS 91-04-12

Page 2

tabulate the actual readings obtained from the gage for the larger and smaller ball, and provide a calculated diameter and angle. A set of tables for each gage has been reproduced from the originals, which I plan to keep. The tables are extremely important; without them the \$3200/each gages are useless.

77PS DESIGN: During the above-mentioned 77PS prototype verification testing, we also piggybacked another test. During powered impulse cycles, we ran half the switches at the spec. of 2 Hz, and the other half at 0.2 Hz. This was an attempt to determine if the relatively high and unrealistic 2 Hz had a negative effect on the contacts. All devices passed; the fast-cycled contacts show marginally more wear but nothing significant. One device had a very high millivolt drop (131 mV versus about 10 for all others); we plan to analyze this further. Devices were purposely pinned at the extremes of the pin window, and the high mV device was one that was pinned high i.e. potential creep release and minimum contact gap.

ECN's are in the process of being placed for various 77PS components. We are going through the exercise of tweaking production tools and/or tweaking prints to match the parts. This includes 46515 (base), 27713 (rebump cup), 36900 (hexport), 36887 and 8 (terminals) and 36889 (spring). Of all of the above, the spring requires the most effort. I plan to submit the other 5 on an ECN, then spend significant time on the spring. We have learned from prototypes that the spring in reality does not deflect exactly as assumed when studied on paper. Effort must be spent to understand how well the prototype parts match the prototype prints, how well the prototype prints match the production prints, then determine how well the prototype assemblies match the production prints, then make tweaks as needed so the all the features of the production parts fall into the proper places.

7795 PROTOTYPE VERIFICATION TEST: TEST 134-07-12 JAN 4/15/91

NY 0 134-07-12

#	CASE	PIN	LOC.	ACT	REL	nT	I/POWER	INITIAL				nT	I/POWER	FINAL				nT	I/POWER	DELTA			
								CASE	ACT	REL	oT			CASE	ACT	REL	oT			CASE	DELTA	oT	DELTA
1	91.6	0.141	low	138	70	1.3	110.2 Hz	90.7	130	80	5.6	1	-1.1	1	2.3	1							
2	94	0.143	low	141	72	5.2	110.2 Hz	92.8	143	81	10.2	1	-1.2	1	5	1							
3	91.5	0.141	low	135	73	4.3	110.2 Hz	90.4	137	81	4.9	1	-1.1	1	4.6	1							
4	93	0.142	low	137	64	5.4	110.2 Hz	91.5	137	77	0.2	1	-1.5	1	2.0	1							
5	90.6	0.142	med	130	78	5.1	110.2 Hz	90.3	130	75	4.1	1	-0.3	1	-1	1							
6	92.9	0.144	med	140	77	5.0	110.2 Hz	92.6	140	80	0.5	1	-0.3	1	2.7	1							
7	92.8	0.144	med	134	72	6	110.2 Hz	93	130	78	7.4	1	0.2	1	1.4	1							
8	93.4	0.144	med	132	60	7.4	110.2 Hz	92.9	140	77	6.3	1	-0.5	1	-1.1	1							
9	92.5	0.145	high	135	71	4.4	110.2 Hz	91.9	139	76	0.4	1	-0.6	1	2	1							
10	91.7	0.145	high	139	73	7.4	110.2 Hz	91	136	77	0.0	1	-0.7	1	3.4	1							
11	92.9	0.146	high	136	80	6.8	110.2 Hz	93	142	80	11.0	1	0.1	1	5.1	1							
12	92.1	0.145	high	141	73	0.7	110.2 Hz	92.5	140	82	130.7	1	0.4	1	125	1							
				137.3	72.7	11		130.4	70.6			1-0.91	-0.10	12.06	1.70	1							
				2.7	5.9	11		3.0	2.2			10.456	0.409	11.07	1.90	1							

TI-NHTSA 001840



TO CAROL DUGLAS
FR. J. SCHUCK
I INFORMED M.H.
THAT THIS IS NOT A
SUPERFICIAL SWIRN

April 15, 1991

R
J.C.S.

Joe Schuck
Texas Instruments - Control Products Division
33737 West 12 Mile Road
Farmington Hills, MI 48331

Dear Joe,

During development testing of the 1993 FN-10 dual proportioning valve one TI switch failed (Ford P/N FZVC-9P924-BA). After 264 cycles of alternate immersion testing, the normally closed pressure switch will not open to pressure rise.

Alternate immersion testing consists of submerging the entire valve assembly in 5% saltwater at 100°F for 5 minutes, then pull valve from water and allow to dry above the tank for 55 minutes. To simulate vehicle condition, the production mating connector is used on the pressure switch to seal the switch. The switch was supplied 5.5 milliamperes at 12 volts D.C.. During the test, the millivolt drop across the switch contacts was measured. The millivolt drop was always low (approx. 0.6 mV.). We are currently setting up to hydraulically operate the valve during the alternate immersion test. The failed pressure switch is enclosed. Please determine root cause of failure and submit an 8-D to detail the problem. Your timely response is greatly appreciated.

Sincerely,

Jim Culpin

/s/

cc: G. Knight
G. Webb
G. Giles
B. Ponce (Ford)

TI-NHTSA 001841

Pages containing material that may be invasive must be witnessed by JES persons who understand the equipment and are not co-investors

Kelley-Hayes Returned Device

Test #142-15-01

Purpose: Determine the root cause of failure.

Nature of failure:

- After 264 cycles of alternate immersion testing, our switch which is normally closed would no longer open.
- Alternate immersion testing consists of submerging the entire valve assembly, including the mounted pressure switch, in 5% salt-water at 100°F for 5 min., then pulling the valve assembly from the water and allowing to dry above the tank for 55 min.
- The pressure switch is not ^{pressure} ~~manually~~ cycled during this test but millivolt drop is monitored and seemed to be normal even after failure.

Analysis:

Visual Inspection:

- Device is a 57054 S-3 (Date Code 0317, Ford P/N #206 98210). It is a post-cure device built with the first rebar cap and was part of sample order 40-95. The housing is an SAE 304 with zinc/yellow chromate plating. Crimp ring is steel, zinc/yellow chromate plating. Base is a gray "L" with centered polarity tab.
- The housing's sealing surface is clean as is are the threads except for the last one. The rest of the exposed areas of the housing, as well as the exposed

WORK OF: Jeffrey DiDomenico

DATE:

I witness this document and understand its contents.

I witness this document and understand its contents.

pages containing material that may be sensitive must be witnessed by two persons who understand the information and are not co-authors

15-01

areas of the cap and crimp ring are severely oxidized, as would be expected. The base is relatively clean. The connector cavity has just a hint of salt deposits in the corners. The terminals look to be in good shape and have what seems to be greenish contact grease left on them. The locking tab on one of the terminals seems to be discolored.

Characterization:

- The disc snaps but there is no continuity change between and release values for the disc when taken as well as millivolt drop with disc actuated and released.

Disc snap: No Drop

Act/Rel: Act/Rel

165/89 mV 325/46 mV

Activation value is a little high, compared to the measurements taken before we shipped the devices.

- Current leakage is excessive, too high to measure or source. Resistance between terminals and crimp ring measures only 40K Ω .

Disassembly:

- Salt penetrated the base assembly as pitted on the bottom of the cap. A great deal of corrosion formed around the transfer pin rendering it stuck. The hinge side of the movable terminal was also severely corroded and stuck. The contacts themselves still looked OK, which accounts for the low millivolt drop.

WORK OF:

Jeffrey D. Domina

DATE: 4/24/94

I witness this document and understand its contents.


I witness this document and understand its contents.

TI-NHTSA 001843

Pages containing material that may be inventive must be witnessed by two persons who understand the invention and are not related to the inventor.

142-15-01

The disc, converter, and washer have some salt on the
from where it pushed passed the transfer pin. The
hydraulic seal is not touched and the bottom of the
hexport is clean.



WORK OF:

Jeffrey D. Donnanis

DATE: 4/24/91

I witness this document and understand its contents.

I witness this document and understand its contents.

Pages containing material that may be sensitive must be witnessed by the person who understood the inspection and are not copy reprints.

Pr. 15-01





Conclusions: The most likely leak path, judging by the affected areas, is past the mating connector into the switch body. The fluid slowly ran down the terminals, particularly the movable terminal, and puddled on the cup and the hinge of the movable terminal, as well as around the transfer pin. The stuck hinge and T-pin account for the lack of continuity change. The good condition of the contacts account for the low resistance drop. A poor environmental seal in the mating connector — is ultimately responsible for the failure.

WORK OF: *Jeffrey D. Donnan*

DATE: 4/24/91

I witness this document and understand its contents.

I witness this document and understand its contents.



TI-NHTSA 001848



No. 112384

Page 122

TO BE COMPLETED BY SUPPLIER

SUPPLIER Texas Instruments, Attleboro, Ma.		LOCATION T097K		AGMT NUMBER F2VC-BF924-AB	
BUYER Fred Hendershot		NO OF SAMPLES 165		PRODUCT GROUP 15	
REASON FOR SAMPLE		PART NAME Next Generation Speed Control Deactivation Pressure Switch		MODEL YEAR AND PRODUCT LINE	
NEW PART ☒ CHANGED PART ☐ NEW LOCATION ☐ NEW TOOL ☐ MULTIPLE CAUSE ☐		B/P DATE 4/17/91		MODEL YEAR AND PRODUCT LINE	
		IN DISPOSITION Pending		N/A	
SAMPLE MADE ON DISSECTION SET-UP AND TOOLS		YES ☐ NO ☐		ADDITIONAL HAND ON TOOL ROOM WORK PERFORMED	
SAMPLE MADE TO B/P DATED 4/17/91		YES ☐ NO ☐		DATE SAMPLED 9/20/91	
		WE HEREBY CERTIFY THE DISSECTION RESULTS BELOW ARE CORRECT AND THAT OUR SAMPLE MEETS YOUR MOTOR COMPANY SPECIFICATIONS		DATE OF DISSECTION 9/26/91	
		SIGNATURE OF PERSONNEL <i>[Signature]</i>		TITLE QRA Eng.	

[illegible]

TO BE COMPLETED BY CONTRACTOR

TO BE COMPLETED BY SUBMITTER					DATE	
DISPOSITION	SERIAL NO.	APPROVED	REJECTED	NOT RECD	INSPECTION AND TESTING CERTIFICATIONS APPROVED YES ☐ NO ☐	SPECIAL GAMES APPROVED YES ☐ NO ☐
DISPOSITION BY DATED	XXXX				SPECIAL GAMES APPROVAL MUST BE GRANTED BY OFFICE OF FIRST PRODUCTION SUPERVISOR YES ☐ NO ☐	CONTINGENT PLAN APPROVED YES ☐ NO ☐
APPROVAL TEST FORM					APPROVED BY STYLING YES ☐ NOT NO ☐ RECD ☐	APPROVED BY TEST ENGINEERING YES ☐ NOT NO ☐ RECD ☐
SEE TEST S&T FORM				IN-CHARGE	AUTHORIZED SIGNATURE	

Prod. Code **292a**

* DESIGNATED CHARACTERISTIC CLASS
▽ - CONTROL ITEM

COST 1

TI-NHTSA 001847

TEXAS INSTRUMENTS



DIMENSIONAL ANALYSIS ON PART NUMBER

F37A-F9CA-0A

	BLUEPRINT SPEC	CAVITY B A2 ACTUAL	CAVITY B C2 ACTUAL	CAVITY B C4 ACTUAL	CAVITY B C6 ACTUAL	CAVITY B D6 ACTUAL	COMMENTS
21	9.25 - 9.66	9.55	9.57	9.56	9.50	9.58	
22	8.32 ±.04	9.22	9.14	9.14	9.21	9.18	
23	14.27 MAX	13.64	13.62	13.56	13.47	13.66	
24	57.17 MAX	55.60	55.60	55.55	55.58	55.52	
25	12.85-13.11	12.83	12.83	12.83	12.86	12.89	
26	11.62-12.17	11.79	11.84	11.89	11.91	11.91	
27	1.90-2.11R 2PL	1.80	2.02	1.82	1.80	1.80	MEAS. SIDE W/ 12"
28	20DEC - 20DEC (401) MEASURED IN SEPARATE SAGE - CABLE SECTION						
29	30.5 MAX	31.61	31.64	31.72	31.64	31.63	
40	14.02-14.53	14.291	14.221	14.225	14.222	14.221	
41	3.30 - 3.60	3.420	3.413	3.441	3.429	3.436	
42	7.22 - 7.37	7.299	7.291	7.300	7.302	7.300	
43	5.51 - 5.85	5.604	5.583	5.641	5.642	5.616	
44	(71.50DEC-7-20DEC) 72DEC 20MIN	72DEC 20MIN	72DEC 20MIN	72DEC 20MIN	72DEC 20MIN	72DEC 20MIN	
	(2 PL)	72DEC 20MIN	72DEC 20MIN	71DEC 20MIN	72DEC 20MIN	71DEC 20MIN	
45	1.42-1.63 2PL	1.595	1.572	1.616	1.581	1.541	
46	0.35 - 0.66	1.571	.557	1.545	.575	1.550	
	(4 PL)	1.582	.560	1.583	.553	1.542	

TEXAS INSTRUMENTS INCORPORATED - 31 FOREST STREET - AUSTIN, TEXAS 78701
512-476-3225 - TELE 512-708-7400 - CABLE TEXAS

TI-NHTSA 001549

TEXAS INSTRUMENTS



DIMENSIONAL ANALYSIS ON PART NUMBER

F37A-9F924-AR

	BLUEPRINT SPEC	CAVITY # 42 ACTUAL	CAVITY # 43 ACTUAL	CAVITY # 44 ACTUAL	CAVITY # 45 ACTUAL	CAVITY # 46 ACTUAL	COPPER'S
47	2.59 - 2.80	L 2.661	L 2.705	L 2.667	L 2.697	L 2.769	
	(2 PL)	R 2.702	R 2.696	R 2.705	R 2.721	R 2.624	
	0.2 x 4 D	L .02, .015	L .000 R .077	L .071 R .061	L .061 R .036	L .01, .015	
	2.465	L 2.464	L 2.450 L 2.465	L 2.390	L 2.369	L 2.364	L 2.462
48	0.95 - 0.96	.465	.456	.539	.530	.571	.492
	(4 PL)	.494	.528	.474	.505	.449	.514
	0.58 - 1.17	.995	.995	.999	.962	.968	.989
	(4 PL)	.963	.951	.996	.959	.975	.929
50	145DEG +/- 2DEG	144DEG 47MIN	144DEG 45MIN	144DEG 46MIN	144DEG 39MIN	145DEG 24MIN	145DEG 50MIN
	(4 PL)	144DEG 47MIN	144DEG 45MIN	144DEG 46MIN	144DEG 39MIN	145DEG 24MIN	145DEG 50MIN
		145DEG 13MIN	144DEG 37MIN	144DEG 11MIN	145DEG 12MIN	145DEG 54MIN	
		145DEG 04MIN	145DEG 20MIN	144DEG 44MIN	144DEG 23MIN	144DEG 20MIN	
51	8.30-8.72	2PL 8.342	8.450	8.352	8.429	8.364	8.499
		8.365	8.429	8.365	8.429	8.365	8.392
52	12.15-2.42	2PL 12.180	2.720	12.196	2.153	12.189	2.219
		12.161	2.170	12.149	2.194		
53	125DEG +/- 2DEG	124DEG 24MIN	124DEG 10MIN	124DEG 47MIN	124DEG 17MIN	125DEG 37MIN	
	(2 PL)	120DEG 32MIN	120DEG 41MIN	123DEG 50MIN	123DEG 04MIN	125DEG 29MIN	
54	COLOR: BLACK	OK	OK	OK	OK	OK	
55	13-19DEG 3PL	ON CROSS	SECTIONED	PART ON	PRINT		
	0.66 - 0.87	ON CROSS	SECTIONED	PART ON	PRINT		
57	0.10 - 0.31	.252	.278	.287	.251	.276	.269
		.287	.269	.276	.251	.257	
58	0.58 - 0.68	.625	.646	.644	.621	.648	.622
		.634	.622	.644	.626		

VIEW FROM FRONT OF PART NUMBER F37A-9F924-AR

TI-NHTSA 001850

TEXAS INSTRUMENTS



DIMENSIONAL ANALYSIS ON PART NUMBER

F2VC-9F924-40

NOTE: DIMENSION PRINT DENOTES CAVITY # 1A

	BUSHEPRINT SPEC	CAVITY # 2A ACTUAL	CAVITY # 3C ACTUAL	CAVITY # 4C ACTUAL	CAVITY # 5H ACTUAL	CAVITY # 6C ACTUAL	COMMENTS
1	11.92 - 11.93	11.90	11.69	11.69	11.70	11.69	
2	11.45 - 11.24	11.42	11.29	11.33	11.26	11.31	
3	19.84 - 19.49	19.62	19.64	19.64	19.60	19.66	
4	16.76 - 16.56	16.62	16.64	16.64	16.64	16.65	
5	2.35 - 2.34	2.91	2.91	2.91	2.91	2.90	
6	11.97 - 11.10	11.70	11.70	11.70	11.77	11.70	
7	2.79 - 2.79	2.84	2.85	2.84	2.85	2.86	2.85
8	8.73 - 8.72	8.49	8.56	8.57	8.51	8.55	8.56
9	10.09 - 10.04	OK	OK	OK	OK	OK	
10	2.15 - 2.05	2.695	2.685	2.680	2.705	2.695	TOOL TO BE CORRECTED

THE PARTS OF F2VC-9F924-40 AND LIGHT TRUCK (F134-9F24-4A) SWITCHES ARE PRODUCED OFF OF THE SAME PRODUCTION TOOLING.

THE F134-9F24-4A FULL DIMENSIONAL ANALYSIS FOLLOWS. DIMENSIONS # 1-10 LISTED ABOVE PERTAIN TO THE POLARITY KEY FEATURE WHICH IS DIFFERENT ON THE F2VC-9F924-40 SWITCH.

TEXAS INSTRUMENTS



DIMENSIONAL ANALYSIS ON PART NUMBER

F3TA-M924-AA

NOTE: BOLD PRINT DENOTES CAVITY # A1

SUBSCRIPT	CAVITY # A2	CAVITY # C3	CAVITY # C4	CAVITY # D5	CAVITY # D6	COMMENTS
SPEC	ACTUAL	ACTUAL	ACTUAL	ACTUAL	ACTUAL	
1	13.42-13.82	13.692	13.423	13.602	13.719	13.646
2	13.225 +/- .005	13.205	13.185	13.165	13.145	13.125
3	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
4	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
5	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
6	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
7	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
8	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
9	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
10	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
11	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
12	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
13	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722
14	13.82 +/- .005	13.802	13.782	13.762	13.742	13.722

TI-NHTBA 001852

**TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL**

TI COMMITMENT (DESIGN/DEVELOPMENT)

- IN 1987, FORD ENGINEERING APPROACHED TI AND REQUESTED US TO DEVELOP A LOW COST PRESSURE SWITCH FOR THE NEXT GENERATION SPEED CONTROL SYSTEM. THIS REQUEST WAS PLACED 5 YEARS IN ADVANCE OF PRODUCTION WITH FULL TI RESPONSE.
- IN SUPPORT OF THIS FORD REQUEST, TI DEPLOYED PRODUCT DESIGN ENGINEERING/TECHNICIAN TEAMS SPECIFIC TO FORD'S REQUEST AND THIS PROGRAM.
 - TI INVESTMENT IN DEVELOPMENT OF PRESSURE SWITCH SINCE 1987 HAS EXCEEDED \$1KK.
- TI HAS BEEN INVOLVED AS SOLE SUPPLIER IN DEVELOPING PRESSURE SWITCH WITH FORD ENGINEERING.
 - THROUGH EVOLUTION OF PRODUCT, TI HAS CONTINUALLY BEEN ABLE TO ADAPT AND DEMONSTRATE IT CAN MEET ALL FORD REQUIREMENTS.
- TI DESIGN ENGINEERING DEVELOPED CUSTOMIZED HEXPORT TO MEET FORD FUNCTIONAL/COST REQUIREMENTS.
 - SIGNIFICANT LEVEL OF EFFORT EXTENDED IN WORKING WITH SAE COMMITTEE.

17 APR 91 CD/DAA 050-0175

TI-MHTBA 001053

TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL

TI COMMITMENT (TOOLING)

- IN ORDER NOT TO JEOPARDIZE INTEGRITY OF PROGRAM TIMING, TI CONTINUED TOOLING DEVELOPMENT FOR SEVERAL MONTHS WITHOUT A FORMAL COMMITMENT FROM FORD.
- TI IS CONTINUING TO LOOK FOR ALTERNATIVES TO REDUCE TOTAL TOOLING BURDEN (TO BOTH FORD AND TI).
 - NEW TI TOOLING PROPOSAL REDUCES FORD BURDEN BY \$100K.
- CRUISE CONTROL PRESSURE SWITCH REPRESENTS STATE OF THE ART IN PRESSURE SWITCH ASSEMBLY TOOLING.
 - FIRST TRADITIONAL SNAP ACTION PRESSURE SWITCH TI WILL MANUFACTURE BY A COMPLETELY AUTOMATED PROCESS.
 - MATERIAL/LABOR AND OVERHEAD RATIO ROUGHLY 72/28 VS. ROUGHLY 55/45 FOR AVERAGE SNAP ACTION SWITCH.

17 APR 91 CB/DAA 050-0175

TI-NHTSA 001854

TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL

TI COMMITMENT (PRICING)

- TI HAS CONTINUED TO OPERATE WITHIN THE FRAMEWORK OF THE ORIGINAL PROGRAM PRICING GOALS AS SET FORTH BY FORD.
 - DELTA TO ORIGINAL PROGRAM PRICING GOAL A RESULT OF DESIGN/FUNCTION MODIFICATIONS REQUIRED BY FORD.
 - TI HAS BEEN RESPONSIVE IN OUTLINING IN DETAIL IMPACT OF EACH MODIFICATION TO ORIGINAL PRODUCT DESIGN/FUNCTION REQUIRED BY FORD.
- GOAL OF TI TO BE LOW PIECE PRICE, LOW TOTAL COST, HIGHEST QUALITY SUPPLIER.
 - TI FORMALLY AWARDED PROGRAM AFTER PRODUCT WAS PUT TO MARKET TEST BY FORD.

TI-NHTSA 001856

17 APR 91 CD/DAA 050-0175

TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL

SUMMARY

- SINCE BEING APPROACHED BY FORD ENGINEERING IN 1987, WE HAVE INVESTED AND EXECUTED EVERY DETAIL OF THIS PRESSURE SWITCH AND A SUCCESSFUL LAUNCH OF THE NEXT GENERATION SPEED CONTROL SYSTEM CAN BE EXPECTED.
- TI HAS WORKED DILIGENTLY TO ACHIEVE A PERFORMANCE LEVEL WORTHY OF A COMPANY GIVEN THE HIGHEST RATING BY FORD'S SWITCH COMMODITY TEAM.
- TI CONTINUES TO LOOK FOR CREATIVE OPPORTUNITIES TO REDUCE/MAINTAIN THE PRESENT COST STRUCTURE OF THIS PROGRAM.
- WE VIEW THAT OUR PERFORMANCE AND COMMITMENT WARRANTS LONG TERM STABILITY FOR TI AS THE SWITCH SUPPLIER, AND WE ARE SEEKING THIS OBJECTIVE FOR MY93 AND BEYOND.

TI-MHTSA 001098

17 APR 91 CD/DAA 050-0175

TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL

CONTRACT PROPOSAL

	-----MODEL YEAR-----			
	92	93	94	95
BASE PRICE	\$2.21	\$2.21	\$2.18*	\$2.22**

• BASE PRICING ASSUMES DESIGN CHANGES:

- \$.09 SAVINGS ASSOCIATED WITH USE OF J514 HEXPORT.

•• BASE PRICING ASSUMES DESIGN CHANGES:

- \$.01 SAVINGS ASSOCIATED WITH AUTHORIZATION TO ELIMINATE ENVIRONMENTAL SEAL.
- \$.01 SAVINGS ASSOCIATED WITH AUTHORIZATION TO ELIMINATE CHROME FINISH ON HEXPORT.

TI-NHT8A 001067

TEXAS INSTRUMENTS INCORPORATED
FORD MOTOR COMPANY
NEXT GENERATION SPEED CONTROL

CONTRACT PROPOSAL NOTES

- FOR MY93, TI WILL ABSORB ALL MATERIAL, LABOR, AND OVERHEAD COST INCREASES.
 - THIS IS SIGNIFICANT IN THAT WITH LABOR AND OVERHEAD ONLY MAKING UP 28% OF THE TOTAL COST, PRODUCTIVITY GAINS TO OFFSET INCREASED COSTS ARE NOT AVAILABLE.
- WITH PROPOSAL ACCEPTANCE BY FORD, TI WILL BE GIVEN RIGHT OF FIRST REFUSAL ON NEXT GENERATION SPEED CONTROL DEACTIVATION PRESSURE SWITCH FUNCTION.
 - IF MOUNTING LOCATION OF SWITCH IS MOVED PRIOR TO MY96, TI IS GIVEN FIRST OPPORTUNITY TO DESIGN/DEVELOP A PRESSURE SWITCH TO FIT NEW MOUNTING LOCATION.
- TI MY93 PRICE QUOTATION IS PREDICATED UPON FORD ACCEPTANCE OF TOTAL LONG TERM PACKAGE PROPOSAL.
- MY94 AND MY95 PRICING IS CONTINGENT UPON WPISOP 3200 INFLATION RATE BEING LESS THAN OR EQUAL TO 3% EACH YEAR.

TI-NHTSA 001856

UNITED ALUMINUM CORPORATION

100 UNITED DRIVE • NORTH HAVEN, CONNECTICUT 06473 • (203) 238-5801



9281

VALENTINE TOOL & STAMPING, INC.
171 WEST MAIN STREET
NORTON, MA 02766-0469
ATTN: DICK WHITNEY

DATE 4/18/91
P.O. # 13876
SHIPPED 4/19/91
UA ORDER # 161499

THIS IS TO CERTIFY THAT THE MATERIAL LISTED BELOW CONFORMS WITH THE CHEMICAL COMPOSITION LIMITS OF DQA-250/2F AND THE FOLLOWING ARE THE LIMITS:

AA 5052

CHEMICAL COMPOSITION

	MIN	MAX
SILICON		0.25
IRON		0.40
COPPER		0.1
MANGANESE		0.1
MAGNESIUM	2.2	2.8
CHROMIUM	0.15	0.35
ZINC		0.1
TITANIUM		
OTHER ELEMENTS (EACH)		0.05
OTHER ELEMENTS (TOTAL)		0.15
ALUMINUM		REMANDEA

MECHANICAL PROPERTIES

TENSILE STRENGTH	28.3 KSI
ELONGATION IN 2"	20%

.032

2.312

5052-0


UNITED ALUMINUM CORPORATION

TI-NHTSA 001859

74797

CRIMP RING

74797



NOTES:

1. PINCH OFF RADIUS ALLOWED.
2. .002 MAX. BURR ALLOWED.
3. PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.
4. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

CERTIFIED PRINT	
ENG. STD. E3898 REV. 2	
Date JUL 1 1991	
THIS DRAWING IS THE PROPERTY OF TEXAS INSTRUMENTS. IT IS TO BE USED FOR THE PURPOSES SPECIFIED IN THE ORDER. IT IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF TEXAS INSTRUMENTS.	

SUPERSEDES DWG. 74797 REV. A DATED 11-2-80

74797-1	ALUMINUM 5052	
PART NO.	MATERIAL	FINISH

REV. 2

BY CHAS. FLEMING 11-2-80
 CH. 1-30-91
 ENG. 1-30-91



TEXAS INSTRUMENTS
 ATTORNEY, BARRISTER, SOLICITOR



74797

TI-NHTSA 001880

SAMPLE ORDER

ORDER NO: C091-21

REQUEST DATE: 04/19/91

CREDIT ACCOUNT: 5902

COST CENTER: 101

PRODUCT CODE: 060

CUSTOMER: FORD MOTOR COMPANY

CUSTOMER P.O. NO: N/A

T1 PART NO: 57PSL5-3

CUSTOMER PART NO: F2VC 9F924 ~~AA~~ BB

QUANTITY: 10

PRICE:

DELIVERY PROMISED: 4/24/91

160419ED

SPECIAL INSTRUCTIONS: PARTS SHOULD BE ~~TAGGED~~ WITH ACTUATION POINT

BILL TO:

SHIP TO:
TEXAS INSTRUMENTS
33737 M. 12 MILE ROAD
FARMINGTON HILLS, MI 48331
ATT'N: JOE SCHUCK

XX PRODUCTION SAMPLES

ENGINEERING DEVELOPMENT SAMPLES

CC: ENGINEERING: STEVE OFFILER

PRODUCTION CONTROL: MARIE CROSSLAND

SALES ENGINEER: JOE SCHUCK

TI-NHTSA 001861

HIGHLIGHTS
Stephen B. Offler
Week Ending 91-04-19

Handwritten signature/initials.



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: In response to the audible noise/feel issues at Ford, we are working on incipient snap discs to produce "quieter" sensors. Jeff DiDomenico has gone through several developmental iterations with .0122" 301V stainless, and has reached a point where it is clear that a thinner material is indicated. We will continue iterations with .010" material. The best lot to date was built up into sensors, shooting for the LT actuation of 200-300 psi, using standard amplification ratio parts (27218 cup). We discovered that pin throw is severely limited, measuring about half that of a standard sensor (.010" versus .020"). The "snap" range of the sensor has a significant slope, at about 6 psi per mil. Four of these sensors were run to 500K on production cycling equipment with no problems. At George Randall's urgent request, we shipped him two devices built with these sensors. He wants to have these at his immediate disposal in case Nehru Modi (a much-feared manager at LT) becomes involved.

Bruce Pease has requested and received his latest print revision, showing the new terminal position tolerance of $\pm 0.25\text{mm}$, up from ± 0.20 . Also, Bruce and George are comparing notes on the WIN88 noise/feel issue, and Bruce has asked for a couple quiet devices like the ones we sent George. Bruce does not indicate any rush is needed. More disc development will be required, since using the low amplification ratio cup (27713) will limit pin throw to an even greater degree compared with the above.

We are pulling together the hydraulic testing requirements for Kelsey-Hayes and for Dana-Weatherhead, and plan to submit a model shop job to create hexports to specific J512 dimensions. Pits has promised to forward their requirements also, but after repeated contact we still do not have any information from them.

PRODUCTION ISSUES: It has been determined that, for the present, Elco will be re-rolling the threads on 36900-1. To avoid the removal of chromate during wash after re-roll, we will be supplying Elco with vanishing oil (which eliminates the need for the wash). We have not reached any final conclusion on this thread-damage issue. Elco is looking at their plating process to determine if less agitation can be used; a change to a harder material has also been suggested. The idea of doing an SPC-controlled thread-chasing operation on our assembly line is not being taken seriously.

Another potential hexport problem has surfaced. In a recent RPQ for a J512 with stubber, Elco's quote as usual listed several exceptions. The significant one relates to .285-.290 on the dog-point O.D. - they want to double this tolerance. The issue lies with the fact that this dimension also appears on 36900-1; however on this part they have not yet mentioned this exception. We immediately measured 20 parts for this dimension, expecting to find them incorrectly built to the doubled tolerance. Instead, all were found to be very near the max. of .290; fully half exceeded the spec. slightly. Visual inspection shows the outermost edge to be damaged in a fashion similar to the thread, with a rolled-over appearance, that also serves to increase the effective O.D. This will become an issue because the TDR chamber gages rely on this O.D. for alignment and a part that is too large will not fit the gage.

DESIGN ISSUES: Visual inspection of the 77PS connectors run under powered impulse test week shows two distinct conditions: 10 of 12 show very little wear and tear, while the other two look terrible, with globs of silver at the interface, a blackened appearance, and have

TI-NHTSA 001862

HIGHLIGHTS 91-04-19

Page 2

copper showing through the silver plated movable contact. These switches were taken from the kludged AMI calibration run, and were very inconsistent in terms of spring angles and contact gap. We are hypothesizing that these two bad switches had very low contact gap, therefore poor arc extinguishing, which explains the damage. This test can be re-run fairly quickly (25K cycles at 2 Hz, about 3.5 hours). Only switches with consistent geometry will be used, and contact gap will be controlled at high and low extremes by pinning.

While assembling prototypes recently, we did a quick characterization of pin-shift due to final crimp. Typically, to determine pin length, a sensor and switch are held together manually while various pin lengths are used; creep actuation indicates short pin and creep release indicates long pin. With the incipient sensors, no creep can be measured, so instead we recorded actuation values for a given pin length held manually, then compared these values after final assembly and crimp. A shift of 15-20 psi was observed, which roughly corresponds to about 3 mils using the given slope of 6 psi per mil. This information will be very useful in the future when choosing pin lengths.

TI-NHTBA 001863

46155-70 4.5 min
- Jilin gage
- Cold gage
- Rel. to. m. h.
- before Jilin
- TS?
- trace gage
- rolled 314 in
- the plating
- process?
- SH2
- NFPC
- NFPC
- NDES

-NSO MF= 276181 FR=CERN TO=PCQA SENT=04/22/91 12:34 PM
RS=101 ST=C DIV=0050 CC=00101 BY=CERN AT=04/22/91 12:34 PM

APRIL 22, 1991

TO: RUSTY STRUBLE RCS2 CC: TON CHARBONNEAU TC
NIKE DeMATTIA PCQA JOHN KOURTESIS NDES
CHARLIE DOUGLAS CPFC STEVE MAJOR NELS
DICK GARISPY HFPC ANDY McGUIRK PCQA
PAUL KOTCH PKI ED O'NEILL ELON
JOE LAZARE JNLB JOE SCHUCK NELS
STEVE OFFILER SBOL GARY SNYDER CPFC
NATT SELLERS PCNE MARTHA SULLIVAN CPFC
BILL SWEET PCNE RAY TOURANGEAU PCNE
JIM WATT PCQA TED BALLARD AFNE
TED BREDIKEN HFPC STAN BOWOL SH2
CLAIRE BALTHEASAR NFPC
BILL CONGDON NFPC
STEVE MCCOY NDES

FR: DAVE CLARK SARE

SJ: FORD CRUISE CONTROL PRESSURE SWITCH START-UP MEETING:
04/18/91 MEETING MINUTES

MEETING

THE NEXT MEETING IS SCHEDULED FOR:

DATE: 04/25 (THURSDAY)
TIME: 10:00 - 11:30 AM
PLACE: MARKETING CONFERENCE ROOM

PLEASE CALL ME IF YOU ARE NOT ABLE TO ATTEND

* - ITEMS THAT ARE NEW OR HAVE BEEN REVISED OR COMPLETED
SINCE PREVIOUS MEETING

57 L/T

Report:

- * QUALIFY J512 GAGES
- * SHIP GAGE/DOCUMENTATION TO ELCO
- * L/T PILOT RUN
(PUSHOUT DUE TO REPORT AVAILABILITY)
- * CLOSE W/ELCO RE: THE EXCEPTION THEY
NOTED ON THE DOG POINT DIA. ON THE
SHUTTER PRINT
- * RULING ON REPORT THREAD ISSUE
- * F/U ON ELCO ISSUES RELATED TO
THREAD DAMAGE
- * RECEIVE RE-ROLLED REPORTS
- * REVIEW/ADVISE ON POULSEN'S REPORT
QUOTES

ISR issues:

- * SUBMIT ISR FOLLOW-UP TO FORD BOA
(PUSHOUT DUE TO AREA DELAY) (4000)

WHO	WHEN	
SELLERS	04/18	ORIG.
	04/18	COMP.
SELLERS	04/23	
SELLERS/	01/24	ORIG.
GARISPY	04/19	REV.
KOTCH	04/25	
OFFILER/	04/12	ORIG.
SELLERS	04/15	COMP.
KOTCH	04/25	
KOTCH	05/02	
KOTCH	05/02	
WATT	04/04	ORIG.
	04/25	REV.

TI-NHTSA 001854

* DELIVER 238 PRODUCTION SWITCHES (PARTS NOT NEEDED BY FORD UNTIL MID-MAY)	SELLERS/	04/01	ORIG.
* UPDATE TEAM ON AUDIBLE NOISE ISSUE	BALTHASAR	05/17	REV.
* INCIPIENT SNAP DISC SPEC AND INFO.	SCHUCK	ONGOING	
TO DISC DEPT.	OFFILER	04/18	ORIG.
* INCIPIENT SNAP SWITCH SAMPLES	OFFILER	04/25	REV.
	OFFILER	04/30	ORIG.
		04/18	COMP.

57 P/C

* LETTER TO FORD TO CLOSE ON TERM POS'E	DOHATTIA	04/25	
* ISR SUPPLEMENT FOR SWITCHES W/BACKS	WATT	04/10	ORIG.
OFFSET POLARITY KEY BASES		05/02	REV.
(PUSHOUT DUE TO AREA DELAY)			
* MODIFY 57PS FMEA FOR PITTS	OFFILER	TBD	
* 238 SWITCHES TO PITTS	SELLERS	04/22	
* UPDATE PROD'N PLAN AS SHOWN BELOW,	STRUBLE	04/25	
REFLECTING THE REPORT DELAY			
* SHIP 21K L5-3'S	GARIEPY/	06/03	
	STRUBLE		

77PS

* DESIGN UPDATE	OFFILER	ONGOING	
* NFG/MECH UPDATE	SELLERS	ONGOING	
* REPORT ON TOKIO, P.S. RESPONSIBILITY	DOUGLAS	ONGOING	
* PROD. LINE SET-UP (NTE CARDS, ETC)	BALTHASAR	ONGOING	
* UPDATE SPC FILES/RUN CAPABILITY STUDIES	BALTHASAR	ONGOING	
* ESTABLISH OVERALL SCHEDULE OF	OFFILER	05/02	
DESIGN ENG. ACTIONS			
* COMPLETE DESIGN FMEA	OFFILER	04/18	ORIG.
		05/20	REV.
* COMPLETE PROCESS FMEA	SELLERS	07/01	
* REPEAT IMPULSE TEST AT 3 HS TO	OFFILER	04/25	
STUDY CONTACT WEAR (SEE DISCUSSION)			
* TEL CONTACT ANALYSES; SLOW VS.	OFFILER	03/02	
FAST CYCLE RATE			
* DETERMINE ACCEPTABLE CALIBRATION WINDOW	OFFILER/	03/14	ORIG.
BY DIMENSIONAL ANALYSIS	SELLERS	04/25	REV.
* VERIFICATION RUN FOR CALIBRATION WINDOW	OFFILER/	03/28	ORIG.
	SELLERS	05/02	REV.
* F/D CHARACTERISATION OF SPRING ARMS	OFFILER	04/18	ORIG.
		04/25	REV.
* GAGING TECHNIQUE FOR IN-PROCESS F/D	SELLERS	04/25	
CHARACTERISATION OF SPRING ARMS			
* QUOTE J512 W/SHUBBER	KOTCH	04/04	ORIG.
		04/18	REV.
		04/20	COMP.
* VISIT EASTERN AUTOMATION RE:	SELLERS/	04/25	
SPRING/TERMINAL ASM. MACHINE	MCCOSET		
* STAKE PROD'N PARTS ON PROD'N STAKER	SELLERS	05/02	ORIG.
AND MEASURE TERMINAL POSITION			
* 57 TO 77 CONVERSION: PHASE 1 TESTING	BONOL	05/10	ORIG.
(PUSHOUT DUE TO COMPONENT AVAILABILITY)		05/06	REV.
* IDENTIFY INSPECTION REQTS. FOR SOP	WATT	05/01	
* 77PS QAS (PRELIMINARY)	WATT	07/01	
* 77PS CHARACTERISTIC SHEETS	WATT	07/15	
* GAGE R&R STUDIES	WATT	07/15	

77PS QAS (FINAL) NATT 08/01
 SET UP SPC FILES/RUN CAPABILITY STUDIES BALTHAZAR 08/01

JOB'S:
 ASE

Production Components:

* UPDATE CUP PRINT	OFFILER	03/28	ORIG.
		05/09	REV.
. RESOLVE OPEN ISSUES ON NOV. TERM.	SELLERS/	02/28	ORIG.
	OFFILER	05/09	REV.
. STATIONARY TERM.	SELLERS/	04/04	ORIG.
(KT BASSLER DELIV. DATE PUSH-OUT)	OFFILER	04/25	REV.
* INVESTIGATE INCONSISTENT SEND RADII	SELLERS	03/22	ORIG.
CALLOUT ON STAT. AND NOV. TERMINALS		04/19	REV.
* RESOLVE OPEN ISSUES ON BASE	OFFILER	04/18	ORIG.
		04/25	REV.
* UPDATE TERMINAL PRINTS/BASE PRINT	SELLERS	04/31	ORIG.
		04/28	REV.
	OFFILER	05/09	

Manufacturing Equipment:

* FINAL ASM MACHINE DEBUG COMPLETION	SELLERS/	06/03	
	KOURTESIS		
. BASE ASM MACHINE BUILD COMPLETION	SELLERS/	05/31	
	KOURTESIS		
* PRESSURE TESTER BUILD COMPLETION	SELLERS/	06/06	ORIG.
(SEE DISCUSSION)	KOURTESIS	06/06	REV.

DISCUSSION

57 L/T AND P/C

TWO SWITCHES WITH INCIPIENT SNAP DISCS WERE SENT TO GEORGE RANDALL WHO WILL BE PARTICIPATING IN SOME VEHICLE TESTING THIS WEEK. WE PLAN TO INVOLVE THE DISC DEPARTMENT IMMEDIATELY IN CONTINUING THE DEVELOPMENT OF THE INCIPIENT SNAP DISC.

PRODUCTION SWITCH BUILDS HAVE HIGHLIGHTED A PROBLEM WITH CRIMPING THE ALUMINUM RING. FOR CURRENT BUILDS, VANISHING OIL IS BEING USED.

77PS

AS HIGHLIGHTED LAST WEEK, A COMBINED IMPULSE/THERMAL CYCLE TEST (12 SWITCHES) WAS CONDUCTED AT 2 CYCLE RATES TO STUDY CONTACT HEATING/EROSION. WHILE ALL SWITCHES PASSED THE TEST, TWO OF THE 12 SETS OF CONTACTS SHOWED SIGNIFICANTLY MORE EROSION AND FILM BUILD-UP THAN THE REST. STEVE IS RE-RUNNING THE TEST WITH CONTACT GAPS SET AT HIGH AND LOW EXTREMES. THE PURPOSE IS TO DETERMINE IF THE HIGH EROSION RATE IS DUE TO EXTENDED ARCING WITH SMALL CONTACT GAPS.

3 SOFTWARE-RELATED CALIBRATOR PROBLEMS WILL BE REMEDIATED BY -MAY 03. AT THAT TIME, WE SHOULD HAVE ALL PRODUCTION COMPONENTS, SO WE CAN RUN A MEANINGFUL CALIBRATOR STUDY. ALSO, THE 57-TO-77 CONVERSION TESTING HAS BEEN PUSHED OUT SO ALL PRODUCTION COMPONENTS CAN BE USED.

TI-NHTSA 001886

THE ASSEMBLY MACHINES AND PRESSURE TESTER ARE PROCEEDING ON SCHEDULE. MECHANIZATION HAS REGAINED TWO WEEKS IN THE PRESSURE TESTER BUILD SCHEDULE, AVERTING A PUSHOUT TO 06/20.

MILESTONES	PLANNED	ACTUAL
57 L/T ISIR	11/21/90	11/21/90
57 L/T JOB 1	09/03/91	
57 P/C ISIR	01/15/91	01/15/91
57 P/C JOB 1	06/03/91	
77PS ISIR	08/01/91	
77PS SOP (TI)	09/01/91	

PRODUCTION PLAN BY MONTH (THOUSANDS) - WITHOUT OVERAGE

	P/C 57PSL5-3	L/T 57PSL5-2	P/C 77PSL2-1	L/T 77PSL2-3
APR	0	0	0	0
MAY	22	2	0	0
JUN	*10 (tentative)	0	0	0
JUL	10	2.3	0	0
AUG	10	2.3	2	0
SEP	10	*2.6	2	0
OCT	0	9.5	**9	2
NOV	0	6.5	25	2
DEC	0	0	25	**9.5

* = PLAN FOR AUGUST AND BEYOND IS TENTATIVE.

= JOB1 FOR 57PS VERSIONS

** = TENTATIVE JOB1 FOR 77PS VERSIONS

REGARDS,
DAVE CLEARS | 20-FORD

TI-NHTSA 001867

Paratech, Inc.

A DIVISION OF AMERON CORP.
SIGNATURE TECHNICAL CERAMICS

12345 MINNESOTA AVENUE • P.O. BOX 718 • PARAMOUNT, CALIFORNIA 90723
TELEPHONE (213) 633-2048 • FAX (213) 633-8807

MATERIAL CERTIFICATION

DATE: 4-22-91

TEXAS INSTRUMENTS, INC.

ORDER NO.: 505049981

PART NO : 74078-146 REV. NO.: F

QUANTITY THIS SHIPMENT: 75,000

SHIPMENT DATE: 4-22-91

PART DESCRIPTION: PIN

WE CERTIFY THAT THE MATERIAL USED TO PRODUCE THE PRODUCT IN THIS
SHIPMENT, NAMELY PIN / STEATITE - 13, CONFORMS TO T.I.
DRAWING AND T.I. PURCHASE ORDER REQUIREMENTS.


PRODUCTION MANAGER

TI-NHTSA 001868

TRANSFER PIN

74078

74078

R.015 MAX.
(BOTH ENDS)

L ±.0005

.156
.150

PARTS MUST BE FREE OF CHIP
MARKS AND PROTRUSIONS. ENDS
MUST BE PERPENDICULAR TO
SIDES TO WITHIN 2 DEGREES.

CONFIDENTIAL

"L" LENGTH IS DETERMINED BY THE SUFFIX OF THE PART NUMBER IN THOUSANDTHS
OF AN INCH. I.E.:

PART NO.	"L"
74078-155	.155
74078-210	.210

VENDOR WILL BE PREPARED TO FURNISH PINS .130 - .250 LONG.

NOTES:

1. FINISHED PARTS TO BE SHIPPED, ISSUED AND STORED IN SEALED PLASTIC BAGS.
SEALED PLASTIC BAGS TO CONTAIN 20,000 PINS (OR LESS FOR PARTIAL BAGS).
BAGS MUST BE CLEARLY LABELED WITH THE PART NO. AND THE QUANTITY OF PARTS
IDENTIFIED ON THE OUTSIDE OF EACH BAG.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

MATERIAL: L-3 GRADE STEATITE (DC-168) OR
L-3 GRADE STEATITE (DC-144E)

CURE PER SPEC.----- 50502-2

SHRINKAGE SPEC.----- 50501-1

CERTIFIED PRINT	
ENR. STD. E9898 REL E	
JUL 1 1991	
THESE PINS ARE THE PROPERTY OF TEXAS INSTRUMENTS, INC. AND ARE TO BE USED ONLY FOR THE PURPOSES SPECIFIED IN THE DRAWING. ANY OTHER USE IS PROHIBITED. THE USER ASSUMES ALL LIABILITY FOR ANY DAMAGE TO THE PINS OR TO THE DRAWING.	

THIS DWG. SUPERSEDES 74078 REV. "E" DATED 8-4-86

DATE: 10-17-88	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 01915	KIDON CERTIFIED PRODUCTS DIVISION	REV. A	74078
THIS DRAWING IS THE PROPERTY OF TEXAS INSTRUMENTS, INC. AND IS TO BE USED ONLY FOR THE PURPOSES SPECIFIED IN THE DRAWING. ANY OTHER USE IS PROHIBITED. THE USER ASSUMES ALL LIABILITY FOR ANY DAMAGE TO THE PINS OR TO THE DRAWING.				

CODE IDENT NO. 82847

TI-NHTSA 00

Form 21605

TEST NO.

DEVICE	DATE REQUESTED	REQUESTED BY	REQUESTED COMPLETION DATE
S-PSL5-3	4-27-91		
PERFORMED BY	DATE STARTED	DATE COMPLETED	APPROVED BY
S-PSL5-3	4-27-91	4-27-91	
PROJECT TITLE:			

CUSTOMER:

PURPOSE OF TEST:

PAGE 6 OF 11

DISC 22.0/10.4

[illegible]

TI-NHTSA 001871



AMERICAN ELECTRO PRODUCTS INC.
1388 THOMASTON AVENUE
WATERBURY CT 06704
(203) 758-7081

01761
Certificate of Compliance

NO. 21047200
REL 1

MILFORD RIVET & NUT
837 BRIDGEPORT AVE

MILFORD CT 06440

DATE 04/24/91

YOUR ORDER NO 1 32704
SHIPPED VIA UNITED P. S.

This is to verify that parts and/or your material furnished against your purchase order number shown above have been manufactured in accordance with requirements and specification as required

PART NO	DESCRIPTION	QUANTITY
6234A	SILVER 9.001100-0.00200 NUT	222.222 2

Tests to substantiate this have been performed in our plant or have been performed by our suppliers and are available upon request from us or our suppliers.

Very truly yours

AMERICAN ELECTRO PRODUCTS INC

Signed by

Quinn Martin
Q.C. Inspector

TI-NHTSA 001872

BELGIAN METALS CORPORATION
452 HIPPERMAN AVENUE
YONKERS, N.Y. 10701

1st CERTIFICATE OF ANALYSIS AND COMPLIANCE

T. 32500

MILFORD RIVET & MACHINE CO.
817 BRIDGEPORT AVENUE
MILFORD, CT. 06460

BMC # 8267
F.O.I. 1200
OUR INVOICE: 3553
DELIVERY DATE: 01/03/69

1. 0870

M.E.A. %

2. 102

ELONGATION:

3.

ROCKWELL HARDNESS:

4. 11

GRAIN SIZE (ASTM FINAL ANNEAL):

TENSILE STRENGTH: 48.63-49.03 KSI **ELECTRICAL CONDUCTIVITY: %**

TEMPER DESIGNATION: H31.5

CHEMICAL ANALYSIS:

CU	ZN	FE	PC	BN
99.98				
AL	MN	NI	SI	P

R:

CERTIFY THAT THIS SHIPMENT CONFORMS TO THE CHEMICAL AND PHYSICAL
VALUES SHOWN ABOVE, AND IS IN COMPLIANCE WITH THE SPECIFICATIONS
OF THIS ORDER




BELGIAN METALS CORPORATION

TI-NHTSA 001873

74408

MOVABLE CONTACT

74408



NOTES:

1. PARTS MUST BE STORED IN PLASTIC BAGS THROUGH ALL SHIPPING AND HANDLING PROCESSES.
2. MATERIAL & PLATING THICKNESS CERTIFICATION REQUIRED WITH EACH SHIPMENT.
3. DIMENSIONS APPLY AFTER PLATING.
4. MEASURE PLATING THICKNESS BY MOUNTING & CROSS-SECTIONING PART.
5. PLATING THICKNESS APPLIES AT THE INDICATED LOCATION ONLY.
6. TOOL VENT MARK ON .040-.050 R ALLOWED. DIMENSIONS MAY NOT EXCEED .001 IN HEIGHT AND .003 IN WIDTH. THERE MUST BE NO VOID IN PLATING IN THIS AREA. .032-.035 DIMENSION MAY MEASURE .036 OVER THIS MARK.
7. PLATING THICKNESS OF .0007 MINIMUM ALLOWED ABOVE TOOL VENT MARK ONLY. ADJACENT AREAS MUST MEET "FINISH" REQUIREMENTS.

56FSL4-1

1ST ISSUE
2ND ISSUE
3RD ISSUE
4TH ISSUE
5TH ISSUE
6TH ISSUE
7TH ISSUE
8TH ISSUE
9TH ISSUE
10TH ISSUE
11TH ISSUE
12TH ISSUE
13TH ISSUE
14TH ISSUE
15TH ISSUE
16TH ISSUE
17TH ISSUE
18TH ISSUE
19TH ISSUE
20TH ISSUE
21ST ISSUE
22ND ISSUE
23RD ISSUE
24TH ISSUE
25TH ISSUE
26TH ISSUE
27TH ISSUE
28TH ISSUE
29TH ISSUE
30TH ISSUE
31ST ISSUE
32ND ISSUE
33RD ISSUE
34TH ISSUE
35TH ISSUE
36TH ISSUE
37TH ISSUE
38TH ISSUE
39TH ISSUE
40TH ISSUE
41ST ISSUE
42ND ISSUE
43RD ISSUE
44TH ISSUE
45TH ISSUE
46TH ISSUE
47TH ISSUE
48TH ISSUE
49TH ISSUE
50TH ISSUE
51ST ISSUE
52ND ISSUE
53RD ISSUE
54TH ISSUE
55TH ISSUE
56TH ISSUE
57TH ISSUE
58TH ISSUE
59TH ISSUE
60TH ISSUE
61ST ISSUE
62ND ISSUE
63RD ISSUE
64TH ISSUE
65TH ISSUE
66TH ISSUE
67TH ISSUE
68TH ISSUE
69TH ISSUE
70TH ISSUE
71ST ISSUE
72ND ISSUE
73RD ISSUE
74TH ISSUE
75TH ISSUE
76TH ISSUE
77TH ISSUE
78TH ISSUE
79TH ISSUE
80TH ISSUE
81ST ISSUE
82ND ISSUE
83RD ISSUE
84TH ISSUE
85TH ISSUE
86TH ISSUE
87TH ISSUE
88TH ISSUE
89TH ISSUE
90TH ISSUE
91ST ISSUE
92ND ISSUE
93RD ISSUE
94TH ISSUE
95TH ISSUE
96TH ISSUE
97TH ISSUE
98TH ISSUE
99TH ISSUE
100TH ISSUE

74408-1	COPPER	SILVER PLT. .0011/.0024 THK (SEE NOTE 5)	.0605-.0625
PART NO.	MATERIAL	FINISH	DIA. A

BY T. Davis 1-6-83	TEXAS INSTRUMENTS INCORPORATED	KUDON	74408
CH. 1-13-83	ATTLEBORO, MASS., U.S.A.	CONTROL PRODUCTS DIVISION	
ENG. R. R. R. 1-13-83			

TI-NHTSA 001874

PRESSURE SWITCH DATA

Form 21605

TEST NO.

DEVICE 77P5L 2-1	DATE REQUESTED 4/27/79	REQUESTED BY Steve Goff	REQUESTED COMPL. DATE
PERFORMED BY Jeffrey P. Hennessey	DATE STARTED 4/27/79	DATE COMPLETED 5/8/79	APPROVED BY
PROJECT TITLE: Ford 714'92 1 location Spray Control Inactivate PS			

CUSTOMER:

PURPOSE OF TEST:

Following page

PROCEDURE:

Subtract .001 for each
of 1000 cycles

Device	Alt	Contact Gap	P. P. 75 pos. rel.	assembly	Act/Rel	M. d. 75	Cycle	A. I. / R. I.	P. P. 75	P. P. 75
141-15-01		Low	.091	1	136/71	11.1	1	136/71	19.2	.091
02			.092	1	136/75	11.8	1	136/75	19.3	.092
03			.093	1	137/74	12.8	1	137/74	19.8	.093
04			.092	1	141/79	12.5	1	141/79	25.8	.092
05			.091	1	140/72	15.1	1	140/72	16.3	.091
06			.092	1	142/74	10.6	1	142/74	18.3	.092
141-15-07		Normal	.096	1	135/94	13.9	1	135/94	19.7	.096
08			.096	1	137/78	13.3	1	137/78	15.8	.096
09			.095	1	140/77	15.3	1	140/77	16.7	.095
10			.097	1	146/78	11.5	1	146/78	16.1	.097
11			.095	1	140/72	16.4	1	140/72	20.5	.095
12			.095	1	138/77	18.9	1	138/77	19.8	.095

2X interch. Complete

141-15-11
2.0 to 2.5 clockwise

(OVER)

TI-NHTSA 001875

77PS CONTACT TEST

PURPOSE(S): One, to find out if high-mV-drop devices from previous test were due to excessive test load, due to low contact gap, or due to something else TBD; two, to gain engineering knowledge of the present contact system.

SCOPE: Only the powered portion of the Impulse test will be run, 24K cycles (instead of 25K) at approx. 2 Hz. Twelve 77PS devices will undergo the test, with the loads rotated every 2K such that each device sees each load for an equal time in order to eliminate individual variations. Half of the devices will be pinned such that the contact gap is at a minimum; the other half will be pinned normally.

PROCEDURE:

- * Check the load bank using a 'scope to determine if any significant variation exists (based on extreme results on two devices from previous test).
- * Build twelve 77PSL2-1 (Pass Car) devices. Use 77PS proto switches. Pin-window each device individually. For the six low-gap devices, try to find a pin length which results in no continuity change. This may be helped if these six are from a calibration lot which measures below .092". Then, back off a few mils, remembering to compensate for the 2 mil shift due to crimp, so we end up with a functional device which is known to have very small contact gap. The other six should be "normal" devices. These too should be individually pinned, hitting roughly the middle of the window w/ crimp compensation.
- * Gage each switch before assembly but after pin windows (in case any springs are deformed slightly in the quest).
- * Check calibration and mV drop.
- * Attach switches to manifold, connect loads, bring oven to normal temps (121 C ambient, 135 C fluid)
- * Run 2K cycles at roughly 2 Hz (speed up slightly if needed), then rotate loads and continue, rotating every 2K until 24K cycles is reached.
- * Recheck calibration and mV drop.
- * Disassemble switches, gage, then inspect contacts.

Filename: 77CONTAX SBO 910425

TI-NHTSA 001876

TPPS CONTACT TEST TEST 141-15-12 JAD 5/9/91

VICE #	CAP	IMAGE	ACT /REL	inV drop	ACT /REL	inV drop	IMAGE
141-15-01	LOW	0.091	136	/ 71	11.3	12	136 / 77
141-15-02	LOW	0.092	142	/ 75	16.0	14	141 / 79
141-15-03	LOW	0.093	137	/ 74	12.0	13	143 / 71
141-15-04	LOW	0.092	142	/ 79	13.5	15	140 / 80
141-15-05	LOW	0.091	140	/ 72	15.1	16	142 / 79
141-15-06	LOW	0.093	142	/ 74	10.6	10	142 / 70
141-15-07	HIGH	0.094	145	/ 84	13.4	13	147 / 86
141-15-08	HIGH	0.094	127	/ 73	13.2	13	135 / 71
141-15-09	HIGH	0.095	143	/ 77	15.3	15	144 / 79
141-15-10	HIGH	0.097	146	/ 70	11.5	11	144 / 70
141-15-11	HIGH	0.095	143	/ 72	16.6	16	142 / 76
141-15-12	HIGH	0.095	130	/ 77	10.4	10	143 / 79

TI-NHTSA 001877

77PS CONTACT TEST

PURPOSE(S): One, to find out if high-mV-drop devices from previous test were due to excessive test load, due to low contact gap, or due to something else TBD; two, to gain engineering knowledge of the present contact system.

SCOPE: Only the powered portion of the impulse test will be run, 24K cycles (instead of 25K) at approx. 2 Hz. Twelve 77PS devices will undergo the test, with the loads rotated every 2K such that each device sees each load for an equal time in order to eliminate individual variations. Half of the devices will be pinned such that the contact gap is at a minimum; the other half will be pinned normally.

PROCEDURE:

- * Check the load bank using a 'scope to determine if any significant variation exists (based on extreme results on two devices from previous test).
- * Build twelve 77PSL2-1 (Pass Car) devices. Use 77PS probe switches. Pin-window each device individually. For the six low-gap devices, try to find a pin length which results in no continuity change. This may be helped if these six are from a calibration lot which measures below .092". Then, back off a few mils, remembering to compensate for the 2 mil shift due to crimp, so we end up with a functional device which is known to have very small contact gap. The other six should be "normal" devices. These too should be individually pinned, hitting roughly the middle of the window w/ crimp compensation.
- * Cage each switch before assembly but after pin windows (in case any springs are deformed slightly in the cage).
- * Check calibration and mV drop.
- * Attach switches to manifold, connect loads, bring oven to normal temps (121 C ambient, 135 C fluid)
- * Run 2K cycles at roughly 2 Hz (speed up slightly if needed), then rotate loads and continue, rotating every 2K until 24K cycles is reached.
- * Recheck calibration and mV drop.
- * Disassemble switches, cage, then inspect contacts.

Filename: 77CONTAX SBO 910425

TI-4417SA 001870

-MSG N1= 397367 FR=CERN TO=PCQA SENT=04/26/91 07:44 AM
 RI=023 ST=C DIV=0050 CC=00101 BY=CERN AT=04/26/91 07:44 AM

TO: RUSTY STRUBLE RCSJ CC: TON CHARBONNEAU TC
 MIKE DeMATTIA PCQA JOHN KOURTESIS NDES
 CHARLIE DOUGLAS CPFC STEVE MAJOR WELS
 DICK GARIEPY NFPC ANDY MCGUIRK PCQA
 PAUL KOTCH PRK1 ED O'NEILL EJON
 JOE LAFARE JMLA JOE SCHUCK WELS
 STEVE OFFILER SBO1 GARY SNYDER CPFC
 NATE SELLERS PCNE NATEA SULLIVAN CPFC
 BILL SWEET PCNE RAY TOURANGEAU PCNE
 JIM WATT PCQA TED BALLARD AVNE
 TED BREDIKEN NFPC STAN BOMOL SHZ
 CLAIRA BALPHASAR NFPC
 BILL CONGDON NFPC
 STEVE MCCOOSY NDES

FR: DAVE CERN SARN

SJ: FORD CRUISE CONTROL PRESSURE SWITCH START-UP MEETING:
 04/25/91 MEETING MINUTES

MEETING

THE NEXT MEETING IS SCHEDULED FOR:

DATE: 05/03 (FRIDAY) **** PLEASE NOTE CHANGE ****
 TIME: 1:00 - 2:30 PM
 PLACE: PURCHASING CONFERENCE ROOM

PLEASE CALL ME IF YOU ARE NOT ABLE TO ATTEND

* * ITEMS THAT ARE NEW OR HAVE BEEN REVISED OR COMPLETED
 SINCE PREVIOUS MEETING

57 L/T

Hexport:

	WHO	WHEN	
* SHIP GAGE/DOCUMENTATION TO ELCO	SELLERS	04/25	ORIG.
		04/25	COMP.
* L/T PILOT RUN	SELLERS/	01/24	ORIG.
(PUSHOUT DUE TO HEXPORT AVAILABILITY)	GARIEPY	05/10	REV.
* CLOSE W/ELCO RE: THE EXCEPTION THEY	KOTCH	04/25	ORIG.
NOTED ON THE DOG POINT DIA. ON THE		04/25	COMP.
SHUTTER PRINT			
* F/U ON ELCO ISSUES RELATED TO	KOTCH	04/25	ORIG.
THREAD DAMAGE		04/25	COMP.
* RECEIVE RE-ROLLED HEXPORTS	KOTCH	05/02	
* VANISHING OIL TO ELCO	KOTCH	05/02	
* ELCO'S INPUTS ON WHY THE SECOND	KOTCH	05/09	
SHIPMENT OF HEXPORTS WERE IMPROVED AND			
NOW THIS GETS CARRIED OVER TO FUTURE LOTS			
* UPDATE HEXPORT SHIPPING SCHEDULE	KOTCH	ONGOING	
* COPY OF FORD'S INSTALLATION TORQUE	SCHUCK	05/09	
IPFC (E820000-8100); SEND TO TIA			
* ADVISE ON POULSEN'S HEXPORT QUOTES	KOTCH	05/02	

ISR issues:

* RELEASE PRINT FROM L/T SCH 05/09

TI-NHTSA 001879

* SUBMIT ISR FOLLOW-UP TO FORD SQA (NEED RELEASE PRINT)	WATT	04/04	ORIG.
		05/10	REV.
* DELIVER 238 PRODUCTION SWITCHES (PARTS NOT NEEDED BY FORD UNTIL MID-MAY)	SELLERS/ BALTHEASAR	04/01	ORIG.
* UPDATE TEAM ON AUDIBLE NOISE ISSUE	SCHUCK	05/17	REV.
* INCIPENT SNAP DISC SPEC AND INFO.	OFFILER	04/18	ORIG.
TO DISC DEPT.		04/25	REV.
* INCIPENT SNAP SWITCH SAMPLES	OFFILER	04/30	ORIG.
		04/18	COMP.

57 P/C

* LETTER TO FORD TO CLOSE ON TERM. POS'N ISSUE FOR ALL 57'S	DENATTIA	04/25	ORIG.
		04/30	REV.
* ISR SUPPLEMENT FOR SWITCHES W/BROWN OFFSET POLARITY KEY BASES (PUSHOUT DUE TO SARA DELAY)	WATT	04/10	ORIG.
		05/03	REV.
* MODIFY 57PS FMEA FOR PITTS	OFFILER	05/09	
* 238 SWITCHES TO PITTS	SELLERS	04/22	ORIG.
		04/29	REV.
* UPDATE PROD'N PLAN AS BROWN BELOW, REFLECTING THE EXPORT DELAY	STONKLE	04/23	ORIG.
		04/25	COMP.
* SHIP 21K LS-3'S	GARYET/ STONKLE	04/03	

77PS

* DESIGN UPDATE	OFFILER	ONGOING	
* MFG/MECH UPDATE	SELLERS	ONGOING	
* REPORT ON TORICO P.S. RESPONSIBILITY	DOUGLAS	ONGOING	
* PROD. LINE SET-UP (RTE CARDS, ETC)	BALTHEASAR	ONGOING	
* UPDATE SPC FILES/RUN CAPABILITY STUDIES	BALTHEASAR	ONGOING	
* ESTABLISH OVERALL SCHEDULE OF DESIGN ENG. ACTIONS	OFFILER	05/03	
* COMPLETE DESIGN FMEA	OFFILER	04/18	ORIG.
		05/30	REV.
* COMPLETE PROCESS FMEA	SELLERS	07/01	
* REPEAT IMPULSE TEST AT 2 SE TO STUDY CONTACT WEAR	OFFILER	04/25	ORIG.
		05/02	REV.
* TEL CONTACT ANALYSIS; SLOW VS. FAST CYCLE RATE	OFFILER	05/02	ORIG.
		05/09	REV.
* DETERMINE ACCEPTABLE CALIBRATION WINDOW BY DIMENSIONAL ANALYSIS	OFFILER/ SELLERS	03/14	ORIG.
		05/09	REV.
* VERIFICATION RUN FOR CALIBRATION WINDOW	OFFILER/ SELLERS	03/28	ORIG.
		05/16	REV.
* F/D CHARACTERIZATION OF SPRING ARMS	OFFILER	04/18	ORIG.
		05/09	REV.
* GAGING TECHNIQUE FOR IN-PROCESS F/D CHARACTERIZATION OF SPRING ARMS	SELLERS	04/25	ORIG.
		05/23	REV.
* VISIT EASTERN AUTOMATION RE: SPRING/TERMINAL ASM. MACHINE	SELLERS/ HCCOONY	04/25	ORIG.
* STAKE PROD'N PARTS ON PROD'N STAKER AND MEASURE TERMINAL POSITION	SELLERS	04/25	COMP.
		05/03	ORIG.
* 57 TO 77 CONVERSION: PHASE 1 TESTING (PUSHOUT DUE TO COMPONENT AVAILABILITY)	MONOL	05/10	ORIG.
		06/06	REV.
* IDENTIFY INSPECTION RIGHTS. FOR SOP	WATT	06/01	
* 77PS QAS (PRELIMINARY)	WATT	07/01	
* 77PS CHARACTERISTICS SHEETS	WATT	07/15	
* GAGE R&R STUDIES	WATT	07/15	
* 77PS QAS (FINAL)	WATT	08/01	
* SET UP SPC FILES/RUN CAPABILITY STUDIES	BALTHEASAR	08/01	

IQP'S:

* BASE

SELLERS/ 02/28 ORIG.
OFFILER 05/09 REV.

Production Components:

* DATE CUP PRINT

OFFILER 03/28 ORIG.
05/09 REV.

* RESOLVE OPEN ISSUES ON NOV. TERM.

SELLERS/ 04/04 ORIG.
OFFILER 05/02 REV.

* STATIONARY TERM.
(KF BASSLER DELIV. DATE PUSH-OUT)

SELLERS 03/22 ORIG.
05/02 REV.

* INVESTIGATE INCONSISTENT BEND RADII
CALLOUT ON STAT. AND NOV. TERMINALS

OFFILER 04/18 ORIG.
04/25 REV.
04/25 COMP.

* CLOSE W/BASSLER RE: BEND RADII ON
TERMINALS

OFFILER 05/02

* RESOLVE OPEN ISSUES ON BASE

SELLERS 04/11 ORIG.
05/02 REV.

* UPDATE TERMINAL PRINTS/BASE PRINT

OFFILER 05/09

Manufacturing Equipment:

* FINAL ASM MACHINE DEBUG COMPLETION

SELLERS/ 06/03
KOURTESIS

* BASE ASM MACHINE BUILD COMPLETION

SELLERS/ 05/31
KOURTESIS

* PRESSURE TESTER BUILD COMPLETION

SELLERS/ 06/20 ORIG.
KOURTESIS 06/04 REV.

DISCUSSION

57 L/T AND P/C

TWO ADD'L LOTS OF EXPORTS (11.8K TOTAL PCS.) WERE RECEIVED AND MARGINALLY PASSED THE ASSEMBLY TORQUE TEST (4.5 IN-LBS MAX.). ELCO HAS NOT DETERMINED WHY THESE PARTS ARE BETTER THAN THE PREVIOUS LOTS; IE, IT COULD BE RELATED TO PLATING, HANDLING OR MACHINE SET-UP DIFFERENCES, ETC. LONG TERM RESOLUTION OF THE THREAD DAMAGE PROBLEM MAY INCLUDE EVALUATING A HARDER MAT'L OR CHANGING THE PLATING PROCESS. AT LEAST 10K ADD'L EXPORTS ARE NEEDED WITHIN 2 WEEKS.

PRODUCTION SWITCH BUILD HAS BEEN IMPACTED BY OUR INABILITY TO CRIMP THE ALUMINUM RINGS WITHOUT CRACKING THE BASE AND WITHOUT CREATING SLIVERS. THE CRACKING PROBLEM APPEARS TO BE ISOLATED TO THE BROWN (P/C) BASES, AND MAY BE PROCESSING RELATED, AS THIS IS THE FIRST TIME PARTS HAVE BEEN MOLDED WITH BROWN 16622 PBT MATERIAL. THE SLIVER PROBLEM IS RELATED TO THE SHARP EDGES ON THE DRAWN RING; VANISHING OIL HELPS BUT DOESN'T SOLVE THE PROBLEM. MFG. AND DESIGN ENG. ARE WORKING TO RESOLVE THIS CRITICAL ITEM; IT NEEDS TO CONTINUE TO RECEIVE TOP PRIORITY SINCE WE CURRENTLY ARE NOT ABLE TO BUILD P/C SWITCHES, AND THE PRODUCTION PLAN CALLS FOR A 21K SWITCH DELIVERY IN EARLY JUNE.

MS

PRELIMINARY SPRINGS RECEIVED FROM EASTERN AUTOMATION SHOWED 2 PROBLEMS: 1. THE .040/.080" RADIUS AT THE BASE OF THE BUMP WAS

TI-NHTSA 001881

ACTUALLY SHARP/PARTIALLY SHEARED AND 2. THE HOLES WERE OVERSIZED.
MATT AND STEVE PLAN TO ADDRESS THIS DURING THEIR 04/25 MEETING.

THE L/T PROGRAM RESPONSIBILITY HAS CHANGED HANDS AT FORD - FROM
ORGE RANDALL (L/T NGSC ENG.) TO JOHN PELKEY (BRAKE ENG.). JOHN
REPORTS TO NEHRU MODI WHO HAS NOT BEEN AN ALLY TO TI IN THE PAST.

MILESTONES	PLANNED	ACTUAL
57 L/T ISIR	11/21/90	11/21/90
57 L/T JOB 1	09/03/91	
57 P/C ISIR	01/15/91	01/15/91
57 P/C JOB 1	06/03/91	
77PS ISIR	08/01/91	
77PS SOP (TI)	09/01/91	

PRODUCTION PLAN BY MONTH (THOUSANDS) - WITHOUT OVERAGE

	P/C 57PSL5-3	L/T 57PSL5-2	P/C 77PSL2-1	L/T 77PSL2-3
APR	0	0	0	0
MAY	22	2	0	0
JUN	*10 (tentative)	0	0	0
JUL	10	2.3	0	0
AUG	10	2.3	2	0
SEP	10	*2.6	2	0
OCT	0	9.5	**9	2
NOV	0	8.5	25	2
DEC	0	0	25	**9.5

* = JOB1 FOR 57PS VERSIONS

** = TENTATIVE JOB1 FOR 77PS VERSIONS

REGARDS,
DAVE CERN \21-FORD

that material meets ordered specification

Bally Diemeter

TEXAS INSTR.
27639-1

QUALITY CONTROL

APR 30 1991

L BALLO

1 3/8 x 0.015
PO Number
021540
MM Number
62276

Lot						AISI			Batch		
657196						C-105			B 7/78		
QC	Wt%	SP	SE	Wt%	SP	QC	Wt%	SP	QC	Wt%	SP
50	78	0.15	0.02	25							
Tensile Strength (ksi)				25 Yield Strength (ksi)				% Elongation in 2"			
Surface		Inclusion Rating		Grain Size							
Decarburization				Microstructure							
Cold Bend											
Parallel to the rolling direction over a						Radius Bend					
Perpendicular to the rolling direction over a						Radius Bend					
Hardness						Microhardness					

I certify that the above data is correct


[Signature] Date 4/26/91
[Signature]
 Quality Control Manager of the New York County of Quality
[Signature]

ROD STRIP STEEL

530 Henry St.
Rome, NY 13440

315-338-5500
FAX 315-338-5510

TI-NHTSA 001893



OFFENSE				
ZONE	CIN	DESCRIPTION	DATE	APPROVED
1		1. THE ARMY OF THE UNITED STATES	11-11-68	48

[illegible]

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED DATE 8-20-96 BY 60322 UCBAW/SJS/KSP/STP

77-441764 001024

CONFIDENTIAL
LAW DIV. (302) 261-1000
Date JUL 1 1974
FBI - NEW YORK

[illegible]

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-04-26

Stang
11/2/91



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: We learned from Joe Schuck this week that George Randall at Light Truck has handed pressure switch release responsibility over to a LT Brake Engineer, John Pelkey (analogous to Bruce Pease at Pass Car). John Pelkey's supervisor is the infamous Neri Modi. The 77PS truck print has been updated for terminal position tolerance, and is being sent to Joe, for hand-delivery to John.

We received a returned device from Kelsey-Hayes. We are not treating it as an official RMR, because it failed during a development test (not any official validation testing) while undergoing a salt water submersion test. We immediately responded that A) our device is not submersible, and that B) potential problems with the environmental seal on the mating connector can cause problems which are completely out of our control. We've learned that the device, installed on K-H's prop. valve asm., would not open on pressure rise after 264 cycles of 5 min. submersion in 5% salt water at 100 F followed by 55 min. drying. The device carried 5.5 mA current at 12 VDC during the test, but was not pressure-cycled. The mV drop remained good at about 30-40 mV even after failure. Our failure analysis showed that the disc still snapped, but indeed the contacts did not open. The current leakage was extremely large, so large that an ohmmeter was used rather than a hipot tester; measurement was 40K ohms. Disassembly showed that a rather large amount of salt water had entered the device, and inspection of all potential leak paths showed that entry was via the connector. The transfer pin was stuck, and the hinge side of the movable terminal asm. was severely corroded, explaining the no-continuity-change. The contacts themselves still looked OK, explaining the low mV drop. K-H has requested an 8D, which will be forwarded to them within a couple of weeks.

We have begun to mark-up the existing 57PS FMEA for this program. The only significant work to be done is to remove references to the O-ring seal and replace it with analogous information pertaining to the J512 seal. Other than that, references to "hydraulic oil" are being replaced with "brake fluid."

DESIGN ISSUES: Mfg. Eng. has been experiencing alleged cracked bases during final crimp on 57PSLS-3 (Pass Car, brown color). The problem manifested itself after successfully crimping 57PSLS-2 (Light Truck, black color). Initially it was thought that some difference in material between black and brown may be the culprit. Steve Walters was consulted, and his impression was that any pigmented material would be weaker than natural, but there should be no significant differences between various pigments. I did some experimentation with dye penetrant and sectioning, and discovered that the "cracks" were not propagating through the thickness at all; they were basically a surface phenomenon. Nonetheless, they are a concern cosmetically, because they look like cracks. Furthermore, Terry (group leader on 57PS line) mentioned that she sees this occasionally on all color bases and with steel crimp nags, and at some point in history it was proven that these parts are shippable. Matt Sellers pointed out that different cups are used for car and truck; measurement of the critical sensor height showed the car parts are .010" larger. They have opened up the crimp tools to compensate for this, and have had much better success. Matt has singled out a few of the worst ones that still show the "cracks", which we are presently analyzing with dye penetrant. I expect to show that these are again a surface phenomenon and there is no cause for concern.

HIGHLIGHTS 91-04-26

Page 2

The latest lots of 36900 hexports have arrived, and have been approved. The thread condition remains an issue; it was necessary to send the gage out for fresh calibration to ensure accuracy because these parts do drag on the gage, however they are consistently below the limit of 4.5 in-lbs. They also drag on Weatherhead mating fittings, which tells us that the customers may be unhappy with the thread condition. However, this drag is subjective while the freshly calibrated gage is the objective final arbitrator. We are looking into having Elco build a prototype lot using a higher-carbon material (10B20 vs. present 10L10). To be truly representative of production, this lot must be plated using the production process with production quantities in the barrel, etc.

We are working on the rerun of the TTPS contact test. Jeff has discovered a bad resistor on one of the loads which would have the effect of increasing the inductive kick, which helps explain the two drastically worse parts from the previous test. That test was run in two halves, which is why one bad load would produce two bad parts. Furthermore, Jeff always puts devices on manifolds in order, and the two bad parts were #6 and #12; these two had the same load, which presumably was the bad one.

We received a small quantity of production spring arms (enhanced, however) from Eastern Automation. I did a quick analysis of the dimensions, and found the bump is quite poor. They have no transition radius from the plane of the spring to the bump; there is a sharp discontinuity here which would surely lead to cracked arms. Steve McCoskey and Matt Sellers are communicating with EA about this; they have delivered SSPS arms to demonstrate the way the bump should look.

Ted Ballard is working on some very low differential discs to try to meet the need for "quiet" devices. After his first attempts, to get him up the learning curve, we plan to sit down to discuss the results Jeff has had to date along with Ted's results.

HIGHLIGHTS
Stephen B. Offler
Week Ending 91-04-26

Signature
4/26/91

cc - Donnan
FRT/2
[Handwritten mark]

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

CUSTOMER ISSUES: We learned from Joe Schuck this week that George Randall at Light Truck has handed pressure switch release responsibility over to a LT Brake Engineer, John Pelkey (analogous to Bruce Pease at Pass Car). John Pelkey's supervisor is the infamous Neru Modi. The 77PS truck print has been updated for terminal position tolerance, and is being sent to Joe, for hand-delivery to John.

We received a returned device from Kelsey-Hayes. We are not treating it as an official RMR, because it failed during a development test (not any official validation testing) while undergoing a salt water submersion test. We immediately responded that A) our device is not submersible, and that B) potential problems with the environmental seal on the mating connector can cause problems which are completely out of our control. We've learned that the device, installed on K-H's prop. valve asm., would not open on pressure rise after 264 cycles of 5 min. submersion in 5% salt water at 100 F followed by 55 min. drying. The device carried 5.5 mA current at 12 VDC during the test, but was not pressure-cycled. The mV drop remained good at about 30-40 mV even after failure. Our failure analysis showed that the disc still snapped, but indeed the contacts did not open. The current leakage was extremely large, so large that an ohmmeter was used rather than a hipot tester; measurement was 40K ohms. Disassembly showed that a rather large amount of salt water had entered the device, and inspection of all potential leak paths showed that entry was via the connector. The transfer pin was stuck, and the hinge side of the movable terminal asm. was severely corroded, explaining the no-continuity-change. The contacts themselves still looked OK, explaining the low mV drop. K-H has requested an 8D, which will be forwarded to them within a couple of weeks.

We have begun to mark-up the existing 57PS FMEA for this program. The only significant work to be done is to remove references to the O-ring seal and replace it with analogous information pertaining to the J512 seal. Other than that, references to "hydraulic oil" are being replaced with "brake fluid."

DESIGN ISSUES: Mfg. Eng. has been experiencing alleged cracked bases during final crimp on 57PSL5-3 (Pass Car, brown color). The problem manifested itself after successfully crimping 57PSL5-2 (Light Truck, black color). Initially it was thought that some difference in material between black and brown may be the culprit. Steve Walters was consulted, and his impression was that any pigmented material would be weaker than natural, but there should be no significant differences between various pigments. I did some experimentation with dye penetrant and sectioning, and discovered that the "cracks" were not propagating through the thickness at all; they were basically a surface phenomenon. Nonetheless, they are a concern cosmetically, because they look like cracks. Furthermore, Terry (group leader on 57PS line) mentioned that she sees this occasionally on all color bases and with steel crimp rings, and at some point in history it was proven that these parts are shippable. Matt Sellers pointed out that different cups are used for car and truck; measurement of the critical sensor height showed the car parts are .010" larger. They have opened up the crimp tools to compensate for this, and have had much better success. Matt has singled out a few of the worst ones that still show the "cracks", which we are presently analyzing with dye penetrant. I expect to show that these are again a surface phenomenon and there is no cause for concern.

The latest lots of 36900 hexports have arrived, and have been approved. The thread condition remains an issue; it was necessary to send the gage out for fresh calibration to ensure accuracy because these parts do drag on the gage, however they are consistently below the limit of 4.5 in-lbs. They also drag on Weatherhead mating fittings, which tells us that the customer(s) may be unhappy with the thread condition. However, this drag is subjective while the freshly calibrated gage is the objective final arbitrator. We are looking into having Elco build a prototype lot using a higher-carbon material (10B20 vs. present 10L10). To be truly representative of production, this lot must be plated using the production process with production quantities in the barrel, etc.

We are working on the rerun of the 77PS contact test. Jeff has discovered a bad resistor on one of the loads which would have the effect of increasing the inductive kick, which helps explain the two drastically worse parts from the previous test. That test was run in two halves, which is why one bad load would produce two bad parts. Furthermore, Jeff always puts devices on manifolds in order, and the two bad parts were #6 and #12; these two had the same load, which presumably was the bad one.

We received a small quantity of production spring arms (unbent, however) from Eastern Automation. I did a quick analysis of the dimensions, and found the bump is quite poor. They have no transition radius from the plane of the spring to the bump; there is a sharp discontinuity here which would surely lead to cracked arms. Steve McCooney and Matt Sellers are communicating with EA about this; they have delivered 55PS arms to demonstrate the way the bump should look.

Ted Ballard is working on some very low differential discs to try to meet the need for "quiet" devices. After his first attempts, to get him up the learning curve, we plan to sit down to discuss the results Jeff has had to date along with Ted's results.

Pages containing material that may be inventive must be witnessed by two persons who understand the invention and are not co-inventors.

Kelsey-Hayes Retarded Device

Test #192-15-01

Purpose: Determine the root cause of failure.

Nature of failure:

- After 364 cycles of alternate immersion testing, our switch which is normally closed would no longer open.
- Alternate immersion testing consists of submerging the entire valve assembly, including the mounted pressure switch, in 5% saltwater at 100°F for 5 min., then pulling the valve assembly from the water and allowing to dry above the tank for 55 min.
- The pressure switch is not ~~continuously~~ ^{continuously} cycled during this test but millivolt drop is monitored and seemed to be normal even after failure.

Analysis:

Visual Inspection:

- Device is a 57826 S-2 (Auto Code 0317, Ford App #206 95310) it is a gas-core device built with the first rebar cage and was part of sample order CD-95. The housing is an SAE 3514 with zinc chromate bonded plating. Gump ring is steel, zinc w/ yellow chromate plating. Base is a grey "L" with centered polarity tab.
- The housing's sealing surface is clean as is are the threads except for the last one. The rest of the exposed areas of the housing, as well as the exposed

WORK OF: Jeffrey DiDonato

DATE:

I witness this document and understand its contents.

I witness this document and understand its contents.

Pages containing material that may be sensitive must be witnessed by two persons who understand the legislation and are not co-inventors.

15-01

areas of the cap and crimp ring, are severely
oxy dited as would be expected. The base is
relatively clean. The connector cavity has just a hint
of salt deposits in the corners. The terminals
look to be in good shape and have what seems to be
greenish contact grease left on them. The locking
tab on one of the terminals seems to be discolored.

Characterization

- The disc snaps but there is no continuity along a rotation
and release values for the disc were taken as well as
millivolt drop with disc actuated and released:

Disc snap	No drop
Act/Rel	Act/Rel
165/87 mV	325/46 mV

Actuation value is a little high, compared to the measurements
taken before we shipped the device.
- Current leakage is excessive, too high to measure at source.
Resistance between terminals and crimp ring measures
only 40K Ω .

Disassembly:

- Salt present. The base severely oxy pited on the bottom
of the cap. A great deal of corrosion formed around
the transfer pin rendering it stuck. The hinge side
of the movable terminal was also severely corroded
and stuck. The contacts themselves still looked OK,
which accounts for the low millivolt drop.

WORK OF: Jeffrey D'Domenico

DATE: 4/24/94

I witness this document and understand its contents.

I witness this document and understand its contents.


Nº 05774- 40

TI LABORATORY AND ENGINEERING NOTEBOOK

Pages containing material that may be sensitive must be witnessed by JAG personnel who understand the information and are not under coercion.

142-15-01

The disc, converter, and washer have some salt on the
from where it pushed passed the transfer pin. The
hydraulic seal is not touched and the bottom of the
hexport is clean.



WORK OF: Jeffrey D. Dominick

DATE: 4/22/91

I witness this document and understand its contents.

I witness this document and understand its contents.

TI-NHTSA 001891

TI LABORATORY AND ENGINEERING NOTEBOOK

Nº 05774- 41

Pages containing material that may be inventive must be witnessed by two persons who understand the invention and are not co-inventors.

14. 15-01



Conclusions: The most likely leak path, judging by the affected areas, is just the mating connector into the switch body. The fluid slowly ran down the terminals, particularly the movable terminal, and puddled on the cap and the hinge of the movable terminal, as well as around the transfer pin. The stuck hinge and T-pin account for the lack of continuity change. The good condition of the contacts account for the low millivolt drop. A poor environmental seal in the mating connector is ultimately responsible for the failure.


WORK OF: Jeffrey D. Donawick

DATE: 4/26/91

I witness this document and understand its contents.

I witness this document and understand its contents.

TI-NHTSA 001892



TI-NHTSA 001893

PRESSURE SWITCH DATA

Form 21605

TEST NO.

DEVICE 77P56 2 1	DATE REQUESTED 11/5/79	REQUESTED BY J. J. J.	REQUESTED COMP. DATE
PERFORMED BY J. J. J.	DATE STARTED 11/5/79	DATE COMPLETED 5/15/80	APPROVED BY
PROJECT TITLE: Ford 117' 75' 1 hole... Spring...			

CUSTOMER

PURPOSE OF TEST

PROCEDURE

Wt.	Pressure	Temp.	10/11/79	11/5/79	11/11/79	11/15/79	11/19/79	11/23/79	11/27/79
5-01	1.91	11.1	146/79	146/79	146/79	146/79	146/79	146/79	146/79
61	1.92	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
62	1.93	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
63	1.94	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
64	1.95	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
65	1.96	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
66	1.97	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
67	1.98	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
68	1.99	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
69	2.00	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
70	2.01	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
71	2.02	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
72	2.03	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
73	2.04	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
74	2.05	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
75	2.06	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
76	2.07	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
77	2.08	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
78	2.09	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
79	2.10	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
80	2.11	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
81	2.12	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
82	2.13	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
83	2.14	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
84	2.15	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
85	2.16	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
86	2.17	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
87	2.18	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
88	2.19	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
89	2.20	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
90	2.21	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
91	2.22	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
92	2.23	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
93	2.24	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
94	2.25	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
95	2.26	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
96	2.27	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
97	2.28	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
98	2.29	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
99	2.30	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79
100	2.31	11.5	146/79	146/79	146/79	146/79	146/79	146/79	146/79

TI-NHTSA 001894

VALENTINE TOOL & STAMPING, INC.

111 WEST MAIN ST., NORFOLK, MASS. 02706
(508) 295-8911

MATERIAL CERTIFICATION

DATE : TUESDAY APRIL 30, 1991

CUSTOMER : TEXAS INSTRUMENTS INC.

CUSTOMER P.O. NO. : 50528715

SUPPLIER INVOICE NO. : 932

PART DESCRIPTION : 94187-01 CRIMP RING REV. 2

SUPPLIER P.O. NO. : 18571

QUANTITY SHIPPED : 20,449

SHIPMENT DATE : 04/30/91

WE CERTIFY THAT THE MATERIAL USED
TO PRODUCE THE PRODUCT IN THIS
SHIPMENT, NAMELY
: 5052 AL
CONFORMS TO T.I. DRAWINGS AND
T.I. PURCHASE ORDER REQUIREMENTS.

SIGNED

James Hoffmann
(Supplier Representative)

DATE OF CERTIFICATION : 04/30/91

TI-NHTSA 001895

VALENTINE TOOL & STAMPING, INC

11 WEST MAIN ST. NORTH ANDOVER, MASS. 02134
(508) 283-9300 FAX (508) 283-9301

CERTIFICATE OF CONFORMANCE

DATE : TUESDAY APRIL 21, 1991

CUSTOMER : TEXAS INSTRUMENTS INC

CUSTOMER P.O. NO. : 505083716

SUPPLIER INVOICE NO. : 92 9

PART DESCRIPTION : 74757-1 CRIMP RING REV.6

SUPPLIER P.O. NO. : 10573

QUANTITY SHIPPED : 20,449

SHIPMENT DATE : 04/30/91

WE CERTIFY THAT ALL ITEMS SHIPPED ON THIS ORDER MEET THE REQUIREMENTS
OF THE PURCHASE ORDER AND APPLICABLE DRAWINGS/SPECIFICATIONS. RESULTS
OF REQUIRED MECHANICAL, VISUAL, FUNCTIONAL AND CHEMICAL TESTS ARE ON
FILE IN OUR QUALITY CONTROL DEPARTMENT.

SIGNED

Jeanne Leflamme
Jeanne Leflamme
Quality Control Manager

TI-NHTSA 001898

UNITED ALUMINUM CORPORATION

100 UNITED DRIVE - NORTH HAVEN, CONNECTICUT 06473 - (203) 338-5881



VALENTINE TOOL & STAMPING, INC.
171 WEST MAIN STREET
MORTON, MA 02766-0469
ATTN: DICK WHITNEY

DATE 6/18/91
P.O. # 13876
SHIPPED 6/19/91
UA ORDER # 161499

THIS IS TO CERTIFY THAT THE MATERIAL LISTED BELOW CONFORMS WITH THE CHEMICAL COMPOSITION LIMITS OF 90A-250/8F AND THE FOLLOWING ARE THE LIMITS:

AA 5052

CHEMICAL COMPOSITION

	MIN	MAX
SILICON		0.25
IRON		0.40
COPPER		0.1
MANGANESE		0.1
MAGNESIUM	2.2	2.8
CHROMIUM	0.15	0.20
ZINC		0.1
TITANIUM		
OTHER ELEMENTS EACH		0.05
OTHER ELEMENTS (TOTAL)		0.15
ALUMINUM	REMAINDER	

MECHANICAL PROPERTIES

TENSILE STRENGTH	28.3 KSI
ELONGATION IN 2"	10%

.032

2.312

5052-0


UNITED ALUMINUM CORPORATION

TI-NHTSA 001897

74797


CRIMP RING

74797



NOTES:

1. FINCH OFF RADIUS ALLOWED.
2. .002 MAX. BURR ALLOWED.
3. PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.
4. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.



SUPERSEDES DNG. 74797 REV. A DATED 11-2-80

74797-1	ALUMINUM 5082	
PART NO.	MATERIAL	FINISH

BY: DMS-FLORUIT 11-2-80
 CH: 1-10-9
 ENG: 1-10-9



TEXAS INSTRUMENTS
 ATTORNEYS, MASSACHUSETTS 01900



DATE: 11-2-80
 REV: 1

TI-NHTSA 001800

Paratich, Inc.

A SUBSIDIARY OF AMERICAN CERAMIC
MINIATURE TECHNICAL CERAMICS

18840 MINNESOTA AVENUE • P.O. BOX 718 • PARAMOUNT, CALIFORNIA 92673
TELEPHONE (213) 633-2045 • FAX (213) 633-8907

MATERIAL CERTIFICATION

DATE: 4-22-91

TEXAS INSTRUMENTS, INC.

ORDER NO.: 505049981

PART NO : 74078-146 REV. NO.: F

QUANTITY THIS SHIPMENT: 75.000

SHIPMENT DATE: 4-22-91

PART DESCRIPTION: PIN


WE CERTIFY THAT THE MATERIAL USED TO PRODUCE THE PRODUCT IN THIS
SHIPMENT, NAMELY PIN / STEATITE - L3, CONFORMS TO T.I.
DRAWING AND T.I. PURCHASE ORDER REQUIREMENTS.

[Signature]
PRODUCTION MANAGER

TI-NHTSA 00188

TRANSFER PIN

74078

R.015 MAX.
(BOTH ENDS).150
Ø .150

PARTS MUST BE FREE OF CHIP
MARKS AND PROTRUSIONS. ENDS
MUST BE PERPENDICULAR TO
SIDES TO WITHIN 2 DEGREES.

"L" LENGTH IS DETERMINED BY THE SUFFIX OF THE PART NUMBER IN THOUSANDTHS
OF AN INCH. I.E.:

PART NO.	"L"
74078-188	.188
74078-210	.210

VENDOR WILL BE PREPARED TO FURNISH PINS .130 - .250 LONG.

NOTES:

1. FINISHED PARTS TO BE SHIPPED, ISSUED AND STORED IN SEALED PLASTIC BAGS. SEALED PLASTIC BAGS TO CONTAIN 20,000 PINS (OR LESS FOR PARTIAL BAGS). BAGS MUST BE CLEARLY LABELED WITH THE PART NO. AND THE QUANTITY OF PARTS IDENTIFIED ON THE OUTSIDE OF EACH BAG.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

MATERIAL: L-3 GRADE STEATITE (DC-1885)
L-3 GRADE STEATITE (DC-144E)

CURE PER SPEC. — 50502-2

SHRINKAGE SPEC. — 50501-1

CERTIFIED PRINT	
Parts Made To This Print Must Conform To	
ENG. STD. E9898 REV. 2	
Date JUL 1 1991	
AGREES THAT THIS PRINT HAS BEEN APPROVED FOR ISSUE. IT IS THE RESPONSIBILITY OF THE DESIGNER TO ENSURE THAT THE PARTS MANUFACTURED TO THIS PRINT MEET THE REQUIREMENTS OF THE DRAWING.	

THIS DWG. SUPERSEDES 74078 REV. "E" DATED 8-4-88

BY: WML/RAJ 10-12-88	CH:	ENG: [Signature]	DATE: 11-11-88	TXI-PA-91	TEXAS INSTRUMENTS ATTLESON, MASSACHUSETTS 01903	KIDON 10000 W. 10TH AVE. DENVER, CO 80231	Q13 Q1 M21P12-36 A	74078
----------------------	-----	------------------	----------------	-----------	---	--	-----------------------	-------

TI-NHTSA 001900

4

3

2

1-

REVISIONS					
ZONE	LTR	DESCRIPTION	DATE	APPROVED	
C7	D	11.40-11.60 WAS 11.83-11.84 CH133536 BS	12-17-80		
C4		48"-50" WAS 30"-30"			
C4		1.10-1.40 WAS 0.30-1.30			
C4		R.25MIN. X 40"-30" WAS 0.75 X 35"-30"			
C3		45.30-45.45 WAS 45.01-45.02			
B3		ADDED NOTE			
A3		R.00-0.07 WAS .001-0.00			
E		ADDED REVISION DETAIL TO PRINT G 32821 BS	1-10-81		

USE HYK 6 1004

REMEMBER YOUR PRINTING THE INFORMATION CONTAINED
ON THIS DRAWING IS THE PROPERTY OF THE FIRM
OF TEXAS INSTRUMENTS, INCORPORATED
OR AGENTS THE SERVICE OF ONE OF ITS AFFILIATED
COMPANIES OR WHOLLY OWNED SUBSIDIARIES

WSS-M89P9999-A1 TO HELP SAFEGUARD
HEALTH, SAFETY AND THE ENVIRONMENT

NO.

F3DC-9F924-AA

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES		BY TOM DALL	DATE 7-9-80	TEXAS INSTRUMENTS CORPORATION		KUXON CORPORATION	
TOLERANCE ON FRACTIONS DECIMALS ANGLES		CHK M. H. H. H.	4/1/81	TITLE PRESSURE SWITCH ENVELOPE DRAWING			
MATERIAL		APPROVED [Signature]	9/10/87	SIZE CODE IDENT NO		77PSLS-2	
				SCALE		SHEET	

METRIC

TI-NHTSA 001901

ATED 3-5-81

SAMPLE ORDER

ORDER NO: 1091-15

REQUEST DATE: 12/10/91

CREDIT ACCOUNT: 8902

COST CENTER: 101

PRODUCT CODE: 060

CUSTOMER: FORD MOTOR COMPANY

CUSTOMER P.O. NO: 47-X-U54023

TI PART NO: ~~57P5L5~~ 77P5L 2-1

CUSTOMER PART NO: F2VC-9F924-AB

QUANTITY: 15

PRICE: \$8.00 EA

DELIVERY PROMISED: 5/03/91

SPECIAL INSTRUCTIONS:

BILL TO:
FORD MOTOR COMPANY
P.O. BOX 1704
DEARBORN, MI 48121

SHIP TO:
FORD MOTOR COMPANY
1800 BAILEY AVE
DEARBORN, MI 48124
ATT'N: DEBBIE NEWMAN

PRODUCTION SAMPLES

XX ENGINEERING DEVELOPMENT SAMPLES

CC: ENGINEERING: STEVE OFFILER

PRODUCTION CONTROL: MARIE CROSSLAND

SALES ENGINEER: JOE SCHUCK

TI-NHTSA 001903

Form 21605

TEST NO.

CUSTOMER:

PURPOSE OF TEST:

PROCEDURE:

[illegible]

TI-NHTSA 001204

DISC DEPT. "INCIPIENT" (LOW-DIFF.) DISCS - I

The Disc Dept. has completed its first pass at low differential, quiet discs. Ted Ballard informs us that these actually make some snap sound, but not very much. His measurements are 29.2/23.9 . Our plan for these discs follows:

- * Pull a disc at random from the bag and attempt to measure free-disc actuation and release. You should be able to do this, since the Disc Dept could. Assuming you have no trouble hearing the discs, search through the bag until you get three discs which have roughly equivalent act/rel characteristics. If you cannot hear them, then pull three at random. Identify each disc somehow for tracking through the test.
- * Do the same thing for three of our standard Light Truck discs.
- * Record X-Y curves for each lot of three discs. All six curves on a single piece of paper, as long as it doesn't end up a mess.
- * Build into sensors, using standard cup per Light Truck practice. Use old (CMC) J512 hexports just in case these become customer evaluation samples. Attempt to measure act/rel using sound.
- * Record X-Y curves for the sensors; again, same piece of paper if possible.

So 7/10/501

FILE : INCI.P.001

TI-NHT&A 001905

DISC DEPT. LOW-DIFF. DISCS II

For the second pass, we will work with the lot of discs with a differential of 2.7 psi. These represent roughly the limit of manufacturability in the Disc Dept.

- * Locate the five discs in this lot that were characterized by the Disc Dept. Choose three of them that are closest in characteristics.
- * Check act/rel of the free discs (if possible); compare with Disc Dept readings.
- * Do X-Y curves of these three discs on same piece of paper.
- * Build into sensors using standard cups (light truck).
- * Attempt to measure act/rel of sensors using sound; try to get a feel for the relative amount of sound they make.
- * Record X-Y curves for each sensor, using separate pieces of graph paper.

The next phases of this test will involve a pin-window type of procedure, as follows.

- * From the lot of calibrated 77FS switches measuring about .096", record force at continuity change (transfer) for each. Do the same thing for .088" switches. Try to come up with two, one from each lot, which have roughly equal force. Record these forces and the reference dimensions for each.
- * Obtain a complete set of pins from .141 thru .157 (?); check with a micrometer and record values to nearest .0001".
- * Working with any one of the three sensors built above, measure the distance from the disc to the cup reference surface and record.

* Add the ref. dim.'s of the .096 switch and the sensor. Starting with a pin slightly below this value, try to record actuation and release. Theoretically, the device will remain open. Move up one pin size and continue. At the pin length where transfer begins to occur, begin to record act/rel until out of pin sizes.

* Change to the .088 switch. Starting with the smallest pin, work through the pin sizes until the device remains closed.


* Tabulate and graph data. For both switch sizes (individually), take the actual switch ref. dim. plus the sensor ref. dim. and subtract this value from the actual pin length, and use the result as the X-axis value to be plotted. Act and Rel are the Y-axis values to be plotted, of course. Plot directly on the hatchet curve for this sensor.

* At this point, we will analyze the results. If this technique looks promising, we will repeat the above for one or both of the other sensors as needed.

so 710507

SENSORS w/ 27.0/12.5 4.5

Sensor w/ snap d-scs




TI-NHTSA 001908

SENSORS w/ 27.0/12.5 .465

Sensor w/ snap d.s.c.s

4/3

4/1/2




TI-NHTSA 001509

SENSORS BUILT W/ 29.2/23.9 DISCS

SUBJECTIVELY, THESE ARE VERY QUIET BUT NOT SILENT

SENSORS w/ 20/23.9 DISCS



TI-NHTSA 001910