

EA02025

**TEXAS INSTRUMENTS, INC.'S
09/10/03 LETTER TO ODI**

REQUEST 9

BOX 12

PART A – O

PART K

Epstein, Sally

From: LaRouche, Steve (S.) [slarouch@ford.com]
Sent: Tuesday, March 30, 1999 2:54 PM
To: Rahman, Aziz; LaPointe, Norman; LaRouche, Steve; Porter, Fred; Reimers, Steve; Stevens, Gregory
Subject: Latest Versions of Switch Log and Testing Checklist



CHKLIST.DOC



SWITCHLOG.DOC

<<chklist.xls>> <<SwitchLog.xls>>

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room M410
(313) 945-4676 (313) 322-1614 FAX

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECTD AT GEN LAB

		Memphis	A	B	C	D	E	F	T
		PY622977	PY665224	NY745119	NY703705	VX145373	NX758774	NY760055	NX762858
Field Info	1 Log Field into site Switch log etc	C	C	C	C	C	C	C	C
	2	C	C	C	C	C	C	C	C
	3 Photograph Switch	C	C	C	C	BF LEAK	NO FIRE/LEAK	BF LEAK	NO FIRE/LEAK
	4 Record any unusual external visual observations	C	C	C	C	C	C	C	C
	5 Check for Connector engagement	C	NA	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	6 Wire 1(LOR) to Wires 2(RANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	7 Wire 1(LOR) to Hesper Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	8 Wire 2(RANGE) to Hesper Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	9 Replicate Harness from Switch	C	NA	NA	C	NA	NA	NA	NA
Connector Only	10 Identify Connector End	C	NA	NA	C	NA	NA	NA	NA
	11 Wire 1(LOR) to Wires 2(RANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	12 Check for full engagement of connector	NA	NA	NA	NA	NA	NA	NA	NA
	13 Check wavy structure	C	NA	NA	NA	NA	NA	NA	NA
	14 Check wavy grey scale	C	NA	NA	NA	NA	NA	NA	NA
Switch External Unpressurized	15 Call view condition to check for corrosion	C	NA	NA	NA	NA	NA	NA	NA
	16 Assemble Switch to Calibration Stand	NA	NA	NA	NA	NA	NA	NA	C
	17 Spring Travel to Defeatway Terminal Openness	NA	NA	NA	NA	0.4	0.2	NP	0.3
	18 Spring Travel to Hesper Resistance	NA	NA	NA	NA	4.8M	INF	2M	INF
	19 Defeatway Travel to Hesper Resistance	NA	NA	NA	NA	NP	NP	NP	INF
	20 Open to Hesper Resistance	NA	NA	NA	NA	T 1	8.8M	NP	3.3M
Switch External Pressurized	24 Spring Opening Pressure	NA	NA	NA	NA	NA	NA	NA	122
	25 Spring Closing Pressure	NA	NA	NA	NA	NA	NA	NA	59
	26 Press Test for Leakage	NA	NA	NA	NA	NA	NA	NA	NO LEAK
	27 Repeat Steps 17 through 20 at 100 psig	NA	NA	NA	NA	NA	NA	NA	C
Switch Technique	17 Spring Travel to Defeatway Terminal Resistance	NA	NA	NA	NA	NA	NA	NA	INF
	18 Spring Travel to Hesper Resistance	NA	NA	NA	NA	NA	NA	NA	INF
	19 Defeatway Travel to Hesper Resistance	NA	NA	NA	NA	NA	NA	NA	INF
	20 Open to Hesper Resistance	NA	NA	NA	NA	NA	NA	NA	INF
	28 Remove alternate camp cap	C	C	NP	C	C	C	C	NP
	29 Examine revealed surfaces Photograph	C	C	NP	C	C	C	C	NP
	30 Remove cap	C	C	NP	C	C	C	C	NP
31 Examine revealed surfaces Photograph	C	C	NP	C	C	C	C	NP	
Technique	31 SEM Clad a Tell trace contacts terminals	C	C	NP	C	C	C	C	NP
	32 SEM LOR & IBE up Hesper master with etc	C	C	C	C	C	C	C	NP
	33 Micrographic analysis of contacts (Look for evidence of corrosion or wiring)	C	NA	NP	C	C	C	C	NP

TI-NHTSA 016838

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT CEN LAB

		3	4	5	6	7	8	9	10
		PY724043	PY628170	PY832329	PY729611	NX726439	PX180223	PX637765	PY689375
Field Info	1 Log Field Info into Switch Logs	C	C	C	C	C	C	C	C
	2 Condition	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK
	3 Photograph Switch	NP	NP	NP	NP	NP	NP	NP	NP
	4 Check for unusual external visual observations	C	C	C	C	C	C	C	C
	5 Check for Connector engagement	NA	NA	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	6 Wire 1 (LGR) to Wire 2 (ORANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	7 Wire 1 (LGR) to Hupset Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	8 Wire 2 (ORANGE) to Hupset Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	9 Separate Harness from Switch	NA	NA	NA	NA	NA	NA	NA	NA
Connector Only	10 Visually Inspect Connector Seal	NA	NA	NA	NA	NA	NA	NA	NA
	11 Wire 1 (LGR) to Wire 2 (ORANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	12 Check for full engagement of separator	NA	NA	NA	NA	NA	NA	NA	NA
	13 Check wire resistance	NA	NA	NA	NA	NA	NA	NA	NA
	14 Check wire only when	NA	NA	NA	NA	NA	NA	NA	NA
Switch External Unpressurized	15 Cut wire resistance to check for continuity	NA	NA	NA	NA	NA	NA	NA	NA
	16 Resistor Switch to Calculator Output	C	C	NA	NA	C	C	C	C
	17 Spring Terminal to Electrical Terminal Resistance	0.2	0.3	NA	NA	0.2	0.2	0.2	2.2
	18 Spring Terminal to Hupset Resistance	INF	INF	NA	NA	INF	INF	INF	INF
	19 Solenoid Terminal to Hupset Resistance	INF	INF	NA	NA	INF	INF	INF	INF
Switch External Pressurized	20 Time to Hupset Observation	11.4	1.8M	NA	NA	7.8M	18.5	7.5M	1.4M
	24 Switch Closing Pressure	134	160	NA	NA	147	132	140	137
	25 Switch Closing Pressure	58	65	NA	NA	70	60	112	68
	26 Proof Test for Leakage	NO LEAK	NO LEAK	NA	NA	NO LEAK	NO LEAK	NO LEAK	NO LEAK
Switch	27 Repeat Steps 17 through 20 at 140 psig	C	C	NA	NA	C	C	C	C
	17 Spring Terminal to Electrical Terminal Resistance	INF	INF	NA	NA	INF	INF	INF	INF
	18 Spring Terminal to Hupset Resistance	INF	INF	NA	NA	INF	INF	INF	INF
	19 Solenoid Terminal to Hupset Resistance	INF	INF	NA	NA	INF	INF	INF	INF
	20 Time to Hupset Observation	INF	INF	NA	NA	INF	INF	INF	INF
	28 Measure aluminum comb temp	NP	NP	C	C	NP	NP	NP	NP
	29 Examine revealed surfaces: Photograph	NP	NP	C	C	NP	NP	NP	NP
Technique	30 Remove Cap	NP	NP	C	C	NP	NP	NP	NP
	31 Examine revealed surfaces: Photograph	NP	NP	C	C	NP	NP	NP	NP
	32 SEM EDX of TR base, contacts, terminals	NP	NP	NP	NP	NP	NP	NP	NP
	33 SEM EDX of TR cup, hupset, washer, comb, etc.	NP	NP	NP	NP	NP	NP	NP	NP
Technique	33 Metallographic analysis of contacts	NP	NP	NP	NP	NP	NP	NP	NP

TI-NHTSA 016839

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT C&N LAB

Task for evidence of compliance is shown		NP	NP	NP	NP	NP	NP	NP	NP
		11	12	13	14	15	16	17	18
		PY728088	PX885270	NY740208	PX623672	PY885374	BY639884	PY650225	PY688785
Field Info	1 Log Field Info into Switch Log etc	C	C	C	C	C	C	C	C
	2 Continue	NO FIRE/LEAK							
	3 Photograph Switch	NP							
	3 Record any unusual external visual observations	C							
	4 Check for Connector engagement	NA							
Switch + Connector Assembly	5 Verify if appropriate	NA							
	5 View 1 (LGR) to View 2 (FRANGE) Resistance	NA							
	6 Other 1 (LGR) to Hegepost Resistance	NA							
	7 Other 2 (FRANGE) to Hegepost Resistance	NA							
	8 Separate Hegepost from Switch	NA							
Connector Only	9 Verify Connector Seal	NA							
	10 View 1 (LGR) to View 2 (FRANGE) Resistance	NA							
	12 Check for full engagement of Cavitation	NA							
	13 Check wire insulation	NA							
	14 Check wire girth tight	NA							
Switch External Unpressurized	15 Cut wire insulation to check for corrosion	NA							
	16 Assemble Switch to Calibration Stand	C							
	17 Supply Terminal to Stationary Terminal Resistance	0.2							
	18 Supply Terminal to Hegepost Resistance	INF							
	19 Stationary Terminal to Hegepost Resistance	INF							
Switch External Pressurized	20 Seal to Hegepost Resistance	INF							
	24 Switch Opening Pressure	138							
	25 Switch Closing Pressure	71							
	26 Proof Test for Leakage	NO LEAK							
	27 Repeat Steps 17 through 20 or 188 page	C							
Switch	17 Supply Terminal to Stationary Terminal Resistance	INF							
	18 Supply Terminal to Hegepost Resistance	INF							
	19 Stationary Terminal to Hegepost Resistance	INF							
	20 Seal to Hegepost Resistance	INF							
	28 Remove aluminum crimp ring	NP							
Techniques	29 Examine revealed surfaces Photograph	NP							
	30 Measure + up	NP							
	31 Examine revealed surfaces Photograph	NP							
	32 SEM EDS of 188 case contacts terminals	NP							
	32 SEM EDS of 188 case contacts terminals etc	NP							

TI-NHTSA 016840

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT GEN LAB

		18	20	21	22	23	1	2	3
		PY774255	PY754575	PX843515	??	PX820034	PY838990	PX163020	PX841595
	33	Photographic analysis of contacts							
		Look for evidence of corrosion or scoring							
Field Info	1	Tag Field Info into Switch Log etc					C	C	C
		Complete					NO FIRE/EAK	NO FIRE/EAK	NO FIRE/EAK
	2	Photograph Switch					C	C	C
	3	Marking any unusual colored metal observations					C	C	C
	4	Check for Connector engagement					C	C	C
	5	Tag if it appropriate					NA	C	NA
Switch + Connector Assembly	6	Wire 1(LGR) to Wren 2(FRAME) Resistance					D3	0.4	0.2
	8	Wire 1(LGR) to Humpal Resistance					INF	INF	INF
	7	Wire 2(FRAME) to Humpal Resistance					INF	INF	INF
	8	Separate Humpal from Switch					C	C	C
Connector Only	9	Verify Connector Seat					C	C	C
	10	Wire 1(LGR) to Wren 2(FRAME) Resistance					INF	INF	INF
	12	Check for full engagement of connector					C	C	C
	13	Check wire resistance					C	C	C
	14	Check wire plug tight					C	C	C
	15	Get wire resistance to check for corrosion					TBP	TBP	TBP
Switch External Unpressurized	16	Assemble Switch to Calibration Stand					C	C	C
	17	Spring Terminal to Elementary Terminal Resistance					D3	0.1	0.2
	18	Spring Terminal to Humpal Resistance					INF	INF	INF
	19	Elementary Terminal to Humpal Resistance					INF	INF	INF
	20	Wire to Humpal Resistance					5.5	INF	17.7K
Switch External Pressurized	24	Switch Closing Pressure					156	127	126
	25	Switch Closing Pressure					68	62	64
	26	Proof Test for Leaking					NO LEAK	NO LEAK	NO LEAK
	27	Repeat Steps 17 through 20 in WD pag					C	C	C
	17	Spring Terminal to Elementary Terminal Resistance					INF	0.1	INF
	18	Spring Terminal to Humpal Resistance					INF	INF	INF
	19	Elementary Terminal to Humpal Resistance					INF	INF	INF
	20	Wire to Humpal Resistance					INF	INF	INF
Switch	28	Remove chambered cover ring					NP	C	NP
	29	Examine revealed surfaces. Photograph					NP	C	NP
	30	Remove cap					NP	C	NP
	31	Examine revealed surfaces. Photograph					NP	C	NP
Techniques	31	SEM EDC if T&E have contacts removed					NP	C	NP

71-NHTSA 016841

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT CEN LAB

		4	5	6	7	8	9	10	11
		PX183312	PY810384	NY724388	PY750172	NY733191	PY758158	PX151140	NY757408
Field Info	1 Log Field Info into Dispatch Log etc	C	C	C	C	C	C	C	C
	Condition	NO FIRE/LEAK	NO FIRE/LEAK	FIRE	NO FIRE/LEAK	FIRE	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK
	2 Photograph Switch	C	C	C	C	C	C	C	C
	3 Record any unusual internal visual observations	C	C	C	C	C	C	C	C
Switch + Connector Assembly	4 Check for Connector engagement	C	C	NA	C	NA	C	NA	C
	5 Only if Applicable	C	NA	NA	NA	NA	C	NA	NA
	6 Wire 16 GRN to Wire 20 (RANGE) Resistance	NP	0.2	NA	INF	NA	2	0.4	NP
	7 Wire 16 GRN to Hopout Resistance	NP	INF	NA	INF	NA	6.0M	INF	NP
Connector Only	8 Wire 20 (RANGE) to Hopout Resistance	NP	INF	NA	INF	NA	8.1M	INF	NP
	9 Separate Wires from Switch	C	C	NA	C	NA	C	C	C
	10 Only Connector End	C	C	NA	C	NA	C	C	C
	11 Wire 16 (GRN) to Wire 20 (RANGE) Resistance	NP	NA	NA	INF	NA	INF	INF	NP
Switch External Unpressurized	12 Check for full engagement of connector	C	C	NA	C	NA	C	C	C
	13 Check only operation	C	C	NA	C	NA	C	C	C
	14 Check into gray valve	C	C	NA	C	NA	C	C	C
	15 Call wire resistance to check by condition	TBP	TBP	NA	TBP	NA	TBP	TBP	TBP
Switch External Unpressurized	16 Assemble Switch to Calibration Stand	C	C	NA	C	NA	C	C	C
	17 Spring Terminal to Stationary Terminal Resistance	0.1	0.2	NA	0.3	NA	1.5	0.4	0.1
	18 Spring Terminal to Hopout Resistance	INF	INF	NA	INF	NA	6.3M	INF	INF
	19 Stationary Terminal to Hopout Resistance	INF	INF	NA	INF	NA	6.4M	INF	INF
Switch External Pressurized	20 Wire to Hopout Resistance	INF	NRCLS	NA	463K	NA	0.4	8.8	INF
	24 Switch Opening Pressure	133	151	NA	136	NA	164	136	135
	25 Switch Closing Pressure	83	82	NA	85	NA	86	108	74
	26 Pass Test for Leakage	NO LEAK	NO LEAK	NA	NO LEAK	NA	NO LEAK	NO LEAK	NO LEAK
Switch External Pressurized	27 Repeat Steps 17 through 20 at 100 psig	C	C	NA	C	NA	C	C	C
	17 Spring Terminal to Stationary Terminal Resistance	INF	INF	NA	INF	NA	0.7	INF	INF
	18 Spring Terminal to Hopout Resistance	INF	INF	NA	INF	NA	-870K	INF	INF
	19 Stationary Terminal to Hopout Resistance	INF	INF	NA	INF	NA	-870K	INF	INF
Switch External Pressurized	20 Wire to Hopout Resistance	INF	INF	NA	INF	NA	INF	INF	INF
	29 Remove aluminum O-ring cap	NP	NP	NP	NP	NP	C	NP	NP
	25 Examine revealed surfaces. Photograph	NP	NP	NP	NP	NP	C	NP	NP
	30 Remove cap	NP	NP	NP	NP	NP	C	NP	NP
Switch External Pressurized	31 Examine revealed surfaces. Photograph	NP	NP	NP	NP	NP	C	NP	NP

TI-NHTSA 016842

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT REC'D AT GEN LAB.

Technique	31	32	33	34	35	36	37	38	39	
31	SEM-EDX FOR leads, contacts, terminals	NP	NP	NP	NP	NP	NP	C	NP	NP
32	SEM-EDX FTIR cup, nitrogen, water seal, etc	NP	NP	NP	NP	NP	NP	C	NP	NP
33	Micrographic analysis of contacts	NP	NP	NP	NP	NP	NP	NP	NP	NP
	Look for evidence of corrosion or galling	NP	NP	NP	NP	NP	NP	C	NP	NP

		12	13	OASIS	OASIS	EAA	EAA	EAA
		PY742638	PY7433413	NY734410	PY605626	PY814995	NY735347	NY706341
Field Info	1 Log Field Info into Switch Log file	C	C	C	C	C	C	C
	2 Corrotype	NO FIRE/LEAK	NO FIRE/LEAK	BF LEAK	BF LEAK	FIRE	FIRE	FIRE
	3 Photograph Switch	C	C	C	C	C	C	NA
	4 Record any unusual external visual observations	C	C	C	C	C	C	NA
	5 Check for Connector engagement	C	C	NA	NA	NA	NA	NA
Switch + Connector Assembly	6 Log # of assemblies	C	NA	NA	NA	NA	NA	NA
	7 Wire 10.00V to Wires 2 (ORANGE) Resistance	0.3	0.3	NA	NA	NA	NA	NA
	8 Wire 10.00V to Hesper Resistance	20.2M	INF	NA	NA	NA	NA	NA
	9 Wire 2 (ORANGE) to Hesper Resistance	21.5M	INF	NA	NA	NA	NA	NA
Connector Only	10 Disconnect Harness from Switch	C	C	NA	NA	NA	NA	NA
	11 Verify Connector Seal	C	C	NA	NA	NA	NA	NA
	12 Wire 10.00V to Wires 2 (ORANGE) Resistance	INF	INF	NA	NA	NA	NA	NA
	13 Check for full engagement of connector	C	C	NA	NA	NA	NA	NA
	14 Check wire resistance	C	C	NA	NA	NA	NA	NA
Switch External Unpressurized	15 Check wire gage	C	C	NA	NA	NA	NA	NA
	16 Cal wire resistance to check for corrosion	TBP	TBP	NA	NA	NA	NA	NA
	17 Reassemble Switch to Calibrate Seal	C	C	C	C	NA	NA	NA
	18 Spring Terminal to Stationary Terminal Resistance	0.2	0.2	>700K	>130K	NA	NA	NA
	19 Spring Terminal to Hesper Resistance	36M	INF	>250K	>17K	NA	NA	NA
Switch External Pressurized	20 Stationary Terminal to Hesper Resistance	36M	INF	>350K	>120K	NA	NA	NA
	21 Wire to Hesper Resistance	63.4K	7.5M	INF	INF	NA	NA	NA
	22 Switch Opening Pressure	145	150	152	NO SOUND	NA	NA	NA
	23 Switch Closing Pressure	61	70	92	NO SOUND	NA	NA	NA
Switch	24 Proof Test for Leakage	NO LEAK	NO LEAK	NO LEAK	NO LEAK	NA	NA	NA
	25 Repeat Steps 17 through 20 at 100 psig	C	C	C	C	NA	NA	NA
	26 Stationary Terminal to Stationary Terminal Resistance	0.1	INF	>1.0M	170K	NA	NA	NA
	27 Spring Terminal to Hesper Resistance	INF	INF	>600K	>140K	NA	NA	NA
	28 Stationary Terminal to Hesper Resistance	INF	INF	>400K	>15K	NA	NA	NA
	29 Wire to Hesper Resistance	INF	INF	INF	INF	NA	NA	NA
	30 Remove aluminum clamp cap	SCI LAB	NP	C	C	TBP	TBP	NA
Switch	31 Remove threaded surface Photograph	SCI LAB	NP	C	C	TBP	TBP	NA
	32 Remove cap	SCI LAB	NP	C	C	TBP	TBP	NA

TI-NHTSA 018843

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT CEN LAB

Techniques	31	Examine exposed surfaces. Photograph	SCI LAB	NP	C	C	TBP	TBP	NA	
	31	SEM EDX FTIR base, contacts, terminals	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	
	32	SEM-EDX FTIR cap, base, upper body, etc.	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	
	33	Metallographic analysis of contacts	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	
		Look for evidence of corrosion or aging	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	

Field Info	1	Log Field into into Switch Log etc								
	2	Photograph Switch								
	3	Inspect any unusual external visual observations								
	4	Check for Connector engagement								
	5	Key #4 Appropriate								
Switch + Connector Assembly	6	Wire 19 GAGE Wire 2 (ORANGE) resistance								
	7	Wire 19 GAGE to Hesper Resistance								
	8	Wire 2 (ORANGE) to Hesper Resistance								
Connector Only	9	Disconnect Hesper from Switch								
	10	Verify Connector Seat								
	11	Wire 19 GAGE to Wire 2 (ORANGE) resistance								
	12	Check rail seat for full engagement of connector								
	13	Check wire condition								
Switch Exposed Unpressurized	14	Check wire gray pins								
	15	Put wire condition to check for corrosion								
	16	Assemble Switch to Calibration Stand								
	17	Spring Terminal to Stationary Terminal Resistance								
	18	Spring Terminal to Hesper Resistance								
Switch Exposed Pressurized	19	Stationary Terminal to Hesper resistance								
	20	Wire to Hesper Resistance								
	21	Switch Opening Pressure								
	22	Switch Closing Pressure								
	23	Proof Test for Leakage								
Switch	24	Repeat Steps 17 through 20 at 100 psig								
	25	Spring Terminal to Stationary Terminal Resistance								
	26	Spring Terminal to Hesper Resistance								
	27	Stationary Terminal to Hesper resistance								
	28	Wire to Hesper Resistance								
	29	Inspect exposed surfaces. Photograph								
	30	Remove 440								

TI-NHTSA 016844

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT CEN LAB

	31	Examine mounted switches. Photograph								
Techniques:	31	SEM EDX FTIR base, contacts, terminals								
	32	SEM EDX FTIR cap, housing, weather seals, etc								
	33	Metallographic analysis of contacts								
		Look for evidence of corrosion or scoring								

TI-NHTSA 016846

**DRAWINGS AVAILABLE UPON
REQUEST**

Epstein, Selvy

From: McGuirk, Andy (a-mcguirk@email.mc.ti.com)
Sent: Thursday, April 01, 1999 2:28 PM
To: 'Frederick J. Porter'
Subject: FW: ANDY.xls



FRED, THIS IS THE CORRECTED MATRIX AND MAY NEED DIALOGUE.....CALL ME OR CHARLIE

A

AUTOMOTIVE SENSORS AND CONTROLS QRA MANGER
34 FOREST ST N/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3749
PAGE: (800) 467-3700 PIN 604-2044

From: Pawlowski, Robin
Sent: Thursday, April 01, 1999 2:04 PM
To: McGuirk, Andy; Douglas, Charles
Subject: ANDY.xls

<<ANDY.xls>>
I have added more locations to the Ford 779SL3-3

TI-NHTSA 016848

for the TYPOL20 could not show all shipping facilities -- symbols for facilities no longer in use.

Category	SHIP TO LOC	Dist Number	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
DASH COMP 1988		TYPOL2-1 / FZVC SFZM AB	21 88	87 11	83 38	8	0	0	8	0	0	0	8	0
		TYPOL2-1 / FZVC SFZM AA	0	0	8	8	23 84	8	74 75	28 88	0	0	0	0
		TYPOL2-3 / FZVA SFZM AA	0	0	8	8	0	8	8	8	0	0	0	8
MT COMP 1982		TYPOL2-1 / FZVC SFZM AB	8 85	8	0	8	0	0	8	0	0	0	0	8
		TYPOL2-2 / FZDC SFZM AA	0	0	0	0	8	0	0	0	0	4 28	8 88	1 84
	1988	TYPOL2-3 / FZDC SFZM AA	1 42	8 48	8 38	1 88	2 88	8 71	8	0	0 47	8 74	0	8 82
	1984	TYPOL2-3 / FZDC SFZM AA	1 42	8 74	1 8	1 42	1 42	0	8 71	8 71	8 71	8 478	8 478	1 18
1988	TYPOL2-3 / FZDC SFZM AA	8 28	8 882	8 882	1 18	0	0	0	0	8	0	0	0	
METEOROLOGICAL 1982		TYPOL2-1 / FZVC SFZM AB	48 83	43 31	8 47	31 88	32 38	3 33	35 23	63 78	21 42	43 38	44 74	18 58
		TYPOL2-2 / FZDC SFZM AA	0	0	0	0	0	0	0	2 78	8	0	0	0
	1988	TYPOL2-1 / FZVC SFZM AB	14 47	18 23	23 88	23 81	14 81	22 81	20 7	30 48	23 88	18 88	24 75	28 7
		TYPOL2-1 / FZVC SFZM AA	8	8	8	0	8	0	8	8	8 88	0	0	3 23
	1984	TYPOL2-1 / FZVC SFZM AB	23 88	12 88	18 71	28 7	23 88	8 28	8 28	3 8	1 18	8 88	0	0
		TYPOL2-1 / FZVC SFZM AA	8	8	8	8	8 71	18 32	83 23	27 8	33 78	34 83	18 8	18 31
1988	TYPOL2-3 / FZVA SFZM CA	8	0	0	0	0	8	8	8	8	0	0	8 8	
1985		TYPOL2-1 / FZVC SFZM AA	27 84	28 88	28 32	28 84	15 7	15 18	18 47	7 14	14 84	8 88	2 88	5 88
		TYPOL2-3 / FZVA SFZM CA	8 478	0	0	0	0	2 14	2 88	8 74	8 74	1 18	8 74	4 84
		TYPOL2-1 / FZVC SFZM AA	8	0	8 28	8 74	8 78	8	8	8	0	0	0	8
1986		TYPOL2-1 / FZVC SFZM AA	21 88	4 78	8 8	8 8	0	8	8	8	0	8	0	8
		TYPOL2-3 / FZVA SFZM CA	0	0	0	1 42	0	8	0	0	0	8	8	0
		TYPOL2-1 / FZVC SFZM AA												
FORD MOTOR 1982		TYPOL2-1 / FZVC SFZM AB	8	8	0	0	0	0	0	0	0 47	0	0	0
		TYPOL2-3 / FZVA SFZM CA	18 81	18 7	18 41	18 8	28 88	18 7	18 8	88 88	18 18	8 82	17 73	15 28
		TYPOL2-3 / FZVA SFZM CA	8	8	8	0	0	2 44	3 33	83 3	83 11	71 87	83 82	44 28
		TYPOL2-2 / FZDC SFZM AA	0	8	8	0	0	0	0	0	0	0	0 47	0
	1988	TYPOL2-1 / FZVC SFZM AB	0	0	0	0	0	0	8	0	0	8 23	0	0
		TYPOL2-3 / FZVA SFZM CA	1 87	8	8	0	0	0	0	8	8	0	0	0
	TYPOL2-3 / FZVA SFZM AA	0	0	0	0	0	0	8	8	8	0 71	8 82	8 74	
1985		TYPOL2-3 / FZVA SFZM CA	25 28	41 88	33 75	44 38	44 34	43 84	23 88	32 43	0 47	8 74	8 42	8 82
		TYPOL2-3 / FZDC SFZM AA	0	8 71	8	0	0	0	0	8	0	0	0	0
		TYPOL2-1 / FZVC SFZM AA	0 28	8	8	0	0	0	0	0 71	0	0	0	0
1986	TYPOL2-1 / FZVC SFZM AB	0 28	8	8	0	0	0	0	0 71	0	0	0	0	

CONFIDENTIAL

TI-NHTSA 016849

	Local Term	77PBL3-3 / FSTA WFOH CA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Civilian Employment	77PBL3-2 / FSTA WFOH AA	142	0 23	11 42	17 08	25 04	10 00	10 00	20 4	24 27	30 7	20 04	10 00						
	Executive Employment	77PBL3-3 / FSTA WFOH CA	3 8	0 011	1 18	1 10	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	1 0	
	Board Membership	77PBL3-2 / FSTA WFOH AA																		
1985	Civilian	77PBL3-2 / FSTA WFOH AA	18 00	18 01	18 00	21 10	20 02	22 37	14 70	20 7	22 37	25 40	11 00	0 75						
1986	Civilian Employment	77PBL3-2 / FSTA WFOH AA	14 00	10 00	21 00	20 41	21 00	10 01	14 02	27 37	18 00	10 00	14 51	15 47						
	Executive Employment	77PBL3-1 / FSTA WFOH AA	0	0	0	0	0 000	0	0	0	0	0 470	0	0						
	Board Membership	77PBL3-3 / FSTA WFOH CA	0	0	0	0	0	0	0	0	0	1 2	0	0						
1987	Civilian Employment	77PBL3-3 / FSTA WFOH AA	21 10	21 42	27 0	24 03	22 04	27 37	4 70	20 41	25 04	24 27	24 75	17 37						
	Executive Employment	77PBL3-1 / FSTA WFOH AA	0	0	0	0	0 714	0	0	0	0	0	0 714	0						
	Board Membership	77PBL3-3 / FSTA WFOH CA	0	0	0	0 40	0	0	0 40	1 2	0	0 40	0 00	0 200						
1988	Civilian Employment	77PBL3-2 / FSTA WFOH AA	14 75	20 25	25 00	23 04	20 50	21 00	1 10	11 0	10 47	22 04	10 17	10 10						
	Executive Employment	77PBL3-1 / FSTA WFOH AA	0	0 002	0	0	0	0	0	0	0 470	0	0 00	0						
	Board Membership	77PBL3-3 / FSTA WFOH CA	2 0	0 40	0 72	1 0	0 72	1 02	0 00	1 02	2 10	2 00	2 00	1 2						
	Executive Employment	77PBL3-1 / FSTA WFOH AA	0	0	11 0	0 200	14 20	0	0	2 00	0 75	0	1 33	0 200						

RELAY-HAYES CO.
1989

77PBL3-1 / FSTA WFOH AA	4 00	4 00	0 23	2 0	2 0	3 07	0 00	0	0	0	0	0	0	0	0	0	0	0	0	0
-------------------------	------	------	------	-----	-----	------	------	---	---	---	---	---	---	---	---	---	---	---	---	---

ALLIED SIGNAL
1983

77PBL3-3 / FSTA WFOH CA	0	0	0 200	0	0	0 200	0	0	0	0	0	0 200	0	0 200						
-------------------------	---	---	-------	---	---	-------	---	---	---	---	---	-------	---	-------	--	--	--	--	--	--

1984

77PBL3-3 / FSTA WFOH CA	0 400	0 200	0	0 470	0 0	0	0 002	0 05	0	2 07	20 30	33 30								
77PBL3-1 / FSTA WFOH AA	0	0	0	0 00	0 00	0	0	0 000	0	0	0	0	4 0							

1985

77PBL3-1 / FSTA WFOH AA	2 0	0	0	0	0 002	10 7	10 47	0	0 50	15 47	17 13	10 00								
77PBL3-3 / FSTA WFOH CA	05 00	20 12	20 70	73 00	00 10	00 00	10 0	43 00	00 12	00 00	43 00	40 30								

1986

77PBL3-1 / FSTA WFOH AA	10 00	22 04	21 42	17 13	10 00	10 00	12 05	0 00	17 13	14 20	1 42									
77PBL3-3 / FSTA WFOH CA	07 02	07 12	00 70	20 00	47 04	03 30	30 34	33 0	00 40	07 2	0 72									

SONOCO

1983

77PBL3-3 / FSTA WFOH CA	0	0	0	1 0	0	2	30	20	00	00	50	40 10								
-------------------------	---	---	---	-----	---	---	----	----	----	----	----	-------	--	--	--	--	--	--	--	--

1984

77PBL3-3 / FSTA WFOH CA	20 10	20 0	72 00	72 72	70 00	20 04	05 00	70	05 12	10 00	10 12	00 02								
-------------------------	-------	------	-------	-------	-------	-------	-------	----	-------	-------	-------	-------	--	--	--	--	--	--	--	--

1985

77PBL3-3 / FSTA WFOH CA	74 00	00 04	70	04	00 00	04 40	02 00	70 2	00 04	01 2	00 30	47 50								
-------------------------	-------	-------	----	----	-------	-------	-------	------	-------	------	-------	-------	--	--	--	--	--	--	--	--

1986

77PBL3-3 / FSTA WFOH CA	50 00	11 44	02 10	71 20	00 72	30 4	00 4	107 0	01 0	00 4	04 0	04 00								
77PBL3-2 / FSTA WFOH AA												0 02								

1987

77PBL3-3 / FSTA WFOH CA	72	07 04	100 0	70 2	10 00	10 10	07 12	107	00	40	02 20	05 04								
77PBL3-2 / FSTA WFOH AA																				

1988

77PBL3-3 / FSTA WFOH CA	50 10	111 0	130 0	70 00	00 00	00 0	101 0	00 00	72 00	00 12	44 4									
77PBL3-2 / FSTA WFOH AA																				

HAYES-DANA
1988

77PBL3-1 / FSTA WFOH AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
-------------------------	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

CONFIDENTIAL

TI-NHTSA 010880

1991	77PBL3-W/F2AC/SPEN AA	8	0	8	0	0	8	8	59	1520	489	1499	89
1994	77PBL3-W/F2AC/SPEN AA	88	88	88	88	48	48	8	0	0	0	0	0
SPECIFIC CHANGE 1995	77PBL3-3 / F2A/SPEN AA	0	0	6	0	0	0.238	8	8	874	0	0	0
1997	77PBL3-2 / F2A/SPEN AA	0	0	0.238	0	0	0	0.238	0	0.238	8	0.478	0.238
1999	77PBL3-3 / F2A/SPEN AA	0	0	0	0	0	8	8	8	0.238	0.238	0	0
MILITARY INDUSTRIAL 1999	77PBL3-W/F2AC/SPEN AA 77PBL3-3 / F2TA/SPEN CA	0	0	0	818	145	886	143	1281	523	1832	28	84
1997	77PBL3-3 / F2TA/SPEN CA 77PBL3-W/F2AC/SPEN AA 77PBL3-1 / F2AC/SPEN AB	789	0	21	28	0	0	28	33	0	148	0	0
1994	77PBL3-3 / F2TA/SPEN CA 77PBL3-W/F2AC/SPEN AA 77PBL3-1 / F2AC/SPEN AB	8	8.32	8.32	184	57	57	8.56	1475	737	0	0	118
1994	77PBL3-3 / F2TA/SPEN CA 77PBL3-W/F2AC/SPEN AA 77PBL3-1 / F2AC/SPEN AB	0	118	214	0.238	8	0	0	0	8	0	0	0
BOCH BRAND 1995	77PBL3-W/F2AC/SPEN AA 77PBL3-3 / F2TA/SPEN CA	0	8	8	0	0	0	0	0	0	0	21.42	2284
1997	77PBL3-W/F2AC/SPEN AA 77PBL3-3 / F2TA/SPEN CA	157	160	165	1858	157	214	858	428	428	0	0	0
1998	77PBL3-W/F2AC/SPEN AA 77PBL3-3 / F2TA/SPEN CA	88.4	83.8	87.12	5378	28.4	4888	2352	38.8	80.4	87.1	83.78	88.4
1998	77PBL3-W/F2AC/SPEN AA 77PBL3-3 / F2TA/SPEN CA	88.4	88.4	87.12	83.8	47	87.8	47	58.4	83.86	88.84	83.7	88.8

CONFIDENTIAL

TI-NHTSA 016861

Epstein, Sally

From: Steve Reimers [sreimers@ford.com]
Sent: Thursday, April 01, 1999 3:34 PM
To: McGuirk, Andy; Porter, F.J.
Subject: Materials Recommendations for Flammability Issue

fyi

Steve Reimers building 5 3E008
RVT Chassis R/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from PAPCSRHU--EXTERNAL 04/01/99 16:09 ***
To: OSTEVEN1--FORD@MTP SREIMERS--FORD@MAIL
cc: O2K07WKT--EXTERNAL Michael J Bauhof

From: Paul J Kane
Subject: Materials Recommendations for Flammability Issue

From: "Paul J Kane" <Paul.J.Kane@USA.dupont.com>
cc: "Michael J Bauhof" <Michael.J.Bauhof@USA.dupont.com>

Greg, I recommend the Zenite 6140L (used at Ford in a wiper motor to solve similar concern where high surgeage going through when motor was in stall torque condition). The DuPont Zenite LCP is a liquid crystal polymer that is V-0 (flame retardant) down to .031 inch thickness and has a melt point of 635F. The Celanex PBT grades have a melt point of 431F and the Noryl GTX 830 which is just a nylon alloy has a melt point of 497 F.

My experience is that in these situations, going to higher melt point is the only hope for solving it from a polymer standpoint.

The other material I recommended is Eytel HTW FR52G10BL which has a melt point of 590 F and is flame retardant. This would be lower cost resin.

I have fax'd data sheet to you and we can rush samples to TI for molding if you want, Paul Kane.....248-583-8107

Epstein, Sally

From: Werner, Pam [pwerner@email.mc.tl.com]
Sent: Wednesday, April 07, 1999 8:48 AM
To: 'porter@ford.com'
Cc: McGuirk, Andy
Subject: ford.xls



ford.xls

Fred,
Please give Andy McGuirk a copy of this spreadsheet when you see him today.
Thank you.

<<fordt1.xls>>

TI-NHTSA 016853

77PS-Related Items

Event No.	Rev. No.	DATE of ECH	Dist. Wrt.	VALUE INFORMATION	Origin (Type)	FORM NO.	ITPS	Qty. (Rev. No.)	Material
1	A	First Issue 5 Nov 60	Flight	Replaced Ext 3423-48 dated 052040 Callout 4388	Steno Officer	F24C-8P24-AB F24C-8P24-AA	77PBL 2-1 77PBL 2-3	2 (Rev. #2) 1 (Block #1)	Callout 4388 Callout 4388
2	B	8 Jan 61	Flight	Callout 4388 CM 10087 Connectivity print 4800	Steno Officer	F24C-8P24-AB F24C-8P24-AA	77PBL 3-1 77PBL 3-2	2 (Block #2) 1 (Block #1)	Callout 4388 Callout 4388
3	C	6 May 62	Flight	Added (-3) OE Meryl GTX 830 CRM 8888	Steno Officer	F24C-8P24-AA F24C-8P24-AA F24C-8P24-AA	77PBL 1-1 77PBL 1-1 77PBL 2-2	3 (Block #2) 3 (Block #2) 3 (Block #2)	OE Meryl GTX 830 OE Meryl GTX 830 OE Meryl GTX 830
4	D	21 May 62	Flight	Added (-4 through -8) CRM 88128 (-4, -7) OE Meryl GTX 830 (-5, -6, -8, -9) Callout 4388	Steno Officer	F24C-8P24-AB F24C-8P24-AB F24C-8P24-AA F24C-8P24-AA F24C-8P24-AA F24C-8P24-AA	77PBL 3-1 77PBL 2-1 77PBL 3-3 77PBL 3-3 8PBL 2-2 8PBL 3-3 8PBL 11-2	3 (Block #2) 2 (Block #2) 3 (Block #2) 7 (Block #1) 8 (Block #1) 8 (Block #1) 4 (Block #1)	OE Meryl GTX 830 Callout 4388 OE Meryl GTX 830 OE Meryl GTX 830 Callout 4388 Callout 4388 OE Meryl GTX 830
5	E	9 Jul 62	Flight	Added - 10 (OE Meryl GTX 830) CRM 88881	Steno Officer	F24C-8P24-AA	77PBL 3-2	10 (all gray #1)	OE Meryl GTX 830
6	F	29 Dec 63	Flight	Changed dimensions CRM 10018	Auto Release				
7	D	1 May 64	Control	Ext added COC note CRM 26287	CRM Wagner				
8	H	20 May 64	Control	Web 4 Revised van 80% CRM 26887	Chris Wagner				
9	J	13 Jan 67	CAD	Added 2 units dia Added note CRM 26887 CRM 26884	DI No				
10	K	16 Dec 67	CAD	Change the phone Revised 48-88 degree change, CRM 26288	DI No				
11	L	28 Feb 68	CAD	Change 688-688 change to 688-028 CRM 26287	DI No				
12	M	1 Apr 68	CAD	Added -11 blocks OE Meryl GTX 830 CRM 26886	DI No	JWR2-2P24-AA	8PBL 2-2	11 (Block #1)	OE Meryl GTX 830
13	N	6 May 68	CAD	Added 12 blocks Callout 4388 CRM 26038	DI No	ABPCB	8PBL 2-2	12 (Block #1)	Callout 4388

CONFIDENTIAL

TI-NHTSA 016864

Epstein, Sally

From: Pawlowski, Robin [rpawlowsk@ama.lmc.1.com]
Sent: Wednesday, April 07, 1999 1:44 PM
To: 'FPORTER@FORD.COM'
Co: Douglas, Charles; McGuirk, Andy
Subject: ANDY.xls



ANDY.xls

<<ANDY.XLS>>

Item	Code	Quantity	Description	Unit	Price	Total
1	H	10000	Hand Saw/10000 CPN 2000			
2	J	10000	10000 Saw/10000 CPN 2000			
3	K	10000	10000 Saw/10000 CPN 2000			
4	L	10000	10000 Saw/10000 CPN 2000			
5	M	10000	10000 Saw/10000 CPN 2000			
6	N	10000	10000 Saw/10000 CPN 2000			
7	O	10000	10000 Saw/10000 CPN 2000			
8	P	10000	10000 Saw/10000 CPN 2000			
9	Q	10000	10000 Saw/10000 CPN 2000			
10	R	10000	10000 Saw/10000 CPN 2000			
11	S	10000	10000 Saw/10000 CPN 2000			
12	T	10000	10000 Saw/10000 CPN 2000			
13	U	10000	10000 Saw/10000 CPN 2000			
14	V	10000	10000 Saw/10000 CPN 2000			
15	W	10000	10000 Saw/10000 CPN 2000			
16	X	10000	10000 Saw/10000 CPN 2000			
17	Y	10000	10000 Saw/10000 CPN 2000			
18	Z	10000	10000 Saw/10000 CPN 2000			

TI-NHTSA 016859

77PS-Molded Base

Entry No.	Rev. No.	ATE of ECN	Dwg Size	VALUE IMP Design Engr	FORD P/N	TI P/N	PN 4651E-xMaterial
1	A	First Issue 9-Nov-90	Aegle	Replaced EX Steve Offiler dated 08/28/90 Cellanex 4300	F2VC-9F92477P8L2-1 F6LC-9F92477P8L2-3		2 (brown, #2) Cellanex 4300 1 (black, #1) Cellanex 4300
2	B	8-Jan-91	Aegle	Cellanex 430 Steve Offiler CN 188897 Correct/clarify print views	F2VC-9F92477P8L2-1 F6LC-9F92477P8L2-3		2 (brown, #2) Cellanex 4300 1 (black #1) Cellanex 4300
3	C	4-May-92	Aegle	Added (-3) Steve Offiler GE Noryl GTX 830 CRM 06968	F2AC-9F92477P8L3-1 84DA-9F92477P8L4-1 F3DC-9F92477P8L5-2		3 (natural #2) GE Noryl GTX 830 3 (natural #2) GE Noryl GTX 830 3 (natural #2) GE Noryl GTX 830
4	D	21-May-92	Aegle	Added (-4 th Steve Offiler CRM 09128 (-4, -7) GE Noryl GTX 83 (-5, -6, -8, -9) Cellanex 430	F2AC-9F92477P8L3-1 F2VC-9F92477P8L2-1 F3DC-9F92477P8L5-2 F3TA-9F92477P8L3-3 F37A-3N82467P8L2-2 F37A-3N82467P8L2-3 84BP-3N82467P8L11-2		3 (natural #2) GE Noryl GTX 830 2 (brown #2) Cellanex 4300 3 (natural #2) GE Noryl GTX 830 7 (red, #1) GE Noryl GTX 830 8 (gray #1) Cellanex 4300 8 (gray #1) Cellanex 4300 8 (green #1) GE Noryl GTX 830
5	E	9-Jul-92	Aegle	Added -10 Steve Offiler (GE Noryl GTX 830) CRM 09881	F68A-9F92477P8L3-2		10 (dk gray #3) GE Noryl GTX 830
6	F	29-Dec-93	Aegle	Clarified dim ziz Rahman CRM 18919			
7	G	1-May-96	Cadras	Dim added Chris Wagner CRM 28757			
8	H	20-May-96	Cadras	Note 4 Chris Wagner Regrind was 50% CRM 29057			
9	J	13-Jan-97	CAD	Adjust 3 note DI Ha Added note CAD drwg CRM 32804			
10	K	18-Dec-97	CAD	Change dim DI Ha Remove 46-56 degree chamfer, CRM 38285			
11	L	23-Feb-98	CAD	Change .085 DI Ha chamfer to .030/.020 CRM 39157			
12	M	1-Apr-98	CAD	Added -11 M DI Ha GE Noryl GTX 830 CRM 39985	XW43-3N8287P8L2-5		11 (brown #1) GE Noryl GTX 830
13	N	6-May-98	CAD	Added 12 Ha DI Ha Cellanex 4300 ECN M40638	A50520	87P8L2-5	12 (white #1) Cellanex 4300



**TEXAS
INSTRUMENTS**

Faxed
9:55
April 7, 1999

FACSIMILE TRANSMITTAL

TO: **Name:** **Fred Porter**

Location: **Ford**

Phone Number: **(313) 845-3723**

FAX Number: **(313) 390-4145**

FROM: **Sean P. Mulligan**
 Mechanical Design
 Precision Controls

TEXAS INSTRUMENTS MS 12-29

Phone Number: **(508) 236-2535**

FAX Number: **(508) 236-3586**

Total number of pages (including header page): 2

COMMENTS: **Fred,**
 Please find an updated schematic of the proposed test circuit included on page (2) of this fax. This schematic includes Ford relay P/N F0AB-14B192-AA. Please phone me after you review the schematic.

Thank you,

Sean Mulligan



**TEXAS
INSTRUMENTS**

Faxed 11:15
April 6, 1999

FACSIMILE TRANSMITTAL

TO: Name: Fred Porter
Location: Ford
Phone Number: (313) 845-3722
FAX Number: (313) 390-4145

FROM: Sean P. Mulligan
Mechanical Design
Precision Controls
TEXAS INSTRUMENTS MS 12-29
Phone Number: (508) 236-2535
FAX Number: (508) 236-3586

Total number of pages (including header page): 2

COMMENTS: Fred,
Please find included with this cover sheet, a drawing of the proposed test circuit for use with a relay. The current supply will be limited to 0.2 Amps. Per our phone conversation, I will contact you at 2:30 (your time) to discuss the proposed test circuit.


Thank you,
Sean P. Mulligan
Sean P. Mulligan

TEXAS INSTRUMENTS INCORPORATED • PO BOX 2964 • 34 FOREST STREET • ATTLEBORO, MA 02763

TI-NHTSA 016861

TI Test Circuit

Current limited to 0.2 Amps





**TEXAS
INSTRUMENTS**

Faird
10:00
April 7, 1999

FACSIMILE TRANSMITTAL

TO: Name: Fred Porter

Location: Ford

Phone Number: (313) 845-3722

FAX Number: (313) 390-4145

FROM: Sean P. Mulligan
Mechanical Design
Precision Controls

TEXAS INSTRUMENTS MS 12-29

Phone Number: (508) 234-2535

FAX Number: (508) 234-3586

Total number of pages (including header page): 3

COMMENTS: Fred,
Please find an updated schematic of the proposed test circuit included on page (2) of this fax. This schematic includes Ford relay P/N F0AB-14B192-AA. Please phone me after you review the schematic. Page (3) shows how this relay may be used in Ford application.


Thank you,

Sean Mulligan

TEXAS INSTRUMENTS INCORPORATED * PO BOX 2964 * 34 FOREST STREET * ATTLEBORO, MA 02783

TI-NHTSA 016863


TI Test Setup



(2)

77PS Proposed Wiring Schematic

14 Volts DC



(W)

Epstein, Sally

From: Roy, Norman [nroy@email.mc.ti.com]
Sent: Thursday, April 08, 1999 8:09 AM
To: McGuirk, Andy
Subject: FW: Materials Recommendations for Flammability Issue

Andy,

Attached is the reply from Ticona regarding material pedigree with additional info regarding effect of colorants. The current runnerless system in the 46515 mold uses heat pipe technology that is not recommended for LCP materials. We are also getting an answer on its compatability with the Zytel material.

Regards,

Norm

From: Dunn, Kevin
Sent: Tuesday, April 06, 1999 9:52 AM
To: Roy, Norman
Subject: FW: Materials Recommendations for Flammability Issue

From: kprice@ticona.com[SMTF:kprice@ticona.com]
Sent: Tuesday, April 06, 1999 9:45 AM
To: kdunn@email.mc.ti.com
Cc: rfyurachek@ticona.com
Subject: RE: Materials Recommendations for Flammability Issue

Mr. Dunn,

The samples sent to you labeled as Celanex 3316 were in fact Celanex 3316. A non-technical test, such as exposing a sample to a simple kitchen match under non-controlled conditions, will yield misleading results. The UL-94 flammability tests are very specific in nature. Items which must be carefully controlled include sample orientation (vertical or horizontal), sample size and thickness, burner size and regulator, type of gas used to supply burner, flame height, temperature and relative humidity. The time that the flame is applied and the relative orientation of the flame to the specimen are also carefully controlled.

I can send you a copy of the procedure, but in order to perform the test properly, you must have the right equipment. If you want a copy, please provide your fax number.

The tensile bar probably behaved better because it was thicker. Colorants can have an effect on the flammability. We have pre-colored materials which have been rated in the UL-94 test. For example, Celanex 3316 natural is rated V-0 down to 0.38 mm thickness, while all other colors are rated V-0 down to 0.75 mm thickness. The natural material is more robust in its flame retardancy.

Celanex 3316 has been successfully used in hot runner systems.

Ken Price

-----Original Message-----

From: Yurachek, Robert, TP/US
Sent: Tuesday, April 06, 1999 12:55 AM
To: Price, Kenneth, TP/US
Subject: FW: Materials Recommendations for Flammability Issue
Importance: High

Ken:

Please contact Kevin and respond to his request. Thanks and please copy me.

Bob

-----Original Message-----

From: Dunn, Kevin [mailto:kdunn@email.mc.ti.com]
Sent: Monday, April 05, 1999 2:52 PM
To: rfyurachek@ticona.com
Subject: FW: Materials Recommendations for Flammability Issue

Hi Bob, Would you please verify that the test bars were 3316 material. Also please check for alternatives.

As you can see, things are getting more attention at the customer.

Kevin

From: Roy, Norman
Sent: Monday, April 05, 1999 9:00 AM
To: Dunn, Kevin
Subject: FW: Materials Recommendations for Flammability Issue

Kevin,

Would you please follow-up with Ticona to insure the sample of Celanex 3316 was indeed that. Also would adding colorant reduce the V-0 flammability rating of the sample Ticona submitted. Feedback from our customer is that the 3316 was no better than the 4300 material when subjected to a non-technical type of flammability test, i.e., "the kitchen match test". However, it was reported that the tensile bars behaved better.

The customer is now getting input to move to a higher melt temperature material such as an LCP that would, in addition to a V-0 rating, provide the flammability resistance they need. Another material being suggested is Dupont Zytel HTM FR52G30BL which is lower cost. Does Ticona have any recommendations keeping in mind that the mold is equipped with a Kona hot runner system?

Please get a response from Ticona on these questions ASAP.

Regards,

Norm

From: McGuirk, Andy
Sent: Thursday, April 01, 1999 5:44 PM
To: Porter, F.J.; 'Steve Reimers'
Cc: Roy, Norman; Dague, Bryan
Subject: RE: Materials Recommendations for Flammability Issue

Steve, got your voice mail and did act upon it.

norm roy is our in-house plastic molding coordinator and has initiated considerations of various plastics. our first concern was 'knit line' integrity of the LCP which might create a mechanical weakness issue. alternates were being reviewed.

also, norm was going to review our celenax 3316 pedigree to assure it was what it should have been as it 'acted' too similar to 4300.

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@email.mo.il.com]
Sent: Thursday, April 08, 1999 10:37 AM
To: 'Frederick J. Porter'
Subject: Materials Recommendations for Flammability Issue

Importance: High

PER MY TELECON

SEVERAL POINTS.....

THE 3316 SAMPLES WERE 3316.

THE 'SIMPLE TEST' WE HAVE USED WITH A KITCHEN MATCH IS NOT 'SANCTIONED' AS A TEST..(but seems to be a pretty good indicator)

COLORANTS ARE KNOWN TO AFFECT FLAMMABILITY

STEVE REIMERS HAD OFFERED TO OBTAIN SOME Dupont Zytel WFN FR52G30BL
.....CAN WE GET SOME AHEAD TO SAMPLE IN OUR MOLD ?

SHOULD I GET IT HERE?

A
AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 504-2044

From: Roy, Norman
Sent: Thursday, April 08, 1999 9:09 AM
To: McGuirk, Andy
Subject: FW: Materials Recommendations for Flammability Issue

Andy,

Attached is the reply from Ticona regarding material pedigree with additional info regarding effect of colorants. The current runnerless system in the 46S15 mold uses heat pipe technology that is not recommended for LCP materials. We are also getting an answer on its compatability with the Zytel material.

Regards,

Norm

From: Dunn, Kevin
Sent: Tuesday, April 06, 1999 9:52 AM
To: Roy, Norman
Subject: FW: Materials Recommendations for Flammability issue

From: kprice@ticona.com(SMTP:kprice@ticona.com)
Sent: Tuesday, April 06, 1999 9:45 AM
To: kdunn@email.mc.ti.com
Cc: rfyurachek@ticona.com
Subject: RE: Materials Recommendations for Flammability issue

Mr. Dunn,

The samples sent to you labeled as Celanex 3316 were in fact Celanex 3316. A non-technical test, such as exposing a sample to a simple kitchen match under non-controlled conditions, will yield misleading results. The UL-94 flammability tests are very specific in nature. Items which must be carefully controlled include sample orientation (vertical or horizontal), sample size and thickness, burner size and regulator, type of gas used to supply burner, flame height, temperature and relative humidity. The time that the flame is applied and the relative orientation of the flame to the specimen are also carefully controlled.

I can send you a copy of the procedure, but in order to perform the test properly, you must have the right equipment. If you want a copy, please provide your fax number.

The tensile bar probably behaved better because it was thicker. Colorants can have an effect on the flammability. We have pre-colored materials which have been rated in the UL-94 test. For example, Celanex 3316 natural is rated V-0 down to 0.38 mm thickness, while all other colors are rated V-0 down to 0.75 mm thickness. The natural material is more robust in its flame retardancy.

Celanex 3316 has been successfully used in hot runner systems.

Ken Price

-----Original Message-----
From: Yurachek, Robert, TP/US
Sent: Tuesday, April 06, 1999 12:55 AM
To: Price, Kenneth, TP/US
Subject: FW: Materials Recommendations for Flammability issue
Importance: High

Ken:

Please contact Kevin and respond to his request. Thanks and please copy me.

Bob

-----Original Message-----
From: Dunn, Kevin [mailto:kdunn@email.mc.ti.com]
Sent: Monday, April 05, 1999 2:52 PM
To: rfyurachek@ticona.com

Subject: FW: Materials Recommendations for Flammability issue

Hi Bob, Would you please verify that the test bars were 3316 material. Also please check for alternatives.

As you can see, things are getting more attention at the customer.

Kevin

From: Roy, Norman
Sent: Monday, April 05, 1999 9:00 AM
To: Dunn, Kevin
Subject: FW: Materials Recommendations for Flammability issue

Kevin,

Would you please follow-up with Ticona to insure the sample of Celanex 3316 was indeed that. Also would adding colorant reduce the V-0 flammability rating of the sample Ticona submitted. Feedback from our customer is that the 3316 was no better than the 4300 material when subjected to a non-technical type of flammability test, i.e., "the Kitchen match test". However, it was reported that the tensile bars behaved better.

The customer is now getting input to move to a higher melt temperature material such as an LCP that would, in addition to a V-0 rating, provide the flammability resistance they need. Another material being suggested is Dupont Zytel HTN FR52G30BL which is lower cost. Does Ticona have any recommendations keeping in mind that the mold is equipped with a Kona hot runner system?

Please get a response from Ticona on these questions ASAP.

Regards,

NORM

From: McGuirk, Andy
Sent: Thursday, April 01, 1999 5:44 PM
To: Porter, F.J.; 'Steve Reimers'
Cc: Roy, Norman; Dague, Bryan
Subject: RE: Materials Recommendations for Flammability issue

Steve, got your voice mail and did act upon it.

norm roy is our in-house plastic molding coordinator and has initiated considerations of various plastics. our first concern was 'knit line' integrity of the LCP which might create a mechanical weakness issue.

alternates were being reviewed.

also, norm was going to review our celenz 3316 pedigree to assure
it was what it should have been as it 'acted' too similar to 4300.

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@email.mc.tl.com]
Sent: Thursday, April 08, 1999 12:32 PM
To: 'Frederick J. Porter'
Subject: SUPPLY CHAIN MANAGEMENT

FRED, I BELIEVE WE WILL SEE THAT ALL PRESSURE SWITCHES FOR THE TOWN CAR PLATFORM TRAVELED THROUGH HILITE INDUSTRIES (PITTS/MAFCO/SURFACES & HILITE) IN TEXAS FOR ASSEMBLY INTO THE PROP VALVE. HAVE YOU HAD DIALOGUE WITH THEM ABOUT PROCESS AND TEST PROTOCOL AND SPECIFICS ABOUT CLEANING OF THE PROP VALVE AND RINSE REGARDING FLUIDS AND RESIDUES ? IS THERE A CHANCE THAT SOME OF THOSE FLUIDS DRIP OUT OF A PROP VALVE AND INTO ELECTRIC SWITCH WHEN THEY ARE MOUNTING/PACKING THE VALVE ?? THERE JUST MIGHT BE A DISTINCTION SOMEWHERE IN THERE THAT HELPS FOCUS.

MEDHAT HABASHI IS THE QUALITY MANAGER THERE AT CARROLLTON, TX AT (972) 242-3432.

MEDHAT AND I HAVE WORKED SEVERAL PRODUCT ISSUES OVER THE YEARS AND WE KNOW EACH OTHER.

A
AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST N/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

TI-NHTSA 016873

Epstein, Sally

From: Steve Reimers (sreimers@ford.com)
Sent: Thursday, April 08, 1999 12:51 PM
To: Porter, F.J.; McGuirk, Andy
Subject: Materials Recommendations for Flammability issue

I have asked Paul Kane at Dupont to send a sample of Zytel to TI, Gerry Torino

....

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 />
*** Forwarding note from FPORTER --DRBN007 04/08/99 12:47 ***
To: SREIMERS--DRBN007

FROM: F. J. Porter USAET(UTC -04:00)
Subject: Materials Recommendations for Flammability issue

Please get the material that Andy asked for.

Regards,
Fred Porter OV - fporter fporter@ford.com
Chassis E/E Systems Applications (313)845-3722
Bldg 5 - Mail Drop 5030 - Cubicle 3E004 fax: 390-4145
*** Forwarding note from PIR43P4A--EXTERNAL 04/08/99 11:48 ***
To: FPORTER --FORDMAIL 'Frederick J. Port

From: McGuirk, Andy
Subject: Materials Recommendations for Flammability issue

From: "McGuirk, Andy"<a-mcguirk@email.mc.ti.com>

PER MY TELECON

SEVERAL POINTS.....

THE 3316 SAMPLES WERE 3316.

THE 'SIMPLE TEST' WE HAVE USED WITH A KITCHEN MATCH IS NOT 'SANCTIONED' AS A TEST..(but seems to be a pretty good indicator)

COLORANTS ARE KNOWN TO AFFECT FLAMMABILITY

STEVE REIMERS HAD OFFERED TO OBTAIN SOME Dupont Zytel NTN FR52G308L
.....CAN WE GET SOME ASAP TO SAMPLE IN OUR MOLD ?

SHOULD I GET IT HERE?

A
AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST N/S 23-05
ATTEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Roy, Norman
Sent: Thursday, April 08, 1999 9:09 AM
To: McGuirk, Andy
Subject: FW: Materials Recommendations for Flammability issue

Andy,

Attached is the reply from Ticona regarding material pedigree with additional info regarding effect of colorants. The current runnerless system in the 46515 mold uses heat pipe technology that is not recommended for LCP materials. We are also getting an answer on its compatability with the Zytel material.

Regards,

Norm

From: Dunn, Kevin
Sent: Tuesday, April 06, 1999 9:52 AM
To: Roy, Norman
Subject: FW: Materials Recommendations for Flammability issue

From: kprice@ticona.com[SMTP:kprice@ticona.com]
Sent: Tuesday, April 06, 1999 9:45 AM
To: kdunn@email.nc.ti.com
Cc: rfyurachek@ticona.com
Subject: RE: Materials Recommendations for Flammability Issue

Mr. Dunn,

The samples sent to you labeled as Celanex 3316 were in fact Celanex 3315. A non-technical test, such as exposing a sample to a simple kitchen match under non-controlled conditions, will yield misleading results. The UL-94 flammability tests are very specific in nature. Items which must be carefully controlled include sample orientation (vertical or horizontal), sample size and thickness, burner size and regulator, type of gas used to supply burner, flame height, temperature and relative humidity. The time that the flame is applied and the relative orientation of the flame to the specimen are also carefully controlled.

I can send you a copy of the procedure, but in order to perform the test properly, you must have the right equipment. If you want a copy, please provide your fax number.

The tensile bar probably behaved better because it was thicker. Colorants can have an effect on the flammability. We have pre-colored materials which have been rated in the UL-94 test. For example, Celanex 3316 natural is rated V-0 down to 0.38 mm thickness, while all other colors are rated V-0 down to 0.75 mm thickness. The natural material is more robust in its flame

redundancy.

Celanex 3316 has been successfully used in hot runner systems.

Ken Price

-----Original Message-----

From: Yurachek, Robert, TP/US
Sent: Tuesday, April 06, 1999 12:53 AM
To: Price, Kenneth, TP/US
Subject: FW: Materials Recommendations for Flammability issue
Importance: High

Ken:

Please contact Kevin and respond to his request. Thanks and please copy me.

Bob

-----Original Message-----

From: Dunn, Kevin [mailto:kdunn@gmail.mc.ti.com]
Sent: Monday, April 05, 1999 2:52 PM
To: rfyurachek@ticona.com
Subject: FW: Materials Recommendations for Flammability issue

Hi Bob, Would you please verify that the test bars were 3316 material. Also please check for alternatives.

As you can see, things are getting more attention at the customer.

Kevin

From: Roy, Norman
Sent: Monday, April 05, 1999 9:00 AM
To: Dunn, Kevin
Subject: FW: Materials Recommendations for Flammability issue

Kevin,

Would you please follow-up with Ticona to insure the sample of Celanex 3316 was indeed that. Also would adding colorant reduce the V-0 flammability rating of the sample Ticona submitted. Feedback from our customer is that the 3316 was no better than the 4300 material when subjected to a non-technical type of flammability test, i.e., "the kitchen match test". However, it was reported that the tensile bars behaved better.

The customer is now getting input to move to a higher melt temperature material such as an LCP that would, in addition to a V-0 rating, provide the flammability resistance they need. Another material being suggested is Dupont Zytel RTM FR52G30BL which is lower cost. Does Ticona have any recommendations keeping in mind that the mold is equipped with a Kona hot runner system?

Please get a response from Ticona on these questions ASAP.

Regards,

NORM

From: McGuirk, Andy
Sent: Thursday, April 01, 1999 5:44 PM
To: Porter, F.J.; 'Steve Reimers'
Cc: Roy, Norman; Dague, Bryan
Subject: RE: Materials Recommendations for Flammability issue

Steve, got your voice mail and did act upon it.

norm roy is our in-house plastic molding coordinator and has initiated considerations of various plastics. our first concern was 'knit line' integrity of the LCP which might create a mechanical weakness issue. alternates were being reviewed.

also, norm was going to review our calenex 3316 pedigree to assure it was what it should have been as it 'acted' too similar to 4300.

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Friday, April 09, 1999 1:28 PM
To: Roy, Norman
Cc: Pechonis, John; Beringhouse, Steven
Subject: FW: Zytel Sample to TI

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Paul J Kane[SMTP:Paul.J.Kane@USA.dupont.com]
Sent: Friday, April 09, 1999 12:34 PM
To: Steve Reimers
Cc: A-mcguirk@ti.com; swalters@ti.com
Subject: Re: Zytel Sample to TI

The V-0(flame retardant) high temperature Zytel HTN FR52G30BL NC010 (natural color) will arrive at TI on Monday April 12. I talked with Andy McGuirk and Steve Walters (molding responsibility) about this product and have fax'd the processing guidelines to Steve. This product will have a 160F higher melt point over the Calanex 4300 and a 100F higher melt point over the Noryl GTX 830 (a nylon alloy). It will also have much better flow and dimensional stability over the Noryl GTX 830. Paul 248-583-8107

Epstein, Sally

From: Hopkins, AL [ahopkins@aol.com]
Sent: Tuesday, April 13, 1999 3:16 PM
To: McGuirk, Andy
Subject: Fax to Ford



Ford Letter.doc

Andy, here is the cover sheet that I was going to fax to Ford with the data.
How does it look?

<<Ford Letter.doc>>

AL

simile transmittal

To: **Rock Carter** Fax: **313-621-0646**

From: **Al Hopkins (Texas Instruments)** Date: **07/12/99**

Re: **SEM-EDS Data Collected at TI** Pages: **This Cover Sheet & 41 Pages of Data**

CC: **[Click here and type name]**

Urgent For Review Please Comment Please Reply Please Recycle

First, this data was accumulated while Ford Engineering was present. They took copies of this data and all the actual parts of the sample. They had, however, left the small amounts of debris for our Chem Lab to perform FTIR analysis to check if there was brake fluid present. In fact, the FTIR analysis showed that this was the case.

As you know, we subsequently were requested to send this small amount of debris (wrapped in aluminum foil) back to Ford. I would think that it would be much more useful to examine the actual vehicle itself.

In any case, this is the key to the data. I am going to try to e-mail you the photos electronically tomorrow. If you have any questions, feel free to call me at 908-296-3541.

<u>Sample</u>	<u>Pages</u>	<u>Photos</u>	<u>Spectra</u>
Top Surf of Cup After Degreasing	1-14	01-05	001-009
Terminal Cavity after Disassembly	15-28	06-15	010-013
"A" - Black Flake from Trough	29-31	20	020-021
"B" - Material Scraped from Cup Assembly	32-37	21	022-026
"C" - Green Material on Cup	38-41	22	027-029

Regards,

Al

Hopkins, AL

From: Hopkins, AL
Sent: Wednesday, April 14, 1999 9:48 AM
To: FORD- Rock Carter
Subject: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Rock,

This is the text of the FAX that I sent you yesterday. The Fax was acting up yesterday so I had to send it in three separate pieces. You should have pages 1-41.

Rock, this data was accumulated while Ford Engineering was present. They took copies of this data and all the actual parts of the sample. They had, however, left the small amounts of debris for our Chem Lab to perform FTIR analysis to check if there was brake fluid present. In fact, the FTIR analysis showed that this was the case.

As you know, we subsequently were requested to send this small amount of debris (wrapped in aluminum foil) back to Ford. I would think that it would be much more useful to examine the actual switch itself.

In any case, this is the key to the data. I am going to try to E-mail you the photos electronically tomorrow. If you have any questions, feel free to call me at 508-236-3040.

<u>Sample</u>	<u>Pages</u>	<u>Photos</u>	<u>Spectra</u>
Top Surf of Cup After Degreasing	1-14	01-05	001-009
Terminal Cavity after Disassembly	15-28	06-15	010-013
"A" - Black Flake from Trough	29-31	20	020-021
"B" - Material Scraped from Cup Assembly	32-37	21	022-026
"C" - Green Material on Cup	38-41	22	027-029

The following images are Windows FCK bit maps. They don't have any annotation on them but you can probably read that off of the faxed copy. The last two digits on the file names are the photo numbers.

 dcpet_182708_01.pct	 dcpet_182708_02.pct	 dcpet_182708_03.pct	 dcpet_182708_04.pct	 dcpet_182708_05.pct	 dcpet_182708_06.pct
 dcpet_182708_07.pct	 dcpet_182708_08.pct	 dcpet_182708_09.pct	 dcpet_182708_10.pct	 dcpet_182708_11.pct	 dcpet_182708_12.pct
 dcpet_182708_13.pct	 dcpet_182708_14.pct	 dcpet_182708_15.pct	 dcpet_182708_16.pct	 dcpet_182708_17.pct	 dcpet_182708_18.pct

If you have any questions, feel free to call. There aren't many spectra from the Terminal Cavity After Disassembly

because I couldn't avoid shadowing without additional disassembly that Ford Engineering didn't want to do at the time.

Regards,

Al

Page 2

TI-NHTSA 016882

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Thursday, April 15, 1999 7:54 AM
To: Frederick J. Porter
Subject: FW: Electronic Image Versions of Photos that had been Faxed on 4/13/99

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 504-2044

From: Hopkins, Al
Sent: Thursday, April 15, 1999 8:46 AM
To: McGuirk, Andy
Subject: FW: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Here is Rock's response

From: Roscoe Carter[SMTP:rcarter@ford.com]
Sent: Thursday, April 15, 1999 8:37 AM
To: 'Hopkins, Al'
Subject: RE: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Al - Thanks for the pictures and the cooperation is great. The electronic pictures are much better than the faxed ones. Thanks again ROC FORD Research

From: Hopkins, Al[SMTP:ahopkins@email.mc.ti.com]
Sent: Wednesday, April 14, 1999 9:49 AM
To: FORD- Rock Carter
Subject: Electronic Image Versions of Photos that had been Faxed on 4/13/99

<<file: daque_150709_01.pcx>><<File: daque_150709_02.pcx>><<File: daque_150709_03.pcx>><<File: daque_150709_04.pcx>><<File: daque_150709_05.pcx>><<File: daque_150709_06.pcx>><<File: daque_150709_07.pcx>><<File: daque_150709_08.pcx>><<File: daque_150709_09.pcx>><<File: daque_150709_10.pcx>><<File: daque_150709_11.pcx>><<File: daque_150709_12.pcx>><<File: daque_150709_13.pcx>><<File: daque_150709_14.pcx>><<File: daque_150709_15.pcx>><<File: daque_150709_20.pcx>><<File: daque_150709_21.pcx>><<File: daque_150709_22.pcx>>Rock,

This is the text of the FAX that I sent you yesterday. The Fax was acting up yesterday so I had to send it in three separate pieces. You should have pages 1-41.

Rock, this data was accumulated while Ford Engineering was present. They took copies of this data and all the actual parts of the sample. They had, however, left the small amounts of debris for our Chem Lab to perform FT/IR analysis to check if there was brake fluid present. In fact, the FT/IR

analysis showed that this was the case.

As you know, we subsequently were requested to send this small amount of debris (wrapped in aluminum foil) back to Ford. I would think that it would be much more useful to examine the actual switch itself.

In any case, this is the key to the data. I am going to try to E-mail you the photos electronically tomorrow. If you have any questions, feel free to call me at 308-236-3040.

<<...>>

The following images are Windows PCX bit maps. They don't have any annotation on them but you can probably read that off of the faxed copy. The last two digits on the file names are the photo numbers.

<<daque_150709_01.pcx>> <<daque_150709_02.pcx>> <<daque_150709_03.pcx>>
<<daque_150709_04.pcx>> <<daque_150709_05.pcx>> <<daque_150709_06.pcx>>
<<daque_150709_07.pcx>> <<daque_150709_08.pcx>> <<daque_150709_09.pcx>>
<<daque_150709_10.pcx>> <<daque_150709_11.pcx>> <<daque_150709_12.pcx>>
<<daque_150709_13.pcx>> <<daque_150709_14.pcx>> <<daque_150709_15.pcx>>
<<daque_150709_20.pcx>> <<daque_150709_21.pcx>> <<daque_150709_22.pcx>>

If you have any questions, feel free to call. There aren't many spectra from the Terminal Cavity After Disassembly because I couldn't avoid shadowing without additional disassembly that Ford Engineering didn't want to do at the time.

Regards,

Al

Epstein, Sally

From: Hopkins, AL [ahopkins@email.mc.ti.com]
Sent: Thursday, April 15, 1999 7:47 AM
To: McGuirk, Andy
Subject: FW: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Here is Rock's response

From: Roscoe Carter[SMT:rcarter@ford.com]
Sent: Thursday, April 15, 1999 8:37 AM
To: 'Hopkins, AL'
Subject: RE: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Al - Thanks for the pictures and the cooperation is great. The electronic pictures are much better than the faxed ones. Thanks again ROC FORD Research

From: Hopkins, AL[SMT:ahopkins@email.mc.ti.com]
Sent: Wednesday, April 14, 1999 9:49 AM
To: FORD- Rock Carter
Subject: Electronic Image Versions of Photos that had been Faxed on 4/13/99

<<File: dague_150709_01.pcx>><<File: dague_150709_02.pcx>><<File: dague_150709_03.pcx>><<File: dague_150709_04.pcx>><<File: dague_150709_05.pcx>><<File: dague_150709_06.pcx>><<File: dague_150709_07.pcx>><<File: dague_150709_08.pcx>><<File: dague_150709_09.pcx>><<File: dague_150709_10.pcx>><<File: dague_150709_11.pcx>><<File: dague_150709_12.pcx>><<File: dague_150709_13.pcx>><<File: dague_150709_14.pcx>><<File: dague_150709_15.pcx>><<File: dague_150709_20.pcx>><<File: dague_150709_21.pcx>><<File: dague_150709_22.pcx>>Rock,

This is the text of the FAX that I sent you yesterday. The Fax was acting up yesterday so I had to send it in three separate pieces. You should have pages 1-41.

Rock, this data was accumulated while Ford Engineering was present. They took copies of this data and all the actual parts of the sample. They had, however, left the small amounts of debris for our Chem Lab to perform FT/IR analysis to check if there was brake fluid present. In fact, the FT/IR analysis showed that this was the case.

As you know, we subsequently were requested to send this small amount of debris (wrapped in aluminum foil) back to Ford. I would think that it would be much more useful to examine the actual switch itself.

In any case, this is the key to the data. I am going to try to E-mail you the photos electronically tomorrow. If you have any questions, feel free to call me at 508-236-3040.

<<...>>

The following images are Windows PCX bit maps. They don't have any

annotation on them but you can probably read that off of the faxed copy. The last two digits on the file names are the photo numbers.

<<dague_150709_01.pcx>> <<dague_150709_02.pcx>> <<dague_150709_03.pcx>>
<<dague_150709_04.pcx>> <<dague_150709_05.pcx>> <<dague_150709_06.pcx>>
<<dague_150709_07.pcx>> <<dague_150709_08.pcx>> <<dague_150709_09.pcx>>
<<dague_150709_10.pcx>> <<dague_150709_11.pcx>> <<dague_150709_12.pcx>>
<<dague_150709_13.pcx>> <<dague_150709_14.pcx>> <<dague_150709_15.pcx>>
<<dague_150709_20.pcx>> <<dague_150709_21.pcx>> <<dague_150709_22.pcx>>

If you have any questions, feel free to call. There aren't many spectra from the Terminal Cavity After Disassembly because I couldn't avoid shadowing without additional disassembly that Ford Engineering didn't want to do at the time.

Regards,

Al

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@email.mn.ti.com]
Sent: Thursday, April 15, 1999 7:56 AM
To: Frederick J. Porter
Subject: FW: ANDY.xls



FRED, THIS SHOULD BE A VERY CLEAR HISTORY OF THE '92-'97 P/S SHIP-TO HISTORY.....INCLUDING TYPE AND COLOR OF PLASTIC USED.

A

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN #04-2044

<<ANDY.xls>>

TI-NHTSA 016887

**DRAWINGS AVAILABLE UPON
REQUEST**

Carrey, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Friday, April 16, 1999 3:43 PM
To: 'Frederick J. Porter'
Subject: Launch/PPAP/SREA dates- Changes via SREA- Alerts



7798 SREA-ALERT
UPDATE.KLS

PER OUR TELECOM, THIS WAS AN 'OLD' FEH INVESTIGATION INTO CHANGES OF RECORD
IN THE 91-94 TIMEFRAME.

WE SAW NOTHING IN HERE OF 'SIGNIFICANCE' AS WE REVIEWED THE CHANGES OVER

A
AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

<<7798 SREA-ALERT UPDATE.KLS>>

77PS-SREA-ALERT UPDATE

Entry No.	SPR/AALERT No.	DATE SUBMITTED	VALUE IMPROVEMENT	FORD P.N.	TI-P.N.
1	40868	27-Feb-96	Use of alternate pressure laser for capacity improvement. Scribe mark indicating "test pass" to be on crimp ring rather than on the plastic connector base.	F2AC-8F824-AA F2VC-8F824-AB F3DC-8F824-AA F68A-8F824-AA F5TA-8F824-CA	77P8L3-1 77P8L2-1 77P8L3-2 77P8L3-2 77P8L3-3
2	40868	27-Feb-96	Use of 10L07 steel from cold headed supplier in lieu of 10L10 steel due to temporary material supply interruption. 10L07 steel ends with same process.	F2AC-8F824-AA F2VC-8F824-AB F3DC-8F824-AA F68A-8F824-AA F3TA-8F824-CA	77P8L3-1 77P8L3-1 77P8L3-2 77P8L3-2 77P8L3-3
3	409937	8-Sep-94	Change p.n. from p.n. 84DA-8F824AA to p.n. 84DA-8F824AB	84DA-8F824AB	77P8L4-1
4	408611	17-Mar-94	Use of color pigments in plastic base containing alternate material in lieu of heavy metal per governmental regulations	F5TA-8F824-CA	77P8L3-3
5	282442	22-Jan-93	Use of part submission of prior level "BA". Converting from snap to quick disconnect. Change is to internal disc only.	F3TA-8F824-CA	77P8L3-3
6	147683	2-Dec-92	Reduce internal cup diameter by .004" from .091" to .087" nominal. Address potential open circuit condition under vacuum, traced to disc envelope under back- up conditions	F2VC-8F824-AB F2AC-8F824-AA F3DC-8F824-AA	77P8L3-1 77P8L3-1 77P8L3-2
7	147678	21-Nov-91	Change thread gaging specification from 2A ga to 3A ga ring gage. Use of ANSI B1.1 Industry Standard for plated thread allowance.	F3TA-8F824-CA	77P8L3-3
8	147671	6-Nov-91	Use blue colored environmental seal in lieu of reddish color with black stripes to help differentiate seal; to reduce potential assembly errors.	F2VC-8F824-AB	77P8L3-1
9	149596	3-Apr-91	Change terminal position dimension from 0.80 \pm 0.20mm to 0.80 \pm 0.25mm	F2TA-8C886-AA	57P8L5-1
10	147688	3-Apr-91	Change terminal position dimension from 0.80 \pm 0.20mm to 0.80 \pm 0.25mm	F3TA-8F824-CA	77P8L3-3
11	Alert No. A10188193	11-Oct-91	Use of manually loaded sensor crimp machine vs auto in-line loaded crimper. Manual crimp passes 85 tests.	F2VC-8F824-AB	77P8L3-1

System: Self

From: Hall, Alison [a-hall@camail.nc.ti.com]
Sent: Wednesday, April 21, 1999 12:44 PM
To: Sharps, Robert
Subject: info from Barb Foster - Ford Service
Importance: High

Barb mentioned Ford Service requested 20k parts over the next 90 days of 7785L2-1 for a recall. Just a heads up in case you have not heard.

Regards

Alison
Alison N. Hall
Texas Instruments
Phone: 248-305-5709
Fax: 248-305-5734

Curry, Pat

From: McGuirk, Andy [a-mcguirk@email.ms.ti.com]
Sent: Sunday, April 25, 1999 11:55 AM
To: Mulligan, Sean
Subject: FW: Switch Log and Eval. Procedure



AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 FIN 604-2044

From: Rahman, Aziz
Sent: Thursday, February 18, 1999 1:45 PM
To: 'Fred Porter (Ford)'; 'Norm LaPointe (Ford)'; 'Steve LaBouche (Ford)'; 'Steve Reimers (Ford)'
Cc: Beringhouse, Steven; Dague, Bryan; Baumann, Russ; McGuirk, Andy; Sharpe, Robert
Subject: Switch Log and Eval. Procedure

Updated as of 2/18/99. There were some switches from the initial 24 switch survey that were opened up at AVT and the tag and switch parts were not kept together. I have noted this in the log.

Since the tag numbers for every incoming shipment start from 1, I suggest we use VIN numbers to track the database. This will uniquely identify the switch.

I suggest that the switch analysis priority be as follows:

- Switches from underhood fires, which have not been severely damaged
- Switches from Town Cars, starting by highest mileage and descending
- Switches from CV and GM, starting by highest mileage and descending
- Severely damaged switches from underhood fires
- Disassembled switches, with suspect paperwork trail

<<SwitchLog>>
Evaluation Procedure updated as of 2/18/99. Note identification of harness wires by color.

<<EVALPROC>>
I think we are closing in on finalizing the log format and the evaluation procedures. I believe that these are good enough for us to start using them for data entry.

In order to reduce confusion, I will plan on updating the log once a week. Please delete the earlier versions, so that you have only one latest copy.

Please comment.

Thanks
Aziz

**DRAWINGS AVAILABLE UPON
REQUEST**

Curry, Pat

From: McGuirk, Andy (a-mcguirk@email.mc.tl.com)
Sent: Sunday, April 25, 1999 11:55 AM
To: Mulligan, Sean
Subject: FW: Switch Evaluation Plan.xls



Brake Pressure Switch

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3880
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Rahman, Aziz
Sent: Thursday, February 18, 1999 10:21 AM
To: 'Fred Porter (Ford)'; 'Norm LaPointe (Ford)'; 'Steve LaRouche (Ford)'; 'Steve Reimers (Ford)'
Cc: Beringhaus, Steven; Deque, Bryan; Baumann, Russ; Sharpe, Robert; McGuirk, Andy
Subject: Switch Evaluation Plan.xls

<<Brake Pressure Switch Evaluation Plan.xls>>

Revised to include Switch dissection procedures.

Regards
Aziz.

Curry, Pat

From: McGuirk, Andy [a-mcguirk@email.mo.ti.com]
Sent: Friday, April 23, 1999 2:56 PM
To: Dague, Bryan; Mulligan, Sean
Cc: Beringhause, Steven
Subject: FW: Printable Ford Findings



Ford Findings.doc

I ASKED AL TO USE THIS AS A FRAME FOR HIS FEEDBACK REPORTS

A

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Hopkins, AL
Sent: Friday, April 23, 1999 1:11 PM
To: McGuirk, Andy
Subject: Printable Ford Findings

This prints out on a single sheet of paper. I had to remove VINS and Date Codes

<<Ford Findings.doc>>

Regards,

Al

Sample	Condition	Report, Weather, Coaxial, and Spacer	Seals	Cup	Base/Switch Cavity/Terminals
Reddick (Merriphel, 1993 Town Car)	Partially burned.	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on field and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. All three Kapton seals are buckled and exhibit brittle cracks which most likely formed leak path. Damage appears to have initiated in seal close to washer. Damaged Kapton fractured and embrittled by unknown mechanism.	Green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.	Base separated below crimp ring. Transfer pin and movable contact missing. Stationary contact exhibits loss of material due to corrosion, evidence of electrolysis, stress corrosion cracking. Base of movable contact melted back into bushhead between switch and terminal cavities. Appears to have occurred in later stages of event. Surfaces of terminals covered with black and green deposits which appear to be sulfur compounds of the terminal materials.
A (1993 Town Car, Houston)	Burned	Elements from contact material detected at fitting end of baseport. Indicate possible flow of fluid back through seals.	Gasket and environmental seal missing. Charred fragments Kapton seals remain.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
B (1992 Town Car, Houston)	Burned	Elements from contact material detected at fitting end of baseport. Indicate possible flow of fluid back through seals.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Transfer pin and movable contact missing. Stationary contact exhibits crack in similar location as that in Reddick sample.
C (1992 Town Car, Houston)	Burned	Elements from contact material detected at fitting end of baseport. Indicate possible flow of fluid back through seals. Black deposit in cavity currently being analyzed (possibly charred gasket).	Gasket appears charred. Environmental seal missing. Damage to Kapton seals currently being evaluated.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
D (1987 Crown Victoria)	Apparent leakage.	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on field and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid is interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Contacts appear intact. Dark green deposits on movable and stationary contacts contain elements from brass contact material. Terminals appear clean (no apparent deposits or corrosion).
E (F11 from survey)	No leaks or other apparent problems	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on field and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit deformation and buckling similar to that found in Reddick sample. Cracking on surfaces suggest incipient damage is occurring.	Face of cup appears clean and dry.	Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
F TI-001289	Apparent leakage	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on field and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid is interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Stationary contact is intact, but flow show stress corrosion cracking in progress in bridge area (same location as in Reddick switch). Movable contact appears to have separated as a result of loss of material (~30% of thickness) due to corrosion. No evidence of heating or arc damage. Dark green deposits on movable and stationary contacts contain elements from brass contact material, as well as sulfur. Terminals exhibit green deposits (currently being analyzed). Deposits extend in from both sides of bushhead between switch and terminal cavities, but do not meet.

Currey, Pat

From: McGuirk, Andy [a-mcguirk@small.mc.ti.com]
Sent: Monday, April 26, 1999 6:05 AM
To: Warner, Pam
Subject: FW: Printable Ford Findings



Ford Findings.doc

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Hopkins, Al
Sent: Friday, April 23, 1999 1:11 PM
To: McGuirk, Andy
Subject: Printable Ford Findings

This prints out on a single sheet of paper. I had to remove VINS and Data Codes

<<Ford Findings.doc>>

Regards,

Al

Sample	Condition	Washer, Washer, Coevaporator, and Spacer	Seals	Cup	Base/Switch Cavity/Terminals
Reddick (Memphis a, 1983 Town Car)	Partially burned.	Black residue containing glycol based material (probably brake fluid) and a metal oxide. Indicates presence of brake fluid on flint and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. All three Kapton seals are buckled and exhibit brittle cracks which most likely formed leak path. Damage appears to have initiated in seal closest to washer. Damaged Kapton deformed and embrittled by unknown mechanism.	Green Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.	Base separated below clamp ring. Transfer pin and movable contact missing. Stationary contact exhibits loss of material due to corrosion, evidence of electrocution, stress corrosion cracking. Base of movable contact melted back into bulkhead between switch and terminal cavities. Appears to have occurred in later stages of event. Surfaces of terminals covered with black and green deposits which appear to be sulfur compounds of the terminal materials.
A (1983 Town Car, Houston)	Burned	Elements from contact material detected at filling end of isoport. Indicates possible flow of fluid back through seals.	Gasket and environmental seal missing. Charred fragments Kapton seals remain.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
B (1982 Town Car, Houston)	Burned	Elements from contact material detected at filling end of isoport. Indicates possible flow of fluid back through seals.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Transfer pin and movable contact missing. Stationary contact exhibits crack in similar location as that in Reddick sample.
C (1982 Town Car, Houston)	Burned	Elements from contact material detected at filling end of isoport. Indicates possible flow of fluid back through seals. Black deposit in cavity currently being analyzed (possibly charred gasket).	Gasket appears charred. Environmental seal missing. Damage to Kapton seals currently being evaluated.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
D (1987 Crown Victoria)	Apparent leakage.	Black residue containing glycol based material (probably brake fluid) and a metal oxide. Indicates presence of brake fluid on flint and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Contacts appear intact. Dark green deposits on movable and stationary contacts contain elements from brass contact material. Terminals appear clean (no apparent deposits or corrosion).
E (F11 from survey)	No leaks or other apparent problems	Black residue containing glycol based material (probably brake fluid) and a metal oxide. Indicates presence of brake fluid on flint and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit deformation and buckling similar to that found in Reddick sample. Cracking on surfaces suggest incident damage is occurring.	Face of cup appears clean and dry.	Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
F	Apparent leakage	Black residue containing glycol based material (probably brake fluid) and a metal oxide. Indicates presence of brake fluid on flint and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Stationary contact is intact, but does show stress corrosion cracking in progress in bridge area (same location as in Reddick switch). Movable contact appears to have separated as a result of loss of material (~80% of thickness) due to corrosion. No evidence of heating or arc damage. Dark green deposits on movable and stationary contacts contain elements from brass contact material, as well as sulfur. Terminals exhibit green deposits (currently being analyzed). Deposits extend in from both sides of bulkhead between switch and terminal cavities, but do not seal.

Curry, Pat

From: Steve Reimers [sreimers@ford.com]
Sent: Thursday, April 29, 1999 9:36 AM
To: McGuirk, Andy
Subject: Date Code

What is the date code for service parts F2VY-9F924-A built before Dec. 1992?

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04143 j>

TL-NHTSA 016908

Curry, Pat

From: Steve Reimers [sreimers@ford.com]
Sent: Thursday, April 29, 1999 9:31 AM
To: slarouch@ford.com
Cc: Porter, F.J.; McGuirk, Andy; Sharpe, Robert
Subject: RE: Brake Switch

I have asked Andy to Fed Ex a 48 inch strip of Kapton and 10 sensors to Rob Sharpe (local TI rep) for you to use in comparative tests with some of the field return samples. Please also include in this test the samples from TI that were removed every 200K cycles from the Impulse testing. Please let me know when these tests could be completed.

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 04/29/99 08:51 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.
cc: FPORTER --FORDMAIL Porter, Fred (F.J. SLAROUCH--FORDMAIL LaRouche, Steve (S

From: LaRouche, Steve (S.)
Subject: RE: Brake Switch

Steve: I should have it to you today; I have a few more entries to make. I received several switches from F-150s. Do you know what the background is on these switches? I also talked to some more people in our polymers section and found that there may be one or two ways for us to quantify the effects of brake fluid on the Kapton. One is called DMA, which can be used to determine the modulus of the material; the other, which is called DSC, can determine the effects indirectly by establishing the glass transition temperature. (Don't ask me what all this stuff means, because it's a mystery to me). I'm going to round up some samples and have them see what they can do with them. Can you get us some new switches so we can remove the Kapton seals? I'd like to use material out of new switches because it has been deformed. Some uninstalled Kapton may also be useful so we can see the effects of deforming the Kapton around the converter and washer.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers [mailto:sreimers@gw.ford.com]
Sent: Wednesday, April 28, 1999 6:59 PM
To: slarouch@mail.ford.com
Subject: Brake Switch

Steve, thanks for the updates. Can I get the updated findings Thursday?

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 04/23/99 16:29 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.

From: LaRouche, Steve (S.)

1

TI-NHTSA 016906

Subject: Brake Switch

Steve: Here are the updated switch log and checklist. I am working on expanded results spreadsheet, incorporating observations on the connectors and wires. I hope to have that completed by Tuesday next week. In addition to the results already reported on the findings spreadsheet you already have,

<<chklist.xls>> <<SwitchLog.xls>>

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4976 (313) 322-1614 FAX

Attachments sent separately:

Data Type	File Name
BINARY	CHKLIST.XLS_PC
BINARY	SWITCHELO.XLS_PC

Curry, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.d.com]
Sent: Friday, April 30, 1999 9:02 AM
To: Beringhouse, Steven; Baumann, Russ
Cc: Andrea, Amy
Subject: FW: Brake Switch

fyl.

we are complying with the requests.....

here's what they are doing....

steve, we ought to have the tsl folks look too. how about it ?

a

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 504-2044

From: Steve Reimers[SMTF:sreimers@ford.com]
Sent: Thursday, April 29, 1999 10:30 AM
To: slarouch@ford.com
Cc: Porter, F.J.; A.McGuirk, a-mcgui; ROB Sharpe, Texas I
Subject: RE: Brake Switch

I have asked Andy to Fed Ex a 48 inch strip of Kapton and 10 sensors to Rob Sharpe (local TI rep) for you to use in comparative tests with some of the field return samples. Please also include in this test the samples from TI that were removed every 200K cycles from the Impulse testing. Please let me know when these tests could be completed.

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 04/29/99 08:51 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.
cc: FPORTER --FORDMAIL Porter, Fred (F.J. SLAROUCH--FORDMAIL LaRouche, Steve (S

From: LaRouche, Steve (S.)
Subject: RE: Brake Switch

Steve: I should have it to you today; I have a few more entries to make. I received several switches from F-150s. Do you know what the background is on these switches? I also talked to some more people in our polymers section

TI-NHTSA 016908

and found that there may be one or two ways for us to quantify the effects of brake fluid on the Kapton. One is called DMA, which can be used to determine the modulus of the material; the other, which is called DSC, can determine the effects indirectly by establishing the glass transition temperature. (Don't ask me what all this stuff means, because it's a mystery to me). I'm going to round up some samples and have them see what they can do with them. Can you get us some new switches so we can remove the Kapton seals? I'd like to use material out of new switches because it has been deformed. Some uninstalled Kapton may also be useful so we can see the effects of deforming the Kapton around the converter and washer.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers [mailto:sreimers@gw.ford.com]
Sent: Wednesday, April 28, 1999 6:59 PM
To: slarouch@mail.ford.com
Subject: Brake Switch

Steve, thanks for the updates. Can I get the updated findings Thursday?

Steve Reimers building 5 JE008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 04/23/99 16:28 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.)

From: LaRouche, Steve (S.)
Subject: Brake Switch

Steve: Here are the updated switch log and checklist. I am working on expanded results spreadsheet, incorporating observations on the connectors and wires. I hope to have that completed by Tuesday next week. In addition to the results already reported on the findings spreadsheet you already have,

<<chklst.xls>> <<SwitchLog.xls>>

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

Attachments sent separately:

Data Type	File Name
BINARY	CHNLIST.XLS_PC
BINARY	SWITCHLO.XLS_PC

Currey, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Friday, April 30, 1999 9:02 AM
To: Beringhause, Steven; Baumann, Russ
Cc: Andres, Amy
Subject: FW: Brake Switch

fyi.

we are complying with the requests.....

here's what they are doing....

steve, we ought to have the tsl folks look too. how about it ?

a

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 FIN 604-2044

From: Steve Reimers[SMTP:sreimers@ford.com]
Sent: Thursday, April 29, 1999 10:30 AM
To: slarouch@ford.com
Cc: Porter, F.J.; A.McGuirk, a-mcgui; Rob Sharpe,Texas I
Subject: RE: Brake Switch

I have asked Andy to Fed Ex a 48 inch strip of Kapton and 10 sensors to Rob Sharpe (local TI rep) for you to use in comparative tests with some of the field return samples. Please also include in this test the samples from TI that were removed every 200K cycles from the Impulse testing. Please let me know when these tests could be completed.

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCHE--FORDNA1 04/29/99 08:51 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S)
cc: FPORTER --FORDMAIL Porter, Fred (F.J. SLAROUCHE--FORDNA1 LaRouche, Steve (S)

From: LaRouche, Steve (S.)
Subject: RE: Brake Switch

TI-NHTSA 016910

Steve: I should have it to you today; I have a few more entries to make. I received several switches from F-150s. Do you you what the background is on these switches? I also talked to some more people in our polymers section

and found that there may be one or two ways for us to quantify the effects of brake fluid on the Kapton. One is called DMA, which can be used to determine the modulus of the material; the other, which is called DSC, can determine the effects indirectly by establishing the glass transition temperature. (Don't ask me what all this stuff means, because it's a mystery to me). I'm going to round up some samples and have them see what they can do with them. Can you get us some new switches so we can remove the Kapton seals? I'd like to use material out of new switches because it has been deformed. Some uninstalled Kapton may also be useful so we can see the effects of deforming the Kapton around the converter and washer.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers [mailto:sreimers@gw.ford.com]
Sent: Wednesday, April 28, 1999 6:59 PM
To: slarouch@mail.ford.com
Subject: Brake Switch

Steve, thanks for the updates. Can I get the updated findings Thursday?

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 04/23/99 16:28 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.)

From: LaRouche, Steve (S.)
Subject: Brake Switch

Steve: Here are the updated switch log and checklist. I am working on expanded results spreadsheet, incorporating observations on the connectors and wires. I hope to have that completed by Tuesday next week. In addition to the results already reported on the findings spreadsheet you already have,

<<chklist.xls>> <<SwitchLog.xls>>

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

Attachments sent separately:

Data Type	File Name
BINARY	CHKLIST.XLS_PC
BINARY	SWITCHLOG.XLS_PC

Currey, Pat

From: Andres, Amy [aandres@email.mc.ti.com]
Sent: Friday, April 30, 1999 9:11 AM
To: Griffin, Hank
Cc: Beringhouse, Steven; McGuirk, Andy
Subject: FW: Brake Switch

Hank, I am forwarding this message for your information. For background on the issue please discuss with Al. He has been extensively involved in the analysis to date.

Please provide the team the DSC analysis requested, and line up our outside supplier of DMA for the upcoming requests.

Best regards,
Amy Andres
aandres@email.mc.ti.com
x3616
pg 0662

From: McGuirk, Andy
Sent: Friday, April 30, 1999 10:02 AM
To: Beringhouse, Steven; Baumann, Russ
Cc: Andres, Amy
Subject: FW: Brake Switch

fyi.

we are complying with the requests.....

here's what they are doing....

steve, we ought to have the tsl folks look too. how about it ?

a

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST N/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Steve Reimers(SMTP:ereimers@ford.com)
Sent: Thursday, April 29, 1999 10:30 AM
To: slarouch@ford.com
Cc: Porter, F.J.; A.McGuirk, a-mcgui; Rob Sharpe,Texas I
Subject: RE: Brake Switch

I have asked Andy to Fed Ex a 48 inch strip of Kapton and 10 sensors to Rob

TI-NHTSA 016812

Sherpe (local TI rep) for you to use in comparative tests with some of the field return samples. Please also include in this test the samples from TI that were removed every 200K cycles from the Impulse testing. Please let me know when these tests could be completed.

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDNA1 04/29/99 08:51 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.
cc: FPORTER --FORDMAIL Porter, Fred (F.J. SLAROUCH--FORDNA1 LaRouche, Steve (S

From: LaRouche, Steve (S.)
Subject: RE: Brake Switch

Steve: I should have it to you today; I have a few more entries to make. I received several switches from F-150s. Do you know what the background is on these switches? I also talked to some more people in our polymers section and found that there may be one or two ways for us to quantify the effects of brake fluid on the Kapton. One is called DMA, which can be used to determine the modulus of the material; the other, which is called DSC, can determine the effects indirectly by establishing the glass transition temperature. (Don't ask me what all this stuff means, because it's a mystery to me). I'm going to round up some samples and have them see what they can do with them. Can you get us some new switches so we can remove the Kapton seals? I'd like to use material out of new switches because it has been deformed. Some uninstalled Kapton may also be useful so we can see the effects of deforming the Kapton around the converter and washer.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers [mailto:sreimers@fw.ford.com]
Sent: Wednesday, April 28, 1999 6:59 PM
To: slarouch@mail.ford.com
Subject: Brake Switch

Steve, thanks for the updates. Can I get the updated findings Thursday?

Steve Reimers building 5 3E008
RVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-04145 ;>
*** Forwarding note from SLAROUCH--FORDNA1 04/23/99 16:28 ***
To: SREIMERS--FORDMAIL Reimers, Steve (S.

From: LaRouche, Steve (S.)
Subject: Brake Switch

Steve: Here are the updated switch log and checklist. I am working on expanded results spreadsheet, incorporating observations on the connectors and wires. I hope to have that completed by Tuesday next week. In addition to the results already reported on the findings spreadsheet you already have,

<<chklist.xls>> <<SwitchLog.xls>>

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410

TI-NHTSA 016813

(313) 845-4876

(313) 322-1614 FAX

Attachments sent separately:

Data Type	File Name
BINARY	CHKLIST.XLS_PC
BINARY	SWITCHLO.XLS_PC

Currey, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Sunday, April 25, 1999 11:55 AM
To: Mulligan, Sean
Subject: FW: Switch Log and Eval. Procedure



SWITCHLOG



EVALPROC

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 FIN 604-2044

From: Rahman, Aziz
Sent: Thursday, February 18, 1999 1:45 PM
To: 'Fred Porter (Ford)'; 'Norm LaPointe (Ford)'; 'Steve LaRouche (Ford)'; 'Steve Reimers (Ford)'
Cc: Beringhouse, Steven; Dague, Bryan; Baumann, Russ; McGuirk, Andy; Sharpe, Robert
Subject: Switch Log and Eval. Procedure

Updated as of 2/18/99. There were some switches from the initial 24 switch survey that were opened up at AVT and the tag and switch parts were not kept together. I have noted this in the log.

Since the tag numbers for every incoming shipment start from 1, I suggest we use VIN numbers to track the database. This will uniquely identify the switch.

I suggest that the switch analysis priority be as follows:

- Switches from underhood fires, which have not been severely damaged
- Switches from Town Cars, starting by highest mileage and descending
- Switches from CV and GM, starting by highest mileage and descending
- Severely damaged switches from underhood fires
- Disassembled switches, with suspect paperwork trail

<<SwitchLog>>

Evaluation Procedure updated as of 2/18/99. Note identification of harness wires by color.

<<EVALPROC>>

I think we are closing in on finalizing the log format and the evaluation procedures. I believe that these are good enough for us to start using them for data entry.

In order to reduce confusion, I will plan on updating the log once a week. Please delete the earlier versions, so that you have only one latest copy.

Please comment.

Thanks
Aziz

Currey, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Sunday, April 25, 1999 11:55 AM
To: Mulligan, Sean
Subject: FW: Switch Evaluation Plan.xls



Brake Pressure Switch
Manual.

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST W/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Rahman, Aziz
Sent: Thursday, February 18, 1999 10:21 AM
To: 'Fred Porter (Ford)'; 'Norm LaPointe (Ford)'; 'Steve LaRouche (Ford)'; 'Steve Reimars (Ford)'
Cc: Beringhause, Steven; Dague, Bryan; Baumann, Russ; Sharps, Robert; McGuirk, Andy
Subject: Switch Evaluation Plan.xls

<<Brake Pressure Switch Evaluation Plan.xls>>

Revised to include Switch dissection procedures.

Regards
Aziz.

Step #	Category	Step #	Action	Related Data	Comments
1	Field Job	1	Log Field into Switch Log.xls		
2	Field Job	2	Photograph Switch		
3	Field Job	3	Record any unusual/abnormal visual observations		
4	Field Job	4	Check for Connector engagement		If not correct contact X-Ray to determine if repaired (See 10 and 10A)
5	Switch Assembly	5	Wire 1 to Wire 2 Resistance		
6	Switch Assembly	6	Wire 1 to Heapsart Resistance		
7	Switch Assembly	7	Wire 2 to Heapsart Resistance		
8	Switch Assembly	8	Separate Heapsart from Switch		
9	Connector Only	9	Verify Connector Size		Visual check of Feed Sheet, Old Item, Interference mark. Interference mark must be 90° degree.
10	Connector Only	10	Wire 1 to Wire 2 resistance		
11	Connector Only	11	Current Leakage Wire 1 to Wire 2		
12	Connector Only	12	Check for full engagement of connector		Visual check of distance in related switch base
13	Connector Only	13	Check wire insulation		
14	Connector Only	14	Check wire gray scale		
15	Connector Only	15	Get wire insulation to check for corrosion		Get insulation lengthwise to check for whitening wire. If signs of corrosion, identify color, send samples for cross-14.
16	Switch Disassembly/Inspection	16	Assemble Switch in Calibration Stand		
17	Switch Disassembly/Inspection	17	Terminal 1 to Terminal 2 Resistance		
18	Switch Disassembly/Inspection	18	Terminal 1 to Heapsart Resistance		
19	Switch Disassembly/Inspection	19	Terminal 2 to Heapsart resistance		
20	Switch Disassembly/Inspection	20	Range to Heapsart Resistance		
21	Switch Disassembly/Inspection	21	Current Leakage Terminal 1 to Heapsart		
22	Switch Disassembly/Inspection	22	Current Leakage Terminal 2 to Heapsart		
23	Switch Disassembly/Inspection	23	Voltage drop at TSD mA		
24	Switch Disassembly/Inspection	24	Switch Opening Pressure		Do not perform on parts from uncalibrated lines, assembly details developed after completion
25	Switch Disassembly/Inspection	25	Switch Closing Pressure		Do not perform on parts from uncalibrated lines, assembly details developed after completion
26	Switch Disassembly/Inspection	26	Proof Test for Leakage		Do not perform on parts from uncalibrated lines, assembly details developed after completion
27	Switch Disassembly/Inspection	27	Repeat Steps 17 through 25 at 100 psi		
Procedure	Switch Disassembly/Inspection		Procedure to remove aluminum wiring ring 1. Apply minimum 100 psi (or plastic if used) pressure to reach the required surface. 2. Also create a pressure point to further reduce chance of contamination during cutting of cable ring. 3. Place a plate of tape over the area to be cut. 4. Cut along ring using hand saw or Circular saw if needed 5. Cut opening of ring at 180 degree orientation 6. Initial cutting ring 7. Carefully examine internal surfaces. Take optical photographs (Digital camera will remove from glass instead of microphotography) and document observations where appropriate. Complete the following steps: 8. Initial surface of wiring ring 9. Seal area and underside of base 10. Top of cap 11. Assess Need for Analytical Techniques 12. Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various sections of the plastic base. 13. Repolish the top surface and remove the cap 14. Carefully document all revealed surfaces starting with cap. 15. Meanwhile, start SEM-EDX analysis on top side of cap. Particularly look for evidence of corrosion or wiring 16. Particularly focus on the edges of the ceramic plug pins and on the internal ring that lines up with interior wall of the switch cavity 17. Particularly look for evidence of corrosion or wiring 18. Decide if you should try to take off any of the overlapping debris to try to examine the underlying metal surface. 19. Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.		
28	Field Job	28	Log 70 data from this sheet into Switch Log Photograph, Document steps into Switch Log and returned by Switch #		

TI-NHTSA 016918

Currey, Pat

From: Steve Reimers [sreimers@ford.com]
Sent: Thursday, April 29, 1999 9:36 AM
To: McGuirk, Andy
Subject: Date Code

What is the date code for service parts F2VY-9F924-A built before Dec. 1992?

Steve Reimers	building 5 3E008
RVT Chassis E/E System Applications	mail drop 5011
39-03286 SREIMERS sreimers@ford.com	fax 39-04145 ,>

Currey, Pat

From: McGuirk, Andy [a-mcguirk@email.mc.ti.com]
Sent: Friday, April 30, 1999 2:25 PM
To: 'Frederick J. Porter'
Subject: FW: Items for Ford

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST M/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Mulligan, Sean
Sent: Friday, April 30, 1999 3:14 PM
To: Baringhouse, Steven; McGuirk, Andy; Dagus, Bryan; Sharpe, Robert
Subject: Items for Ford

The following items were sent to Ford for analysis via Robert Sharpe:

(10) 77FS switches.
(1) 48 inch roll of Kapton from production.

The items will be delivered Monday morning.

All the best,

Sean F. Mulligan

Phone (508) 236-2535
Fax (508) 236-3586

Ford Thermal Event

- Ford has announced a recall campaign for 1992-1993 Town Car, Crown Victoria and Grand Marquis (279K)
- TI position/conclusion letter sent to Fred Porter on 25 May
 - 1992 switches met Ford specification (data to support)
 - removal of constant power recommended
 - agreement to bring diagnostic journey to conclusion
- Porter supported our conclusion of meeting spec. *man vs auto crimp*
- Hosted Ford (1 person) for one day for site visit; Beringhouse/McGuirk felt it was favorable to TI. *Rymer - S&A reports to Porter. } records - no new data seen crimping.*
- Delivered 225KU replacement pressure switches as requested by Ford to support recall. *Replied at price. Southern Pres.*
- Ford/TI now named by 3 plaintiffs (2 lawsuits) in conjunction with vehicle fires. *we've talked to Ford's attorney - Lampely (Dalg) August last year added us with comment in May 99*
 - Ford legal's position is TI made a crimping change in February of 92 resulting in a systems performance change causing thermal events
- We are not clear of Ford's position of TI liability

Ford will testify that crimp change

TI-NHTSA 016921

Send them



A. R. O'Neil
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P.O. Box 1804
Dearborn, MI 48121-1804

May, 1999

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control.

**Safety
Defect**

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause the brake light fuse to open.

Repairs:

Repair parts may not be available until mid-June, 1999. If your dealer is not able to obtain the parts needed for this recall, an Interim Repair can be performed at no charge to you. However a second visit to your dealer will be required at a later date to have the permanent repair performed. We regret this inconvenience, but your safety is our primary concern.

Interim Repair: If parts are not available, the Interim Repair should be performed immediately. This repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch and protecting the connector end from contamination. The Speed Control system will be inoperative until the Permanent Repair is performed; normal vehicle operation without Speed Control is not affected.

Permanent Repair: Parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

TI-NHTSA 016922



11007

**How Long
Will It Take?**

The time needed for either of the repairs is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 99S15.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. If available, parts would be expected to arrive within a week after ordering. If parts are not available, your dealer can perform the Interim Repair free of charge. When parts are available, your dealer will perform the Permanent Repair free of charge.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

Refunds:

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your Ford or Lincoln Mercury dealer. To avoid delays, do not send receipts to Ford Motor Company.

**Changed Address
Or Sold The
Vehicle?**

Please fill out the enclosed prepaid postcard and mail it to us if you have changed your address or sold the vehicle.

If the dealer doesn't make the repair promptly and without charge, you may contact the Ford Customer Assistance Center, P.O. Box 6248, Dearborn, Michigan 48121. You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline 1-800-424-9393 (Washington, D.C. area residents may call 366-0123).

We regret the inconvenience this service may cause you, but we want you to have the work done for your safety and satisfaction with your Ford or Lincoln built vehicle.

Sincerely,



A. R. O'Neill
Director
Vehicle Service and Programs

Safety Recall
99S15


TI-NHTSA 016923

NEAL RESSLER, V.P. R.V.T.

To: MS
From: Andy

CARRIE WILLSON, DIRECTOR, ELEC SYSTEM

Ford
Thames


Ford Motor Company


Tina F. Donovan
Manager
EE Systems-Ongoing Prod. Dev.
EE Systems Engineering

Building 5, Mail Drop 8017
20000 Rolando Drive, Rm. 1A043
Dearborn, MI 48121-9053 USA

Tel: 313 380-7488
Fax: 313 317-8158
T.DONOVAN
ustinc78n@tmmail.com

E.donovan@ford.com

DEEPAK GOEL
MANAGER
EMC, Power Supply,
RESPONSE, CRASHES



Ford Motor Company

John S. Jenks
Engineer
Supplier Technical Assistance
Ford Automotive Operations

Quality, Manufacturing & Purchasing
17101 Rolando Drive, MD610
Dearborn, MI 48121 USA

Tel: 313 387-8827
Fax: 313 380-3449
J.JENKS
jjenks@ford.com


STA


Ford Motor Company

Thomas E. Masters
Supervisor Large/Lux Car & Truck
Systems & Wiring OPD
AVT EESE - OPD

20000 Rolando Drive MD 5017
Rm. 2A024, Bldg. 45
Dearborn, MI 48121-2053 USA

Tel: 313 380-8887
Fax: 313 317-8188


Ford Motor Company

Frederick J. Porter
Supervisor
Security, Safety & Chassis Appl.
E/E Systems Engineering
Advanced Vehicle Technology

20000 Rolando Drive SDH
Bldg. 5, 3E004, Mail Drop 4680
Dearborn, MI 48121-2053 USA

Tel: 313 380-8722
Fax: 313 380-4145
FPORTER
fporter@ford.com

~~WILLIAM ABRAHAM SICK~~




~~313 322 9284~~

Steve Palmara

Product Design Engineer
Core Suspension and Steering
Chassis Electronic Systems
Advanced Vehicle Technology

20000 Rolando Drive
Dearborn, MI 48121
Bldg. 16, 3C006, MD 45080
Telephone: 313/380 1288

TT-NHTSA 018924



Service Recall Bulletin

May, 1999

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 99S15: Certain 1992 and 1993 Crown Victorias, Grand Marquis, and Lincoln Town Cars with Speed Control - Speed Control Deactivation Switch

AFFECTED VEHICLES

Certain 1992 and 1993 Crown Victoria and Grand Marquis with Speed Control built at the St. Thomas assembly plant from February 5, 1992 through November 30, 1992. Also, certain 1992 and 1993 Town Cars built at the Vitom Assembly plant from November 4, 1991 through November 30, 1992.

REASON FOR RECALL

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause a fuse to open.

SERVICE ACTION

Repair parts will not be available until mid-June, 1999. Until parts are available, the interim repair described in Attachment III should be used. When parts are available the permanent repair must be completed to close this recall.

Interim Repair: This repair should be performed immediately to eliminate the possibility of a fire. This interim repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch, taping the connector end to protect it from contamination and securing the connector with a tie-strap. The speed control system will be inoperative until the permanent repair is performed.

Permanent Repair: The parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

TI-NHTSA 016928

Safety Recall 99E18
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars
with Speed Control - Speed Control Deactivation Switch

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

Please note that the interim repair will not remove the VIN from OASIS.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACEBH Manual for claims preparation and submission information.
- After performing the Permanent Repair, the replaced parts must be returned to the Warranty Parts Return Center for inspection (See Attachment II page 2). PCS 700 tags will be sent as soon as the claim for the Permanent Repair is submitted.

OWNER REFUND

Ford Motor will only refund for owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACEBH Manual for Refund information.

Safety Recall 99S15
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch

LABOR ALLOWANCES

Interim Repair

Description	Labor Operation	Labor Time
Remove, Tape and Secure the Speed Control Deactivation Switch *	99S15E*	0.1 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

* Labor Operation 99S15E will NOT close the Recall.

Permanent Repair

Description	Labor Operation	Labor Time
Replace Speed Control Deactivation Switch and Hard-shell Connector	99S15B	0.5 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	after July 1, 1999	Normal order process
Emergency Orders	before July 1, 1999	Call 1-800-325-8621

Part Number	Description	Quantity
XWTZ-99882-AA	Speed Control Deactivation Switch Kit	1

5/11/01

Safety Recall 99S16
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch

DEALER PRICE

For latest prices, check or call your:

- Order Processing Center
- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

DISPOSITION OF REMOVED PARTS

Parts Return Requested (after completion of Permanent Repair):

We are requesting that the removed parts be returned to Ford Motor Company:

- Speed Control Deactivation Switch
- Switch Hardshell Connector

Packaging and Shipping:

- Speed Control Deactivation Switch
 - Do not drain the brake fluid from inside the Speed Control Deactivation Switch.
 - Use the plastic cap from the new switch to trap and seal as much oil inside the switch as possible.
- Switch Hardshell Connector
 - Connect the hardshell connector to the Speed Control Deactivation Switch.
 - Attach the FCS 700 tag to the part
 - Place the part in a plastic bag and secure with twist-tie.
- Shipping Instructions
 - Follow direction on FCS 700 tag
 - See Section 3 of the ACES II manual for more details

INTERIM REPAIR

DISABLE SPEED CONTROL DEACTIVATION SWITCH

SERVICE PROCEDURE

1. Disconnect the electrical connector from the speed control deactivation switch. See Figure 1.




FIGURE 1

2. Tape the end of the connector to prevent contamination from entering the end of the connector.
3. Tie strap the connector to the wiring harness located on the left splash shield.

81-00
81-00
81-00

PERMANENT REPAIR

SPEED CONTROL DEACTIVATION SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES: CERTAIN 1993 AND 1993 CROWN VICTORIA, GRAND MARQUE
AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the speed control deactivation switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the new connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the speed control deactivation switch. See Figure 2.




FIGURE 2


© 1993 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
000

RT2

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 3.




FIGURE 3

4. Obtain the new connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully seated in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the speed control deactivation switch from the parts kit.
7. Remove the old speed control deactivation switch.
8. Fill the new speed control deactivation switch with High Performance DOT 3 Brake Fluid and install the speed control deactivation switch. Tighten the switch to 18 Nm (13 lb-ft).
9. Attach the electrical connector to the speed control deactivation switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
 - Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.

UPR © 1998 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
878