

EA02025

TEXAS INSTRUMENTS, INC.'S

09/10/03 LETTER TO ODI

REQUEST 13

BOX 13

PART A – E

PART A

EA02-025
TEXAS INSTRUMENTS, INC.'S

Response to NHTSA Request No. 13

Substrate/Board: Speed Control Reciprocating Pressure Switch
 Design Responsibility: Stephen S. OFFICE
 Other Items Involved:

Qualities and Flaws (Defects):
 Detail View/Configuration:
 Engineering Release Date:

Prepared by:
 Date: 11/13/80

Check:

Part Name, Number & Description	Potential Failure Mode	Potential Effect of Failure	Severity	Criticality	Potential Cause of Failure	Occurrence	Design Verification	Detection	Recommended Action	Step/Individual Responsible & Completion Date	ACTION NEEDED	REMARKS	DATE	INITIALS
WIRE (WIRE) Provides features which locate and align the movable and stationary terminals. Provides insulation the electrical elements from the environment. Provides a reference surface which locates the electrical elements relative to the pressure sensor. Provides a flange to secure the environmental seal. Provides geometry of electrical connector.	Installed out of proper location	Difficulty installing wiring electrical connector			Insufficient location features in base area out of spec.		WFI; in-process check; final insp.							
	Insufficient lines	Intermittent continuity			Insufficient location features in base area out of spec.		WFI; in-process check; final insp.							
	Connector dimensions improper	Difficulty installing wiring connector			Broken/over mold		WFI; in-process check; final insp.							
	Low insulation resistance	Current leakage pressure switch from function circuit			Contamination/wrong material		WFI; in-process check; final insp.							
	Leadage of environmental substances past connector	Excessive current leakage High contact resistance Contacts stuck open Contacts stuck closed			Improper geometry of environmental seal and surface caused by broken/over mold Handling damage to seal surface		WFI; in-process check; final insp. In-process equal check							
	Lock tabs too small	Wiring core falls off			Broken mold required inspection		WFI							
	Lock tabs too big	Difficulty installing wiring connector			Broken/over mold		WFI; in-process check; final insp.							
	Seal gasket between base and pressure sensor too small	Base and sensor do not seal properly causing leak in system			Broken mold required inspection		WFI							
	Seal gasket too big	Base/sensor seal causes leakage in leakage			Broken/over mold		WFI; in-process check; final insp.							
	Incorrect polarity key location	Wiring connector will not fit			Molding error		WFI; in-process check; final insp.							
FUNCTION: INSIDE CHASSIS Provides a brass blade for interconnection. Provides a silver-plated surface for electrical contact. Provides a feature for device calibration. Provides a feature for stacking into base.	High contact resistance/low continuity at blade	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Blade dimensions improper	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Insufficient lines in base	Intermittent continuity			Insufficient location features in base area out of spec.		WFI; in-process check; final insp.							
	High resistance at contacts	Apparent open circuit			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Contact resistance increases over life	Performance degradation over time			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Improper calibration	Wp. (yield loss and cal. detected at pressure test)			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	High contact resistance/low continuity at blade	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Blade dimensions improper	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Insufficient lines in base	Intermittent continuity			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	High resistance at contacts	Apparent open circuit			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
FUNCTION: INSIDE CHASSIS Provides a brass blade for interconnection. Provides a silver-plated surface for electrical contact. Provides a feature for device calibration. Provides a feature for stacking into base.	High contact resistance/low continuity at blade	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Blade dimensions improper	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Insufficient lines in base	Intermittent continuity			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	High resistance at contacts	Apparent open circuit			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Contact resistance increases over life	Performance degradation over time			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Improper calibration	Wp. (yield loss and cal. detected at pressure test)			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	High contact resistance/low continuity at blade	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Blade dimensions improper	Device appears open-circuit w/ wiring connector installed			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	Insufficient lines in base	Intermittent continuity			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							
	High resistance at contacts	Apparent open circuit			Blade appears open-circuit w/ wiring connector installed		WFI; in-process check; final insp.							

TI-NHTSA-019042A

Subcontractor/Manufacturer: Speed Control Diagnostics Pressure Switch
Design Responsibility: Stephen H. Offiler
Order Status: Pending

Regulations and Plans: Affected:
Small Business/Disadvantaged:
Environmental Reform Index:

Prepared by
John Peter Ward

Clus:

[illegible]

Signature/Name: _____ Social Security Number: _____
 Rank: _____ Branch: _____
 Date: _____

Soil/Litter and Plants Affected:
None (None, Unpublished)
Bromus horridus, Bromus ciliaris

Prepared by:
Ruth Martin, Director

Conclusion

[illegible]

Subgroup/Team: David Central Electronics Program Switch
Design Responsibility: Stephen M. Gifford
Other Team Members:

Supplier and Material Reference:
None Applicable
Engineering Release Date:

Prepared by:
FWS (John Grogg)

QSA-24

Part Name, Number & Description	Potential Failure Mode	Potential Effects of Failure	SEV	OC	Potential Cause(s) of Failure	OP	PP	Design Verification	DES	PP	Recommended Action	Assign/Initiated Responsible & Completion Date	ACTION	RES	YTD
SWITCH (C476) Press flexible element of fluid contact switch during overpressure pressure from fluid in programming element	Insufficient material properties	Reduced life leading to lock			Supplier error										
SWITCH (C476) Provides a portion of the support surface for diaphragm Provides support for compression of gasket Locates converter and disc with respect to day	Surface roughness	Reduced diaphragm life leading to leakage			Improper heat-treat Chips in tool										
	Incorrect diameter	Shift in outpoints Reduced diaphragm life leading to leakage			Manufacture tool										
	Heat	Reduced disc strength, compression failure Reduced gasket strength results in leak			Broken, worn, or improperly set-up tools										
	Wrong material	Improper hardness and/or strength leading to leakage			Supplier error										
	Wrong heat-treatment	Improper hardness and/or strength leading to leakage			Supplier error										
	Incorrect ID	Too small results in difficult assembly to converter Too small results in friction between converter and converter, leading to shift in outpoints over life Too large results in poor location of converter, shift in outpoints or impingement Too large results in reduced diaphragm life			Broken, worn, or improperly set-up tools										
	Incorrect OD	Too large results in difficult assembly Too small results in poor location of converter, shift in outpoints or impingement			Broken or worn tools										
	Incorrect thickness	Too thick results in poor spring, leads to reduced diaphragm life or reduced burst resistance Too thin leads to leakage			Wrong tool, thickness, supplier error										
	None	Reduced diaphragm life			Broken, worn, or improperly set-up tools										
SWITCH (C476) Overpressure pressure from fluid tube displaced to a form as secondary-sensing disc Provides alignment and support to spacer and disc	Irregularities on surface making with diaphragm	Reduced diaphragm life			Broken, worn, or improperly set-up tools										
	Incorrect bottom dia	Too large results in difficult assembly to tooling Too large results in friction between converter and converter, leading to shift in outpoints over life Too small results in poor location of converter, shift in outpoints or impingement Too small results in reduced diaphragm life			Broken or worn tools										
	Bottom dia of tool-precision roughness to disc locate feature	Difficult assembly Poor location of disc leading to irregularities device or shift in outpoints			Broken, worn, or improperly set-up tools										

TT-NHTSA 019046

Subject/Topic: Diesel Control Pressure Switch
 Degree/Responsibility: Stephen E. Gifford
 Other Name: (none)

Suppliers and Parties Affected:
Model Year/Vehicle(s):
Manufacturer's Name:

Prepared by
John John Corbett

Figure 2

[illegible]

Subject: William: Speed Control Demonstration Program Subject
Design: Response Ability: Stephen H. Gifford
Other: Steve Gifford

Suppliers and Plants Affected:
 Ford Motor Vehicle Co.
 Ford Motor Vehicle Co.

Exposure Date
1998-1999

Conclusions

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	Cause	Effect	Detection Method	Prevention Method	Inspection Method	Acceptance Criteria	Action Required	Result
	Wrong material	Too soft or hard leads to poor sealing, reduced pressure capability, reduced diaphragm life		Supplier error						
	Disc support hoop geometry incorrect	Incorrect calibration Disc fatigue Improper die design		Bad disc, worn or improperly set-up tools						
	Geometry of under-lying ring stop incorrect	Too high - excessive disc wear/tear leads to increased leakage strain, incorrect calibration Too low - insufficient disc coverage, air-leakage disc and improper die design Die wall results in difficult assembly Die large results in poor location of component, shift in alignment or deformation		Bad disc, worn, or improperly set-up tools						
	Geometry of pin guide incorrect	Die small results in poor seating - may give erratic operation at temperature extremes Die large results in shift in pin position, erratic electrical characteristics Too short provides poor guidance, results in seated pins, deformation or erratic function Too long may short circuit to housing		Bad disc, worn, or improperly set-up tools						
	Thickness incorrect	Too thin results in poor seal; leakage of substrate from environment Too thick causes difficulty in final cryo. transfer in large flanges, or impairs/severely limits operation		Tooling set-up error						
	ID incorrect	Too large - may not engage satisfactorily around circumference Too small - won't assemble		Bad disc, worn, or wrong extruder						
TI-NHTSA 018047	OD incorrect	Too small - insufficient seal area		Bad disc, worn, or wrong extruder						
	Wrong material	Long-term degradation results in leakage		Supplier error						
	Porosity in material	May result in leakage if combined with fractured epoxies		Supplier error						
	Discolor incorrect	Die large results in poor seating - may give erratic operation at temperature extremes Die small results in shift in pin position, erratic electrical characteristics		Bad disc or worn tool						
CRIME RING C-9977 Sealure disc motion to suitable electrical contact Insulation electrical components from switch housing	Length incorrect	Too short - low resistance or failure upon activation Too long - High resistance, inadequate contact with contacts over time		Mishandling / wire-burned array						
	Material incorrect	Shift in alignment with temp Current leakage to housing Fractures/cracks; erratic or impossible function		Supplier error						
	ID incorrect	Too large results in poor grip Too small hinders assembly		Bad disc, worn, or improperly set-up tooling						
	OD incorrect	Too large results in poor grip Too small hinders assembly		Bad disc, worn, or improperly set-up tooling						

Subsystem/Vehicle: Small Control Description: Pressure Switch
 System Responsibility: Stephen B. OFFICE
 Other Areas Involved:

Supplier and Vendor (if noted):
 (Part Name/Supplier/Co):
 Engineering Release Date:

Prepared by:
 (Name Date Code):

(Rev):

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S.N.C.	C.N.C.	Potential Cause(s) of Failure	O.N.C.	Design Specification	D.N.C.	Recommended Actions	Responsible Person & Completion Date	ACTION Items Taken	RESULTS			
												P.	C.	D.	R.
	Length incorrect	Too long or short causes poor contact and resistance to rotation of hose pul. to cause control leak			Stretch, wear, or incorrect end-up loading										
	Material incorrect	DIFFICULT to leak relief Corrosion (if incorrect not SL)			Supplier error										
	Thickness incorrect	Too thin results in poor sealing Too thick results in difficulty to replace			Supplier error										

TI-NHTSA 018048

Part/Process Name: CRIMPING MACHINE
 Design Responsibility: CRIMPING MACHINE
 Other Areas (Include): CRIMPING MACHINE

Supplier and Plants Affected:
 Model No. 100-1 (Rev. 1-77)
 Drawing Release Date:

Prepared by:
 Date: 10/1/77
 Revision:

Class: A

Process Description/Program	Potential Failure Mode	Potential Effect(s) of Failure	S.N.C.	Potential Cause(s) of Failure	O.C.	Current Controls	D.S.C.	D.F.M.	Recommended Action	Area/Individual Responsible	Action Taken	RECUR	TS
CRIMP PART 8, CUSTOMER NAME AND DATE CODE ON PART	WRONG PART 8	WRONG PART 8 ON CRIMP RING	5	OPERATOR SET-UP	3	QC SAMPLE	1	15					
	WRONG DATE CODE	LOSS OF LOT CONTROL	3	OPERATOR SET-UP	3	VISUAL & QC SAMPLE	1	9					
	WRONG PLATING	IMPROPER DEVICE	7	PRET ISSUING ERROR	1	VISUAL & QC SAMPLE	1	7					
				OPERATOR ERROR									
	NO CODE	LOSS OF PART IDENTITY AND LOT CONTROL	7	MACHINING ERROR	1	VISUAL & QC SAMPLE	1	7					
				CONE BLACK MARK									
	ILLEGIBLE CODE	LOSS OF PART IDENTITY AND LOT CONTROL	5	MACHINING ERROR	3	VISUAL & QC SAMPLE	1	15					
				CONE BLACK MARK		PREVENTIVE MAINTENANCE							
PLACE SENSOR INTO CRIMP RING	DISCONNECT DATE CODE	LOSS OF LOT IDENTITY FOR FIELD RETURN	3	EXCESS TOLERANCE	1	QC SAMPLE AT WORKING	1	3					
				OPERATOR ERROR		LEAD OPERATOR CHECK AND APPROVED SET-UP							
	NO SENSOR	FAILS TO ASSEMBLE		OPERATOR ERROR		UTERINE AIDE							
	NO CRIMP RING	FAILS TO ASSEMBLE		OPERATOR ERROR		UTERINE AIDE							
						JUST-IN-TIME MANUFACTURING SYSTEM							
PLACE ENVIRONMENTAL SEAL OVER LEAD ON SENSOR	MISPLACED	INTERNAL CORROSION OVER LIFE	7	OPERATOR ERROR	3	SFC ON BREECH-TO-SENSOR TORQUE	1	21					
	MISSED	INTERNAL CORROSION OVER LIFE	7	OPERATOR ERROR	1	SFC ON BREECH-TO-SENSOR TORQUE							
						P-CHECK ON AIR LEAK							
	TWO SEALS	INTERNAL CORROSION OVER LIFE	7	OPERATOR ERROR	1	SFC ON BREECH-TO-SENSOR TORQUE	1	7					
						P-CHECK ON AIR LEAK							
PLACE TRANSFER PIN ON SENSOR CRIMP PIN GUIDE	WRONG SIZE PIN	CRIMP	2	MIXED PIN	3	LEAK FUNCTION TEST	1	21					
		MARGINAL TRANSFER TIME		OPERATOR ERROR		PIN AVAILABLE FOR LEAKY PICK TO PASSING TO FLOOR							
		CONDUCTIVITY				ROUTE CHASE							
	PIN NOT IN PLACE	NO CONDUCTIVITY-DEVICE WON'T FUNCTION	7	OPERATOR ERROR	1	LEAK FUNCTION TEST	1	7					
ASSEMBLE BASE TO SENSOR ASSEMBLY WITH CRIMP PIN AND ENVIRONMENTAL SEAL	WRONG BASE	CRIMP	7	OPERATOR ERROR	1	LEAK FUNCTION TEST	1	7					
		NO FUNCTION											
	DISLOOSE PIN	NO FUNCTION	7	ROUGH HANDLING	1	LEAK FUNCTION TEST	1	7					
		INTERMITTENT CONDUCTIVITY											
	MISPLACED ENVIRONMENTAL SEAL	INTERNAL CORROSION	7	OPERATOR ERROR	1	AIR LEAK SAMPLE	3	21					
						CRIMP-TO-SENSOR TORQUE SFC							
CRIMP PINN. BASE ASSEMBLY	CRIMP DIAMETER OUT OF SPECIFICATION	INTERNAL CORROSION	7	HIGH CYCLER PRESSURE	1	LEAK TEST	1	7					
		CRIMP		WORN TOOL		ATP LEAK SAMPLE							
						TORQUE SFC							
						LEAK FUNCTION TEST							

TI-NHTSA 019049

[illegible]

TI-NHTSA 019067

[illegible]

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	Cause(s) of Failure	Effect(s) of Failure	Design Verification	Design	Recommended Actions	Form/Individual Responsibility & Completion Date	ACTION R	S	U	T	R
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94	PROX (40015) Provides features which locate and align the movable and stationary terminals	Terminal out of proper location	Difficulty installing wiring electrical connector	1	Terminal locating features in base are out of spec.	1	PHI: in-process check: final insp.	1	3				
		Terminal loose	Intermittent continuity	7	Terminal locking features in base are out of spec.	1	PHI: in-process check: final insp.	1	7				
		Corroder dimensions improper	Difficulty installing wiring connector	3	Broken/worn mold	1	PHI: in-process check: final insp.	1	3				
		Low insulation resistance	Current leakage prevents switch from breaking circuit	7	Contamination/wrong material	1	Mat'l certification	1	7				
		Leakage of ground-reference past connector	Excessive current leakage	7	Improper geometry of mating surface and surface caused by broken/worn mold	3	PHI: in-process check: final insp.	1	81				
		Provides geometry of electrical connector	High contact resistance	7	Welding damage to seal surface	1	PHI: in-process check: final insp.	1	7				
			Contacts stuck open	7	Broken mold required improperly	1	PHI: in-process check: final insp.	1	7				
			Contacts stuck closed	7	Broken mold required improperly	1	PHI: in-process check: final insp.	1	7				
		Lock tabs too small	Mating won't fall off	7	Broken mold required improperly	1	PHI: in-process check: final insp.	1	7				
		Lock tabs too big	Difficulty installing wiring connector	7	Broken/worn mold	1	PHI: in-process check: final insp.	1	7				
		Small gland between base and pressure sensor too small	Base and sensor do not meet properly, causing shift in setpoint	5	Broken mold required improperly	1	PHI: in-process check: final insp.	1	5				
		Small gland too big	Insufficient seal causes leakage to leakage	7	Broken/worn mold	1	PHI: in-process check: final insp.	1	7				
		Incorrect polarity key location	Mating connector will not fit	1	Molding error	5	PHI: in-process check: final insp.	1	45				
		High contact resistance/continuity at blade	Device appears open-circuit w/ mating connector installed	5	Mat'l too thin	3	Supplier process controls and TI Receiving Inspection	1	45				
		Blade dimensions improper	Device appears open-circuit w/ mating connector installed	5	Wavy/broken stamping tools, or wrong material thickness	1	Supplier process controls and TI Receiving Inspection	3	15				
		Provides a feature for device calibration	Difficulty installing wire.	7	Improper lance	3	Supplier process controls and TI Receiving Inspection	3	63				
		Provides a feature for storing data base	Intermittent continuity	7	Improper lance	3	Supplier process controls and TI Receiving Inspection	3	63				
			Shift/Fluctuation in setpoint	7	Improper lance	3	Supplier process controls and TI Receiving Inspection	3	63				
			High resistance at contacts	7	Wrong material	1	Mat'l certification	1	7				
			Intermittent continuity	7	Wrong material	1	Mat'l certification	1	7				
			Contact resistance increases over time	5	Wrong material	1	Mat'l certification	1	7				
			Improper calibration	9	Wrong material	1	Mat'l certification	1	7				
			High contact resistance/continuity at blade	5	Wrong material	1	Mat'l certification	1	7				
			Blade dimensions improper	5	Wrong material	1	Mat'l certification	1	7				
			Provides a feature for storing data base	7	Wrong material	1	Mat'l certification	1	7				
			Intermittent continuity	7	Wrong material	1	Mat'l certification	1	7				
			Shift/Fluctuation in setpoint	7	Wrong material	1	Mat'l certification	1	7				

TI-NHTSA 019065

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S.N.	C.R.	Potential Cause(s) of Failure	O.C.	Design Identification	D.C.	S.N.	Recommended Action	Sign/Individual Responsibility & Completion Date	ACTION	U.S.	U.S.	U.S.	U.S.
SPRING (36809) Provides contact force Provides continuity between terminals Provides feature to interface with transfer pin Provides mounting location for movable contact Provides feature for attachment to stationary contact	High resistance at spring interface	Apparent open circuit Intermittent continuity			Piling/misalignment		Mat'l certification									
	Loose spring	Erratic operation Shift/drift in setpoints	7		Rivet hole oversized	1	Supplier process controls and TI Manufacturing Inspection	3	21							
	Rivet hole size/location bad	Will not assemble to spring properly	3		Stamping tool wear or broken	3	Supplier process controls and TI Manufacturing Inspection	3	20							
	Low contact force	High millivolt drop across contacts	3		Incorrect geometry	7	SFC check on last line	1	21							
	High contact force	Change in setpoints Disc fracture	3		Incorrect material	7	Mat'l certification	1	21							
	High resistance at movable terminal interface	Apparent open circuit	7		Piling/misalignment	1	Mat'l certification	1	7							
	Rivet hole size/location bad	Will not assemble to terminal properly	3		Stamping tool wear or broken	3	Assembly equipment source spring pressure/force	1	7							
	Transfer pin jump out of position or missing	Spring failure over life	7		Broken stamping tool	3	SFC/visual check	1	21							
	Length undersize	Spring falls off movable turn	3		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	20							
	Length oversize	Loose spring	7		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	63							
SPRING (74171) Holds spring and movable terminal together	Diameter undersize	Loose spring	7		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	63							
	Diameter oversize	Assembly difficulty	3		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	20							
	Head undersize	Loose spring	5		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	45							
	Head oversize	Assembly difficulty	3		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	20							
	Hollow point oversize	Weak rivet - spring falls off	7		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	63							
	Hollow point undersize	Difficult to rivet - loose spring	3		Supplier tooling	3	Supplier process controls and TI Manufacturing Inspection	3	20							
	High contact resistance/no continuity	Device appears open circuit No wiring connector installed Intermittent continuity	5		Silver too thin Piling/misalignment	3	Supplier process controls and TI Manufacturing Inspection	3	45							
	Resistance increases over life	Degradation of electrical parameters over time	7		Silver too thin	3	Mat'l certification	1	21							
	Contacts weld	Device permanently closed-circuit; no response to fluid pressure	7		Excessive overcurrent from outside electrical system	1	Run-in/fuse-like	1	7							
	Sharp geometry incorrect	Contact does not assemble as spring, or falls off	3		Broken, worn, or improperly set-up tooling	3	Supplier process controls and TI Manufacturing Inspection	1	7							
DOUBLE CONTACT (74080) Provides electrical switching interface with stationary terminal																

TI-NHTSA 018066

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	Criticality	Potential Cause(s) of Failure	Design Verification	Prevalence	Recommendation	Form/Individual Responsible & Completion Date	Action Taken	Result	Comments
Support and discharge		Excessive squeaking results in support assembly and reduced life of gasket leading to leak Insufficient squeaking results in leak Gasket diameter too large, results in assembly difficulty Gasket diameter too small, results in leak		Wrong extruder tool	Receiving inspection						
	Wrong material	Reduced gasket life, leading to leak Permanent set after temperature exposure leads to leak	9	Supplier error	Mat'l certification	1	9				
DISBURSER (C7176) Transfers fluid from fluid container to fluid	Insufficient material properties	Reduced life leading to leak	9	Supplier error	Mat'l certification	1	9				
DISBURSER (C7176) Provides a portion of the support surface for discharge	Surface roughness	Reduced discharge life leading to leakage	9	Extruder heat-treat Chips in tool	Supplier process controls and TI Receiving inspection	3	29				
DISBURSER (C7176) Provides support for compression of gasket	Incorrect diameter	Shift in setpoints	9	Broken/ worn tool	Supplier process controls and TI Receiving inspection	3	29				
DISBURSER (C7176) Transfers pressure from fluid to pressure-bearing element	Part	Reduced disc wear, improper assembly Reduced gasket exposure results in leak	3	Broken, worn, or improperly set-up tools	Supplier process controls and TI Receiving inspection	3	29				
	Wrong material	Excessive hardness and/or strength leading to bending	3	Supplier error	Mat'l certification	1	3				
DISBURSER (C7176) Provides support for compression of gasket	Wrong heat-treatment	Excessive hardness and/or strength leading to bending	3	Supplier error	Hardness add at TI Receiving inspection	3	29				
	Incorrect ID	Too small results in difficult assembly to converter Too small results in friction between washer and converter, leading to shift in setpoints over life Too large results in poor location of converter, shift in setpoints or fragmentation Too large results in reduced discharge life	5	Broken, worn, or improperly set-up tools	Supplier process controls and TI Receiving inspection	3	45				
DISBURSER (C7176) Provides support for compression of gasket	Incorrect OD	Too large results in difficult assembly Too small results in poor location of converter, shift in setpoints or fragmentation	3	Broken or worn tools	Supplier process controls and TI Receiving inspection	3	29				
	Incorrect thickness	Too thick results in poor drive, leads to reduced discharge life or reduced burst capacity Too thin leads to bending	3	Wrong mat'l choice, supplier error	Supplier process controls and TI Receiving inspection	3	29				
DISBURSER (C7176) Transfers pressure from fluid to pressure-bearing element	Part	Reduced discharge life	5	Broken, worn, or improperly set-up tools	Supplier process controls and TI Receiving inspection	3	45				
	Insufficient material properties	Reduced discharge life	5	Broken, worn, or improperly set-up tools	Supplier process controls and TI Receiving inspection	3	45				
DISBURSER (C7176) Provides alignment and support to spacer and disc	Incorrect button dia	Too large results in difficult assembly to washer Too large results in friction between washer and converter, leading to shift in setpoints over life Too small results in poor location	5	Broken or worn tools	Supplier process controls and TI Receiving inspection	1	45				

TI-NHTSA 019058

Subsystem/Item: Speed Control Deactivate Pressure Switch
Design Responsibility: Steven R. Offiler
Other Areas Involved:

Suppliers and Plants Affected:
Model Year/Vehicle(s):
Outstanding Release Date:

Prepared by: Steven R. Offiler
PWS Date (09/07): 9/18/2008
Drawn: VAS/20

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	C C C	P P P	Potential Cause(s) of Failure	C C C	Design Verification	D V V	R P P	Recommended Review	Area/Individual Responsible & Completion Date	ACTION Actions Taken	RESULTS S U C C E S S F U L	DIS C U S S I O N
		cation of camshaft, shift in setpoints or inoperative Too small results in reduced discharge life												
	Bottom out of two-position rotation to disc locate feature	Difficult assembly Poor location of disc leading to inoperable device or shift in setpoints	3		Broken, worn, or improperly set-up tools	3	Supplier process controls and II Receiving Inspection	3	27					
	Incorrect geometry of disc locate features	Disc shifts relative to camshaft; shift in setpoints or inoperable device Camshaft bottoms against cup or disc wedge contacts do not open or contact gap too small	3		Broken, worn, or improperly set-up tools	3	Supplier process controls and II Receiving Inspection	3	27					
	Incorrect material	Excessive flow causes device degradation	3		Supplier error	1	Mat'I certification	1	3					
	Incorrect thickness	Too thick leads to assembly difficulty and/or disc pressure and inoperable device Too thin leads to excessive flow, device degradation	3		Supplier error	1	II Receiving Inspection	3	9					
	No vent hole	Trapped pressure behind disc leads to increase in setpoints & variations with temperature	5		Broken, worn, or improperly set-up tool	3	Supplier process controls and II Receiving Inspection	3	45					
	Incorrect geometry of OD	Too small causes difficulty with disc locating inoperable device Too large causes interference with cup, prevents operation or inoperable device	3		Broken, worn, or improperly set-up tool	3	Supplier process controls and II Receiving Inspection	3	27					
EPACOR 722950 Pushes function between disc and camshaft	OD too large	Causes disc to locate incorrectly to camshaft; or-ratic device operation, shift in setpoints or inoperable	5		Wrong punch	1	II process controls	3	15					
	OD too small	Excess friction in arms with-out proper tension disc wear, and shift in setpoints over life	5		Wrong punch	1	II process controls	3	15					
	Incorrect thickness	Excessive thickness causes reduced disc envelope; possible inoperable device Too thin leads to early wear-out, leading to excess disc friction and shift in setpoint	3		Supplier error	3	Supplier process controls and II Receiving Inspection	1	15					
	Improper Teflon coating	Too thin leads to early wear-out, leading to excess disc friction and shift in setpoint	5		Supplier error	3	Mat'I certification	1	15					
WISC 300063 Controls actuation and re-limes set-points of switch relative to applied force	Incorrect diameter	Harder assembly Inoperative device Incorrect calibration	1		Wrong stamping tool Wrong stamping tool	3	SPC	1	3					
	Excessive wear	Harder assembly Inoperative device Incorrect calibration	1		Worn or improperly set-up tool	3	SPC	1	3					
	Material composition	Shift in setpoints over life Reduced proof capability Disc fatigue failure	5		Supplier error Improper heat-treat	3	Mat'I certification II process controls	3	45					
	Excessive burr	Shift in setpoints over life	5		Worn tools	3	SPC	1	15					
	Wrong thickness	Too thin requires increased force to achieve setpoints; results in reduced life Too thick requires decreased force to achieve setpoints; reduced throw, inadequate contact gap	3		Supplier error	3	SPC	1	9					
QIF 027000 and 277123	Crush area geometry	Poor crush leads to reduced	5		Incorrect punch-off	3	Supplier process	3	45					

TLNHTSA 019069

Subsystem/Phase: Speed Control Mechanism Pressure Switch
 Design Responsibility: Stephen E. O'Neil
 Other Areas Involved:

Regulators and Flange ASPECTS:
 Total Year/Unit/Case:
 Engineering Release Date:

Prepared by: Stephen E. O'Neil
 NQA Date (Date): 7/18/98
 (Rev): 7/18/98

Part Name, Number & Description	Potential Failure Mode	Potential Effects of Failure	Criticality	Potential Cause(s) of Failure	Design Verification	Preventive Action	Area/Individual Responsible & Completion Date	ACTION	REMARKS	DATE	BY	DATE	BY
771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000	Provides crimpable area which holds pressure-sensor together	Incorrect	Good/best capability, reduced displacement life	Broken, worn, or improperly set-up tools	Controls and II Receiving Inspection								
Provides support for disc	Wrong material thickness	Too thick will not fit in assembly tooling disc	1	Supplier error	Supplier process controls and II Receiving Inspection	27							
Locates washer relative to other components	Wrong material	Too thin leads to reduced good/best capability, reduced displacement life	3	Supplier error	Mat'l certification	1							
Provides guide for transfer pin	Disc support bump geometry incorrect	Incorrect calibration	5	Broken, worn, or improperly set-up tools	Supplier process controls and II Receiving Inspection	45							
	Disc fatigue	Improper device											
	Geometry of washer locating step incorrect	Too high - excessive disc movement leads to increased displacement strain, incorrect calibration	3	Broken, worn, or improperly set-up tools	Supplier process controls and II Receiving Inspection	27							
		Too low - insufficient disc pressure, pre-wrapped disc and impregnated device											
		Disc small results in difficult assembly											
		Disc large results in poor location of component, shift in assembly or impregnation											
	Geometry of pin guide incorrect	Disc small results in pin sticking - may give erratic operation at temperature extremes	7	Broken, worn, or improperly set-up tools	Supplier process controls and II Receiving Inspection	63							
		Disc large results in shift in pin position, erratic electrical characteristics											
		Too short prevents proper alignment, results in dropped pins, impregnation or erratic operation											
		Too long may affect spring in loading											
SWITCHING PIN (74247)	Thickness incorrect	Too thin results in poor seal; leakage of materials from environment	7	Tooling set-up error	Supplier process controls and II Receiving Inspection	83							
Seal base assembly to sensor assembly		Too thick causes difficulty in final crimp, cracks in base flange, or impregnation/erratic sensor operation											
	ID incorrect	Too large - may not square uniformly around circumference	5	Broken, worn, or wrong extruder	Supplier process controls and II Receiving Inspection	45							
		Too small - won't assemble											
	OD incorrect	Too small - insufficient seal area	5	Broken, worn, or wrong extruder	Supplier process controls and II Receiving Inspection	45							
	Wrong material	Long-term degradation results in leakage	7	Supplier error	Mat'l certification	21							
	Poreosity in material	May result in leakage if combined with insufficient squaring	1	Supplier error	Supplier process controls and II Receiving Inspection	27							
SWITCHING PIN (74247)	Dimension incorrect	Disc large results in pin sticking - may give erratic operation at temperature extremes	7	Broken or worn tool	Supplier process controls and II Receiving Inspection	63							
Impregnates disc section to provide electrical contact		Disc small results in shift in pin position, erratic electrical characteristics											
Insulation electrical components from switch housing	Length incorrect	Too short - low outpoints or device open-circuited	3	Misaligned / wear-house error	Caught at pressure-test of 100% of finished parts	15							
		Too long - high outpoints, inadequate contact gap, contacts											

TI-NHTSA 019070

Subsystem/Name: Speed Control Diagnostic Procedure Switch
 Design Responsibility: Stephen E. Offiler
 Other Areas Involved:

Supplier and Plant: Offshore
 Model Year/Model/Chassis
 Engineering Release Date:

Directed by: Stephen E. Offiler
 Part Date (Orig): 9/18/94 Chg#: 918928

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S E U	C R I T	Potential Cause(s) of Failure	O C C	Design Verification	D E T	R F N	Recommended Actions	Assign/Individual Responsible & Completion Date	Actions Taken	RES U L T	U L T	U L T	U L T
CRUISE ENGINE (7977) Hold together base assembly and sprayer assembly	Material incorrect	Shift in setpoints with temp Current linkage to housing Pneumatic/liquid events or inoperable device	7		Supplier error	3	Mat'l certification	1	21							
	ID incorrect	Too large results in poor crisp Too small hinders assembly	3		Broken, worn, or in- properly set-up tooling	3	Supplier process controls and II Receiving inspection On-Line SPC	1	9							
	Length incorrect	Too long or short causes poor crisp low resistance to rotation of base rel. to ser- vice cracked base	5		Broken, worn, or in- properly set-up tooling	3	Supplier process controls and II Receiving inspection On-Line SPC	1	15							
	Material incorrect	Difficult or weak crisp Oxidation (if ferrous not AL)	5		Supplier error	3	Mat'l certification	1	15							
	Thickness incorrect	Too thin results in poor crisp Too thick results in diffi- culty cramping/wresting in disc	3		Supplier error	3	II Recv. inspection	3	20							

TI-NHTSA 019071

Part Name, Number & Description	Material Failure Mode	Potential Effect(s) of Failure	Severity	Frequency of Failure	Repair	Preventive Action	Recommended Action	Applicable Standards & Completion Date	SECTION 5 Action Taken	DATE	BY	CHKD	APPD
Engine V80 C4200 Cylinder head gasket to cover cylinder	Cracking of gasket material	Oil will seep into gas chamber - may cause explosion or compression loss Oil large quantity in shift in gas position, erratic electrical characteristics Gas short provides poor seal - gas will seep into gas chamber, resulting in erratic operation or erratic timing Gas loss may short spring to failure	7	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection							
	Thickness incorrect	Gas will seep into gas chamber, resulting in erratic operation Gas will seep into gas chamber, resulting in erratic operation Gas will seep into gas chamber, resulting in erratic operation	7	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection							
	Oil incorrect	Gas large - may not seep into gas chamber, resulting in erratic operation Gas small - can't absorb	5	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection							
	Oil incorrect	Gas small - insufficient seal area	5	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection							
	Wrong material	Long-term degradation: results in leakage	7	Supplier error	1	Part I certification							
	Flaking in material	Gas seeps into gas chamber if combined with insufficient seal area	1	Supplier error	1	Supplier process controls and II Monitoring Inspection							
Engine V80 C4200 Cylinder head gasket to cover cylinder	Supplier incorrect	Oil large quantity in gas chamber - may cause explosion or compression loss Oil large quantity in shift in gas position, erratic electrical characteristics	7	Broken or worn tool	1	Supplier process controls and II Monitoring Inspection							
	Length incorrect	Gas short - low compression or erratic operation Gas long - high compression, erratic operation, can't seal	7	Defective / worn - broken drive	1	Check up process - part of 20% of finished parts							
	Material incorrect	Shift in operation with temp Current leakage to housing Properly installed gasket or compression device	7	Supplier error	1	Part I certification							
Engine V80 C4200 Cylinder head gasket to cover cylinder	Oil incorrect	Gas large quantity in gas chamber Gas small - can't absorb	7	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection On-line SPC							
	Length incorrect	Gas long or short causes poor seal - low compression or variation of temp. to cover's cracked head	5	Broken, worn, or improperly installed	1	Supplier process controls and II Monitoring Inspection On-line SPC							
	Material incorrect	Defective or weak or big Corrosion (if surface not OK)	5	Supplier error	1	Part I certification							
	Thickness incorrect	Gas will seep into gas chamber Gas will seep into gas chamber, resulting in erratic operation	1	Supplier error	1	Part I certification							

Sacramento, Calif. General Francisco General
 Sacramento, Calif. General Francisco General

David W. Brown, Editor
David W. Brown, Editor

Prepared by: Stephen B. Miller
Date: 08-23-2009

[illegible]

TI-NHTSA 018073

Major: Special Control Procedures Research Unit
 Major: Engineering Section 1 Office
 Other: None

Qualifiers and Values of
 Qualifier Factors:
 Engineering Section 1

Control by Section 1, Office
 Date: 11/22/77

12070

Task Area, Major & Subtask	Functional Failure Mode	Potential Effects of Failure	Qualifiers and Values of Qualifier Factors	Potential Effects of Failure	Qualifiers and Values of Qualifier Factors	Recommended Actions	Recommended Actions	Completion Date	Action Taken	By	When	How	Where
Thrust	Thrust	Reduced thrust available, long-crested thrust	1	Reduced, zero, or irregularly set-up thrust	2	Supplier process controls and TI	Supplier process controls and TI	27					
	Heavy materials	Excessive loadings and/or irregular loading to landing	1	Supplier stress	1	Reg'l certification	Reg'l certification	1					
	Heavy fast-trackers	Excessive loadings and/or irregular loading to landing	1	Supplier stress	1	Reg'l certification	Reg'l certification	27					
	Insufficient ID	The small results in difficult assembly to converter	5	Reduced, zero, or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
		The small results in friction between converter and converter, leading to shift in trajectory over life											
		The large results in poor location of converter, shift in trajectory or trajectory											
		The large results in reduced discharge life											
	Insufficient ID	The large results in difficult assembly	3	Reduced or zero thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
		The small results in poor location of converter, shift in trajectory or trajectory											
	Insufficient thickness	The thick results in poor location of converter, shift in trajectory or trajectory	3	Heavy and/or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
Thrust	Thrust	Reduced discharge life	5	Reduced, zero, or irregularly set-up thrust	1	Supplier process controls and TI	Supplier process controls and TI	27					
	Irregularities in loading with discharge	Reduced discharge life	5	Reduced, zero, or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
	Insufficient thrust life	The large results in difficult assembly to converter	5	Reduced or zero thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
		The large results in friction between converter and converter, leading to shift in trajectory over life											
		The small results in poor location of converter, shift in trajectory or trajectory											
		The small results in reduced discharge life											
	Design out of thrust position relative to other thrust factors	Difficult assembly	1	Reduced, zero, or irregularly set-up thrust	1	Supplier process controls and TI	Supplier process controls and TI	27					
		The location of the thrust to irregularly thrust or shift in trajectory											
	Insufficient geometry of thrust factor	The shift relative to converter, shift in trajectory or trajectory	3	Reduced, zero, or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
		Converter thrust control and/or thrust geometry do not meet or control the thrust											
Thrust	Insufficient material	Excessive thrust factor discharge	1	Supplier stress	1	Reg'l certification	Reg'l certification	1					
	Insufficient thickness	The thick results in poor location of converter, shift in trajectory or trajectory	1	Supplier stress	1	TI Reg'l inspection	TI Reg'l inspection	1					
		The thick results in poor location of converter, shift in trajectory or trajectory											
	Thrust life	Excessive thrust factor discharge	5	Reduced or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					
	Insufficient geometry of thrust	The small results in difficult assembly to converter	1	Reduced, zero, or irregularly set-up thrust	3	Supplier process controls and TI	Supplier process controls and TI	27					

TI-NHTSA 019076

[illegible]

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DECISION MATRIX)

Document Number 503796

Page 1

Revision Level 0

Revision Date 4-May-86

Original (Invent) Date 28-Dec-93

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Vytoss

Key Date 1983

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	S a v	C l e s	Potential Cause(s) Mechanism(s) of Failure	C c u f	Current Design Controls	D a i b e	R P N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results	S a v	C l e	D c i	R P N
DIAPHRAGM (OR SEAL) (SR) (2x178) Form flexible element of fluid containment cavity		Fails to contain fluid.	Fluid leakage.	3		Gradual rupture over life due to improper design of supporting elements. Gradual rupture over life due to excessive stress/displacement. Gradual rupture over life due to stress concentrations caused by asymmetric strain distribution. Chemical attack due to incorrect material specified. Incorrect thickness (or 3 of layers) of diaphragm material. Insufficient manufacturing of diaphragm.	1	Burst, rupture, and thermal cycle tests. Material only recommended. Comparison of design with similar products.	1	2	CONFIDENTIAL						
Transfer pressure from fluid to pressure-transmitting elements.		Change in area of pressure transfer over life. Excessive change of pressure transfer over service pressure.	Fail to separate over life. Excessively high pressure needed to adequately force pressure transfer area; while signs on separate due to unpredictability at some pressure.	3 4		Diaphragm too stiff. Incorrect material specified. Diaphragm too soft. Incorrect material specified.	1 1	Life testing of characteristics at intermediate points. Force and pressure versus deflection testing to calculate effective areas.	1 1	3 6							

TI-NHTSA 019081

DESIGN - FAILURE MODES AND EFFECTS ANALYSIS

F2AC-1B091-0A

**PROPORTIONAL BRAKE VALVE
WITH SPEED CONTROL SWITCH**

1992 EN-53, EN-56

Prepared for

FORD

By

SURFACES

Division of JIRLITE Industries Inc.

October 18, 1991

TI-NHTSA 019082

SURFACES - DESIGN FAILURE MODES & EFFECT ANALYSIS (D.F.M.E.A.)

PRODUCT FAMILY: Brake Valves PRODUCT TYPE: PROPORTIONING WITH SPEED CONTROL SWITCH

CUSTOMER: FORD / DUTCH VEHICLE: EN-53, EN-56 D.F.M.E.A. NO.: 6876 REVISED: 26 Jul 79

ASSEMBLY: VALVE ASSEMBLY

ASSEMBLY PART NO.: 806076

FORD ASSEMBLY PART NO.: F24C-20091

CHANGE LEVEL: 01

CHANGE LEVEL: 0A

D.F.M.E.A. INDEXES CODES

P.O. - PROBABILITY OF OCCURRENCE

P.D. - PROBABILITY OF NON-DETECTION

F.S. - FAILURE SEVERITY

R.P. - RISK PRIORITY

ANALYST: J. HUTCHESON

DATE:

REVISED:

PAGE: 26 of 29

PART: SWITCH


PROCESS:

CHANGE LEVEL: 01

FEATURE & FUNCTION	FAILURE MODE	FAILURE MECHANISM	EFFECT OF FAILURE ON ASSEMBLY	SYSTEM	VEHICLE	D.F.M.E.A. INDEXES P.O. F.S. P.D. R.P.	DESIGN VERIFICATION PLAN	CORRECTIVE ACTION REQUIRED YES/NO/COMPL. DATE
1. Thrush	a. Slip thrush	a. Pinch too low - end plug ejected.	Sudden pressure loss.	Sudden loss of air brake.	Longer stopping distance without warning.	1 00 1 00	E.S. Strength test	
		b. Engagement length too short.	Delayed lock.	No pressure in rear brake.	Longer stopping distance.	1 00 1 00	E.S. Strength test	
2. 4" Cone Seal, sealing surface.	Leak	a. Curvature	Yuck	Sudden pressure loss.	Sudden longer stopping distance.	1 00 1 00	E.S. Environmental test and 2000 PSI	No
		b. Chamfer	Switch lock loss	Sudden pressure loss.	Sudden longer stopping distance.	1 00 1 00	E.S. Durability, Leak Test	No
		c. Underlap	Distorted irregularity. Leak	Sudden pressure loss.	Sudden longer stopping distance.	1 00 1 00	E.S. Low pressure leak test	No
3. Lock	Lock through slight leak	Friction	Pinched Lock	No pressure in rear brake	Longer stopping distance	1 00 1 00	E.S. Durability	No
4. Choked	Switch lock		None	None	Engage and control	1 5 1 1	E.S. Durability	No

REVISION

TI-NHTSA 019083



© 2012 by American Institute of Aeronautics and Astronautics
All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage or retrieval system, without permission in writing from the American Institute of Aeronautics and Astronautics, 1801 Alexander Bell Drive, Suite 1207, Reston, Virginia 20191-4400.

1000-444444
page 1 of 45
1000-444444
1000-444444

TI-NHTSA 018084



FOIA b(7)(D)
Exemption 7(D)
Unlawful disclosure
FOIA b(7)(D) : EXEMPTED BY 7(D) FROM DISCLOSURE

NAME	DATE	TIME	LOCATION	REMARKS
...	...	...	...	...

Printed on 1074 44 and 44 77
Revised for 1074 44 and 44 77

Submitted as Conference Paper

Polymers
• **Alkanes** C_nH_{2n+2} $n = 1, 2, 3, \dots$

TI-NHTSA 019085

Design FMEA

5-24

Occurrence, Continued

Occurrence Rating Table

The following table is used to estimate the failure rate and/or criteria to develop a rating for each cause.

PROBABILITY OF FAILURE	POSSIBLE FAILURE RATES	RANKING
Very High: Failure is almost inevitable.	≥ 1 in 2	10
	1 in 3	9
High: Repeated failures.	1 in 8	8
	1 in 20	7
Moderate: Occasional failures.	1 in 80	6
	1 in 400	5
	1 in 2,000	4
Low: Relatively few failures.	1 in 15,000	3
	1 in 150,000	2
Remote: Failure is unlikely.	≤ 1 in 1,500,000	1

- The Criteria column may be augmented by the FMEA Team to meet local requirements only if:
 - The table is used consistently throughout the engineering offices.
 - Supporting rationale for changes are documented and attached to the FMEA
 - Changes have been approved by local Ford Management and Quality Office.
- The criteria for rating "1" cannot be changed without prior approval of Environmental & Safety Engineering.

TABLE 7EFFECT OF TEMPERATURE ON INSTRON TEAR STRENGTH

1 Mil. H Film

Temp., °C	g/mil	
	MD	TD
22	6.0	10.6
50	7.5	9.3
100	7.5	7.9
150	7.4	8.1
200	7.2	9.1
250	7.3	9.7

TABLE 8BENDING RECOVERY OF FILMS FROM 180° BEND

	% Recovery				
	15 sec.	30 sec.	60 sec.	120 sec.	300 sec.
H Film (.002")	59	60	62	63	64
100 "Mylar"	43	50	51		
300 Cellophane	15	26	30		

2. Two mil H film (Roll 70-1-1) samples were stretched 1, 3 and 5% on the Instron Tester and both the work recovery and form recovery were measured in each case with and without a 30 second delay before recovery. Rate of deformation was 100%/minute and recovery permitted at the same rate. Summarized in Table 9 are the work and tensile form recovery data.

TABLE 9WORK AND FORM RECOVERY FROM TENSION

H Film (.002") Roll 70-1-1

	Work Recovery		Form Recovery		30 sec. delay
	% Stretch	Instantaneous	30 sec. delay	Instantaneous	
1%	MD	97	76	100+	100+
	TD	98	66	100+	100+
3%	MD	78	50	100+	91+
	TD	78	50	100+	91
5%	MD	59	44	88	80
	TD	58	41	87	78

H. Dynamic Mechanical Measurements

Dynamic mechanical measurements made by the Plastics Department up to 500°C have failed to reveal the presence of a glass transition temperature. This appears to be verified by the fact that the mechanical properties measured over wide temperature ranges have failed to indicate any discontinuities or changes in slope as in the case at the glass transition temperature.

R. M. Ikeda ** has found a mechanical loss peak at -60°C by use of the torsional pendulum. The height of the peak is nine times greater than the base value. This peak corresponds to the dielectric loss peaks found in this temperature range. After peaking at -60°C the loss value remains constant out to 250°C, the maximum temperature used by Ikeda.

I. Abrasion Resistance

H film has shown a high degree of resistance to abrasion suggesting its utility as a bearing material. The rate of abrasion for one mil H film with the Ball Sand Plast Abrader was 7.7 minutes/mil as compared to 4-5 minutes/mil for "Tedlar"® PVF Film.

III. Dimensional Stability

H film offers a high degree of dimensional stability at temperatures above the melting point of most polymers. As shown in Figure 11 the shrinkage is less than 1% at 300°C on belt cast film. Typical data are given in Table 10 where the shrinkage was measured after five minutes exposure to the indicated temperature.

TABLE 10

SHRINKAGE OF H FILM AT VARIOUS TEMPERATURES

Roll No.	% Shrinkage					
	130-1-2		134-1-1		100-1-1	
Temp. °C	MD	TD	MD	TD	MD	TD
200	0.25	0.66	0.14	0.14	0.00	0.43

** "H Film Infra Red Studies II" PWR-62-8 RM Ikeda

®Du Pont Registered Trademark

LEA:cam

-11-

TI-NHTSA 019080

TABLE 7

EFFECT OF TEMPERATURE ON INSTRON TEAR STRENGTH

1 Mil, H Film

<u>Temp., °C</u>	<u>g/mil</u>	
	<u>MD</u>	<u>TD</u>
22	6.0	10.6
50	7.5	9.3
100	7.5	7.9
150	7.4	8.1
200	7.2	9.1
250	7.3	9.7

TABLE 8

BENDING RECOVERY OF FILMS FROM 180° BEND

	<u>% Recovery</u>				
	<u>15 sec.</u>	<u>30 sec.</u>	<u>60 sec.</u>	<u>120 sec.</u>	<u>300 sec.</u>
H Film (.002")	59	60	62	63	64
100 "Mylar"	43	50	51		
300 Cellophane	15	26	30		

2. Two mil H film (Roll 70-1-1) samples were stretched 1, 3 and 5% on the Instron Tester and both the work recovery and form recovery were measured in each case with and without a 30 second delay before recovery. Rate of deformation was 100%/minute and recovery permitted at the same rate. Summarized in Table 9 are the work and tensile form recovery data.

TABLE 9

WORK AND FORM RECOVERY FROM TENSION

H Film (.002") Roll 70-1-1

	<u>Work Recovery</u>		<u>Form Recovery</u>		<u>30 sec. delay</u>
	<u>% Stretch</u>	<u>Instantaneous</u>	<u>30 sec. delay</u>	<u>Instantaneous</u>	
1%	MD	97	76	100+	100+
	TD	98	66	100+	100+
3%	MD	78	50	100+	91+
	TD	78	50	100+	91
5%	MD	59	44	88	80
	TD	58	41	87	78

LEA:cam

LEA:cam

-10-

H. Dynamic Mechanical Measurements

Dynamic mechanical measurements made by the Plastics Department up to 500°C have failed to reveal the presence of a glass transition temperature. This appears to be verified by the fact that the mechanical properties measured over wide temperature ranges have failed to indicate any discontinuities or changes in slope as in the case at the glass transition temperature.

R. M. Ikeda ** has found a mechanical loss peak at -60°C by use of the torsional pendulum. The height of the peak is nine times greater than the base value. This peak corresponds to the dielectric loss peaks found in this temperature range. After peaking at -60°C the loss value remains constant out to 250°C , the maximum temperature used by Ikeda.

I. Abrasion Resistance

H film has shown a high degree of resistance to abrasion suggesting its utility as a bearing material. The rate of abrasion for one mil H film with the Bell Sand Blast Abrader was 7.7 minutes/mil as compared to 4-5 minutes/mil for "Tedlar". PVF Film.

III. Dimensional Stability

K film offers a high degree of dimensional stability at temperatures above the melting point of most polymers. As shown in Figure 11 the shrinkage is less than 1% at 300°C on belt cast film. Typical data are given in Table 10 where the shrinkage was measured after five minutes exposure to the indicated temperature.

TABLE 10

SHRINKAGE OF E FILM AT VARIOUS TEMPERATURES

Roll No.	% Shrinkage					
	13D-1-2		13A-1-1		100-1-1	
Temp. °C	MD	TD	MD	TD	MD	TD
200	0.25	0.66	0.14	0.14	0.00	0.43

** "X Film Infra Red Studies II" Pub-62-8 RM Ikeda

*Du Pont Registered Trademark

LEA: cam

-11-

[illegible]

Subject/Part: Speed Control Decelerate Pressure Switch
 Design Responsibility: Stephen B. Offiler
 Other Areas Involved:

Supplier and Parts Effects:
 Model Year/Revision:
 Engineering Release Date:

Prepared by: Stephen B. Offiler
 RSH Date (Orig): 11/00/94 Chg#: 911188

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C r i t i c i t y	Potential Cause(s) of Failure	D i s c r i b e	Design Verification	D e s i g n C o n f i r m	E n g i n e e r i n g	Recommended Actions	Area/Individual Responsible & Completion Date	ACTION Item(s) Taken	E S S E N T I A L	C O N S I D E R A B L E	N E G L I G I B L E	Y E S	N O	N E E D E D	N E E D E D			
SWITCH (40516) Provides a system of slots which guide, locate, and physically support terminals Provides features to enhance the effectiveness of terminal staking Provides a dielectric surface for the electrical elements Provides physical isolation of the switch components Provides a reference surface which locates the electrical elements relative to the pressure sensor Provides a flange to compress the internal environmental seal Provides interference tabs to locate and temporarily hold the base in relation to the crimp ring prior to crimp Provides a flange surface for the crimp ring Provides lock tabs, base, and features which mate to electrical connectors Provides compression to environmental seal in connector	Fails to properly locate terminals Fails to properly guide the terminals - difficult insertion Fails to properly support the terminals Terminals move relative to each other or the base (such as under physical or thermal loading) Terminal staking is insufficient Shift/fluctuation in switch setpoints Current leakage between terminals Fails to physically isolate: ingress of water from environment Fails to properly locate the switch elements relative to the pressure sensor Excessive current leakage High contact resistance Contacts stuck open Contacts stuck closed Mating conn. falls off Difficulty installing wiring connector Base and sensor do not seat properly, causing shift in setpoints Insufficient seal causes leakage Mating connector will not fit High contact resistance/no continuity at pins Mating connector open-circuit w/ wiring connector installed Difficulty installing conn. Intermittent continuity Shift/fluctuation in switch setpoints	Terminals out of position Device will not assembly properly; yield loss in mfg. Terminals move relative to each other or the base (such as under physical or thermal loading) Loose terminals Shift/fluctuation in switch setpoints Crack of speed control system does not disengage High current leakage High millivolt drop Erratic or insensitive switch action Shift in setpoints Erratic or insensitive switch Excessive current leakage High contact resistance Contacts stuck open Contacts stuck closed Mating conn. falls off Difficulty installing wiring connector Base and sensor do not seat properly, causing shift in setpoints Insufficient seal causes leakage Mating connector will not fit High contact resistance/no continuity at pins Mating connector open-circuit w/ wiring connector installed Difficulty installing conn. Intermittent continuity Shift/fluctuation in switch setpoints			Incorrect dimensions and/or tolerances between slots and terminals Incorrect dimensions and/or tolerances between slots and terminals Insufficient land-in Excessively large dimensions of the terminal slots Incorrect material specified Incomplete understanding of staking operation/process Low insulation resistance Incorrect material specified Incorrect material specified Vergence of the reference surface Intrusion of other design elements into the plane of the reference surface Excessive clearance between mating features allow shift Excessive current leakage High contact resistance Contacts stuck open Contacts stuck closed Mating conn. falls off Difficulty installing wiring connector Base and sensor do not seat properly, causing shift in setpoints Insufficient seal causes leakage Mating connector will not fit High contact resistance/no continuity at pins Mating connector open-circuit w/ wiring connector installed Difficulty installing conn. Intermittent continuity Shift/fluctuation in switch setpoints																	
STATIONARY TERMINAL (36008) Provides a base blade for interconnection Provides a silver-inlay surface for electrical contact Provides a feature for device calibration Provides a feature for staking into base	High contact resistance/no continuity at pins Mating connector open-circuit w/ wiring connector installed Difficulty installing conn. Intermittent continuity Shift/fluctuation in switch setpoints	Device appears open-circuit w/ wiring connector installed Difficulty installing conn. Intermittent continuity Shift/fluctuation in switch setpoints																				

TI-NHTSA 018093

TI-NHTSA 018093

Subcomponent: Speed Control (switches Pressure Switch)
 Design Responsibility: Stephen B. Offiler
 Other Areas Involved:

Suppliers and Plants Affected:
 Model Year/Version(s):
 Engineering Release Date:

Prepared by: Stephen B. Offiler
 Date: 05/05/07 (Orig): 91W784 (Rev): 711180

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	E v e n t	C o n s e q u e n c e	Potential Cause(s) of Failure	D e s i g n U n c e r t a i n t y	D e s i g n F a u l t	Recommended Actions	Item/Individual Responsible Completion Date	ACTION Actions Taken	RE C O R D E D	RE C O R D E D	RE C O R D E D	RE C O R D E D
105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188	High resistance at contacts Intermittent continuity Contact resistance increases over life Improper alignment High contact resistance Provides a means blade for inspection Provides a warning point for the spring/variable contact Provides a feature for stacking into base Terminal loose in base High resistance at spring interface Loose spring Mount hole size/location bad Low contact force High contact force High resistance at movable terminal interface Mount hole size/location bad Transfer pin bump out of position or rubbing Length undersize Length oversize Diameter undersize Blowout oversize Hole undersize Hole oversize	Apparent open circuit Intermittent continuity Performance degradation over time Wg. shield loss (and cal. detected at pressure transducer) Device appears open-circuit w/ mating connector installed Device appears open-circuit w/ mating connector installed Difficulty installing conn. Intermittent continuity Shift/Fluctuation in switch setpoints Apparent open circuit Intermittent continuity Erratic operation Shift/Shift in setpoints Will not assemble to spring properly High millivolt drop across contacts Change in setpoints Disc fracture Apparent open circuit Will not assemble to terminal properly Spring failure over life Spring falls off movable term Loose wiring Loose spring Assembly difficulty Loose spring Assembly difficulty												

TI-NHTSA 019084

Subject/Name: Power Control Reciprocating Pressure Switch
 Design Responsibility: Stephen B. Offiler
 Other Areas Involved:

Supplies and Plants Affected:
 Model Year/Version(s):
 Engineering Release Date:

Prepared by: Stephen B. Offiler
 PWS Data (Orig): 718724 (Rev): 71118W

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	U w v	C r i t	Potential Cause(s) of Failure	D r a f t	Design Specification	D r a f t	Recommended Action	Item/Individual Responsible & Completion Date	ACTION	W h e n	E f f e c t	S e v e r i t y
POWER CONTROL (718724) Provides electrical switching interface with stationary terminal	Hollow point causes	Weak rivet - spring falls off												
	Hollow point undercuts	DIFFicult to rivet - loose eye												
	High contact resistance/no continuity	Device appears open-circuit w/ wiring connector installed Intermittent continuity												
	Resistance increases over life	Degradation of electrical parameters over time												
	Contacts weld	Device permanently closed-circuit; no response to fluid pressure												
	Weak secondary interconnect	Contact does not assemble to spring, or falls off												
SEALING COVERED Provides a hydraulic sealing surface per SAE J512 Provides external thread for installation into mating part Provides hex flange for 3/16" wrench Provides fluid passage to pressure-sensing elements Provides gland for internal sealant Provides flange which interlocks with other components to form pressure-sensing structure	Fails to seal	Leakage of brake fluid	7		Incorrupt surface finish specification Incorrupt external specification Inappropriately specified geometry Excessive pressure	1	Cross-check of part dimensions vs SAE standard Comprehensive qualification of design at tolerance limits Harsh testing to customer-specified limits	1	7					
	Fails to properly install in mating part	Damages threads in mating part during installation Does not allow installation	7	6 1 8	Threads specified incorrectly Threads specified correctly but not gaged per established SAE spec's Flaking buildup	7	Cross-check of applicable SAE and AMS standards	5	345	Completed and reviewed TI and customer gaging practices relative to actual good versus bad threads Completion Date: none assigned yet				
	Separately installs but fails to properly seat and seal	Brake fluid leakage	7	6 1 8	Threads specified improperly Threads specified correctly but not gaged per established SAE spec's Flaking buildup	7	Cross-check of applicable SAE and AMS standards	5	345	Completed and reviewed TI and customer gaging practices relative to actual good versus bad threads Completion Date: none assigned yet				
	Incorrect hex size	Damage to hex flats during wrenching 3/16" wrench does not fit	5		Hex feature improperly specified per established SAE/AMS spec's	1	Cross-check of applicable SAE and AMS standards	1	5					
	Fluid passage is too small	Electrical signal from switch is delayed or, pressure signal especially at very low temp. Subject to blockage by foreign matter	1		Inadequate size of fluid passage specified Inadequate review of Ford standard practices	1	Review of Ford standard practices Review of industry practices	1	9					
	Fluid passage is too large	Resulting thin wall section causes leakage: - during installation - during underhood service operations	7		Fluid passage specified excessively large	1	Torque testing	1	7					
	Fails to seal in	Leakage of brake fluid	7		Gland dimensions	1	Cross-check with	1	9					

TI-NHTSA 018095

Subsystem/Name: Speed Control
 Design Responsibility: Stephen E. Offiler
 Other Names Involved:

Supplier and Plants Affected:
 Model Year/Vehicle(s):
 Engineering Release Date:

Prepared by: Stephen E. Offiler
 NHTSA Date (or by): 9/18/74 (Rev): 9/11/88

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	C o n s e q u e n c e s	Potential Cause(s) of Failure	D e s i g n U n c e r t a i n t y	Recommended Actions	Owner/Individual Responsible & Completion Date	ACTION Initiated Taken	F e e l d e f e c t s	S e r i o u s n e s s i t y	T y p e o f f a i l u r e
CONNECT (741763) Provides fluid seal between support and diaphragm	Wrong size	Excessive gasket spacing distorts gasket, results in leak Excessive spacing results in improper assembly and reduced life of gasket leading to leak Insufficient spacing results in leak Gasket diameter too large, results in assembly difficulty Gasket diameter too small, results in leak									
	Wrong material	Reduced gasket life, leading to leak Permanent set after temperature exposure leads to leak									
DIAPHRAGM (741763) Provides flexible element of fluid containment sealing	Insufficient material properties	Reduced life leading to leak									
Transfer pressure from fluid to pressure-sense elements	Surface roughness	Reduced diaphragm life leading to leakage									
Provides a portion of the support surface for diaphragm	Incorrect chamfer	Shift in setpoints Reduced diaphragm life leading to leakage									
Provides support for compression of gasket	Bent	Reduced disc envelope, inoperative device Reduced gasket spacing results in leak									
Locates converter and disc with respect to sup	Wrong material	Improper hardness and/or strength leading to bending									
	Wrong heat-treatment	Improper hardness and/or strength leading to bending									
	Incorrect ID	Too small results in difficult assembly to converter Too small results in friction between converter and converter,									

TI-NHTSA 019097

Subsystems/Items: Engine Control Deactivate Pressure Switch
Design Responsibility: Stephen D. Offiler
Other Areas Involved:

Explosion and Flareup Affected:
Model Navy/Unhale(4):
Explosion Release Data:

Prepared by: Stephen H. Offler
 Date Rec'd (10-12): 9/19/76 (Rev): 9/19/76

[illegible]

Subsystem/Name: Speed Control Electronics Pressure Switch
 Design Responsibility: Stephen E. Offiler
 Other Name Involvement:

Suppliers and Plants Affected:
 Model Year/Configuration:
 Engineering Release Date:

Prepared by: Stephen E. Offiler
 PWH Date Orig: 7/18/94 Date: 9/11/98

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S e u. t.	C r i t.	Potential Cause(s) of Failure	O c c.	Design Verification	D e t.	R. F. M.	Recommended Actions	Area/Individual Responsible & Completion Date	ACTION Required	R e s.	C o n.	F. e.	J. S.	R. F. M.
		Small disc envelope; possible inoperative device															
		Too thin leads to early wear-out, leading to excess disc friction and shift in output															
	Improper Teflon coating	Too thin leads to early wear-out, leading to excess disc friction and shift in output															
DISC (28450)	Incorrect diameter	Winders assembly Inoperative device Incorrect calibration															
Controls actuation and release set-points of switch relative to applied force	Excessive wear	Winders assembly Inoperative device Incorrect calibration															
	Material degradation	Shift in output over life Reduced proof capability Disc fatigue failure															
	Excessive burr	Shift in output over life															
	Wrong thickness	Too thin requires increased force to achieve setpoints; results in reduced life Too thick requires decreased force to achieve setpoints; reduced thermal insulation contact gap															
Our 07208 and 07713	Crack area geometry incorrect	Four crack leads to reduced proof/burst capability, reduced discharge life															
Provides integrable area which holds pressure-sensor together	Wrong material thickness	Too thick will not fit in assembly tooling dies Too thin leads to reduced proof/burst capability, reduced discharge life															
Provides support for disc	Wrong material	Too soft or hard leads to poor wrap, reduced proof/burst capability, reduced discharge life															
Locates sensor relative to other components	Disc support loop geometry incorrect	Incorrect calibration Disc fatigue Inoperative device															
Provides guide for transfer pin	Geometry of sensor locating step incorrect	Too high - excessive disc envelope; leads to increased discharge stress, incorrect calibration Too low - insufficient disc envelope; pre-wrapped disc and inoperative device Disc small results in difficult assembly Disc large results in poor location of sensor, shift in output or inoperative															
	Geometry of pin guide incorrect	Disc small results in pin sticking - may give erratic operation at temperature extremes Disc large results in shift in pin position, erratic electrical characteristics Too short provides poor guidance, results in crushed pin, inoperative or erratic device Too long may short spring to															

TI-NHTSA 018099

Subsystem/Name: Speed Control Electromechanical Pressure Switch
 Design Responsibility: Stephen H. OFFILER
 Other Areas Involved:

Regulators and Flare Effects:
 Model Year/Revision(s):
 Engineering Business Data:

Prepared by: Stephen H. OFFILER
 FMEA Data Orig: 9/10/94 Date: 9/11/99

Part Name, Number & Description	Potential Failure Mode	Potential Effect(s) of Failure	S u b	C a u s e	P o t e n t i a l C o n s e q u e n c e s of Failure	O c c u r r e n c e	D e s i g n U n d e r l i n e	D e t e c t	R e v i s i o n	Recommended Action	Responsible Person	Completion Date	ACTION E	S	D	I	S	T	S
		Sealing																	
DISCONNECT RING (74277) Held together brass assembly and sensor assembly	Thickness incorrect	Too thin results in poor seal; leakage of materials from environment Too thick causes difficulty in final step, cracks in base flange, or incomplete/erratic device operation																	
	ID incorrect	Too large - may not engage uniformly around circumference Too small - won't assemble																	
	OD incorrect	Too small - inefficient seal area																	
	Wrong material	Long-term degradation results in leakage																	
	Poreosity in material	May result in leakage if combined with insufficient squeeze																	
DISCONNECT RING (74277) Transfers disc action to workable electrical contact	Diameter incorrect	Too large results in pin sticking - may give erratic operation at temperature extremes Too small results in shift in pin position, erratic electrical characteristics																	
	Length incorrect	Too short - low setpoints or device open-circuited Too long - high setpoints, inadequate contact gap, contacts won't open																	
	Material incorrect	Shift in setpoints with temp Current leakage to housing Fracture/chips: erratic or inoperable device																	
CRIMP RING (74277) Held together brass assembly and sensor assembly	ID incorrect	Too large results in poor crimp Too small hinders assembly																	
	Length incorrect	Too long or short causes poor crimp; low resistance to rotation of base rel. to sensor; cracked base																	
	Material incorrect	Difficult to work crimp Corrosion (if ferrum not Al)																	
	Thickness incorrect	Too thin results in poor crimp Too thick results in difficulty crimping/inserting in disc																	

TI-NHTSA 019100

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
[DESIGN FMEA]

Document Number: 503788
Revision Level: C
Revision Date: 4-24-90
Original (Issue) Date: 20 Dec 85

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Model Year(s): 1990

Key Date: 1993

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Cause(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	F a i l u r e C o n s e q u e n c e s	C u r r e n t D e s i g n C o n t r o l s	D e s i g n C o n t r o l s	R e c o m m e n d e d A c t i o n s	Responsibility & Target Completion Date	Action Results Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r a b l e
SLIDE VALVE (upside) Provides a system of slide which guide, locate, and physically support terminals.	Fails to properly locate terminals.	Terminals out of position.	3	Incorrect dimensions and/or tolerances specified between slide and terminals. Inadequate assembly design concept.	1	Comparison with dimensions of similar STPS product.	1	3						
	Fails to properly guide the terminals without insertion.	Slides will not assemble properly; yield loss in sub.	5	Incorrect dimensions and/or tolerances specified between slide and terminals. Insufficient lead-in.	1	Review with assembly equipment engineers to determine correct clearances and lead in.	1	5						
	Fails to properly support the terminals.	Terminals move relative to each other or the base (such as vertical physical or thermal expansion).	5	Incorrect material specified. Excessively large dimensions specified on terminal wires.	1	Comparison with design of similar STPS product.	1	5						
Provides features to enhance the serviceability of terminal wiring.	Terminal wiring is improperly terminated.	Loose terminals. Splicing/wiring in wrong locations.	5	Incomplete understanding of design of wiring features.	1	Comparison with design of similar STPS product. Wiring inspections.	1	5						
Provides a electric shield for the electrical equipment.	Current leakage between terminals or terminal-to- housing.	Improper shielding system.	1	Low insulation materials. Incorrect material specification.	1	Comparison with design of similar STPS product. Material evaluation.	1	3						

CONFIDENTIAL

TI-NHTSA 019101

12/20/93

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503786
Revision Level: C
Revision Date: 4 Nov 95
Original (Initial) Date: 20 Dec 93

Page: 2

System
Subsystem
X Component

Pressure Switch

Design Responsibility: Pressure Switch Group

Model Year(s)/Vehicle(s): Various

Key Date: 1993

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e r i o u s n e s s	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e r a t e	Current Design Controls	D e t e r m i n e d	R e l a t e d P r o b a b i l i t y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actual Taken	S e r i o u s n e s s	C o n s e q u e n c e s	D e t e r m i n e d	R e l a t e d P r o b a b i l i t y
BASE (PS) (see 1a) Provides physical closure of the switch components.	Fails to physically isolate: ingress of water from external environment.	High current leakage. High resistance drop. Erratic or inoperative switch action.	6	1	Insufficient material specified. Poor molded part design i.e. wall thickness too thin, etc.	1	Comparison with design of similar STPS product. Design review with molder. Mold flow analysis.	1	3							
Provides a reference surface which locates the switch elements relative to the pressure surface.	Fails to properly locate the switch elements relative to the pressure surface.	Shift in setpoints. Erratic or inoperative switch.	5	1	Warpage of the reference surface. Intrusion of other design elements into the plane of the reference surface. Excessive clearance specified between mating features.	7	Specification of tolerance on prod. Rough the surface to prevent intrusion of other elements. Tolerance stackup analysis.	1	5							
Provides a flange to compress the internal environmental seal.	Improper comprehension of internal environmental seal.	Waterproof impregnation only held to flange of outer. Excessive compression may prevent switch from seating correctly to sensor assembly.	7	1	Incorrect seal gland design. Warpage.	1	Review of standard gland design practice. Comparison to similar products. Failure specified on prod.	1	7	CONFIDENTIAL						

TI-NHTSA 019102

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 501766
Revision Level C
Revision Date 4-Nov-96
Original (initial) Date 20-Dec-93

Page 1

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects or Failure	S e r i o u s n e s s	C r i t i c a l	Potential Cause(s) Mechanism(s) of Failure	D i c t i o n a r y	Current Design Controls	D i s c r i m i n a t i o n	Recommended Action(s)	Res. Plan & Target Completion Date	Action Results Taken	S e r i o u s n e s s	C r i t i c a l	D i s c r i m i n a t i o n
BASE (PS) (48815) Provides interference tabs to locate and temporarily hold the base in position to the crimp ring prior to comp.	Failure to properly lock/unlock prior to comp.	Tab large only cause difficulty in assembly, base cracking, or prevent switch from locking to sensor. Tab small provides no effect, possibly affecting subsequent assembly operations.	5		Design of interference tabs is insufficient.	1	Calculation and superimposition to determine force of tabs Tolerance stackup analysis.	1	5					
Provides a large surface for the crimp ring.	Failure to provide adequate geometry for crimp ring.	Base loose or insufficient torque withstand. Base cracked.	7		Incorrect design of large for crimp ring.	1	Comparison with design of similar SNPS product.	1	7					
Provides lock tabs, keys, and features which mate to electrical connector.	Mating electrical connector doesn't fit properly.	Connector difficult to install. Connector falls off.	8		Connector geometry improperly specified.	1	Review of dimensions relative to mating connector prints.	1	8					
Provides compression to environmental seal in connector.	Mating connector seal is not properly compressed.	Ingress of matter into switch cavity. Connector difficult to install and/or falls off.	7		Connector geometry and/or surface conditions/finish is improperly specified. Incorrect material specified.	1	Review of dimensions relative to mating connector prints. Material evaluation.	1	7					

CONFIDENTIAL

TI-NHTSA 019103

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DEMON FMEA)

Document Number 503785
Revision Level D
Revision Date 28-May-98
Original (Inch) Date 20-Dec-93

Page 1

System
Subsystem
K Component Pressing Switch
Model Year(s)/Vehicle(s) Various

Design Responsibility Pressing Switch Group

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effects(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e d	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results				
											Action Taken	S e v e r i t y	C o n s e q u e n c e	D e t e r m i n e d	R e c o m m e n d e d A c t i o n(s)
STATIONARY TERMINAL (36488 & 36729)															
Provides a brass tab for interconnection.	Poor interconnection.	Device appears open- circuit resulting connector inched.	7		Contamination of brass tab. Material specified too thin.	1	Review design and dimensions of mating connector to ensure proper interference and wiping action.	1	7						
	Blade geometry improper	Difficult to install mating connector	5		Lead-in chamfers on terminal are insufficiently specified Material specified too thick.	1	Review design and dimensions of mating connector Comparison with design of similar SYPS product.	1	5						
		Device appears open- circuit. Intermittent continuity High resistance drop	7		Incorrect contact material specified Contamination Silver layer specified too thin.	1	Review of TI proprietary and general contact design info. Estimate points for degrees of contamination.	1	7	CONFIDENTIAL					
	Excessive loss of contact height dimension (mechanical loads)	Shift in set points over life.	7		Silver layer specified too thick.	1	Review of TI proprietary and general contact design info. Life Testing	1	7						
Erosion of contacts due to electrical loads.	Shift in setpoints over life. Intermittent or no continuity	7		Incorrect material specified for particular electrical loading	1	Review of TI proprietary and general contact design info. Review and testing with actual electrical loads.	1	7							

TI-NHTSA 019104

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503798
Revision Level 1
Revision Date 28 May 98
Original (NMSI) Date 20 Dec 93

Page 2

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) Various

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item / Function	Potential Failure Mode	Potential Effects of Failure	S 4 3 2 1	C 1 2 3 4	Potential Cause(s) Mechanism(s) of Failure	O 5 4 3 2 1	Current Design Controls	D 5 4 3 2 1	R P N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Actions Taken	S 4 3 2 1	C 1 2 3 4	O 5 4 3 2 1	R P N
STATIONARY TERMINAL (35665 & 36728) Provides feature for device connection	Poor calibration	Mfg. yield loss Shift in setpoints over life.	5	1	Design is excessively stiff. Design not a selective spring back. Material hardness is incorrectly specified. Initial position requires excessive deformation to calibrate. Design has inadequate strength to maintain calibration over life.	1	Mechanical (and/or FEA) Analysis Force deflection springback testing Testing with actual production calibration equipment	1	5							
Provides feature to ensure adequate seating into base.	Terminal is inadequately shaped into base	Large terminals Distortion in high output.	2	1	Incomplete understanding of design of seating features	1	Comparison of design with similar STPS product Seating evaluation	1	1		CONFIDENTIAL					
Provides feature which mates with plate in base for location of terminal	Fails to properly locate terminal.	Terminals out of position.	3	1	Incorrect dimensions and/or tolerances specified between plate and terminal. Inadequate seating design concept	3	Comparison of design with similar STPS product	1	3							
Provides electrical path from silver alloy contact to mating connector	Fails to provide adequate conductivity.	High resistance shown as high voltage drop.	5	1	Incorrect material specified. Inadequate contact design area	1	Calculations of resistance Testing	1	5							

TI-NHTSA 019105

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DEADIM FMEA)

Document Number 500750
Revision Level C
Revision Date 4-Nov-86
Origin (Print) Date 28 Dec 86

Page 1

System
Subsystem
X Category Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Vehicle

Key Date 1983

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C a u s e s	Potential Cause(s) Mechanism(s) of Failure	C o n t r o l s	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r t u r e
MOVABLE TERMINAL (36557)																
Provides a means blade for interconnection	Poor interconnection	Device appears open- circuit when connector installed.	7		Material specified too thin.	1	Review design and dimensions of mating connector to ensure proper interference and spring action.	1	2							
	Blade geometry improper.	Difficult to install mating connector.	5		Lead-in chamfers on terminal are insufficiently specified. Material specified too thick.	1	Review design and dimensions of mating connector Comparison with design of similar STPS product.	1	5							
Provides a mounting point for the spring wire lead.	Fails to allow proper spring wire distribution	Shift/backlash in switch contacts (loss stroke). Improper device (wire hole out completely). Bulky wire hole.	7		Rivet hole size is specified incorrectly. Rivet hole position is specified incorrectly. Support surface for spring is incorrectly specified. Choice of fastener style incorrect.	1	Compare with design of other products. Check with recommendations of rivet manufacturer. Testing	1	1		CONFIDENTIAL					
Provides means to secure adequate seating into base.	Terminal is inadequately seated into base.	Loose terminals. Shift/backlash in switch contacts.	7		Incomplete understanding of design of seating features.	1	Comparison of design with similar STPS product. Seating examinations.	1	7							

TI-NHTSA 019106

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number: 820790
 Revision Level: C
 Revision Date: 4-Nov-88
 Original (Incept) Date: 20-May-80

Page 2

System
 Subsystem
 X Component: Pressure Switch
 Model Name(s)/Vehicle(s): Various

Design Responsibility: Pressure Switch Group

Key Date: 1983

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	C o n s e q u e n c e s	D e t e c t i o n	R e s p o n s e
MOVABLE TERMINAL (34887) Provides to chassis which mate with shells in base for location of terminal	Failure to properly locate terminal.	Terminal out of position.	3		Incorrect dimensions and/or incorrect specified between slots and terminals. Inadequate mating design concept.	3	Comparison of design with similar STPS product	1	9		CONFIDENTIAL					
Provides electrical path from movable contact via spring to mating connector	Failure to provide adequate conductivity.	High resistance shown at high pressure drop.	3		Incorrect material specified. Inadequate cross- section area.	1	Calculations of resistance Testing	1	3		CONFIDENTIAL					

TI-NHTSA 019107

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(PERFORM PMEA)

Document Number 503781
Revision Level C
Revision Date 4 Nov 96
Original (Initial) Date 20 Oct 93

Page 1

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wagner

Case Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S = 1 = 2 = 3	C = 1 = 2 = 3	Potential Cause(s) Mechanism(s) of Failure	O = 1 = 2 = 3	Current Design Controls	D = 1 = 2 = 3	R = 1 = 2 = 3	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S = 1 = 2 = 3	O = 1 = 2 = 3	D = 1 = 2 = 3	R = 1 = 2 = 3
SPRING (34646) Provides contact force	Low contact force	High without deep groove contacts.	2	1	Incorrect geometry specified Incorrect material specified	3	Beam deflection equations Forecasted testing	1	15							
	High contact force	Chill in subpoints. Disc cracking over life	7	1	Incorrect geometry specified Incorrect material specified	3	Beam deflection equations Forecasted testing	1	21							
Provides electrical path between movable contact in movable terminal	Fails to provide adequate conductivity	High resistance shown as high without drop	2	1	Incorrect material specified Inadequate cross- section area	1	Calculations of resistance using $R = \frac{\rho L}{A}$ Testing	1	2							
Provides feature to interface with transfer pin	Fails to interface correctly with transfer pin	Spilling feature over life Chill in subpoints over life. Dipping transfer pin causes intermittent operation.	7	1	Inadequate height of feature specified Inadequate shape of feature specified. Improper position of feature specified.	1	Comparison of design with similar product Dimension and tolerance stackup analysis Actual measurement Testing	1	7		CONFIDENTIAL					
Provides feature to interface with movable contact	Fails to provide adequate mounting for movable contact	Intermittent or erratic operation Open circuit.	4	1	Hole size/position incorrectly specified. Flanges inadequate	1	Review mfg. recommendations Comparison of design with similar product Testing	1	8							
Latches movable contact	Fails to adequately locate movable contact relative to stationary contact.	High without drop over life. Excessive contact pressure over life	7	1	Spilling geometry incorrectly specified	1	Dimension and tolerance stackup analysis Testing	1	7							

TI-NHTSA 018108

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 801752
Revision Level: C
Revision Date: 4 May 86
Original (Initial) Date: 20 Dec 83

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch
Model Year(s)/Production Volume: _____

Design Responsibility: Pressure Switch Group

Key Date: 1992

Prepared By: C. Wygore

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Function	Potential Failure Mode	Potential Effects of Failure	S a v e	C i n c u r e	Potential Cause(s) Mechanism(s) of Failure	O c c u r e	Current Design Controls	D e t e r m i n e	R e l a t i v e	Recommened Action(s)	Responsibility & Target Completion Date	Action Results Actions Taken	S e v e r e	O c c u r e n c e	D e t e r m i n e	R e l a t i v e
SP-1000 (20000)	Provides feature for attachment to machine tool	Fails to properly attach to machine tool	Electric - intermittent operation. Shift in sequence Open or short circuit	2		Noted note size or position incorrectly specified. Flanges inadequate Choice of material type incorrect	1	Run inp. measurements Comparison of design with similar product Testing	1	4							
SP-1000 (20000)	Provides disc overtravel	Fails to allow disc overtravel	Shift in sequence. Disc cracking Device inoperative at assembly. Poor calibration	3		Incorrect geometry specified Incorrect material specified	3	Beam deflection inspection Forward deflection testing	1	15							
SP-1000 (20000)	Provides force to open contacts	Insufficient force to open contacts	Insufficient resistance to mechanical vibration. Shift in sequence.	4		Incorrect geometry specified. Incorrect material specified	1	Beam deflection inspection Forward deflection testing	1	4							
SP-1000 (20000)	Provides force to open contacts	Excessive force to open contacts	Shift in sequence. Disc cracking. Device inoperative at assembly. Poor calibration	3		Incorrect geometry specified. Incorrect material specified	3	Beam deflection inspection Forward deflection testing	1	21							

CONFIDENTIAL

TI-NHTSA 019109

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 501784
Revision Level: C
Revision Date: 1-Nov-96
Original (Issue) Date: 20 Dec-93

Page 1

System: _____
Subsystem: _____
Component: Pressure Section

Design Responsibility: Pressure Section Group

Model Year(s)/Vehicle(s): Various

Key Date: 1993

Prepared By: C. Vazirani

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S A V	C I H S	Potential Cause(s) Mechanism(s) of Failure	D C U F	Current Design Controls	D E I C	R P N	Recommended Actions	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S A V	C I H S	D C U F	R P N
SEALING (PRESS) Provides fluid seal between pump and discharge	Fail to provide adequate fluid seal	Excess fluid leakage	1	1	Insufficient compression specified. Very excessive compression specified, leading to displacement from gland Incorrect ID and/or OD leading to displacement from gland Incorrect cross-section shape specified Incorrect material specified, fluid incompatibility Incorrect design of sealing mechanism	1	Review of general seal design principles Manufacturer's recommendations Burst, impulse and thermal cycle tests Comparison with design of similar products	1	1		CONFIDENTIAL					

TI-NHTSA 019110

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503795
Revision Level: C
Revision Date: 4-Nov-95
Original (paper) Date: 20-Dec-93

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Model Year(s)/Vehicle(s): Various

Key Date: 1993

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) / Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r a b i l i t y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r a b i l i t y
CUP 27713 OR 27208 Prevents interchangeable hose which holds pressure sensor together.	Fails to provide a parallel geometry for clamp.	Leakage. Low level.	8		Clamp wall thickness incorrectly specified. Clamp wall height incorrectly specified. Incorrect material specified.	1	Burst and impulse testing. Comparison of design with similar product.	1	8							
Locates bearing, dampener, and pulley.	Fails to correctly locate bearing, dampener, or pulley.	Difficult assembly.	5		ID specified incorrectly.	1	Tolerance stackup analysis.	1	5	CONFIDENTIAL						
Provides support and location for disc.	Fails to support and locate the disc/coupler correctly.	Shift in setpoints. Erratic operation. Stuck open at assembly. Reduced disc life.	7		Incorrect disc on wedge specified. Bump stop-position incorrectly specified. Four surface condition of bump, no control specified.	1	Tolerance stackup analysis. Impulse testing.	1	7							
Provides guide for transfer pin.	Fails to guide transfer pin correctly.	Erratic operation. Device stuck short-circuit.	7		Pin guide geometry is incorrectly specified.	1	Tolerance stackup analysis.	1	7							
Provides portion of environmental seal gasket.	Fails to allow a proper environmental seal.	Leakage of media. Switch does not seal correctly to cup.	7		Surface condition required for good seal not understood or not correctly specified. Geometry incorrectly specified.	1	Environmental testing. Switch cavity pressurization testing. Review of standard gasket design rules.	1	7							

TI-NHTSA 019111

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503795
Revision Level C
Revision Date 4 May 89
Original (Initial) Date 20 Dec 82

Page 2

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Phase(s) Various

Key Date 1983

Prepared by C. Yarnall

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S = 1 = 2 = 3	C = 1 = 2 = 3	Potential Cause(s) Mechanism(s) of Failure	O = 1 = 2 = 3	Current Design Controls	D = 1 = 2 = 3	R = 1 = 2 = 3	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S = 1 = 2 = 3	O = 1 = 2 = 3	D = 1 = 2 = 3	R = 1 = 2 = 3
211P (211) CR (7228) Provides surface to interface with base switch assembly.	Fail to properly locate relative to switch.	Still is aspinous. Erratic or inoperative switch.	6		Incorrect geometry of mating surface specified.	1	Tolerance stackup analysis. Cross-section actual dimension for inspection of interface.	1	3	CONFIDENTIAL						
(Post-crimp- crimp) provides geometry for final assembly with switching	Fail to allow proper final assembly with crimp ring.	Erratic operation. Ingress of water. Cracked base	7		Post-crimp geometry is not controlled per design intent. Cup diameter incorrectly specified.	1	Tolerance stackup analysis. Bore torque testing.	1	1							

TI-NHTSA 019112

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 50-4716
Revision Level 0
Revision Date 6 Feb 65
Original (Initial) Date 20 Feb 64

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) Various

Key Date 1962

Prepared By J. Jaggard

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e r i o u s n e s s	E l e m e n t s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e d	R e c o m m e n d e d	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Actions Taken	S e r i o u s n e s s	D e t e r m i n e d	R e c o m m e n d e d
DIAPHRAGM (OR SEAL) (BP) (74171) Form 1. Seals between of fluid containing cavity	Fails to seal fluid.	Fluid leakage.	0		Gradual rupture over life due to improper design of supporting elements. Gradual rupture over life due to incorrect seamless placement. Gradual rupture over life due to stress concentrations caused by asymmetric stress distributions. Chemical attack due to incorrect material specified. Incorrect thickness (or # of layers) of diaphragm material. Insufficient location/clamping of diaphragm.	1	Stress, rupture, and thermal cycle tests. Material mg recommendation. Comparison of design with similar products.	1	1	1	CONFIDENTIAL				
Transfer pressure from fluid to pressure- sensing elements.	Change in area of pressure transfer over life. Excessive change of pressure transfer area versus pressure.	Shift in setpoints over life. Excessively high pressures needed to adequately form pressure transfer area; wide swing in setpoints due to irreproducibility of lower and higher.	1		Diaphragm too stiff. Incorrect material specified. Diaphragm too stiff. Incorrect material specified.	1	Life testing for characteristics of intermediate points. Force and pressure versus deflection testing to calculate effective stress.	1	1	1					

TI-NHTSA 019113

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN AREA)

Document Number 503757
Revision Level C
Revision Date 4-26-96
Original (initial) Date 20 Dec 93

Page 1

System
Subsystem
K Component Potable Supply

Design Responsibility Potable Switch Group

Model Year(s)/Vehicle(s) Veritas

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	E S S E N T I A L	C I T Y	Potential Cause(s) Mechanism(s) of Failure	D C C U R E N T D E S I G N C O N T R O L S	D R E P R E N S I B I L I T Y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Taken	S E R I O U S N E C E S S A R Y	O C C A S I O N A L	D I S T A N T	R E P A R A B L E
VALVE IN (PS) (2 NICH)	Provides a portion of the support surface for diaphragm.	Fails to correctly support the diaphragm	Reduced diaphragm life results in leakage.	6		Contours of diaphragm support surface are specified incorrectly (Condition of edges of support surface specified incorrectly (Clearance between washer I.D. and conometer bump is specified too small	1	Burst, Impulse, and Thermal Cycle tests Comparison of design with similar products							
Provides support for compression of gasket	Fails to give proper gasket compression.	Leakage.		8		Washer thickness is incorrectly specified or unspecified Washer thickness is specified too small Washer material and/or heat-treat is incorrectly specified	1	Burst, Impulse, and Thermal Cycle tests Comparison of design with similar products							
Locates and guides conometer with respect to cup.	Conometer is not properly located relative to cup	Shift in sealpoint. Erratic behavior.		5		Incorrectly specified bushing guide I.D. Incorrectly specified washer O.D.	1	Comparison of design with similar products. Tolerance stackup analysis							
	Conometer travel is restricted by washer.	Clack cannot release; gasket is stuck open- valued.		7		Washer thickness is incorrectly specified or unspecified. Washer thickness is specified too small Washer material and/or heat-treat is incorrectly specified I.D. of bushing guide is too small	1	Burst, Impulse, and Thermal Cycle tests Comparison of design with similar products Tolerance stackup analysis							

TI-NHTSA 018114

CONFIDENTIAL

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(POTENTIAL FMEA)

Document Number: 10797
Revision Level: C
Revision Date: 4 Nov 84
Original (Initia) Date: 20 Dec 83

Page 2

System: _____
Subsystem: _____
Component: Pressure Switch
Model Year(s)/Vehicle(s): Various

Design Responsibility: Pressure Switch Group
Key Date: 1985

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												As soon as pos sible	S e v e r i t y	O c c u r r e n c e	D e l a y	
WATER (PC) (27634)	Interface with cup feature and provide a portion of constant stick in cup.	Callout assembly washer O.D. too large. Poor washer/washer location relative to cup (washer O.D. too large).	7		Washer O.D. specified incorrectly	1	Comparison of design with similar products Tolerance stack up analysis	1	2	CONFIDENTIAL						
	Fails to allow proper crimp.	Reduced burst capacity leads to leakage. Reduced fatigue resistance leads to leakage.	8		Thickness incorrectly specified O.D. incorrectly specified Edge condition incorrectly or unspecified	1	Tolerance stack up analysis Burst, impact, and Thermal Cycle tests	1	8							

TI-NHTSA 019116

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 303758
Revision Level 5
Revision Date 13 May 86
Original (Issue) Date 20 Dec 93

Page 1

System
Subsystem
X Component Pressure Section
Model Year(s)/Vehicle(s) Various

Design Responsibility Pressure Switch Group

Key Date 1993

Prepared By D. H.

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S = 1 = 2 = 3 = 4	C = 1 = 2 = 3 = 4	Potential Cause(s) Mechanism(s) of Failure	O = 1 = 2 = 3 = 4	Current Design Controls	D = 1 = 2 = 3 = 4	R = 1 = 2 = 3 = 4	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S	O	D	R
CONVERTER (PS) (17104)	Transfers pressure from fluid bell diaphragm to a force on pressure sensing disc	Fails to correctly transfer fluid pressure to force on disc			Bellon O.D. incorrectly specified relative to washer I.D. Converter major O.D. incorrectly specified relative to cup I.D. Converter thickness incorrectly specified Incorrect material specified	1	Tolerance stackup analysis Force/deflection analysis to determine strength and resistance to plastic deformation Burst, impulse, and thermal cycle tests	1	5	CONFIDENTIAL						
Provides alignment and support to disc	Fails to properly align and support disc	Loose tolerances allow misalignment which may cause shift in sealpoint or erratic operation. Disc out-of-plane relative to converter may cause erratic operation or inoperative device, shock open- circuit.	5		Bellon O.D. incorrectly specified relative to washer I.D. Converter major O.D. incorrectly specified relative to cup I.D. Disc support bump incorrectly specified Disc mounting wall incorrectly specified	1	Tolerance stackup analysis Comparison of design with similar product	1	5							

TI-NHTSA 019116

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 500796
Revision Level E
Revision Date 11-May-98
Original (Initial) Date 20-Dec-93

Page 2

System
Subsystem
X Component Program Output

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By Dr. Ho

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	P o t e n t i a l C a u s e(s) M e c h a n i s m(s) o f F a i l u r e	O c c u r r e n c e F r e q u e n c y	C u r r e n t D e s i g n C h a r a c t e r i s t i c	D e t e r m i n e d P r o b a b i l i t y	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results				
											Action Taken	S	O	D	R
CONVERTER (PS) (37418)	Fails to properly support diaphragm.	Reduced diaphragm life results in leakage.	8		Condition of surface in contact with diaphragm are specified incorrectly. Condition of edges in contact with diaphragm are specified incorrectly. Clearance between converter base and wafler (D) are specified incorrectly.	1	Burst, impulse, and thermal cycle tests. Comparison of design with similar product.	1	2						
Provides disc support during over pressure (proofpoint)	Fails to properly support disc during over pressure.	Disc deformation results in shift in setpoints. Reduced disc travel if disc motion is restricted permanently. Reduced disc life.	8		Features which control disc motion during over pressure are incorrectly specified.	3	Pre and post-proof stress distribution Poststress-deflection measurements of disc motion.	1	18						
Vent in manifold prevents pressure buildup from shocking setpoints.	Does not vent properly.	Shift in setpoints over time. Reduced disc usage.	5		Vent hole incorrectly specified.	1	Comparison of design with similar product. Temperature characterization.	1	5						

CONFIDENTIAL

TI-NHTSA 019117

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DEFINITION AREA)

Document Number 501798
Revision Level C
Revision Date 4-10-95
Original (initial) Date 20-Dec 93

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Prototype Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wayne

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Supply

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S = V	C = =	Potential Cause(s) Mechanism(s) of Failure	O = C =	Current Design Controls	D = I =	R = P =	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S =	O =	D =	R =
SPACER (1355) Resists friction between disc and connector	Spoke is effectively rotated Motion.	Spoke is subjected over life. Reduced disc life.	1	1	Incorrect material specified. Incorrect dimension specified.	1	Input and Thermal Cycle Tests. Pre- and Post-life characterizations Tolerance stack-up analysis	1	5		CONFIDENTIAL					
Allow venting of chamber formed by disc and connector	Spoke is slow rotating.	Spoke is subjected over temp. Reduced disc action	1	1	Vent hole incorrectly specified	1	Comparison of design with similar product Temperature characterization	1	5		CONFIDENTIAL					

TL-NHTSA 019118

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503600
Revision Level C
Revision Date 4-May-98
Original (Issued) Date 20-Dec-93

Page 1

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1995

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D e t e c t i o n	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results					
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e s p o n s e	
CMC (partial)																	
Controls a cushion and release setpoints of cushion relative to applied force.	Failure to adjust and/or release at the proper points of assembly.	Slip, yield loss.	5		Dec material improperly specified. Dimensions and tolerances improperly specified.	1	Characterization experiments Comparison of design with service product.	1	5								
Key component in locking mobile service life of device	Dec solution and/or release setpoints change excessively over life.	Slip in device setpoints over life.	5		Dec material improperly specified. Dec heat-treat improperly specified Material thickness improperly specified Excessive force applied by spring.	1	Insulated testing Pre- and post- characterizations.	1	5		CONFIDENTIAL						
	Service life shorter than business requirements.	Drastic shift in setpoints over life. Device imperative - safety critical.	7		Dec material improperly specified. Dec heat-treat improperly specified Material thickness improperly specified Excessive force applied by spring.	1	Insulated testing Pre- and post- characterizations.	1	7								

TI-NHTSA 019119

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503801
Revision Level: C
Revision Date: 4-Nov-96
Original (Issued) Date: 29-Dec-93

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch
Model Year(s)/Vehicle(s): Various

Design Responsibility: Pressure Switch Group
Key Date: 1993

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C a u s e s o f F a i l u r e	D e t e c t i o n	C u r r e n t D e s i g n C o n t r o l s	O r i g i n a l P r e v e n t i o n	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results			
										Action Taken	S e v e r i t y	O c c u r r e n c e	R e p a r t i b i l i t y
CLAMP PLATE (74787) Holds together base assembly and sensor assembly.	Fails to hold base to sensor correctly.	Static switch operation. Caused base SAR in solenoid. Low base status displayed.	5	Incorrect geometry of clamping area specified. Incorrect geometry at formed edge Incorrect material specified	3	Impulse, thermal cycle, base fatigue, and base/terminal impact test	1 15						
Impacts a surface for part identification code	ID characters legible	Improperly identified parts or assembly plans	2	Geometry/tolerances not properly specified Wrong material specified	1	Coding tests Environmental tests	1 2						
Impart electromagnetic interference and disturbance to device	Ability to withstand environment	Corrosion causes excessive consumption, loss of mechanical properties, switch eventually fails off sensor. Moisture causes	7	Wrong material specified	1	Environmental tests	1 7						
Provides lubrication to cylinder base via oil capillary	Insufficient lubrication	Moisture/foreign matter enters device port(s)	3	Incorrect or insufficient oil specified	1	Clamping tests	1 5						

CONFIDENTIAL

TI-NHTSA 019120

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503607
Revision Level: C
Revision Date: 4-Nov-86
Original (Invent) Date: 20 Dec 83

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Model Type(s)/Variation(s): Various

Key Date: 1993

Prepared By: J. Wymer

Core Team: Design Engineers, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Adm Task	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e s p o n s e
TRANSFER PIN (2407g) Transfers elec trical signal to movable electrical contact	Fails to properly transfer electrical signal	Contacts stuck open. Contacts stuck closed. Erratic operation	7		Clearance incorrectly specified. Chip/fragments cause pin to lodge	1	Tolerances checked between pin and pin guide in cup Check with supplier for material properties regarding chips	1 2			CONFIDENTIAL					
WELDED Electrical components from switch housing	Fails to weld	Continuity between movable terminal and housing to ground	5		Wrong material specified	1	Check with supplier for material properties. Check with customer for electrical logic of movable terminal	1 5			CONFIDENTIAL					

TI-NHTSA 018121

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 507402
Revision Level: C
Revision Date: 4-Nov-95
Original (Initial) Date: 20-Dec-93

Page 1

System: _____
Subsystem: _____
Component: Program Switch
Model Year(s)/Version(s): Various

Design Responsibility: Precision Switch Group

Rev Date: 1993

Prepared By: C. Wagner

Core Team: Design Engineers, Manufacturing Engineers, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C o n s e q u e n c e s	Failure Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S	O	D	R
TRANSDUCER PIN (74078) Transmits elec signal to movable electrical contact	Fails to properly transfer elec motion	Contacts stuck open. Contacts stuck closed. Erratic operation.	7		Diameter incorrectly specified. Chips/fragments cause pin to lodge	1	Tolerance stacking between pin and pin guide in cup Check with supplier for material properties regarding chips	1	7	CONFIDENTIAL						
INSULATING electrical components from switch housing	Fails to insulate.	Connectivity between movable terminal and housing to ground.	5		Wrong material specified	1	Check with supplier for material properties Check with customer for electrical logic of movable housing	1	5							

TL-NHTSA 019122

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503803
Revision Level C
Revision Date 4 Nov 93

Page 1

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20 Dec 93

Model Year(s)/Vehicle(s) Verity

Key Date 1993

Prepared By C. Wagner

Case Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D e t e c t i o n	Current Design Controls	D i f f e r e n c e	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	E v a l u e	C o n f i r m	D i f f e r e n c e	R e p a r t u r e
ENVIRONMENTAL (SEAL 74247) Prevents ingress of water in switch cavity.	Carbonaceous matter in switch cavity.	High current leakage High voltage drop. Erratic or inoperative switch operation.	7		Tablet thickness is specified too small Liners (L) possibly not specified Incorrect material	1	Review of standard practice for gland design Review with gasket manufacturer Comparison of design with similar products	1	7	CONFIDENTIAL						
FUNCTIONAL FUNCTION TO AID IN mounting base assembly	Base rotates too easily	Perceived as inadequate by assembly plant and/or service personnel.	5		Gasket thickness improperly specified	1	Review of standard practice for gland design Torque-to-tighten testing Comparison of design with similar products	1	5	CONFIDENTIAL						

TI-NHTSA 019123

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(POTENTIAL FMEA)

Document Number: 501803
Revision Level: C
Revision Date: 4 Nov 86
Original (Issued) Date: 20 Dec 83

Page 1

System
Subsystem
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Key Date: 1993

Prepared By: C. Kappert

Model Year(s)/Release(s): Various

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D e t e r m i n e d	C u r r e n t D e s i g n C o n d i t i o n s	D e t e r m i n e d	R e c o m m e n d e d	R e s p o n s i b i l i t y & Target Completion Date	Action Results				
											Action Taken	S e v e r i t y	C o n s e q u e n c e s	D e t e r m i n e d	R e c o m m e n d e d
ENVIRONMENTAL L SEAL (74247) Prevents ingress of water to push cavity	Contaminants enter switch cavity.	High current leakage High rail-to-rail drop Erratic or no operation switch operation.	2		Gasket thickness is specified too small Units on poorly not specified Incorrect material	I	Review of standard practice for gland design Review with gasket manufacturers Comparison of designs with similar product	1	2						
PREVENTS INGRESS TO AND IN PREVENTING DRAIN REFUSION	Edible rodent too small	Permitted by manufacturer by assembly plant and/or service personnel.	1		Gasket thickness improperly specified	I	Review of standard practice for gland design Torque-to-torque testing Comparison of designs with similar product	1	2						

CONFIDENTIAL

TI-NHTSA 019124

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503804
Revision Level C
Revision Date 4-Nov-96
Original (Initial) Date 20-Dec-93

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1992

Prepared By C. Wagoner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S =	C =	Potential Cause(s) Mechanism(s) of Failure	O =	Current Design Controls	D =	R =	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S =	O =	D =	R =
THREAD CAP (TASS) Protects hexagon threads from damage during shipping and unpacking. Prevents dust from entering the fluid cavity.	Incorrect length.	Does not protect threads sufficiently.	3	1	Length inconsistency specified	1	Dimensional stack-up study	1	5							
	Loose Cap.	Allows dirt to enter fluid cavity.	4	1	Incorrect diameter specified	1	Dimensional analysis	1	4							

CONFIDENTIAL

TI-NHTSA 019126

POTENTIAL
FAILURE MODES AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 102806
Revision Level: C
Revision Date: 30-Oct-88

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch
Model Year(s)/Vehicle(s): Various

Design Responsibility: Pressure Switch Group

Original (Initial) Date: 20-Dec-83

Key Date: 1993

Prepared By: C. Pichner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e f r e q u e n c y	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r i t y	O c c u r r e n c y	D e t e c t i o n	R e s p o n s e
PERFORM 300000																
Provides a hydraulic sealing surface per SAE J512.	Fails to seal.	Leakage of brake fluid.	8	FF	Incorrect surface finish specification. Incorrect material specification incorrectly specified geometry. Excessive pressure.	1	Cross-check of print dimensions vs. SAE standard. Compare theoretical intersection of design at tolerance limits. But testing to customer specified limits.	1	9							
Provides external thread for installation into mating part.	Flare is properly thread in mating part.	Damage to threads in mating part during installation. Does not allow installation.	7	FF	Threads specified improperly. Threads not gauged per ANSI spec's. Flaring bulging.	3	Cross-check of applicable SAE and ANSI standards.	3	83							
	Apparentity installs, but fails to properly seal and seal.	Brake fluid leakage.	8	FF	Threads specified improperly. Threads not gauged per ANSI spec's. Flaring bulging.	1	Cross-check of applicable SAE and ANSI standards.	3	27							
Provides hint feature for 1/16" smooth.	Incorrect hint size.	Damage to hint hole during wrenching 1/16" smooth does not fit.	8		Hint feature improperly specified per established SAE/ANSI spec's.	1	Cross-check of applicable SAE and ANSI standards.	1	5							
Provides fluid passage to pressure-sensing element.	Fluid passage is too small.	Electrical signal from switch is delayed vs. pressure signal especially at very low levels. Subject to blockage by foreign matter.	7	FF	Inadequate size of fluid passage specified. Inadequate review of Ford standard practices.	1	Review of Ford standard practices. Review of industry practices.	1	7							
	Fluid passage is too large.	Recalling this will section causes blockage during installation during windshield service operations.	7	FF	Fluid passage specified excessively large.	1	Torque testing.	1	7							

CONFIDENTIAL

TI-NHTSA 019126

POTENTIAL
FAILURE MODES AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 502804
Revision Level: C
Revision Date: 30-Dec-95
Original (Initial) Date: 20 Dec 93

Page 2

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Key Date: 1995

Prepared By: C. Wigner

Model Year(s)/Vehicle(s): Various

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Rev Function	Potential Failure Mode	Potential Effect(s) of Failure	S E V E R I T Y	C O N S I D E R A B I L I T Y	Potential Cause(s) Mechanism(s) of Failure	D E T E C T I V I T Y	Current Design Controls	D E T E C T I V I T Y	R E P A R A B I L I T Y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Actions Taken	S E V E R I T Y	C O N S I D E R A B I L I T Y	D E T E C T I V I T Y	R E P A R A B I L I T Y
REPORT (38800)	Provides gland for internal gasket.	Falls to seal internal gasket properly.	9	1	Gland dimensions improperly specified. Surface finish improperly specified. Gland geometry improperly designed.	1	Cross-check with recommendations of gasket supplier. Comprehensive testing.	1	8							
	Provides flange which interfaces with other components to form pressure- sensor structure.	Dis. too large results in assembly difficulty. Flange too small results in bad component alignment. Flange too thick results in poor crimp. Flange too thin results in reduced burst capacity. Improper edge chamfer results in stress concentration which initiates crack.	8	1	Improper or incomplete specification of dimensions and tolerances.	1	Experiments and analysis to determine proper thickness for required strength. Tensile strength analysis. Print review.	1	9							
	Material too soft or weak.	Independable burst capacity. Change of shape during installation or subsequent service. Threads prone to damage, leads to leakage or rupture.	8	1	Improper material selection.	1	Comprehensive evaluation of physical properties.	1	9							
	Wegged edges.	Leakage of gas leads to leakage.	9	1	Improper material selection.	1	Review of material properties.	1	8							
	Material degrades in presence of working fluid(s).	Leakage	8	1	Improper material selection.	1	Cross-check with gasket products.	1	8							
	Insufficient environmental protection.	Long-term effect causes weakening of key areas which leads to leakage or rupture.	9	1	Improper or insufficient plating specification.	1	Comprehensive environmental testing.	2	27							

CONFIDENTIAL

TI-NHTSA 019127

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
[DESIGN AREA]

Document Number 503605
Revision Level C
Revision Date 30 Oct 86
Original (initial) Date 29 Dec 83

Page 3

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) Various

Key Date 1983

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Prepared By C. Knapik

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e	C o n s e q u e n c e	Potential Cause(s) Mechanisms of Failure	D e t e c t i o n	Current Design Controls	D e t e c t i o n	R e s p o n s e	Recommended Action(s)	Responsibility & Target Completion Date	Action Review				
												Action Taken	S	C	D	R
HEAD-OFF (35506) Provides range which identifies with other components in form pressure- sensitive structure.		Cosmetic problems.	8			I	Review of piping practices	3	27							

CONFIDENTIAL

TI-NHTSA 01912B

PeriCammer® **Moveable Caricou**
 P-2 (10 x 10000) ALPAA 4 (10, 10000-21) @
 PERI 10000 4.200
 10000.1000000000

**Design Responsibility & Issues in Cellular
Manufacturing in Manufacturing of Steel Rods**

[illegible]

TI-NHTSA 019129

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 508770 Page 1
 Revision Level 5
 Revision Date 5-Nov-96

System _____
 Subsystem _____
 Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-93

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By D. Hs

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effects(s) of Failure	S e v e r i t y	C a u s e s o f F a i l u r e	D e t e c t i o n	C u r r e n t D e s i g n C o n t r o l s	D e t e c t i o n	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results				
										Actual Taken	S e v e r i t y	O c c u r r e n c e	D i s c o n f i r m a n c y	R e p a r t i c i p l e
RIVET (74815) Fastens spring to movable terminal Provides a force between movable terminal and spring which causes intimate contact for current flow	Fails to adequately fasten spring to movable terminal.	Spring rotates about axis of rivet. Spring falls off movable terminal.	6	Improper rivet diameter for given hole sizes. Improper rivet length for given material thickness. Improper head size. Improper tubular feature. Improper material.	1	Rivet manufacturer recommendations. Compliance with similar products. Testing to determine torque to rotate spring.	1	5						
	Inadequate force between spring and movable terminal.	High resistance or no contact at interface of spring and movable terminal.	6	Improper rivet diameter for given hole sizes. Improper rivet length for given material thicknesses. Improper head size. Improper tubular feature. Improper material.	1	Rivet manufacturer recommendations. Compliance with similar products. Testing to determine torque to rotate spring.	1	5	CONFIDENTIAL					

TI-NHTSA 019130

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 507788
Revision Level C
Revision Date 4-Nov-90
Original (Initial) Date 29-Oct-93

Page 1

System
Subsystem
Component Purpose Switch

Design Responsibility Purpose Switch Group

Prepared By C. Wagner

Model Year(s)/Vehicle(s) Various

July Date 1993

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) / Mechanism(s) of Failure	C u r r e n t D e s i g n C o n t r o l s	D e f i c i e n c y	R e c o m m e n d e d A c t i o n (s)	Responsibility & Target Completion Date	Action Results / Action Taken	S e v e r i t y	C o n s e q u e n c e	E l e m e n t	R e p a r t
BASE P/S (MIS15) Provides a system of three switch units, locate, hold, and physically support terminals	Fails to properly locate terminals	Terminals not in position	3		Incorrect dimensions and/or tolerances specified between slots and terminals Inadequate stacking design concept	1	1 3							
	Fails to properly guide the terminal during assembly	Device will not assemble properly, yields loss or injury	6		Incorrect dimensions and/or tolerances specified between slots and terminals Insufficient lead-in	1	1 5							
	Fails to properly support the terminals	Terminals must attach to each other or the base (such as under physical or thermal loading)	5		Incorrect margin specified Excessively large dimensions specified on terminal slots	1	1 5							
Provides features to enhance the effectiveness of terminal stacking	Terminal stacking is insufficient	Loose terminals Substitution in switch components	2		Incomplete understanding of design of stacking features	1	1 5							
Provides a detecting medium for the electrical elements	Current leakage between terminals or terminal-to-housing	Improper switching action	5		Low insulation resistance Incorrect material specified	1	1 5							

CONFIDENTIAL

TI-NHTSA 019131

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503788
Revision Level C
Revision Date 4-26-90
Original (Initial) Date 28 Dec 91

Page 2

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) 1990

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	S E V	C I A V	Potential Cause(s) Mechanism(s) of Failure	O C C U R R E N C Y	Current Design Controls	O V E R A L L	R P N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results	A C T I O N	C O M P L E T E D	R E P A R E D	P R E V E N T
1000 (P01) (40518)	Provides physical isolation of the switch components	Fail to physically isolate: ingress of engine heat external environment	High current leakage High solvent drop Erratic or insensitive switch action	5		Incorrect material specified Poor material part design i.e. wall thickness too low, etc	1	Comparison with design of similar STP3 product Design review with molders Mold flow analysis	1	5							
	Provides a reference surface which locates the electrical elements relative to the pressure sensor	Fail to properly locate the switch elements relative to the pressure sensor	Shift in response Erratic or insensitive switch	5		Warpage of the reference surface Intrusion of other design elements into the plane of the reference surface Excessive clearance specified between mating features	1	Specification of flatness on part Review the surface to prevent intrusion of other elements Tolerances analysis	1	5		CONFIDENTIAL					
	Provides a flange to compress the internal subcomponent seal	Inadequate compression of integral environmental seal	Inadequate compression may lead to ingress of fluid Excessive compression may prevent switch from seating correctly to sensor assembly	7		Incorrect seal gland design Warpage	1	Review of standard gland design practice Comparison to similar products Flatness specification on part	1	7							

TI-NHTSA 019132

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503708
Revision Level C
Revision Date 4-Nov-96
Original (Initial) Date 20-Dec-93

Page 3

System
Subsystem
A Component

Potential Failure Mode

Design Responsibility Potomac Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wright

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item	Potential Failure Mode	Potential Effects of Failure	S	C	Potential Cause(s) Mechanism(s) of Failure	O	Current Design Controls	D	R	Recommended Action(s)	Responsibility & Target Completion Date	Action Results	S	O	D	R
Function			e	i		c		e	i			Notes	a	c	e	r
BASE (P4) (46515) Provides interference tabs to locate and temporarily hold the base in position in the clamp ring prior to clamp	Base is properly located prior to clamp	Too large may cause difficulty in assembly, base cracking, or permanent notch from seating is easier. Too small provides no effect, possibly affecting subsequent assembly operations	1	1	Design of interference tabs is insufficient	1	Calculation and experimentation to determine limits of fit Tolerance stack-up analyzed	1	5							
Provides a flange surface for the clamp ring	Flange is provided adequate geometry for clamp ring	Base loose or insufficient torque retained Base cracked	7	1	Incorrect design of flange for clamp ring	1	Comparison with design of similar STPS products	1	7		CONFIDENTIAL					
Provides lock tabs, keys, and features which mate to electrical connector	Mating electrical connector doesn't fit properly	Connector difficult to install Connector falls off	8	1	Connector geometry improperly specified	1	Review of dimensions, radius in mating connector parts	1	8		CONFIDENTIAL					
Provides compression to environmental seal in connector	Mating connector seal is not properly compressed	Ingress of water into switch cavity Connector difficult to install prior to seal off	7	1	Connector geometry and/or surface condition/finish is improperly specified Incorrect material specified	1	Review of dimensions relative to mating connector parts Adjust seal specification	1	7							

TI-NHTSA 019133

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FORM)

Document Number 150780
Revision Level 0
Revision Date 28 May 98
Original (Issued) Date 20 Dec 93

Page 1

System
Subsystem
Component

Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) V1000

Key Date 1993

Prepared By L. Wayner

Core Team Group Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D i c t i o n a r y	Current Design Controls	D e f i c i e n c y	R e p a r a b i l i t y	Recommended Action(s)	Responsible S. Target Completion Date	Action Results Taken	S e v e r i t y	D i c t i o n a r y	R e p a r a b i l i t y
STATIONARY TERMINAL (36596 & 36728)															
Provides a bulk head for interconnection	Poor interconnection	Device appears open- circuit, vibrating compressor installed	7		Contamination of bulk head Material specified too thin	1	Review design and dimensions of mating connector to ensure proper interference and sealing action	1	2						
	Blade geometry irregular	Difficult to install mating connector	5		Lead-in channels on terminal are insufficiently specified Material specified too thick	1	Review design and dimensions of mating connector Compressors with design of similar STPS product	1	5						
Provides a silver layer surface for electrical contact	Fails to provide adequate electrical contact	Device appears open- circuit Intermittent continuity High resistance drop	7		Incorrect contact material specified Contamination Silver layer specified too thin	1	Review of TI proprietary and general contact design info. Eliminate paths for ingress of contamination	1	7		CONFIDENTIAL				
	Excessive loss of contact height dimension (mechanical loads)	Shift in all points over life	7		Silver layer specified too thick	1	Review of TI proprietary and general contact design info. Life Testing	1	7						
	Excessive corrosion due to electrical loads	Shift in all points over life Intermittent or no continuity	7		Incorrect material specified for particular electrical loading	1	Review of TI proprietary and general contact design info. Review and testing with actual electrical loads	1	7						

TI-NHTSA 018134

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number: 50175
Revision Level: 0
Revision Date: 28 May 98
Original (Initial) Date: 20 Dec 93

Page 2

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Key Date: 1993

Prepared By: C. Wagner

Model Table(s)/Vehicle(s): Various

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Action Taken	S	O	R
STATIONARY TERMINAL (30000 & 30720) Provides interface for device operation	Post calibration	Mfg. yield loss Shift in supports over life.	2		Design is excessively stiff Design has excessive spring back Material hardness is incorrectly specified Initial position requires excessive deflection to calibrate Design has inadequate strength to maintain calibration over life	7	Mechanical (and/or FEA) analysis Force deflection springback testing Testing with actual production calibration equipment	1	5						
Provides interface to ensure adequate slaking into base	Terminal is inadequately slaked into base	Loose terminals Inadequate slaking into base	7		Incomplete understanding of design of slaking features.	7	Comparison of design with similar BPPS product Slaking evaluations	1	7		CONFIDENTIAL				
Provides interface which mate with slide in base for location of terminal	Fails to properly locate terminal	Terminal out of position.	2		Incorrect dimensions and/or tolerances specified between slide and terminals. Inadequate slaking design concept	2	Comparison of design with similar BPPS product	1	5		CONFIDENTIAL				
Provides electrical path from silver solder contact to mating connection	Fails to provide adequate conductivity	High resistance shown as high voltage drop	5		Incorrect material specified Inadequate cross- section area	1	Calculations of resistance Testing	1	2						

TI-NHTSA 019136

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503754
Revision Level C
Revision Date 2 Nov 92
Original (Initial) Date 29 Dec 93

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Williams

Core Team Design Engineers, Manufacturing Engineers, Manufacturing Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	Severity	Occurrence	Detectability	Potential Cause(s) Mechanism(s) of Failure	Current Design Controls	Occurrence	Severity	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Taken	S	G	D	R
MOVABLE TERMINAL (30007)																	
Provides a fast slide for wire connection	Fast installation	Device appears open, casual refueling connector twisted	7	1	1	1	Mislead specified too fast	Review design and dimensions of mating connector to ensure proper interference and mating action	1	1	2						
	Slide partially unresponsive	Difficult to install mating connector	5	1	1	1	Lead-in dimensions on terminal are insufficiently specified aligned specified too weak	Review design and dimensions of mating connector Compare with design of similar STPS product	1	1	5						
Provides a mounting post for the spring valve	Fast to allow proper spring/valve installation	Shift/rotation in valve post/pin (slide post) Inoperative device (valve fails out completely) Self yield loss	7	1	1	1	Rivet hole size as specified incorrectly Rivet not position as specified incorrectly Support surface for spring is incorrectly specified Choice of fastener style incorrect	Comparison with design of similar products Check with recommendations of rivet manufacturer Testing	1	1	1						
Provides features to ensure adequate seating and force	Terminal is adequately seated into hole	Leak is possible Self-healing is enough post/pin	7	1	1	1	Incomplete understanding of design of seating feature	Comparison of design with similar STPS product Seating evaluation	1	1	2						

CONFIDENTIAL

TI-NHTSA 019136

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number: 503780
Revision Level: C
Revision Date: 4 May 96
Original (Printed) Date: 20 Feb 83

Page 2

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Key Date: 1993

Model Year(s)/Version(s): Various

Prepared By: C. Wagner

Core Team: Design Engineers, Manufacturing Engineers, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S	O	D	R
MOVABLE TERMINAL (36887) Provides features which mate with slots in base for location of terminal	Fails to properly locate terminal	Terminals out of position	3		Incorrect dimensions and/or tolerances specified between base and terminals Inadequate racking during process	3	Comparison of design with similar BPS product	1	3		CONFIDENTIAL					
Provides horizontal path from movable contact via spring to mating connector	Fails to provide adequate conductivity	High resistance shown at high solvent drop	1		Incorrect material specified Inadequate cross- section area	1	Calculations of resistance Testing	1	3							

TI-NHTSA 019137

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 501192
Revision Level C
Revision Date 4 Nov 86
Original (issue) Date 20 Oct 83

Page 1

System
Subsystem
Component Prime Mover

Design Responsibility Prime Mover Group

Model Year(s)/Vehicle(s) Various

Key Date 1983

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C a u s e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	C u r r e n t D e s i g n C o n t r o l s	O f f e c t i v e n e s s	R e c o m m e n d e d A c t i o n s	Responsibility & Target Completion Date	Action Results Taken	S e v e r i t y	O f f e c t i v e n e s s	D i s c r i m i n a t i o n	R e p a r a b i l i t y
SP-1000 (2000) Provides contact force	Low contact force	High initial drop across contacts	6	Incorrect geometry specified Incorrect material specified	3	Beam deflection equations Force/deflection testing	1	15							
	High contact force	Shell in subpoints Disc cracking over life	7	Incorrect geometry specified Incorrect material specified	3	Beam deflection equations Force/deflection testing	1	21							
Provides electrical path from movable contact to stationary terminal	Fails to provide adequate conductivity	High resistance shows as high initial drop	5	Incorrect material specified Inadequate cross- sectional area	1	Calculations of resistance using $R = \rho(l/A)$ Testing	1	2		CONFIDENTIAL					
Provides contact to interface with transfer pin	Fails to interface correctly with transfer pin	Spring failure over life Shell in subpoints over life Eccentric transfer pin causes intermittent operation	7	Inadequate length of feature specified Inadequate shape of feature specified Intentional position of feature specified	1	Comparison of design with similar product Dimension and tolerance stackup analysis Actual measurement Testing	1	7							
Provides feature for attachment to movable contact	Fails to provide adequate flange for adequate contact	Intermittent or erratic operation Open circuit	8	Hole misposition incorrectly specified Fit/finish inadequate	1	Real ing recommendations Comparison of design with similar product Testing	1	6							
Locates movable contact	Fails to adequately locate movable contact relative to stationary contact	High initial drop over life Excessive contact resistance over life	7	Spring geometry incorrectly specified	1	Dimension and tolerance stackup analysis Testing	1	7							

TI-NHTSA 019139

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN PAREA)

Document Number 12345
Revision Level C
Revision Date 4 Nov 96
Original (Initial) Date 20 Dec 93

Page 2

System _____
Subsystem _____
Component Pressure Switch
Model Year(s)/Part(s) Various

Design Responsibility Pressure Switch Group

Key Date 1803

Prepared By C. Ruffner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D e t e c t i o n	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Actions Taken	S e v e r i t y	D e t e c t i o n	R e p a r t u r e
SPRING (44444) Provides return for attachment to movable terminal	Fail to properly attach to movable terminal	Elastic or intermittent operation Stall in sequence Open or short circuit	4	1	Pivot hole size or position incorrectly specified Fineness inadequate Choice of material style incorrect	1	Pivot mtg recommendations Comparison of design with similar product Testing	1	5						
Alarm BSC outward	Fail to show out- overload	Stall in response Over cranking Device inoperative at assembly Poor calibration	5	1	Incorrect geometry specified Incorrect material specified	2	Beam deflection equations Force/deflection testing	1	10						
Housing base in open contacts	Inadequate force in open contacts Excessive force in open contacts	Insufficient resistance to mechanical vibration Short circuit Stall in sequence Over cranking Device inoperative at assembly Poor calibration	4 7	1 3	Incorrect geometry specified Incorrect material specified Incorrect geometry specified Incorrect material specified	1 3	Beam deflection equations Force/deflection testing Beam deflection equations Force/deflection testing	1 1	4 21						

CONFIDENTIAL

TI-NHTSA 019139

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 562794
Revision Level C
Revision Date 4 Nov 95
Original Issue Date 20 Dec 93

Page 1

ch Design Responsibility Pressure Switch Group

Key Date 1993

Prepared By C. Wayner

Core To

Endpoints, Manufacturing Quality

Item Function	Mode	Effect of Failure	R a n k	C l a s s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e	R e c o m m e n d e d A c t i o n s	Responsibility & Target Completion Date	Action Results Action Taken	S e v e r e n e s s	O c c u r r e n c e	D e t e r m i n e	R e p a r t u r e
GASKET (74353) Provides fluid seal between flanges and headflange	Fail to provide adequate fluid seal	Broken fluid leakage.	1	1	Insufficient compression specified Very excessive compression specified, leading to displacement from gland Incorrect ID and/or OD leading to displacement from gland Incorrect cross-section shape specified Incorrect material specified, and inadequately incorrect design of sealing arrangement	1	Review of general and design principles Manufacturer's recommendations Burst, rupture and thermal cycle tests Comparison with design of similar products	1	9	CONFIDENTIAL					

TI-NHTSA 019140

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 5017-55
Revision Level C
Revision Date 4 Nov 90

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Original Issue Date 20 Dec 93

Model Year(s) / Mileage(s) / Variant

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	S A V	C I A V	Potential Cause(s) Mechanism(s) of Failure	O C A U S E	Current Design Controls	D A P R S	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S	O	C	R
22P (27713 OR 27728)	Provides shrapnel area which holds pressure sensor together	Fail to provide a suitable geometry for comp. Leakage Low burst		6		Comp wall thickness incorrectly specified Comp wall height incorrectly specified incorrect material specified	1	Burst and impulse testing Comparison of design with similar product	1	5						
	Prevents leakage through diaphragm, and washer	Fail to correctly locate support, diaphragm, or washer	Difficult assembly	1		ID specified incorrectly	1	Tolerance stackup analysis	1	5						
	Provides support and location for disc	Fail to support and locate the disc/corvette correctly Shift in setpoints Excess operation Shock upon assembly Reduced disc life		7		Incorrect disc envelope specified Bump location incorrectly specified Poor surface condition of bump, no control specified	1	Tolerance stackup analysis Impulse testing	1	7						
	Provides guide for transfer pin	Fail to guide transfer pin correctly Erratic operation Device stuck when closed		7		Pin guide geometry is incorrectly specified	1	Tolerance stackup analysis	1	7						
	Prevents portion of environmental test gases	Fail to allow a proper environmental test Ingress of matter Switch does not seal correctly to cup. Geometry incorrectly specified		7		Surface condition required for good seal not understood or not correctly specified	1	Environmental testing Switch cavity permeation testing Review of standard good design rules	1	7						

CONFIDENTIAL

TI-NHTSA 019141

☐ System
☐ Subsystem
☒ Component

Pressure Switch

POTENTIAL
 FAILURE MODE AND EFFECTS ANALYSIS
 (DESIGN FMEA)

Design Responsibility Pressure Switch Group

Document Number 563796
 Revision Level C
 Revision Date 4 Nov 96
 Original (Initial) Date 20 Dec 93

Page 2

Model Year(s)/Version(s) Variant

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineers, Manufacturing Engineers, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	D e v	C l a s s	Potential Cause(s) Mechanism(s) of Failure	O c c u r	Current Design Controls	D e f i c i e n c y	R e p a r a b l e	Recommended Actions	Responsibility & Target Completion Date	Action Results					
												Action Taken	S e v	D e t	O c c u r	R e p a r a b l e	
CLIP (37712 OR 37286) Provides surface to interface with base/switch assembly	Fail to properly locate relative to switch	Switch is inoperative. Exhibit to inoperative switch.	6		Incorrect geometry of mating surface specified	1	Tolerance stackup analysis. Cross-section actual devices for inspection of shape	1	5								
Post sensor-crimp provides geometry for base assembly with crimp ring	Fail to allow proper fit assembly with crimp ring	Exhibit operation Ingress of moisture Cracked base	7		Post-crimp geometry is not controlled per design intent. Cup diameter incorrectly specified	1	Tolerance stackup analysis. Base torque testing	1	7								

CONFIDENTIAL

TI-NHTSA 019142

POTENTIAL FAILURE MODE AND EFFECTS ANALYSIS (DESIGN FMEA)

Document Number: 503764
Revision Level: D
Revision Date: 4 Nov 95
Original (first) Date: 20 Dec 93

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Prepared By: C. Yung

Model Year(s)/Vehicle(s): Vehicle

Key Date: 1993

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S I M S	C I M S	Potential Cause(s) Mechanism(s) of Failure	D C C M I	Current Design Controls	D R P E N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Action Taken	S e v e r e	O c c u r r e n c e	D e t e c t i o n	R e p a r a b l e
DIAPHRAGM (OR SEAL) (SW) 74179 Form flexible element of fluid containment cavity	Fail to contain fluid.	Fluid leakage	B		Gradual rupture over life due to improper design of supporting elements Gradual rupture over life due to excessive pressure/displacement Gradual rupture over life due to stress concentrations caused by asymmetric strain distributions Chemical attack due to incorrect material specified Incorrect thickness for # of layers of diaphragm material Insufficient location/jumping of diaphragm	1	Burst, impulse, and thermal cycle tests Material mg recommendation Comparison of design with similar products	1 5		CONFIDENTIAL					
Transfer pressure from fluid to pressure- sensing element(s)	Change in area of pressure transfer over life Excessive change of pressure transfer area versus pressure.	Shift in setpoint over life Excessively high pressure needed to adequately form pressure transfer area, with shifts on setpoint due to unpredictability of lower pressure.	S E		Diaphragm too stiff incorrect material specified Diaphragm too soft Incorrect material specified	1 1	Life testing w/ characteristics at intermediate points Force and pressure versus deflection testing to calculate effective area.	1 5 1 5							

FIN-111

TR-NHTSA 019143

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(POTENTIAL FMEA)

Document Number 502767
Revision Level C
Revision Date 4 Nov 96
Original (mkz) Date 26 Dec 93

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) 1993

Key Date 1993

Prepared By C. Vignier

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

new Function	Potential Failure Mode	Potential Effect(s) of Failure	S = v s	C = a s	Potential Cause(s) Mechanism(s) of Failure	O C C U r r e n c e	Current Design Controls	D E P N	Recommended Action(s)	Responsibility & Target Completion Date	Action Return	S = v s	O C C U r r e n c e	D E P N
WASHER (PS) (27826) Provides a portion of the support surface for diaphragm	Fails to correctly support the diaphragm	Reduced diaphragm life results in leakage.	2	1	Condition of diaphragm support surface are specified incorrectly Condition of edges of support surface specified incorrectly Clearance between washer (D) and converter bump is specified too wide	1	Burst, impulse, and Thermal Cycle tests Comparison of design with similar products	1	2					
Provides support for compression of gasket	Fails to allow proper gasket compression	Leakage	2	1	Washer thickness is incorrectly specified or unspecified Washer thickness is specified too small Washer material and/or heat-treat is incorrectly specified	1	Burst, impulse, and Thermal Cycle tests Comparison of design with similar products	1	2					
Locates and guides converter with respect to cup	Converter is not properly located within the cup	Shift in setpoints Erratic behavior	2	1	Incorrectly specified bush guide (D) Incorrectly specified washer (D)	1	Comparison of design with similar products Tolerance stackup analysis	1	2					
	Converter travel is restricted by washer.	Erratic release, device is stuck open circuit	2	1	Washer thickness is incorrectly specified or unspecified Washer thickness is specified too small Washer material and/or heat-treat is incorrectly specified (D) at bush guide is too small	1	Burst, impulse, and Thermal Cycle tests Comparison of design with similar products Tolerance stackup analysis	1	2					

CONFIDENTIAL

TI-NHTSA 019144

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESRM FMEA)

Document Number 51171
Revision Level 1
Revision Date 4 Nov 95
Original (inset) Date 20 Dec 93

Page 2

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Prepared By C. Wagner

Model Year(s)/Vehicle(s) Vaux

Key Date 1993

Core Team Design Engineering Manufacturing Engineering Manufacturing Quality

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	D e s i g n e r r	Concurrent Design Concern	D e s i g n e r r	R e c o m m e n d e d A c t i o n s	Responsibility & Target Completion Date	Action Results	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r a b l e
WASHER (PS) (27830)	Interface with cup fixture and provides a portion of component stack for comp	Fails to interface correctly with cup	Difficult assembly Washer O.D. too large Poor washer/cup interface Leakage relative to cup Washer O.D. too small	7		Washer O.D. specified incorrectly	1	Comparison of design with similar products Tolerance stack-up analysis	1	7						
	Fails to allow proper crimp	Reduced burst capacity leads to leakage Reduced leakage resistance leads to leakage	8		Thickness incorrectly specified O.D. incorrectly specified Edge condition incorrectly or unsupported	1	Tolerance stack-up analysis Burst impulse, and Thermal Cycle tests	1	8							

CONFIDENTIAL

TI-NHTSA 019145

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503795
Revision Level: E
Revision Date: 13 May 98
Original (Issue) Date: 29 Dec 93

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch
Model Year(s)/Article(s): Various

Design Responsibility: Pressure Switch Group
Key Date: 1993

Prepared By: DAH

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Rev Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) at Failure	D e t e r m i n e d	Current Design Controls	O p e r a t i n g	R e p a r i n g	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e r m i n e d	R e p a r i n g
CONVERTER (PS) (27408)	Transfers pressure from fluid (and diaphragm) to a force on pressure sensing disc	Fails to correctly transfer fluid pressure to force on disc	5	Shift in sealpoint	Bulge O D incorrectly specified relative to rubber ID Converter major O D incorrectly specified relative to cup ID Converter thickness incorrectly specified Incorrect material specified	1	Tolerance stack-up analysis Force/deflection analysis to determine strength and sealant to plastic deformation Burst, impulse, and Thermal cycle tests	1	5			CONFIDENTIAL				
Provides alignment and support to disc	Fails to properly align and support disc	Loose tolerances allow misalignment which may cause drill in sealpoint or erratic operation. Out-of-true place relative to converter may cause erratic operation of pressure sensing device, fluid operation	5		Bulge O D incorrectly specified relative to rubber ID Converter major O D incorrectly specified relative to cup ID Disc support bump incorrectly specified Disc retaining wall incorrectly specified	1	Tolerance stack-up analysis Comparison of design with sample product	1	5							

TI-NHTSA 019146

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503796
Revision Level E
Revision Date 13-May-96
Original (Initial) Date 20-Dec-93

Page 2

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Prepared By D. Ha

Model Year(s)/Vehicle(s) Variant

Key Date 1993

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e r i o u s n e s s	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	D e t e c t i o n	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsible & Target Completion Date	Action Results				
												Actions Taken	S	O	D	R
CONVERTER (PE) (27405) Provides a portion of the support surface for diaphragm	Failure to properly support diaphragm	Reduced diaphragm life results in leakage.	5		Contour of surface in contact with diaphragm are specified incorrectly Condition of edges in contact with diaphragm are specified incorrectly Clearance between converter frame and washer I.D. are specified incorrectly	1	Burst, impulse, and Thermal cycle tests Comparison of design with similar product	1	5							
Provides disc support during over pressure (protrusion)	Failure to properly support disc during over pressure	Disc deformation results in shift in setpoints Reduced disc travel if disc motion is restricted prematurely. Reduced disc life.	5		Features which control disc motion during over pressure are incorrectly specified	2	Pre and post proof characterization Pressure-deformation measurements of disc motion	1	16							
Vent in converter prevents pressure buildup from affecting setpoints	Does not vent properly	Shift in setpoints over time Reduced disc life	5		Vent hole incorrectly specified	1	Comparison of design with similar product Temperature chamber evaluations	1	5							

CONFIDENTIAL

TI-NHTSA 019147

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 507799
Revision Level C
Revision Date 4-Nov-86
Original (Initial) Date 20 Dec 84

Page 1

System
Subsystem
A Component

Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) Various

Key Date 1980

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) (Mechanisms) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Actions Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n
SPACER (Yokes) Reduce friction between disc and conveyor	Fail to effectively reduce friction	Shut is subjected over life. Reduced disc life.	5		Increased material wear/loss Increased dimensions specified	1	Impulse and Thermal Cycle tests Pre- and Post-Me characterizations Tolerance stackup analysis	1	5						
Allow venting of chamber formed by disc and conveyor	Fail to allow venting	Shut is subjected over temp Reduced disc action	5		Vent hole incorrectly specified	1	Comparison of design with similar product Temperature characterization	1	5						

CONFIDENTIAL

TI-NHTSA 019148

System
Subsystem
Component Prognosis Switch

Model Year(s)/Vehicle(s) Various

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

POTENTIAL FAILURE MODE AND EFFECT ANALYSIS (DESIGN FMEA)

Design Responsibility Prognosis Switch Group

Key Date 1993

Document Number 503809
Revision Level C
Revision Date 4 Nov 89
Original (Initial) Date 20 Dec 83

Page 1

Prepared By C. Wagner

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e F r e q u e n c y	Current Design Controls	D e t e c t i o n M e t h o d s	R e s p o n s e T i m e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	Q u a n t i t y	D e t e c t i o n	R e s p o n s e
CONFIDENTIAL																
Disc (2000)																
Complete actuation and release set-points of switch relative to applied force	Fails to actuate and/or release at the proper point in its travel	Mis. yield loss	5		Disc material improperly specified Dimensions and tolerances improperly specified	1	Characterization experiments Comparison of design with similar products	1	5							
May compress or define usable service life of device	Disc actuation and/or release separates during operation over life	Shift in device segments over life	5		Disc material improperly specified Feed back heat improperly specified Material thickness improperly specified Excessive force applied by spring	1	Impulse testing Pre- and post- characterizations	1	5							
Service life shorter than customer requirements	Disc actuation and/or release separates over life. Design insensitive - upset detail	Chronic shift in segments over life.	7		Disc material improperly specified Disc heat-treated improperly specified Material thickness improperly specified Excessive force applied by spring	1	Impulse testing Pre- and post- characterizations	1	7							

TI-NHTSA 019149

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(dEEMOM FMEA)**

Document Number 503601
Revision Level C
Revision Date 4 May 96
Original (Initial) Date 70 Dec 93

Page 1

System _____
Subsystem _____
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Version(s) Various

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r i t y	C a u s e s	P o t e n t i a l C a u s e(s) Mechanism(s) at Failure	O c c u r r e n c e	C u r r e n t D e s i g n C o n t r o l s	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility at Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r t u r e
CHAMP Riser (34757) More together base assembly and sensor assembly	Fails to hold base to sensor correctly	Erratic switch operation. Cracked base Fail in response. Low base torque withstand	5		Incorrect geometry of castable pins specified Incorrect geometry of formed pins Incorrect material specified	3	Impulse, thermal cycle, base torque and base-thermal impact tests	1	15							
Pressure is a surface for part identification code	ID character legible	Improperly identified parts at assembly plant	2		Geometry/thickness not properly specified Wrong material specified	1	Coding tests Environmental tests	1	2							
Improve environmental protection and sealing to device	Leakage in wireless equipment	Corrosion causes material consumption, loss of mechanical properties, switch eventually fails or shorts. Highly visible	7		Wrong material specified	1	Environmental tests	1	2							
Provide lubrication to chop dies via oil pump	Insufficient lubrication	Metal flakes/particles on external device surfaces	5		Incorrect or insufficient specs specified	1	Crushing tests	1	5							

CONFIDENTIAL

TI-NHTSA 018160

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN PMEA)

Document Number: 101802
Revision Level: C
Revision Date: 4 MAR 95
Original (Initial) Date: 20 MAR 93

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Model Year(s)/Vehicle(s): Various

Key Date: 1992

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Potential Failure Mode	Potential Effect(s) of Failure	S	C	Potential Cause(s) Mechanism(s) of Failure	C	Current Design Controls	D	R	Recommended Actions	Responsibility & Target Completion Date	Action Results Taken	S	O	D	R
Function			e	a		c		e	P				e	c	e	P
			v	s		n		e	N				y	c	t	N
TRANSFER PIN (7-074) Transfers disc motion to movable electrical contact	Fails to properly transfer disc motion	Contacts stuck open Contacts stuck closed Excessive arcing	7		Discs incorrectly specified Disc/spring/plate guide pin to ledge	1	TollWaste stackup between pin and pin guide in cup Check with supplier for material properties regarding creep	1	7		CONFIDENTIAL					
Insulate electrical components from switch housing	Fails to insulate	Continuity between movable terminal and housing to ground	5		Wrong material specified	J	Check with supplier for material properties Check with customer for electrical logic of allowable terminal	1	5		CONFIDENTIAL					

TI-NHTSA 019181

System _____
 Subsystem _____
 Component Pressure Switch
 Model Year(s)/Vehicle(s) Various

POTENTIAL
 FAILURE MODE AND EFFECTS ANALYSIS
 (DESIGN FMEA)
 Design Responsibility Pressure Switch Group
 Key Date 1993

Document Number 301802
 Revision Level C
 Revision Date 4-Mar-95
 Original (Issue) Date 20-Dec-93
 Prepared By C. Wright

Page 1

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S 4 3 2	C 1 2	Potential Cause(s) Mechanism(s) of Failure	D 4 3 2	Current Design Controls	D 4 3 2	R 1 2 3	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Action Taken	S 4 3 2	C 1 2	R 1 2 3
TRANSFER PIN (74078) Transfer decoupler to movable electrical contact	Fails in properly transfer decoupler	Contact stick open Contact stick closed Event separation	7		Dimension incorrectly specified Chip/soldering not cause pin to lodge	1	Tolerance stack-up between pin and pin guide in cup Check with supplier for material properties regarding chips	1	7		CONFIDENTIAL				
Electrical connector components from switch housing	Fails to route	Continuity between receptacle terminal and housing to ground	5		Wiring assembly specified	1	Check with supplier for material properties. Check with customer for electrical type of movable terminal	1	5		CONFIDENTIAL				

TI-NHTSA 019162

System
Subsystem
Component Paraspac Switch

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Design Responsibility Paraspac Switch Group

Document Number 583403
Revision Level C
Revision Date 4-Nov-95

Page 1

Original (Initial) Date 20 Dec 93

Model Year(s)/Vehicle(s) Various

Key Date 1990

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	R n v	C i n s	Potential Cause(s) Mechanism(s) of Failure	S c e n a r i o	Current Design Controls	D e t e r m i n e	R i p n	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S c e n a r i o	Q c e n t r i l	D e t e r m i n e	R i p n
ENVIRONMENTAL SEAL (74247) Prevents ingress of water to switch cavity Prevents fire from extinguisher from penetrating base mounting	Contaminants enter switch cavity.	High current leakage High internal temp. Erratic or irregular switch operation.	7		Design thickness is specified too small Limits are possibly not specified Incorrect material	1	Review of standard practice for gland design Review with gasket manufacturers Comparison of design with similar product	1	7		CONFIDENTIAL					
	Base screws pre- lubricated	Particulate in lubricant by assembly plant and/or service personnel.	6		Design thickness improperly specified	1	Review of standard practice for gland design Tap-to-tap locking Comparison of design with similar product	1	5							

TI-NHTSA 019163

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503633
Revision Level: C
Revision Date: 4 Nov 90
Original (Initial) Date: 20-Dec-91

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Model Year(s)/Version(s): Various

Key Date: 1990

Prepared By: C. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S o f t w a r e	C o n t r o l s	Potential Cause(s) (Mechanism(s)) of Failure	O c c u r r e n c e	Current Design Constraints	D e t e r m i n e d	R e l i a b i l i t y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results					
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e r m i n e d	R e l i a b i l i t y	
ENVIRONMENTAL SEAL (TIGHT)																	
Prevents ingress of water in switch cavity	Contaminants enter switch cavity	High current leakage High null-volt drop Erratic or inoperative switch operation.	7		Gasket thickness is specified too small Leads on potting not specified Incorrect material	1	Review of standard practices for gland design Review with gasket manufacturer Comparison of design with similar product	1	7		CONFIDENTIAL						
Provides friction to aid in overruling base rotation	Base rotates too easily	Interlocks not adequate by assembly plant and/or service personnel	5		Gasket thickness improperly specified	1	Review of standard practices for gland design Torque-to-rotate testing Comparison of design with similar product	1	5		CONFIDENTIAL						

TI-NHTSA 018164

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number: 503804
Revision Level: C
Revision Date: 1-16-95
Original (Initial) Date: 20 Dec 91

Page 1

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Key Date: 1993

Prepared By: C. Wagoner

Model Year(s)/Vehicle(s): Various

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r t u r e
THREAD CAP (Fitted) Prevents transport threads from damage during shipping and assembly Prevents dust from entering the fluid circuit	Incorrect length	Does not protect threads sufficiently.	4		Length incorrectly specified	1	Dimensional stackup study	1	5		CONFIDENTIAL					
	Loose Cap	Allows dust to enter fluid cavity.	4		Incorrect diameter specified	1	Dimensional analysis	1	4		CONFIDENTIAL					

TI-NHTSA 019166

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(POTENTIAL FMEA)

Document Number 503805
Revision Level C
Revision Date 30 Oct 86
Original (Initial) Date 20 Dec 83

Page 1

System
Subsystem
Component

Design Responsibility Friction Switch Group

Model Year(s)/Vehicle(s) Variant

Key Date 1987

Prepared By C. W. WOOD

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) in Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R e c o m m e n d e d A c t i o n	Responsibility & Target Completion Date	Action Required	S e v e r i t y	C o n s e q u e n c e	D e t e c t i o n	R e c o m m e n d e d A c t i o n
REPORT (38000)															
Provides a hydraulic testing surface per SAE J512	Fails to seal	Leakage of brake fluid	8	FF	Incorrect surface finish specification, incorrect material specification, incorrectly specified geometry- Excessive pressure	1	Cross-check of part dimensions by SAE standard Comprehensive evaluation of design at tolerance level. Burst testing to customer specified limits	1	9						
Provides internal spread for regulation into lubricating port	Fails to properly seal in mating port	Damage occurs in mating port during installation Does not allow lubrication	7	FF	Threads specified incorrectly Threads not gauged per ANSI spec's. Flaring burrs	3	Cross-check of applicable SAE and ANSI standards	3	93						
	Assembly installed, but fails to properly seal and port	Brake fluid leakage	8	FF	Threads specified incorrectly Threads not gauge per ANSI spec's. Flaring burrs	1	Cross-check of applicable SAE and ANSI standards	3	27						
Provides for release for 1/4" or wrench	Incorrect burr size	Damage to fast field during wrenching. 1/16" wrench does not fit	4		New features improperly specified per established SAE/ANSI spec's	1	Cross-check of applicable SAE and ANSI standards	1	5						
Provides fluid passage to pressure sensing element	Fluid passage is too small	Electrical signal from switch is delayed vs. pressure's signal especially at very low temp. Subject to blockage by foreign matter.	7	FF	Inadequate size of fluid passage specified	1	Review of Ford standard practices	1	7						
	Fluid passage is too large	Revealing thin wall section means breakage: during installation during underhood sealing conditions	7	FF	Inadequate review of Ford standard practices	1	Review of industry practices	1	7						
					Fluid passage specified excessively large	1	Torque testing	1	7						

CONFIDENTIAL

TI-NHTSA 019168

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 507805
Revision Level C
Revision Date 20-Oct-98
Original (Issue) Date 20-Dec-91

Page 2

System
Subsystem
X Component
Previous Design
Model Year(s)/Vehicle(s) Various

Design Responsibility Program Switch Cleanup
Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S 1 2 3 4 5	C 1 2 3 4 5	Potential Cause(s) Mechanism(s) of Failure	C 1 2 3 4 5	Current Design Controls	D 1 2 3 4 5	R 1 2 3 4 5	Recommended Controls	Responsibility & Target Completion Date	Action Results			
												Action Taken	S 1 2 3 4 5	C 1 2 3 4 5	R 1 2 3 4 5
PERFORM Catalytic Converter	Failure to heat exhaust properly.	Leakage of toxic fumes.	5	5	Dead catalysts, improperly specified catalyst material, improperly specified dead geometry improperly specified.	1	Catalytic check with technical drawings of gasket supplier. Comprehensive testing.	1	5						
Provides flange which interfaces with other components to form pressure- tight seal.	Flange fails to mate properly with other components of pressure vessel.	Flange leaks results in leakage of toxic fumes. Flange has small cracks in bad component alignment. Flange has thick welds in poor shape. Flange for this results in reduced burst capacity. Improper edge chamfer results in stress concentration which initiates cracking. Inadequate burst capacity. Component fatigue during installation or subsequent service. Thermal stress in damage, leads to leakage difficulties.	5	5	Improper or incomplete specification of dimensions and tolerances.	1	Examination and analysis to determine proper thickness for required strength. Reference stack-up analysis. Free system.	1	5						
	Material too soft or weak.	Material failure during installation or subsequent service. Thermal stress in damage, leads to leakage difficulties.	5	5	Improper material selection.	1	Comprehensive evaluation of physical properties.	1	5						
	Material cracks.	Leakage of toxic fumes to leakage.	5	5	Improper material selection.	1	Review of material properties.	1	5						
	Material degradation in presence of working fluids.	Leakage.	5	5	Improper material selection.	1	Cross-check with similar products.	1	5						
	Insufficient environmental protection.	Leakage of toxic fumes which leads to leakage or leakage.	5	5	Improper or insufficient sealing specification.	1	Comprehensive environmental testing.	1	27						

CONFIDENTIAL

TI-NHTSA 019167

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 800665
Revision Level C
Revision Date 20 Oct 96
Original (Issued) Date 20 Dec 93

Page 3

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C a u s e s	Potential Cause(s) Mechanism(s) of Failure	D e t e c t a b i l i t y	Current Design Controls	D i s c r i m i n a t e d	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results				
											Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t a b i l i t y	R e p a r a b i l i t y
HEAPORT (26900) Provides range which interfaces with other components in beam pressure control circuit		Gasometric problems.	9			1	Review of phasing practices	3	27						

CONFIDENTIAL

TI-NHTSA 019168

Design Responsibility of System ID Card
 - - - - -
 Design Responsibility of System ID Card
 - - - - -

[illegible]

CONFIDENTIAL

TI-NHTSA 018169

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 508770 Page 1
 Revision Level B
 Revision Date 5-Mar-86
 Original (Initial) Date 20-Dec-93

System _____
 Subsystem _____
 Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By D. Ha

Core Team Design Engineers, Manufacturing Engineers, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C a u s e s	P o t e n t i a l C a u s e(s) M e c h a n i s m(s) o f F a i l u r e	O c c u r r e n c e	C o n s e q u e n c e	D e t e c t i o n	R e p a r t u r e	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R e p a r t u r e
RIVET (74818) Fastens spring to movable terminal	Fails to adequately fasten spring to movable terminal	Spring rotates about axis of rivet. Spring fails off movable terminal.	6		Improper rivet diameter for given hole sizes. Improper rivet length for given material thickness Improper head size Improper tubular feature Improper material	1	Rivet manufactures recommendations Comparison with similar products Testing to determine torque to rotate spring	1	6							
	Provides a force between movable terminal and spring which causes intimate contact for current flow	Inadequate force between spring and movable terminal	6		Improper rivet diameter for given hole sizes Improper rivet length for given material thicknesses Improper head size Improper tubular feature Improper material	1	Rivet manufactures recommendations Comparison with similar products Testing to determine torque to rotate spring	1	6	CONFIDENTIAL						

TI-NHTSA 018160

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number
Revision Level
Revision Date
Original (Inaug) Date

Page 1

System
Subsystem
Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Number/Vehicle/Variety

Very Date 1982

Prepared By

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Document #

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

30374

Item	Function	Potential Failure Mode	Potential Effect(s) of Failure	D	C	Potential Cause(s) Mechanism(s) of Failure	O	Current Design Controls	D	R	P	N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results
30374	Provide adequate area which holds pressure switch together.	Failure to provide a suitable gasket for crimp.	Leakage	4	1	Crimp wall thickness incorrectly specified.	1	Burst and impulse testing.	1	1	1	1			print specified
30374	Form double element of lead containment cavity	Failure to contain lead.	Fluid leakage.	5	1	Gradual rupture over life due to improper design of supporting elements Gradual rupture over life due to excessive thermal displacement Gradual rupture over life due to stress concentrations caused by asymmetric strain distribution Chemical attack due to incorrect material specified Incorrect thickness (or # of layers) of diaphragm material Insufficient lead containment at diaphragm	1	Burst, impulse, and Thermal Cycle tests. Material only. Comparison of design with similar products.	1	1	1	1			industry usage comparison.
30374	Provide a surface of the support surface for diaphragm.	Failure to correctly support the diaphragm.	Reduced diaphragm life results in leakage.	5	1	Contours of diaphragm support surface are specified incorrectly	1	Burst, impulse, and Thermal Cycle tests	1	1	1	1			FEA

CONFIDENTIAL

Kaplan

Leakage

TI-NHTSA 019161

Washer					Condition of edges of support surface specified incorrectly. Clearance between washer I.D. and converter pump is specified too wide.	Comparison of design with similar products.				
Provides support for compression of gasket.	Fails to allow proper gasket compression.	Leakage.	6		Washer thickness is incorrectly specified or unspecified.	Burst, Impact, and Thermal Cycle tests.	1	1		
					Washer thickness is specified too small.	Comparison of design with similar products.				
					Washer material and/or heat-treat is incorrectly specified.					
Interfaces with cup flange and provides a portion of component stack for crimp.	Fails to interface correctly with cup.	Difficult assembly washer O.D. too large.	7		Washer O.D. specified incorrectly.	Comparison of design with similar products.	1	1		
		Poor washer/converter location relative to cup washer O.D. too small.				Tolerance stacking analysis.				
	Fails to allow proper crimp.	Reduced burst strength leads to leakage. Reduced torque resistance leads to leakage.	8		Thickness incorrectly specified.	Tolerance stacking analysis.	1	1		
	Washer I.D. = .317				O.D. incorrectly specified.	Burst, Impact, and Thermal Cycle tests.				
	Washer I.D. = .317				Edge condition incorrectly or unspecified.					
Provides a portion of the support surface for diaphragm.	Fails to properly support diaphragm.	Diaphragm displacement leads to leakage.	9		Contours of surface in contact with diaphragm are specified incorrectly.	Burst, Impact, and Thermal Cycle tests.	1	1		
					Location of edges in contact with diaphragm are specified incorrectly.	Comparison of design with similar products.				
					Clearance between converter pump and washer I.D. are specified too wide.					

CONFIDENTIAL

TI-NHTSA 019162

Report sent to

REPORT (38800)										Page 2
Provides a hydraulic sealing surface per SAE J512.	Fails to seal.	Leakage of brake fluid <i>outside ? switch</i>	9	FF	Intermittent surface finish specification. Incorrect material specification. Incorrectly specified geometry. Estimates pressure.	1	Cross-check of part dimensions vs. SAE standard. Comprehensive evaluation of design at tolerance limits. Surfactant testing to customer specified limits.	1	9	
Provides external thread for installation into mating port.	Fails to properly install in mating port. Apparently installs, but fails to properly seal and seal.	Derivates threads in mating port during installation. Does not allow installation. Brake fluid leakage.	7	FF	Threads specified incorrectly. Threads not gauged per ANSI spec's. Plating buildup. Threads specified incorrectly. Threads not gauged per ANSI spec's. Plating buildup.	3	Cross-check of applicable SAE and ANSI standards. Cross-check of applicable SAE and ANSI standards.	3	13	
Provides flange which interfaces with other components in form pressure-bearing structure.	Material wraps.	Loosening of alloy leads to leakage.	9		Improper material selection.	1	Review of material properties.	1	9	
	Material degradation in presence of working fluid(s).	Leakage.	9		Improper material selection.	1	Cross-check with similar products.	1	8	
	Insufficient environmental protection.	Long-term attack causes weakening of alloy which leads to leakage or breakage.	9		Improper or insufficient plating specification.	1	Comprehensive environmental testing.	5	27	

TM-NHTSA 019163

CONFIDENTIAL

EA02025

**TEXAS INSTRUMENTS, INC.'S
09/10/03 LETTER TO ODI**

REQUEST 13

BOX 13

PART A – E

PART B