

EA02-025

10-28-03

**FORD 10/28/03
LETTER TO ODI**

BOOK 1 OF 2

PART A – D

PART B

VIGO COUNTY SUPERIOR COURT
STATE OF INDIANA

407214

ENG-025 3001

STATE OF INDIANA)
) SS:
COUNTY OF VIGO)

IN THE VIGO SUPERIOR COURT
CAUSE NO. 84D02 9904 ET 544

[REDACTED]

Plaintiff,

v.

FORD MOTOR COMPANY,

Defendant.

FILED
VIGO COUNTY SUPERIOR COURT
APR 01 1999
William L. Marshall
CLERK

COMPLAINT

COMES now Plaintiff, [REDACTED], by its counsel, and for its
Complaint against Defendant, Ford Motor Company, states and alleges:

1. That at all times relevant herein, Plaintiff, [REDACTED]
[REDACTED] is an insurance carrier licensed to do business in the State of Indiana and insures [REDACTED]
[REDACTED]
2. That at all times relevant herein [REDACTED] insured [REDACTED], is
an Indiana resident, residing at [REDACTED] Terre Haute, Indiana.
3. That at all times relevant herein, Defendant, Ford Motor Company ("Ford"), is a
corporation organized and existing under the laws of Indiana, qualified and licensed to do business in
Indiana, and is engaged in the manufacture of Mercury Grand Marquis automobiles.
4. In 1993, [REDACTED] purchased a used 1992 Mercury Grand Marquis manufactured by
Defendant, Ford, from Esten Fuson Cadillac.
5. On or about April 6, 1997, [REDACTED] parked the 1992 Grand Marquis in her garage.
6. At approximately 11:30 p.m. that evening, [REDACTED] discovered that her garage and
house were on fire.

7. [REDACTED] vehicle and house were severely damaged as a result of the fire.

8. On May 29, 1997, [REDACTED] employed Pace, Inc., in the person of Frederick F. Franklin to visit the [REDACTED] residence and to perform a Cause and Origin Investigation of the fire.

9. On May 29, 1997, Pace, Inc. visited the scene of the accident and made a Cause and Origin Investigation and issued its report, a copy of which is attached hereto as Exhibit A.

10. According to the Pace, Inc. Cause and Origin Investigation Report, the fire at the [REDACTED] residence was caused by short circuit arcing in the right, front corner engine compartment of [REDACTED] 1992 Mercury Grand Marquis.

11. Plaintiff and Pace, Inc. determined that a defective wiring system was the direct and proximate cause of the fire and the ensuing damage to the vehicle and house.

12. That Defendant's negligent design and/or manufacture of the 1992 Mercury grand Marquis' wiring system was a direct and proximate cause of the fire.

13. That as a result of the Defendant's negligence, [REDACTED] vehicle and house were severely damaged.

14. That as a proximate result of the accident, [REDACTED] has been required to make payments to its insurer [REDACTED] for her loss in the amount of One Hundred Ten Thousand One Hundred and Four Dollars and Seventy-Seven Cents (\$110,104.77).

15. That [REDACTED] is entitled to reimbursement for its payments by subrogation from Defendant.

16. That Defendant has failed and/or refused to pay the cost for damages as of this date to Hartford.

17. The 1992 Mercury Grand Marquis was built and assembled by Defendant and in doing so, Defendant, through its agents and employees, negligently and unlawfully designed and/or installed defective wiring in the right, front corner engine compartment of the 1992 Mercury Grand Marquis, which defect could have been ascertained with reasonable inspection by the Defendant.

WHEREFORE, Plaintiff [REDACTED], respectfully requests the Court to enter judgment for Plaintiff and against Defendant, in the principal amount of One Hundred Ten Thousand One Hundred Four Dollars and Seventy-Seven Cents (\$110,104.77), for prejudgment interest, and costs together with all other just and proper relief in the premises.

Respectfully submitted,

McCROSSON & NERZ

By: Thomas E. Schulte
Thomas E. Schulte, Esq. (20360-49)

By: Dennis F. McCrosson 7-5
Dennis F. McCrosson, Esq. (10249-49)

Thomas E. Schulte, Esq.
Dennis F. McCrosson, Esq.
McCROSSON & NERZ
1811 N. Meridian St.
Indianapolis, IN 46204
Phone: (317) 921-7500
Fax: (317) 921-7595

[REDACTED] FORDA

PACE INC. PROFESSIONAL ANALYTICAL & CONSULTING ENGINEERS, INC.

4322 Indeco Court • Cincinnati, Ohio 45241 • (513) 793-2771
1-800-PACE-050 • Fax: (513) 793-0538

VEHICLE AND GARAGE FIRE

2625 EAST THOMAS AVENUE

TERRE HAUTE, INDIANA

CLAIM NO.: 565DP07941

INSURED: [REDACTED]

DATE OF LOSS: APRIL 6, 1997

P.A.C.E. PROJECT NO. I-2006A

MAY 29, 1997

FOR:

ITT-HARTFORD INSURANCE COMPANY

P.O. BOX 40

WEST POINT, INDIANA 47992



8002-025 35455

TABLE OF CONTENTS

<u>SECTION</u>	<u>Page</u>
1. Introduction	1
2. Observations	1
3. Analysis	5
4. Conclusions	9

Addendum

1. INTRODUCTION

1.1

Professional Analytical and Consulting Engineers (P.A.C.E.) was requested by Mr. Norman Hayman of the [REDACTED] West Point, Indiana to investigate a fire which occurred in a house owned by [REDACTED] and located at [REDACTED] Terre Haute, Indiana, and also her 1992 Mercury Grand Marquis which was parked in her garage.

1.2

A professional opinion was requested in an attempt to determine the cause of this fire.

2. OBSERVATIONS

2.1

A site visit was conducted on April 11, 1997 by Mr. Frederick Franklin, P.A.C.E. Electrical-Mechanical Engineer. The photographs shown in this report were taken there by me at that time. Figure 1 is a front view of the

7
house, and Figure 2 is a view of the garage from the front. Figure 3 is a view of the house and garage from the rear.

2.2

Figures 4 and 5 look through the garage door toward the remains of the 1992 Mercury Grand Marquis which was parked in the garage at the time of the fire.

2.3

Figure 6 is a view looking through the kitchen of the house toward the doorway to the garage. Figures 7 and 8 are additional views of the kitchen. By comparing these photographs to Figures 4 and 5, it is clear that the fire originated in the garage area, in my opinion.

2.4

Figure 9 is a view of the much lighter burn damage in the dining room. Figure 10 is a view of the living room, and Figure 11 is a view of the hallway which leads to the bedrooms on the opposite end of the house from the garage.

2.5

Figure 12 looks across the engine compartment of the automobile toward the rear wall of the garage. The engine hood was made of aluminum and it has melted during the fire. Figure 13 looks toward the rear wall of the garage and the doorway to the kitchen. Figures 14 and 15 are closer views of the circuit breaker panel shown from a distance in Figure 13. These photographs demonstrate that no hole has ever occurred in the metal panels of the circuit

breaker enclosure. Thus this fire could not have been caused by a malfunction inside the circuit breaker panel, in my opinion.

2.6

Figure 16 looks toward the garage door at the front of the house. It may be observed in Figures 4, 5, and 16 that almost all the roof of the garage has been consumed, and that the timbers have fallen onto the top of the automobile. This means that the fire did not start around the periphery of the garage, in my opinion. Rather the fire started in the vicinity of the automobile, in my opinion.

2.7

Figure 17 looks down the stairway in the garage to the basement. This stairway is shown at the far left of Figure 16.

2.8

Figure 18 is another view of the engine compartment of the Mercury. Figure 19 looks across its dashboard area, and Figures 20, 21, and 22 are interior views of its passenger compartment. Figures 23 and 24 are views of the trunk of the automobile. Because the rubber tire in the trunk has never been consumed, it is clear that the fire could not have originated in this trunk, in my opinion. There was an electrical device in this trunk which assisted [REDACTED] [REDACTED] by extending a wheel chair for her, but it could not have been the cause, in my opinion.

2.9

Figure 25 is a view of the remains of a romex-type cable which had traveled through the ceiling area above the automobile at the time of the fire. Figure 26 is a close view of the ends of this cable. The melted copper suggests that short circuit arcing may have occurred in this cable at some point in time, in my opinion.

2.10

Figure 27 is a view of what may be the opposite end of this same romex-type cable. Figures 28, 29, and 30 are close views of metallic melts left by short circuit arcing in this cable which occurred at some point in time. The window shown in Figure 27 is the same window shown at the middle of Figure 2 on the side wall of the garage.

2.11

Figure 31 is a view of another romex-type cable which has arced at some point in time near the garage door. I took these three sets of romex-type cables which contained copper melts with me as evidence to store at P.A.C.E. in case anyone else ever wants to see them in person.

2.12

At the middle of Figure 2 a "clean area" may be observed on the block wall. This "clean area" is an area of very intense heating. This area was approximately in line with the right, front corner of the Mercury, which is where I believe the fire originated. Figure 33 is a view of this right, front

corner of the Mercury, and Figure 34 is another view. Figure 35 is a closer view of the wiring harness remains shown in Figures 33 and 34. I believe a vehicle short circuit arc in this area is what caused this fire.

2.13

Figure 36 is another view of the partially melted right, front wheel. This wheel was much more intensely damaged than the other three wheels on the Mercury, which are shown in Figures 37, 38, and 39, in my opinion.

2.14

Figures 40, 41, and 42 are views of the garage door opener which has fallen onto the roof of the Mercury. I could find no holes in its metal cover. In my opinion, any short circuit arc inside the garage door opener would have to create a hole in the metal cover before flying copper globules could exit to cause a fire.

3. ANALYSIS

3.1

On May 8, 1997 I traveled to a Mercury dealership near my office. The service managers there told me that the power distribution center for a 1992 Mercury Marquis is located at the right, front corner of the engine compartment. The service managers told me that a plastic enclosure

contains the power distribution center. Figure 37 is a view of this area, looking forward across the right, front wheel in the subject vehicle. The larger battery cable leading toward the shelf at the top of the photograph may be observed, along with copious amounts of electrical wiring. The power distribution center is where the large battery cable connects to smaller feeder cables, and to even smaller circuit wires via fuses. Thus there is no question that some conductors in this area, which I believe was the area of origin, were energized at the time the fire occurred, in my opinion. That is, turning off the ignition switch would not de-energize all of these conductors. Many of the conductors in and around this distribution center would have voltage even when the ignition switch was turned off.

3.2

On May 16, 1997, I took the Polaroid photographs shown in Figures 44, 45, and 46. These photographs show the engine compartment of an exemplar 1992 Mercury Grand Marquis owned by an acquaintance of mine. The arrow in Figure 45 points to the plastic enclosure of the power distribution center.

3.3

A copy of a one minute videotape is enclosed which illustrates how arcs in vehicle electrical wiring can cause fires even when they are fed by 15 or 20 ampere fuses, let alone larger fuses. In this videotape, two each, 16 gauge stranded copper conductors, six feet long are connected to a 12 volts, D.C. vehicle battery. A torch is used to set up carbon path arcing. It may be observed that the arcing lasts for well over one minute and that the arcing

finally melts both copper conductors completely apart without ever drawing enough current to pop a 15 or 20 ampere vehicle fuse.

3.4

Included in the Addendum section of this report are two articles. "Vehicle Short Circuit Fires and Their Prevention" discusses in more detail why short circuit arcs can cause fires without popping a 15 or 20 ampere fuse, or larger. The article also discusses that vehicle short circuit arcs can create fires without leaving a melt on the copper conductors. This explains why I did not find any significant copper melt on the copper conductors at the right, front corner of the engine compartment. I did not remove anything from the Mercury Marquis, but rather left it entirely as I found it.

3.5

The other article, "Latent Short Circuit Defects," discusses how insulation which is damaged during the manufacture of an automobile can lie dormant for years until an arc occurs one day to cause a fire.

3.6

Because of the intense fire damage at the right, front corner of the automobile, I could not determine exactly what short circuited to cause this fire. Since the vehicle had been parked for nine hours prior to the fire, without its engine running, there would have been no other source of heating power in the vehicle to cause a fire other than a short circuit arc, in my

opinion. Thus it is my opinion that a short circuit are in the right, front corner area of the Mercury Marquis was the cause of this fire.

3.7

On May 19, 1997, I spoke to the house and Mercury owner, [REDACTED], on the telephone. [REDACTED] stated that when she discovered the fire, flames were already coming through the kitchen door between her kitchen and the garage. Thus, she never was able to look into the garage to see where the fire was burning in the garage, because the fire was already so intense at that time. She stated this fire occurred at approximately 11:30 p.m. to midnight. [REDACTED] stated that she had no smoke detectors in the house, and thus it was fortunate that she was awake watching the news on television when the fire occurred.

3.8

[REDACTED] stated that she had no gasoline cans anywhere in the garage, nor any type of other flammable liquid in the garage.

3.9

[REDACTED] stated that she purchased this Mercury used in 1993 from Esten Fuson Cadillac and that it had approximately 27,000 miles on it at that time. At the time of the fire, it had approximately 41,000 miles on its odometer. [REDACTED] stated that the Mercury never required any type of service, except routine service, and that it never had any problem at all.

Because of this, I believe that it is doubtful that it ever required anything but routine service during its first 27,000 miles, although this remains a possibility.

3.10

██████████ stated that she last purchased a battery for the vehicle on October 31, 1995 at a service station located at the corner of Lafayette and Fort Harrison Road in Terre Haute. She remembers this date well, because she broke her leg three days later. It may be observed that the battery is also located at the right, front corner of the engine compartment in this Mercury.

4. CONCLUSIONS

4.1


Based upon the observations and analysis as set forth in this report, it is my opinion that the fire which occurred in the garage of a house owned by Ms. ██████████ at ██████████ in Terre Haute, Indiana was caused by short circuit arcing in the right, front corner of the engine compartment of her 1992 Mercury Grand Marquis.

4.2

Thus, it is my opinion that the Ford Motor Company is responsible for the

7
cause of the fire in the Grand Marquis and to [REDACTED] home and garage.

PROFESSIONAL ANALYTICAL AND CONSULTING ENGINEERS



Frederick F. Franklin
Professional Engineer
State of Indiana
Registration No. 15629

Addendum



FIGURE 1

FRONT VIEW OF HOUSE AND GARAGE



FIGURE 2

VIEW OF GARAGE

ERG2-028 35667



FIGURE 3

REAR VIEW OF HOUSE AND GARAGE



FIGURE 4

VIEW OF GARAGE LOOKING THROUGH GARAGE DOORWAY

EP02-025 3568



FIGURE 5

VIEW OF GARAGE LOOKING THROUGH GARAGE DOORWAY



FIGURE 6

VIEW OF KITCHEN LOOKING TOWARD DOOR TO GARAGE



FIGURE 7

VIEW OF KITCHEN LOOKING TOWARD DOOR TO GARAGE



FIGURE 8

VIEW OF NORTH WALL OF KITCHEN



FIGURE 9

VIEW OF DINING ROOM



FIGURE 10

VIEW OF LIVING ROOM



FIGURE 11

VIEW OF HALLWAY LEADING TO WEST BEDROOMS



FIGURE 12

VIEW LOOKING FORWARD ACROSS ENGINE COMPARTMENT OF
MERCURY



FIGURE 13

VIEW LOOKING TOWARD SOUTHWEST CORNER OF GARAGE



FIGURE 14

VIEW OF CIRCUIT BREAKER PANEL



FIGURE 15

VIEW OF AREA ABOVE CIRCUIT BREAKER PANEL



FIGURE 16

VIEW LOOKING NORTHWARD IN GARAGE



FIGURE 17

VIEW OF BASEMENT STAIRWAY IN GARAGE



FIGURE 18

VIEW OF MERCURY ENGINE COMPARTMENT



FIGURE 19

VIEW OF DASHBOARD AREA



FIGURE 20

VIEW LOOKING REARWARD THROUGH WINDSHIELD



FIGURE 21

VIEW OF FRONT SEATS

1962-021 35888



FIGURE 22

VIEW OF REAR SEATS




FIGURE 23

VIEW OF TRUNK



FIGURE 24

CLOSER VIEW IN TRUNK



FIGURE 25

VIEW OF ROMEX CABLE REMAINS



FIGURE 26

VIEW OF MELTED ROMEX-TYPE CABLE CONDUCTORS



FIGURE 27

VIEW OF ROMEX-TYPE CONDUCTORS NEAR NORTHEAST CORNER OF
GARAGE




FIGURE 29

CLOSE VIEW OF MELTED COPPER



FIGURE 29

CLOSE VIEW OF MELTED COPPER



FIGURE 30

CLOSE VIEW OF MELTED COPPER



FIGURE 31

VIEW OF ROMEX-TYPE CABLE ABOVE GARAGE DOOR



FIGURE 32

VIEW OF "CLEAN AREA" ON WEST GARAGE WALL

ENR-025 2000




FIGURE 33

FRONT VIEW OF MERCURY




FIGURE 34

VIEW OF RIGHT FRONT CORNER OF MERCURY



FIGURE 35

CLOSE VIEW OF RIGHT FRONT CORNER OF MERCURY



FIGURE 36

VIEW OF RIGHT FRONT WHEEL



FIGURE 37

VIEW OF RIGHT REAR WHEEL



FIGURE 38

VIEW OF LEFT REAR WHEEL



FIGURE 39

VIEW OF LEFT FRONT WHEEL



FIGURE 40

VIEW OF GARAGE DOOR OPENER REMAINS




FIGURE 41

VIEW OF GARAGE DOOR OPENER REMAINS



FIGURE 42

VIEW OF GARAGE DOOR OPENER REMAINS



FIGURE 43

INSIDE VIEW OF RIGHT FRONT CORNER OF ENGINE COMPARTMENT



FIGURE 44

VIEW OF EXEMPLAR 1992 MERCURY GRAND MARQUIS




FIGURE 45

VIEW OF EXEMPLAR 1992 MERCURY GRAND MARQUIS



FIGURE 46

VIEW OF EXEMPLAR 1992

MERCURY GRAND MARQUIS

ADDENDUM

R



Vehicle Short Circuit Fires and Their Prevention

By FREDERICK F. FRANKLIN

According to NFPA statistics, nearly as many vehicle fires (447,500) occur in this country as do building fires (745,000) (*Fire Journal*, Sept. 1989). Besides smoking and arson, short circuits and flammable liquid leaks are the two primary causes of vehicle fires. Although gasoline is typically the flammable liquid involved, power steering fluid, transmission fluid, oil or ethylene glycol coolant can occasionally be the cause. Most short circuit fires and gasoline leaks can be easily prevented.

In 1983, General Motors (GM) was experiencing ongoing problems with its electric door lock switches. These switches were short circuiting and causing fires. To demonstrate the problem, GM conducted simulations. A Nov. 22, 1983 letter from M.D. Osterhoff of Fisher Body to B.R. Wanlass stated,

"The door lock switch is powered by a battery feed line that is protected by a 20-ampere fuse. Misalignment of the conductor and/or improper assembly of the base to escutcheon may cause the conductor blade to contact the plated plastic escutcheon, causing a 'high resistance' short in the switch. This situation is sufficient to draw enough current and produce enough heat to start a fire and still not blow the 20 ampere fuse. Fisher Body Electrical Lab was able to simulate this situation and cause an arcing fire on May 7, 1983."

Those who have investigated vehicle fires know that 20-ampere fuses do not prevent short circuit fires in vehicle wiring, for the reason clearly stated by Osterhoff. The arc is not a dead short, but rather a relatively "high-resistance" arc. In simulations conducted by an independent firm, this resistance has been determined to be in the general

range of 0.5 to 1.0 ohm, which results in arcing currents in the range of 12 to 24 amperes.

At 24 amperes, a 20-ampere fuse may take several minutes to pop—enough time to cause a fire. To prove that arcs will continue that long, the firm videotaped an arc that lasted well over 60 seconds. The arc finally melts both 16-gauge conductors apart, yet it never pops a 20-ampere vehicle fuse.

It was determined following numerous experiments that vehicle short circuit fires could be prevented. Figure 1 illustrates a typical vehicle fuse time-current curve. Based on this graph, it is difficult to detect much difference between a 20-ampere fuse and a 10-ampere fuse. A different configuration of this graph (Figure 2), however, illustrates that at most arcing currents, a 10-ampere fuse pops hundreds of times faster than a 20-ampere fuse.

The heating energy delivered to the arc is proportional to the opening time of the fuse. Figure 2 shows the energy allowed into an arc by each size before it pops, as a function of the current that the short circuit arc draws. Between 15 and 25 amperes of arcing current, a 20-ampere fuse allows hundreds of times more heating energy into an arc than a 10-ampere fuse. Likewise, a 30-ampere fuse allows hundreds of times more energy into an arc between 7 and 15 amperes than a 5-ampere fuse.

Reducing the heating energy (opening time) by hundreds of times reduces the probability of fire by a like amount. Therefore, effective short circuit protection can be accomplished by using smaller fuses.

Beginning in 1966, the author shared this information with various automobile and truck manufacturers. Some reward for these efforts was realized during 1971. George Farrell, manager of technical services for Littelfuse, which manufactures most vehicle fuses, indicated that GM must be licensing based on the way it was utilizing fuses in the new Saturn automobile.

Photos A and B show Saturn fuse panels, while photo C shows the fuse panel from a 1988 Oldsmobile 98. As the pictures indicate, the Saturn uses mostly 5-, 7.5- and 10-ampere fuses; the Oldsmobile used mostly larger fuses. In addition, the Saturn uses many more circuits so that individual fuse ratings can be smaller. The Saturn uses 38 fuses compared to 15 in the 1988 Oldsmobile.

The author believes near-perfect protection could be obtained by using all 5-ampere fuses wired in bundles; however, this solution would be more difficult and more expensive. Apparently, GM has decided that using mostly 5-, 7.5- and 10-ampere fuses is adequate protection for most short circuit arcs. In another positive move, the Saturn uses 30-ampere fuses in place of fusible links. Also, no circuit breakers are visible (Franklin 42+).

RESIDENTIAL AND VEHICLE ARCS

It is interesting to note that both 120 volts A.C. residential arcs and vehicle wiring arcs have the same general range of electrical resistances—0.5 to 1.0 ohm (Franklin 42+). Since vehicle voltage (12 volts D.C.) is 10 times less than household voltage, from the formula:

$$P = \frac{V^2}{R}$$

the power delivered to a vehicle arc is roughly 100 times less than a residential arc. However, the vehicle arc lasts 100 times longer than a residential one; therefore, the total energy delivered to the arcs is about the same.

FIGURE 1 TYPICAL VEHICLE FUSE TIME-CURRENT CURVE





FIGURE 2 ENERGY ALLOWED INTO THE ARC




$$E = P \times t$$


Energy = Power × Time
Joules = Watts × Seconds

The 20,000 watts of electrical power delivered to a household arc melts copper so quickly that tons of copper globules 1/16-inch in diameter at over 2,500° F fly off in all directions, some landing up to six feet away.

Vehicle arcs are different. They are usually a very intense, localized white hot spot about 1/8-inch in diameter. In the author's opinion, both types of arcs can directly ignite electrical wiring insulation and/or plastic. Because vehicle short circuit arcing power is so much less, often no copper will remain on the wiring where the short circuit occurred. This has been confirmed in in-



As Photo A (above) and
 B (right show, the
 intake hose usually 8-,
 7.5- and 10-ampere
 hoses, while the 1000
 Milwaukee (Photo E,
 below) used mostly
 larger hoses. In
 addition, the intake
 hose of these—
 compared to 15 in the
 Milwaukee.



PROFESSIONAL SAFETY

investigations of several vehicle fires that produced limited damage.

The latent short circuit defect placed in vehicle wiring at the time of vehicle manufacture can cause an arcing fire at any time from one-half hour to years later (Franklin 38+). An independent firm investigated three separate vehicle fires at the same manufacturing plant. All three fires occurred after the cars were placed on semi-truck carriers located outside the plant.

Gasoline leaks can also cause vehicle fires. Most leaks occur at the short sections of neoprene rubber hoses inserted into the fuel line at the engine and fuel tank to dampen vibrations. Loose metal tubing connections rarely cause such fires. However, because these rubber sections are completely consumed during a fire, those without extensive experience may have difficulty determining the fire's cause.

Both short circuit and fuel leak fires can occur while the vehicle is being driven. Typically, if a fire occurs within a few minutes of stopping or exiting a vehicle, a fuel leak is the likely cause. While the vehicle is moving, wind blows fuel away from the leak, thus preventing a fire. Once the vehicle stops, however, fuel collects in a pool and is then ignited by hot engine parts.

If the fire occurs more than 30 minutes after parking the vehicle (and smoking or arson are not involved), it is usually a short circuit fire. With a cold engine, nothing else can produce enough heating energy to ignite a fire.

Replacing rubber hose sections with a coiled, expandable metal line, like those used in brake line tubing, and reducing the size of fuses would likely prevent most accidental vehicle fires. In addition, eliminating these fires could enhance arson investigation. ■

REFERENCES

Franklin, Frederick J. "Circuit Breakers: The Myth of Safety." *Professional Safety*, June 1990: 28-31.

Franklin, Frederick J. "Latent Short Circuit Defects." *The Fire and Arson Investigator*, Dec. 1991: 26-27. Reprinted in *Professional Safety*, Sept. 1992: 26-27.

Frederick J. Franklin, P.E., is president of Professional Analytical and Consulting Engineers (P.A.C.E.), a forensic engineering firm in Channahon, Ill. During the past 30 years, Franklin has investigated more than 250 vehicle fires, 1,400 building fires and 570 vehicle accidents of all types.

Reprinted from *The Fire and Arson Investigator*. Copyright International Assn. of Arson Investigators Inc.

LATENT SHORT CIRCUIT DEFECTS

By Frederick F. Franklin, P.E., F.A.C.E., Cincinnati, OH.

How does a rymex-type cable short circuit inside a plaster wall space twelve years after an electrician installed it there? What caused a power cord lying on a carpet to short circuit suddenly and cause a fire when no one is home to notice it or vibrate it in any manner? How exactly do short circuit arcs occur in the first place?

These questions have been answered after years of observing short circuit arcs in laboratory experiments and after 1800 on-the-scene fire investigations. The author noticed, in fifteen years of fire investigation, that copper and aluminum melts left on conductors by short circuits which cause fires appear the same as melts from short circuits which occur as a result of the arcing fire. Thus, he deduced that the electrical currents producing the melts should be the same. Consequently, this hypothesis, he began burning through plastic insulation on electrical cables to create short circuit arcs, and then measuring the resulting electrical currents. That research resulted in a much better understanding of why American circuit breakers do not open quickly enough to prevent short circuit fires.¹ It also led to the conclusion that the process which initiates the arc is causative and results in short circuits is the same - namely, a carbon path flashover.

When a broom is used to slowly burn through the plastic insulation on an electrical cord or cable supplied by 120 volts A.C., the eventual one or two second arc that results is usually not caused because the conductors touch. Rather, it occurs because the burned plastic creates a carbon path between the two conductors. Simply stated, when the electrical resistance of this carbon path reaches a critical low value, it instantaneously breaks down into an electrical flashover (As with any flashover the actual physics includes localized heating effects, ionization, avalanching of electrons, negative resistance, and other plasma theories).

Although it is generally agreed that it takes over 380 volts A.C. to initiate an electrical discharge for even the most minute distance between two conductors in air, this carbon path theory does not violate that law, because the conducting medium here is not air but rather carbon.

The knowledge that flashovers can occur through carbon paths is as old as the electrical industry itself. Typical examples are the high voltage ceramic string insulators in coal plants and other plants where coal or coke dust is present. If these insulators are not cleaned regularly, a carbon path flashover will eventually occur and break out

power to the plant. The author investigated one of these cases near Youngstown, Ohio in 1979.

A similar concept to the carbon path arcing described in this article is "arc tracking." This term refers to a flashover along a path or track of minerals or salts left by an evaporating water solution. Again, when the total electrical resistance or the physical makeup of the "track" reaches a critical point, a flashover and resulting arcing occurs. As with the carbon path, at over 10,000°F the precipitating medium is instantly vaporized and the arc is sustained in the air or plasma in which it takes place until the protective fuse or circuit breaker opens, or until the magnetic forces move the conductors too far apart. Arc tracking typically takes place on open surfaces, such as printed circuit boards or on the surface of solid insulators.

Why does the defect in electrical insulation sometimes take 12 years or more to reach the critical value of carbon resistance (or physical makeup) required for a flashover? Let us first look at some mechanical analogies to get a feel for other latent defects which take months or years to break down.

Figure 1 is a magnified view of a hole in a 3/4 inch copper water pipe in a new home. This hole was made when the end of the nail shown was accidentally hammered into the pipe by a drywall installer during the house construction. Six months later a water leak developed which flooded the basement. The connection process in this "connection" between the nail and the water pipe wall took that amount of time to break down, allowing the water to flow freely from the hole.

Figure 2 is another example of a mechanical latent defect. This photograph shows a section of plastic water tubing which was damaged when pulled against the sharp edge of a fence post as it was installed in the attic of a home. A water leak did not develop until 7 years later, when the plastic wall of the tube finally degraded enough to open.

A short circuit in plastic electrical insulation can be thought of as a kind of "current leak," much like the water leaks in the above examples. A very tiny leakage of water traveled through the "connection" around the nail in the copper pipe for six months and through the wall of the plastic water hose for seven years before a flood (flashover) of water current suddenly took place. Similarly, in electrical cables which have been damaged to create a tiny latent defect in the plastic between two conductors (see Figure 3), microcurrents (microamperes) flow for many years. The microcurrents gradually increase in amplitude until they become large enough to begin to oxidize (corrode) the plastic ever so slightly. Then the carbon residue slowly builds up, lowering the electrical resistance of the carbon

1. Frederick F. Franklin, "Circuit Breakers: The Myth of Safety," *The Fire and Arson Investigator*, Volume 41, No. 4, June, 1991, Pages 43-45.

Reprinted with permission
from the I.A.A.I.

FIRE AND ARSON INVESTIGATOR 38
Volume 42
Number 2
December 1991



FIGURE 1 - MAGNIFIED VIEW OF DRYWALL SEAL WHICH WAS ACCIDENTALLY NAILED INTO A 3/4" COPPER WATER PIPE. IT CAUSED A FLOOD SIX MONTHS LATER.



FIGURE 2 - PLASTIC WATER TUBING WHICH BEGAN FLOODING SEVEN YEARS AFTER IT WAS OUT.

Latent Defect



FIGURE 3 - MOISTURE IN CRACK ALLOWS MICROCURRENTS TO FLOW FOR MANY YEARS BEFORE A FLASHOVER OCCURS.



FIGURE 4 - P.A.C.E. MEGGER SHOWING READING OF 1800 MEGOHMS

path or changing its physical makeup to the critical point at which a flashover suddenly occurs.

Tests performed by an electrical engineer over 25 years ago revealed that three initial microcurrents in electrical insulation defects are carried by moisture.² This moisture may be in the form of humidity which finds its way into a crack in the insulation.

In other cases, as recently described by an article published by the Society of Automotive Engineers (SAE), water can "wick" its way into a conductor via capillary action, traveling many inches or feet along the conductor, within the insulation.³ This confirms that insulation is often not perfectly dry or moisture tight.

Engineers and electric technicians use a device called a megohmmeter ("megger") to find these types of electrical defects in motors or transformers by measuring their insulation resistance. A megger is one million ohms of electrical resistance, and a megohmmeter reads very dry electrical faults in "megohms." Moreover, to try to force a breakdown at any potential electrical fault, a megger typically uses a 500 volt or 1000 volt source rather than the 1.5 volt or 9V battery used in normal ohmmeters. The user might require a reading of 50 megohms before certifying that a new or recently repaired large motor or transformer is safe to use. For units which have been through a flood or some type of physical damage, a reading of 1 megohm to 10 megohms would not be uncommon. This reading is a sign to the serviceman that the unit is likely to break down into a short circuit with continued use.

The important point here is that the serviceman would take the unit out of service even though the test is only drawing:

$$\begin{aligned} 500 \text{ mA} &= 0.0005 \text{ amperes} \\ 10,000,000 \text{ ohms} & \end{aligned}$$

which is 50 microamperes. If you add these servicemen what causes readings at these values, most of them would confirm that it is very dry amounts of moisture which have found their way into the insulation. In fact, one repair procedure often utilized is to place the motor or transformer into a large oven and "bake" the moisture out of the insulation. The "baking" continues until the megger reading is acceptable, e.g. 50 megohms. This process is also used after manufacture.

The theory of moisture causing dry electrical microcurrents in electrical insulation is well known in the electrical industry. Meggers have been used for many decades for just this reason, to test for extremely low fault

2. David K. Ellison, "Short Circuits and Wet Faults," I.E.E.E. Spectrum, August, 1981, Page 14.

3. Karen Clark, "Corrosion in Automotive Wiring," Automotive Engineering, Volume 902, No. 3, March 1981, Pages 28-32.

currents in an attempt to prevent a catastrophic short circuit at a hot point in line.

Whatever the exact mechanism by which they occur, the objective fire investigator knows that a significant percentage of fires is caused by wiring short circuits. The theories outlined in this article explain the time delay associated with most of them. The carbon paths are created during the author's simulations remain the only good answer to how arcs occur within plastic and cloth insulation, in the author's opinion. A video tape of some of these simulations is available from P.A.C.E., Inc., 4822 Indiana Court, Cincinnati, Ohio 45241.

Once one understands carbon path flashovers, arc tracking flashovers, and the details of circuit breaker response times, the systems surrounding short circuit fires should evaporate.

Fredrick F. Fratkin, P.E. is an Electrical Engineering graduate of The Ohio State University (1984). He is President of Professional Analytical and Consulting Engineers (P.A.C.E.).

TABLE A

Relative ages of 18 romex-type cables which short circuited to cause fires.

<1/2 Hour	18 Years	
2 Weeks		18 Years
2 Weeks		19 Years
2 Years		18 Years
6 Years	●	30 Years
8 Years	●	40 Years
9-12 Years	●	50 Years
9 Years		

PACE

INC.

PROFESSIONAL ANALYTICAL & CONSULTING ENGINEERS, INC.

4325 Indaco Court • Cincinnati, Ohio 45241 • (513) 753-2771
1-800-PACE-030 • Fax: (513) 753-0330

"KEEPING PACE"-#63

VEHICLE FIRES

The attached color copies of fuse blocks in various automobiles demonstrate how the manufacturers are progressing toward more and smaller fuses. This provides much better protection against short circuit arcing fires. 10 ampere and smaller fuses will open roughly 100 times faster than 15 ampere and larger fuses when an arc occurs. The arc is extinguished so quickly by the 10 ampere and smaller fuses that no fire ensues. I have been told that the 1996 Lincoln Continental will have about 90 mostly smaller fuses in its fuse block.

For a complete discussion of this theory, please refer to "Keeping P.A.C.E." #50, which includes my article, "Vehicle Short Circuit Fires and Their Prevention." That article was based on information I began supplying to the automotive industry in 1987. What really got their attention was my video tape. This one minute video tape shows two each, 16 gauge stranded copper conductors, six feet long, connected to a 12 volts, D.C. vehicle battery. A torch is used to set up carbon path arcing between the conductors. The arcing current lasts for well over one minute and finally melts both copper conductors completely apart without ever drawing enough electrical current to pop a 15 or 20 ampere vehicle fuse. This video tape and my article are included with each of our reports on vehicle short circuit fires.

The color copy of fuse blocks that is attached was made with our laser color copier. We use this copier for all our reports so that you may have clear color copies of photographs pertaining to your case, as well as the original photographs.

Sincerely,


Frederick F. Franklin, President



1991 Lincoln Continental

Fuse Color Code

Amber 5 amperes
Red 10 amperes
Blue 15 amperes
Yellow 20 amperes
Green 30 amperes



1988 Oldsmobile 98



1995 Lincoln Continental



1984 Chevrolet Caprice



1993 Buick Park Avenue



Components for fuse block
of 1995 Lincoln Continental



1984 Chevrolet Caprice



1995 Chrysler PT Cruis

PAGE TWO

March 20, 1998

CONSUMER AFFAIRS
SECTION




'98 MAR 26 P2:53

Ford Motor Company
300 Renaissance Center, Po Box 43360
Detroit, MI 48249

Claim Number: [REDACTED]
Key Claim Number: [REDACTED]
Our Insured: [REDACTED]
Date of Loss: 04/06/97
Amount of Loss: \$11,270.00
Location of Loss: TERRE HAUTE IN
Our Account No: SUB100101

407214 ✓
DU



Dear Ford Motor Company :

This company carries insurance for the above named insured. Under the coverage provisions of our policy we were obligated to pay damages in the above amount.

Our investigation indicates that the damages resulted from your negligence.

If you are insured with liability coverage, notify your carrier at once. Please write the name of the insurance company and your policy number below and return to the address shown below. If you are not insured, contact the writer at once so that arrangements can be made to settle this matter amicably and without the necessity of litigation.

INSURANCE COMPANY _____
POLICY NUMBER _____
COMPANY ADDRESS _____
AGENT'S NAME _____
ADDRESS _____
PHONE # _____

Description of Loss: OUR INSURED'S VEHICLE CAUGHT ON FIRE THAT IS TOTALLED

Very truly yours,

Steven Lewis
Steven Lewis
Central Recovery Office
Hartford Underwriters Insurance Co.
(973) 361-3700, ext. 317


Garden State Regional Claims Office
Bankway 80 Corporate Center
108 Enterprise Drive
P.O. Box 8009
Bankway, NJ 07826
973 261 3700
973 261 4486 Fax

ENR2-028 38787



April 02, 1998

Ford Motor Company
300 Renaissance Center, Po Box 43360
Detroit, MI 48243



Claim Number:

Insured:

Address:

Date of Loss:

Amount of Loss:

Location of Loss:

Account Number:

Terre Haute, IN
04/05/97
\$11,270.00
TERRE HAUTE IN
SUB100101

407214
JW
Closed

Dear Ford Motor Company

We have written to you on prior occasions advising you of our subrogation rights in connection with the above captioned claim. We have had no response from you as to your position concerning settlement of our claim.

We are writing this final letter for the purpose of notifying you that we are contemplating suit within the next 20 days if we do not receive a reply. Please give this matter your prompt attention.

Very truly yours,

Steven Lewis


Hartford Underwriters Insurance Co.

Carolina State Regional Claim Office
Rushway 20 Corporate Center
100 Enterprise Drive
P.O. Box 2400
Rushway, NJ 07066
973 361 5700
973 361 4486 Fax


EP02-025 35788













ER62-025 35713



2982-025 35714



BR2-825 35715





1962-025 35710






ER32-625 2871B
















EP82-826 35724




ER62-925 35725














ER02-025 35728



ERG2-025 35731



EA02-025 35732



ER62-625 38733






ER02-025 38735




EA82-025 36735



EA02-025 35737





EA82-625 35736



2002-025 35739




ER62-025 35746



ERR2-025 35741




ER82-025 35742




5982-828 35743









NR02-025 28748














EA02-028 30780



0482-625 35751









ERG2-025 38754



5982-025 35728




ER02-028 35756







ER02-025 3575A




ERG2-025 35758








ER92-825 25752



BA82-825 35763




ER62-628 35784






DAG-820 35788



BR62-825 38787





=>

VIN: 2MECM75W1NX616160 CASE: _____ HOME PHONE: _____
 LAST NAME: _____ ZIP/POSTAL: _____ CTRY: _____

A	CUSTOMER NAME/ C City	Address/ St/Prov	Zip/Postal	Address/ Ctry	Home Phone
	SULLIVAN	IN		USA	

F1=Help F2=VehicleList
 F7=Prev F8=Next
 NO MORE RECORDS AVAILABLE

F4=UpdCustInfo
 F11=Menu

F5=AddCustIssue
 F12=Return

OGDB191

==>

Name:

Address:

Address:

City:

SULLIVAN

Zip/Postal:

Home Phone:

Day Phone:

State/Prov: IN

Country: USA

A	VIN/	Year	Model/	Sale Type/
C	Owner Status		Previous Owner	Open Issues
	1LNFM83WBXY606179	1999	TOWN CAR	Individual Rtl
	ORIGINAL			
	1LNLM91V7VY698076	1997	MARK VIII	Individual Rtl
	ORIGINAL			
	2MECM75W1NK616160	1992	GRAND MARQUIS	Individual Rtl
	ORIGINAL			
	2MEBP93F0GX634377	1986	GRAND MARQUIS	Individual Rtl
	ORIGINAL			

F1=Help

F2=IssueList

F5=AddIssue

F7=Prev

F8=Next

F9=ESP

F10=WarrHistory

F11=Menu

F12=Return

F13=Recall/ONP

F14=SpecialCoverage

NO MORE RECORDS AVAILABLE

OGDB191

-->

VIN: 2MECM75W1NX616160 Year: 1992 Model: GRAND MARQUIS
WSD: 05/02/91 Build Date: 04/12/91

A	-----Campaign-----				Status	Dealer
C	Number	Type	Description	Status	Date	Code

F1=Help F7=Prev F8=Next F11=Menu F12=Return
NO DETAIL RECORDS FOUND

OGDB191

```

ENTER CAMPAIGN NUMBER=>          VIN=> 2MECM75WLNK616160  TYPE OF SEARCH: A
MODEL YEAR:   DEFECT:             BODY STYLE:
NEW STATUS CODE:                   CAMP DIV      :
REPAIR INFORMATION:   TYPE CODE:   SUPP CODE   :
REPAIR DATE:         DEALER P/A:   KIT CODE    :
MICRO REF:           CLAIM NUM:    OASIS DATE  :
DELETE REASON:                                     VENDOR N/A INFORMATION:
RESP DEALER INFORMATION: NEW:      IND:   MATCH CODE:
CURRENT:             ASSIGNED:    SOURCE:   EXTRACT DATE:
***** STATUS INFORMATION: ***** ***** REPAIR INFORMATION: *****
CODE DESCRIPTION      DATE  TYPE  DATE  P/A  CLAIM# MICRO# CL SRC

```

```

DELETE REASON:
F1-INQUIRY F2-G140 F3-EXIT F5-G130 F7-FIRST F8-NEXT F9-MORE STATUS
F10-ADD STATUS F11-REVISE (ALL DATA FIELD DATES YY-MM-DD)
#807-END OF CAMPAIGNS FOR VEHICLE - CURRENT AND HISTORY DATABASES      OGDB191

```

```

ENTER CAMPAIGN NBR ==>          VIN ==> 2MECM75W1NX616160
DEFECT      : _____          BODY STYLE DESC: _____
RESP DEALER : _____          BEGINNING MAILED DATE: _____ YY-MM-DD
RELEASE DESC : _____          ENDING MAILED DATE   : _____ YY-MM-DD
CAMPAIGN DIV : _____          FLEET CODE: _____ FLEET MGMT LOC CODE: _____
LAST NAME   : _____          INITIALS: _____
STREET ADDR1 : _____
ADDR2       : _____          ST/PRV: _____
CITY        : _____          CTRY: _____
ZIP/POSTAL CODE: _____      N-A SOURCE: _____ N-A EFF DATE: _____ YY-MM-DD
*****
RESP DEALER : _____          BEGINNING MAILED DATE: _____ YY-MM-DD
RELEASE DESC : _____          ENDING MAILED DATE   : _____ YY-MM-DD
CAMPAIGN DIV : _____          FLEET CODE: _____ FLEET MGMT LOC CODE: _____
LAST NAME   : _____          INITIALS: _____
STREET ADDR1 : _____
ADDR2       : _____          ST/PRV: _____
CITY        : _____          CTRY: _____
ZIP/POSTAL CODE: _____      N-A SOURCE: _____ N-A EFF DATE: _____ YY-MM-DD
F1-INQUIRY  F3-EXIT  F4-QUIT  F5-G150  F7-FIRST PAGE  F8-NEXT PAGE  F9-G140
KSD3-VIN NOT FOUND
OGDR191

```

```

==>
VEHICLE ID: 2NNX616160 (WVYFEBEEN) Vin: 2HECM75W1NX616160 Div: 3 Status: 800
Vehicle Line: CFP Convy Deliv: 050291 Orig P-Lvl: 210 Selling Dlr: 46X625
Order Recpt: 032191 ShipTo Stat: Curr P-Lvl: 210 Sale Date: 050291
Orig Sched: 032591 Rls-To Stat: IN Order Dlr/Rqg: 46625/46 Demo Dt:
Inv Prep: 040591 Orig Int St: 042391 Orig Rls Dir: 46625 Deliv Type: 0
Prod Date: 041291 Curr Int St: 042391 Rls Dlr P&A: 11592 Sales Prd: 091051
Rls Date: 042291 Dlrfin Ext: 052591 Warr Start: 050291 Cancel Sl:
Memo Consgn: P&C Ext: 052591 Warr#-Ind: Sale Status: G
Orig Fltbus: 042291 Advert Ext: 052591 -Date- -Dealer- -Region-
Curr Fltbus: 042291 Slopn S#:#: 4420 Shipped: 042591
T/Name: ██████████ Curr Stock: 042291 46X625 46
Addr: ██████████ State: IN 1st-Prior:
City: SULLIVAN W/A-Rep#: 050691 2nd-Prior:
Zip: ██████████ Warr-Ins-Ind: 3rd-Prior:
V.O.:1 2 3 4 5 6 7 8
12345234567890123456789012345678901234567890123456789012345678901234
N75NKY 2 J1 25C9293 IC 8 T3 J3P8Q7 3 KH B 46X625 1 DD
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
HH3H 3 2 W2MEC1 2 2 172A59WT 8
F1=Help F3=Exit F4=Primary Menu F5=Financial Screen F9=Screen #3

```

OGDB191

==>
VEHICLE ID: 2MNX616160 (NWIFPABRERS) Vin: 2MECM75WINX616160 Div: 3 Status: 800

Ordering Name: [REDACTED]		Distr Status: P
Secondary Name:		Last NAVIS St: 050791
Ordering FIN:	Selling FIN:	Distr Stat Dt: 050291
Order-For FIN:	Sold-To Fin:	Last Activity: 010992
Orig Ordz Type: 1		Serialized Dta: 032191
		Scheduled Dta: 032591
		Mexico Status:

Component Data -----

Dr Post/Calib: GAA	Tire Brand: A4
Main Cntl Lbl: HAA	SEC:
Engine Tag Cd: 2G802AB	
Engine Serial: W	
Driver Airbag: 1PUW088E10140	
Passgr Airbag:	Air: GY

F1=Help F3=Exit F4=Primary Menu F5=Financial Screen F6=Screen #1

OG08191

-->

VEHICLE ID: 2RNX616160 (NVPASS) Via: 2MECH75WINX616160 Div: 3 Status: 800

Financial Data					
Orig Totl Inv:	20963.00	A-Plan Price:	19997.00	Fredal Invoice:	.00
Curr Totl Inv:	20963.00	Total Adj:	.00	Sched-A GST:	.00
Base Vehicle:	16821.00	Base Adj:	.00	FOC GST:	.00
Options:	3157.00	Option Adj:	.00	Price Protect:	.00
Base Holdback:	594.00	Base Hb Adj:	.00	Chargeback Amt:	
Optn Holdback:	112.00	Option Hb Adj:	.00	30-Day FF Amt:	.00
Misc Charges:	.50	Gas Amt:	14.50	Floor Plan:	87.34
Finance Charge:	260.00	Sched-B Amt:	535.00	F&C Charge:	53.20
FDAS/LMCA:	175.00	Mktng Contrib:	.00	Pre-Dlvry Amt:	.00
Financing Data					
Finance Source:	0000001	O-Warr Start:	050291	Release Date:	042291
Orig Int St-Su:	N	Co Tag Number:		Transit Time:	14
Net Draft Ind:		Pre-del Date:		Elis Plus Trans:	050691
Floor Plan Date:	052591	Prdlvry S.Code:		Ramp Code:	50
Advt Comm Code:	1	Lease Code:		Method Shipped:	7
Upfront FF Ind:		Invoice In-Proc:		Name Cons Loc:	

F1=Help F2=Exit F4=Primary Menu F6=Screen #1 F8=Screen #3

OGDB191

INSTALLED OPTION INFORMATION:

Air Conditioning:	C/S - MANUAL AIR CONDITIONER	GVW Code:	-
Alternator Amp Rating:	*	GVW Class Code:	C
Audio Dials:	* - [N/A]	Instrumentation:	* - [N/A]
Axis Ratio:	EQACC - 3.08 FINAL DRIVE RATIO	Mirror(Driver Side):	* - [N/A]
Axis Type:	EQHAC - LIMITED SLIP REAR AXLE	Mirror(Passg Side):	* - [N/A]
Battery Amp Rating:	FC	Paint:	PN0AD - MOCHA Frost CC
Brake Code:	* - [N/A]	Power Antenna:	AE - POWER TELESCOPIC RADIO ANTENNA
Brake Code(Service):	* - [N/A]	Radio:	AE - ELECTRONIC AM/FM STEREO/CASSETTE
Calibration Code:	318AR00A	Sound System:	* - [N/A]
Color(Access):	* - [N/A]	Suspension Axle:	* - [N/A]
Color(Trim):	* - [N/A]	Tire Brand:	AJ - MICHELIN TIRE VENDOR
Delivery Type:	D	Tire Size:	D30MF - P215/70R13 WSW
Driveshaft Code:	*	Traction Control:	AB - ANTI-SPIN TRACT BRAKES W/O TSD
Front Seat:	CK - SEAT-SPLIT BENCH	Wheel Base:	* - [N/A]
Fuel Type:	* - [N/A]		

EPA INFORMATION: EMISSIONS INFORMATION:

EPA Code:	* Emission Code:	C/S - C/S
EPA Coverage(Air):	* Emission Cert Type:	F
EPA Coverage(Temp):	* Emission Desc Suffix:	HAA
EPA Plan Year:	* Engine Family:	NFMM45V10P8
EPA Signature Date:		

Any comments? You can contact

webmaster@crw.ford.com

Standard Claims List For Model Year 1992

Note: All Costs are in US Dollars

2M8CM75W1NX616160	C77	C/M	C/A	C/AJ	C/B	AW	C/D	C/VN	12-APR-1991	02-MAY-1991	346625	USA	2	4
AWB Claim Key:	10886711	Trx Code:	1	Labor Hrs:	6	Labor Cost:	16.8	Material Cost:	0					
Dr. C#-Sub C#:	11593-*	Name:	BOB WALTERS LINC-MERC INC		Ph:	812-8474306	St:	IN	City:	USA				
Task Comments:	BATTLE RIGHT SIDE UNDERBATH CAR-TEST DRIVE-RIGHT BRACKET AND INSULATOR LO													
2M8CM75W1NX616160	C77	C/M	C/A	C/AJ	C/B	AW	C/D	C/VN	12-APR-1991	02-MAY-1991	346625	USA	2	3
AWB Claim Key:	10886711	Trx Code:	1	Labor Hrs:	6	Labor Cost:	16.8	Material Cost:	0					
Dr. C#-Sub C#:	11593-*	Name:	BOB WALTERS LINC-MERC INC		Ph:	812-8474306	St:	IN	City:	USA				
Task Comments:	CUSTOMER COMPLAINS CAR PULLS TO RIGHT-GE ALIGNMENT-IS WITHIN SPEC													
2M8CM75W1NX616160	C77	C/M	C/A	C/AJ	C/B	AW	C/D	C/VN	12-APR-1991	02-MAY-1991	346625	USA	29	4
AWB Claim Key:	10886711	Trx Code:	894	Labor Hrs:	9	Labor Cost:	23.8	Material Cost:	123.28					
Dr. C#-Sub C#:	04418-*	Name:	CLINTON FORD-MERCURY SALES INC		Ph:	317-8321564	St:	IN	City:	USA				
Cost Comments:	NOISY MUFFLER													
Task Comments:	REPLACE CORRODED AND FITTED MUFFLER													

Any comments? You can contact



webmaster@ams.ford.com

Claim Detail Report

Note: All costs are in US dollars

Model Year = 1992; Claim Key = 10996710

Vehicle Information

Model Year: 1992
 Market Derived: C/M - L-M DIVISION DERIVATIVE
 Body/Cab Type: C/FA - 4 DOOR SEDAN-4 LITE
 Version/Series: C/ALLS VERSION
 Drive Type: C/B-2 WHL L/H REAR DRIVE
 Vehicle Line: C/FP-GRAND MARQ (EN53/EN114)
 [92-99]
 Warranty Start Date: 02-MAY-1991
 Production Date: 12-APR-1991
 VIN: 2MECM75W1NX616160

Claim Information

Document Number: 203443
 Repair Date: 25-JUN-1991
 Distance: 642
 TIS: 2

Dealer Information:

Dealer Name: BOB WALTERS LINC-MERC INC
 Dealer Code: 11592 - *
 Address: ROUTE 4, BOX 163
 City: LINTON
 State: IN Zip Code: 47441
 Country: USA Region Code: NA
 Phone: (812)430-4306

Expense Information

Customer Paid Amount: 0
 Deductible Amount: 0
 Dealer Paid Amount: 0
 Labor Cost: 16.8
 Misc. Expense Amount: 0
 Part Markup Amount:
 Material Cost: 0
 Total Cost Gross: 16.8

Cust. Concern Code: * -

Condition Code: * -

Technician Comment: RATTLE RIGHT SIDE UNDERNEATH CAR--TEST DRIVE--RIGHT
 BRACKET AND INSULATOR LO

Customer Comment:

Labor On Code Labor Op Description Labor Op Cost

M 0

Causal Flag	Full Part Number	Part Description	Part CPSC	Extended Quantity	Amount
Y	* 5C263 *	BRKT&INS ASY MUFFLER	090303	0	0

Any comments? You can contact



webmaster@qis-ford.com

Claim Detail Report

Note: All costs are in US dollars
 Model Year = 1992; Claim Key = 10996709

Vehicle Information

Model Year: 1992
 Market Derived: C/M - L-M DIVISION DERIVATIVE
 Body/Cab Type: C/FA - 4 DOOR SEDAN-4 LITE
 Version/Series: C/AJ-LS VERSION
 Drive Type: C/B-2 WHL L/R REAR DRIVE
 Vehicle Line: C/FP-GRAND MARQ (EN53/EN114)
 [92-99]
 Warranty Start Date: 02-MAY-1991
 Production Date: 12-APR-1991
 VIN: 2MECM75W1NK616160

Claim Information

Document Number: 203443
 Repair Date: 25-JUN-1991
 Distance: 642
 TIS: 2

Dealer Information:

Dealer Name: BOB WALTERS LINC-MERC INC
 Dealer Code: 11592 - *
 Address: ROUTE 4, BOX 163
 City: LINTON
 State: IN Zip Code: 47441
 Country: USA Region Code: NA
 Phone: (812)430-4306

Expense Information

Customer Paid Amount: 0
 Deductible Amount: 0
 Dealer Paid Amount: 0
 Labor Cost: 16.8
 Misc. Expense Amount: 0
 Part Markup Amount:
 Material Cost: 0
 Total Cost Gross: 16.8

Cust. Concern Code: * -

Condition Code: * -


Technician Comment: CUSTOMER COMPLAINS CAR PULLS TO RIGHT-CK ALIGNMENT-IS WITHIN SPECS

Customer Comment:

Labor Op Code	Labor Op Description	Labor Op Cost
3001AF	CASTER, CAMBER, TOE-IN CHECK	0

Causal Flag	Full Part Number	Part Description	Part CPSC	Quantity	Extended Amount
Y	* FRONT *	FRONT END ALIGNMENT	040001	0	0

Any comments? You can contact



webmaster@us-ford.com

Claim Detail Report

Note: All costs are in US dollars

Model Year - 1992; Claim Key - 10996711

Vehicle Information

Model Year: 1992
 Market Derived: C/M - L-M DIVISION DERIVATIVE
 Body/Cab Type: C/FA - 4 DOOR SEDAN-4 LITE
 Version/Series: C/AJ-LS VERSION
 Drive Type: C/B-2 WHL L/H REAR DRIVE
 Vehicle Line: C/FP-GRAND MARQ (EN53/EN114)
 [92-99]
 Warranty Start Date: 02-MAY-1991
 Production Date: 12-APR-1991
 VIN: 2MECM75WINX616160

Claim Information

Document Number: 010375
 Repair Date: 14-SEP-1993
 Distance: 29142
 TIB: 29

Dealer Information:

Dealer Name: CLINTON FORD-MERCURY SALES
 INC
 Dealer Code: 04618 - *
 Address: 335 S THIRD ST
 City: CLINTON
 State: IN Zip Code: 47842
 Country: USA Region Code: NA
 Phone: (317)356-3564

Expenses Information

Customer Paid Amount: 0
 Deductible Amount: 0
 Dealer Paid Amount: 0
 Labor Cost: 28.8
 Misc. Expense Amount: 0
 Part Markup Amount:
 Material Cost: 123.28
 Total Cost Gross: 152.08

Cust. Concern Code: N59 - OTHER SQUEAK/RATTLE (EXCLUDING WIND NOISE)

Condition Code: 08 - OTHER/UNKNOWN(NO APPROPRIATE COND. CODE)

Technician Comment: REPLACE CORRODED AND PITTED MUFFLER

Customer Comment: NOISY MUFFLER

Labor Op Code Labor Op Description Labor Op Cost

5230A MUFFLER REPLACE 0

Causal Flag	Full Part Number	Part Description	Part CPSC	Part Quantity	Extended Amount
Y	F2AZ 5230 E	MUFFLER ASY	090101	1	0

Any comments? You can contact



webmaster@mm-ford.com