

EA02-025

10-28-03

**FORD 10/28/03
LETTER TO ODI**

BOOK 2 OF 2

PART A - E

PART C

88-400

11

11

1196

CL

SEARCHED	INDEXED
SERIALIZED	FILED
FBI - [illegible]	

88-400-2100


State Farm Insurance Companies



State Farm Insurance Claim Office
2701 Executive Drive
P.O. Box 11637
Green Bay, Wisconsin 54307-1637
Phone: 414-497-5555

May 22, 1996

Howard E Keyse
Ford Motor Company
Parklane Towers Suite 300
Dearborn MI 48126-2568



RE: Our Claim Number: 49-F091-379
Our Insured: [REDACTED]
Date of Loss: 01/26/96

REDACTED

Dear Mr. Keyse:

We recently received a claim for the above date of loss for damages in the amount of \$14,936.75 for a car fire which was started due to faulty problems with a light and bumper to a Crown Victoria. I have attached copies and documentation from our cause and origin expert and also verification of the damages. Please send a draft for the actual cash value damage amount for the above damages. I have enclosed a self-addressed envelope for your convenience in forwarding payment to me.

Should you like to discuss this further, please feel free to contact me at 414-497-5572.

Very truly yours,

Kevin Wolff
Claim Specialist
State Farm Fire & Casualty Co.

KW/rw


Enclosures

Charles C. Roberts, Jr., Ph.D., P.E.
CONSULTING ENGINEERS, INC.

ANALYSIS OF A 1992 FORD CROWN VICTORIA

Insured: [REDACTED]

Claim Number: 49-1955582



BIG ROCK, ILLINOIS 60611 • 708 555-3039

ENR2-825-B 2187

G. ROBERTS CONSULTING ENGINEERS, INC.

48 W 182 GRANARY ROAD
BIG ROCK, ILLINOIS 60011

708 855-3030
815 498-3600

Charles C. Roberts, Jr., Ph.D., P.E.

ANALYSIS OF A 1992 FORD CROWN VICTORIA

Insured: [REDACTED]

Claim Number: 49-1955562

REPORT TO:

Lisa Jelen
State Farm Insurance
P.O. Box 11937
Green Bay, WI 54307-1937

Date of Report: February 22, 1996

C. ROBERTS CONSULTING ENGINEERS, INC.

48 W 103 GRANARY ROAD
BIG ROCK, ILLINOIS 60011

708 555-3923
315 498-3990

Charles C. Roberts, Jr., Ph.D., P.E.

INTRODUCTION

An inspection was performed on a 1992 Ford Crown Victoria located at Valley Auto Pool, Appleton, Wisconsin. The purpose of the inspection was to obtain information so that an opinion could be offered on the probable cause of a fire that badly damaged the vehicle. This report details the results of the inspection and an analysis.

INSPECTION

Figures 1 through 4 show various views of the vehicle. Figure 5 is a view of the rear of the vehicle. Figures 6 through 8 show close-ups of the rear of the vehicle showing a symmetrical burn pattern. Figure 9 is a view of the trunk lid. Figure 10 is a view inside the trunk. Burn patterns suggest that the fire did not start in the trunk of the vehicle. Figure 11 is a view of the rear license plate showing burn patterns consistent with the polymer coating on the bumper having been ignited. Figures 12 and 13 are views of taillight lamp wiring which was unremarkable. Figure 14 is a view of the license plate light socket which was badly damaged. Figure 15 is a close-up of a faulted wire at the light socket. This is, in my opinion, a result of insulation breakdown in this area, causing the fire.

CONCLUSION

In my opinion, the probable cause of the fire was an electrical malfunction causing faulting at the license plate assembly, resulting in ignition of the polymer coating material on the bumper.

Respectfully Submitted,



Charles C. Roberts, Jr.

CCR/op



Figure 1 Front view of vehicle



Figure 2 Right view of vehicle



Figure 3 Rear view of vehicle



Figure 4 Left view of vehicle



Figure 5 Rear view of vehicle




Figure 6 Close-up of right rear




Figure 7 Close-up of middle of rear bumper




Figure 8 Close-up of left rear




Figure 9 View of trunk lid



Figure 10 View inside trunk



Figure 11 View of rear license plate



Figure 12 View of left rear lamp wiring



Figure 13 View of right rear lamp wiring



Figure 14 View of license plate light




Figure 15 Close-up of faulted wire

VEHICLE EQUIPMENT (CHECK IF VEHICLE HAD ANY OF THE FOLLOWING)

FEB 02 1996

Radio AM ☒ Air Cond. ☒ Power Windows ☒ Tires ☒ Transmission ☒
 AM/FM ☒ Power Steer ☒ Power Seats ☒ W/W ☒ Auto ☒
 Stereo ☒ Power Brakes ☒ Tinted Glass ☒ Radial ☒ Beams ☒
 Tape Deck ☒ Vinyl Roof ☒ Mag Wheels ☒ Special ☒ Console ☒

CB Radio Type _____ Cost _____ Date Installed _____ Purchased from _____

IV. VEHICLE CONDITION

Paint Fair Good Excellent ☒
 Transmission Fair Good Excellent ☒
 Engine Fair Good Excellent ☒
 Body Fair Good Excellent ☒

OTHER DISTINGUISHING FEATURES, [Dents, decals, trailer hitch, interior, etc.] _____

Name and address of service station/garage: _____

1. Who performs routine maintenance service _____

2. Who performs State MV inspection _____

Date last serv. 1-2-96
 Date last insp. _____

V. Date car purchased 10-25-95 New ☒ Used ☒ Purchase Price \$ 15,995⁰⁰
 Trade-in car 1990 Allowance \$ _____
 Seller Dealer/Individual Van Horn

[name] address city, state

How did you learn car was for sale? Check ☒ 1615

How was car paid for? Cash ☒ Trade ☒

If financed, name and address of finance company Van Horn Credit Union

Account # 009 Balance due 945.50 Loan term 36 months @ 5.99%

Date of last loan payment made 1-20-96 Is account past due? Yes ☒ No ☒

How long? Are keys in your possession? Yes ☒ No ☒

Ignition Key ☒ Title Key ☒ Do you have other insurance?

Yes ☒ No ☒ Policy # _____ Name of insurance Co. _____

Was this a rebuilt wreck? Yes ☒ No ☒ If yes, name of rebuilder _____

Was it a recovered theft? Yes ☒ No ☒ If yes, date of theft _____

IV. Are the answers you have given true to the best of your knowledge and belief?

Yes ☒ No ☒

Witness _____ Policyholder Karmer & Chynick
 [signature]

Address _____

FEB 02 1996

AFFIDAVIT OF VEHICLE FIRE

(All Questions Must Be Answered)

1. Name of Insured [REDACTED] Claim Number 1955582
 Address [REDACTED] Home Phone No. [REDACTED]
 Occupation Homeowner Driver's License [REDACTED]
 Marital Status Married Date of Birth [REDACTED]
 Number of Dependents 0

2. Date of fire 1-25-96 Time 7:10 AM PM Was vehicle locked? NO
 Amount for which you are making claim \$1,500 Were windows rolled up? YES
 Specific location where vehicle burned In the Garage
 Reason vehicle was at this location Truck when it R. rolled when not used
 Name & address of person who left auto at this location KAYMEN, Oldsmobile
 Their Driver's License # 0426-5051-1111-03
 When was fire discovered? Date 1-25 Time 7 AM PM By whom KAYMEN, O.
 When was fire reported to fire dept? Date 1 Time PM PM By whom KAYMEN, O.
 Location of fire station Abrams, NJ
 Describe fire (where, color of smoke, cause, etc.) It was out when discovered by vehicle
 Was vehicle being driven? Yes NO Describe exactly what occurred prior
 to noticing smoke or fire (electrical or mechanical malfunction) while up
and saw car was black when out to check it out
 Have you had similar problems prior to fire? Yes NO If yes, describe:

Were you carrying a container of flammable liquid in the vehicle at the time of
 fire? Yes NO If yes please answer the following, type of liquid
None Size and type of container None Where was the
 container at time of fire?

Did you smell smoke or see flames first? NO

Make of vehicle 1992 Year 500 Model VAN Type Color Red

Vehicle Idem. # 5FAC74W2NXX05451 License Plate # KAC 183 State WV

Certificate of Title # 9532707010-8 If none, why None

No. of cylinders 8 H.P. or Cubic/in 4.1 Odometer reading 45,300

Has vehicle been damaged during past three years? Yes NO

Describe (location, type, amount, date)

Were repairs completed? Yes NO Partial - By whom None

Name and address of insurance company who paid damage claims, if any

Any other claims in last 3 years on

this or any other auto? Yes NO Any other vehicles in your household? Yes NO

Name of insurance company and agent on other vehicles State Farm

Your prior insurance company and agent State Farm

Any homeowners claims in past 6 mos. with State Farm? NO Other Company NO

5-14

96-3833

MIN

5/96

cl

97-24494-30
1-19WD

2002-000 20077

Office of the General Counsel



Ford Motor Company
Parklane Towers West
Suite 400
Three Parklane Boulevard
Dearborn, Michigan 48125-2598

May 20, 1997

Elch & Franklin
Attorneys At Law
11 East Adams Street
Chicago, IL 60608
ATTENTION: THOMAS G. GRACE

Re: Claimant: [REDACTED]
Date of Event: November 18, 1996
Your File: 599-722-151

Dear Mr. Grace:

This responds to your letter of May 1, 1997 regarding the above claimant.

Enclosed please find a copy of warranty as well as the recalls for the claimant's vehicle. We believe our denial of May 20, 1996, is proper and prepared to defend should litigation ensue.

Please be advised that all necessary steps should be taken to ensure that the subject vehicle and all of its component parts are maintained and preserved for trial. Ford Motor Company has the right to inspect the vehicle and remove and test any component part that you claim to be defective, and to be presented with the vehicle and the subject component part(s) at the time of trial, should litigation ensue from this informal claim.

If you propose to repair the vehicle for continued usage, such repairs may not be performed until after Ford Motor Company has inspected the vehicle and removed and tested any component part you claim to be defective or advised you in writing that it does not intend to perform such inspection and/or testing at this time. But even in that event, Ford Motor Company will insist that all components claimed to be defective are maintained and preserved for trial.

Sincerely,

Nancy Carpenter
Claims Analyst


EP62-626 28578




ERG-825 20070

WARRANTY SUMMARY

New Vehicle Limited Warranty



Emissions Warranty



WHAT IS NOT COVERED

ALTERATION, MISUSE, OR DAMAGE CAUSED BY ACCIDENT

Examples are:

- ◆ Collision, fire, theft, freezing, vandalism, riot, explosion, or objects striking the vehicle
- ◆ Missing the vehicle, such as driving over curbs, overloading, racing, or using the vehicle as a stationary power source
- ◆ Alteration or modification of the vehicle, including the body, chassis, or components after the vehicle leaves the control of Ford
- ◆ Tampering with the vehicle, tampering with the emissions systems or with other parts that affect these systems
- ◆ Disconnecting or altering the odometer, or where the actual mileage cannot be determined due to the odometer being inoperative for an extended period of time
- ◆ Contaminated or improper fuel/fluids
- ◆ Customer-applied chemicals

DAMAGE CAUSED BY USE AND/OR THE ENVIRONMENT

Surface rust and deterioration of paint, trim, and appearance items that results from use and/or exposure to the elements are not covered. Examples are:

- ◆ Stone Chips, Scratches
- ◆ Dings/Dents
- ◆ Road Salt, Tree Sap
- ◆ Bird Droppings
- ◆ Lightning, Hail
- ◆ Windstorm
- ◆ Earthquake
- ◆ Water or Flood



Office of the General Counsel

Ford Motor Company
Parklane Towers West
Suite 400
Three Parklane Boulevard
Dearborn, Michigan 48124

May 20, 1996

The St. Paul and Marine Insurance Company
Midwest Recovery Office
P.O. Box 9379
Bloomington, MN 55440-9379
ATTENTION: DEBRA PAGE

Re: Claimant: [REDACTED]
D/E: November 13, 1995
Y/Claim #: 15001-7221-6

Dear Ms. Page:

Following a review of the facts and circumstances surrounding this event, Ford Motor Company finds no evidence of a manufacturing or design defect, therefore, we must deny liability for this claim.

Please be advised that all necessary steps must be taken to ensure that the subject vehicle and all of its component parts are maintained and preserved for trial. Ford Motor Company has the right to inspect the vehicle and remove and test any component part that you claim to be defective, and to be presented with the vehicle and the subject component part(s) at the time of trial, should litigation ensue from this informal claim.

If you propose to repair the vehicle for continued usage, such repairs may not be performed until after Ford Motor Company has inspected the vehicle and removed and tested any component part you claim to be defective or advised you in writing that it does not intend to perform such inspection and/or testing at this time. But even in that event, Ford Motor Company will insist that all components claimed to be defective are maintained and preserved for trial.

Your engineering report is enclosed per your request.

Sincerely,

Nancy Carpenter
Claims Analyst

Encl.

stpa/cg/indbgm/kl.w22

ENC2-025 29581

GENERAL INCIDENT REPORT		2. Incident Description CAR FIRE		3. Box 300	4. PIA 12	5. Date Reported 95-11-0800	
1. Route To: Traffic <input type="checkbox"/> MID <input checked="" type="checkbox"/> File <input type="checkbox"/> Patrol <input type="checkbox"/> Other <input type="checkbox"/>		4. Type Premise DRIVEWAY		6. Date Occurred 111395		7. Time Occurred 2330	
8. Location of Incident 481 DEVISION		9. Time Dispatched KANE 2330		10. Time Arrived 2333		11. Time Cleared 0018	
12. Name of Employer/Occupation M A		13. Address ELGIN		14. Home Phone		15. Victim/Offender Relationship	
16. Name and address of injured/witness		17. Transported to hospital by:		18. Hospital Name		19. Name of Physician	
20. Carver Name		21. Date Notified		22. Time Notified		23. Location of Victim/Offender at time of incident	
24. Other Persons: V-Victim; L-Legal Owner; S-Suspect; A-Arrested; R-Reported; M-Monitored; HAD-Accident or Public Hearing; S-Supervisor; W-Witness; R-Report; SP-Special; S-Suspect; O-Other (Specify)							
25. Other Persons: V-Victim; L-Legal Owner; S-Suspect; A-Arrested; R-Reported; M-Monitored; HAD-Accident or Public Hearing; S-Supervisor; W-Witness; R-Report; SP-Special; S-Suspect; O-Other (Specify)							
26. Name (Last, First, Middle)							
27. Date of Birth							
28. Home Address							
29. Home Phone							
30. Business Phone							
31. Height							
32. Weight							
33. Build							
34. Hair Color							
35. Hair Style							
36. Eye Color							
37. Skin Tone							
38. State Origin							
39. Markings, Scars, Tattoos							
40. Source/Reference							
41. Vehicle Involved							
42. Year Make							
43. Body Style							
44. License No.							
45. VIN							
46. Chy Sinker No.							
47. Motor of entry where							
48. Method of entry where							
49. Where Home							
50. Last Notified (Name)							
51. Date Notified							
52. Weather Conditions							
53. Temperature Range							
54. Method of Theft (if applicable)							
55. Name of Supervisor at Scene							
56. Task Charge							
57. Other							

On 11/8/95 at 2330hrs. A/C. Name was dispatched to 481 DEVISION ALONG
 WITH EFD ENGINE 1. W/DRIVEWAY TO A VEHICLE FIRE. I WAS INCHARGED BY PIA
 AND FIREFIGHTERS. IT WAS DETERMINED THE CAUSE OF THE BLAZE WAS UNDETERMINED
 THE NAME NO EVIDENCE OF SUSPICIOUS ACTIVITY COULD BE DETECTED IN OR AROUND THE
 VEHICLE. THE VEHICLE SUFFERED EXTENSIVE DAMAGE DUE TO FIRE.


48. First Officer Assigned		49. Assigning Officer Assigned	
50. Status		51. Status	
52. Status		53. Status	
54. Status		55. Status	
56. Status		57. Status	
58. Status		59. Status	
60. Status		61. Status	
62. Status		63. Status	
64. Status		65. Status	
66. Status		67. Status	
68. Status		69. Status	
70. Status		71. Status	
72. Status		73. Status	
74. Status		75. Status	
76. Status		77. Status	
78. Status		79. Status	
80. Status		81. Status	
82. Status		83. Status	
84. Status		85. Status	
86. Status		87. Status	
88. Status		89. Status	
90. Status		91. Status	
92. Status		93. Status	
94. Status		95. Status	
96. Status		97. Status	
98. Status		99. Status	
100. Status		101. Status	
102. Status		103. Status	
104. Status		105. Status	
106. Status		107. Status	
108. Status		109. Status	
110. Status		111. Status	
112. Status		113. Status	
114. Status		115. Status	
116. Status		117. Status	
118. Status		119. Status	
120. Status		121. Status	
122. Status		123. Status	
124. Status		125. Status	
126. Status		127. Status	
128. Status		129. Status	
130. Status		131. Status	
132. Status		133. Status	
134. Status		135. Status	
136. Status		137. Status	
138. Status		139. Status	
140. Status		141. Status	
142. Status		143. Status	
144. Status		145. Status	
146. Status		147. Status	
148. Status		149. Status	
150. Status		151. Status	
152. Status		153. Status	
154. Status		155. Status	
156. Status		157. Status	
158. Status		159. Status	
160. Status		161. Status	
162. Status		163. Status	
164. Status		165. Status	
166. Status		167. Status	
168. Status		169. Status	
170. Status		171. Status	
172. Status		173. Status	
174. Status		175. Status	
176. Status		177. Status	
178. Status		179. Status	
180. Status		181. Status	
182. Status		183. Status	
184. Status		185. Status	
186. Status		187. Status	
188. Status		189. Status	
190. Status		191. Status	
192. Status		193. Status	
194. Status		195. Status	
196. Status		197. Status	
198. Status		199. Status	
200. Status		201. Status	
202. Status		203. Status	
204. Status		205. Status	
206. Status		207. Status	
208. Status		209. Status	
210. Status		211. Status	
212. Status		213. Status	
214. Status		215. Status	
216. Status		217. Status	
218. Status		219. Status	
220. Status		221. Status	
222. Status		223. Status	
224. Status		225. Status	
226. Status		227. Status	
228. Status		229. Status	
230. Status		231. Status	
232. Status		233. Status	
234. Status		235. Status	
236. Status		237. Status	
238. Status		239. Status	
240. Status		241. Status	
242. Status		243. Status	
244. Status		245. Status	
246. Status		247. Status	
248. Status		249. Status	
250. Status		251. Status	
252. Status		253. Status	
254. Status		255. Status	
256. Status		257. Status	
258. Status		259. Status	
260. Status		261. Status	
262. Status		263. Status	
264. Status		265. Status	
266. Status		267. Status	
268. Status		269. Status	
270. Status		271. Status	
272. Status		273. Status	
274. Status		275. Status	
276. Status		277. Status	
278. Status		279. Status	
280. Status		281. Status	
282. Status		283. Status	
284. Status		285. Status	
286. Status		287. Status	
288. Status		289. Status	
290. Status		291. Status	
292. Status		293. Status	
294. Status		295. Status	
296. Status		297. Status	
298. Status		299. Status	
300. Status		301. Status	
302. Status		303. Status	
304. Status		305. Status	
306. Status		307. Status	
308. Status		309. Status	
310. Status		311. Status	
312. Status		313. Status	
314. Status		315. Status	
316. Status		317. Status	
318. Status		319. Status	
320. Status		321. Status	
322. Status		323. Status	
324. Status		325. Status	
326. Status		327. Status	
328. Status		329. Status	
330. Status		331. Status	
332. Status		333. Status	
334. Status		335. Status	
336. Status		337. Status	
338. Status		339. Status	
340. Status		341. Status	
342. Status		343. Status	
344. Status		345. Status	
346. Status		347. Status	
348. Status		349. Status	
350. Status		351. Status	
352. Status		353. Status	
354. Status		355. Status	
356. Status		357. Status	
358. Status		359. Status	
360. Status		361. Status	
362. Status		363. Status	
364. Status		365. Status	
366. Status		367. Status	
368. Status		369. Status	
370. Status		371. Status	
372. Status		373. Status	
374. Status		375. Status	
376. Status		377. Status	
378. Status		379. Status	
380. Status		381. Status	
382. Status		383. Status	
384. Status		385. Status	
386. Status		387. Status	
388. Status		389. Status	
390. Status		391. Status	
392. Status		393. Status	
394. Status		395. Status	
396. Status		397. Status	
398. Status		399. Status	
400. Status		401. Status	
402. Status		403. Status	
404. Status		405. Status	
406. Status		407. Status	
408. Status		409. Status	
410. Status		411. Status	
412. Status		413. Status	
414. Status		415. Status	
416. Status		417. Status	
418. Status		419. Status	
420. Status		421. Status	
422. Status		423. Status	
424. Status		425. Status	
426. Status		427. Status	
428. Status		429. Status	
430. Status		431. Status	
432. Status		433. Status	
434. Status		435. Status	
436. Status		437. Status	
438. Status		439. Status	
440. Status		441. Status	
442. Status		443. Status	
444. Status		445. Status	
446. Status		447. Status	
448. Status		449. Status	
450. Status		451. Status	
452. Status		453. Status	
454. Status		455. Status	
456. Status		457. Status	
458. Status		459. Status	
460. Status		461. Status	
462. Status		463. Status	
464. Status		465. Status	
466. Status		467. Status	
468. Status		469. Status	
470. Status		471. Status	
472. Status		473. Status	
474. Status		475. Status	
476. Status		477. Status	
478. Status		479. Status	
480. Status		481. Status	
482. Status		483. Status	
484. Status		485. Status	
486. Status		487. Status	
488. Status		489. Status	
490. Status		491. Status	
492. Status		493. Status	
494. Status		495. Status	
496. Status		497. Status	
498. Status		499. Status	
500. Status		501. Status	
502. Status		503. Status	
504. Status		505. Status	
506. Status		507. Status	
508. Status		509. Status	
510. Status		511. Status	
512. Status		513. Status	
514. Status		515. Status	
516. Status		517. Status	
518. Status		519. Status	
520. Status		521. Status	
522. Status		523. Status	
524. Status		525. Status	
526. Status		527. Status	
528. Status		529. Status	
530. Status		531. Status	
532. Status		533. Status	
534. Status		535. Status	
536. Status		537. Status	
538. Status		539. Status	
540. Status		541. Status	
542. Status		543. Status	
544. Status		545. Status	
546. Status		547. Status	
548. Status		549. Status	
550. Status		551. Status	
552. Status		553. Status	
554. Status		555. Status	
556. Status		557. Status	
558. Status		559. Status	
560. Status		561. Status	
562. Status		563. Status	
564. Status		565. Status	
566. Status		567. Status	
568. Status		569. Status	
570. Status		571. Status	
572. Status		573. Status	
574. Status		575. Status	
576. Status		577. Status	
578. Status		579. Status	
580. Status		581. Status	
582. Status		583. Status	
584. Status		585. Status	
586. Status		587. Status	
588. Status		589. Status	
590. Status		591. Status	
592. Status		593. Status	
594. Status		595. Status	
596. Status		597. Status	
598. Status		599. Status	
600. Status		601. Status	
602. Status		603. Status	
604. Status		605. Status	
606. Status		607. Status	
608. Status		609. Status	
610. Status		611. Status	
612. Status		613. Status	
614. Status		615. Status	
616. Status		617. Status	
618. Status		619. Status	
620. Status		621. Status	
622. Status		623. Status	
624. Status		625. Status	
626. Status		627. Status	
628. Status		629. Status	
630. Status		631. Status	
632. Status		633. Status	
634. Status		635. Status	
636. Status		637. Status	
638. Status		639. Status	
640. Status		641. Status	
642. Status		643. Status	
644. Status		645. Status	
646. Status		647. Status	
648. Status		649. Status	
650. Status		651. Status	
652. Status		653. Status	
654. Status		655. Status	
656. Status		657. Status	
658. Status		659. Status	
660. Status</			

PROPERTY/EVIDENCE REPORT

ELGIN

ROUTE TO:		2. Type Report		3. Date Report Number	
TRAFFIC <input type="checkbox"/> PATROL <input type="checkbox"/>		Personal <input type="checkbox"/> Personal Property <input type="checkbox"/>		95-11-0320	
AND <input type="checkbox"/> JUVENILE <input type="checkbox"/>		Stolen <input type="checkbox"/> Crime Scene Evidence <input type="checkbox"/> Damaged <input checked="" type="checkbox"/>			
OTHER <input type="checkbox"/>		Recoveries <input type="checkbox"/> Safe Keeping <input type="checkbox"/> Other: Specify <input type="checkbox"/>			
4. Incident Description				5. Date	6. Time
CAR FIRE				11/3/95	2330
7. Incident Location					
481 DIVISION ST					
8. Arrest Information		First	Middle	DOB	Address
Off Name Last	First	Middle	DOB	Address	TX Name
01	N/A				
02					
03					
04					
9. Victim Information		First	Middle	DOB	Address
Off Name Last	First	Middle	DOB	Address	TX Name
V1		N/A			
V2					
V3					
10. ID#	11. Item No.	Qty.	Description: Manufacturer, brand, model, etc.		Serial No.
V7	1	1	1995 Ford Taurus CAR VIN: 1LNLM92W68Y764087		5,000.00
12. Investigated By		13. Date	14. Time	15. Turned over to or stored	16. Date
17. Name of Officer Submitting		18. Date	19. Time	20. Received By	21. Date
22. Analysis Requested (Give Item #)					95-11-0320
Biological _____					
Chemical _____					
Fingerprint _____					
Other _____					
23. Remarks					
24. Serial Destroyed		25. Destroyed By		26. Method	27. Date
28. Officer Reporting		29. Signature	30. Submitting Officer		31. Date
Myerson		2/14	[Signature]		7/1


BMS-625 20033




ERG-025 2004

PHOTO SHEET


10 95 120000 1000 000



DESCRIPTION: L front




DESCRIPTION: L front



DESCRIPTION: front

INSURED NAME: [REDACTED]
POLICY # [REDACTED]

PA-219 6/89
81007




DESCRIPTION: _____


CLAIM: [REDACTED]

PHOTOS TAKEN: 1-16-96 BY: A. Jowers
Date Agent/Adjuster


ESB2-028 20005



DESCRIPTION:

REAR

DESCRIPTION:


INTERIOR-DASH

DESCRIPTION:

REAR

INSURED NAME:

POLICY #



DESCRIPTION:

CLAIM #

PHOTOS TAKEN:

Date

BY:

A. PHOENIX

Agent/Adjuster

15001-7221-6

C. ROBERTS CONSULTING ENGINEERS, INC.
48 W 192 GRANARY ROAD
BIG ROCK, ILLINOIS 60011

Charles C. Roberts, Jr., Ph.D., P.E.

708 559-3039
815 488-3080

ANALYSIS OF A 1995 LINCOLN TOWN CAR
Insured: [REDACTED]
Claim Number: [REDACTED]

REPORT TO:

Anita Powers
St Paul/Economy Ins. Co.
500 Economy Ct.
Freeport, IL 61032

Date of Report: November 28, 1995

C. ROBERTS CONSULTING ENGINEERS, INC.

48 W 182 GRAMART ROAD
BAG ROCK, ILLINOIS 60011

Charles C. Roberts, Jr., Ph.D., P.E.

708 588-3030
815 488-3080

INTRODUCTION

An inspection was performed on 1995 Lincoln Town Car located at [REDACTED] Elgin, Illinois. The purpose of the inspection was to obtain information so that an opinion could be offered on the probable cause of a fire that badly damaged the engine. This report details the results of the inspection and an analysis.

INSPECTION

Figures 1 through 4 show various views of the vehicle. According to the insured, he had just parked the vehicle in the driveway when about a half hour later the vehicle was found to be on fire. Figure 5 is a view of the occupant compartment showing little fire damage when compared to the engine compartment. Figures 6 and 7 show views of the engine compartment. Burn patterns on the hood suggest a fire to the left side of the engine compartment. Figure 8 shows the engine compartment with the hood removed. Figures 9 and 10 are additional views of the engine. Figure 11 is a view of a wiring harness next to the brake booster. Figures 12 and 13 are close-ups of the wiring harness that appears to be at the origin of the fire. Figures 14 through 16 show a myriad of faulted wiring in this area.

CONCLUSION

In my opinion, the origin of the fire was on the left side of the vehicle in the vicinity of a wiring harness. There was electrical faulting in this area consistent with an electrical malfunction. In my opinion, the cause of the fire was an electrical malfunction causing heating in the wiring harness on the left side of the vehicle.

Respectfully Submitted,



Charles C. Roberts, Jr.

CCR/cp



Figure 1 Front view of vehicle



Figure 2 Right view of vehicle



Figure 3 Rear view of vehicle



Figure 4 Left view of vehicle



Figure 5 View of occupant compartment



Figure 6 View of engine compartment



Figure 7 View of engine compartment




Figure 8 View of engine compartment with hood removed



Figure 9 View of left side of engine




Figure 10 View of engine



Figure 11 View of wiring harness near brake booster



Figure 12 Close-up of wiring harness




Figure 13 Close-up of wiring harness



Figure 14 Close-up of faulted wires



Figure 15 Close-up of faulted wires



Figure 16 Close-up of faulted wires

415946

TX

ED

2005-02-02 14:00

00-212
4-14W1



UNITED SERVICES AUTOMOBILE ASSOCIATION
9800 Fredericksburg Road, San Antonio, TX 78288

CONSUMER AFFAIRS
FORT MOTOR CORP.
16800 EXECUTIVE DEPT
MD #3NE/B
DEARBORN MI 48126-4207

415045



February 28, 1999

Policyholder: [REDACTED]
Reference Number: [REDACTED]
Date Of Loss: November 20, 1998
Loss Location: Claypool, Indiana
FIRE OF OUR 1995 LINC. TOWN CAR
VIN. NO. 1LNLM81W6SY638160

DEAR SIR:

As a result of the above incident, our insured's property was damaged in the amount of \$20,461.30.

Our investigation reveals liability rests with you. We are subrogated to our insured's right of recovery against you to the extent of our payment. Our insured has no authority to give you a release for any portion of this loss for which we have paid.

The attached form needs to be completed and returned to us. However, if you were not insured please forward your certified check or money order made payable to USAA. Also, show the reference number above on your check. Please call me if you would like to discuss a payment plan.

If you wish to discuss this matter, please contact me.

Sincerely,

Virginia Gonzales

Virginia Gonzales
Claims Representative
Great Lakes Region
Phone: 1-800-531-8222 ext.7-9652
Fax Phone: 1-800-845-9053

Encl: 12763 Env

30 MAR -5 P1:19

CONSUMER AFFAIRS
SECTION

REQUEST FOR INSURANCE INFORMATION

Policyholder: [REDACTED]
Reference Number: [REDACTED]
Date Of Loss: November 20, 1998
Loss Location: Claypool, Indiana

Please fill out the following information about your insurance company and return it to us at your earliest convenience.

Claimant Name: FORT MOTOR CORP.

Your Insurance Company Name

Your Insurance Company Address

Your Policy Number

The Agent or Claims Office you reported your claim to

94-5848

ENCLOSURE

==>

ENTER VIN ==> 2MELM75W. JX702552

NAME ==> GRAY

ZIP ==> 01960

MODEL YR ==>

OWNER NAME :

STREET ADDR :

CITY : PEABODY

ST/PRV: MA CTRY:

ZIP/POSTAL CODE:

N/A DATE: 94-11-07

N/A SOURCE: M

MODEL YEAR : 94 PLANT: X

SALE DATE: 94-08-23

BODY STYLE DESC: 4 DOOR SEDAN LS

PRODUCTION DATE: 94-07-06

VEHICLE DESC : 1994 GRAND MARQUIS

DIVISION DISTRICT ZONE DEALER PDC CODE PCSD REGION

SHIP-TO

FACING

RESPONSIBLE

3

36

A

491

3

12

A

491

CA EMISSION :

ENGINE TAG CODE : EG806AA

CAMPAIGN COUNTS

NAVIS STATUS : 800

COMPANY CAR IND :

TOTAL CAMPAIGNS : 01

DSO DISTRICT :

FLEET CODE :

OPEN : 01 CLOSED : 00

DSO NUMBER :

FLEET STATUS :

ACTIVE : 01 HISTORY : 00

F1=INQUIRY F3=EXIT F4=G160 F5=G150 F8=CONTINUE SEARCH F9=G130

CGDB140

ENTER CAMPAIGN NUMBER==> 94889 VIN==> 2MBLN75W2RX702552 TYPE OF SEARCH: A
MODEL YEAR: 94 DEFECT: ADAPTER PLT. BODY STYLE: 4 DOOR SEDAN LS
NEW STATUS CODE: _____ CAMP DIV : 6
REPAIR INFORMATION: _____ SUPP CODE :
TYPE CODE: _____ REPAIR DATE: _____ KIT CODE : AA
DEALER P/A: _____ MICRO REF: _____ OASIS DATE : 94-08-12
DELETE REASON: _____ VENDOR N/A INFORMATION:
RESP DEALER INFORMATION: NEW: _____ IND: MATCH CODE:
CURRENT: 3 12 491 ASSIGNED: 94-11-08 SOURCE: PX EXTRACT DATE:
***** STATUS INFORMATION: ***** REPAIR INFORMATION: *****
CODE DESCRIPTION DATE TYPE DATE P/A CLAIM# MICRO# CL SRC
M RELEASED FOR MAILING 94-12-06
M RELEASED FOR MAILING 94-08-17
R READY TO RELEASE 94-08-11

DELETE REASON:

F1=INQUIRY F2=G140 F3=EXIT F5=G130 F7=FIRST F8=NEXT F9=MORE STATUS
F10=ADD STATUS F11=REVISE
I037=NO MORE DATA TO DISPLAY

OGDB140

HART AND LAMOND, P.C.

ATTORNEYS AT LAW

SUITE 427-428

174 CENTRAL STREET

LOWELL, MA 01852

TELEPHONE (603) 454-1181

TELECOMMER (603) 454-8880


**DAVID J. HART
JOHN T. LAMOND
JAY L. SEIBERT
PATRICIA A. MATTHEWS**
ALSO ADMITTED IN MAINE

WALTER C. GALLAGHER
OF COUNSEL

October 2, 1995

CERTIFIED MAIL: RETURN RECEIPT REQUESTED

**FORD MOTOR COMPANY
Parklane Towers West, Suite 300
Three Parklane Boulevard
Dearborn, Michigan 48126-2568**



RE: [REDACTED] as subrogee of [REDACTED]

Dear Sir/Madam:

I represent [REDACTED] through [REDACTED] its insurer, concerning its claim with respect to your company's manufacture, assembly and sale of a 1994 Mercury Grand Marquis Sedan, VIN 2MELM75W2RX702552. On or about October 28, 1994, said motor vehicle spontaneously erupted in fire as a result of an electrical malfunction in said motor vehicle during normal intended and expected use, as a result of which extensive damages were caused to said motor vehicle.

It is our contention that your company breached implied warranties of fitness and merchantability with regard to the manufacture, assembly and/or sale of this vehicle and/or the component parts thereof. Demand is hereby made for payment of damages in the amount of \$22,043.00, the total net loss.

It is my further contention that your company's conduct in this transaction in your manufacturing, assembly and/or sale of this defective vehicle and/or its component parts constituted a breach of implied warranties of fitness and merchantability and as a consequence thereof was an unfair and deceptive act or practice as defined and described in Massachusetts General Laws Chapter 93A and the regulations promulgated thereunder. See also [REDACTED] v. [REDACTED] (Mass. 1984) and [REDACTED] v. [REDACTED] (Mass. 185 (1990)).

In accordance with the requirements of Chapter 93A, this letter constitutes a written demand for relief. In the event that the damages of \$22,043.00 are not paid within thirty (30) days of your receipt hereof, we will seek an award of treble damages, attorney's fees and costs in any litigation which may be filed in this case.

DAVID J. HART
JOHN T. LAMOND
JAY L. SEIBERT
ATTORNEYS AT LAW

October 2, 1995
Page Two

May I have your response?

Very truly yours,


David J. Hart
HART AND LAMOND, P.C.

DJH/ck

cc: 

ER62-625 29619



FAX (604) 774-7194

1. The first step is to identify the problem. In this case, the problem is that the system is not working properly.

[illegible]

FOR CIRCULATION:
PUBLISHED BY THE
JOURNAL OF THE

1. 姓名: 王明
 2. 性别: 男
 3. 年龄: 25
 4. 职业: 教师
 5. 籍贯: 江苏
 6. 民族: 汉族
 7. 婚姻状况: 已婚
 8. 子女情况: 1子1女
 9. 学历: 本科
 10. 学位: 硕士
 11. 职称: 副教授
 12. 工作单位: 江苏省教育厅
 13. 联系电话: 13812345678
 14. 电子邮箱: wangming@jsh.gov.cn
 15. 联系地址: 江苏省南京市鼓楼区

**Certified Mail
Return Receipt Requested
Z#040 682 683**

Chief Executive Officer
Ford Motor Company
c/o Skip Keyes, Senior Claims Analyst
Suite 300
Parklane Towers - West
3 Parklane Blvd.
Dearborn, MI 48126

**Certified Mail
Return Receipt Requested
78040 682 684**

Chief Executive Officer
Ford Motor Credit Corporation
c/o Gary Sirface
Department Manager, Customer Service
One Term Drive
Andover, MA 01810

RE: Claimants: [REDACTED]
Date of Loss: October 28, 1994
FMC Claim No.: 94-5048

Dear Sirs:

As you may know, this office represents [REDACTED] with regard to property damage and emotional distress suffered by them on October 28, 1994 when a green 1994 Mercury Grand Marquis sedan leased by [REDACTED] as principal of [REDACTED] exploded and caught fire in their driveway at [REDACTED] Peabody, Massachusetts. This letter is a demand for relief pursuant to M.G.L. Chapter 93A on behalf of [REDACTED] for damages they sustained as a result of the negligence and/or breach of warranty of merchantability by Ford Motor Company ("FMC") and Ford Motor Credit Corporation ("FMCC") which caused the explosion and fire.

FD-203 (Rev. 2-15-11)

A. THE OCCURRENCE

On August 23, 1994, [REDACTED] in her capacity as President and sole Director of [REDACTED] leased a 1994 Mercury Grand Marquis from North Shore Lincoln Mercury in Peabody, Massachusetts. FMCC financed the lease (lease number JNN50-FMJ5) and was the registered owner of the vehicle. At the inception of the lease, [REDACTED] made a deposit of \$5,787. The vehicle was insured by Travelers Insurance under a "garage-keeper's" policy for [REDACTED]

[REDACTED] had driven the new Ford 2,142 miles before the explosion. No service or repairs were performed on the vehicle during this time, and the vehicle had sustained no damage prior to the subject incident.

On October 28, 1994, a short time after [REDACTED] had parked the Ford in her driveway at 20 Clark Road, she heard two explosions. She looked out her window and saw that the Ford was on fire. She and her newborn baby got out of the home and [REDACTED] watched as the fire from the vehicle spread to her home. [REDACTED] was called from work and arrived to see the home ablaze. Attached at Tab 1 are color photocopies of the damage to the vehicle and to [REDACTED] home as a result of the explosions and subsequent fire. The charred Ford remained in her driveway until November 22, 1994.

B. THE CHAPTER 93A VIOLATIONS

Under Massachusetts law, every sale or lease of consumer goods carries with it an implied warranty of merchantability which cannot be modified or limited in any way. M.G.L. c.106 §§2-314 and 2-316A. A breach of the warranty of merchantability, such as the original equipment defect in the subject vehicle that exploded, constitutes an unfair and deceptive practice under M.G.L. c.93A §2. Further, the Massachusetts Attorney General has promulgated a regulation pursuant to Chapter 93A providing that "[i]t shall be an unfair and deceptive act or practice to fail to perform or fulfill any promises or obligations under a warranty." 940 C.M.R. 3.08(2). The regulations specifically include the implied warranty of merchantability under the definition of "warranty." 940 C.M.R. 3.01.

In addition to the warranty breach, at least two cause-and-origin experts have examined the vehicle on behalf of FMC (and/or its affiliated companies FMCC and Ford Leasing) since the occurrence. The first examination was performed in November 1994 by Larry Barhard who not only inspected the vehicle for the cause and origin of the fire/explosion, but also interviewed [REDACTED] at length on two occasions. A second inspection, which lasted approximately three hours, was

performed by Ford engineer Burgess Young on May 9, 1995 at Travelers' storage facility in Salem, New Hampshire.

Despite repeated requests, FMC by its attorneys has failed to provide either (a) copies of the reports generated by these inspections, or (b) a summary of the experts' conclusions and the factual bases therefor. Consequently, [redacted] are unable to determine why FMC continues to deny their claim. Indeed, one obvious inference to be drawn from FMC's failure to produce this information is that FMC's own experts have concluded that the likely cause of the fire/explosion was in fact a defect in the vehicle's original equipment.

By contrast, Travelers has supplied a copy of the report by its cause-and-origin expert, Dennis Lyons. He concludes that the cause of the fire and explosion was the overheating and ignition of a defective electrical component located at the left front of the engine compartment. Attached at Tab 2 is a copy of that report. We are also informed that other Ford vehicles of of similar configuration have exploded and/or caught fire under similar circumstances.

C. DAMAGES

As a result of the explosions and fire, [redacted] vehicle was a total loss and approximately \$17,102 damage was done to the [redacted] home. Following the incident, Mrs. Gray promptly notified all relevant parties of her loss: Travelers, her homeowner's carrier Utica, FMC and FMCC.

As a result of the negligence and/or warranty breach by FMC and FMCC, the [redacted] special damages are as follows:

Damage to Home (Utica subrogation):	\$17,102.13
Down payment on the lease:	5,787.69
Utica Insurance deductible:	500.00
Travelers Insurance deductible:	500.00
Lease payments prior to loss:	525.38
Rental of replacement vehicle:	845.25
Public Adjuster fee relating to Utica loss adjustment:	<u>1,553.47</u>
	\$26,813.92

Attached at Tab 3 is a copy of statement as to cost of repairs to the [redacted] home and a breakdown of the necessary repairs; at Tab 4 is a copy of the lease executed by [redacted] with North Shore Lincoln Mercury, Inc.; at Tab 5 is a copy of the extension

agreement which evinces lease payments made by [REDACTED] and at Tab 6 is a copy of the bill regarding the rental of the replacement vehicle.

In addition, [REDACTED] have sustained severe emotional distress as a result of this incident. Specifically, both suffer from sleeplessness, depression, feelings of despair, concentration problems, and have difficulty in driving and working. In addition, [REDACTED] has a fear of parking her husband's vehicle in the garage or even near their home. Further, they are continually reminded of the incident due to the fact that the damage to their home has not been fully repaired. The emotional distress components of these claims are valued conservatively at \$40,000 per claimant.

D. DEMAND FOR RELIEF

In light of the above, including [REDACTED] horrific experience of witnessing her car explode and home catch fire, the [REDACTED] resulting emotional distress, and special damages in excess of \$26,000, demand is hereby made for prompt payment of \$106,000 in full settlement of all claims [REDACTED] have against Ford Motor Company and Ford Motor Credit Corporation.


As you may know, M.G.L. Chapter 93A provides a thirty-day period for reply to this demand for relief. Should this matter not be settled, a court may subsequently find that refusal to grant relief upon this demand was made in bad faith or with knowledge or reason to know that the act complained of did violate Chapter 93A §2. In that case, [REDACTED] would be entitled to recover multiple damages of up to three times the value of their claim. In any event, if a court finds a violation of Chapter 93A §2, [REDACTED] would be entitled to recover their reasonable attorney's fees and costs of litigation in accordance with Chapter 93A §9.

Very truly yours,


Paul R. Schneider

PRS:tm
Enclosures

cc William B. Scarpelli, Esq.
Campbell & Associates
One Constitution Plaza
Boston, MA 02129



S. D. LYONS, INC.

Specialists: Automobile Fires, Fraud Detection, Physical Damage and Mechanical Analysis, Accident Reconstruction

**835 WATERMAN AVENUE, SUITE C
EAST PROVIDENCE, RI 02914-1700
TEL: (401) 438-9380 / FAX: (401) 438-9406**

March 8, 1995

**Travelers/Premier
P.O. Box 9201
Westwood, MA 02090
Attention: Mary Anne Hayes**

SDL # 6410.1

Re:

**File No.: DFT 8669
Insured : [REDACTED]
Vehicle : 1994 Mercury Grand Marquis
VIN : 2HELM75W2RX702552
ODOM : 2,142
DOL : October 28, 1994**

Background

The 1994 Mercury Grand Marquis was purchased as a new vehicle by the insured. The Mercury was parked in the driveway of the insured's residence for approximately one hour on October 28, 1994. The insured was in the house, heard the horn sounding, and went out and observed the vehicle on fire. The insured heard two explosions while the vehicle was burning. The fire department responded and extinguished the blaze in the vehicle and on a portion of the dwelling.

Objective

Inspect the Mercury Grand Marquis and determine the origin and cause of the fire.

The Mercury was inspected by S. D. Lyons, Inc., on November 3, 1994, at the owner's residence at 20 Clark Road in Peabody, Massachusetts.

Report Highlights

The Mercury Grand Marquis was purchased as a new vehicle. There were no aftermarket accessories in the vehicle, and the Mercury had not been previously damaged or repaired. The vehicle had been parked and at rest for approximately an hour before the fire occurred. The fuel system or exhaust heat did not cause the fire. The fire originated at the left front of the engine compartment just behind the radiator support. The fire was

ENCLOSURE 20015

caused by an electrical defect in the electrical circuits, which remain energized while the vehicle is parked and at rest. The fire was accidental in nature.

MAJOR FINDINGS

Vehicle Equipment

The vehicle is a 1994 Mercury Grand Marquis, four door. It is equipped with a 4.6 liter, overhead cam fuel injected V8 engine mounted inline with an automatic four speed transmission and rear wheel drive. The Mercury was also equipped with air conditioning, cruise control, ABS brakes, gas pressurized shock absorbers, alloy wheels, keyless entry, power windows, power locks, power mirrors, leather upholstered front and rear bench seats, a cassette stereo/radio, and a tilt steering column assembly with an air bag. The Grand Marquis was not equipped with any aftermarket accessories.

Cosmetic Condition Before Loss

An examination of the frame rails, the radiator support, and each of the body panels revealed no evidence of prior repairs or repainting. The Grand Marquis was brand new at the time of the loss and had the original painted finish. There was no existing collision damage to the body panels or trim. Nothing was missing from the interior or the exterior of the vehicle.

Vehicle Inspection at Residence

At the time of the inspection, the Mercury was parked on the left side of the insured's driveway. The left front of the Marquis was approximately four feet from the front of the garage. The left front body structure of the Marquis was extensively burned. The Marquis had not been moved since the fire. Radiant heat produced by the burning vehicle ignited shingles and trim on the front of the garage attached to the main dwelling. The garage door was open at the time of the fire. The evidence clearly indicates that the fire originated at the left front of the Mercury Grand Marquis then spread to the dwelling at a later stage.

Burn Pattern Analysis

Burn patterns appearing on the exterior body panels of the Mercury Grand Marquis consist of melting to the left side of the

caused by an electrical defect in the electrical circuits, which remain energized while the vehicle is parked and at rest. The fire was accidental in nature.

MAJOR FINDINGS

Vehicle Equipment

The vehicle is a 1994 Mercury Grand Marquis, four door. It is equipped with a 4.6 liter, overhead cam fuel injected V8 engine mounted inline with an automatic four speed transmission and rear wheel drive. The Mercury was also equipped with air conditioning, cruise control, ABS brakes, gas pressurized shock absorbers, alloy wheels, keyless entry, power windows, power locks, power mirrors, leather upholstered front and rear bench seats, a cassette stereo/radio, and a tilt steering column assembly with an air bag. The Grand Marquis was not equipped with any aftermarket accessories.

Cosmetic Condition Before Loss

An examination of the framersails, the radiator support, and each of the body panels revealed no evidence of prior repairs or repainting. The Grand Marquis was brand new at the time of the loss and had the original painted finish. There was no existing collision damage to the body panels or trim. Nothing was missing from the interior or the exterior of the vehicle.

Vehicle Inspection at Residence

At the time of the inspection, the Mercury was parked on the left side of the insured's driveway. The left front of the Marquis was approximately four feet from the front of the garage. The left front body structure of the Marquis was extensively burned. The Marquis had not been moved since the fire. Radiant heat produced by the burning vehicle ignited shingles and trim on the front of the garage attached to the main dwelling. The garage door was open at the time of the fire. The evidence clearly indicates that the fire originated at the left front of the Mercury Grand Marquis then spread to the dwelling at a later stage.

Burn Pattern Analysis

Burn patterns appearing on the exterior body panels of the Mercury Grand Marquis consist of melting to the left side of the

aluminum hood panel and extensive scorching to the left front fender, the left framerrail, the left side of the radiator support, and the left side of the aluminum bumper support. The patterns indicate that the fire burned with the longest duration at the left front of the engine compartment. The fire progressed toward the rear of the compartment at a later stage.

The right front fender was not burned, and the plastic lamps in the right front of the vehicle were not melted. The Marquis is fitted with a flexible bumper cover and an aluminum bumper support. The right side of the bumper cover and the radiator support still remained painted and they were not burned. The left side of the bumper cover was consumed, and the left side of the aluminum bumper support was melted. The left side of the radiator support was extensively scorched. Within the engine compartment, the Marquis had plastic inner fender panels. The left side plastic inner fender panel was consumed. The right side plastic inner fender panel remained in place, although it had begun to melt.

The Grand Marquis is equipped with a 4.9 liter, V8 engine. The V8 engine has electronic sequential fuel injection and overhead camshafts. It has fiberglass camshaft covers. Components on the top side of the V8 engine were melted. The engine utilized a plastic air induction system that attached to the alloy throttle body at the center rear of the engine. The plastic had melted and pooled on the top of the intake manifold. Components in the front of the engine and along the right side of the engine compartment were damaged by a buildup of convection heat. Plastics began to melt, but there was only minimal consumption. The patterns clearly indicate that the fire did not originate anywhere on the top of the V8 engine, the front of the engine, or along the right side of the engine compartment.

The left side framerrail and all components above the framerrail were extensively burned from the firewall panel forward. The burn patterns indicate that the fire progressed toward the rear of the engine compartment and burned the firewall panel at a later stage. The left side of the windshield began to burn, and the top of the dash pad began to melt. However, the fire was extinguished before it progressed into the passenger compartment. The melting of the aluminum hood indicates that the fire burned with a longer duration toward the front of the compartment but quickly progressed toward the rear. The entire left side of the aluminum hood panel was melted above the left framerrail.

The fire did not progress into the passenger compartment. The leather upholstery of the front and rear seats was damaged by a buildup of smoke and soot. Plastics in the left side of the dash began to melt but damage was minimal. The patterns within the passenger compartment clearly indicate that the fire did not originate anywhere in the dash assembly or within the passenger compartment.

An examination of the left side of the engine compartment revealed that the fire had burned intensely at the left front just behind the radiator support. This area exhibited evidence that the fire burned with the longest duration and consumed all of the available combustible materials and began to melt alloy components. Several wiring harnesses extend from the left side of the firewall panel toward the left front of the compartment. There were a series of relays and electrical components mounted on the inner fender panel and in the left front of the engine compartment. All of the electrical wire insulation and all of the plastic components of the electrical items were consumed by the fire. Only the wire cores and several metal components of the electrical items remained. The electrical wiring system, extending from the firewall panel to the front of the vehicle, was completely destroyed by the fire. We examined many of the remains of the wire strands. We found evidence of numerous melted and beaded ends. The small wire strands would melt and bead during the natural course of the fire. As wiring insulation was melted, many of the electrical circuits began to short and were energized during the course of the fire.

The Grand Marquis has a fuel pump relay and an engine control module relay located at the left front. These relays remain energized at all times, even when the vehicle is parked and at rest. A faulty relay could result in overheating of the relay, melting of the plastic, and subsequent ignition of the plastics and surrounding combustible materials. Because all of the relays and electrical components were destroyed by the fire, we could not analyze the individual circuits and components.

The fuel injection system has a fuel inlet and fuel return line that extends along the left framerrail. The inlet lines connect to the fuel inlet and return line on the rail located over the left side camshaft cover. Two flex hoses connected the lines. The flex hoses were consumed by the fire, and only the steel lines remained. The evidence is not consistent with the leakage of fuel and subsequent ignition of the vapor. Because the vehicle had been at rest for a period of an hour and there were no ignition sources present in the engine compartment while the vehicle was at rest, the fuel system could not have caused the fire. Residual fuel in the line at the time of the fire would have been consumed rapidly with minimal effects to the resulting burn pattern.

Fire Origin and Cause

The origin of the fire was at the left front of the engine compartment just behind the radiator support. The cause of the fire was the overheating and ignition of an electrical component located at the left front of the engine compartment. There are several wiring circuits and relays that are energized even when

the vehicle is parked and at rest. Because the electrical system was destroyed by the fire, we could not determine the exact cause. Heat was generated by the electrical malfunction and plastics were ignited. The fire was accidental in nature. The fire was the result of a defective component in the electrical system at the left front of the 1994 Mercury Grand Marquis.


S. Dennis Lyons



Photograph 1
Right rear view of the 1994 Mercury Grand Marquis. The vehicle was brand new, and it had not been previously damaged or repaired.



Photograph 2
Left rear view. There was no existing collision damage. Nothing was missing from the Marquis at the time of the loss.



Photograph 3
The Marquis was parked in the insured's driveway at the time of the fire. The fire spread from the Grand Marquis to the dwelling at a later stage.



Photograph 4
The left front of the Marquis was parked in close proximity to the front of the garage. The garage door appeared to have been open at the time of the loss.



Photograph 5
View of damage to the front of the garage.



Photograph 6
Left front view of the Grand Marquis. The fire burned with a longer duration at the left front of the engine compartment. It progressed toward the rear of the engine compartment at a later stage.



Photograph 7
View of the melted hood panel. Most of the scorching and melting to the hood occurred at the left front.



Photograph 8
Right front view of the Marquis. The fire did not spread to the right side of the hood panel or to the right front structure of the vehicle.




Photograph 9
View of burn patterns at the left front. The left side of the radiator support was extensively scorched, and the left side of the bumper support was melted.



Photograph 10
Another view of the burn patterns. They show the fire originated at the left front of the engine compartment and then progressed toward the rear at a later stage. It began to burn through the windshield and melt the dash panel before it was extinguished. The consumption of materials and the duration factors indicate that the fire did not originate at the rear of the compartment.



Photograph 11
View of the forward passenger compartment. The interior was
damaged by smoke and soot.



Photograph 12
View of the dash assembly. The fire did not originate in
the dash of the vehicle.



Photograph 13
View of burn patterns appearing on the front body structure.
There was intense burning at the left front corner but no
burning to the right front corner.



Photograph 14
View of the front of the radiator support and the header
panel. Only the left side was scorched.



Photograph 15
The gas shock absorber and the left front tire blew out during the fire. The explosion would have produced the sound heard by the insured.



Photograph 16
Burn patterns on the tire indicate that the fire burned with a longer duration at the front of the wheelwell opening (arrow).




Photograph 17
Overview of the 4.9 liter, fuel injected V8 engine. The plastic air cleaner assembly melted on top of the engine.




Photograph 18
W of the engine. The patterns clearly indicate
a not originate on top of the engine, in front of
a, or along the right side of the compartment.


Photograph 19
 Overhead view of the
 left side of the engine
 compartment. The fire
 burned intensely along
 the left framerail and
 consumed most of the
 available combustible
 materials above the
 framerail.




Photograph 20
 Circles show the location of the steel fuel lines extending
 from the frame to the fuel rail on the engine. The flex
 hoses were burned off.



Photograph 21
The fire was not caused by the ignition of fuel vapor from the fuel lines or by exhaust heat produced by the engine.




Photograph 22
The left side plastic inner fender panel was consumed. The fire burned intensely from the firewall panel to the radiator support.



Photograph 23
View of the left side of the firewall panel. Some of the electrical wiring harnesses extending from the firewall panel were extensively damaged by the fire.



Photograph 24
All of the wire insulation was burned off. The fire progressed to the firewall panel at a later stage.



Photograph 25
View of the left front of the engine compartment. The fire originated just behind the radiator support. The electrical components located on the inner fender panel were destroyed by the fire.



Photograph 26
View of the origin of the fire at the left front of the engine compartment. Several of the electrical wiring circuits are energized even when the vehicle is parked and at rest.



Photograph 27

Another view of the left side of the fender, the radiator support, and the framerail. The electrical relays and the wiring harnesses were extensively burned by the fire.



Photograph 28

Overhead view of the left framerail and portions of the ABS control unit located at the left front of the compartment. There was extensive scorching to the framerail and to the surrounding components.



Photograph 29
Another view of the left front structure of the Grand
Marquis. The fire burned intensely in the lower left front.




Photograph 30
We removed leaves and debris and exposed some of the burned
wiring and electrical components that had fallen from the
left front.



Photograph 31

View of the burned wiring harness at the left front.



Photograph 32

View of burned electrical components that had fallen to the ground at the left front of the vehicle.



Photograph 33

View of an electric motor, which was recovered from the left front. The fire was caused by an electrical defect in one of the components located at the left front of the engine compartment. Because of the destruction caused by the fire, we could not determine the exact cause of the electrical defect.



Photograph 34
View of the VIN.

END-525 25638



ENC-920 28071







1982-425 20540











EA62-625 20003




0002-025 20004



EP02-025 20005



0902-025 20006



LM2-825 2007




EW02-025 20054




1753-025 20000




0002-025 28700






W42-025 25782











BM2-825 28767



MF02-020 20700






ERW2-025 28716



EM62-825 28711



DA82-029 20712







ENC2-825 28715






1002-025 20717



8902-025 28716




1002-025 28710



1002-025 28720



2002-020 20721











ERG2-025 28725






1982-828 28727




EP62-625 28728



ENCLOSURE 20720






WFO2-225 38781

1964

24


1962-628 28732









1002-025 20735



2002-025 20736








5402-025 28730



9902-025 20730





80-410

20


7/62

87-21150-35
4-434

SEARCHED	INDEXED
SERIALIZED	FILED
FBI - NEW YORK	
JUL 10 1962	

80-410-1 2003

2




1042-625-8 2584



1982-025-5 2005







Office of the General Counsel

Ford Motor Company
Parklane Towers West
Suite 400
3 Parklane Boulevard
Dearborn, MI 48124

August 1, 1996

GEICO Claims
One GEICO Center
Macon, GA 31296-0001
ATTENTION: MICHAEL LEWIS - D279

Re: Claimant: [REDACTED]
DOVE: 9/12/95
Vehicle: 1995 Town Car
Your Claim No.: [REDACTED]

Dear Mr. Lewis:

Following a review of the facts and circumstances surrounding this event, Ford Motor Company finds no evidence of a manufacturing or design defect, therefore, we must deny liability for this claim.

Please be advised that all necessary steps must be taken to ensure that the subject vehicle and all of its component parts are maintained and preserved for trial. Ford Motor Company has the right to inspect the vehicle and remove and test any component part that you claim to be defective, and to be presented with the vehicle and the subject component part(s) at the time of trial, should litigation ensue from this informal claim.

If you propose to repair the vehicle for continued usage, such repairs may not be performed until after Ford Motor Company has inspected the vehicle and removed and tested any component part you claim to be defective or advised you in writing that it does not intend to perform such inspection and/or testing at this time. But even in that event, Ford Motor Company will insist that all components claimed to be defective are maintained and preserved for trial.

Sincerely,


Davana Fajack
Litigation Assistant

file

BP22-025-5 2000

GETCO INC. CO,
PO BOX 6052 COLUMBUS GA 31907
(334) 230-6207

VOICE MAIL AND DEETER
1-800-393-8710
FID 887-6383
Damage Assessed By: RON MERRY

* FAILURE TO PRESENT ESTIMATE TO REPAIR FACILITY *
* NOT INCREASE YOUR FINANCIAL RESPONSIBILITY *

Type of Loss: Comprehensive
Date of Loss: 09/12/95
Policy Number: 01308180
Deductible: 0.00

Insured: [REDACTED]
Address: [REDACTED] COLUMBUS GA [REDACTED]
Telephone: Work Phone: [REDACTED] Home Phone: [REDACTED]
Mitchell Service: 011818

Description: 1995 LINCOLN TOWN CAR 316 40 SEDAN
VIN: 1JLWNEHMY711887 License/CH TIME: 7FHE53 GA TL

Mileage: 1,102

PAY CODE 00

OEI/ALT: 0
Color: GREY

Search Code: 651298

Line Entry	Line	Operation	Description	Part Type/ Part Number	Quantity	Unit
1	100211	REMOVE/REPLACE	STEERING WHEEL W/AIR BAG	FSBY 3000 F	250.68	0.2
2	100214	REMOVE/REPLACE	STEERING AIR BAG MODULE	ORDER FROM DEALER	579.44	INCL
3	100250	REMOVE/REPLACE	W/SHIELD REAR VIEW MIRROR	FSBY 17708 B	287.20	0.4
4	000600	REMOVE/REPLACE	CARPET	0413000	587.10*	2.0*
5	000600	REMOVE/REPLACE	CARPET PAD	0413040	290.80*	1.0*
6	111200	REMOVE/REPLACE	R W/SHIELD SIDE VIBER	ORDER FROM DEALER	136.17	0.2
7	111640	REMOVE/REPLACE	L W/SHIELD SIDE VIBER	ORDER FROM DEALER	136.17	0.2
8	100250	REMOVE/REPLACE	DOOR PANEL ASSY	ORDER FROM DEALER	1,082.22	8.3
9	100251	REMOVE/REPLACE	DOOR PANEL CLUSTER FINISH PANEL	ORDER FROM DEALER	307.63	INCL
10	100272	REMOVE/REPLACE	DOOR PANEL ARMSTRAY MOUNTING	ORDER FROM DEALER	65.18	
11	111270	REMOVE/REPLACE	DOOR PANEL MOUNTING	PM2 040420 A	50.00	INCL
12	AUTO	REFIN	ARMSTRAY COVER			0.3
13	000600	REMOVE/REPLACE	INTERIOR CLUSTER	10040	580.00*	0.5*
14	100274	REMOVE/REPLACE	DOOR PANEL BLOWER	FSBY 540016 A	105.70*	INCL
15	111240	REMOVE/REPLACE	DOOR PANEL BLOWER LATCH	FSBY 5400372 A	25.63*	INCL
16	AUTO	REFIN	LOCK			0.2
17	000600	REMOVE/REPLACE	LT HEADREST COVER	0411180	147.55*	0.5*
18	000600	REMOVE/REPLACE	LT HEADREST	0411000	115.55*	0.5*
19	000600	REMOVE/REPLACE	RT HEADREST	NEW	115.55*	0.5*
20	000600	REMOVE/REPLACE	RT AIR VIBER	040454	52.90*	0.3*

ESTIMATE SERIAL NUMBER: 09/20/95 18:28:52 004050040101040-01

Mitchell Data Version: SEP_95_A

Copyright (C) 1994, Mitchell International
All Rights Reserved

Page 1 of 4

21	800600	NECH	*REMOVE/REPLACE	*LT AIR VENT	NEW	59.80	0.3	
22	800600	NECH	*REMOVE/REPLACE	*LT GNL TRN PANEL	5402345	38.07	0.3	
23	800600	NECH	*REMOVE/REPLACE	*RT GNL TRN PANEL	5402344	38.07	0.3	
24	800600	NECH	*REMOVE/REPLACE	*FRT FLOOR MATS	5413000	88.00		
25	800600	NECH	*REMOVE/REPLACE	*REAR FLOOR MATS	5413100	88.00		
26	800600	NECH	*REMOVE/REPLACE	*RT FRT AIR REST	5424141	75.25	0.5	
27	800600	NECH	*REMOVE/REPLACE	*LT FRT AIR REST	5424140	75.25	0.5	
28	800600	NECH	*REMOVE/REPLACE	*DOOR MOUNT STRAPS 3 001.10	5431400	35.30	0.3	
29	800600	NECH	*REMOVE/REPLACE	*DASH BOOF TRN RT	NEW	440.80	0.5	
30	800600	NECH	*REMOVE/REPLACE	*DASH BOOF TRN LT	NEW	440.80	0.5	
31	800600	NECH	*REMOVE/REPLACE	*RT SEAT BELT ASBY FRT 100	NEW	280.85	1.0	
32	800600	NECH	*REMOVE/REPLACE	*LT SEAT BELT ASBY FRT 100	NEW	250.85	1.0	
33	800600	NECH	*REMOVE/REPLACE	*RT SEAT BELT ASBY	NEW	121.00	1.0	
34	800600	NECH	*REMOVE/REPLACE	*LT SEAT BELT ASBY	NEW	121.00	1.0	
35	800600	NECH	*REMOVE/REPLACE	*ELECTRIC WINDOW ROLLING HANDLES	NEW	98.05	3.5	
36	800600	NECH	*REMOVE/REPLACE	*A/C HAND	13000	545.80	1.0	
37	800600	NECH	*REMOVE/REPLACE	*DR BOTTOM SEAT COVER	NEW	760.47	1.0	
38	800600	NECH	*REMOVE/REPLACE	*DR SEAT BACK COVER	NEW	716.57	1.0	
39	800600	NECH	*REMOVE/REPLACE	*PASSENGER SEAT BOTTOM COVER	NEW	760.47	1.0	
40	800600	NECH	*REMOVE/REPLACE	*PASSENGER SEAT BACK COVER	NEW	716.57	1.0	
41	800600	NECH	*REMOVE/REPLACE	*REAR SEAT SEAT BOTTOM COVER	NEW	1,088.50	1.0	
42	800600	NECH	*REMOVE/REPLACE	*REAR SEAT BACK COVER	NEW	670.82	1.0	
43	800600	NECH	*REMOVE/REPLACE	*DR SEAT PADS BOTTOM & BACK	NEW	572.27	1.0	
44	800600	NECH	*REMOVE/REPLACE	*PANO SEAT PADS BOTTOM & BACK	NEW	572.27	1.0	
45	800600	NECH	*REMOVE/REPLACE	*SEAT SEAT PADS	NEW	431.25	1.0	
46	800600	NECH	*REMOVE/REPLACE	*SEAT SEAT AIR REST PAD AND COVER	NEW	385.40	1.0	
47	800600	NECH	*REMOVE/REPLACE	*RT FRT PILLAR TRN	NEW	49.80	0.5	
48	800600	NECH	*REMOVE/REPLACE	*LT FRT PILLAR TRN	NEW	49.80	0.5	
49	800600	NECH	*REMOVE/REPLACE	*CENTER PILLAR TRN RAL 2 & 00.00	NEW	181.20	0.5	
50	800600	NECH	*REMOVE/REPLACE	*RT & LT RTH TRN	NEW	145.20	1.0	
51	800600	NECH	*REMOVE/REPLACE	*GRN VIBOR CLTRN	NEW	11.80	0.3	
52	800600	NECH	*REMOVE/REPLACE	*CELLULAR PHONE	NEW	500.00	1.0	
53	800600	NECH	*REMOVE/REPLACE	*CELLULAR PHONE CRADLE	NEW	125.00	1.0	
54	800600	NECH	*REMOVE/REPLACE	*RT SEAT AIR REST AND COVER	NEW	587.00	1.0	
55	800600	NECH	*REMOVE/REPLACE	*LT SEAT AIR REST AND COVER	NEW	587.00	1.0	
56	800600	NECH	*REMOVE/REPLACE	*REAR PASSENGER TRAY	NEW	180.85	1.0	
57	800600	NECH	*REMOVE/REPLACE	*REAR OPENER COVERS	NEW	78.80	0.5	
58	800600	NECH	*REMOVE/REPLACE	*RT A/C REGISTER ASBY	NEW	74.85	0.5	
59	800600	NECH	*REMOVE/REPLACE	*LT A/C REGISTER ASBY	NEW	74.85	0.5	
60	800600	NECH	*REMOVE/REPLACE	*CENTER A/C REGISTER ASBY	NEW	241.80	0.5	
61	800600	NECH	*REMOVE/REPLACE	*RT HEAD REST COVER	NEW	147.77	1.0	
62	800600	NECH	*REMOVE/REPLACE	*DOOR LAMOR OPENER AND FORTNATE VEHICLE	GRULET	950.00		
63	100270	NECH	*REMOVE/REPLACE	1ST PANEL AIR BAO HANDLE	-H	UNDER FROM DEALER	772.81	2001
64	123701	NECH	*REMOVE/REPLACE	2ND PANEL AIR BAO	PORT JACOB G	646.80	2001	
65	800600	NECH	*REMOVE/REPLACE	*DOOR LOCKING HANDLES	140005	752.85	0.5	
66	800600	NECH	*REMOVE/REPLACE	*DOOR LOCKING HANDLES	14401	528.85	0.5	
67	800600	NECH	*REMOVE/REPLACE	*DOOR LOCKING HANDLES	FORV14200	342.80	4.0	
68	800600	NECH	*REMOVE/REPLACE	*DOOR TRN	5400463	248.14	5.0	
69	800600	NECH	*REMOVE/REPLACE	*DOOR TRN	5401230	172.45	5.0	
70	100270	NECH	*REMOVE/REPLACE	1 FRT DOOR TRN PANEL ASBY	UNDER FROM DEALER	574.20	0.5	
71	100270	NECH	*REMOVE/REPLACE	1 FRT DOOR TRN PANEL ASBY	UNDER FROM DEALER	574.20	0.5	
72	100270	NECH	*REMOVE/REPLACE	1 REAR DOOR TRN PANEL ASBY	UNDER FROM DEALER	574.20	0.5	

ESTIMATE RECALL NUMBER: 03/20/95 10:28:12 004957034101040-01

Witchell Data Version: SEP_95_A

Copyright (C) 1998, Mitchell International

Page 2 of 4

All Rights Reserved

1002-025-0 3101

73 100324 WECB -REPAIR/REPLACE L REAR BUM TRIM PANEL BODY
74 100150 WECB -REPAIR/REPLACE ROOF HEADLINER
75 100226 WECB -REPAIR/REPLACE FRT ROOF INTERIOR LAMP
76 100232 WECB -REPAIR/REPLACE REAR ROOF INTERIOR LAMP
77 AUTO ADD'L COST PAINT MATERIALS

* Judgment Fee

ORDER FROM DEALER 518.70 0.8
ORDER FROM DEALER 540.52 1.8
ORDER FROM DEALER 110.55 0.3
ORDER FROM DEALER 110.55 0.3
7.00

Damage

NO DI STUCK, NO PRIOR DAMAGE NOTED. FIRE STARTED AROUND AREA OF CIGARETTE LIGHTER. SHOP SAID CAUSED BY FIRE BUSTER SHORTING OUT. I FEEL THAT THE FIRE OR RELAY SHOULD HAVE KICKED OUT BEFORE FIRE STARTED. SCOTT DENHAM ALSO LAMED AT VEN ON 08-14-95 AND HE ALSO FEELS RELAY OR FUSE SHOULD HAVE KICKED OUT. FORD MOTOR CO. REP. LAMED AT VEN AND DENIED PRODUCT LIABILITY. ADVISED SCOTT AND HE HAD COMPLETE APPR AND TOTAL VEN. COMPLETED APPR ON 9-20-95 AFTER SHOP FURNISHED FIGURES ON PARTS NEEDED.

		Add'l					
		Labor	Sublet				
I. Labor Subtotals	Units	Rate	Amount	Amount	Total		
Refinish	0.5	28.00			14.00		
Mechanical	78.2	48.00		3,753.60	4,218.40		
				Labor Subtotal	4,233.90		
Labor-Summary Totals		78.7			4,233.90		
						II. Part Replacement Summary	Amount
						Vehicle Parts	23,808.12
						Sales Tax @ 6.00%	1,418.40
						Non-Vehicle Parts	181.20
						Total Replacement Parts Amount:	25,407.72
						IV. Adjustments	Amount
						Insurance Deductible	0.00
						Customer Responsibility:	0.00
						I. Total Labor:	4,233.90
						II. Total Replacement Parts:	25,407.72
						III. Total Additional Costs:	7.42
						Gross Total:	29,648.04
						IV. Total Adjustments:	0.00
						Net Total:	29,648.04

Point of Impact: REAR COLLISION Inspection Site: GATEWAY LINC. BELLEVILLE
Body Shop: GATEWAY LINC-BEAC-TOUCH, INC. Work Phone: (708) 312-5875
Address: 1304 5TH. AVE. CHICAGO IL 60602

L7524

21387

GATEWAY
LINCOLN-MERCURY-ISUZU

1300 E. Avenue

COLUMBUS, GEORGIA 31902

Phone 322-5575

INVOICE

PAGE 1

COLUMBUS GA
HOME:

SERVICE ADVISOR: 5930 J. R. PEARSON

ISUZU

CHASSIS	YEAR	MAKE/MODEL	VIN	DATE	TIME	DATE	TIME
GREY	95	LINCOLN TOWN CAR	1LKLMB2W9SY711567	1143/1143			
DEL DATE	3000 DATE	WARRANTY	PROMISED	POIN	DATE	DATE	DATE
24AUG95	20MAR95		17:30	09OCT95	45.00		09OCT95
A/C OPENED		READY	OPTIONS: STR:L7524 DLR:38K115 ENG:99W		TRN:ELECTRONIC AUTO O/D TRANS		
12:44 12SEP95		12:24 09OCT95					

LINE DECODE TECH TYPE HOURS LIST NET TOTAL
 A CAUGHT ON FIRE AND WAS TOWED IN
 ABS STORAGE FOR VEHICLE, 28 DAYS
 1367 CP 0.00 156.00 156.00

B** TOW
 TOW TOW
 1367 CP 0.00 15.00 15.00



The only warranties applying to this period are those which may be offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor endorses any other person's service for its any liability in connection with the sale of this period under service. Buyer shall not be entitled to recover from the damage to property, damages for loss of use, loss of time, loss of profits, or business, or any other incidental damages.

THE ABOVE WORK HENRY AUTHORIZED AND CONDITIONS APPLIED TO AN OUTLINED BELLY. MY CAR MAY BE DRIVEN BY YOUR EMPLOYEES FOR ROAD TEST AT MY OWN RISK.

TERMS AND CASH ON DELIVERY. ESTIMATES ARE FOR LABOR ONLY. MATERIAL IS EXTRA.

Not responsible for loss or damage to cars or vehicles left in care of the dealer, including, but not limited to, theft, vandalism, flooding, or any other cause not covered. An express warranty is hereby acknowledged and agreed to by the customer to ensure the amount of repair charges. A charge may be made to your repair order for the handling of environmentally hazardous materials.

The owner of the above described vehicle agrees to pay reasonable attorney's fees and court costs incurred in the collection of this amount, by the perfection of any lien.

CUSTOMER'S SIGNATURE

CUSTOMER

DESCRIPTION	AMOUNT
LABOR AMOUNT	241.00
PARTS AMOUNT	0.00
SAE. OIL LUBE	0.00
SUBST AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGE	241.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	241.00

SERVICE HOURS
 Monday thru Friday 7:30 - 5:30
 No Cars Delivered after 5:30

8802-035-B 2153

106 006318

September 27, 1995

Customer, Mr. [REDACTED]

You recently contacted us regarding your 1995 Lincoln Town Car
insurance claim.

Customer satisfaction is one of the primary objectives of Ford
Motor Company and we try to make every attempt to ensure that
our customers are satisfied. We recognize the importance of
maintaining customer confidence in us after the purchase.

After the inspection of the vehicle by an independent third
party it is Ford's position that your claim was not covered by a
manufacturer's defect. The third party inspection indicated the
first way to go to the appropriate repair shop was
located on the windshield and was placed near the cigarette
lighter. This type of situation is usually handled by your
insurance carrier. If your insurance company feels there should
be a manufacturer liability due to a product defect, they would
file a subrogation claim against us.

Thank you for contacting Ford. We appreciate the opportunity
to consider your request.

Sincerely,

W. J. Small
Litigation Prevention Section
Customer Relations Operations