

EA02-025

10-27-03

**FORD 10/27/03
LETTER TO ODI**

BOOK 6 OF 22

PART A – D

PART C

1

10/10/67

1002-022-8 11967

CAUSE NO. 23350

AND

IN THE COUNTY COURT

Plaintiff

v.

AT LAW NUMBER 2

FORD MOTOR COMPANY

Defendant

TRAVIS COUNTY, TEXAS

ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

COME NOW [REDACTED] and [REDACTED] ("Plaintiffs") and file this Original Petition against Ford Motor Company ("Defendant") and for cause would show the following:

I.
PARTIES

Plaintiffs are individuals residing in the State of Texas.

Defendant is a company duly licensed and doing business in the State of Texas. It may be served through its registered agent for service of process, CT Corporation Systems, 350 North St. Paul Street, Dallas, TX 75201.

II.
BACKGROUND FACTS

On June 10, 1996, Plaintiffs' 1992 Ford Crown Victoria caught fire due to a defect or malfunction causing an overheating condition within the wiring or connections in the electrical distribution box. As a result of this, Plaintiffs sustained \$11,026.63 in damages.

III.
DEFECTIVE PRODUCT

At the time of this occurrence, Defendant was engaged in the business of designing, manufacturing and marketing automobiles, including the one made the basis of this claim, for

sale to and for use by members of the general public. Plaintiff would show that the automobile in question (V.I.N. 2FACP73W6NX155863) was defective and unsafe for its intended purposes at the time it left the control of Defendant, in that it was defectively designed and/or manufactured in a manner which made the product unreasonably and inherently dangerous. Plaintiff would further show that the automobile in question was defectively marketed by Defendant in that Defendant failed to adequately warn or instruct consumers, including Plaintiff, of the dangers associated with the product.

IV.
STRICT PRODUCT LIABILITY

Plaintiff invokes the doctrine of strict liability, Section 402A, RESTATEMENT (SECOND) OF TORTS, as adopted by the Supreme Court of Texas. Plaintiff alleges that Defendant is strictly liable for designing, manufacturing and marketing the automobile into the stream of commerce when the product was unreasonably dangerous. The defective design, manufacture and/or marketing of the automobile was the proximate cause of the occurrence and of Plaintiff's damages.

Plaintiff would further show that Defendant is strictly liable to Plaintiff under 402B of the RESTATEMENT (SECOND) OF TORTS for misrepresenting that the product was safe and without defect. These representations were false and involved a material fact concerning the character or quality of the automobile. Plaintiff would show that he relied on these representations and that Defendant's misrepresentations were the proximate cause of the occurrence and of Plaintiff's damages.

V.
NEGLIGENCE

Plaintiff alleges that Defendant was negligent in the design, manufacture and/or

marketing of the automobile, in that Defendant knew, or in the exercise of ordinary care, should have known, that the automobile was defective and unreasonably dangerous to ultimate consumers. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of the occurrence and of Plaintiff's damages.

VI. RES IPSA LOQUITUR

In that alternative, Plaintiff would further show that he cannot more specifically allege the specific acts of negligent design and manufacture on the part of Defendant, for the reason that the facts in that regard are peculiarly within the knowledge of Defendant, and in the event Plaintiff is unable to prove specific acts of negligent design and manufacture, Plaintiff relies on the doctrine of *res ipsa loquitur*. In this connection, Plaintiff will show that the design and manufacture of the automobile were within the exclusive control of Defendant. Plaintiff had no means of ascertaining the method or manner in which the automobile was designed or manufactured by Defendant. Plaintiff would show that the product came into his possession in the same condition it was in when it left the control of Defendant. The occurrence causing harm to Plaintiff was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of Plaintiff's damages.

VII. BREACH OF WARRANTY

Plaintiff further alleges that Defendant expressly and impliedly warranted to the public that the automobile was of merchantable quality and was safe and fit for the purposes intended when used under ordinary conditions and in an ordinary manner. Plaintiff would show that Defendant's breach of these warranties were the proximate cause of the occurrence

and of Plaintiff's damages. TEX. BUS. & COM. CODE Sec. 2.314 - 2.315, Sec. 17.50

(a)(2), (Vernon 1989). Plaintiff would further show that Defendant is liable for all attorney fee's pursuant to §38.001 of the Texas Civil Practice & Remedies Code.

VII
DECEPTIVE TRADE PRACTICES ACT

Plaintiff would show that Defendant is also liable for violations of the Texas Deceptive Trade Practices and Consumer Protection Act ("DTPA"), including:

- A. Representations that the product in question, and its component parts, possessed qualities, characteristics, uses and benefits which they did not possess - [TEX. BUS & COM. CODE §17.46(5), (Vernon 1990)];
- B. Representations that the product in question, and its component parts, were merchantable when, in fact, they were not fit for the ordinary purposes for which such products were to be used - [TEX. BUS & COM. CODE §17.46(19), (Vernon 1990)];
- C. Failing to disclose information concerning dangers of the automobile known to Defendant, when such failure was intended to induce the consumer to purchase the product - [TEX. BUS & COM. CODE §17.46(22), (Vernon 1990)];

The above acts and/or omissions of Defendant were a proximate cause of the occurrence and of Plaintiff's \$11,026.63 damage to his real and personal property.

Pursuant to the common law of Texas and to the various statutes referenced herein, Defendant is liable to Plaintiff for actual and treble damages, interest, court costs, and reasonable attorney fees.

WHEREFORE, PREMISES CONSIDERED, Plaintiff requests that Defendant be cited to appear and answer, and that on final trial, Plaintiff have:

- 1. Judgment against the defendant for a sum in excess of the minimum jurisdictional limits of the Court;
- 2. Pre-judgment interest and post-judgment interest as provided by law;
- 3. Costs of suit;

4. Attorney fees;
5. Such other and further relief to which the she may be justly entitled.

Respectfully submitted,

LAW OFFICES OF RICHARD B. GEIGER
1513-C West Sixth Street
Austin, Texas 78703
(512) 320-8844 - Telephone
(512) 320-8854 - Facsimile

By:

Rich Geiger (w/permission EP)
Richard B. Geiger
State Bar No. 07791980

Erik Peters
State Bar No. 00791432

ATTORNEY FOR PLAINTIFFS




Fire Investigation & Remains Evaluation
P.O. Box 154086
Irving, Texas 75015-4086
(214) 254-2075 Pager (214) 909-7245
FAX (214) 253-1583

COPY

RECD BY VIN
CC CSO

AUG 22 1996

RECEIVED

AUG 23 1996

VICTORIA CSO

August 19, 1996

F.I.R.E. # 150BB96

First Report

CLIENT: V. J. Harper, II
State Farm Insurance Companies
P. O. Box 270550
Corpus Christi, Texas 78427

INSURED: [REDACTED]

INSURED VEHICLE: 1992 Ford Crown Victoria
VIN: 2FACP73W6NX155863

DATE OF FIRE: 6/10/96

POLICY #: [REDACTED]

CLAIM #: [REDACTED]

This report is prepared for the above named client. Release to any other person, company or agency **MUST** be approved by the client or covered by applicable disclosure laws.

IF82-025-2 11573



150BB96

1.

ASSIGNMENT

This assignment was received July 15, 1996 at 1:16 p.m. via FAX from Property Claim Trainer Michael Huck with instructions to conduct a vehicle fire cause examination. Investigation commenced 8/14/96.

ENCLOSURES

1. 29 vehicle photographs

INSURED PROPERTY



The risk is a dark blue, 1992 Ford Crown Victoria, four door sedan bearing Texas license plate PCW-68Z. The vehicle identification number is 2FACP73W6NX155863. The car is powered by a large displacement, fuel injected, V-8 motor and automatic transmission. It is equipped with power steering, power brakes, electric door locks and windows, dash mounted radio, cruise control and all season heating and air conditioning. All four tires and simulated wire wheel hubcaps were still on the vehicle. The body was straight and I saw no evidence of prior collision damage. According to the odometer, there were 58,865 miles on the car.

VEHICLE EXAMINATION

NOTE: All references to sides and corners are made as if you were sitting in the driver's seat.

ENR2-025-3 11574



150BB96

2.

A vehicle fire cause examination was conducted on Wednesday, 8/14/96 commencing at 12:45 p.m. at the Insurance Auto Auctions storage and sale facility, 4701 Agnes Street, Corpus Christi, Texas. The risk was photographed and diagrammed at that time. There were no adverse conditions or appreciable alterations to the car; therefore, a true and accurate fire cause determination was possible. I was the only person present during this portion of the investigation.

From an exterior examination it was almost impossible to tell a fire had occurred. None of the exterior paint was burned or blistered and all window glass was still intact. Once the hood was raised, a minor amount of paint damage and heat stress was present on the underside, near the right front corner (photo #7).

Even with the hood open it was difficult to tell a fire had occurred until some significant burning to the right front inner fender well was noted (photo #8). This corresponds with the damaged paint and heat stress to the underside of the hood. Virtually all combustibles, including hoses, belts, plastic parts and wiring insulation, were still intact. This was especially true on the left side of the engine compartment where no burning was noted to any of the various components (photo #9).

The left side was the area where the rubber fuel lines and quick-connectors were routed. They were attached to the fuel rail on the left side of the motor and had obviously not received any fire damage (photo #10). It has been my experience that fires caused by an electrical defect or malfunction are much more centralized than those involving flammable or combustible liquids. Even the fire damage on the right side of the V-8 motor was minimal (photo #11).

All of the burning was clearly localized to the extreme, right front corner of the engine compartment (photo #12). The twelve volt battery had been removed prior to my examination but I did not see any localized burning to the battery tray or nearby sheet metal (photo #13). The most intense burning was clearly localized around the forward end of an electrical block and fuse panel. I did see that one of the bare wires had become unattached from a fitting or connection (photo #14).

The wires were closely examined; however, I did not see any evidence of arcing or shorting on the bare copper conductors. The separated end is the only evidence of


separation possibly due to an arc or short circuit. A check of a repair manual indicated the correct name for the electrical block/fuse panel was the "electrical distribution box". It had apparently been bolted to the inner fender well as the mounting studs and nuts were still attached (photo #15).

When the electrical distribution box was picked up and more closely examined, I saw an eyelet, solderless terminal, attached to a large electrical lug, was the area where the separated wire had been connected (photo #16). The interior of the electrical distribution box also exhibited fairly heavy fire damage (photo #18).

Once the fuse box cover was removed, it was evident the only fire damage was to two of the large fuses on the rear of the panel (photo #19). The bottom cover was removed from the electrical distribution box at which time I noted an interior cover was burned approximately half way off (photo #20). The burning to the underside of the component was clearly localized with fire damage to three of the wires (photo #21).

A check of the fuse panel revealed two of the blade type fuses had blown. In this instance, the short circuit was sufficient to "weld or bond" one of the fuse legs to the mounting slot. These fuses were removed which confirmed the heavy damage to each one (photos #23 & 24).

After more of the plastic case, on the power distribution block, was removed, burning was noted to the base of the fuse receptacles. This is clearly internal, localized heating coming from a wire or connection on the power distribution box. In this instance, I feel an arc or spark occurred between the wire attached to the electrical lug with the eyelet, solderless, terminal (photo #29). The following conceptual diagram shows the engine compartment of the risk, the location of the power distribution box and the specific area where the fire originated.



DETERMINATION OF FIRES CAUSE

Based on physical evidence remaining on the vehicle and information obtained from various sources, it is my opinion this was an accidental fire. It occurred from an unspecified defect or malfunction which caused an overheating condition within the wiring or connections in the electrical distribution box.

COMMENTS

With the completion of my investigation, I feel the cause of this fire has been well documented. The minor amount of burning is clearly centered around the power distribution box and the area where the wire came off the solderless terminal could have caused resistance heating or a short circuit. Although this car was approximately four years old, it appeared to be in very good shape and I saw no evidence of abuse, neglect, alterations or non-OEM parts. If the electrical system, specifically the power distribution box, has not been worked on then whatever caused this fire was built into the car at the assembly plant.

Although no additional investigation is anticipated, I am leaving this file open for 30 days to allow you sufficient time for review and evaluation. If either yourself or Mr. Huck have any further instructions, questions or information, please feel free to call at anytime. As always, I can be contacted through my Irving, Texas office or my digital pager.

Respectfully Submitted,

Byron R. Bryson

Byron R. Bryson, C.F.E.I.

For the Firm



Enclosures

BRB/db



150BB96

5.

PHOTOGRAPHS

1. Front of fire damaged 1992 Ford Crown Victoria.
2. Right front corner of involved vehicle.
3. Right rear corner of involved vehicle.
4. Left rear corner of involved vehicle.
5. Left front corner of involved vehicle.
6. Undamaged paint on exterior surface of the hood.
7. Minor damage and heat stress on right front corner of hood.
8. Fire damage in engine compartment and to V-8 motor.
9. Undamaged combustible components on left side of V-8 motor.
10. Close up of fuel supply hoses and quick-connectors.
11. Burning on right side of V-8 motor.
12. Isolated fire damage in right front corner of engine compartment.
13. Isolated fire damage in right front corner of engine compartment.
14. Burning to electrical distribution box. NOTE separated end of wire.
15. Side of electrical distribution box and mounting studs.
16. End of solderless terminal where wire had been connected.
17. Fire damaged wires within area of origin.
18. Close up of burning inside distribution box.



150BB96

6.



PHOTOGRAPHS

19. Fire damage to fuses in electrical distribution box.
20. Burning to lower cover on electrical distribution box.
21. Burning to under side of electrical distribution box.
22. Burning to under side of electrical distribution box. NOTE loose wire was replaced in approximate area prior to fire.
23. Blown and damaged fuse.
24. Blown and damaged fuse.
25. Close up of damage to fuses in electrical distribution box.
26. Localized burning to end of electrical distribution box.
27. Localized burning to end of electrical distribution box.
28. Internal burning in electrical distribution box.
29. Internal burning to electrical distribution box.

**FIRE
PHOTOGRAPHS**

No. 1



No. 2




EP62-675-B 11388

F.I.R.E.
PHOTOGRAPHS

No. 3




No. 4



F.I.E.
PHOTOGRAPHS

No. 5



No. 6



F. L. R. E.
PHOTOGRAPHS

No. 7



No. 8



FIRE
PHOTOGRAPHS

No. 9



No. 10



FIRE
PHOTOGRAPHS

No. 11



No. 12



F.I.R.E.
PHOTOGRAPHS

No. 13



No. 14



FIRE
PHOTOGRAPHS

No. 15



No. 16




EX-102-525-B 11587

F. I. R. E.
PHOTOGRAPHS

No. 17




No. 18



FIRE
PHOTOGRAPHS

No. 19




No. 20



ERG2-825-B 11549

F. I. R. E.
PHOTOGRAPHS

No. 21



No. 22



FIRE
PHOTOGRAPHS

No. 23




No. 24



WFO2-025-B 11591

F. I. E.
PHOTOGRAPHS

No. 25



No. 26



F. LEE
PHOTOGRAPHS

No. 27



No. 28



EA02-020-B 11583

FIRE
PHOTOGRAPHS

No. 29



6262-625-5 11884



Technical Services Dept.
703-673-4800

TECHNICAL BULLETIN

Ford IAR Alternators
with Battery Plug Connection

COPY

WARNING! WARNING! WARNING!

*To reduce the risk of premature alternator failure
and/or wiring harness fire, these precautions must be followed.*

1. PROFESSIONAL INSTALLATION REQUIRED

This internally-regulated Ford alternator requires professional installation utilizing proper equipment. You should not attempt this installation unless you are properly equipped and trained.

2. CHANGE THE LARGE PLUG-IN CONNECTOR!

The heavy wire 3-prong connector carries all of the output current produced by the alternator. This plug was designed for original assembly line installation without tools. It snaps tightly into place and is difficult to remove. The twisting and pulling which occurs during removal will cause the metal connectors within the plug to spread and weaken. If the plug is re-used, the poor contact made between it and the terminals in the alternator creates resistance and heat, which leads to alternator failure and/or a catastrophic wiring harness fire.

Always use a new plug connector when installing this type of alternator. An O.E.M. style connector with splicing pigtail is supplied with your Precision remanufactured alternator as of 12/01/92 production date codes.

3. INSTALLATION

These procedures must be followed to ensure a professional, high quality installation.

- A. Disconnect the battery.
- B. Mount the alternator to the brackets with the output plug in place.
- C. Cut the vehicle harness at an appropriate spot to easily match the length of the supplied plug and pigtail.
- D. Strip the insulation back 3/8" and ensure that the exposed copper wires are clean and shiny.
- E. Apply a small amount of rosin-type flux directly on the wires and insert them into the tube connectors provided. - continued on reverse

FILE COPY

3. INSTALLATION (continued)

- F. Crimp the connector securely with a proper tool that is designed to "stake" the connection. You must make a strong physical connection before soldering.
- G. Slide the heat shrink tubing as far away from the connector as possible to avoid premature shrinking.
- H. Solder the terminal using a 60/40 rosin core solder. Be careful to heat the connector properly and allow the solder to flow into and through the connection.
- I. After the soldered connection is cool, slide the heat shrink tubing in place and heat until it conforms to the connection and seals it.

NOTE: Do not skip any steps.

Do not use acid core solder or acid type flux.

Do not rely on solder alone or crimping alone to make the connection. You must do both.

Do not use wire nuts or Scotch-Loc connectors.

Call for assistance. Our Technical Services Department will be glad to help explain this installation.

FAILURE TO PROPERLY INSTALL THIS PLUG VOIDS YOUR WARRANTY.

4. CONNECT IT ONCE

As mentioned previously, removal of the large plug loosens the connection. Therefore, removal and replacement of even a new connector may lead to failure. The plug has been installed using a special contact gel recommended by Ford. Do not remove this gel!

5. LOAD TEST THE BATTERY

Faulty batteries strain the vehicle's electrical system. Load testing the batteries will detect bad batteries before they cause a comeback. This is especially important on Ford internally-regulated charging systems.

6. CHARGE OR REPLACE THE BATTERY

You must fully charge the battery with an appropriate battery charger. Alternators are not designed to recharge a "dead" or even a new battery. Using the alternator to bring a battery to a full state of charge is a poor service practice that can overheat and destroy the alternator. Continuous high alternator output required to recharge a dead battery will result in an overheated connector plug and may cause a wiring harness fire.

FILE COPY

SOUTHLAND REBUILDERS

— DIVISION OF FORDVILLE & CO. —

REMANUFACTURER'S BULLETIN

July 15, 1992

RS-T-92-102

TO: All Dealer Parts and Service Managers
FROM: Southland Rebuilders - Quality Assurance
SUBJECT: IAR Alternator Failures

SEP 2 1992

The IAR Alternators have been experiencing problems that result in failure of the rectifier due to shorting out the diodes and/or burning the wiring harness. Both failure modes are caused by excessive heat being generated within the system.

We have concluded, with the cooperation of a few dealers within our network, that the problem is caused by a damaged harness plug. In the process of removing the failed alternator, the harness plug is pried out of the rectifier and the side clips are distorted and/or broken off. These clips are critical in retaining the harness plug in the rectifier to prevent the plug from backing out. Should the plug back out, an air gap will develop and arcing will occur which will cause heat.

Southland Rebuilders' recommendation is to replace the damaged and/or broken plug with a new plug, FORD part number E7FZ-10A583-A. We also suggest that the rectifier socket have a dielectric compound, FORD part number D7AZ-13A331-A, grease applied to the terminals. We recommend that a tie wrap be wrapped around the outside of the harness plug for added security. Care must be taken that the plug is fully seated in the rectifier socket.

The above recommendation has been approved by FORD Product Engineering, Rawsonville Plant, and by FORD Parts and Service Division Remanufacturing Engineering.

With the above in mind, Southland Rebuilders' position regarding the warranty of failed alternators will be:

IN ORDER TO BE COVERED BY SOUTHLAND'S WARRANTY, ANY IAR ALTERNATOR THAT HAS FAILED DUE TO A BURNED RECTIFIER THAT WAS INSTALLED AFTER AUGUST 1, 1992, WILL REQUIRE THAT THE ALLEGED DEFECTIVE ALTERNATOR AND PLUG BE RETURNED TO OUR PLANT, ALONG WITH THE USUAL WARRANTY PAPERWORK, TO SHOW THAT THE PLUG WAS REPLACED WITH E7FZ-10A583-A.

FILE COPY

Vallejo, CA 94598

O. Box 906

S. Cole & Assoc., Inc.

Loose Alternator Bearing Cap

• Can Cause Fire

In March of this year we investigated an interesting car fire that occurred while the vehicle was operating at high idle RPMs in a car wash. The automobile was a 1992 Ford Mustang with a 5.0 liter high output engine with electronic fuel injection.

Our report on the investigation stated:

"The vehicle was identified as in caption with a manufacture date of August 1991 and recorded mileage of 876 miles. The passenger compartment did

not suffer fire or heat damage. The fire damage was confined to the engine compartment and primarily on the right side. The vehicle is powered by a 5.0 liter V8 engine. The fuel supply and return lines were in place and the snap guards were in place over the quick connect fittings. The plastic portions of these fuel lines had burned and melted away as is common in these cases. The general fire pattern in the engine compartment would not indicate that a fuel leak took place. In examining the right side of the engine compartment it was noted that a circular metal type of 'cap' had attached itself to the alternator output wiring. Closer checking revealed this attach-

ment was caused by a 'welding' process created when the metal cap made contact with the alternator wiring and 'short' occurred.

Continuing examination revealed the metal 'cap' was for the rear alternator bearing. The bearing itself had partially fallen out and was lost. It is opinion that the fire was electrical nature and was caused by the rear alternator bearing falling out and short against the output wiring."

Ford Motor Company reimburse insurance carrier for their pay on this loss. ■

Alternator fire- continued

Point of Origin

1. The primary burn damage to the hood indicates that the fire originated in the area above the alternator.
2. The alternator pulley/fan has a heat pattern radiating from the center indicating higher heat at the center.
3. The discoloration of the alternator pulley/fan indicates higher heat in this component than in other areas of the engine compartment.
4. The alternator bearings felt very rough when the alternator pulley was turned by hand. Some of this could be due to the fire, but other components, such as the water pump, freon compressor, power steering pump, and idler pulleys felt smooth when turned by hand.
5. Reportedly the alternator drive belt had been replaced shortly before the fire occurred.

Conclusions

1. The fire was caused by an overheated alternator, which ignited nearby flammable components.
2. The bearings likely were faulty before the belt was changed. This could have contributed to the previous belt needing replacement. Bearing failure due to faulty belt installation is not likely, as this system is equipped with automatic belt tensioners and requires no adjustment.

3. The bad alternator bearings likely could have been detected at the time of belt installation by merely spinning the pulley by hand. It is also likely that the bearings would make an abnormal noise.

Recommendations

1. If the repair was done by a service facility, subrogation should be looked into. The installer should be questioned regarding the repair. If a bearing noise was heard the alternator should have been checked to determine the problem. Arguably, the alternator and other accessories should have been spun by hand as a minimum check during belt replacement. If the previous belt was broken, or had worn out in a short time, or if there had been complaints indicating low charging, the technician that changed the belt should have checked the alternator bearings. This could have been done simply by spinning the pulley, and by feeling by hand for roughness or looseness (this would have taken only a matter of seconds to do)."

We thank Ed and Gene for sending along this information. It would be interesting to know if a trend is developing here. If any of you have any similar cases we would like to know about them. ■

Copyright & Subscription Information:

The *Vehicle Safety & Security Report* is written monthly by Lee S. Cole & Associates, Inc. & published by Lee Books, P.O. Box 806, Novato, California 94948-0906. Subscription price is \$38.00 per year in the U.S. or \$50.00 per year for all other countries. Copyright © 1992 by Lee S. Cole & Associates, Inc. All rights reserved. No part of this newsletter may be reproduced in any form without the written consent of the copyright owner. For information call (415) 458-4388.

Editor: Lee S. Cole
Publisher: Lee Books
Use Wanka-Cole

FILE COPY

Vehicle Safety & Security Report

Prepared By Lee S. Cole & Associates, Incorporated

(NOV 08 1983)

Ford Alternator Fires

IN THIS ISSUE:

- 3 Minivan Fires
- 4 Recalls
- 5 Shocking Verdict
• pickup fires

In past issues of *Vehicle Safety & Security Report* we have reported on two cases where an alternator malfunction resulted in an engine compartment fire in a Ford product. One of these was a Thunderbird and the other a Mustang. Mr. Ed Horksey of Horksey & Associates and Mr. Gene Meng of Meng Engineering have sent us information on a similar fire in a 1988 Ford Mustang. Their joint report follows:

"Inspection of the Vehicle

General condition:

1. The burn damage was limited to the front of the vehicle. The front bumper and body plastic were severely burned and melted from the center to the left front corner.
2. The paint above the left front wheel opening is burned, and the front edge of the driver's door is lightly burned.
3. There are two burn patterns on the hood, a light pattern at the rear of the hood extending into the cowl, and a heavier pattern above the area where the alternator is located.

4. The fire damage inside the engine compartment is extensive, particularly at the front of the engine. Most of the non-metal materials in the front of the engine compartment have been consumed or melted.
5. The fan shroud had been consumed.
6. The flat accessory drive belts had been consumed except for a small portion that was trapped between two pulleys.
7. The battery was trashed, and partially consumed.
8. The coolant overflow bottle was completely gone.
9. The windshield washer fluid bottle was gone.
10. The air cleaner and associated tubing was melted and/or missing.
11. The underhood insulation material had melted down onto the engine.
12. The fuel lines at the rear of the engine had melted and added fuel to the fire during the last stages of the fire.

continued on page 2

FILE COPY

FILE COPY Eye On Electronics



Mike Dale

There are several ways to repair wiring harnesses. This month, Mike takes a look at a few different methods and examines the pros and cons of each.

In reading through a pile of service bulletins recently, I was struck by the similarity of some of the complaints. One of them involved high-ampereage Ford alternators used between 1966 and 1969. These alternators, used on various Lincoln, T-Bird, Thunder and Mustang applications, were running into significant failures associated with the voltage regulator and the wire harness connector.

The gist of the problem was that high currents from the alternator were causing damage to the small terminals in the regulator. This in turn caused deterioration of the wire harness connector. Sometimes the connectors and the alternator/regulator would overheat and catch fire. The problem is so serious that many rebuilders will not guarantee Ford alternators unless a new \$14 wire harness connector is replaced at the time of installation.

A similar problem is afflicting the O₂ sensor replacement business. A look through a Nisshoff catalog shows almost 80 different sensors listed for the various applications they cover. Some aftermarket companies are offer-

ing universal-fit replacement sensors that require cutting and splicing the wire harness connector. Supplying one sensor to be mated to a whole bunch of OE connectors greatly simplifies the inventories that have to be carried by local parts houses.

The common thread between the Ford alternators and the O₂ sensors is the recommendation to cut and splice the wiring harness. Without a doubt, this can be and is done every day without problem. However, if it's done badly, you can wind up installing more trouble than you fixed. The key to a good spliced connection is understanding what you're trying to accomplish and what can go wrong when you do it incorrectly. For those of you jumping ahead of me, solder may not always be the best solution.


The first thing to remember is that the best connection is no connection at all. The unbroken, stranded wire strung safely inside its PVC or crosslink polyester insulation is very efficient. Unless it sees a drastic overcurrent condition or mechanical damage, that wire will last virtually forever. The only reason you should ever splice a harness is because you have to.

In making the splice, you're trying to get the wire-to-wire junction back as close to original as possible. This includes not only the electrical connection, but mechanical features such as wire sealing, wire draping and support and wire location.

The electrical connection itself can be made by either soldering the wires or crimping them together with a mating terminal such as a butt splice. The disadvantage of using solder is that if you don't have a sound mechanical connection, you run the risk of last-minute motion between the wires occurring before the solder is totally solid. That results in a pasty, or cold, solder joint.

When soldering, the two wires to be spliced are often held parallel and then twisted together. That means that after the joint is made and the harness is

continued on page 22



Butt splice connectors (inset) are color-coded for the size of the wire and usually have a range of only two gauge sizes. After the butt splice is completed, the heat-shrink tubing must be uniformly and evenly shrunk, and should extend a minimum 1/4 inch beyond each end of the connector.

repositioned, the connection sometimes winds up being perpendicular to the drops of the wires.

You can see the problem here if you think of the wires coming away from the joint as lever arms, with the stiffness of the wire transmitting force to the junction of the wires. The right-angle joint focuses the lever action of the wires onto the angle of the joint. This is an inherently weak connection from a vibration and mechanical standpoint.

In making a good solder joint, we also run into the problem of capillary action. In the same way that a wick soaks up kerosene in a lamp, the multiple strands of copper in a wire can soak up solder, solder flux and eventually salt water and other liquid contaminants. If solder wicks back up into the wire, it can result in the wire being stiff because the strands are soldered together. Flux and salt wicking can cause hidden corrosion, as well.

There are two alternatives to the right-angle, twisted solder joint. One is to slightly splay or fray the two

ends, stick them into each other, then crimp and solder them. This doesn't have as firm a mechanical locking as the twisted joint. However, it's better in that it has the joint properly aligned to the eventual lay of the finished wire. The other problems remain, but at least it solves the right-angle leverage problem.

The second alternative is to butt-splice the connection. A butt splice is an open-ended copper cylinder. The object is to stick the stripped end of one wire in one end and the stripped end of the other wire into the opposite end. The cylinder is then crushed to mechanically lock the splice to the stranded wire.

The advantages of butt-splicing include proper alignment of the junction with the lay of the wire and lack of capillary reflowing associated with solder and solder flux. Butt splices can also be used on nonsolderable wires such as stranded stainless steel.

On the short side, the butt splice alone, even with its plastic overshield, cannot protect the joint from the elements. Getting the metal part of the

splice to crush evenly depends on the material the splice is made of and the tool used to deform it. Often, the size of the butt splice chosen doesn't match well with the wire size. This leads to poor crimping and the possibility that the crush of the splice is not really holding the wires securely.

Like a lot of other things, there are butt splices and then there are butt splices. The cheap ones usually have an overcoat sleeve made of brittle PVC. When you crimp it, the blue plastic turns white and often pushes the tool away from a clean, even crimp. The ones they sell to professional electricians have a polyethylene overcoat that's softer, more compliant and easier to crimp. Personally, I prefer the T&B (Thomas & Betts) brand.

If you distort a butt splice by using a cheap crimping tool, don't expect good results. The same also applies to ring lugs, forks and other popular types of crimp terminals. The Klein Tool Co. makes a crimp tool for professional electricians. Like lots of other tools, if you buy a good one to start

The Quality Leader in the Lift Industry As Always, Setting the Standard... The New GPOA Series

New!



The GPOA Series features a lifting capacity of up to 12,000 lbs., an "Asymetric-Pull" design for full door opening and extra room around the vehicle, twin-cylinder construction for smooth operation and exclusive carriage guides that ensure long life. Safety features include automatic arm restraints, self-aligning rear locks and single point lock release. Backed by our 6-year warranty and meeting all ANSI/SAE safety requirements.

FP-12 Heavy Duty Four Post lift systems handle general service, four-wheel or wheel alignment with capacities up to 12,000 lbs. Feature built-in control and secure and the capability to service up to 30" wheelbase vehicles.



For more information CALL (800) 421-2943

UNIVIL **GRAND-PRX**
AUTOMOTIVE LIFT SYSTEMS

Made in the U.S.A.

For more information, circle #15
22 MOTOR March 1995

STEELMAN.

QUALITY TOOLS FOR THE PROFESSIONAL

CAN'T FIND THAT NOISE?



FIND IT FAST WITH
ENGINEAR
THE ADVANCED
ELECTRONIC
STETHOSCOPE

- Quickly diagnoses noise and location of bad bearings, bushings, broken gear teeth, leaks, squeaks and rattles.
- Versatile for hydraulic pumps, valves, strainers, A/C compressors, mechanical controls and fan systems.
- Simply place the microphone tip on the suspect part, place headphones over ears and listen to what's going on!



Product available from your Snap-On, Mac Tools, Matco Tools and Cornwell Quality Tool Distributor.

CALL 800-225-7811 FOR A DISTRIBUTOR NEAR YOU.

STEELMAN.

IF YOU CAN'T SEE IT, WE CAN. 24 HOURS A DAY, 7 DAYS A WEEK. 24 HOURS A DAY. 24 HOURS A WEEK. 24 HOURS A WEEK. 24 HOURS A WEEK.

For more information, circle #14

with, it'll last you a lifetime.

In the end, it's hard to say which connection method is best. My experience is that, on average, the butt splice, if made with the proper crimping tool, offers the simplest connection with the best results. Just be sure the butt splice you use matches closely size-wise with the wire you're splicing. The end-to-end solder joint can also work quite well, if you don't go crazy piling on too much solder.

Once the joint is complete, the next step is to insulate it. Here, the possibilities are almost endless—PVC electrical tape, friction tape, silicone RTV, heat-shrink tubing, etc. Probably the poorest choice is that 89-cent roll of PVC tape. Because of its poor flexibility, especially when cold, the tape almost always separates from the joint. Instead of holding moisture away from the connection, it acts as a poultice, holding the crud and other stuff in contact with the metals of the joint.

Friction tape might actually be better if for no other reason than its

heavy goo/tar/asphalt coating protects the joint just as much as the fiber of the tape itself.

While it won't work on a right-angle joint, by far the best sealing alter-

"My experience is that, on average, the butt splice, if made with the proper crimping tool, offers the simplest connection with the best results."

native is heat-shrink tubing. Usually about an inch long, this tubing is cut

to fit from 10-inch pieces commonly available at electronics supply shops. The inside diameter of the tubing can be two or three times that of the wire when you put it on before making the solder or butt splice joint. The best way to cure it is with a hot air gun, although you can limp along with a hair dryer. The key to using it is to make sure there's plenty of contact between the tube and the wire insulation on either side once the tubing has been shrunk to fit. That way, there's plenty of distance to prevent moisture from creeping between the wire and the heat-shrink tubing. You should figure a coverage of at least 4 to 8 inch beyond either side of the joint.

Once each individual wire is sealed up, you need to tangle the wire harness in its original location with the strain relief properly positioned. As we said earlier, the individual wires and the wire harness form a lever that acts on the terminations at each end. If you leave it out there flopping around, eventually it damages either the end connections or the cable itself.

REPLACEMENT

Motor 280ZX (4-cyl) \$478.14
 Ford 2800 (4-cyl) \$438.37
 and 79-80 \$438.12
 Chrysler 36-47 \$398.00
 Ford EXP (4-cyl) \$487.00

WE OFFER GUARANTEED
 12 MONTHS 50,000 MILE WARRANTY

Power 31-47 \$498.00
 Ford 31-47 \$498.00
 Chrysler 31-47 \$498.00
 Ford EXP \$498.00
 Power 37 \$498.00

For more information, circle #81

WE HEARD YOU GUYS

For more information, circle #8
 March 1995 MOTOR

SAMPLE "PUT ON NOTICE" LETTER

FOR FORD

BLOWER MOTOR RESISTER FAILURES

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Ford Motor Company
Parklane Tower West
Suite 300
3 Parklane Blvd.
Dearborn, MI 48126

ATTN: Mr. Howard E. Keys
Mgr.- Product Claims Dept.

Re: Our Claim #
Our insured:
Date of loss:
Vehicle Data: 19XX Ford XXXXXXXXXX
VIN XXXXXXXXXX

This State Farm insured vehicle was involved in a non collision vehicle fire (while being driven, or after parking, or while idling). Damage to the vehicle resulted in a (total or partial) loss of \$XX,XXX.

Our investigation reveals the cause of the fire to be related to failure of the blower motor resistor.

Enclosed is documentation of our claim (including our experts report, or drivers statement, or affidavit, or invoices). We are holding the vehicle for XX days in the event you wish to make an inspection. You may contact me at (XXX)XXX-XXXX to make arrangements.

Please consider this letter as our claim to Ford Motor Company to reimburse State Farm for its interest of \$XX,XXX.

Very Truly Yours,

John Doe
Claim Specialist

Overview of Recall 439

une. 1982

Subject

Service Recall 439 - Certain 1982 Escort, Lynx, and LN7 Vehicles for Replacement of Air Conditioner (A/C) Blower Motor Resistor Assembly.

Description Of Defect And Correction

Ford Motor Company has determined that a defect involving motor vehicle safety exists in certain 1982 Escort, Lynx, and LN7 vehicles with optional factory installed air conditioning. With the blower motor switch in the medium-low position, the possibility exists that a resistor in the motor's electrical circuit could overheat in the event that the blower became stuck or jammed for some unrelated reason. An overheating resistor could eventually melt and ultimately ignite the air conditioner case (located under the instrument panel), producing a fire which potentially could spread to other flammable materials inside the vehicle.


Ford is recalling these vehicles to correct this condition. The blower motor resistor assembly will be replaced with a new assembly having a lower effective heat range thermal limiter to ensure electrical current interruption should it be needed. All affected vehicles are to have the new resistor assemblies installed. An initial supply of the replacement resistor assemblies, part number 12FZ-19A706-A, will be one-time direct shipped to all dealers in early June, 1982, in coordination with owner notifications. Dealers should order additional parts, as needed, from Whelen using the mailing address found in this Bulletin.


<u>Vehicles Affected</u>	<u>Assembly Plant</u>	<u>Production Dates</u>	
		<u>From</u>	<u>Through</u>
Escort and Lynx	Edison	8/10/81	2/23/82
	Wayne	7/27/81	3/10/82
	St. Thomas	8/10/81	3/01/82
	San Jose	9/04/81	2/25/82
EXP and LN7	San Jose	9/04/81	2/25/82
	St. Thomas	8/10/81	3/01/82

Vehicles involved in this recall are all 1982 Escort, Lynx, EXP and LN7 with factory installed air conditioning built at the assembly plants during the periods shown in illustration.

WIRING
CONNECTOR


BLOWER MOTOR
RESISTOR AS
B2F2-18A70E





FORD FULL SIZE PASSENGER VEHICLES AND TRUCKS

Engine Compartment Cover



Rear RH Side Of Engine Compartment

```
*****
*
*
*****
*   GENERATED BY:
*   CHRISTIE LONG
*
*   FROM: 813-845-0716
*
*   JCN: 0609140
*
*   JOBDAT: 12/20/96
*
*   TIME: 13:50:58
*
*****
```

+ | ***** VEHICLE HISTORY (SEE-II) TYPE *****

```

* SERIAL YEAR          = 92
* CUT-OFF DATE        = 12NOV96
* REPORT TITLE        = DELGADO
* VEHICLE TYPE        = CAB
*
* IMPORT CLAIM TYPE    = ALL CLAIMS
*
* OUTPUT FILE NAME    = ██████████.O.SERIALS.REPORT
*
* REPORT SORT SEQUENCE = PLANT CODE \ SERIAL NO
*
* PAGE ON PRIMARY SORT?
*
* PARETO HIS VALUE    =
*
* PLANT/SERIAL NUMBER = IL5863

```

ZGDEC16
PAGE 2.01

1992 SE-II PARTS BY CONCERN CODE (OLD CONDITION CODE) SUMMARY (12NDV96 C/O)
DATA ORDERED BY DESCENDING PART NO. FREQUENCY

PART NO	CC	COUNT
10654	15	1
14W029	41	1
6108	56	1
7F230	88	1

EN02-025-0 11000

2409096
PAGE 1.01

1992 SE-XX PARTS BY CUSTOMER CONCERN CODE SUMMARY (12M0796 C/O)
DATA ORDERED BY DESCENDING PART NO. FREQUENCY
[REDACTED] LONG

PART NO	CEN	COUNT
16484	ANY	1
148089	ANY	1
6188	ANY	1
7F32D	WOL	1

2002-023-5 11019

2808256
PAGE 4.61

1992 22-II PARTS BY CONDITION CODE SUMMARY (1200756 C/O)
DATA ORDERED BY DESCENDING PART NO. FREQUENCY
CHRISTIE LONG

PART NO	CD	COUNT
18684	18	2
148889	41	1
6108	56	1
77330	60	1

11011 9-022-3 11011

28DEC95
PAGE 5.01

1992 SS-II PART/CONCRETE CASE DESCRIPTION SUMMARY (L28CV96 C/G)
DATA OBTAINED BY DESCENDING REPAIR COUNT

CONCRETE LOG

NUMBER	PART DESCRIPTION	COUNT	CC-DESCRIPTION	COUNT	CD-DESCRIPTION	COUNT	CCL-DESCRIPTION	UNDT
10834	BATTERY	1	00-OTHER/UNKNOWN	1	00-OTHER/UNKNOWN	1	ANT-NO CODE PROVIDED	3
14888	RELAY ASSY	1	15-WILL NOT HOLD CHARGE	1	15-DEAD/WEAK BATT	1	POI-HARD TO SHIFT	1
4108	PISTON & PIN ASSY	1	41-STICKS, BIRDS, GRASS, SWI	1	41-NICK/CRACK/TOOT	1		
77330	INCL TR THROT VALVE	1	56-NOISE, RATTLES, SQUAKS	1	56-NOISY OPERATION	1		

1992-028-9 11812

XXXXXXXXXX	XX	XX	XX	XX	XX	XXXXXXXXXX	XXXXXXXXXX	XX	XX
XXXXXXXXXX	XX	XX	XXXX	XXXX	XXXX	XXXXXXXXXX	XXXXXXXXXX	XX	XX
XX	XX	XX	XXXXX	XXXXX	XXXXX	XX	XX	XX	XX
XX	XX	XX	XXXXX	XXXX	XXXX	XX	XX	XX	XX
XXXXXXXXXX	XX	XX	XX	XX	XX	XXXXXXXXXX	XXXXXXXXXX		XX
XXXXXXXXXX	XX	XX	XX	XX	XX	XXXXXXXXXX	XXXXXXXXXX		XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XXXXXXXXXX	XXXXXXXXXX	XX	XX	XX	XX	XX	XX	XX	XX
XXXXXXXXXX	XXXXXXXXXX	XX	XX	XX	XX	XX	XX	XX	XX

 * CLAIMS LISTING FOR 1992 MODEL [REDACTED] REQUESTED BY: CHRISTIN LONG L2MOV96 C/O
 * SORTED BY: PLATCODE SERIAL# KIA 892 DATA SOURCE: PAMS SE-II

***** SUMMARY *****												
***** TOTALS *****							***** RATION *****					
CLAIMS	CLAIMS W/COMMENTS	CLAIMS IN THE	VEHICLES	DEALERS	MATERIAL COST	TOTAL COST	CLAIMS PER VEHIC	CLAIMS PER DEALER	CLAIMS TOTAL/RAMP	MATERIAL COST/REP	TOTAL COST/REP	PER CLAIM W/COMMENTS
4	2	4	1	2	\$389.15	\$1,546.68	4.00	2.80	1.00	\$57.94	\$386.72	94%

[illegible]

|*** 1992 MODEL YEAR PASSENGER CAR BODY DESCRIPTIONS *****|

VEHICLE	BODY	DESCRIPTION	VEHICLE	BODY	DESCRIPTION		
MUSTANG (MOS)	2LK	2 DOOR STYLISH LK	3LK	3 DOOR	LK		
	2CG	2 DOOR CONVERT GT	3GT	3 DOOR	GT		
	2CL	2 DOOR CONVERT LK					
FORD (FEB)	3GL	3 DOOR	GL	CAROL (CAR)	2-S 2 DOOR CONVERT BASH		
	3LK	3 DOOR	LK	2KK	2 DOOR CONVERT KR2		
	3GT	3 DOOR	GT				
MERCURY (MRC)	3-S	3 DOOR	BASH	TRACER (TRA)	4-S 4 DOOR	BASH	
	3GT	3 DOOR	GT	4LT	4 DOOR	LTS	
	WIX	STATION WAGON	LK	W-S	4 DOOR	BASH	
	3LK	3 DOOR	LK				
	4LK	4 DOOR	LK	FESTIVA (FES)	3-L 3 DOOR	BASH	
	4LK	4 DOOR	LK-S	3GL	3 DOOR	GL	
	5LK	5 DOOR	LK				
TEMPO (TEM)	2-S	2 DOOR	L	TOPAL (TOP)	3GS	3 DOOR	GS
	2GL	2 DOOR	GL	3KR	2 DOOR	KRS	
	2-G	2 DOOR	GL SPORT	4GS	4 DOOR	GS	
	4-S	4 DOOR	L	4LS	4 DOOR	LS	
	4GL	4 DOOR	GL	4LT	4 DOOR	LTS	
	4LK	4 DOOR	LK				
	4-G	4 DOOR	GL SPORT				
TAUNUS (TAU)	4-S	4 DOOR	BASH	WOL	ST WAGON	ALOCK BASH	
	4-P	4 DOOR	POLICE	WOL	ST WAGON	ALOCK GL	
	4PL	4 DOOR	ALOCK POLICE	WLL	ST WAGON	ALOCK LK	
	4SK	4 DOOR	ALOCK SHO				
	4-S	4 DOOR	GL	SALE (CAR)	4GS	4 DOOR	GS
	4LK	4 DOOR	LK	4LS	4 DOOR	LS	
	4PL	4 DOOR	ALOCK BASH	4GL	4 DOOR	ALOCK GS	
	4GL	4 DOOR	ALOCK GL	4LL	4 DOOR	ALOCK LS	
	4LL	4 DOOR	ALOCK LK	WOS	STATION WAGON	GS	
	W-S	STATION WAGON	BASH	WIS	STATION WAGON	LS	
	W-H	STATION WAGON	GL	WLL	ST WAGON	ALOCK GS	
	WIX	STATION WAGON	LK	WLL	ST WAGON	ALOCK LS	
T-BIRD (TBD)	2-S	2 DOOR	BASH	COURAR (COR)	2LS	2 DOOR	LS
	2LK	2 DOOR	LK	2KR	2 DOOR	ALOCK KRT	
	2RC	2 DOOR	ALOCK RC	2LL	2 DOOR	ALOCK LS	
	2HL	2 DOOR	ALOCK BASH	ALOCK - EQUIPPED WITH 4-WHEEL ANTI-LOCK DISC BRAKES.			
	2LL	2 DOOR	ALOCK LK				
FORD CROWN	4-S	4 DOOR	B		4PL	4 DOOR	ALOCK POLICE
	4-L	4 DOOR	BASH				
VICTORIA (VBD)	4LK	4 DOOR	LK	MERCURY	4GS	4 DOOR	GS
	4GL	4 DOOR	ALOCK L	4LS	4 DOOR	LS	
	4PL	4 DOOR	ALOCK BASH	MANGULA (MRC)	4GL	4 DOOR	ALOCK GS
	4LL	4 DOOR	ALOCK LK	4LK	4 DOOR	ALOCK LS	
	4-P	4 DOOR	POLICE				
LINCOLN	4-L	4 DOOR	BASH		4LL	4 DR	ALOCK BASH
TOWN CAR (LBC)	4-S	4 DOOR	SIGNATURE		4PL	4 DR	ALOCK SIGNATURE
	4DC	4 DOOR	CARTIER		4DL	4 DR	ALOCK CARTIER
MARE VII (MK7)	2KH	2 DOOR	BLASH	CONTWIL (CON)	4-L	4 DOOR	BASH
	2RC	2 DOOR	LRC	4-S	4 DOOR	SIGNATURE	

***** 1992 LIGHT TRUCK BODY DESCRIPTIONS *****

VEHICLE	BODY	DESCRIPTION	VEHICLE	BODY	DESCRIPTION			
P-MERLIN	15P	150 L.DUTY CONV.	35B	350 H.DUTY SUPER				
4X2 (PR2)	25P	150 L.DUTY CONV.	35C	350 H.DUTY CREW				
4X4 (PR4)	2HP	250 H.DUTY CONV.	45Z	450 H.DUTY COM				
	35P	350 H.DUTY CONV.						
	15S	150 L.DUTY SUPER	BROWNCO	N-2	BLANK 4X4			
	35S	350 L.DUTY SUPER	(BRO)	BLT	BLT 4X4			
	25S	250 H.DUTY SUPER	HHH	HOODED HAUSER	4X4			
VEHICLE	BODY	DESCRIPT	BODY	DESCRIPT	DRIVE CODES			
RANGE	CON	CONV	CAN	SUP	SUPER	CAN	(RA2)-4X2	(RA4)-4X4
EXPLORER	2-D	2 DR BLANK					(HX2)-4X2	(HX4)-4X4
	2XL	2 DR XL	4XL	4 DR XL				
	2XS	2 DR XL/ST	4XT	4 DR XLT				
	2ED	2 DR HAUSER	4ED	4 DR HAUSER				
ARCTICAT	4X2 (AR2)	4X4 (AR4)	VEHICLE	BODY	DESCRIPTION	VEHICLE	BODY	DESCRIPTION
	SWL	WINDOW WAGON BASE	SWL	WINDOW WAGON BASE				
	SWH	WINDOW WAGON XL	SWH	WINDOW WAGON XL				
	SWT	WINDOW WAGON XLT	SWT	WINDOW WAGON XLT				
	SWH	HOODED HAUSER WAGON	SWH	HOODED HAUSER WAGON				
	SWL	CARGO VAN BASE	SWL	CARGO VAN BASE				
	SWH	CARGO VAN XL	SWH	CARGO VAN XL				
	SWL	WINDOW VAN BASE	SWL	WINDOW VAN BASE				
	SWH	WINDOW VAN XL	SWH	WINDOW VAN XL				

***** 1992 BIRMINGHAM/CLUB RACONS *****

VEHICLE	BODY	DESCRIPTION	VEHICLE	BODY	DESCRIPTION
(ECN)	<---	ECN/MAJOR	<---	CLAS	REASON
12H	150	HIGHWID DOOR RASH	12H	150	HIGHWID DOOR CUST
12X	160	HIGHWID DOOR XL	12X	150	HIGHWID DOOR XLT
20H	200	HIGHWID DOOR RASH	18T	150	HIGHWID DOOR CREAT
20X	250	HIGHWID DOOR XL	30H	350	HIGHWID DOOR CUST
25H	250	HIGH DR SUPE RASH	20X	250	HIGHWID DOOR XLT
25X	250	HIGH DR SUPE XL	30P	350	HIGHWID DOOR CREAT
30H	350	HIGHWID DOOR RASH	30L	350	HIGH DR SUPE XL
30X	350	HIGHWID DOOR XL	30H	350	HIGH DR SUPE CUST
30P	350	HIGH DR SUPE RASH	30X	350	HIGH DR SUPE XLT
35L	350	HIGH DR SUPE XL	10H	150	SLIDING DOOR CUST
10H	150	SLIDING DOOR RASH	10X	150	SLIDING DOOR XLT
10X	150	SLIDING DOOR XL	10P	150	SLIDING DOOR CREAT
20H	250	SLIDING DOOR RASH	20H	250	SLIDING DOOR CUST
20X	250	SLIDING DOOR XL	20H	250	SLIDING DOOR XLT
20P	250	SLIDING DOOR RASH	20P	250	SLIDING DOOR CREAT
30X	250	SLIDING DOOR XL			
30L	350	CUTAWAY RASH			
30H	350	CUTAWAY XL			
30T	350	STRIPPED CHASSIS			

1000000 CLAIMS LISTING FOR 1992 MODEL
PAGE 1 SORTED BY PLSTCODE SERIALNO MILEAGE

12NOV94 C/O REQUESTED BY: CHRISTIE LONG
DATA SOURCE: PAMS SR-TI X53400

NOTE: IF TIS VALUE HAS (*) THEN CLAIM NOT USED IN TIS MATRIX

VEHICLE INFORMATION						REPAIR INFORMATION																	
SERIAL NUMBER	CAE LBR	E/S CUI	W/S RAM	STN DATE	FROM DATE	MAKE DATE	MODEL DATE	CLARK NUMBER	MICRO NUMBER	C C	WOC PART	CC NUMBER	CCC CD	EXPR DATE	T IS	TACT CODE	MILES	MATL. COST	TOTL COST	LRG HRS	REPR ST		
155563	FED	4-L	WTY	STN	12AUG91	25AUG91	06035	034354	MOE17231	1202	6108	06	ANY	56	03DEC91	4	2	18761	223.24	619	9.0	06450	LA
** COMMENTS-CLAIM #1 TECH-H TIME, TIME TO TRANSFER INTERIOR MANIFOLD AND ENGINE WIRING HARNESS FROM OLD E																							
155563	FED	4-L	WTY	STN	12AUG91	25AUG91	06025	035130	MOH40631	7A01	18484	15	ANY	15	13DEC91	4	2	18710	61.42	98	0.6	06450	LA
155563	FED	4-L	WTY	STN	12AUG91	25AUG91	06026	035167	MOE17161	7C05	14W08	41	ANY	41	14DEC91	4	2	18794	8.24	40	0.9	06450	LA
155563	FED	4-L	WTY	STN	12AUG91	25AUG91	06026	061922	06520121	2C02	7F338	08	PO1	08	28NOV94	40	93B3	33297	92.29	791	3.4	06450	TI
** COMMENTS-CLAIM #4 CCOR-OVERDRIVE SLIPPING. TRCH-TRANS WAS NO OVERDRIVE. SENT TRANS OUT FOR REPAIRS. REINSTALL TRANS., NEW TORQUE CONVERTOR, BRASS BU TCH-CHING AND CLIP TO TV THROTTLE LINKAGE.																							

THIS LISTING CONTAINED 4 TOTAL CLAIMS

1992-025-B 11810

[illegible]

*1	END	JUN15935	0000LGRD	RVS39236	ROOM	11.44.26	AM	20	DHC	56	R0541027	SYA1	ACCTNG	JUN15935	END	A=
*2	END	JUN15935	0000LGRD	RVS39236	ROOM	11.44.26	AM	20	DHC	56	R0541027	SYA1	ACCTNG	JUN15935	END	A=
*3	END	JUN15935	0000LGRD	RVS39236	ROOM	11.44.26	AM	20	DHC	56	R0541027	SYA1	ACCTNG	JUN15935	END	A=
*4	END	JUN15935	0000LGRD	RVS39236	ROOM	11.44.26	AM	20	DHC	56	R0541027	SYA1	ACCTNG	JUN15935	END	A=

```

*****
*           E N D                               V F S R6.1  STC: WYVS          E N D           *
*****
*
*           JOB / PRINTJOB IDENTIFICATION          OFF-PRINTER          VFS JOB RELATED PRINT STATISTICS
*
* JOBSNAME: OSWELRAD PRINTJOB NAME:  R0541027    DATA:  96.265          ELAPSED PRINT TIME  00.00.03.66  AVG COMP LINE LGTH (Q)-----59
* JOBID:    JOB15935  VPSJOB NUMBER:  RV532336    12/30/96          NUMBER LINES PRINTED-----211  AVG COMP LINE LGTH (V)-----197
*                                     WRI          NUMBER PAGES PRINTED-----8    NUMBER FORM SHEETS-----34
*                                     TIME:  11.44.26.92  NUMBER D/S PRINTED-----1    NUMBER SPECIFIC I/O'S-----8
*
*****

```

CSOR0087

MORS II O.R. VIN Customer Selection

12/19/1996 10:42:13

VIN: 2FACP73W6NX155863

Model: CROWN VI

Model Year: 92

To SELECT an O.R. Customer: Type an "X" in the "A" column and Press ENTER

A	S	Acqd	Last Name	First Name	MI	Address	City	St	Zip
---	---	------	-----------	------------	----	---------	------	----	-----

F1=HELP F3=EXIT F7=FIRST F8=NEXT

I223 NO CUSTOMER DATABASE INFORMATION FOR THIS REQUEST

OGDE352

VIN: 2FACP73W6NX155863
Year: 92 Model: CROWN VICTORIA

Build Date: 08/12/1991
WSD: 08/29/1991

Campaign Number	Campaign Type	1864 Description	Campaign Status	Status Date	Dealer Code
93B31	O	TV ROD BUSHG	COMPLETE	11/28/1994	04409

F3=EXIT

1002 REQUESTED INFORMATION DISPLAYED

OGDB352

VIN: 2FACP73W6NX155863

Year: 92

Model: CROWN VICTORIA

Contract Selling Dealer P&A Code: 04409 Name: LEONARD JOHNSON'S AUTO RANCH

Contract Owner

Street

City

Zip/PC

VICTORIA

ESP INFORMATION:	Plan	Option	Expiration	Signature					
	YR	Code	Date	Mi/Km	Date	Rent	Days	Tow	Ded
	95		03/01/1997	66394	03/01/1995	25	5	45	100

COVERAGE DESCRIPTION: E1995 USED 24/24,000 POWERTRAINCARE

Cancel	Processing	Dealership Credited		W&P	Percentage of
Date	Date	Name	P&A	Statement	Refund
-----	-----	-----	-----	-----	-----

F3=EXIT F7=FIRST F8=NEXT

I112 LAST RECORD DISPLAYED - FORWARD SCROLL NOT ALLOWED

OGDB352

VIN: 2FACP73W6MX155863

Year: 92

Model: CROWN VICTORIA

Name:

Calib: 218AR00

Build Date: 08/12/1991

Recall Description

Axle: NOT AVAILABLE

WSD: 08/29/1991

NO RECALLS

Engine: 4.6L SOHC (MODULAR)

Trans: AUTOMATIC OD 4 SPEED ONP Count: 0

Message:

ESP INFORMATION:		Plan	Option	Expiration		Signature				
YR	Code	Date	Mi/Km	Date	Rent	Days	Tow	Ded		
95		03/01/1997	66394	03/01/1995	25	5	45	100		

COVERAGE DESCRIPTION: E1995 USED 24/24,000 POWERTRAINCARE

F3=EXIT

I002 REQUESTED INFORMATION DISPLAYED

OGDB352

VIN: 2FACP73W6NX155863

Year: 92

Model: CROWN VICTORIA

Name:

P&A Code	Repairing Dealer Name	Repair Date	R.O. Number	Mi/Km	Cond Code	Part Number	Labor Operation
-------------	--------------------------	----------------	----------------	-------	--------------	----------------	--------------------

F3=EXIT F7=FIRST F8=NEXT

E943 NO REPAIR HISTORY ON VEHICLE

OGDB352

CAUSE NO. 23350

IN THE COUNTY COURT

Plaintiff

v.

FORD MOTOR COMPANY

Defendant

AT LAW NUMBER 2

TRAVIS COUNTY, TEXAS

ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

COME NOW [redacted] and [redacted] ("Plaintiffs") and file this Original

Petition against Ford Motor Company ("Defendant") and for cause would show the following:

I.
PARTIES

Plaintiffs are individuals residing in the State of Texas.

Defendant is a company duly licensed and doing business in the State of Texas. It may be served through its registered agent for service of process, CT Corporation Systems, 350 North St. Paul Street, Dallas, TX 75201.

II.
BACKGROUND FACTS

On June 10, 1996, Plaintiffs' 1992 Ford Crown Victoria caught fire due to a defect or malfunction causing an overheating condition within the wiring or connections in the electrical distribution box. As a result of this, Plaintiffs sustained \$11,026.63 in damages.

III.
DEFECTIVE PRODUCT

At the time of this occurrence, Defendant was engaged in the business of designing, manufacturing and marketing automobiles, including the one made the basis of this claim, for

2382-025 20332

CK
4/3/97

sale to and for use by members of the general public. Plaintiff would show that the automobile in question (V.I.N. 2FACP73W6NX155863) was defective and unsafe for its intended purposes at the time it left the control of Defendant, in that it was defectively designed and/or manufactured in a manner which made the product unreasonably and inherently dangerous. Plaintiff would further show that the automobile in question was defectively marketed by Defendant in that Defendant failed to adequately warn or instruct consumers, including Plaintiff, of the dangers associated with the product.

IV. STRICT PRODUCT LIABILITY

Plaintiff invokes the doctrine of strict liability, Section 402A, RESTATEMENT (SECOND) OF TORTS, as adopted by the Supreme Court of Texas. Plaintiff alleges that Defendant is strictly liable for designing, manufacturing and marketing the automobile into the stream of commerce when the product was unreasonably dangerous. The defective design, manufacture and/or marketing of the automobile was the proximate cause of the occurrence and of Plaintiff's damages.

Plaintiff would further show that Defendant is strictly liable to Plaintiff under 402B of the RESTATEMENT (SECOND) OF TORTS for misrepresenting that the product was safe and without defect. These representations were false and involved a material fact concerning the character or quality of the automobile. Plaintiff would show that he relied on these representations and that Defendant's misrepresentations were the proximate cause of the occurrence and of Plaintiff's damages.

V. NEGLIGENCE

Plaintiff alleges that Defendant was negligent in the design, manufacture and/or

marketing of the automobile, in that Defendant knew, or in the exercise of ordinary care, should have known, that the automobile was defective and unreasonably dangerous to ultimate consumers. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of the occurrence and of Plaintiff's damages.

VI.
RES IPSA LOQUITUR

In that alternative, Plaintiff would further show that he cannot more specifically allege the specific acts of negligent design and manufacture on the part of Defendant, for the reason that the facts in that regard are peculiarly within the knowledge of Defendant, and in the event Plaintiff is unable to prove specific acts of negligent design and manufacture, Plaintiff relies on the doctrine of *res ipsa loquitur*. In this connection, Plaintiff will show that the design and manufacture of the automobile were within the exclusive control of Defendant. Plaintiff had no means of ascertaining the method or manner in which the automobile was designed or manufactured by Defendant. Plaintiff would show that the product came into his possession in the same condition it was in when it left the control of Defendant. The occurrence causing harm to Plaintiff was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of Plaintiff's damages.

VII.
BREACH OF WARRANTY

Plaintiff further alleges that Defendant expressly and impliedly warranted to the public that the automobile was of merchantable quality and was safe and fit for the purposes intended when used under ordinary conditions and in an ordinary manner. Plaintiff would show that Defendant's breach of these warranties were the proximate cause of the occurrence

and of Plaintiff's damages. TEX. BUS. & COM. CODE Sec. 2.314 - 2.315, Sec. 17.50

(a)(2), (Vernon 1989). Plaintiff would further show that Defendant is liable for all attorney fees pursuant to §38.001 of the Texas Civil Practice & Remedies Code.

VII.
DECEPTIVE TRADE PRACTICES ACT

Plaintiff would show that Defendant is also liable for violations of the Texas Deceptive Trade Practices and Consumer Protection Act ("DTPA"), including:

- A. Representations that the product in question, and its component parts, possessed qualities, characteristics, uses and benefits which they did not possess - [TEX. BUS & COM. CODE §17.46(5), (Vernon 1990)];
- B. Representations that the product in question, and its component parts, were merchantable when, in fact, they were not fit for the ordinary purposes for which such products were to be used - [TEX. BUS & COM. CODE §17.46(19), (Vernon 1990)];
- C. Failing to disclose information concerning dangers of the automobile known to Defendant, when such failure was intended to induce the consumer to purchase the product - [TEX. BUS & COM. CODE §17.46(22), (Vernon 1990)];

The above acts and/or omissions of Defendant were a proximate cause of the occurrence and of Plaintiff's \$11,026.63 damage to his real and personal property.

Pursuant to the common law of Texas and to the various statutes referenced herein, Defendant is liable to Plaintiff for actual and treble damages, interest, court costs, and reasonable attorney fees.

WHEREFORE, PREMISES CONSIDERED, Plaintiff requests that Defendant be cited to appear and answer, and that on final trial, Plaintiff have:

- 1. Judgment against the defendant for a sum in excess of the minimum jurisdictional limits of the Court;
- 2. Pre-judgment interest and post-judgment interest as provided by law;
- 3. Costs of suit;

4. Attorney fees;
5. Such other and further relief to which the she may be justly entitled.

Respectfully submitted,

LAW OFFICES OF RICHARD B. GEIGER
1513-C West Sixth Street
Austin, Texas 78703
(512) 320-8844 - Telephone
(512) 320-8854 - Facsimile

By:

Rich Geiger (w/permission EP)
Richard B. Geiger
State Bar No. 07791980

Erik Peters
State Bar No. 00791432

ATTORNEY FOR PLAINTIFFS




Fire Investigation & Remains Evaluation

P.O. Box 154086

Irving, Texas 75015-4086

(214) 254-2075 Pager (214) 909-7245

FAX (214) 253-1583

COPY

REC'D BY VJH
CC CSO

AUG 22 1996

RECEIVED

AUG 28 1996

VICTORIA CS

August 19, 1996

F.I.L.E. # 150BB96

First Report

CLIENT:

V. J. Harper, II
State Farm Insurance Companies
P. O. Box 270550
Corpus Christi, Texas 78427

INSURED:

[REDACTED]

INSURED VEHICLE:

1992 Ford Crown Victoria
VIN: 2FACP73W6NX155863

DATE OF FIRE:

6/10/96

POLICY #:

[REDACTED]

CLAIM #:

[REDACTED]

This report is prepared for the above named client. Release to any other person, company, or agency **MUST** be approved by the client or covered by applicable disclosure laws.

ERG2-625 28337



150BB96

1.

ASSIGNMENT

This assignment was received July 15, 1996 at 1:16 p.m. via FAX from Property Claim Trainer Michael Huck with instructions to conduct a vehicle fire cause examination. Investigation commenced 8/14/96.

ENCLOSURES

1. 29 vehicle photographs

INSURED PROPERTY



The risk is a dark blue, 1992 Ford Crown Victoria, four door sedan bearing Texas license plate PCW-68Z. The vehicle identification number is 2FACP73W6NX155863. The car is powered by a large displacement, fuel injected, V-8 motor and automatic transmission. It is equipped with power steering, power brakes, electric door locks and windows, dash mounted radio, cruise control and all season heating and air conditioning. All four tires and simulated wire wheel hubcaps were still on the vehicle. The body was straight and I saw no evidence of prior collision damage. According to the odometer, there were 58,865 miles on the car.

VEHICLE EXAMINATION

NOTE: All references to sides and corners are made as if you were sitting in the driver's seat.



150BR96

2

A vehicle fire cause examination was conducted on Wednesday, 8/14/96 commencing at 12:45 p.m. at the Insurance Auto Auctions storage and sale facility, 4701 Agnes Street, Corpus Christi, Texas. The risk was photographed and diagrammed at that time. There were no adverse conditions or appreciable alterations to the car, therefore, a true and accurate fire cause determination was possible. I was the only person present during this portion of the investigation.

From an exterior examination it was almost impossible to tell a fire had occurred. None of the exterior paint was burned or blistered and all window glass was still intact. Once the hood was raised, a minor amount of paint damage and heat stress was present on the underside, near the right front corner (photo #7).

Even with the hood open it was difficult to tell a fire had occurred until some significant burning to the right front inner fender well was noted (photo #8). This corresponds with the damaged paint and heat stress to the underside of the hood. Virtually all combustibles, including hoses, belts, plastic parts and wiring insulation, were still intact. This was especially true on the left side of the engine compartment where no burning was noted to any of the various components (photo #9).

The left side was the area where the rubber fuel lines and quick-connectors were routed. They were attached to the fuel rail on the left side of the motor and had obviously not received any fire damage (photo #10). It has been my experience that fires caused by an electrical defect or malfunction are much more centralized than those involving flammable or combustible liquids. Even the fire damage on the right side of the V-8 motor was minimal (photo #11).

All of the burning was clearly localized to the extreme, right front corner of the engine compartment (photo #12). The twelve volt battery had been removed prior to my examination but I did not see any localized burning to the battery tray or nearby sheet metal (photo #13). The most intense burning was clearly localized around the forward end of an electrical block and fuse panel. I did see that one of the bare wires had become unattached from a fitting or connection (photo #14).

The wires were closely examined; however, I did not see any evidence of arcing or shorting on the bare copper conductors. The separated end is the only evidence of



150BB96

3.


separation possibly due to an arc or short circuit. A check of a repair manual indicated the correct name for the electrical block/fuse panel was the "electrical distribution box". It had apparently been bolted to the inner fender well as the mounting studs and nuts were still attached (photo #15).

When the electrical distribution box was picked up and more closely examined, I saw an eyelet, solderless terminal, attached to a large electrical lug, was the area where the separated wire had been connected (photo #16). The interior of the electrical distribution box also exhibited fairly heavy fire damage (photo #18).

Once the fuse box cover was removed, it was evident the only fire damage was to two of the large fuses on the rear of the panel (photo #19). The bottom cover was removed from the electrical distribution box at which time I noted an interior cover was burned approximately half way off (photo #20). The burning to the underside of the component was clearly localized with fire damage to three of the wires (photo #21).

A check of the fuse panel revealed two of the blade type fuses had blown. In this instance, the short circuit was sufficient to "weld or bond" one of the fuse legs to the mounting slot. These fuses were removed which confirmed the heavy damage to each one (photos #23 & 24).

After more of the plastic case, on the power distribution block, was removed, burning was noted to the base of the fuse receptacles. This is clearly internal, localized heating coming from a wire or connection on the power distribution box. In this instance, I feel an arc or spark occurred between the wire attached to the electrical lug with the eyelet, solderless, terminal (photo #29). The following conceptual diagram shows the engine compartment of the risk, the location of the power distribution box and the specific area where the fire originated.



BB2-025 28348



150BB96

4.

DETERMINATION OF FIRES CAUSE

Based on physical evidence remaining on the vehicle and information obtained from various sources, it is my opinion this was an accidental fire. It occurred from an unspecified defect or malfunction which caused an overheating condition within the wiring or connections in the electrical distribution box.

COMMENTS

With the completion of my investigation, I feel the cause of this fire has been well documented. The minor amount of burning is clearly centered around the power distribution box and the area where the wire came off the solderless terminal could have caused resistance heating or a short circuit. Although this car was approximately four years old, it appeared to be in very good shape and I saw no evidence of abuse, neglect, alterations or non-OEM parts. If the electrical system, specifically the power distribution box, has not been worked on then whatever caused this fire was built into the car at the assembly plant.

Although no additional investigation is anticipated, I am leaving this file open for 30 days to allow you sufficient time for review and evaluation. If either yourself or Mr. Huck have any further instructions, questions or information, please feel free to call at anytime. As always, I can be contacted through my Irving, Texas office or my digital pager.

Respectfully Submitted,

Byron R. Bryson
Byron R. Bryson, C.F.E.I.
For the Firm



Enclosures

BRB/db

0002-025 20341



150BB96

5. [REDACTED]

PHOTOGRAPHS

1. Front of fire damaged 1992 Ford Crown Victoria.
2. Right front corner of involved vehicle.
3. Right rear corner of involved vehicle.
4. Left rear corner of involved vehicle.
5. Left front corner of involved vehicle.
6. Undamaged paint on exterior surface of the hood.
7. Minor damage and heat stress on right front corner of hood.
8. Fire damage in engine compartment and to V-8 motor.
9. Undamaged combustible components on left side of V-8 motor.
10. Close up of fuel supply hoses and quick-connectors.
11. Burning on right side of V-8 motor.
12. Isolated fire damage in right front corner of engine compartment.
13. Isolated fire damage in right front corner of engine compartment.
14. Burning to electrical distribution box. NOTE separated end of wire.
15. Side of electrical distribution box and mounting studs.
16. End of solderless terminal where wire had been connected.
17. Fire damaged wires within area of origin.
18. Close up of burning inside distribution box.



150BB96

6.

PHOTOGRAPHS

19. Fire damage to fuses in electrical distribution box.
20. Burning to lower cover on electrical distribution box.
21. Burning to under side of electrical distribution box.
22. Burning to under side of electrical distribution box. NOTE loose wire was replaced in approximate area prior to fire.
23. Blown and damaged fuse.
24. Blown and damaged fuse.
25. Close up of damage to fuses in electrical distribution box.
26. Localized burning to end of electrical distribution box.
27. Localized burning to end of electrical distribution box.
28. Internal burning in electrical distribution box.
29. Internal burning to electrical distribution box.

1982-025 29343

F. I. R. E.
PHOTOGRAPHS

No. 1




No. 2




FIRE
PHOTOGRAPHS

No. 3




No. 4



F.I.R.E.
PHOTOGRAPHS

No. 5



No. 6



F.I.R.E.
PHOTOGRAPHS

No. 7




No. 8




F.I.R.E.
PHOTOGRAPHS

No. 9



No. 10



EP82-825 28348

FIRE
PHOTOGRAPHS

No. 11



No. 12



F.I.R.E.
PHOTOGRAPHS

No. 13



No. 14



FIRE
PHOTOGRAPHS

No. 15



No. 16



ENG-825 29381

F. I. R. I. E.
PHOTOGRAPHS

No. 17




No. 18



END-028 20362

F.I.R.E.
PHOTOGRAPHS

No. 19



No. 20



F. I. R. E.
PHOTOGRAPHS

No. 21



No. 22



FIRE
PHOTOGRAPHS

No. 23




No. 24




F.I.R.E.
PHOTOGRAPHS

No. 25




No. 26



F.I.R.E.
PHOTOGRAPHS

No. 27



No. 28



F.I.R.E.
PHOTOGRAPHS

No. 29



PROPERTY 1.5.6.3

[illegible]

2-22-2006

[illegible]

DEALER

52L 328 | VW 2FACP78W6NX155863

DEALER'S PRICE

JANUARY

BATCH-ID 8246000008 D TA AA
PRICE LEVEL 212130P75

VIN: 2FACP78W6NX155863

REQUESTOR: MMASON5

CASE: DELCADO

THIS INVOICE MAY NOT REFLECT THE FINAL COST OF THE VEHICLE BECAUSE OF THE POSSIBILITY OF FUTURE REBATE, ALLOWANCE, CREDITORS AND BONUS/REBATES FROM FORD MOTOR COMPANY TO THE DEALER. * THIS PORTION OF THE VEHICLE PRICE WILL BE PROVIDED TO THE APPROPRIATE FORD BANK TO SUPPORT REGIONAL/DEALER ADVERTISING.					
INVOICE NUMBER	INVOICE TOTAL	NET CHECK FOR FORD ACCOUNT	DEALER CREDIT FOR FORD ACCOUNT	DEALER CREDIT FOR FORD ACCOUNT	A PLAN

SOLD TO
MC LARTY FORD INC FOR ARI
P.O. BOX 5039
MT LAUREL NJ 08054

52L328

FURTHER TERMS
ON REVERSE
SIDEPLT RLSE DTE
08/15/91
RK85

SHIP TO (IF OTHER THAN ABOVE)

28056

CHAMPION FORD, INC.
5778 BUSINESS PARK DRIVE
SHREVEPORT LA 71105

SHIP THROUGH

DATE OF DELIVERY
08/08/91ITEM NUMBER
52-2199ITEM PRICE
14

INVOICE & UNIT IDENTIFICATION NO.

FORD ASSEMBLY POINT

FINANCIAL COMPANY AND/OR BANK

2FACP78W6NX155863

ST. THOMAS

PHILADELPHIA NATIO 038808

THIS INVOICE IS TO BE USED FOR THE BILLING OF VEHICLES ONLY

DEALER COPY

FINANCIAL - 52L - 42054 (8/91)

52L-425 23368

DEALER 52L 328 1VN 2FACP73W6NX155863

	EXAMINED RETAIL PRICE	PROFIT
1992 CROWN VIC 4-DR SEDAN	18728 00	14154 00
NK TWILIGHT BLUE CLEARCOAT		
ZY SHADOW BLUE CLOTH		
PREFERRED EQUIPMENT PKG.111A	1923 00	1435 00
57Q REAR WINDOW DEFROSTER		
12H FRONT CARPETED FLOOR MATS		
12Q REAR CARPETED FLOOR MATS		
47J ILLUMINATED ENTRY SYSTEM		
943 LIGHT/DECOR GROUP		
903 POWER LOCK GROUP		
58H AM/FM STEREO RADIO W/CASSETTE		
18K REMOTE RELEASE FUEL DOOR		
122 SPARE TIRE COVER		
15C TRUNK CARGO NET		
643 RADIAL SPOKED WHEEL COVERS		
21A 4-WAY POWER DRIVER'S SEAT		
525 SPEED CONTROL		
LEATHER-WRAP STEERING WHEEL		
99W 4.6L OHC SEFI V8 ENGINE	NC	NC
44T AUTO OVERDRIVE TRANSMISSION	NC	NC
T37 P215/70R15 BSW TIRES	NC	NC
153 FRONT LICENSE PLATE BRACKET	NC	NC
TOTAL VEHICLE & OPTIONS	20651 00	17789 00
DESTINATION & DELIVERY	535 00	535 00
TOTAL BEFORE DISCOUNTS	21186 00	18324 00
**SPECIAL ADDED DISCOUNTS*	376 00-	319 00-

TOTAL FOR VEHICLE 20810 00

10 U.S. GAL GAS FACTORY 14 00
 NATIONAL FLEET INCENTIVE 1000 00-
 FLEET P.O. NUMBER 99411
 BATCH-ID 5266000008 D TA AA
 SCHEDULE-B LEVEL 00000
 PRICE LEVEL 212150P73 VIN: 2FACP73W6NX155863
 SHIPPING WEIGHT 3593 LBS.

THIS INVOICE MAY NOT REFLECT THE FINAL COST OF THE VEHICLE IN VIEW OF THE POSSIBILITY OF FUTURE REBATES, ALLOWANCES, DISCOUNTS AND BONUS AWARDS FROM FORD MOTOR COMPANY TO THE DEALER.					
* THE PORTION OF THE USABLE PRICE WILL BE PROVIDED TO THE APPROPRIATE FORD LMDA TO SUPPORT REGIONAL DEALER ADVERTISING.					
REGIONAL ADVERTISING	INVOICE TOTAL	LESS FORD MOTOR COMPANY ALLOWANCE	LESS FORD MOTOR COMPANY BONUS	LESS FORD MOTOR COMPANY REBATE	A PLAN
195.00	17,214.00	609.00	235.00	16,370.00	

609.00 47.00 1316.00 1000.00- 562.80 15919.00

SOLD TO		FURTHER TERMS ON REVERSE SIDE		PLT RLSE DTE	
MC LARTY FORD INC FOR ARI		52L328		08/13/91	
P.O. BOX 5039				RK58	
MT LAUREL NJ 08054					
SHIP TO (IF OTHER THAN ABOVE)		23034		DATE FOR PAYMENT	
CHAMPION FORD, INC.				52-9199	
8770 BUSINESS PARK DRIVE				TY 14	
SHREVEPORT LA 71105		SHIP THROUGH			

OFFICIAL & UNIT IDENTIFICATION NO. 2FACP73W6NX155863 FINAL ASSEMBLY POINT ST. THOMAS PHILADELPHIA NATIO 030004
 THIS INVOICE IS TO BE USED FOR THE BILLING OF VEHICLES ONLY DEALER COPY

5262-525 23061

CAUSE NO. 233550

██████████ AND
Plaintiffs

v.
FORD MOTOR COMPANY
Defendant

§
§
§
§
§
§
§

IN THE COUNTY COURT

AT LAW NUMBER

TRAVIS COUNTY, TEXAS

FILED
96 DEC -5 PM 4:44
CLERK OF DISTRICT COURT
TRAVIS COUNTY, TEXAS

ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

COME NOW ██████████ and ██████████ ("Plaintiffs") and file this Original
Petition against Ford Motor Company ("Defendant") and for cause would show the following:

I.
PARTIES

Plaintiffs are individuals residing in the State of Texas.

Defendant is a company duly licensed and doing business in the State of Texas. It may
be served through its registered agent for service of process, CT Corporation Systems, 350
North St. Paul Street, Dallas, TX 75201.

II.
BACKGROUND FACTS

On June 10, 1996, Plaintiffs' 1992 Ford Crown Victoria caught fire due to a defect or
malfunction causing an overheating condition within the wiring or connections in the electrical
distribution box. As a result of this, Plaintiffs sustained \$11,026.63 in damages.

III.
DEFECTIVE PRODUCT

At the time of this occurrence, Defendant was engaged in the business of designing,
manufacturing and marketing automobiles, including the one made the basis of this claim, for

sale to and for use by members of the general public. Plaintiff would show that the automobile in question (V.I.N. 2FACP73W6NX155863) was defective and unsafe for its intended purposes at the time it left the control of Defendant, in that it was defectively designed and/or manufactured in a manner which made the product unreasonably and inherently dangerous. Plaintiff would further show that the automobile in question was defectively marketed by Defendant in that Defendant failed to adequately warn or instruct consumers, including Plaintiff, of the dangers associated with the product.

IV. STRICT PRODUCT LIABILITY

Plaintiff invokes the doctrine of strict liability, Section 402A, RESTATEMENT (SECOND) OF TORTS, as adopted by the Supreme Court of Texas. Plaintiff alleges that Defendant is strictly liable for designing, manufacturing and marketing the automobile into the stream of commerce when the product was unreasonably dangerous. The defective design, manufacture and/or marketing of the automobile was the proximate cause of the occurrence and of Plaintiff's damages.

Plaintiff would further show that Defendant is strictly liable to Plaintiff under 402B of the RESTATEMENT (SECOND) OF TORTS for misrepresenting that the product was safe and without defect. These representations were false and involved a material fact concerning the character or quality of the automobile. Plaintiff would show that he relied on these representations and that Defendant's misrepresentations were the proximate cause of the occurrence and of Plaintiff's damages.

V. NEGLIGENCE

Plaintiff alleges that Defendant was negligent in the design, manufacture and/or

marketing of the automobile, in that Defendant knew, or in the exercise of ordinary care, should have known, that the automobile was defective and unreasonably dangerous to ultimate consumers. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of the occurrence and of Plaintiff's damages.

VI.
RES IPSA LOQUITUR

In that alternative, Plaintiff would further show that he cannot more specifically allege the specific acts of negligent design and manufacture on the part of Defendant, for the reason that the facts in that regard are peculiarly within the knowledge of Defendant, and in the event Plaintiff is unable to prove specific acts of negligent design and manufacture, Plaintiff relies on the doctrine of *res ipsa loquitur*. In this connection, Plaintiff will show that the design and manufacture of the automobile were within the exclusive control of Defendant. Plaintiff had no means of ascertaining the method or manner in which the automobile was designed or manufactured by Defendant. Plaintiff would show that the product came into his possession in the same condition it was in when it left the control of Defendant. The occurrence causing harm to Plaintiff was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of Plaintiff's damages.

VII.
BREACH OF WARRANTY

Plaintiff further alleges that Defendant expressly and impliedly warranted to the public that the automobile was of merchantable quality and was safe and fit for the purposes intended when used under ordinary conditions and in an ordinary manner. Plaintiff would show that Defendant's breach of these warranties were the proximate cause of the occurrence

and of Plaintiff's damages. TEX. BUS. & COM. CODE Sec. 2.314 - 2.315, Sec. 17.50

(a)(2), (Vernon 1989). Plaintiff would further show that Defendant is liable for all attorney fee's pursuant to §38.001 of the Texas Civil Practice & Remedies Code.

VII.

DECEPTIVE TRADE PRACTICES ACT

Plaintiff would show that Defendant is also liable for violations of the Texas Deceptive Trade Practices and Consumer Protection Act ("DTPA"), including:

- A. Representations that the product in question, and its component parts, possessed qualities, characteristics, uses and benefits which they did not possess - [TEX. BUS & COM. CODE §17.46(5), (Vernon 1990)];
- B. Representations that the product in question, and its component parts, were merchantable when, in fact, they were not fit for the ordinary purposes for which such products were to be used - [TEX. BUS & COM. CODE §17.46(19), (Vernon 1990)];
- C. Failing to disclose information concerning dangers of the automobile known to Defendant; when such failure was intended to induce the consumer to purchase the product - [TEX. BUS & COM. CODE §17.46(22), (Vernon 1990)];

The above acts and/or omissions of Defendant were a proximate cause of the occurrence and of Plaintiff's \$11,026.63 damage to his real and personal property.

Pursuant to the common law of Texas and to the various statutes referenced herein, Defendant is liable to Plaintiff for actual and treble damages, interest, court costs, and reasonable attorney fees.

WHEREFORE, PREMISES CONSIDERED, Plaintiff requests that Defendant be cited to appear and answer, and that on final trial, Plaintiff have:

- 1. Judgment against the defendant for a sum in excess of the minimum jurisdictional limits of the Court;
- 2. Pre-judgment interest and post-judgment interest as provided by law;
- 3. Costs of suit;

4. Attorney fees;
5. Such other and further relief to which the she may be justly entitled.

Respectfully submitted,

LAW OFFICES OF RICHARD B. GEIGER
1513-C West Sixth Street
Austin, Texas 78703
(512) 320-8844 - Telephone
(512) 320-8854 - Facsimile

By:

Rich Geiger (w/permission EP)
Richard B. Geiger
State Bar No. 07791980

Erik Peters
State Bar No. 00791432

ATTORNEY FOR PLAINTIFFS



အမည်အသံအသံအသံ	11	555555555555	9999999999	3333333333	555555555555	AAAAA
အမည်အသံအသံအသံ	111	555555555555	999999999999	333333333333	555555555555	AAAAA
အသံ	1111	55	99	33	55	AA
အသံ	11	55	99	33	55	AA
အသံ	11	55	99	33	55	AA
အသံ	11	5555555555	9999999999	3333	55555555	AAAAA
အသံ	11	5555555555	9999999999	3333	5555555555	AAAAA
အသံ	11	55	99	33	55	AA
အသံ	11	55	99	33	55	AA
အသံ	11	55	99	33	55	AA
အသံ	11111111	555555555555	999999999999	333333333333	555555555555	AAAAA
အသံ	1111111111	555555555555	999999999999	333333333333	555555555555	AAAAA

A START	J0815935	060816AD	RV539236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV939236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV939236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV815936	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815936	START	A
A START	J0815935	060816AD	RV539236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A
A START	J0815935	060816AD	RV839236	ROOM	11.44.23	AM	28	DEC	96	R0541027	STAL	ACCTWS	J0815935	START	A

```
*****
*
*
* *****
*   GENERATED BY:
*   CHRISTIE LOPE
*
*   PHONE: 313-845-8714
*
*   JOB: ODELEAD
*
*   JOBDATE: 12/28/96
*
*   TIME: 18:50:55
*
*
* *****
```

EXERCISE 2.7

TRIPOLIS HISTORY (JUL-21) 1442

```
* MODEL YEAR          = 81
* CUT-OFF DATE        = 12/30/76
* REPORT TITLE        [REDACTED]
* VEHICLE TYPE        = CAR
* REPORT CLAIM TYPE    = ALL CLAIMS
* OUTPUT FILE NAME     = C080136.DELGADO.SERISERY.REPORT
* REPORT SORT SEQUENCE = WANT CODE \ SERIAL NO
* PAGE ON PRIMARY SORT=
* WANTO MIS VALUE      =
* PLANT/SERIAL NUMBER  = X18551
```

877-333-2644

2000000
PAGE 2.01

1992 SN-11 PARTS BY CONCHAM CODE (OLD CONDITION CODE) SUMMARY (12NOV96 C/O)
DATA ORDERED BY DESCENDING PART NO. FREQUENCY
DELEADO CHRISTIE LONG

PART NO	CC	COUNT
10004	1M	1
140003	41	1
6108	84	1
7F310	08	1

ENCLOSURE

3408014
Page 2.01

1992 AB-11 PARTS BY CUSTOMER CONCERN COOL SUMMARY [12NOV94 C/D]
DATA ORDERED BY DESCENDING PART NO. FREQUENCY
CHRISTIE LONG

PART NO	CCC	COUNT
14684	ANY	1
148089	ANY	1
8108	ANY	1
77228	F01	1

0002-000 20070

1508074
PAGE 4.01

1972 SE-II PARTS BY CONDITION CODE SUMMARY (LHNUV6 C/O)
DATA ORDERED BY DESCRIBING PART NO. FREQUENCY
CHRISTIE LONG

PART NO	CD	COUNT
10854	15	1
14808	41	1
6108	56	1
77330	85	1

DMC-620 28371

20DEC95
PAGE 5.01

1992 SR-17 PART/CONCERN CODE DESCRIPTION SUMMARY (12NOV96 C/O)
DATA ORDERED BY DESCENDING REPAIR COUNT

RELIANT CHRISTIE LONG

NUMBER	PART DESCRIPTION	COUNT	CC-DESCRIPTION	COUNT	CC-DESCRIPTION	COUNT	CCC-DESCRIPTION	COUNT
10624	BATTERY	1	02-OTHER/UNKNOWN	1	02-OTHER/UNKNOWN	1	ANY-NO CODE PROVIDED	3
140083	RELAY ASSY	1	15-WILL NOT HOLD CHARGE	1	15-DEAD/WEAK BATT	2	PS1-BAUD TO SHFT	1
5100	PINTON & PIN ARM	1	41-STEER, STEER, CHASS, ETC	1	41-STEER/STEER/TOGT	1		
77330	INEL TR THEROT VALVE	1	56-NOISE, RATTLE, SQUEAKS	1	56-NOISE OPERATION	1		

2002-025 20072

XXXXXXXX	XXXXXXXX	XXXXXX	XXXXXX	XXXXXXXX	XX	XX	XX	XX	XX	XXXXXXXX	XXXXXXXX	XX	XX
XXXXXXXX	XXXXXXXX	XXXXXX	XXXXXX	XXXXXXXX	XX	XX	XX	XX	XX	XXXXXXXX	XXXXXXXX	XX	XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XXXXXXXX	XXXXXX	XXXX	XX	XX	XX	XX	XX	XX	XX	XXXXXXXX	XXXXXXXX	XX	XX
XXXXXXXX	XXXXXX	XXXX	XX	XX	XX	XX	XX	XX	XX	XXXXXXXX	XXXXXXXX	XX	XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XXXXXXXX	XXXXXXXX	XXXXXX	XXXXXX	XXXXXXXX	XX	XX	XX	XX	XX	XX	XX	XX	XX
XXXXXXXX	XXXXXXXX	XXXXXX	XXXXXX	XXXXXXXX	XX	XX	XX	XX	XX	XX	XX	XX	XX

 * CLAIMS LISTING FOR 199X MODEL ***** REQUESTED BY: CHRISTIN LONG 12NOV96 C/O *
 * SORTED BY: PLATCODE SERIALNO MILEAGE DATA SOURCE: PAMS SE-II *****

 SUMMARY

 TOTALS ***** RATION *****

CLAIMS	W/COMPTS	IN TIS	VEHICLES	DEALERS	MATERIAL COST	TOTAL COST	CLAIMS PER VEHIC	CLAIMS PER DEAL	CLAIMS TOTL/DEAL	MATERIAL COST/REP	TOTAL COST/REP	PCT CLAIMS W/COMPTS
4	3	4	1	1	\$289.85	\$1,546.85	4.00	2.00	1.00	\$97.34	\$386.72	60%

***** CLAIMS LISTING TITLE ABBREVIATIONS *****

SERIAL	CAR	D/S	TIS	PAT	FROM	DATE	DATE	DEAL	CLAIM	MICRO	C	MOC	PART	CC	CC	CD	DATE	T	TRACT	MILE	MATL	TOTL	LR	DATE	ST
NUMBER	LEN		CHI	MAN	DATE	DATE	DEAL		NUMBER	NUMBER	S	NUMBER													
123456	ABC	30T	88H	WAY	77NOV91	04FEB92	12112		123456	JHP34001	7F04	17A552	46	C06	46	22AHP52	8*	886	10188	11.25	123	0.1	12345	MT	

CARD SEQUENCE NO.-->
 CONVEN CODE(OLD CONDITION CODE)-->
 <--SAMPLE INDICATOR(YES,NO) CUSTOMER CONCERN CODE-->
 CONDITION CODE-->
 TIME IN SERVICE-->
 <--TRANSACTION CODE-PAY PAYMENT MOY-->
 <-- IF THIS ASTERISK APPEARS THEN CLAIM IS NOT USED IN TIS MATRIX. ('CLAIMS IN TIS' TOTAL (IN SUMMARY ABOVE) EQUALS TOTAL CLAIM COUNT MINUS ASTERISK TIS CLAIMS)

***** ENGINE CODES ***** <--TRANSMISSION CODES-->
 C = 2.3EFI-PROBE U = 3.0EFI A = 2000
 E = 5.0EFI-NO W = 4.6EFI-DOHC D = 17E (BATAVIA)
 H = 1.8EFI-FESTIVA X = 3.3EBC D = 17E (5 SPEED)
 J = 1.9EFI Y = 3.0EFI-SHO E = 17E (4 SPD-4 EAT)
 L = 2.3EFI-TURBO-PRE H = 1.6EFI-CAPRI L = 3400
 M = 2.3EFI-TWIN PLUG Z = 3.2EFI-PHD M = 17E (3 SPD FESTIVA)
 R = 3.2EFI-SUPERCAR 4 = 3.2EFI-RED P = 1000 (ELECTRONIC)
 T = 5.0EFI-NO LO-PRO 6 = 1.6EFI-TURB-CAPRI T = 400
 S = 1.6EFI-DOHC W = 17E (5 SPEED)
 X = 17E (4 SPD-AUTO-7A/CP)
 Z = 5.0EFI (75-MUSTANG)
 4 = 17E (4 SPD-4 EAT)
 5 = 5.0EFI (T-BIRD S.C.) 7 = 17E (5 SPD PRG/CAS)

EM2-425 28073

2808098 CLAIMS LISTING FOR 1992 MODEL [REDACTED]
 PAGE 1 SORTED BY PARTCODE SERIALNO WIL8882

1280V94 C/O REQUESTED BY: CHRISTIE LONG
 DATA SOURCE: PAGE 58-II K53488

NOTE: IF TIS VALUE HAS (*) THEN CLAIM NOT USED IN TIS MATRIX

VEHICLE INFORMATION						REPAIR INFORMATION																				
SERIAL	CAR	5/8	STG	PLT	WROD	YEAR	SELL	CLAIM	MICRO	C	WCE	PART	CC	CC	CC	REPR	T	TACT	MILES	MAIL	TOTL	LR	REPR	WT		
NUMBER	LINE	CCI	REN	DATE	DATE	DEAL	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER	DATE	IS	CODE	COST	COST	RES	DEAL				
155863	FED	4-L	WTY	STX	12AUG91	28AUG91	86025	884354	MOE17121	1802	6108	84	ANT	54	02DEC91	4	2	10781	221.29	519	9.0	06450	LA			
** COMMENTS-CLAIM #1																										
EACH-M TIME, TIME TO TRANSFER INSTANT MANIFOLD AND ENGINE WIRING HARNESSES FROM OLD E																										
155863	FED	4-L	WTY	STX	12AUG91	28AUG91	06828	026138	MOE45511	7851	18654	15	ANT	15	13JUN91	4	2	18718	54.42	90	0.8	06450	LA			
155863	FED	4-L	WTY	STX	12AUG91	28AUG91	06825	035157	MOE17141	7C85	14888	41	ANT	41	14DEC91	4	2	18794	9.38	48	0.9	06450	LA			
155863	FED	4-L	WTY	STX	12AUG91	28AUG91	06825	061922	MOE20121	3C81	7F130	08	PS1	08	28NOV94	40	5383	39297	92.23	788	2.4	04403	TX			
** COMMENTS-CLAIM #4																										
CCKK-OVERDRIVE SLIPPING.																										
EACH-TRANS WAS NO OVERDRIVE. SENT TRANS OUT FOR REPAIRS. REINSTALL TRANS., NEW TORQUE CONVERTOR, BEARS BY																										
EACH-SHIMS AND CLIP TO TV THROTTLE LINKAGE.																										

THIS LISTING CONTAINED 4 TOTAL CLAIMS

800-425 28078

[illegible]

A END	JOB15935	OSHELAND	RVS39236	ROOM	11.44.26	AM	20	DEC	96	80541027	STAL	ACCTING	JOB15935	END	A
A END	JOB15935	OSHELAND	RVS39236	ROOM	11.44.28	AM	20	DEC	96	80541027	STAL	ACCTING	JOB15935	END	A
A END	JOB15935	OSHELAND	RVS39236	ROOM	11.44.28	AM	20	DEC	96	80541027	STAL	ACCTING	JOB15935	END	A
A END	JOB15935	OSHELAND	RVS39236	ROOM	11.44.26	AM	20	DEC	96	80541027	STAL	ACCTING	JOB15935	END	A

```

*****
*          E N D                      V P S R6.1 STC: WTPPS                      E N D          *
*****
*
*          JOB / PRINTER IDENTIFICATION          OFF-PRINTER          VPS JOB RELATED PRINT STATISTICS
*
*  JOBNAME: [REDACTED] PRINTER NAME: R0541827  DATE: 06.355  ELAPSED PRINT TIME 00.00.03.66  AVG COMP LINE LGTH (Q)-----88
*  JOBID:   JOB18931 VPR12 NUMBER: RVS39236    PRI 11/20/96  NUMBER LINES PRINTED-----211  AVG COMP LINE LGTH (P)-----107
*                                     TIME: 11.44.26.93  NUMBER PAGES PRINTED-----8  NUMBER VPRN SEEDS-----34
*                                     NUMBER D/S PRINTED-----1  NUMBER STAGING I/O'S-----0
*
*****

```

CSOR0087

MORS II O.R. VIN Customer Selection

12/19/1996 10:42:13

VIN: 2FACP73W6MX155863

Model: CROWN VI

Model Year: 92

To SELECT an O.R. Customer: Type an "X" in the "A" column and Press ENTER

A	S	Acqd	Last Name	First Name	MI	Address	City	St	Zip
---	---	------	-----------	------------	----	---------	------	----	-----

F1=HELP F3=EXIT F7=FIRST F8=NEXT

I223 NO CUSTOMER DATABASE INFORMATION FOR THIS REQUEST

OGDB352

END-028 28377

CSOR0021

NORS II Recall Inquiry

12/19/1996 10:42:23

VIN: 2FACP73W6NK155863

Build Date: 08/12/1991

Y: 92 Model: CROWN VICTORIA

WSD: 08/29/1991

Campaign Number	Campaign Type	1864 Description	Campaign Status	Status Date	Dealer Code
93B31	0	TV ROD BUSEG	COMPLETE	11/28/1994	04409

F3=EXIT

I002 REQUESTED INFORMATION DISPLAYED

OGDB352

EP02-025 20378

CSOR0023

MORE II ESP Inquiry

12/19/1996 10:42:35

VIN: 2FACF73W6NK155863

Year: 92

Model: CROWN VICTORIA

Contract Selling Dealer P&A Code: 04409 Name: LEONARD JOHNSON'S AUTO RANCH

Contract Owner

Street

City

Zip/PC

VICTORIA

ESP INFORMATION:		Plan	Option	Expiration		Signature				
YR	Code	Date	Mi/Km	Date	Rent	Days	Tow	Ded		
95		03/01/1997	66394	03/01/1995	25	5	45	100		

COVERAGE DESCRIPTION: E1995 USED 24/24,000 POWERTRAINCARE

Cancel Date	Processing Date	Dealership Credited Name	P&A	W&P Statement	Percentage of Refund
----------------	--------------------	-----------------------------	-----	------------------	-------------------------

F3=EXIT F7=FIRST F8=NEXT

I112 LAST RECORD DISPLAYED - FORWARD SCROLL NOT ALLOWED

OGDB352

5702-025 28379

CSOR0024

MORS II OASIS Inquiry

12/19/96 10:42:41

VIN: 2FACP73W6NX155863

Year: 92

Model: CROWN VICTORIA

Name:

C b: 218AR00

Build Date: 08/12/1991

Recall Description

Axle: NOT AVAILABLE

WSD: 08/29/1991

NO RECALLS

Engine: 4.6L SOHC (MODULAR)

Trans: AUTOMATIC OD 4 SPEED ONP Count: 0

Message:

ESP INFORMATION:		Plan Option	Expiration		Signature				
YR	Code	Date	Mi/Km	Date	Rent	Days	Tow	Ded	
95		03/01/1997	66394	03/01/1995	25	5	45	100	

COVERAGE DESCRIPTION: E1995 USED 24/24,000 POWERTRAINCARE

F3=EXIT

1002 REQUESTED INFORMATION DISPLAYED

OGDB352

1003-025 26300

CSOR0026

MORS II Warranty Inquiry

12/19/1996 10:42:53

VIN: 2FACP73W6NX155863

Year: 92

Model: CROWN VICTORIA

Name:

P&A
Code

Repairing
Dealer Name

Repair
Date

R.O.
Number Mi/Km

Cond Part
Code Number

Labor
Operation

F3=EXIT F7=FIRST F8=NEXT

1943 NO REPAIR HISTORY ON VEHICLE

OGDB352

EP02-025 28381



Fire Investigation & Remains Evaluation

P.O. Box 154086

Irving, Texas 75015-4086

(214) 254-2075 Pager (214) 909-7245

FAX (214) 253-1583

COPY

REC'D BY VJH
CC CSO

AUG 22 1996

RECEIVED

AUG 23 1996

VICTORIA CSO

August 19, 1996

F.I.R.E. # 150BB96

First Report

CLIENT: V. J. Harper, II
State Farm Insurance Companies
P. O. Box 270550
Corpus Christi, Texas 78427

INSURED: [REDACTED]

INSURED VEHICLE: 1992 Ford Crown Victoria
VIN: 2FACP73W6NX155863

DATE OF FIRE: 6/10/96

POLICY #: [REDACTED]

CLAIM #: [REDACTED]

This report is prepared for the above named client. Release to any other person, company or agency MUST be approved by the client or covered by applicable disclosure laws.

ENR2-025 20382



150BB96

1.

ASSIGNMENT

This assignment was received July 15, 1996 at 1:16 p.m. via FAX from Property Claim Trainer Michael Huck with instructions to conduct a vehicle fire cause examination. Investigation commenced 8/14/96.

ENCLOSURES

1. 29 vehicle photographs

INSURED PROPERTY



The risk is a dark blue, 1992 Ford Crown Victoria, four door sedan bearing Texas license plate PCW-68Z. The vehicle identification number is 2FACP73W6NX155863. The car is powered by a large displacement, fuel injected, V-8 motor and automatic transmission. It is equipped with power steering, power brakes, electric door locks and windows, dash mounted radio, cruise control and all season heating and air conditioning. All four tires and simulated wire wheel hubcaps were still on the vehicle. The body was straight and I saw no evidence of prior collision damage. According to the odometer, there were 58,865 miles on the car.

VEHICLE EXAMINATION

NOTE: All references to sides and corners are made as if you were sitting in the driver's seat.



150BB96

2.

A vehicle fire cause examination was conducted on Wednesday, 8/14/96 commencing at 12:45 p.m. at the Insurance Auto Auctions storage and sale facility, 4701 Agnes Street, Corpus Christi, Texas. The risk was photographed and diagrammed at that time. There were no adverse conditions or appreciable alterations to the car; therefore, a true and accurate fire cause determination was possible. I was the only person present during this portion of the investigation.

From an exterior examination it was almost impossible to tell a fire had occurred. None of the exterior paint was burned or blistered and all window glass was still intact. Once the hood was raised, a minor amount of paint damage and heat stress was present on the underside, near the right front corner (photo #7).

Even with the hood open it was difficult to tell a fire had occurred until some significant burning to the right front inner fender well was noted (photo #8). This corresponds with the damaged paint and heat stress to the underside of the hood. Virtually all combustibles, including hoses, belts, plastic parts and wiring insulation, were still intact. This was especially true on the left side of the engine compartment where no burning was noted to any of the various components (photo #9).

The left side was the area where the rubber fuel lines and quick-connectors were routed. They were attached to the fuel rail on the left side of the motor and had obviously not received any fire damage (photo #10). It has been my experience that fires caused by an electrical defect or malfunction are much more centralized than those involving flammable or combustible liquids. Even the fire damage on the right side of the V-8 motor was minimal (photo #11).

All of the burning was clearly localized to the extreme, right front corner of the engine compartment (photo #12). The twelve volt battery had been removed prior to my examination but I did not see any localized burning to the battery tray or nearby sheet metal (photo #13). The most intense burning was clearly localized around the forward end of an electrical block and fuse panel. I did see that one of the bare wires had become unattached from a fitting or connection (photo #14).

The wires were closely examined; however, I did not see any evidence of arcing or shorting on the bare copper conductors. The separated end is the only evidence of

BB-2-125 20384



150BB96

3.


separation possibly due to an arc or short circuit. A check of a repair manual indicated the correct name for the electrical block/fuse panel was the "electrical distribution box". It had apparently been bolted to the inner fender well as the mounting studs and nuts were still attached (photo #15).

When the electrical distribution box was picked up and more closely examined, I saw an eyelet, solderless terminal, attached to a large electrical lug, was the area where the separated wire had been connected (photo #16). The interior of the electrical distribution box also exhibited fairly heavy fire damage (photo #18).

Once the fuse box cover was removed, it was evident the only fire damage was to two of the large fuses on the rear of the panel (photo #19). The bottom cover was removed from the electrical distribution box at which time I noted an interior cover was burned approximately half way off (photo #20). The burning to the underside of the component was clearly localized with fire damage to three of the wires (photo #21).

A check of the fuse panel revealed two of the blade type fuses had blown. In this instance, the short circuit was sufficient to "weld or bond" one of the fuse legs to the mounting slot. These fuses were removed which confirmed the heavy damage to each one (photos #23 & 24).

After more of the plastic case, on the power distribution block, was removed, burning was noted to the base of the fuse receptacles. This is clearly internal, localized heating coming from a wire or connection on the power distribution box. In this instance, I feel an arc or spark occurred between the wire attached to the electrical lug with the eyelet, solderless, terminal (photo #29). The following conceptual diagram shows the engine compartment of the risk, the location of the power distribution box and the specific area where the fire originated.



ENG-225 28345



150BB96

4.

DETERMINATION OF FIRES CAUSE

Based on physical evidence remaining on the vehicle and information obtained from various sources, it is my opinion this was an accidental fire. It occurred from an unspecified defect or malfunction which caused an overheating condition within the wiring or connections in the electrical distribution box.

COMMENTS

With the completion of my investigation, I feel the cause of this fire has been well documented. The minor amount of burning is clearly centered around the power distribution box and the area where the wire came off the solderless terminal could have caused resistance heating or a short circuit. Although this car was approximately four years old, it appeared to be in very good shape and I saw no evidence of abuse, neglect, alterations or non-OEM parts. If the electrical system, specifically the power distribution box, has not been worked on then whatever caused this fire was built into the car at the assembly plant.

Although no additional investigation is anticipated, I am leaving this file open for 30 days to allow you sufficient time for review and evaluation. If either yourself or Mr. Huck have any further instructions, questions or information, please feel free to call at anytime. As always, I can be contacted through my Irving, Texas office or my digital pager.

Respectfully Submitted,

Byron R. Bryson

Byron R. Bryson, C.F.E.I.

For the Firm



Enclosures

BRB/db

5902-025 20044



150BB96

5. 

PHOTOGRAPHS

1. Front of fire damaged 1992 Ford Crown Victoria.
2. Right front corner of involved vehicle.
3. Right rear corner of involved vehicle.
4. Left rear corner of involved vehicle.
5. Left front corner of involved vehicle.
6. Undamaged paint on exterior surface of the hood.
7. Minor damage and heat stress on right front corner of hood.
8. Fire damage in engine compartment and to V-8 motor.
9. Undamaged combustible components on left side of V-8 motor.
10. Close up of fuel supply hoses and quick-connectors.
11. Burning on right side of V-8 motor.
12. Isolated fire damage in right front corner of engine compartment.
13. Isolated fire damage in right front corner of engine compartment.
14. Burning to electrical distribution box. NOTE separated end of wire.
15. Side of electrical distribution box and mounting studs.
16. End of solderless terminal where wire had been connected.
17. Fire damaged wires within area of origin.
18. Close up of burning inside distribution box.

ER82-825 29487



150BB96

6.

PHOTOGRAPHS

19. Fire damage to fuses in electrical distribution box.
20. Burning to lower cover on electrical distribution box.
21. Burning to under side of electrical distribution box.
22. Burning to under side of electrical distribution box. NOTE loose wire was replaced in approximate area prior to fire.
23. Blown and damaged fuse.
24. Blown and damaged fuse.
25. Close up of damage to fuses in electrical distribution box.
26. Localized burning to end of electrical distribution box.
27. Localized burning to end of electrical distribution box.
28. Internal burning in electrical distribution box.
29. Internal burning to electrical distribution box.

ERG2-625 28388

F.I.R.E.
PHOTOGRAPHS

No. 1




No. 2




SP2-575 28388

F.I.R.E.
PHOTOGRAPHS

No. 3



No. 4



F.I.R.E.
PHOTOGRAPHS

No. 5



No. 6



F.I.R.E.
PHOTOGRAPHS

No. 7



No. 8



F.I.R.E.
PHOTOGRAPHS

No. 9



No. 10



F.I.R.E.
PHOTOGRAPHS

No. 11



No. 12



5002-025 28384

FIRE
PHOTOGRAPHS

No. 13



No. 14



ENC-625 20305

F.I.R.E.
PHOTOGRAPHS

No. 15



No. 16




F.I.R.E.
PHOTOGRAPHS

No. 17




No. 18




**FIVE
PHOTOGRAPHS**

No. 19



No. 20



F.I.R.E.
PHOTOGRAPHS

No. 21



No. 22



F.I.R.E.
PHOTOGRAPHS

No. 23




No. 24




ERG2-826 29468

F.I.R.E.
PHOTOGRAPHS

No. 25




No. 26



EP02-025 29401

FIRE
PHOTOGRAPHS

No. 27




No. 28



F. I. R. E.
PHOTOGRAPHS

No. 29



CAUSE NO. 233550

[REDACTED] AND
Plaintiffs

v.

FORD MOTOR COMPANY
Defendant

§
§
§
§
§
§
§

IN THE COUNTY COURT

AT LAW NUMBER 2

TRAVIS COUNTY, TEXAS

96 DEC -5 PM 1:44
CLERK
TRAVIS COUNTY, TEXAS

ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

COME NOW **[REDACTED]** and **[REDACTED]** ("Plaintiffs") and file this Original
Petition against Ford Motor Company ("Defendant") and for cause would show the following:

I.
PARTIES

Plaintiffs are individuals residing in the State of Texas.

Defendant is a company duly licensed and doing business in the State of Texas. It may be served through its registered agent for service of process, CT Corporation Systems, 350 North St. Paul Street, Dallas, TX 75201.

II.
BACKGROUND FACTS

On June 10, 1996, Plaintiffs' 1992 Ford Crown Victoria caught fire due to a defect or malfunction causing an overheating condition within the wiring or connections in the electrical distribution box. As a result of this, Plaintiffs sustained \$11,026.63 in damages.

III.
DEFECTIVE PRODUCT

At the time of this occurrence, Defendant was engaged in the business of designing, manufacturing and marketing automobiles, including the one made the basis of this claim, for

sale to and for use by members of the general public. Plaintiff would show that the automobile in question (V.I.N. 2FACP73W6NX155863) was defective and unsafe for its intended purposes at the time it left the control of Defendant, in that it was defectively designed and/or manufactured in a manner which made the product unreasonably and inherently dangerous. Plaintiff would further show that the automobile in question was defectively marketed by Defendant in that Defendant failed to adequately warn or instruct consumers, including Plaintiff, of the dangers associated with the product.

IV. STRICT PRODUCT LIABILITY

Plaintiff invokes the doctrine of strict liability, Section 402A, RESTATEMENT (SECOND) OF TORTS, as adopted by the Supreme Court of Texas. Plaintiff alleges that Defendant is strictly liable for designing, manufacturing and marketing the automobile into the stream of commerce when the product was unreasonably dangerous. The defective design, manufacture and/or marketing of the automobile was the proximate cause of the occurrence and of Plaintiff's damages.

Plaintiff would further show that Defendant is strictly liable to Plaintiff under 402B of the RESTATEMENT (SECOND) OF TORTS for misrepresenting that the product was safe and without defect. These representations were false and involved a material fact concerning the character or quality of the automobile. Plaintiff would show that he relied on these representations and that Defendant's misrepresentations were the proximate cause of the occurrence and of Plaintiff's damages.

V. NEGLIGENCE

Plaintiff alleges that Defendant was negligent in the design, manufacture and/or

marketing of the automobile, in that Defendant knew, or in the exercise of ordinary care, should have known, that the automobile was defective and unreasonably dangerous to ultimate consumers. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of the occurrence and of Plaintiff's damages.

VI.
RES IPSA LOQUITUR

In that alternative, Plaintiff would further show that he cannot more specifically allege the specific acts of negligent design and manufacture on the part of Defendant, for the reason that the facts in that regard are peculiarly within the knowledge of Defendant, and in the event Plaintiff is unable to prove specific acts of negligent design and manufacture, Plaintiff relies on the doctrine of *res ipsa loquitur*. In this connection, Plaintiff will show that the design and manufacture of the automobile were within the exclusive control of Defendant. Plaintiff had no means of ascertaining the method or manner in which the automobile was designed or manufactured by Defendant. Plaintiff would show that the product came into his possession in the same condition it was in when it left the control of Defendant. The occurrence causing harm to Plaintiff was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant. Plaintiff would show that Defendant's negligent acts and/or omissions were the proximate cause of Plaintiff's damages.

VII.
BREACH OF WARRANTY

Plaintiff further alleges that Defendant expressly and impliedly warranted to the public that the automobile was of merchantable quality and was safe and fit for the purposes intended when used under ordinary conditions and in an ordinary manner. Plaintiff would show that Defendant's breach of these warranties were the proximate cause of the occurrence

and of Plaintiff's damages. TEX. BUS. & COM. CODE Sec. 2.314 - 2.315, Sec. 17.50 (a)(2), (Vernon 1989). Plaintiff would further show that Defendant is liable for all attorney fee's pursuant to §38.001 of the Texas Civil Practice & Remedies Code.

VII.
DECEPTIVE TRADE PRACTICES ACT

Plaintiff would show that Defendant is also liable for violations of the Texas Deceptive Trade Practices and Consumer Protection Act ("DTPA"), including:

- A. Representations that the product in question, and its component parts, possessed qualities, characteristics, uses and benefits which they did not possess - [TEX. BUS & COM. CODE §17.46(5), (Vernon 1990)];
- B. Representations that the product in question, and its component parts, were merchantable when, in fact, they were not fit for the ordinary purposes for which such products were to be used - [TEX. BUS & COM. CODE §17.46(19), (Vernon 1990)];
- C. Failing to disclose information concerning dangers of the automobile known to Defendant, when such failure was intended to induce the consumer to purchase the product - [TEX. BUS & COM. CODE §17.46(22), (Vernon 1990)];

The above acts and/or omissions of Defendant were a proximate cause of the occurrence and of Plaintiff's \$11,026.63 damage to his real and personal property.

Pursuant to the common law of Texas and to the various statutes referenced herein, Defendant is liable to Plaintiff for actual and treble damages, interest, court costs, and reasonable attorney fees.

WHEREFORE, PREMISES CONSIDERED, Plaintiff requests that Defendant be cited to appear and answer, and that on final trial, Plaintiff have:

1. Judgment against the defendant for a sum in excess of the minimum jurisdictional limits of the Court;
2. Pre-judgment interest and post-judgment interest as provided by law;
3. Costs of suit;

4. Attorney fees;
5. Such other and further relief to which the a/c may be justly entitled.

Respectfully submitted,

LAW OFFICES OF RICHARD B. GEIGER
1513-C West Sixth Street
Austin, Texas 78703
(512) 320-8844 - Telephone
(512) 320-8854 - Facsimile

By:

Rich Geiger (w/permission EP)
Richard B. Geiger
State Bar No. 07791980

Erik Peters
State Bar No. 00791432

ATTORNEY FOR PLAINTIFFS

