

TEXAS INSTRUMENTS, INC.'S

09/10/03

REQUEST 6

BOX 7

PART A-P

PART A


REDDICK

TI-NHTSA 8682

REDDICK

TI-NHTSA 9883


REDDICK




TJ-NHTSA 9504


REDDICK


71-NHT8A 9895





TI-NHTSA 9586





Date: Tue Jan 05 14:33:38 1999

Scans: 128

Resolution: 8.000

TI-NHTSA 9589

TECHNICAL SERVICE LABS

LOG NO. _____

TEST NO. **150709**

TEST NO. **150709**

PCC I.D.	73	STATE YOUR PROBLEM OR SAMPLE DESCRIPTION Failure Analysis of Returned switches	INFORMATION DESIRED: → Try to determine the following: ① Did switch leak? ② Signs of corrosion? ③ Signs of racing? ④ Other signs of fire ignition?
REGULATOR COST CENTER	352		
PRODUCT CODE	069		
REQUESTOR	DAKKE		
MAIL STATION	12-29		
EXTENSION	3334		
USE ID	Dak		
DATE SUBMITTED	1/7/99		
DATE REQUIRED	1/7/99		
NO. OF SAMPLES	1		
COMPOSITION			

REPORT OF RESULTS:

3 MATERIALS
Washed in Acetone
Filtered 41 Whatman
Air Dried

99-033

DATE RECEIVED _____ DATE OUT **1/7/99**

TECHNICIAN			
HOURS WORKED			
PROCEDURE USED			

*PCC I.D.

- | | | | |
|----------|----------|------------|-----------|
| MC-328 | TM-431 | CLKE-122 | FACL-514 |
| PC-127 | WIRE-432 | CAN-354 | FACL-521 |
| VERB-186 | EPD-621 | AD DEV-288 | FACL-531 |
| AFCC-483 | PEP-622 | EMCO-677 | STAFF-665 |
| IMD-430 | CBD-635 | | |

Ford 77Ps Recovered Parts Analysis

Make Lincoln

Model Town Car

Year 1942

Date Recovered 1-20-1989

Recovery Location Coyle's New Bedford

Mileage TMC

TI Test # F77-1 Vehicle # 2VU9F42A AB 2124

Technician LEC

Date Tested 1-21-89

Device Photograph

ATTACHED
BACK
PAGE

Kapton Photograph

ATTACHED
BACK
PAGE

Ford 77PS Issue Recovered Parts Analysis

External switch condition Fair - Corrosion on Hex AND
Partially Deformed Terminals - Soldered Circuit -
Slight Displacement of O-Rings on Plug Inlet

Remove Connector

Terminal Condition Good - Clean with no Corrosion

Switch Pocket Good - Clean with no Fluid or
Dust

Remove Crimp Ring

Contact Assembly Clean - No Contamination
No Marking of Contacts - No Heat Discoloration or
Cracked Area

Sensor Assembly Some Corrosion Approaching
Base/Sensor Socket and Completely Absent Bottom
of Sensor Near Hex

Transfer Pin Shows No Visible Wear

Environmental Seal Good Condition

Disassemble Sensor


Kapton Condition Good - Some dust from cycling DELAYER
Bottom - Cracking seen with Fluid Seepage to DELAYER
Contacts - Minor Spitting from Bottom in High Pressure

Snap Disc Good - Shows Evidence of Cycling


Washer Good - Clean

Converter Good - Clean


Hex port Internal Some Corrosion



TI-NHTSA 9592



F77-1



F77-1

Full Test STOPPED DUE TO WATER DAMAGE
Kapton ONLY

Ford 77Ps Recovered Parts Analysis

Make Mercury

Model GRAND MARQUIS

Year 1992

Date Recovered 1-20-99

Recovery Location Sylvia's Auto Parts

Mileage T.M.U.

TI Test # F77-7 V F2V69F924 AB 2052

Technician LEC

Date Tested 1-25-99

Device Photograph
Attached

Kapton Photograph
Attached

Device OPEN to Elements - Does not work
Tested with connector from P77-5 device

Actuation

Release

M.V.D.

.30 @ 12ma
0- PST

TI-NHTSA 9594

Ford 77PS Issue Recovered Parts Analysis

External switch condition Good - Little red rust - most plating
VISIBLE - Partial Corrosion on mating faces.
Surface of Seal Clean

Remove Connector - NO CONNECTOR
WIRES Removed from car

Terminal Condition CORROSION SHOWN ON TERMINALS
DUE TO EXPOSURE FROM NO CONNECTOR

Switch Pocket Clean

Remove Crimp Ring

Contact Assembly Water Damage

Sensor Assembly Water Damage

Transfer Pin Shows Normal Wear

Environmental Seal Intact

Disassemble Sensor

Kapton Condition Starting to show initial signs of
DE-LAMINATION

Snap Disc Water Damage

Washer Water Damage

Converter Water Damage

Hex port Internal Slight Corrosion



F77-7

Ford 77Ps Recovered Parts Analysis

Make MERCURY

Model Grand Marquis

Year 1992

Date Recovered 1-20-99

Recovery Location Sylvia's Auto Parts

Mileage 54,691

TI Test # F77-6 F2Y69F924 AB 1347

Technician LCC

Date Tested 1-26-99

Device Photograph
ATTACHED

Kapton Photograph
ATTACHED

ACTUATION
112.5

Release
61.7

M.V.D. TI-NHTSA 9597
.25 mv @ 12 mA

Ford 77PS Issue Recovered Parts Analysis

External switch condition good - RED Rust on hex and PARTIALLY DOWN THREADS - Connector clean - mating surface good

Remove Connector

Terminal Condition CLEAN - NO CORROSION - Slight mis-alignment of terminals

Switch Pocket CLEAN -

Remove Crimp Ring

Contact Assembly good - NO ARCING or discoloration Shows normal wear

Sensor Assembly CORROSION UP SIDE UNDER CRIMP RING

Transfer Pin good - Shows normal wear

Environmental Seal good -

Disassemble Sensor

Kapton Condition CRACKS AND/OR DELAMINATION ON 1ST LAYER
2 - Normal wear
3 - Normal wear

Snap Disc NORMAL WEAR


Washer NORMAL WEAR

Converter good - normal wear

Hex port Internal Some Sludge and Corrosion



TI-NHTSA 9599



F77-6



F77-6



Ford TTPs Recovered Parts Analysis

Make LINCOLN

Model TOWN CAR

Year 1992

Date Recovered 1-20-99

Recovery Location Goyette's Auto Parts SK# 4072

Mileage T.M.U.

TI Test # F77-5 F2VC9F924 AS 1341

Technician APC

Date Tested 1-25-99

Device Photograph
ATTACHED

Kapton Photograph
ATTACHED

ACTUATION
157.2

Release
79.6

M.V.D.
3.1 MV @ 12mA
0-PSI

TI-NHTSA 9601

Ford 77PS Issue Recovered Parts Analysis

External switch condition Fair - Red Rust on hex Port
NO CORROSION ON CRIMP RING - Partial corrosion
DOWN THREADS

Remove Connector

Terminal Condition Good - Clean NO FLUIDS OR DEBRIS
NO CORROSION - Good alignment

Switch Pocket Clean - NO FLUIDS OR CONTAMINATION

Remove Crimp Ring

Contact Assembly GOOD - NO DISCOLORATION - NO PITTING
NORMAL WEAR

Sensor Assembly Slight corrosion UP SIDE - overall
good condition

Transfer Pin NORMAL WEAR

Environmental Seal Good

Disassemble Sensor

Kapton Condition 1 - De-laminated with Fluid - not all the way through
2 - normal
3 - normal

Snap Disc Good - Normal wear

Washer Deformation in Button area - CAUSING MISHAPE IN Kapton

Converter Good - Normal wear

Hex port Internal mild corrosion AND Buildup of Gasket good



F77-5

TI-NHTSA 9603



F77-5



F77-5



F77-5

TI-NHTSA 9804

Ford 77Ps Recovered Parts Analysis

Make LINCOLN

Model TOWN CAR

Year 1992

Date Recovered 1-20-99

Recovery Location Goyett's Auto Parts STX# 4271

Mileage T.M.U.

TI Test # E77-4 F2VCSF924 AB 2079

Technician LCC

Date Tested 1-25-99

Device Photograph
Attached

Kapton Photograph
ATTACHED

TI-NHTSA 9805

ACTUATION
149.6

RELEASE
77.8

M.V.P.
4.23 mk e 12mm
0-PSI

Ford 77PS Issue Recovered Parts Analysis

External switch condition Red Rust on hex part - Slight Amount
on Crimp Ring - Seal Area good Same Debris as what
Partial Corrosion Down Threads

Remove Connector

Terminal Condition Good - NO CORROSION - GOOD ALIGNMENT

Switch Pocket CLEAN - NO Fluid or Debris

Remove Crimp Ring

Contact Assembly GOOD - NO DISCOLORATION - NORMAL WEAR
& NO SIGN OF ARCING

Sensor Assembly CORROSION UP SIDE AND ONTO TOP WEAR
AN AREA

Transfer Pin Good - Normal WEAR

Environmental Seal Slight Lift FROM SENSOR TO GASKET FROM RUST
DISTORTED SHAPE

Disassemble Sensor

Kapton Condition Print FROM GASKET MARK on Kapton
1- Delamination Seen 2- Normal wear DRY
3- Normal wear - DRY

Snap Disc Normal wear Shows sign of cycling

Washer Normal wear

Converter Normal wear

Hex port Internal Slight Contamination + Debris



F77-4

TI-NHTSA 9807

F77-4



F77-4



Ford 77Ps Recovered Parts Analysis

Make MERURY

Model Grand Marquis

Year 1992

Date Recovered 1-20-99

Recovery Location HANK ZIEM'S

Mileage 102,291

TI Test # F77-2 VIN# F2VLC9F92A AB 3167

Technician LCC

Date Tested 1-22-99

Device Photograph

ATTACHED
BACK
PAGE

Kapton Photograph

ATTACHED
BACK
PAGE

ACTUATION

41.7

Release

67C

MVD

67mv G. 12mm 1.10
6-1-99

TI-NHTSA 9809

Ford 77PS Issue Recovered Parts Analysis

External switch condition Fair - Condenser has no dust on it, Drive Threads and Crank Ring - Seal Area Good in Contamination seen on inlet of Drive

Remove Connector

Terminal Condition Clean No Corrosion - Good Alignment

Switch Pocket Clean - No Fluid or Dust

Remove Crimp Ring

Contact Assembly Good Condition - No Sign of Aging or Short - No Heat Discoloration

Sensor Assembly Corrosion to Seal - No RED Rust

Transfer Pin Good Shows Normal wear

Environmental Seal Good

Disassemble Sensor

Kapton Condition to Fuel side - Shows Determination of Kruptor - Cranks in middle - Normal wear - Dry shows on surface in combustion side - Good - Normal wear

Snap Disc Good - Shows Evidence of Cycling - Dust



Washer Good - Shows Evidence of Cycling - Dust

Converter Good - Shows Normal wear

Hex port Internal Light amount of Debris - Gasket Good



TI-NHTSA 9811



TI-NHTSA 9612

Ford 77Ps Recovered Parts Analysis

Make FORD

Model CROWN VICTORIA

Year 1992

Date Recovered 1-20-99

Recovery Location HANK ZIENS

Mileage T M U

TI Test # F 77-3 F2VC9F929 AB 1930

Technician SEC

Date Tested 1-22-99

Device Photograph

ATTACHED
TO
BACK

Kapton Photograph

ATTACHED
TO
BACK

TI-NHTSA 9613

ACTUATION

121.6

Release

61.8

M.V.D.

.13mv @ 12mA load

0 PSI

Ford 77PS Issue Recovered Parts Analysis

External switch condition Fair - Red Rust Showing on Hex Port -
Typical Dust + oil Buildup - Light corrosion on threads
Seal Surface good - Bulge on CRIMP RING NEAR hex port - Side

Remove Connector

Terminal Condition Good - NO CORROSION - good alignment

Switch Pocket Clean / DRY

Remove Crimp Ring

Contact Assembly Good - NO DEBRIS OR FLUIDS - CONTACTS
SHOW NORMAL WEAR - NO DISCOLORATION - NO PATTERNS
OF CONTACT AREA

Sensor Assembly EXTERNAL CORROSION - Heavy deposits Between
SENSOR + BASE - INTERNAL AREA CLEAN + DRY

Transfer Pin NORMAL WEAR

Environmental Seal GOOD CONDITION, SLIGHT INCREASE OF CORROSION

Disassemble Sensor

Kapton Condition: Layer 1 - Delaminated Kapton Fluid Penetration
Layer 2 - starting to delaminate -
Layer 3 - NORMAL WEAR - NO delamination

Snap Disc Good - NORMAL WEAR

Washer Good - NORMAL WEAR

Converter Good - NORMAL WEAR

Hex port Internal GASKET good - some INTERNAL CORROSION




F77-3

TI-NHTSA 9515



F77-2



F77-3



F77-3

TI-NHTSA 9816

Kill, Beth

From: Kill, Beth
Sent: Friday, January 06, 1990 3:15 PM
To: Dague, Bryan
Cc: Hopkins, Al
Subject: TEL # 150708, Fluid Identification

Objective:

isolate and identify the fluid samples found in customer returned device.

Results:

First, I rinsed the cap, excluding the transfer pin hole, with chloroform. I filtered the mixture to remove the solids, and then evaporated the solvent. The remaining residue was identified as brake fluid by FT-IR spectroscopy. The match factor was 80% compared to a reference sample of Nissan brake fluid in my database. Visual comparison of the Nissan fluid to the sample suggests the fluid from the sample contains less water. This may be due to slightly different formulations produced by different manufacturers.

Next, I scanned the samples of fluid, provided by Al, from the transfer pin hole and the converter of this device. The two samples from the transfer pin hole are identical to the fluid rinsed from the cap with chloroform. The fluid from the converter also appears to be brake fluid, but appears to contain slightly more water than the other samples.

I will forward the spectral data to you by internal mail. Please let me know if I can discard the remaining fluid samples, or if you would like me to forward these to you also.

Regards,

Beth

Ext. 3059 MB 10-18 Fax 1670

TECHNICAL SERVICE LABS

LOG NO. _____

TEST NO. 150709

TEST NO. 150709

*PCC I.D.	127	STATE YOUR PROBLEM/ SAMPLE DESCRIPTION <i>Failure Analysis of Returned switches.</i>	INFORMATION DESIRED: <i>→ Try to determine the following:</i> <ol style="list-style-type: none"> ① Did switch leak? ② signs of corrosion? ③ signs of arcing? ④ other signs of fire ignition?
REQUESTOR	357		
PRODUCT CODE	069		
REQUESTOR	DA6-UE		
MAIL STATION	12-29		
EXTENSION	3234		
MSG ID	Dmg -		
DATE SUBMITTED	1/7/99		
DATE REQUIRED	1/9/99		
NO. OF SAMPLES	1		
COMPOSITION			

REPORT OF RESULTS:

DATE RECEIVED _____ DATE OUT _____


TECHNICIAN			
HOURS WORKED			
PROCEDURE USED			

*PCC I.D.

MC-325	TM-431	CLKE-122	FACIL-514
PC-127	WIRE-432	CAN-854	FACIL-521
VERS-188	EPD-821	AD DEV-288	FACIL-531
AFCC-483	PEP-822	EMCD-877	STAFF-855
IMD-430	CSO-835		

DISTRIBUTION: White and Yellow - Lab Pink - Requestor

TI-NHTSA 9818



OMNIC Search


Spectrum: TSL # 150709, Extracted with chloroform

Fri Jan 08 11:18:42 1999

Region: 3995.85 649.98

Search type: Correlation

Comment:



Index	Match	Compound name	Library
10394	90.09	Poly(ethylene glycol methyl ether), avg.	Alrich Condensed Phase
90	89.55	Automotive brake fluid, Nissen	TSL
10392	87.98	Poly(ethylene glycol), avg. m.w. 8,000	Alrich Condensed Phase
10395	87.69	Poly(ethylene glycol methyl ether), avg.	Alrich Condensed Phase
9540	87.10	Brj 99; Polyoxyethylene(20) octyl ether	Alrich Condensed Phase
9613	86.38	Brj 35; Polyoxyethylene(20) lauryl ether	Alrich Condensed Phase
9539	84.80	Brj 78; Polyoxyethylene(20) stearyl ether	Alrich Condensed Phase
10393	83.20	Poly(ethylene glycol methyl ether), avg.	Alrich Condensed Phase
9535	83.05	Tetraethylene glycol dimethyl ether, 98%	Alrich Condensed Phase
10388	82.99	Poly(ethylene glycol), avg. m.w. 600	Alrich Condensed Phase

Epstein, Sally

From: Hopkins, AL [ahopkins@email.mc.ti.com]
Sent: Friday, January 18, 1999 5:08 PM
To: Lincoln, Maureen
Cc: Dagus, Bryan; Proia, Stephen; McGuirk, Andy; Chura, Stephen; Pavao, Joe
Subject: 99-030: TEL # 180388: HIGH FALLOUT RATE ON ASSEMBLY LINE DUE TO NO-CONTINUITY: Status Report

OBJECTIVE:

Perform SEM analysis on Terminal 2 stationary contact to check for contamination.

RESULTS AND DISCUSSION:

The original samples were from a lot that was giving high fallout. I examined all the samples visually and only found one that gave indications to me that there was a significant amount of contamination present. SEM-EDX analysis of this sample showed mainly particles of the PPS plastic base and the glass fibers that are used to reinforce the plastic.

At this point I asked Maureen to send over some known failures. She sent over four samples and out of this group, one had a visible particle on the contact and another had a plastic fiber on it. We removed the large particle on the first sample and determined that it was again PPS. Do you want us to have the Chem Lab determine the identity of the plastic fiber on the second sample?

We also examined one of the devices that didn't have any optically detectable (by me) contamination on it. Again, we found that particles of the casing plastic and fragments of glass reinforcing fibers were the main constituents.

This is not to say that there weren't other species present on the above devices. We found sodium, chlorine, titanium, potassium, etc; the amounts, however, weren't large enough to explain the problem.

We will be looking at the last of this group of 4. Maureen, you also had sent over a base that was still attached to the brass hex; it didn't come apart easy. I don't know if I caused damage during my disassembly or if all these drill holes were the cause. Please let me know more about this particular sample. Also, could I have a schematic of the device?

The data was collected under the guidelines of TSL-5-71, Rev A which can be accessed at <http://www-mod.mc.ti.com/tes/>. SEM-EDAX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis was used in the above described analysis. The data will be sent through the internal mail.

AL HOPKINS

MSG ID: ANOF

PHONE: 506/236-3040

TI-NHTSA 9621

Dague, Bryan

From: Hopkins, Al
Sent: Wednesday, January 20, 1998 11:21 AM
To: Dague, Bryan; Baumann, Russell
Cc: McGuirk, Andrew; Andra, Amy
Subject: 99-033; TSL # 160706; ANALYSIS OF MATERIAL REMOVED FROM 77PS THERMAL EVENT

ATTORNEY-CLIENT PRIVILEGED COMMUNICATION

OBJECTIVE:

Determine nature of deposit; in particular, determine if it is consistent with the results from Ford's analysis.

SUMMARY:

The results were very similar to those found by Ford. The main difference is that our EDX detector has a much better low energy cutoff than did the Ford detector. Their detector is unable to detect carbon and oxygen. Our analysis showed large amounts of carbon and oxygen on all three samples.

RESULTS AND DISCUSSION:

All of the samples were comprised of a mixture of different phases that had agglomerated together. A description of our findings is shown below:

BLACK FLAKE FROM TROUGH: We found the following elements which are listed in a very approximate decreasing order of preponderance: copper, oxygen, carbon, chrome, zinc, potassium, sulfur, and silver.

MATERIAL SCRAPPED FROM CUP ASSEMBLY: There were a very large number of glass fibers present which had the composition that is typically used in plastics for reinforcing purposes. In other words, this is almost certainly from thermal decomposition of the plastic base. The EDX detectable elements in these fibers are calcium, aluminum, silicon and oxygen. The rest of the material was very similar in composition to that reported for the above sample although we also detected some phosphorus in this sample.

GREEN MATERIAL ON CUP: This material was similar to that found on the first sample although the amount of chrome was much less.

The data was collected under the guidelines of TSL-S-71, Rev A which can be accessed at <http://www-mcd.mc.ti.com/tsl/>. SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis was used in the above described analysis. The data will be sent through the internal mail.


AL HOPKINS

MSG ID: AHOP

PHONE: 508/236-3040

Hydraulic Pressure Switch Cross Section

Normally Closed



TI-NHTSA 9623

Hopkins, AL

From: Hopkins, AL
Sent: Wednesday, January 20, 1999 11:21 AM
To: Dague, Bryan; Baumann, Russ
Cc: McGuirk, Andy; Andree, Amy
Subject: 98-033: TSL # 150709: ANALYSIS OF MATERIAL REMOVED FROM 77PS THERMAL EVENT

ATTORNEY-CLIENT PRIVILEGED COMMUNICATION

OBJECTIVE:

Determine nature of deposit; in particular, determine if it is consistent with the results from Ford's analysis.

SUMMARY:

The results were very similar to those found by Ford. The main difference is that our EDX detector has a much better low energy cutoff than did the Ford detector. Their detector is unable to detect carbon and oxygen. Our analysis showed large amounts of carbon and oxygen on all three samples.

RESULTS AND DISCUSSION:

All of the samples were comprised of a mixture of different phases that had agglomerated together. A description of our findings is shown below:

BLACK FLAKE FROM TROUGH: We found the following elements which are listed in a very approximate decreasing order of preponderance: copper, oxygen, carbon, chrome, zinc, potassium, sulfur, and silver.

MATERIAL SCRAPPED FROM CUP ASSEMBLY: There were a very large number of glass fibers present which had the composition that is typically used in plastics for reinforcing purposes. In other words, this is almost certainly from thermal decomposition of the plastic base. The EDX detectable elements in these fibers are calcium, aluminum, silicon and oxygen. The rest of the material was very similar in composition to that reported for the above sample although we also detected some phosphorous in this sample.


GREEN MATERIAL ON CUP: This material was similar to that found on the first sample although the amount of chrome was much less.

The data was collected under the guidelines of TSL-S-71, Rev A which can be accessed at <http://www-god.nc.ti.com/tsl/>. SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis was used in the above described analysis. The data will be sent through the internal mail.

AL HOPKINS

MSG ID: ABOF

PHONE: 506/236-3040



150709 A-black flake from trough, 50x bae 20


TI-NHTSA 9825

Acquisition completed.

5

9227 FS

✓ dages_150709_020 A-black flake from trough




TI-NHTSA 9626

Acquisition completed. Σ

✓ dagne_150709_021 A-black flake from trough

9986 FS




TI-NHTSA 9827




150709 B, material scraped from cup assembly, 50x bsc 21

TI-NHTSA 9029



TI-NHTSA 9629




TI-NHTSA 9630

Acquisition completed.

8360 FS

✓ dagne_150780_024 E-material scraped from cup




TI-NHTSA 9931

Acquisition completed.

2394 FS

✓ dague_158769_025 E-material scraped from cup




TMHTBA 9632

Acquisition completed.

— / daga_150709_026 B-material scraped from cup

5679 FS




TM-NHTSA 9039

TI-NHTSA 9034



150789 C, green material on cup, 50x hsa 22




TI-NHTSA 9635

Acquisition completed.

7203 FS

— ✓ daga_150709_028 C- gross material on exp




TI-NHTBA 0636

Acquisition completed.

✓ daga_150709_029 C- green material on cup

0066 F3



TI-NHTSA 9637




Figure 6: EDS X-ray spectrum of one of three samples of the white powder taken from the connector cavity below the wire seal.




Figure 7: EDS X-ray spectrum of the second of three samples of the white powder.




Figure 8: EDS X-ray spectrum of the third of three samples of the white powder.

Note: Nominal magnifications given for photomicrographs.




Figure 1: EDS X-ray spectrum of material scraped from the side of the stationary contact body.




Figure 2: EDS spectrum of greenish compound scraped from the cup region.




Figure 3: EDS X-ray spectrum of fibrous material scraped from the cup region.

Note: Nominal magnifications given for photomicrographs.

TI-NHTSA 98039

Rob Sharpe

(248) 888-2013

p. 1

Post-It Fax Note	7671	Date	3/5/99	Page	1
To	Charles Douglas	From	Rob Sharpe		
Co./Dept.	TI - Atlanta	Co.			
Phone #	(508) 236-3657	Phone #			
Fax #	(508) 236-5788	Fax #			

AS TO 92483856734

P.01/01

January 15, 1999

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 300 brass, which is highly susceptible to SCC.

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the base port and on the cap, however, and also appear to be compounds which may have formed from a reaction between decomposition products (solid) of the polyester base of the brake fluid and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

BLACK RESIDUE BRAKE FLUID & AN CARBONATE OR METAL

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any mating parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragms.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (surfaces bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.

The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (in plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus)

Steve LaRouche

TI-NHTSA 9640

Ford Motor Company
77PS Style
Pressure Switches

Events - by year of return

Root Cause Analysis(Corrective Action Reports)

	1994	1995	1996	1997	1998	Total Events
Contaminated Terminals	0	0	0	0	1	1
Continuity Anomaly	1	0	0	1	0	2
Wrong Parts Shipped	0	0	3	3	0	6
Damaged Threads/ Hexport	0	5	1	0	0	6
Noisy Switch	0	0	1	0	0	1
Cracked Bases	0	0	1	0	0	1
Vacuum Dependency	0	1	0	0	0	1
Device Leak	0	1	0	0	0	1
Incorrect Code	0	1	0	0	0	1
Low Release Calibration	0	1	0	0	0	1
(Total)	1	9	6	4	1	

Root Cause Analysis(Return Device Analysis)

	1994	1995	1996	1997	1998	
Failure Due To Customer	n/a	n/a	0	0	0	0
Contaminated Terminals	n/a	n/a	0	1	0	1
Trouble Not Found	n/a	n/a	0	1	3	4
Damaged Base	n/a	n/a	0	1	0	1
(Total)	n/a	n/a	0	3	3	

(n/a= not available)

Total 1994 Ford Motor (77PS) customer returns: 1

Total 1997 Ford Motor (77PS) customer returns: 7

Total 1995 Ford Motor (77PS) customer returns: 9

Total 1996 Ford Motor (77PS) customer returns: 4

Total 1996 Ford Motor (77PS) year to date customer returns: 6

Total 1998 Ford Motor (77PS) customer returns year to date: none

TI-NHTSA 9641

Graveline, Dora

From: Hopkins, AL
Sent: Thursday, February 11, 1999 1:58 PM
To: Dague, Bryan
Co: Saumann, Russell
Subject: FW: TSL # 150708, Fluid Identification

This is the work that Beth had done to show that the fluid from the switch from the Lincoln Town car fire was almost certainly brake fluid.

Regards,

AI

From: KB, Beth
Sent: Friday, January 08, 1999 3:15 PM
To: Dague, Bryan
Co: Hopkins, AI
Subject: TSL # 150708, Fluid Identification

Objective:

Isolate and identify the fluid samples found in customer returned device.

Results:

First, I rinsed the cap, excluding the transfer pin hole, with chloroform. I filtered the mixture to remove the solids, and then evaporated the solvent. The remaining residue was identified as brake fluid by FT-IR spectroscopy. The match factor was 89% compared to a reference sample of Nissan brake fluid in my database. Visual comparison of the Nissan fluid to the sample suggests the fluid from the sample contains less water. This may be due to slightly different formulations produced by different manufacturers.

Next, I scanned the samples of fluid, provided by AI, from the transfer pin hole and the converter of this device. The two samples from the transfer pin hole are identical to the fluid rinsed from the cap with chloroform. The fluid from the converter also appears to be brake fluid, but appears to contain slightly more water than the other samples.

I will forward the spectral data to you by internal mail. Please let me know if I can discard the remaining fluid samples, or if you would like me to forward these to you also.

Regards,

Beth
Ext. 3089 MB 10-16 Fax 1670

Epstein, Sally

From: DAGU\mimi@magic.itg.ti.com
Sent: Thursday, February 11, 1999 2:47 PM
To: Rahman, Aziz
Subject: FW: TSL # 150709, Fluid Identification

-MSG #8= 985122 FR=DAGU TO=ZIZ SENT=02/11/99 02:39 PM TYPE=N
R#067 ST=C DIV=0050 CC=00357 BY=DAGU AT=02/11/99 02:39 PM

To: Rahman <Rahman>
Aziz ZIZ ZIZ

From: "Dague, Bryan" <bdague@mail.mc.ti.com>

Subj: FW: TSL # 150709, Fluid Identification

From: Hopkins, Al
Sent: Thursday, February 11, 1999 1:58 PM
To: Dague, Bryan
Cc: Baumann, Russell
Subject: FW: TSL # 150709, Fluid Identification

This is the work that Beth had done to show that the fluid from the switch from the Lincoln Town car fire was almost certainly brake fluid.

Regards,

Al

From: Kill, Beth
Sent: Friday, January 08, 1999 3:15 PM
To: Dague, Bryan
Cc: Hopkins, Al
Subject: TSL # 150709, Fluid Identification

Objective:
Isolate and identify the fluid samples found in customer returned device.

Results:
First, I rinsed the cap, excluding the transfer pin hole, with chloroform. I filtered the mixture to remove the solids, and then evaporated the solvent. The remaining residue was identified as brake fluid by FT-IR spectroscopy. The match factor was 89% compared to a reference sample of Nissan brake fluid in my database. Visual comparison of the Nissan fluid to the sample suggests the fluid from the sample contains less water. This may be due to slightly different formulations produced by different manufacturers.

Next, I scanned the samples of fluid, provided by Al, from the transfer pin hole and the converter of this device. The two samples from the transfer pin hole are identical to the fluid rinsed from the cap with chloroform. The fluid from the converter also appears to be brake fluid, but appears to contain slightly more water than the other samples.

I will forward the spectral data to you by internal mail. Please let me know if I can discard the remaining fluid samples, or if you would like me to forward these to you also.

Regards,

Bob
Ext. 3069

MS 10-16

Fax 1670

Epstein, Sally

From: Beringhouse, Steven [sberinghouse@gmail.com]
Sent: Wednesday, February 17, 1999 6:48 AM
To: Rahman, Aziz
Subject: FW: 89-003: PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM 77PS FROM LINCOLN TOWN CAR

Aziz,

Here was Al's first pass proposal. I am not sure if the final process changed. I will find out today, but I do not think it did. Bryan is not in yet, my guess is he is still sick. I will follow up with Al or Bryan at home.

Steve

**PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM
77PS FROM LINCOLN TOWN CAR**

- * Review Ford's Analysis data that they are bringing in.
- * Examine threads and determine if it is OK to just chase the threads to get a good seal or should we remove material for analysis.
- * Pressure Leak Test the device (15 minute static-hold, air-pressurized test).
- * Decide if we should remove any material or try any other analysis before we start disassembling the device.
- * Do a practice decap using the below procedure on a deliberately fractured part (to mimic the condition that the returned device will be in) before performing it on the real sample. Bryan, you and I could do this now.
- * Procedure to remove aluminum crimp ring
- * Use aluminum foil (or plastic if Ford prefers) to mask the analysis surface.
- * Also create a paper/tape shield to further reduce chance of contamination during cutting of crimp ring.
- * Place a piece of tape over the area to be cut.
- * Cut crimp ring using jewelers saw or Dremel cutoff wheel in one of the two areas indicated on optical photo.
- * Cut corners of ring at 180 degree orientation
- * Unfold crimp ring
- * Optically examine revealed surfaces. Take optical photographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate. Examine the following areas
 - * Inside surface of crimp ring.
 - * Seal area and underside of base
 - * Top of cap
- * Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.
- * Reprotect the top surface and remove the cap. Bryan had originally suggested just using an end mill to remove the cap. I wouldn't, however, go all the way through with the end mill. I would leave some material behind as a shield. I would suggest then bending the cap off.
- * Optically document all revealed surfaces starting with cap.
- * Meanwhile, start SEM-EDX analysis on top side of cap. Particularly focus in on the edges of the ceramic pin guide and on the indented ring that lines up with interior wall of the switch cavity. Particularly look for evidence of corrosion or arcing.
- * Decide if we should try to flake off any of the overlying debris to try to examine the underlying metal surface.
- * Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.
- * Non-destructively probe inside of the grommet to determine its resilience which will give us an indication of the temperature that it saw. Another indication might be the depth of the indentations left by the grommet seal rings in the wire.
- * Decide if it makes sense to further examine the mating connector or grommet seal.

TI-NHTSA 9645

Regards,

Al

TI-NHTSA 9848

Hopkins, AL

From: Hopkins, AL
Sent: Wednesday, April 14, 1999 9:48 AM
To: FORD- Rock Carter
Subject: Electronic Image Versions of Photos that had been Faxed on 4/13/99

Rock,

This is the text of the FAX that I sent you yesterday. The fax was acting up yesterday so I had to send it in three separate pieces. You should have pages 1-41.

Rock, this data was accumulated while Ford Engineering was present. They took copies of this data and all the actual parts of the sample. They had, however, left the small amounts of debris for our Chem Lab to perform FTIR analysis to check if there was brake fluid present. In fact, the FTIR analysis showed that this was the case.

As you know, we subsequently were requested to send this small amount of debris (wrapped in aluminum foil) back to Ford. I would think that it would be much more useful to examine the actual switch itself.

In any case, this is the key to the data. I am going to try to E-mail you the photos electronically tomorrow. If you have any questions, feel free to call me at 508-235-3040.

<u>Sample</u>	<u>Pages</u>	<u>Photos</u>	<u>Spectra</u>
Top Surf of Cup After Degreasing	1-14	01-05	001-009
Terminal Cavity after Disassembly	15-28	06-15	010-013
"A" - Black Flake from Trough	29-31	20	020-021
"B" - Material Scraped from Cup Assembly	32-37	21	022-026
"C" - Green Material on Cup	38-41	22	027-029

The following images are Windows PCX bit maps. They don't have any annotation on them but you can probably read that off of the faxed copy. The last two digits on the file names are the photo numbers.



If you have any questions, feel free to call. There aren't many spectra from the Terminal Cavity After Disassembly

because I couldn't avoid shadowing without additional disassembly that Ford Engineering didn't want to do at the time.

Regards,

Al