

**EA02-025**

**TEXAS INSTRUMENTS, INC.'S**

**9/10/03**

**REQUEST NO. 7**

**BOX 10**

**PART A - I**

**PART E**



CAUSE NO. C-4178-98-F

[REDACTED]

\* IN THE DISTRICT COURT  
\*  
\* OF HIDALGO COUNTY, TEXAS  
\*  
\*  
\* 332nd JUDICIAL DISTRICT

VS.

VAN BURKLEO MOTORS, INC.;  
FORD MOTOR COMPANY;  
and UNITED TECHNOLOGIES  
AUTOMOTIVE, INC.

[REDACTED]

COMES NOW, FORD MOTOR COMPANY, a Defendant in the above-entitled and numbered cause, and files this Cross-Claim Against Texas Instruments, Inc., and in support thereof would respectfully show unto the Court as follows:

I  
JURISDICTION, PARTIES AND VENUE

1.01. This Court has jurisdiction over the parties and the subject matter of the underlying suit and of this Cross-Claim; the amount in controversy exceeds the minimum jurisdictional requirements of this Court, and all conditions precedent to the filing of this suit have been satisfied.

1.02 Defendant/Cross-Plaintiff Ford Motor Company ("Ford") sues herein Cross-Defendant Texas Instruments, Inc. ("Texas Instruments"), a Delaware Corporation doing business in Texas. Texas Instruments, having already appeared and answered herein, may be served by service upon its counsel of record in this cause: Mr. Johnny Carter and Mr. Eric Mayer, Susman & Godfrey, 1000 Louisiana, Suite 5100, Houston, Texas 77002; and Michaela Alvarez, Holo & Alvarez, L.L.P., 612 West Nolana, McAllen, Texas 78504. By copy of this Cross-claim, service is being accomplished on Texas Instruments at this time.

1.03 Venue of this Cross-claim will follow venue over the primary action.

II  
FACTUAL BACKGROUND

2.01. Plaintiffs [redacted] filed this action on or about August 6, 1998, and filed an Amended Petition adding Texas Instruments as a party on or about May 20, 1999. In this suit, they allege that they purchased a 1993 Lincoln Town Car manufactured by Ford, which they allege caught fire on or about December 28, 1997, allegedly causing extensive property damage to Plaintiffs' home and personal property. In their most recent amended Petition, Plaintiffs specifically contend that the vehicle's speed control deactivation switch was the ignition source for the fire and the cause of Plaintiffs' alleged injuries and damages.

2.02. While Ford does not agree and expressly disputes Plaintiffs' claim that the speed control deactivation switch (or any other alleged defect in the vehicle) caused the fire at issue, to the extent that the trier of fact may determine such to be the cause of the fire, such a cause would be the responsibility of Texas Instruments as the manufacturer of the speed control deactivation switch, for the reasons set out below.

2.03. [redacted] Lincoln Town Car and Mercury Grand Marquis vehicles contain a speed control deactivation switch. [redacted] This switch problem was caused by the negligence of Texas Instruments in its manner of assembling the switches. To the extent that the trier of fact may determine the switch to be the cause of the fire, then, Ford alleges that Plaintiffs' injuries and damages were caused by such a manufacturing defect and/or such negligence by Texas Instruments rather than by any act, omission, or product for which Ford is responsible.

2.04. Ford purchased the speed control deactivation switch at issue from Texas Instruments relying upon express warranties and the Uniform Commercial Code's implied

warranties of merchantability and of fitness for a particular purpose. With regard to the warranty of fitness for a particular purpose, Texas Instruments had reason to know that Ford was purchasing the switch specifically for use as a speed control deactivation switch in a 1992 Ford vehicle which would need to perform as such during all of the functions performed by a passenger vehicle purchased by a United States consumer/driver of such a vehicle. Ford relied upon Texas Instruments' skill and judgment as a manufacturer of electrical switches for automotive applications to select and furnish a suitable switch for this purpose.

2.05 To the extent that the trier of fact may find that the fire at issue was caused by the speed control deactivation switch, [REDACTED] Ford relied upon these warranties and would not have purchased the switch without them. Ford would also show that injuries and damages such as those claimed by Plaintiffs are foreseeable consequential damages of the breaches of the above warranties committed by Texas Instruments.

2.06 In addition, Ford purchased the speed control deactivation switch from Texas Instruments pursuant to a written purchase order, which constituted a written contract and which contained language by which Texas Instruments agreed to indemnify Ford for damages caused by claims such as that of Plaintiffs herein.

2.07 Ford has requested that Texas Instruments fulfill its responsibilities to indemnify Ford in this matter; however, to date, Texas Instruments has failed and refused to do so, requiring Ford to bring this Cross-Claim against Texas Instruments in order to protect its rights in this matter.

**III**  
**FIRST CAUSE OF ACTION**  
**COMMON-LAW CONTRIBUTION AND/OR INDEMNIFICATION**

3.01 While Ford does not agree and expressly disputes Plaintiffs' claim that the speed control deactivation switch (or any other alleged defect in the vehicle) caused the

fire at issue, to the extent that the trier of fact may determine such to be the cause of the fire, Ford relies upon its rights in such a case under Tex. Civ. Prac. & Rem. Code §32.001, et seq. In such case, Ford asks that the trier of fact be asked to determine the percentage of causation attributable as between Ford and Texas Instruments, and alleges that

3.02 Ford thus sues for common law contribution and/or indemnity herein.

**IV.  
SECOND CAUSE OF ACTION  
BREACH OF WARRANTIES**

4.01 Ford purchased the speed control deactivation switches from Texas Instruments relying upon express warranties and the Uniform Commercial Code's implied warranties of merchant ability and of fitness for a particular purpose, found in Michigan law at M.C.L.A. 440.2313, 440.2314 & 440.2315 and alternatively in Texas law at Tex. Busi & Com. Code § 2.313, 2.314 and 2.315. To the extent that the trier of fact may determine the switch to be the cause of the fire at issue, Ford alleges that the above warranties were breached and that foreseeable consequential damages of such breaches are the damages caused to Ford by the claims of Plaintiffs herein, including any expenses incurred by Ford in investigating, defending itself from and/or resolving such claims.

4.02 All conditions precedent to the bringing of this cause of action have occurred or are waived.

4.03 Ford thus sues for its damages, as stated above, in excess of the minimum jurisdictional limits of this Court, for these breaches of warranties.

V.  
**THIRD CAUSE OF ACTION  
BREACH OF CONTRACT OF INDEMNIFICATION**

5.01 Ford purchased the speed control deactivation switch at issue pursuant to a purchase order which constituted a written contract, which included a provision by which Texas Instruments agreed to indemnify Ford for any claims of the type brought by Plaintiffs herein. Ford has requested that Texas Instruments fulfill its responsibilities to indemnify Ford in this matter; however, to date, Texas Instruments has failed and refused to do so. Ford thus alleges that Texas Instruments has breached its written contractual agreement to indemnify Ford in this matter and that foreseeable consequential damages of such breach are the damages caused to Ford by the claims of Plaintiffs herein, including any expenses incurred by Ford in investigating, defending itself from and/or resolving such claims.

5.02 All conditions precedent to the bringing of this cause of action have occurred or are waived.

5.03 Ford thus sues for its damages, as stated above, in excess of the minimum jurisdictional limits of this Court, for this breach of the indemnification agreement in the purchase order.

VI  
**FOURTH CAUSE OF ACTION  
RECOVERY OF ATTORNEYS FEES**

6.01 Ford has made written demand upon Texas Instruments that it fulfill its obligations under the purchase order/contract for the speed control deactivation switch at issue. As stated herein, then, Ford has a claim for breach of a written contract, and thus for its attorneys' fees herein pursuant to Tex. Civ. Prac. & Rem. Code §38.001 (8).

6.02 All conditions precedent to the bringing of this cause of action have occurred or are waived.

6.03 Ford thus sues for its attorneys' fees incurred in bringing this Third Party Complaint.

VII  
PRAYER

WHEREFORE, PREMISES CONSIDERED, Defendant/Cross-Plaintiff Ford Motor Company prays that it be afforded the following relief:

- (1) Judgment for common law contribution and/or indemnity as determined by the findings as to percentages of responsibility made by the trier of fact herein;
- (2) Judgment in its favor for damages caused by breaches of warranties and/or breach of contract in an amount to be determined by the trier of fact;
- (3) Judgment in its favor for reasonable and necessary attorneys' fees;
- (4) Costs of Court;
- (5) Prejudgment and post judgment interest at the maximum legal rate; and,
- (6) For any and all further relief, at law or in equity, to which Plaintiff may show themselves justly entitled to receive.

Respectfully submitted,

RODRIGUEZ, COLVIN & CHANEY, L.L.P.

By: 

Jaime A. Shenz  
State Bar No. 17614859  
Alison B. Kennamer  
State Bar No. 11289400  
1201 East Van Buren  
Post Office Box 2153  
Brownsville, Texas 78522  
(956) 542-7441  
Fax (956) 541-2170

ATTORNEYS FOR DEFENDANT,  
FORD MOTOR COMPANY

**CERTIFICATE OF SERVICE**

I hereby certify that a true and correct copy of the above and foregoing was served upon all counsel of record, to-wit:

Norman Jolly  
1018 Preston, 4th Floor  
Houston, Texas 77002

Ramon Garcia  
Law Offices of Ramon Garcia  
222 West University Drive  
Edinburg, Texas 78539

James J. Parker  
W. Scott Red, Jr.  
Red & Parker, L.L.P.  
12200 NW Freeway, Suite 325  
Houston, Texas 77092

Anthony B. James  
134 East Van Buren, Suite 310  
Harlingen, Texas 78550

Ms. Alicia M. Matsumura  
Law Office of William W. Keas, Jr.  
Attorneys at Law  
101 North Shoreline, Suite 216  
Corpus Christi, Texas 78401

Johnny Carter  
Eric Mayer  
Susman & Godfrey  
1000 Louisiana, Suite 5100  
Houston, Texas 77002

Michaela Alvarez  
Hole & Alvarez, L.L.P.  
612 West Nolana  
McAllen, Texas 78504

Andrew Schirrmelster  
Schirrmelster Ajamie  
711 Louisiana, Ste. 2150  
Houston, Texas 77002

by certified mail, return receipt requested, facsimile transmission, and/or hand delivery, pursuant to the Texas Rules of Civil Procedure, on this the 2 day of December, 1999.

  
Alison Krennemer



**RODRIGUEZ, COLVIN & CHANEY, L.L.P.**

**ATTORNEYS AT LAW**

**A REGISTERED LIMITED LIABILITY PARTNERSHIP**

**JARRO ROBERTO RODRIGUEZ  
NORTON A. COLVIN, JR.  
MITCHELL C. CHANEY  
HARROLD C. STYSEL  
JAMES A. BARNETT  
JOSEPH A. (TONY) RODRIGUEZ  
ALISON D. KENNAMER**

**1801 EAST VAN BUREN  
P. O. BOX 2155  
BROWNSVILLE, TEXAS 77822  
TELEPHONE (936) 842-7444  
TELECOPIER (936) 844-8170**

**LAURA J. URBIS  
LEOLA L. CHANEY  
DANIEL S. HERMAN  
S. PATRICK RODRIGUEZ  
ROSAMARIA VILLAGOMEZ**

**MEMBER OFFICE OF PROFESSIONAL  
ACCOUNTANTS  
MEMBER TEXAS BAR  
MEMBER TEXAS BOARD OF LEGAL SPECIALIZATION  
MEMBER OFFICE OF LEGAL COUNSEL  
MEMBER TEXAS LAW  
MEMBER TEXAS BOARD OF LEGAL SPECIALIZATION**

**OF COUNSEL  
BENJAMIN S. HARTY (PHOTO)  
GARRIN W. JOHNSON  
NEIL S. HERRICK  
CHRIS A. BRISACK  
MATTHEW A. COWLEY**

December 6, 1999

*Via Hand Delivery*



Edinburg, Texas

Re: Cause No. [Redacted]

[Redacted] vs. Van Burkleo Motors, Inc.; Ford Motor Company, and United Technologies Automotive, Inc.  
Our File: 17,110

Dear [Redacted]

Enclosed for filing in the above-referenced matter, please find the following original documents to be filed with the Court:

- 1. Ford Motor Company's Cross-Claim Against Texas Instruments, Inc.

By copy hereof, I am serving a copy of said documents on all counsel of record.

Please file stamp our copy for our records. Thank you for your courtesy.

Very truly yours,

RODRIGUEZ, COLVIN & CHANEY, L.L.P.

*[Handwritten Signature]*  
Alison Kennamer

ADK/pg  
w/enclosures

cc: Mr. Norman Jolly  
Attorney at Law  
1018 Preston, 4th Floor  
Houston, Texas 77002

Mr. James J. Parker  
Red & Parker, L.L.P.  
12200 NW Freeway  
Houston, Texas 77092

Mr. Ramon Garcia  
Law Offices of Ramon Garcia  
Attorneys at Law  
222 West University Drive  
Edinburg, Texas 78539

Mr. Anthony B. James  
Ms. Lorraine Torres  
134 East Van Buren,  
Harlingen, Texas 78550

Ms. Alicia M. Matsushima  
Law Office of William W. Keas, Jr.  
Attorneys at Law  
101 North Shoreline, Suite 216  
Corpus Christi, Texas 78401

Mr. Johnny Carter  
Mr. Eric Mayer  
Susman & Godfrey  
1000 Louisiana, Suite 5100  
Houston, Texas 77002

Ms. Michaela Alvarez  
Hols & Alvarez, L.L.P.  
612 West Nolana  
McAllen, Texas 78504

Mr. Andrew Schirrmelster  
Schirrmelster Ajámié  
711 Louisiana, Suite 2150  
Houston, Texas 77002

Epstein, Sally

**From:** McGuirk, Andy [a-mcguirk@email.mc.tl.com]  
**Sent:** Tuesday, June 01, 1999 9:39 AM  
**To:** Pechonis, John; Dagus, Bryan; Frois, Stephen; Watt, Jim  
**CC:** Baumann, Russ  
**Subject:** FW: Ford Core (sam update)



For your background info as we host Steve reidura wed

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST N/S 23-03  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3743  
MOBILE: (508) 208-6119  
PAGE: (800) 487-3700 PIN 604-2044

**From:** McGuirk, Andy  
**Sent:** Friday, May 28, 1999 1:22 PM  
**To:** 'Frederick J. Foster'  
**CC:** Bexinghaus, Steven; Sharpe, Robert  
**Subject:** Ford Core team update

Fred, per our discussions and Rob Sharpe's visit enclosed is our updates...

<<FredFertCera.doc>> <<synopsis.doc>> <<TESTLOGS.xls>>  
<<77P8L2\_1.xls>>

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST N/S 23-03  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3743  
MOBILE: (508) 208-6119  
PAGE: (800) 487-3700 PIN 604-2044



TI-NHTSA 015990

May 26, 1999

Mr. Frederick J. Porter, Supervisor  
E/E Systems Engineering  
Building 5, Mail Drop 5011  
20000 Rotunda Drive, Rm 3E004  
Dearborn MI 48121-2053

Dear Fred:

I want to review our recent support of the Ford core team to assure we do not have any misunderstandings regarding our pressure switch performance, our continued contribution to the 'core' team, and our commitment to a quick conclusion.

For six months the Texas Instruments Automotive Sensors & Controls Team has been supporting the Ford Core Diagnostic Team with technical facts, data, and analysis regarding our brake pressure switch product applied in the Ford cruise control deactivation circuit.

A senior TI pressure switch engineer was in residence at Ford for three weeks to assist with switch related issues in the system-diagnostic process. Senior TI leadership participation has also been involved in virtually every Ford Core Team meeting delivering facts, data, and technical support year-to-date '99.

We also investigated switch capability, and using agreed upon accelerated simulation life testing techniques, demonstrated the ability of the model year '92 & '93, Town Car speed control deactivation switches to consistently exceed "cycle life specification" of 500,000 pressure cycles. TI Weibull reports of pressure switches tested in 1999 conservatively demonstrate 95% reliability to 1 million cycles (with confidence intervals greater than 50%).

Additionally "success testing records" of some 685 ES units that were tested during the 1991 - 1992 (11/91 - 12/92) showed zero leakage at 500,000 cycles.

Conclusion to date: 1992 period switches met specification. 1999 switch meets or exceeds specification

We have developed and delivered a model of accelerated performance simulation of the switch. The model is a physical model of the switch which is populated with a simulation of constant power as described in the speed control circuit. Theories from the model suggest that noise in the switch cavity in the presence of uninterrupted power could lead to a corrosion product formation which might create a plastic base ignition path.

TI-NHTSA 016891

Mr. Fred Porter  
May 26, 1999  
Page 2

Conclusion to date: Constant speed control power allows long term corrosion

In light of this laboratory model and the need for cruise system power only during vehicle operation, we suggest the system architecture of "key-on/off" based power be considered.

We have been open and forthright in our communications and delivery of information and we believe we have been instrumental in helping Ford address the underhood fire concern issue.

In this regard, we think it is appropriate at this point that our active participation in the diagnostic journey of the vintage 1992 product move towards a timely conclusion. Toward this end, we will continue to support the "core" team review of 1992 product history with targeted completion in July 1999.

We are preparing to fulfill your request for hosting a site visit, supporting campaign field return device analysis, and participating in robust system brainstorming sessions moving toward conclusion in July, as well as reviewing the optimization of our product line process controls.

Our prime focus at this time is in rapidly supplying Ford with 225,000 units in support of the field actions.

Regards,

Andrew C. McGuirk  
ORA Manager  
Texas Instruments

attachments: 1992 Testing History  
TI 77PS Test synopsis  
TI 77PS Investigation Flow Diagram

TI-NHTSA 015892

## TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

• **Test 1**

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch hexport electrically grounded.

**Results:** (8) samples were tested total:  
(2) with 4% H<sub>2</sub>O in brake fluid.  
(2) with 6% H<sub>2</sub>O in brake fluid.  
(2) with 10% H<sub>2</sub>O in brake fluid.  
(2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 015993

• Test 2

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.  
14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).  
Switch hexport electrically grounded.

Results: (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

Conclusion: A (1) Amp load through switch terminals did not ignite brake fluid in the contact cavity of switches.

• Test 6

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.  
Power applied to the heater element until plastic base melts.  
Spark generated in contact cavity of switch.  
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

Results: (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Conclusion: A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.  
5 watts of power dissipated in heating element.  
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 016894

**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• **Test 6a**

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5 Ohms. A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.  
Continuous 14 Volt power applied to the switch.  
Hasport is grounded.  
Current is limited at 15 Amps.

• **Test 6c**

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• **Test 7**

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PBL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

TI-NHTSA 015895

TI 77P2 Test Synopsis 06/21/99



occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• Test 15a

**Objective:** Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm and an increase in hexport current.

• Test 17

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.  
Switches at continuous 14 Volts power.  
Switches subjected to vibration for (1) hour per day.  
Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. These results are consistent with results previously found in Test 15a at the 300 hour point.

TI-NHTSA 016886

Conclusion: New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current versus time show an increase in current until the point of ignition.

Conclusion: A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

Objective: Compare various fluids in the established ignition method.

Results: The following fluids were tested.

(1) NaCl in H<sub>2</sub>O.

(1) tap water

(1) rain water

(1) used brake fluid

(1) used brake fluid with 5 wt. % H<sub>2</sub>O

(1) new brake fluid

(1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

Conclusion: Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition within a 3 hour lab test. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O can cause an ignition in a 3 hour lab test exposure.

• Test 15

Objective: Compare the ignition characteristics of various plastics as switch base material.

Results: When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusions: All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

Objective: Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

Results: Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

Level 5 Objective:

Test 16

• Objective: Test proposed relay circuit.

Results: (1) switch was injected with a solution of 5 wt. % NaCl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition.

TI-NHTSA 015889

TI 7778 Test Synopsi 06/15/90

Brake Pressure Switch Test Log, Updated 8/22/99

Category	Test	Location	Test Parameters	Results Update
Leak Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in new Brake Fluid 14Vdc to one terminal, harness grounded Water Conc: 4%, 6%, 10%, 75%	200+ hours, Current draw in the 0.5mA to 5mA range Field has shorted out No significant temperature rise. Test suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, harness grounded	250+ hours, Constant temperature. No significant temperature rise with time Test suspended.
	3	AVT	new Brake Fluid in Switch, 24 VDC to one terminal, harness grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	new Brake Fluid in Switch, 24 VDC to one terminal, harness grounded, Ambient at 100 C	50 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	new Brake Fluid in Switch, 10 Amps through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	new Brake Fluid in Switch approx. 50 Amps through Switch Terminals	Temperature rise to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Small heater elements into Switch. Heat in failure, include opening. 71% solution of Brake Fluid and 6 wt. % H <sub>2</sub> O	3 tests, Smoke observed, ignition observed on part heater One attached Test complete Smoke field is easily blown down heat build-up Smoke observed at 675 F, hose melts and falls off at 800 F
	6a	TI	Coarse heater by convolving spring into but water solution, 14V between spring and harness	One set of 15 devices increased resistance to 5 ohms. Others either very low resistance or nonconductive It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through harness. See photo and video.
	6c	TI	Pure new brake fluid with metal shavings	Additional test include the water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TI-NHTSA 018900

Brake Pressure Switch Test Log, Updated 8/22/99

				conducibility
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per ES	First leak observed at 720,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	8	Central Labs	Field returns from dealer labs, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (T) Evaluating Factors Effecting Diaphragm Wear	10	TI	Vary water concentration in 'new' Brake Fluid 12 samp • 12 quiet switches w/ 0 % water in BF 12 samp • 12 quiet switches w/ 5 % water in BF	[Test] Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess changing environment.
Impulse test				
On-Vehicle Characterization of Pressure & Temperature Profile in Test Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT.....see Ford charts...>500k in car?
Brake Fluid analysis Used fluid at master cylinder.	11a	TI	Analysis used brake fluid at the master cylinder (RMC), used brake fluid at the caliper (LCA) and new brake fluid (NEW) for rust and water content.	Test complete. RMC: Cu = 415 (ug/ml), Fe = 6.6 (ug/ml), Cr = 6.08 (ug/ml), 1.1 %H2O LCA: Cu = 582 (ug/ml), Fe = 5.5 (ug/ml), Cr = 1.8 (ug/ml), 1.1 %H2O NEW: Cu = <0.01 (ug/ml), Fe = 0.02 (ug/ml), Cr = <0.01 (ug/ml), 0.3 %H2O
Spark Arc Study	12	Central Labs	Determine if arcing/spark occurs in switch using switch heads and high speed video. Use dry switches as well as switches with various brake fluid under stress.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from junkyards & other sources	13	Central Labs	Chemical/electrical, mechanical and chemical aspects of retrieved switches	Test log and analysis methodology set up complete. Analysis of switches in progress.
Fluid ingress tests	13a	TI	Repeat ignition simulation with different fluids. (3) hour tests: 5% NaCl in tap water rain water (24) hour tests: tap water	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mA/amps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mA/amps and showed some signs of corrosion.

TI-NHTSA 016901

Brake Pressure Switch Test Log, Updated 6/22/00

			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 6% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Very simple concentration in test brake fluid	Test completed. Analysis in process to assess test findings.
Repeat of test 10			10 amp + 20 quib switches w/ 6% water in BF	
			20 amp + 20 quib switches w/ 6% water in BF	
Compatibility of Repton with Oxalic Acid	14	Dupont	Characterize change in properties of Repton with various % oxalic acid in brake fluid	Test in progress (100 hours completed). Oxalic Acid shows minor effects but water has no Repton precipitate.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and availability of different grades of plastic rods with addition to improved plastic part performance	Test completed. Colson and Hylar tested 20 and 250 lbs P.T.C. material tested 100 failures
Long duration brake fluid exposure test	16a	TI	(1) samples with new brake fluid (2) samples with used brake fluid	Test completed (100) hours completed. Used brake fluid current dropped off by <170 mA/amp. New BF showed current was increase of flow under const. power
Evaluation of Switch Orientation	16b	TI	Assess switch availability in switch orientation. Test vertical versus 45 degree. Test horizontal versus 45 deg. orientation.	Test completed. Switch is impacted in switch orientation. Increased switch failures can occur in vertical or 45 degree angle. Switch failures are minimal in switch rotational alignment.
Relay Circuit Test	18	TI	Remove and test in field relay circuit for 100 hrs. Bring switch to operating position in 100 Amp circuit then place in relay circuit for 100 hrs. Repeat after circuit power has been on 48 hrs.	Test completed. 100 hours. Coverage this test is fully followed. switched power in circuit to create or move toward failure in lab failure element was verified in the field.
Long duration brake fluid exposure test number 2	17	TI	(1) 1000 hours test with new brake fluid (1) hour of vibration per day (1) hour soak at 100 deg C per day	Test completed. 1000 hours completed. Average input current is 1.5 mA/amp (activation = 1.8 mA/amp)

71-NHTSA 016902

## 77PBL2-1: Impulse Data Results 11/91 - 12/92

preliminary draft summary of TI record search findings of May 14-17 1999

summary by Steve Beringhouse &amp; Andy McQuirk May 19th 1999

TI PN: 77PBL2-1

Ford P/N: F2VC-99934-AB

Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Qty	
		Impulse Tested	Leak
25-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
7-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,850	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
13-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
25-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 015903




77PSL2-1: Impulse Data Results 11/81 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
15-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals units</b>	<b>265,696</b>	<b>669</b>	<b>-</b>
---------------------	----------------	------------	----------

TI-NHTSA 015904



TI-NHTSA 018905


DEPOSITION  
EXHIBIT

TI-NHTSA 016908

DEPOSITION  
EIGHT  
4

DEPOSITION  
EXHIBIT  
5

.001" teflon



500 FN 131




.005" thick

Teflon  
coated  
Kapton

.003" polyimide

## Scenario



1. Contamination enters switch cavity through perforated kapton seal or connector seal.
2. Switch components and cap corrode with aid of electric field and contamination.
3. Current path forms between battery and ground.
4. Current increases as material builds until heat is generated to melt plastic.
5. When plastic melts enough to open the switch cavity to external air, the plastic ignites consuming the switch housing and connector.



Mead

DEPOSITION  
EXHIBIT  
7

NEAT SHEETS

**80 SHEETS**

COLLEGE RULED

11 x 8 1/2 in / 27.9 x 21.5 cm

SUBJECT


NEATBOOK<sup>®</sup> NOTEBOOK

TI-NHTSA 018909



Steve Rivers

313-390-3286



Thru end of Jan. A  
 9/13 = 69%

February 92 B  
 10/11 = 91%

March 92 - Dec '92 C  
 5/16 = 31%

Total = 24/40 = 60

TI 0001112C

TI-NHTSA 016911