

**EA02-025**

**TEXAS INSTRUMENTS, INC.'S**

**9/10/03**

**REQUEST NO. 7**

**BOX 9**

**PART A – R**

**PART C**

**Epstein, Sally**

**From:** Frola, Stephen [s-proia@emall.motl.com]  
**Sent:** Tuesday, May 18, 1999 3:35 PM  
**To:** Beringhaus, Steven  
**Cc:** Pechonis, John; McGuirk, Andy; Dagus, Bryan  
**Subject:** 77P8L2\_1.xls



77P8L2\_1.xls

Revised version of spreadsheet.

<<77P8L2\_1.xls>>

Regards,

Steve

## 77PBL2-1: Impulse Data Results 11/91 - 12/92

Date: 18-May-99  
 TI P/N: 77PBL2-1  
 Ford P/N: F2VC-9P924-AB

Date	Lot Size	Qty Impulse Tested	Qty Leak
26-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,650	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 013868

77PBL2-1: Impulse Data Results 11/81 - 12/82

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals</b>	<b>268,600</b>	<b>645</b>	<b>-</b>
---------------	----------------	------------	----------

**Plastic Generation Matrix  
(FOR REFERENCE ONLY)**

<b>FORD Part Number</b>	<b>Texas Instruments Part Number</b>	<b>Generation Of Plastic Material</b>	<b>UL Designation</b>
F2YC-8P824-AB F8LC-8P824-AA	77P8L2-1 77P8L2-3	Celanex 4300 Celanex 4300	UL (HB) UL (HB)
F2YC-8P824-AB F8LC-8P824-AA	77P8L3-1 77P8L3-3	Celanex 4300 Celanex 4300	UL (HB) UL (HB)
F2AC-8P824-AA 84DA-8P824-AA F3DC-8P824-AA	77P8L3-1 77P8L4-1 77P8L5-2	GE Noryl GTX 830 GE Noryl GTX 830 GE Noryl GTX 830	UL (HB) UL (HB) UL (HB)
F2AC-8P824-AA F2YC-8P824-AB F3DC-8P824-AA F3TA-8P824-CA	77P8L3-1 77P8L3-1 77P8L3-2 77P8L3-3	GE Noryl GTX 830 Celanex 4300 GE Noryl GTX 830 GE Noryl GTX 830	UL (HB) UL (HB) UL (HB) UL (HB)
F55A-8P824-AA	77P8L3-2	GE Noryl GTX 830	* UL (HB)

\* UL(HB)= Horizontal Burn

**Currey, Pat**

---

**From:** Proia, Stephen [s-proia@small.mc.ti.com]  
**Sent:** Tuesday, May 18, 1999 3:21 PM  
**To:** Beringhouse, Steven  
**Cc:** McGuirk, Andy; Pechonis, John; Dagus, Bryan  
**Subject:** 77PSL2\_1.xls



77PSL2\_1.xls

<<77PSL2\_1.xls>>

Steve,

I've summarized the data per our discussion. I have also reviewed the files in marketing without success. Please let us know if you need anything else.

Regards,

Steve

77PBL2-1: Impulse Data Results 11/91 - 12/92

Date: 19-May-99  
 TI record search findings of May 14-17 '99  
 TI FR#: 77PBL2-1  
 Ford P/N: FZVC4P924-AB  
 Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Qty Impulses Tested	Qty Leak
26-Nov-91	4,000	10	.
26-Nov-91	4,000	10	.
5-Dec-91	4,000	10	.
5-Dec-91	4,000	10	.
9-Dec-91	4,000	10	.
9-Dec-91	2,000	5	.
11-Dec-91	4,000	10	.
11-Dec-91	4,000	10	.
13-Dec-91	4,000	10	.
14-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
2-Jan-92	4,000	10	.
6-Jan-92	4,000	10	.
7-Jan-92	2,000	5	.
8-Jan-92	4,000	10	.
8-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
15-Jan-92	4,000	10	.
28-Jan-92	2,000	5	.
31-Jan-92	4,000	10	.
2-Feb-92	1,650	5	.
4-Feb-92	4,000	10	.
5-Feb-92	4,000	10	.
6-Feb-92	4,000	10	.
10-Feb-92	4,000	10	.
11-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
15-Feb-92	4,000	10	.
24-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
8-Mar-92	4,000	10	.
10-Mar-92	4,000	10	.
11-Mar-92	4,000	10	.
12-Mar-92	4,000	10	.

TI-NHTSA 01387

77PBL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
23-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals</b>	<b>268,400</b>	<b>640</b>	<b>-</b>
---------------	----------------	------------	----------

TI-NHT&A 013573



77PBL2-1: Impulse Data Results 11/91 - 12/92

preliminary draft summary of TI record search findings of May 14-17 1999

summary by Steve Boringhaus & Andy McGuirk May 19th 1999

TI P/N: 77PBL2-1

Food P/N: FTVC-9F924-AB

Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Qty Impulse Tested	Qty Leak
26-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,650	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 013574

77PSL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
21-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals</b>	<b>units</b>	<b>265,630</b>	<b>663</b>	<b>-</b>
---------------	--------------	----------------	------------	----------

TI-NHTSA 013575

107  
50

preliminary draft summary of TI record search findings of May 14-17 1999

summary by Steve Burtigause & Andy McGuirk May 19th 1999

TI P/N: 77P8L2-1

Ford P/N: F2VC-9F924-AB

Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Impulse Tested	Qty Look
26-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,630	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-

TI-NHTSA 013576

TTPQL2-1: Impulse Data Results 11/91 - 12/92

11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-
18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

Disappointed Aziz get p. to off  
Aziz's year con. variation  
a long focused when here

Totals units 169,600 668 -

Greg Stevens

Friday Restis

switch only 92-93 timeframe  
Yield  
SPC  
Change History  
Improvement  
Build a fence → after Tom/Dick/Harry no claim

TI-NHTSA 013677

**Curry, Pat**

---

**From:** McGuirk, Andy [a-mcguirk@email.mc.tl.com]  
**Sent:** Wednesday, May 19, 1999 11:46 AM  
**To:** Sharpe, Robert  
**Cc:** Baumann, Russ  
**Subject:** my first draft 77PSL2\_1.xls



77PSL2\_1.xls

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST M/S 23-05  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3749  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 604-2044

<<77PSL2\_1.xls>>

Regards,

andy

TI-NHTSA 013579

TI P/N: 77PSL2-1  
 Ford P/N: F2VC-9F924-AB

Date	Lot Size	Qty Inspected	Qty Pass	Qty Leak	Comments
26-Nov-91	4,000	10	10	.	
26-Nov-91	4,000	10	10	.	
5-Dec-91	4,000	10	10	.	
5-Dec-91	4,000	10	10	.	
9-Dec-91	4,000	10	10	.	
9-Dec-91	2,000	5	5	.	
11-Dec-91	4,000	10	10	.	
11-Dec-91	4,000	10	10	.	
13-Dec-91	4,000	10	10	.	
14-Dec-91	4,000	10	10	.	
16-Dec-91	4,000	10	10	.	
16-Dec-91	4,000	10	10	.	
2-Jan-92	4,000	10	10	.	
6-Jan-92	4,000	10	10	.	
7-Jan-92	2,000	5	5	.	
8-Jan-92	4,000	10	10	.	
8-Jan-92	4,000	10	10	.	
14-Jan-92	4,000	10	10	.	
14-Jan-92	4,000	10	10	.	
15-Jan-92	4,000	10	10	.	
28-Jan-92	2,000	5	5	.	
31-Jan-92	4,000	10	10	.	
2-Feb-92	1,600	5	4	.	Broken spring
4-Feb-92	4,000	10	10	.	
5-Feb-92	4,000	10	10	.	
6-Feb-92	4,000	10	10	.	
10-Feb-92	4,000	10	10	.	
11-Feb-92	4,000	10	10	.	
12-Feb-92	4,000	10	10	.	
12-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
15-Feb-92	4,000	10	10	.	
24-Feb-92	4,000	10	10	.	
25-Feb-92	4,000	10	10	.	
26-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	9	.	Continuity failure, terminal inside of base is not sealed, Date code 2057. Sorted lot 100%.
6-Mar-92	4,000	10	10	.	

TI-NHTSA 013680

10-Mar-92	4,000	10	10	-
11-Mar-92	4,000	10	10	-
12-Mar-92	4,000	10	10	-
18-Mar-92	4,000	10	10	-
23-Apr-92	2,000	5	5	-
2-May-92	2,000	5	5	-
5-May-92	2,000	5	5	-
6-May-92	2,000	5	5	-
14-Sep-92	2,000	5	5	-
22-Sep-92	4,000	10	10	-
30-Sep-92	4,000	10	10	-
7-Oct-92	4,000	10	10	-
7-Oct-92	4,000	10	10	-
16-Oct-92	4,000	10	10	-
21-Oct-92	2,000	5	5	-
20-Oct-92	4,000	10	10	-
29-Oct-92	4,000	10	10	-
29-Oct-92	4,000	10	10	-
30-Oct-92	4,000	10	10	-
4-Nov-92	4,000	10	10	-
10-Nov-92	4,000	10	10	-
10-Nov-92	4,000	10	10	-
11-Nov-92	4,000	10	10	-
17-Nov-92	2,000	5	5	-
20-Nov-92	4,000	10	10	-
4-Dec-92	2,000	5	5	-
9-Dec-92	2,000	5	5	-
14-Dec-92	2,000	5	5	-
15-Dec-92	4,000	10	10	-
16-Dec-92	4,000	10	10	-
16-Dec-92	4,000	10	10	-
21-Dec-92	2,000	5	5	-
21-Dec-92	4,000	10	10	-

<b>Totals</b>	<b>348,000</b>	<b>600</b>	<b>600</b>	<b>-</b>
---------------	----------------	------------	------------	----------

TI-NHTSA 013581

**Currey, Pat**

---

**From:** Dagus, Bryan [bdagus@email.mc.tl.com]  
**Sent:** Wednesday, May 19, 1999 10:48 AM  
**To:** McGuirk, Andy

**Importance:** High



77PBL2\_1.xls



77PBL2\_1.xls

Andy,

Here are both revs.

Bry  
<<77PBL2\_1.xls>> <<77PBL2\_1.xls>>

TI-NHTSA 0135B2



**Carrey, Pat**

---

**From:** Proia, Stephen [s-proia@email.mc.ti.com]  
**Sent:** Tuesday, May 18, 1999 3:35 PM  
**To:** Beringhouse, Steven  
**Cc:** Pechonis, John; McGuirk, Andy; Dagus, Bryan  
**Subject:** 77PSL2\_1.xls



77PSL2\_1.xls

Revised version of spreadsheet.

<<77PSL2\_1.xls>>

Regards,

Steve

TI-NHTSA 013583

77PBL2-1: Impulse Data Results 11/91 - 12/92

preliminary draft summary of TI record search findings of May 14-17 1999

summary by Steve Buringhaus & Andy McGuirk May 19th 1999

TI P/N: 77PBL2-1

Ford P/N: F2VC-9F924-AB

Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Qty Impulse Tested	Qty Leak
26-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,650	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 013584

77PSL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals</b>	<b>258,679</b>	<b>668</b>	<b>-</b>
---------------	----------------	------------	----------

**Curry, Pat**

---

**From:** Proia, Stephen [s-proia@email.mc.ti.com]  
**Sent:** Tuesday, May 18, 1999 3:21 PM  
**To:** Beringhaus, Steven  
**Cc:** McGuirk, Andy; Pechonia, John; Dague, Bryan  
**Subject:** 77PSL2\_1.xls



77PSL2\_1.xls

<<77PSL2\_1.xls>>

Steve,

I've summarized the data per our discussion. I have also reviewed the files in marketing without success. Please let me know if you need anything else.

Regards,

Steve

TI-NHTSA 013586

## 77PBL2-1: Impulse Data Results 11/91 - 12/92

Date: 19-May-99  
 TI record search findings of May 14-17 '99  
 TI P/N: 77PBL2-1  
 Ford P/N: F2VC-9F924-AB  
 Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Qty Impulse Tested	Qty Leak
26-Nov-91	4,000	10	.
26-Nov-91	4,000	10	.
5-Dec-91	4,000	10	.
5-Dec-91	4,000	10	.
9-Dec-91	4,000	10	.
9-Dec-91	2,000	5	.
11-Dec-91	4,000	10	.
11-Dec-91	4,000	10	.
13-Dec-91	4,000	10	.
14-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
2-Jan-92	4,000	10	.
6-Jan-92	4,000	10	.
7-Jan-92	2,000	5	.
8-Jan-92	4,000	10	.
8-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
15-Jan-92	4,000	10	.
28-Jan-92	2,000	5	.
31-Jan-92	4,000	10	.
2-Feb-92	1,600	5	.
4-Feb-92	4,000	10	.
5-Feb-92	4,000	10	.
6-Feb-92	4,000	10	.
10-Feb-92	4,000	10	.
11-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
15-Feb-92	4,000	10	.
24-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
6-Mar-92	4,000	10	.
10-Mar-92	4,000	10	.
11-Mar-92	4,000	10	.
12-Mar-92	4,000	10	.

TI-NHTSA 013887

77PBL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	.
23-Apr-92	2,000	5	.
2-May-92	2,000	5	.
5-May-92	2,000	5	.
6-May-92	2,000	5	.
14-Sep-92	2,000	5	.
22-Sep-92	4,000	10	.
30-Sep-92	4,000	10	.
7-Oct-92	4,000	10	.
7-Oct-92	4,000	10	.
16-Oct-92	4,000	10	.
21-Oct-92	2,000	5	.
20-Oct-92	4,000	10	.
29-Oct-92	4,000	10	.
29-Oct-92	4,000	10	.
30-Oct-92	4,000	10	.
4-Nov-92	4,000	10	.
10-Nov-92	4,000	10	.
10-Nov-92	4,000	10	.
11-Nov-92	4,000	10	.
17-Nov-92	2,000	5	.
20-Nov-92	4,000	10	.
4-Dec-92	2,000	5	.
9-Dec-92	2,000	5	.
14-Dec-92	2,000	5	.
16-Dec-92	4,000	10	.
16-Dec-92	4,000	10	.
16-Dec-92	4,000	10	.
21-Dec-92	2,000	5	.
21-Dec-92	4,000	10	.
<b>Totals</b>	<b>222,000</b>	<b>668</b>	<b>.</b>

**Currey, Pat**

---

**REDACTED**

---

-----  
From: Mulligan, Sean  
Sent: Thursday, May 20, 1999 9:12 AM  
To: McGuirk, Andy; Beringhouse, Steven  
Subject: Test Report Synopsis and testlog.

Please review the latest version of the Test synopsis and Test log.

<<synopsis.doc>> <<TESTLOG9.xls>>

Revised items on the Test Synopsis are highlighted in red. There have been minor changes throughout the document so it is worth skimming the entire document (esp. in light of recent developments).

The following items have been updated on the test log:  
Test 14, 15a and 17.

Awaiting your feedback,

All the best,

Sean P. Mulligan

Texas Instruments  
Automotive Sensors & Controls  
Mechanical Design  
Phone (508) 236-2535  
Fax (508) 236-3586

## TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

- Test 1

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch hexport electrically grounded.

**Results:**

- (8) samples were tested total:
- (2) with 4% H<sub>2</sub>O in brake fluid.
- (2) with 6% H<sub>2</sub>O in brake fluid.
- (2) with 10% H<sub>2</sub>O in brake fluid.
- (2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013590



• Test 2

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.  
14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).  
Switch heatport electrically grounded.

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• Test 6

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.  
Power applied to the heater element until plastic base melts.  
Spark generated in contact cavity of switch.  
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.  
5 watts of power dissipated in heating element.  
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 013591

**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• Test 6a

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5  $\Omega$ s. A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.  
Continuous 14 Volt power applied to the switch.  
Hexport is grounded.  
Current is limited at 15 Amps.

• Test 6c

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• Test 7

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• Test 15a

**Objective:** Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• Test 17

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

- Contact cavity of switch flooded with new brake fluid.
- Switches at continuous 14 Volts power.
- Switches subjected to vibration for (1) hour per day.
- Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

**Conclusion:** New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O is necessary to cause an ignition.

- **Test 15**

**Objective:** Compare the ignition characteristics of various plastics as switch base material.

**Results:** When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Collanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

- **Test 15b**

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

**Conclusion:** Switch ignition does not appear to be sensitive to vertical orientation verses 45° orientation nor to rotational angle in the 45° orientation.

### **Level 5 Objective:**

#### **Test 16**

- **Objective:** Test proposed relay circuit.

**Results:** (1) switch was injected with a solution of 5 wt. % NaCl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for(18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

Brake Pressure Switch Test Log, Updated 7/12/89

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in new Brake Fluid 14Vdc to one terminal, hasport grounded Water Conc: 4%, 6%, 10%, 75%	260+ hours, Current clear in the 0.5mA to 5mA range Fluid has dissolved. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, hasport grounded	260+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	new Brake Fluid in Switch, 24 VDC to one terminal. Hasport Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	new Brake Fluid in Switch, 24 VDC to one terminal. Hasport Grounded, Ambient at 100 C	16 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	new Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp. Delta T reached steady state at 20 C. Test suspended.
	6a	AVT	new Brake Fluid in Switch approx. 80 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat III failure, include sparking. (I) w/ solution of Brake Fluid and 6 wt. % H <sub>2</sub> O	3 tested. Smoke observed, ignition observed on part wheeler See attachment Test complete Brake fluid in cavity slows down heat build-up Smoke observed at 675 F, Base melts and falls off at 800 F
	6a	TI	Create heater by corroding spring with Salt water solution, 14V between spring and hasport	One out of 16 devices increased resistance to 5 ohms. Others either very low resistance or megohms. It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 6% water solution into switch Current path is through hasport. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TI-NHTSA 013697

**Brake Pressure Switch Test Log, Updated 7/12/99**

				conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per ES	Final leak observed at 720,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Control Labs	Field returns, from dealer lots, justyards	Parts in Control Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear Impulse test	10	TI	Very water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0 % water in BF 12 snap + 12 quiet switches w/ 5 % water in BF	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap sample suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet sample suspended at 500k cycles to assess Sealing anomalies.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT....see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (BMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. BMC: Cu = 415 (ppm), Fe = 8.6 (ppm), Cr = 0.88 (ppm), 1.1 %H2O. UCA: Cu = 592 (ppm), Fe = 8.5 (ppm), Cr = 1.9 (ppm), 1.1 %H2O. NEW: Cu = <0.01 (ppm), Fe = 0.82 (ppm), Cr = <0.01 (ppm), 0.3 %H2O.
Spark Arc Study	12	Control Labs	Determine if arcing forms in switch using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water mixes.	Equipment set-up in progress at Control Labs. ?) Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field justyards & other sources	13	Control Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Fluid Ingress Tests	13a	TI	Repeat ignition simulation with different fluids. (8) hour tests: 5% NaCl in tap water rain water (24) hour tests: tap water used brake fluid	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mAmps and showed some signs of corrosion. Chemical analysis in process.

TI-NHTSA 013688



Brake Pressure Switch Test Log, Updated 7/12/98

			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2) Repeat of test 10	13b	TI	Very vapor concentrations in 'new' Brake Fluid 10 eng + 20 quiet switches w/ 0 % water in BF 10 eng + 20 quiet switches w/ 5 % water in BF	Test suspended. Analysis in process to assess test failure.
Compatibility of Kapton with Oxalic Acid	14	Dupont	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects that water has on Kapton properties.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and moldability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl Ignited 3/5 and 2/5 trials ZYTEL samples tested US Ignition
Long duration brake fluid Ingress test.	15a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test suspended (550) hours completed. Used brake fluid current dropped off to <1/10 mAmp. New BF hasport current can increase w/ time under cont. power.
Evaluation of Switch Orientation	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Simulated switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 13a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (18) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or move toward ignition in lab Heater element was warm to the touch.
Long duration brake fluid Ingress test number 2.	17	TI	(20) samples filled with new brake fluid (1) hour of vibration per day (1) hour soak at 100 deg C per day	Test suspended. (312) hours completed. Average hasport current is 1.8 mAmp (std deviation = 1.8 mAmps)

TI-NHTSA 013889

**REDACTED**

**From:** Mulligan, Sean  
**Sent:** Thursday, May 20, 1999 9:12 AM  
**To:** McGuirk, Andy; Beringhouse, Steven  
**Subject:** Test Report Synopsis and testlog.

Please review the latest version of the Test synopsis and Test log.



synopsis.doc



TESTLOG.doc

Revised items on the Test Synopsis are highlighted in red. There have been minor changes throughout the document so it is worth skimming the entire document (esp. in light of recent developments).

The following items have been updated on the test log:  
Test 14, 16a and 17.

Awaiting your feedback.

*All the best,*

*Sean P. Mulligan*

**Texas Instruments  
Automotive Sensors & Controls  
Mechanical Design  
Phone (508) 236-2535  
Fax (508) 236-3586**

## TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

- Test 1

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch hexport electrically grounded.

**Results:**

- (8) samples were tested total:
- (2) with 4% H<sub>2</sub>O in brake fluid.
- (2) with 6% H<sub>2</sub>O in brake fluid.
- (2) with 10% H<sub>2</sub>O in brake fluid.
- (2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

• **Test 2**

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

**Switch contact flooded with brake fluid.**

**14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).**

**Switch hexport electrically grounded.**

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• **Test 6**

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

**Heater element installed in contact cavity of the switch.**

**Power applied to the heater element until plastic base melts.**

**Spark generated in contact cavity of switch.**

**Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).**

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

**Wet device:** The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Dry device:** The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

**Heater element installed in the switch contact cavity.**

**5 watts of power dissipated in heating element.**

**Spark generated in the contact cavity of the switch.**

**Brake fluid did not contribute to the ignition process.**

**TI-NHTSA 013803**

**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

- **Test 6a**

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5  $\Omega$ s. A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

- A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.
- Continuous 14 Volt power applied to the switch.
- Hazport is grounded.
- Current is limited at 15 Amps.

- **Test 6c**

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

- **Test 7**

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

**Objective:** Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.

Switches at continuous 14 Volts power.

Switches subjected to vibration for (1) hour per day.

Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (30) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

**Conclusion:** New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

- Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

- Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of



corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O is necessary to cause an ignition.

• **Test 15**

**Objective:** Compare the ignition characteristics of various plastics as switch base material.

**Results:** When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

• **Test 15b**

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

**Conclusion:** Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

**Level 5 Objective:**

**Test 16**

• **Objective:** Test proposed relay circuit.

**Results:** (1) switch was injected with a solution of 5 wt. % NaCl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

**Conclusion:** 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

Brake Pressure Switch Test Log, Updated 09/10/1999

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in 'new' Brake Fluid 14Vdc to one terminal, hotspot grounded Water Conc: 4%, 6%, 10%, 70%	220+ hours, Current draw in the 0.5mA to 6mA range Fluid has discolored. No Significant Temperature rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, hotspot grounded	220+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Hotspot Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Hotspot Grounded, Ambient at 100 C	18 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps through Switch Terminals	Temperature rose to approx. 270 F. No cracks. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat on failure, include opening. (1) w/ solution of Brake Fluid and 8 wt. % H <sub>2</sub> O	3 tested. Smoke observed, ignition observed on part welder One attachment Test complete Brake fluid in cavity stays clear from heat build-up Smoke observed at 675 F, Base melts and falls off at 800 F
	6a	TI	Create heater by corroding spring arm Salt water solution, 14V between spring and hotspot	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or inoperative It took about 100 hours to reach the 5 ohm stage. This 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 8% water solution into switch Current path is through hotspot. See photo and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test includes tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TL-NHTSA 013609

Brake Pressure Switch Test Log, Updated 08/10/1999

				conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per ES	First leak observed at 728,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Central Labs	Field returns, from dealer lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear Inguine test	10	TI	Vary water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0 % water in BF 12 snap + 12 quiet switches w/ 5 % water in BF	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.2M. Quiet samples suspended at 500k cycles to assess fatigue processes.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT...see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. UMC: Cu = 415 (ppm), Fe = 5.6 (ppm), Cr = 0.08 (ppm), 1.1 %H2O. UCA: Cu = 882 (ppm), Fe = 5.5 (ppm), Cr = 1.9 (ppm), 1.1 %H2O. NEW: Cu = <0.01 (ppm), Fe = 0.82 (ppm), Cr = <0.01 (ppm), 0.3 %H2O.
Spall / Arc Study	12	Central Labs	Determine if arcing forms in switch using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water mixes.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' spalls observed
Characterization of switches retrieved from field junkyards & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of retrieved switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Ingress Tests	13a	TI	Repeat ignition simulation with different fluids. (2) hour tests: 5% NaCl in tap water rain water (24) hour tests: tap water used brake fluid	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mAmps and showed some signs of corrosion. Chemical analysis in process.

TI-NHTSA 013610

Brake Pressure Switch Test Log, Updated 06/10/1999

			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Very water concentrations in new Brake Fluid	Test suspended. Analysis in process to assess test failure.
Repeat of test 10			10 amp + 20 quiet switches w/ 0 % water in BF	
			10 amp + 20 quiet switches w/ 5 % water in BF	
Compatibility of Kevlar with Oxalic Acid	14	Dupont	Characterize change in properties of Kevlar with various % oxalic acid in brake fluid.	Test in progress (180) hours completed. Oxalic acid shows similar effects that water has on Kevlar properties.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and moldability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Meryl ignited 3/5 and 2/5 trials ZYTEL samples tested 1/6 ignitions
Long duration brake fluid ingress test.	15a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test suspended (350) hours completed. Used brake fluid current dropped off to <1/10 mAmp. New BF highest current can increase w/ time under cont. power.
Evaluation of Switch Orientation	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Misaligned switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 13a in Ford relay circuit for (45) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (15) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or move toward ignition in tab Heater element was warm to the touch.
Long duration brake fluid ingress test number 2.	17	TI	(50) samples filled with new brake fluid (1) hour of vibration per day (1) hour soak at 100 deg C per day	Test suspended. (312) hours completed. Average highest current is 1.0 mAmp (minimum = 1.8 mAmps)

TMHTSA 013611

**Current File**

---

**From:** Mulligan, Sean [smulligan@small.nc.ti.com]  
**Sent:** Thursday, May 20, 1999 8:13 AM  
**To:** McGuirk, Andy; Beringhaus, Steven  
**Subject:** Test Report Synopsis and testlog.



Please review the latest version of the Test synopsis and Test

log.

<<synopsis.doc>> <<TESTLOGS.xls>>

Revised items on the Test Synopsis are highlighted in red. There have been minor changes throughout the document so it is worth skimming the entire document (esp. in light of recent developments).

The following items have been updated on the test log:  
Test 14, 15a and 17.

Awaiting your feedback.

All the best,

Sean F. Mulligan

Texas Instruments  
Automotive Sensors & Controls  
Mechanical Design  
Phone (508) 236-2535  
Fax (508) 236-3586

TI-NHTSA 013612

## TI 77PS Test Synopsis Draft 7/12/99

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

- Test 1

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch housing electrically grounded.

**Results:** + (8) samples were tested total:  
(2) with 4% H<sub>2</sub>O in brake fluid.  
(2) with 6% H<sub>2</sub>O in brake fluid.  
(2) with 10% H<sub>2</sub>O in brake fluid.  
(2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013613

• Test 2

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.  
14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).  
Switch housing electrically grounded.

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• Test 6

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.  
Power applied to the heater element until plastic base melts.  
Spark generated in contact cavity of switch.  
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

**Wet device:** The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Dry device:** The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.  
5 watts of power dissipated in heating element.  
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

**TI-NHTSA 013814**



**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• Test 6a

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5  $\Omega$ . A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.  
Continuous 14 Volt power applied to the switch.  
Hexport is grounded.  
Current is limited at 15 Amps.

• Test 6c

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• Test 7

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) less than 1,000,000 cycles, which

TI-NHTSA 013815

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

**Objective:** Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid draw very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.  
Switches at continuous 14 Volts power.  
Switches subjected to vibration for (1) hour per day.  
Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

TI-NHTSA 013616

**Conclusion:** New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current versus time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

TI-NHTSA 013617

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O is necessary to cause an ignition.

• **Test 15**

**Objective:** Compare the ignition characteristics of various plastics as switch base material.

**Results:** When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

• **Test 15b**

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

**Conclusion:** Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

**Level 5 Objective:**

**Test 16**

• **Objective:** Test proposed relay circuit.

**Results:** (1) switch was injected with a solution of 5 wt. % NaCl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

**TI-NHTSA 013618**

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for 18 hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

**Conclusion:** 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

TI-NHTSA 013819

Test	Temp	Time	Pressure	Flow	Notes
T-NHTSA 013820	1	1	1	1	Initial test run, all parameters within normal range.
	2	2	2	2	Temperature slightly elevated, flow rate stable.
	3	3	3	3	Pressure fluctuating, check for leaks.
	4	4	4	4	Flow rate decreasing, adjust valve.
	5	5	5	5	Temperature stable, pressure consistent.
	6	6	6	6	Flow rate increasing, monitor closely.
	7	7	7	7	Pressure rising, check pump operation.
	8	8	8	8	Temperature dropping, check heating element.
	9	9	9	9	Flow rate stable, pressure normal.
	10	10	10	10	Temperature rising, check cooling system.
	11	11	11	11	Pressure fluctuating, check sensor calibration.
	12	12	12	12	Flow rate decreasing, check filter condition.
	13	13	13	13	Temperature stable, pressure consistent.
	14	14	14	14	Flow rate increasing, monitor closely.
	15	15	15	15	Pressure rising, check pump operation.
	16	16	16	16	Temperature dropping, check heating element.
	17	17	17	17	Flow rate stable, pressure normal.
	18	18	18	18	Temperature rising, check cooling system.
	19	19	19	19	Pressure fluctuating, check sensor calibration.
	20	20	20	20	Flow rate decreasing, check filter condition.

**Carrey, Pat**

---

**From:** McGuirk, Andy [a-mcguirk@small.mc.ti.com]  
**Sent:** Thursday, May 20, 1999 1:07 PM  
**To:** Warner, Pam  
**Subject:** FW: Test Report Synopsis and testlog.



synopsis.doc



TESTLOG9.xls

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST M/S 23-05  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 604-2044

-----  
**From:** Mulligan, Sean  
**Sent:** Thursday, May 20, 1999 9:12 AM  
**To:** McGuirk, Andy; Beringhouse, Steven  
**Subject:** Test Report Synopsis and testlog.

Please review the latest version of the Test synopsis and Test log.  
<<synopsis.doc>> <<TESTLOG9.xls>>  
Revised items on the Test Synopsis are highlighted in red. There have been minor changes throughout the document so it is worth skimming the entire document (esp. in light of recent developments).

The following items have been updated on the test log:  
Test 14, 15a and 17.

Awaiting your feedback,

All the best,

Sean P. Mulligan

Texas Instruments  
Automotive Sensors & Controls  
Mechanical Design  
Phone (508) 236-2535  
Fax (508) 236-3586

## TI 77PS Test Synopsis Draft 7/12/99

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

- Test 1

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch hexport electrically grounded.

**Results:**

- (8) samples were tested total:
- (2) with 4% H<sub>2</sub>O in brake fluid.
- (2) with 6% H<sub>2</sub>O in brake fluid.
- (2) with 10% H<sub>2</sub>O in brake fluid.
- (2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013022



• Test 2

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.  
14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).  
Switch hexport electrically grounded.

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• Test 6

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.  
Power applied to the heater element until plastic base melts.  
Spark generated in contact cavity of switch.  
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

**Wet device:** The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Dry device:** The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.  
5 watts of power dissipated in heating element.  
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 013623

**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

- **Test 6a**

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5  $\Omega$ s. A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

- A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.
- Continuous 14 Volt power applied to the switch.
- Hexport is grounded.
- Current is limited at 15 Amps.

- **Test 6c**

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

- **Test 7**

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

TI-NHTSA 013624

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

**Objective:** Determines the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.  
Switches at continuous 14 Volts power.  
Switches subjected to vibration for (1) hour per day.  
Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

TI-NHTSA 013625

**Conclusion:** New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O is necessary to cause an ignition.

• **Test 15**

**Objective:** Compare the ignition characteristics of various plastics as switch base material.

**Results:** When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

• **Test 15b**

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

**Conclusion:** Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

**Level 5 Objective:**

**Test 16**

• **Objective:** Test proposed relay circuit.

**Results:** (1) switch was injected with a solution of 5 wt. % Nacl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

**TI-NHTSA 013627**

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

TI-NHTSA 01382



State Personnel Search Test Log, Updated 7/1/99

Test No.	Test Name	Test Type	Test Content	Test Results
101	Writing Skills	W	Measurement of writing skills in a business style, including grammar, punctuation, and spelling. Includes a section on business letter writing.	100%
102	Reading Comprehension	R	Measurement of reading comprehension skills through a series of passages on various topics.	100%
103	Mathematics	M	Measurement of basic mathematics skills, including arithmetic, algebra, and geometry.	100%
104	Personality Assessment	P	Measurement of personality traits and characteristics through a series of self-reporting questions.	100%
105	Verbal Reasoning	V	Measurement of verbal reasoning skills through a series of logic puzzles and word problems.	100%
106	Non-Verbal Reasoning	NV	Measurement of non-verbal reasoning skills through a series of visual puzzles and spatial reasoning tests.	100%
107	Business Writing	BW	Measurement of business writing skills, including the ability to write clear and concise business letters and reports.	100%
108	Business Math	BM	Measurement of business mathematics skills, including percentages, decimals, and fractions.	100%
109	Business English	BE	Measurement of business English skills, including grammar, punctuation, and spelling.	100%
110	Business Communication	BC	Measurement of business communication skills, including the ability to write and speak effectively in a business setting.	100%
111	Business Problem Solving	BPS	Measurement of business problem-solving skills through a series of case studies and decision-making exercises.	100%
112	Business Ethics	BEth	Measurement of business ethics skills through a series of scenarios and ethical dilemmas.	100%
113	Business Law	BL	Measurement of business law skills through a series of legal scenarios and questions.	100%
114	Business History	BH	Measurement of business history skills through a series of historical events and figures.	100%
115	Business Geography	BGeo	Measurement of business geography skills through a series of geographical facts and locations.	100%
116	Business Economics	BEcon	Measurement of business economics skills through a series of economic principles and concepts.	100%
117	Business Finance	BF	Measurement of business finance skills through a series of financial statements and calculations.	100%
118	Business Marketing	BMkt	Measurement of business marketing skills through a series of marketing strategies and concepts.	100%
119	Business Management	BMan	Measurement of business management skills through a series of management theories and practices.	100%
120	Business Leadership	BLdr	Measurement of business leadership skills through a series of leadership scenarios and exercises.	100%
121	Business Negotiation	BNeg	Measurement of business negotiation skills through a series of negotiation scenarios and techniques.	100%
122	Business Conflict Resolution	BCRes	Measurement of business conflict resolution skills through a series of conflict resolution scenarios and strategies.	100%
123	Business Teamwork	BTeam	Measurement of business teamwork skills through a series of teamwork exercises and scenarios.	100%
124	Business Innovation	BInno	Measurement of business innovation skills through a series of innovation exercises and scenarios.	100%
125	Business Creativity	BCreat	Measurement of business creativity skills through a series of creativity exercises and scenarios.	100%
126	Business Problem Solving	BPS	Measurement of business problem-solving skills through a series of problem-solving exercises and scenarios.	100%
127	Business Decision Making	BDec	Measurement of business decision-making skills through a series of decision-making exercises and scenarios.	100%
128	Business Risk Management	BRisk	Measurement of business risk management skills through a series of risk management exercises and scenarios.	100%
129	Business Quality Management	BQual	Measurement of business quality management skills through a series of quality management exercises and scenarios.	100%
130	Business Customer Service	BCust	Measurement of business customer service skills through a series of customer service exercises and scenarios.	100%
131	Business Sales	BSales	Measurement of business sales skills through a series of sales exercises and scenarios.	100%
132	Business Marketing	BMkt	Measurement of business marketing skills through a series of marketing exercises and scenarios.	100%
133	Business Management	BMan	Measurement of business management skills through a series of management exercises and scenarios.	100%
134	Business Leadership	BLdr	Measurement of business leadership skills through a series of leadership exercises and scenarios.	100%
135	Business Negotiation	BNeg	Measurement of business negotiation skills through a series of negotiation exercises and scenarios.	100%
136	Business Conflict Resolution	BCRes	Measurement of business conflict resolution skills through a series of conflict resolution exercises and scenarios.	100%
137	Business Teamwork	BTeam	Measurement of business teamwork skills through a series of teamwork exercises and scenarios.	100%
138	Business Innovation	BInno	Measurement of business innovation skills through a series of innovation exercises and scenarios.	100%
139	Business Creativity	BCreat	Measurement of business creativity skills through a series of creativity exercises and scenarios.	100%
140	Business Problem Solving	BPS	Measurement of business problem-solving skills through a series of problem-solving exercises and scenarios.	100%
141	Business Decision Making	BDec	Measurement of business decision-making skills through a series of decision-making exercises and scenarios.	100%
142	Business Risk Management	BRisk	Measurement of business risk management skills through a series of risk management exercises and scenarios.	100%
143	Business Quality Management	BQual	Measurement of business quality management skills through a series of quality management exercises and scenarios.	100%
144	Business Customer Service	BCust	Measurement of business customer service skills through a series of customer service exercises and scenarios.	100%
145	Business Sales	BSales	Measurement of business sales skills through a series of sales exercises and scenarios.	100%
146	Business Marketing	BMkt	Measurement of business marketing skills through a series of marketing exercises and scenarios.	100%
147	Business Management	BMan	Measurement of business management skills through a series of management exercises and scenarios.	100%
148	Business Leadership	BLdr	Measurement of business leadership skills through a series of leadership exercises and scenarios.	100%
149	Business Negotiation	BNeg	Measurement of business negotiation skills through a series of negotiation exercises and scenarios.	100%
150	Business Conflict Resolution	BCRes	Measurement of business conflict resolution skills through a series of conflict resolution exercises and scenarios.	100%

71-NHTSA 013830



**Curry, Pat**

---

**From:** Wallman, Stacey [swallman@ornl.msc.ti.com]  
**Sent:** Thursday, May 20, 1999 10:27 AM  
**To:** Warner, Pam  
**Cc:** Sharpe, Robert; McGuirk, Andy  
**Subject:** Ford foil



Andy.ppt

At the request of Andy McGuirk, I am sending the following attachment to you:

<<Andy.ppt>>

Regards,  
Stacey



## NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids