

EA02-025

TEXAS INSTRUMENTS, INC.'S

9/10/03

REQUEST NO. 7

BOX 9

PART A - R

PART D

Epstein, Sally

From: Proia, Stephen [s-proia@small.nc.ti.com]
Sent: Thursday, May 20, 1999 1:49 PM
To: Beringhaus, Steven; Dague, Bryan; McGuirk, Andy
Cc: Pachonik, John
Subject: FW: L2-1 Yields



777SL2-1
Yield_1992.xls

Steve,

Here is the '92 yield data you requested. Please review and get back to me with any questions. I have a meeting at 3:00 PM and should be back around 4:00.

Thanks.

Steve

From: Balthazar, Claire
Sent: Thursday, May 20, 1999 2:16 PM
To: Proia, Stephen
Subject: L2-1 Yields

Steve,

Here are the numbers for 1992. I saw no evidence of any major leak problems. If you look at the lot reports, you will see some failures in the leak category. If this number is divisible by 4 (if 1 leaks the tester shorts the test and calls them all bad) it usually means that a set of nests went through empty or there was a bad seal between the device and the machine. The devices would then be rerun separately one by one with other devices to identify the leaker if there was one. Kind of a process of elimination. The leak quantity on the lot report should be manually adjusted by the operator.

That is what should be happening but I can't guarantee it and it is probably not written anywhere on the specs.

<<777SL2-1 Yields_1992.xls>>

Summary sheet is at the beginning.

Claire

TI-NHTSA 013633

77PSL2-1 Yields for 1992

<u>Date</u>	<u>Tested</u>	<u>Good</u>	<u>%</u>
January-92	14341	14200	99.1%
February-92	10589	10487	99.0%
March-92	28771	27980	97.3%
April-92	15527	15478	97.8%
May-92	12018	11138	92.7%
June-92	23443	23133	98.7%
July-92	11638	11673	99.8%
August-92	18536	18283	98.6%
September-92	11683	11582	99.0%
October-92	3836	3527	92.7%
November-92	0	0	0.0%
December-92	18939	15481	81.8%
Total	182473	149816	82.2%

TI-NHTSA 013634

Date	Tested	Good	%	Failure Modes		
January-82						
1/8	508	799	99.9%			
1/13	1208	1208	99.8%			
1/14	50	50	100.0%			
1/18	1748	1741	99.6%			
1/19	796	734	92.4%	cont 10	scr 20	rlor 22
1/25	52	52	100.0%			
1/19	31	31	100.0%			
1/14	44	44	100.0%			
1/18	48	48	100.0%			
1/14	48	48	100.0%			
1/8	52	51	98.1%			
1/8	52	48	92.3%			
1/14	52	51	98.1%			
1/14	52	52	100.0%			
1/25	80	80	100.0%			
1/14	84	84	100.0%			
1/14	212	209	98.6%			
1/25	238	234	98.3%			
1/14	264	254	100.0%			
1/8	304	299	98.4%			
1/13	378	375	99.7%			
1/14	398	398	100.0%			
1/13	501	499	99.6%			
1/25	718	711	98.3%			
1/25	854	854	100.0%			
1/25	958	955	99.7%			
1/14	1096	1092	99.7%			
1/8	1308	1278	97.7%			
1/18	1918	1914	99.8%			
Total	14341	14258	99.1%			

TI-NHTSA 013635

Date	Tested	Good	%	Failure Modes				
February-82								
2/1	52	52	100.0%					
2/1	671	666	99.3%					
2/1	248	248	100.0%					
2/1	468	466	99.6%					
2/1	444	442	99.5%					
2/1	316	316	100.0%					
2/1	184	183	99.5%					
2/1	48	48	100.0%					
2/1	1384	1382	99.9%					
2/4	1248	1199	96.1%	cont 6	accr 3	achi 36	rhl 1	rlcr 3
2/4	158	151	95.6%					
2/4	908	905	99.8%					
2/4	518	515	99.4%					
2/23	1429	1429	100.0%					
2/17	219	219	100.0%					
2/25	630	625	99.4%					
2/25	188	186	98.9%					
2/25	1088	1088	99.0%					
2/25	212	208	97.2%					
Total	18889	18487	98.0%					

TI-NHTBA 013636

Date	Tested	Good	%	Failure Modes			
March-82							
3/1	48	48	95.8%				
3/2	420	413	98.3%				
3/3	328	325	99.1%				
3/8	916	908	98.9%				
3/10	384	324	84.4%	achi 58	rio 1		
3/10	872	748	85.8%	achi 145	dmf 3		
3/11	292	291					
3/11	692	691					
3/11	256	255					
3/11	198	198					
3/11	428	425					
3/18	718	715	99.6%				
3/18	288	282	98.0%				
3/22	48	48					
3/22	148	147					
3/22	200	199					
3/22	816	813					
3/22	1400	1393					
3/23	878	873	99.5%				
3/23	140	139	99.3%				
3/23	1564	1558	99.5%				
3/23	230	218	94.8%				
3/23	788	745	94.5%				
3/23	292	288	98.6%				
3/24	384	383	99.7%				
3/24	592	523	88.3%				
3/28	1220	1213					
3/28	80	80	100.0%				
3/28	392	390	99.5%				
3/28	1370	1364	99.5%				
3/28	564	560	99.3%				
3/11	1811	1879	98.3%				
3/8	408	407	99.8%				
3/18	1380	1388	99.9%				
3/18	412	410	99.5%				
3/18	280	277	99.0%				
3/18	1724	1720	99.8%				
3/18	360	360	100.0%				
3/18	1032	1028	99.6%				
3/18	244	205	84.0%	achi 37	rhl 1	rlor 1	
3/18	358	353	98.6%				
3/31	488	485	99.4%				
3/31	1878	1882	99.9%				
3/31	381	278	73.0%	achi 85			
3/31	1381	1129	81.7%	achi 220	cont 1	rlor 1	
3/31	80	25	31.3%	cont 4	achi 7	rio 1	rlor 7
3/31	278	223	80.2%	cont 8	achi 45		dmf 11
Total	28771	27888	97.3%				

TI-NHTSA 013637

Date	Tested	Good	%	Failure Modes
April-82				
4/29	118	118	100.0%	
4/1	1440	1433	99.5%	
4/1	488	488	100.0%	
4/20	419	388	92.6%	
4/20	388	333	85.8%	scr1 36
4/12	1275	1267	99.3%	
4/13	788	784	99.6%	
4/13	124	124	100.0%	
4/13	352	340	96.3%	
4/14	1000	884	88.4%	scr1 114 scr1 rcr1
4/21	388	393	99.2%	
4/21	212	211	99.5%	
4/21	548	547	99.6%	
4/21	28	28	100.0%	
4/21	1288	1287	99.3%	
4/21	388	388	99.6%	
4/21	212	207	97.6%	
4/21	400	400	100.0%	
4/21	548	543	99.1%	
4/27	498	493	99.0%	
4/27	212	212	100.0%	
4/27	1432	1387	96.6%	
4/27	212	211	99.5%	
4/27	388	382	98.2%	
4/27	884	884	100.0%	
4/27	388	388	100.0%	
4/29	288	288	100.0%	
4/29	792	775	97.8%	
4/29	384	378	98.2%	
Total	18827	18478	97.6%	

TI-NHTSA 013638

Date	Tested	Good	%	Failure Modes				
May-82								
5/8	419	381	90.9%	cont 3	scr 1	schl 1	ricr 29	
5/8	1426	1280	89.4%	cont 3	scr 1	schl 1	schl 14	ricr 147
5/11	1128	1016	90.1%	scr 5	schl 2	ricr 106		
5/11	200	183	91.5%	schl 1	ricr 18			
5/11	247	211	85.4%	schl 4	ricr 21			
5/11	61	51	83.6%	schl 1	ricr 7			
5/11	185	169	91.3%	schl 3	ricr 21	cont 2		
5/11	80	48	60.0%					
5/12	489	416	85.0%	schl 53	ricr 17			
5/12	139	128	92.0%					
5/14	564	552	97.9%					
5/14	345	320	92.7%					
5/25	1299	1239	95.3%					
5/25	336	271	80.7%	schl 17	ricr 48			
5/25	1630	1618	99.2%	cont 1	scr 1	schl 15	ricr 195	
5/28	132	132	100.0%					
5/28	152	152	100.0%					
5/28	1119	1117	99.8%					
5/28	702	700	99.7%					
5/28	904	901	99.7%					
5/28	104	102	98.1%					
5/28	60	60	100.0%					
5/28	124	123	99.2%					
Total	13018	11139	85.5%					

TI-NHTSA 013639

Date	Tested	Good	%	Failure Modes
June-82				
6/1	358	360	97.8%	
6/1	408	404	99.0%	
6/1	271	255	94.1%	
6/1	1394	1391	99.8%	
6/2	1028	1024	99.6%	
6/2	980	959	97.9%	
6/2	1583	1583	100.0%	
6/2	198	188	94.9%	
6/2	200	197	98.5%	
6/8	948	944	99.6%	
6/11	378	375	99.2%	
6/11	391	380	97.2%	
6/11	198	188	94.9%	
6/11	978	783	79.9%	
6/11	1278	1273	99.6%	
6/11	408	407	99.8%	
6/11	978	974	99.6%	
6/11	580	578	99.7%	
6/12	170	170	100.0%	
6/12	1044	1043	99.9%	
6/12	183	183	100.0%	
6/12	134	134	100.0%	
6/12	783	781	99.7%	
6/12	183	182	99.5%	
6/12	1282	1280	100.0%	
6/12	240	238	99.2%	
6/12	338	338	100.0%	
6/12	313	313	100.0%	
6/12	317	317	100.0%	
6/12	240	238	99.2%	
6/12	182	188	97.8%	
6/14	1438	1433	99.7%	
6/23	174	174	100.0%	
6/23	882	858	97.3%	
6/23	501	487	97.2%	
6/28	1188	1188	100.0%	
6/28	1128	1118	99.1%	
6/28	144	142	98.6%	
6/28	280	287	102.5%	
Total	23443	23133	98.7%	

TI-NHTSA 013840

Date	Tested	Good	%	Failure Modes
July-82				
7/26	840	831	98.9%	
	196	194	98.0%	
	1132	1118	98.0%	
7/8	815	779	95.6%	
7/15	357	355	99.4%	
7/14	698	688	98.4%	
	424	421	99.3%	
	692	686	99.0%	
	399	382	95.7%	
7/28	1360	1338	98.4%	
7/26	592	585	98.8%	
7/20	798	791	99.0%	
7/30	367	363	98.9%	
7/21	178	178	100.0%	
	204	204	100.0%	
	398	393	98.2%	
7/19	638	632	98.4%	
7/12	750	748	99.7%	
	1204	1192	99.0%	
Total	11838	11673	98.6%	

TI-NHTSA 013841

Date	Tested	Good	%	Failure Modes
August-82				
8/8	1870	1834	97.9%	
8/9	948	944	99.6%	
8/9	520	518	99.6%	
8/9	520	518	99.5%	
8/9	355	355	100.0%	
8/10	1978	1972	99.6%	
8/12	1327	1300	98.0%	
8/18	505	505	99.4%	
8/18	500	555	99.1%	
8/18	208	208	100.0%	
8/18	152	152	100.0%	
8/19	304	300	98.7%	
8/19	80	80	98.3%	
8/19	987	954	98.7%	
8/19	610	588	96.4%	
8/19	52	51	98.1%	
8/24	975	873	89.4%	
8/24	55	55	100.0%	
8/24	982	951	97.8%	
8/24	52	52	100.0%	
8/24	285	281	98.6%	
8/25	980	944	96.3%	
8/25	1782	1768	98.6%	
8/31	2055	2053	99.9%	
Total	18538	18383	99.2%	

Date	Tested	Good	%	Failure Modes
Sep-82				
9/2	1144	1143	99.9%	
9/2	220	219	99.5%	
9/2	578	559	96.7%	
9/3	835	835	99.9%	
9/3	1081	1076	99.5%	
9/7	2009	2001	99.6%	
9/8	1829	1815	99.2%	
9/8	1082	1023	93.7%	schl 68 cont 1 scdr 1 sclo 1
9/8	48	47		
9/8	218	203		schl 13
9/16	960	960	100.0%	
9/16	208	208	100.0%	
9/15	820	819	99.9%	
9/15	84	84	100.0%	
9/15	308	308	100.0%	
9/15	192	192	100.0%	
Total	11683	11663	99.8%	

Date	Tested	Good	%	Failure Modes
Oct-82				
10/1	1403	1403	99.8%	
10/10	232	231	99.6%	
	239	239	100.0%	
	268	268	100.0%	
	1252	1250	99.8%	
10/2	268	265	98.9%	
	178	178	100.0%	
Total	3335	3327	99.7%	

TI-NHTSA 013844

Date	Tested	Good	%	Failure Modes
------	--------	------	---	---------------

Nov-68				
--------	--	--	--	--

No reports

Total	0	0		
-------	---	---	--	--

TI-NHTSA 013648

Date	Tested	Good	%	Failure Modes	
Dec-82					
12/10	19	19	100.0%		
	220	211	95.9%		
	1665	1491	89.6%	cont 6	schf 122
	60	48	80.0%		
12/16	1044	1042	99.8%		
	708	707	99.9%		
	1084	1082	99.8%		
	1028	1027	99.9%		
12/19	409	371	90.7%	cont 1	schf 37
	50	50	100.0%		
	1376	1259	91.3%	cont 7	schf 113
12/15	540	540	100.0%		
	424	423	99.8%		
	524	522	99.6%		
	60	60	100.0%		
	932	930	99.8%		
	475	475	100.0%		
	228	228	100.0%		
	72	72	100.0%		
	50	50	100.0%		
	252	251	99.6%		
	632	632	100.0%		
	640	640	100.0%		
12/15	1500	1460	97.3%		
	280	280	100.0%		
	438	438	100.0%		
	179	179	100.0%		
12/3	50	44	88.0%	flor 6	
	719	645	89.7%	cont 2	flor 72
Total	18839	18481	97.1%		

TI-NHT8A 013640

Proia, Stephen

From: Balhazar, Claire
Sent: Thursday, May 20, 1999 2:16 PM
To: Proia, Stephen
Subject: L2-1 Yields

Steve,

Here are the numbers for 1992. I saw no evidence of any major leak problems. If you look at the lot reports, you will see some failures in the leak category. If this number is divisible by 4 (if 1 leaks the tester aborts the test and calls them all bad) it usually means that a set of nests went through empty or there was a bad seal between the device and the machine. The devices would then be rerun separately one by one with other devices to identify the leaker if there was one. Kind of a process of elimination. The leak quantity on the lot report should be manually adjusted by the operator.

That is what should be happening but I can't guarantee it and it is probably not written anywhere on the specs.



77PBL3-1
Yields_1992.doc

Summary sheet is at the beginning.

Claire

* YIELD DATA IS BASED ON 120 BOXES
OF LOT REPORTS FROM '91-'92 PERIOD
COPIES HAVE NOT BEEN MADE FROM
THESE BOXES UNTIL REQUESTED TO
DO SO.


Function Test Pareto Categories

Test Acronym	Definition	Cause	Disposition
ACHH	Actuation High	Device tests out of spec on the high side. Disc / Component selection.	Scrap
ACLO	Actuation Low	Device tests out of spec on the low side. Disc / Component selection.	Scrap
ACCR	Actuation Creep	Device fails creep test (< 200 ms). Creep is calculated from the time a switch changes electrical continuity to the time in which the system microphone detects an audible snap.	Scrap
RELH	Release High	Device tests out of spec on the high side. Disc / Component selection.	Scrap
RELO	Release Low	Device tests out of spec on the low side. Disc / Component selection.	Scrap
RELCR	Release Creep	Device fails creep test (< 200 ms). Creep is calculated from the time a switch changes electrical continuity to the time in which the system microphone detects an audible snap.	Scrap
CONT	Continuity	System fails to detect continuity between terminals. Typically caused by bad tester pogo pins.	Scrap
DPHI	Differential High	Device tests out of spec on the low side. Disc / Component selection.	Scrap
DPLO	Differential Low	Device tests out of spec on the low side. Disc / Component selection.	Scrap
LEAK	Leak	All nests must be full on the tester in order to complete a test sequence. If (1) device tests the tester aborts the test and calls all (4) devices bad.	Re-test to determine defective device, Scrap & Adjust lot report

TI-NHTSA 013849

77PSL2-1 Yields for 1982

Date	Tested	Good	%
January-82	14341	14209	99.1%
February-82	10589	10487	99.0%
March-82	28771	27980	97.3%
April-82	15827	15478	97.8%
May-82	12018	11138	92.7%
June-82	23443	23133	98.7%
July-82	11838	11673	98.6%
August-82	15536	15253	98.5%
September-82	11883	11582	98.0%
October-82	3638	3527	96.7%
November-82	0	0	0.0%
December-82	15839	15481	97.1%
Total	182478	180610	97.7%

Date	Tested	Good	%	Failure Modes
January-82				
1/8	808	799	98.9%	
1/13	1208	1208	99.8%	
1/14	50	50	100.0%	
1/18	1748	1741	99.6%	
1/19	788	734	93.4%	cont 10 accr 20 ror 22
1/25	52	52	100.0%	
1/19	31	31	100.0%	
1/14	44	44	100.0%	
1/18	48	48	100.0%	
1/14	48	48	100.0%	
1/8	52	51	98.1%	
1/8	52	48	92.3%	
1/14	52	51	98.1%	
1/14	52	52	100.0%	
1/25	80	80	100.0%	
1/14	84	84	100.0%	
1/14	212	209	98.6%	
1/25	238	234	98.2%	
1/14	284	284	100.0%	
1/8	304	290	95.4%	
1/13	378	375	99.7%	
1/14	398	398	100.0%	
1/13	501	498	99.4%	
1/25	718	711	98.9%	
1/25	884	884	100.0%	
1/25	858	855	99.7%	
1/14	1085	1082	99.7%	
1/8	1308	1278	97.7%	
1/18	1918	1914	99.8%	
Total	14341	14288	99.7%	

Date	Tested	Good	%	Failure Modes					
February-82									
2/1	52	52	100.0%						
2/1	671	658	98.1%						
2/1	248	248	100.0%						
2/1	458	458	99.8%						
2/1	444	442	99.5%						
2/1	316	316	100.0%						
2/1	184	183	99.5%						
2/1	48	48	100.0%						
2/1	1364	1362	99.9%						
2/4	1248	1199	96.1%	cont 8	eccr 3	achi 36	rhi 1	ricr 3	
2/4	188	151	96.8%						
2/4	908	906	99.8%						
2/4	516	515	99.8%						
2/23	1428	1428	100.0%						
2/17	219	219	100.0%						
2/25	830	825	99.4%						
2/25	188	186	98.9%						
2/25	1088	1066	98.0%						
2/25	212	209	97.2%						
Total	10569	10467	99.0%						

Date	Tested	Good	%	Failure Modes			
March-82							
3/1	46	46	96.5%				
3/2	420	413	98.3%				
3/3	328	325	99.1%				
3/8	916	905	98.8%				
3/10	384	324	84.4%	achi 59	rio 1		
3/10	872	748	85.8%	achi 146	dfl 3		
3/11	292	291					
3/11	892	891					
3/11	256	256					
3/11	198	198					
3/11	428	425					
3/16	716	716	99.9%				
3/18	288	282	98.6%				
3/22	48	48					
3/22	148	147					
3/22	200	199					
3/22	818	813					
3/22	1400	1393					
3/23	576	573	99.5%				
3/23	140	139	99.3%				
3/23	1584	1556	98.9%				
3/23	220	218	99.1%				
3/23	788	745	98.2%				
3/23	292	286	97.9%				
3/24	304	303	99.7%				
3/24	532	523	98.3%				
3/28	1220	1213					
3/29	50	50	100.0%				
3/29	382	390	99.8%				
3/29	1378	1364	99.1%				
3/29	884	559	99.1%				
3/11	1911	1879	98.3%				
3/8	408	407	99.8%				
3/18	1380	1368	99.0%				
3/18	412	410	99.6%				
3/18	280	277	99.0%				
3/18	1724	1720	99.8%				
3/19	380	380	100.0%				
3/19	1032	1028	99.6%				
3/19	244	206	84.0%	achi 37	rfl 1	ric 1	
3/19	336	333	99.1%				
3/31	468	466	99.6%				
3/31	1978	1962	99.2%				
3/31	331	275	83.4%	achi 55			
3/31	1361	1129	83.0%	achi 220	cont 1	ric 1	
3/31	80	25	41.7%	cont 4	achi 7	rio 1	
3/31	276	223	80.8%	cont 8	achi 45	ric 7	dfl 11
Total	28771	27880	97.3%				

TI-NHTSA 013652

Date	Tested	Good	%	Failure Modes
April-88				
4/29	118	118	100.0%	
4/1	1440	1433	99.5%	
4/1	488	488	100.0%	
4/20	419	388	92.6%	
4/20	388	333	85.8%	ach 35
4/12	1278	1287	99.9%	
4/13	788	784	99.6%	
4/13	124	124	100.0%	
4/13	382	348	91.3%	
4/14	1000	884	88.4%	ach 114 mocr 1 rcr 1
4/21	388	383	98.7%	
4/21	212	211	99.5%	
4/21	548	547	99.8%	
4/21	28	28	100.0%	
4/21	1288	1287	99.9%	
4/21	388	388	100.0%	
4/21	212	207	97.6%	
4/21	400	400	100.0%	
4/21	548	543	99.1%	
4/27	488	483	99.2%	
4/27	212	212	100.0%	
4/27	1432	1387	96.9%	
4/27	212	211	99.5%	
4/27	388	382	98.2%	
4/27	884	854	96.6%	
4/27	388	358	92.3%	
4/29	288	283	98.3%	
4/29	782	778	99.5%	
4/29	384	378	98.2%	
Total	18827	18478	97.9%	

Date	Tested	Good	%	Failure Modes			
May-83							
5/5	418	381	90.9%	cont 3	scr 1	achi 1	ricr 29
5/5	1426	1280	89.4%	cont 3	scr 1	achi 1	achi 14 ricr 147
5/11	1128	1016	90.1%	scr 6	achi 2	ricr 105	
5/11	200	183	91.5%	achi 1	ricr 16		
5/11	247	211	85.4%	achi 4	ricr 21		
5/11	81	51	63.0%	achi 1	ricr 7		
5/11	155	159	85.8%	achi 3	ricr 21	cont 2	
5/11	50	45	90.0%				
5/12	458	416	90.8%	achi 53	ricr 17		
5/12	138	126	91.3%				
5/14	554	552	99.7%				
5/14	348	320	92.0%				
5/25	1299	1239	95.4%				
5/25	338	271	80.2%	achi 17	ricr 48		
5/25	1836	1618	88.1%	cont 1	scr 1	achi 18	ricr 198
5/25	132	132	100.0%				
5/26	182	182	100.0%				
5/26	1118	1117	99.9%				
5/26	702	700	99.7%				
5/26	904	901	99.7%				
5/26	104	102	98.1%				
5/26	80	80	100.0%				
5/26	124	123	99.2%				
Total	12018	11138	92.7%				

Date	Tested	Good	%	Failure Modes
June-82				
6/1	389	380	97.8%	
6/1	406	404	99.5%	
6/1	271	255	94.1%	
6/1	1384	1391	99.8%	
6/2	1026	1024	99.8%	
6/2	960	959	99.9%	
6/2	1553	1553	100.0%	
6/2	198	195	98.5%	
6/2	200	197	98.5%	
6/6	846	844	99.8%	
6/11	378	375	99.7%	
6/11	391	390	99.7%	
6/11	198	195	98.5%	
6/11	978	783	78.2%	
6/11	1275	1273	99.8%	
6/11	408	407	99.8%	
6/11	978	974	99.6%	
6/11	550	578	99.7%	
6/12	170	170	100.0%	
6/12	1044	1043	99.9%	
6/12	183	183	100.0%	
6/12	134	134	100.0%	
6/12	783	781	99.7%	
6/12	183	182	99.5%	
6/12	1282	1288	100.3%	
6/12	240	238	99.2%	
6/12	338	338	100.0%	
6/12	313	313	100.0%	
6/12	317	317	100.0%	
6/12	240	238	99.2%	
6/12	192	188	97.9%	
6/14	1436	1433	99.8%	
6/23	174	174	100.0%	
6/23	682	688	99.4%	
6/23	501	497	99.2%	
6/29	1198	1188	99.2%	
6/29	1128	1118	98.9%	
6/29	144	142	98.6%	
6/29	299	297	99.3%	
Total	23443	23133	98.7%	

TI-NHTSA 013655

Date	Tested	Good	%	Failure Modes
July-82				
7/28	640	631	98.6%	
	198	194	98.0%	
	1132	1119	98.8%	
7/8	818	779	95.2%	
7/16	357	355	99.4%	
7/14	898	885	98.4%	
	424	421	99.3%	
	892	885	99.0%	
	399	382	95.7%	
7/28	1350	1338	98.4%	
7/28	592	585	98.8%	
7/20	799	791	99.0%	
7/30	357	353	98.9%	
7/21	178	178	100.0%	
	204	204	100.0%	
	398	383	96.2%	
7/19	636	632	99.4%	
7/12	750	748	99.7%	
	1204	1192	99.0%	
Total	11838	11673	98.6%	

TI-NHTSA 013858

Date	Tested	Good	%	Failure Modes
August-82				
8/9	1978	1934	97.8%	
8/9	948	944	99.6%	
8/9	520	519	99.8%	
8/9	820	816	99.5%	
8/9	388	388	100.0%	
8/10	1978	1972	99.8%	
8/12	1327	1300	98.0%	
8/18	808	806	99.8%	
8/18	580	585	99.1%	
8/18	208	208	100.0%	
8/18	182	182	100.0%	
8/18	304	300	98.7%	
8/18	80	80	100.0%	
8/18	967	964	99.7%	
8/19	610	608	99.7%	
8/19	82	81	98.8%	
8/24	878	873	99.4%	
8/24	58	58	100.0%	
8/24	962	961	99.9%	
8/24	82	82	100.0%	
8/24	286	281	98.3%	
8/25	990	944	95.4%	
8/25	1792	1788	99.8%	
8/31	2088	2063	98.8%	
Total	18838	18853	99.5%	

TI-NHTSA 013857

Date	Tested	Good	%	Failure Modes
8/2	1144	1143	99.9%	
8/2	220	219	99.5%	
8/2	576	569	98.8%	
8/3	836	835	99.8%	
8/3	1081	1078	99.6%	
8/7	2069	2061	99.6%	
8/8	1828	1815	99.2%	
8/8	1082	1023	93.7%	schl 66 cont 1 scrr 1 sclo 1
8/8	48	47		
8/8	218	203		schl 13
8/15	990	990	100.0%	
8/15	208	208	100.0%	
8/15	820	819	99.8%	
8/15	64	64	100.0%	
8/15	308	308	100.0%	
8/15	182	182	100.0%	
Total	11883	11842	99.6%	

Date	Tested	Good	%	Failure Modes
Oct-82				
10/1	1408	1403	99.6%	
10/19	232	231	99.6%	
	238	238	100.0%	
	288	288	100.0%	
	1282	1280	99.8%	
10/2	288	288	99.9%	
	178	178	100.0%	
Total	3838	3827	99.7%	

Date	Tested	Good	%	Failure Modes
------	--------	------	---	---------------

Nov-82

No reports

Total	0	0		
-------	---	---	--	--

Date	Tested	Good	%	Failure Modes	
Dec-82					
12/19	19	19	100.0%		
	220	211	95.9%		
	1885	1491	85.5%	cont 8	achi 188
	50	48	92.0%		
12/18	1044	1042	99.8%		
	708	707	99.8%		
	1084	1082	99.8%		
	1028	1027	99.9%		
12/19	408	371	90.7%	cont 1	achi 37
	50	50	100.0%		
	1378	1258	91.3%	cont 7	achi 113
12/18	540	540	100.0%		
	424	423	99.8%		
	524	522	99.6%		
	50	50	100.0%		
	832	830	99.8%		
	478	478	100.0%		
	228	228	100.0%		
	72	72	100.0%		
	50	50	100.0%		
	252	251	99.6%		
	532	532	100.0%		
	640	640	100.0%		
12/18	1500	1499	99.9%		
	280	280	100.0%		
	438	438	100.0%		
	178	178	100.0%		
12/3	80	44	55.0%	ricr 8	
	719	646	89.7%	cont 2	ricr 72
Total	18839	18481	97.1%		

TI-NHTSA 013861

TI 77PS Test Synopsis Draft 5/20/99

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

Level 1 Objective: Determine if a switch ignition can be created in the laboratory.

- **Test 1**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H₂O.
14 volts applied to one terminal, second terminal electrically floating.
(No electrical load across switch terminals).
Switch hexport electrically grounded.

Results:

- (8) samples were tested total:
- (2) with 4% H₂O in brake fluid.
- (2) with 6% H₂O in brake fluid.
- (2) with 10% H₂O in brake fluid.
- (2) with 75% H₂O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013882

• Test 2

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.
14 volts applied to one terminal, second terminal connected to a 14 Ω resistor which is tied to ground. (1 Amp load across switch terminals).
Switch hexport electrically grounded.

Results: (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

Conclusion: A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• Test 6

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.
Power applied to the heater element until plastic base melts.
Spark generated in contact cavity of switch.
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

Results: (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Conclusion: A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.
5 watts of power dissipated in heating element.
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

Level 2: Objective: Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

- Test 6a

Objective: Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

Results: (1) out of (15) samples tested increased resistance to 5 Ω s. A solution of 5 wt. % NaCl in H₂O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H₂O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

Conclusion: A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H₂O is injected into contact cavity of a switch.
Continuous 14 Volt power applied to the switch.
Hexport is grounded.
Current is limited at 15 Amps.

- Test 6c

Objective: Determine if brake fluid with metal shavings is conductive enough to create an ignition.

Results: (3) devices with various size metal particles were tested. No significant current increase detected.

Conclusion: Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

- Test 7

Objective: Determine if switch meets cycle life specification.

Results: Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

Conclusions: Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

Objective: Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

Results: Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmps. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

Conclusion: Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

Objective: Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.
Switches at continuous 14 Volts power.
Switches subjected to vibration for (1) hour per day.
Switches subjected to 100°C for (1) hour per day.

Results: Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

TI-NHTSA 013865

Conclusion: New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

Level 3: Objective: Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H₂O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

Conclusion: A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H₂O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

Level 4: Objective: Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

Objective: Compare various fluids in the established ignition method.

Results: The following fluids were tested.

- (1) NaCl in H₂O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H₂O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H₂O

The switch filled with 5 wt. % NaCl in H₂O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

Conclusion: Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its significantly higher conductivity, an ionic rich fluid such as NaCl in H₂O is necessary to cause an ignition.

• Test 15

Objective: Compare the ignition characteristics of various plastics as switch base material.

Results: When 5 wt. % NaCl in H₂O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusions: All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

Objective: Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

Results: Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

Level 5 Objective:

Test 16

• Objective: Test proposed relay circuit.


Results: (1) switch was injected with a solution of 5 wt. % NaCl in H₂O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.


Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.



TI-NHTSA 013669

CONFIDENTIAL

Attachment



TI-NHTSA 013670

Copyright © 1999 Texas Instruments

Attachment

Epstein, Sally

From: Gildea, Robert [rgildea@small.mot.ti.com]
Sent: Thursday, May 20, 1999 4:26 PM
To: Proia, Stephen; Fechneris, John; Martin, Scott; Dague, Bryan; Mulligan, Sean; Basiliere, Robert; Watt, Jim
Subject: Gaps in sensor building process

Team,

After reviewing the sensor building process for gaps that could cause leaks the following is a list of what I came up with. I also reviewed this with Bob Basiliere who went through the program in depth to insure that the machine was programmed the way we assumed it was. I also had the AMI operator duplicate the failures to insure the program was working properly.

1) Gasket check station. This station is not fail safe. It is designed to check for a gasket and its position using four reflective sensors. There are several problems with this design. First, the operator can not tell if the sensors are working while the machine is running. They can only determine this while doing SPC checks which are performed roughly every four hours. Therefore there is the potential to produce approximately 4k to 5k sensors without all the sensors working. Secondly, there is no detection to see if the station actually stroked down and checked the nest for a gasket. If the station gets jammed up it will call every nest good.

2) Kapton Check Stations. These stations also are not fail safe. These stations are designed to work using a continuity probe to insure the proper number of kaptons are in the nest, and that they are in the proper orientation. The first check station checks that there is two pieces of kapton. Four pogo pins come down and check for the corners of the kapton and as long as the pins do not go to ground they call the nest good. Once again the problem is that the station could be stuck up and there is no way for the machine to know it. Also, the pogo pins could be bent, broken, or missing and the system wouldn't know it. The only back check that we have is that all the pogo pins are wired in series and if one of the wires is broken it will break the series and send a fault signal to the panel. The check for the third station works in the exact same way, but it also has one feature that makes it even less reliable. Because we make devices with two kaptons we fixture the check station for the third kapton so the station can be stored up out of the way while we are running the two kapton devices. If the operator does not put the station down and perform the SPC they could conceivably run for hours without the third check station engaged. Also, as with the gasket station, we do not check to see if the check stations actually stroke down and check the nest.

3) The crimp table. We call out exact pressures with tolerances on our process specifications for the 45 degree crimp, 90 degree crimp, and overpressure, but the gauges we are using are not calibrated. Also, we do not have a PM procedure in place for the crimp dies, we leave it up to the operators and the tool room. What we depend on are our SPC checks, which are very capable. We use a poka-yoke to check the diameter of the sensor and a dial indicator to check the height. The CpK for the sensor height is 2.6.

Regards,

Bob Gildea
Phone: (508) 236-2023
Fax: (508) 236-3586
email: rgildea@ti.com



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:	Power Steering Fluid					
	Brake Fluid					
CONFIDENTIAL	Transmission Fluid					


- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

TI-NHTSA 013672

TOWN CAR SWITCH SEQUENCE ...

*PITTS?
 HILITES?*

thinks



12/20/91



NA Hydraulic Switch History


Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:	<div style="display: flex; justify-content: space-between;"> <div style="width: 20%;">Power Steering Fluid</div> <div style="width: 80%;"></div> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="width: 20%;">Brake Fluid</div> <div style="width: 80%;"></div> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="width: 20%;">Transmission Fluid</div> <div style="width: 80%;"></div> </div>					

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

TI-NHTSA 013674



OVERVIEW OF
CONCERN TIME LINE



TI-NHTSA 013678

C:\A\Gent\99\poten\theor\Ford

Attachment




Brake Switch Overview

- **Mounted under hood...14 inches under master cylinder**
- **Mounted on proportional valve at frame of vehicle**
- **Switch oriented approximately 25 degrees off vertical
(connector up)**
- **Switch controls speed control...normally closed, opens at
130 psi**
- **Continuously powered by battery 15 amp connection**




**PRESSURE SWITCH "FLOW DIAGRAM"
('92, '93, TOWN CAR)**



TI-NHTSA 013677

CMA/Cast/Proportion/Fuel

Attachment



TI-NHTSA 013878


C.M. Galt/Typos/initials/Part

Attachment



TEXAS
INSTRUMENTS

Brake Pressure Switch Potential Thermal Event Theory Profile 5/20/99



TLNHT8A 013679

C:\MrGask\Procedures\Ford

Attachments



Ford recalls 279,000 cars because of risk of cruise-control fires

05/19/1999

Associated Press Newswires

Copyright 1999. The Associated Press. All Rights Reserved.

DEARBORN, Mich. (AP) - Ford Motor Co. has recalled 279,000 full-size cars because of a cruise-control switch that could short-circuit and cause a fire.

The recall affects the 1992 and '93 Lincoln Town Car, Mercury Grand Marquis and Ford Crown Victoria. About 10,900 of the recalled cars are in Canada.

There have been 147 reports of fires and two injuries attributed to the defect, Ford spokeswoman Karen Shaughnessy said Tuesday.

The automaker said it is still obtaining replacement switches. Until the switch can be fixed, customers should take their cars to their dealer and have the cruise control disabled, Ford said.



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

TI-NHTBA 013692



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering	Power Steering	Power Steering	Power Steering	Power Steering
		Suspension	Suspension	Suspension	Suspension	Suspension
			Transmission	Transmission	Transmission	Transmission
				Cruise	Cruise	Cruise
					Clutch	Clutch
Fluid:	Power Steering Fluid					
		Brake Fluid				
			Transmission Fluid			

TI-NHT9A 019884

- TI has some 18 years and 138 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

CONFIDENTIAL



1. Operational Definition (Problem Statement): TOWN CAR ENGINE/OD FUEL			
2. Description	IS	IS NOT	Get Information
WHAT	Town Car MY '91, '93, '94	Crown Victoria? Grand Marquis? TD Super Coupe? MY '91, '93, '94? '92, '95 Escalade?	COMPARE PLATFORMS
	FUEL... - Electrical pressure switch - Converter - Servo system - Electrical Distribution SYSTEM FAILURE... - Cruise Inoperative - Locked in park - Shift Inoperative - Brake Lights Inoperative - Discharged battery - Door lock? - Speed Inop?	Not only pressure switches Other circuits	COLLECT/TEST OTHER SYSTEM COMPONENTS FOR 'SYNERGY' COMPARE VEHICLE OPTIONS FOR SYNERGY COMPARE WARRANTY
WHERE	Driver side head Medium height in engine compartment	Passenger side head Dash - just compartment Not high in engine compartment Not low in engine compartment	EVALUATE HEAT SOURCES
WHEN	1-24 hours after parking Ignition off After 4-6 years After XXX miles After AAA switch cycles	Not while driving Not while ignition on Not before 3 years? Not before XXX miles Not before XXX cycles	EVALUATE POWER AND HEAT AND WIND SOURCES REVIEW MILES
HOW BIG	140 mm / 220 mm "waffle star" shape	Not all size? Not "exploded"	COMPARE PLATFORMS READ PER RPTS
	Several pressure switches	Not all unlabeled size Not all pressure switches	VERIFY UNDERHOOD

CONFIDENTIAL



**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99**



**Texas Instruments
Automotive Service & Controls
RD Report**

Attachment

Customer Title 77 PG Thermal Events		Open Date 2/99	
TI CAR Report Number CAR 98-29		System ABS	
Make/Model Lincoln Town Car		Part Name Brake Speed Control Deactivation Pressure Switch	
Year 1998		Part No. 7723 B-1	
1. Team: S. Robinson, M. Dyer, A. McCall, G. Hill, A. Johnson, C. Douglas, T. Rowland		2. Problem Description: Under load on fire	
3. Customer Action(s): Under review, awaiting braking speed control system		% Effectiveness	Implementation Date
4. Root Cause: See attachment 1, 2 - 8 HOUR Table, (Timeline of 3/2/99) <ul style="list-style-type: none"> - Water enters pressure switch from connector - Connector power drive corrosion - Corrosion causes high resistance - Resistance causes load shedding - Several exposures over time (?) - Load shedding ignites pressure switch and connector joints - Corrosion present on 7723B 		% Contribution	Unknown
5. Corrective/Permanent Corrective Action: See attachment 1, 2, 4 Under Review: <ul style="list-style-type: none"> - Relay Issues - Connector Issue - Create ground fault protector - Improve connector - Eliminate contact wear - Change IM resistance - Provide power response reduction - Modify plastic components - Optimize polarity - Minimize ground potential 		Verification TBD by lab experiments	% Effectiveness Unknown
6. Implemented Permanent Corrective Action:		Implementation:	
7. Action(s) to Prevent Recurrence: Minimize contact wear, reduce power to switches used, cut into other "Wag" electrical function		Implementation:	
8. Copyrightable Item	Class Date	Reported By: A. McCall Dept. Name: QA Manager Telephone No.: (972) 236-3333	

CONFIDENTIAL


Classified by: [illegible]

Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99



77pcB-1		GROSS QTY		COMPLETE	COMPLETE	REM	IMPACT	COMMENTS/CONCNS
COMPONE	DESCRIPTE	REQUIRED	SUPPLIER	1WK	2WK	PARTIAL	TO TI	
27408-1	CONVERTER	2,040,000	RF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY
27630-1	WASHER/A	2,040,000	DEMASTER	10 WKS	18 WKS	2 WKS	NONE	MATERIAL AVAILABILITY
27713-1	CUP/TIPS	2,040,000	VALENTINE	8 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
30630-27	5/TFS	2,040,000	DEC DEPT	12+ WKS	24 WKS	3 WKS	TOOL \$?	POSSIBLE CAPACITY ISSUE
30800-1	HERFOT 7	2,040,000	ELOD	10 WKS	25 WKS	3 WKS	NONE	RAW MATERIAL AVAILABILITY
74224-1	KAPTON	204	ENDUFONT	2 WKS	2 WKS	2 WKS	NONE	
27225-1	KAPTON ST	1,102	ENDUFONT	3 WKS	3 WKS	2 WKS	NONE	
74353-1	GASKET	2,040,000	JEL PAPER	8 WKS	18 WKS	3 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
30808-1	STATIONAR	2,040,000	RF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/FELS
28744-1	CONTACT-S	2,040,000	DEFFINGER	4 WKS	8 WKS	1 WK	NONE	MATERIAL AVAILABILITY
30807-1	MOVABLE E	2,040,000	RF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/FELS
27716-1	BECLISSU	448	BRUSHWEL	1 WK	2 WKS	1 WK	NONE	NONE
74016-1	RIFET	2,040,000	JOHN HASS	8 WKS	11 WKS	4 WKS	NONE	RAW MATERIAL AVAILABILITY
48515-2	PRESSURE S	2,040,000	MINICLON	16 WKS	32 WKS	4 WKS	NONE	RAW MATERIAL CHANGE OVER PRESS CAPACITY
74078-143	CERAMINFE	2,040,000	PARATECH	7 WKS	15 WKS	2 WKS	NONE	
74074-4	BLUE OYND	2,040,000	JEL PAPER	8 WKS	10 WKS	2 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
74077-1	GRIPRING	2,040,000	VALENTINE	8 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
74080-1	RED THERM	2,040,000	MARK M CH	3 WKS	8 WKS	1 WK	NONE	
77FS	SWITCH		TI	7/15/91, 8/91	250K/MONTH			7 day weeks, thru summer vacations, 100% plastic hold;

TL-NHTSA 013897




TI-NHTSA 013888

C:\n\0000\p\m\m\of\of

CONFIDENTIAL

Attachment



TI-NHTBA 019689

CONFIDENTIAL

**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/90**



Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	II	Vary water concentrations in "new" Brake Fluid 14Vdc to one terminal, lamp grounded Water Conc: 4%, 8%, 16%, 32%	220+ hours. Current draw in the 0.5mA to 5mA range Field was discharged No significant temperature rise. Test Suspended Initial Analysis suspended
	2	II	New Brake Fluid 1 Amp through one side terminals 14Vdc to one terminal, lamp grounded	220+ hours. Constant temperature No significant temperature rise with time Test Suspended
	3	AVT	"new" Brake Fluid in Switch, 24 VDC to one terminal. Lamp not grounded	> 200 hours into test, zero current flow No significant change with time. Test ongoing
	4	AVT	"new" Brake Fluid in Switch, 24 VDC to one terminal. Lamp not grounded, Ambient at 100 C	10 hours into test zero current flow No significant temperature rise with time. Test suspended
	5	AVT	"new" Brake Fluid in Switch, 16 Amps through one side terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended
	6a	AVT	"new" Brake Fluid in the Switch approx. 60 Amps through one side terminals	Temperature rose to approx. 270 F. No arcing. No ignition Test suspended
	6	II	Build heater elements into the Switch. Heat of failure, include sparking With Fluid & Dry	2 tested. Device observed, ignition observed on post to heater One observed Test complete Brake fluid is easily drawn down and built up Sparks observed at 675 F, flame with and falls off at 800 F
	6b	II	Coils heater by covering spring arm Salt water solution, 14Vdc to one spring and lamp	One out of 15 devices increased resistance to 6 ohms. Others either vary low resistance or resistance It took about 100 hours to reach the 5 ohm stage. The 5 ohm device failed under conditions similar to Test 6.
	6c	II	Re-run ignition test to understand repeatability and current path.	Switch ignition w/ it repeated 5% w/ other switches into one Switch Current path is through lamp See plots and video Additional test includes tap water, oil BF, new BF and other.

TI-NHTSA 013690

Brake Pressure Switch

Potential Thermal Event Theory Profile 5/20/99



Item	SN	TR	Flow Test / Test Method	Test Results / Observations
			Flow Test / Test Method	Test Results / Observations
Life Cycle Reliability of Pressure Switch	7	TR	2-1400 psi pressure pulses at 1000 per 20	Flow test observed at 200,000 cycles. Seal Checked. Seal attached Water Chest.
Life Cycle Reliability	8	TR	2-1400 psi pressure pulses at 1000	Flow test observed every 5000 cycles, discontinued for wear.
Field on Life Cycle	9	Control Valve	Field returns, Swivel Valve, 2-1400 psi	Flow in Control Valve, see Field operations
Design of Experiments (1) Evaluating Flammability Bleeding Diaphragm Filter Injection Test	10	TR	Flow under conditions in "low" brake field 10 drops + 10 equal surges w/ 5% water in BP 10 drops + 10 equal surges w/ 5% water in BP	Test Results indicate flow under conditions. Suspected at 1.2 million cycles with no leaks observed. Seal samples suspended at 1.2 million cycles with 2 leaks observed at 1.2M. Child samples suspended at 1.2M cycles to review testing accuracy.
On-Vehicle Characterization of Pressure & Temperature Profile in Test Car	11	AVT	Monitor Pressure and Temperature at the Inlet Location for ABS and non-ABS braking events.	Test at AVT... see Field reports... -0000 in part?
Brake Fluid Analysis Used Fluid at master cylinder	12a	TR	Analyze wet/dry fluid at the master cylinder (MCA), used brake fluid at the caliper (UCA) and new brake fluid (NCA) for metal and water content.	Test samples: MCA: Cu = 418 ppb, Fe = 5.0 ppb, Cr = 0.000 ppb, 1.1 %H ₂ O UCA: Cu = 100 ppb, Fe = 0.5 ppb, Cr = 0.0 ppb, 1.1 %H ₂ O NCA: Cu = <0.001 ppb, Fe = 0.001 ppb, Cr = <0.001 ppb, 0.3 %H ₂ O
Spent Fluid Study	13	Control Valve	Characterize & analyze fluid from in certain - using clean bench and high speed rotor. Also try replicate as well as the field with various brake fluid in other valves.	Spent fluid set up in progress at Control Valve. If supplemented with an "identical" spent sample observed.
Characterization of Corrosion Potential Inherent in Various Materials Inherent in Components & other systems	14	Control Valve	Characterize the electrical, mechanical and chemical aspects of various materials.	Test log and samples currently set up complete. Results of the tests in progress.
Field Injection Tests	15a	TR	Inject water into the system with various flow rates. 1000 psi flow 5% NaCl in tap water rain water 1000 psi flow tap water used brake fluid new brake fluid w/ 5% NaCl new brake fluid new brake fluid w/ 5% NaCl	Test results: 5% NaCl sample injected in an injection. All brake fluid samples draw less than 3 amps. No corrosion observed on large field samples. Flow of air and tap water samples draw <10 amps and show ed some signs of corrosion. Chemical analysis in progress.

TI-NR-TSA 013891

Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99




Compatibility of Nylon with Oxalic Acid	14	Expend	Characterize change in properties of Nylon with various % oxalic acid in brake fluid.	Compatibility of Nylon with Oxalic Acid	14	Expend	Characterize change in properties of Nylon with various % oxalic acid in brake fluid.
Evaluation of Plastic Materials with Impact Parameters	15	W	Assess properties and suitability of different grades of plastic materials with addition to impact plastic part performance.	Evaluation of Plastic Materials with Impact Parameters	15	W	Assess properties and suitability of different grades of plastic materials with addition to impact plastic part performance.
Long duration brake fluid exposure test.	16a	W	(1) samples with new brake fluid (2) samples with used brake fluid	Long duration brake fluid exposure test.	16a	W	(1) samples with new brake fluid (2) samples with used brake fluid
Evaluation of Switch Operation	17a	W	Assess ignition suitability in switch operation. Test vertical versus 45 degree. Test rotational suitability in 45 deg. orientation.	Evaluation of Switch Operation	17a	W	Assess ignition suitability in switch operation. Test vertical versus 45 degree. Test rotational suitability in 45 deg. orientation.
Relay Circuit Test	18	W	Expend test 120 in Ford relay circuit for (40) hrs. Relay switch to bypassing ignition in (10) Amp circuit then place in relay circuit for (30) hrs. Signal max. circuit pop or into heater on switch.	Relay Circuit Test	18	W	Expend test 120 in Ford relay circuit for (40) hrs. Relay switch to bypassing ignition in (10) Amp circuit then place in relay circuit for (30) hrs. Signal max. circuit pop or into heater on switch.

7-NHTSA 013892



**OVERVIEW OF
CONCERN TIME LINE**



TI-NHTSA 013694

CONFIDENTIAL




Brake Switch Overview

- **Mounted under hood...14 inches under master cylinder**
- **Mounted on proportional valve at frame of vehicle**
- **Switch oriented approximately 25 degrees off vertical (connector up)**
- **Switch controls speed control...normally closed, opens at 130 psi**
- **Continuously powered by battery 15 amp connection**

CONFIDENTIAL




**PRESSURE SWITCH "FLOW DIAGRAM"
('92, '93, TOWN CAR)**




CONFIDENTIAL

TI-NHTBA 013088



TI-NHT8A 013897

CONFIDENTIAL



TI-NHTBA 013898

Ford recalls 279,000 cars because of risk of cruise-control fires

05/19/1999

Associated Press Newswires

Copyright 1999. The Associated Press. All Rights Reserved.

DEARBORN, Mich. (AP) - Ford Motor Co. has recalled 279,000 full-size cars because of a cruise-control switch that could short-circuit and cause a fire.

The recall affects the 1992 and '93 Lincoln Town Car, Mercury Grand Marquis and Ford Crown Victoria. About 10,900 of the recalled cars are in Canada.

There have been 147 reports of fires and two injuries attributed to the defect, Ford spokeswoman Karen Shughnessy said Tuesday.

The automaker said it is still obtaining replacement switches. Until the switch can be fixed, customers should take their cars to their dealer and have the cruise control disabled, Ford said.

CONFIDENTIAL




NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering	Power Steering	Power Steering	Power Steering	Power Steering
		Suspension	Suspension	Suspension	Suspension	Suspension
			Transmission	Transmission	Transmission	Transmission
				Cruise	Cruise	Cruise
					Clutch	Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

Contributing Factors



1. Connector Seal
2. Kapton Life
3. Continuous Power
4. Switch Orientation
5. Current Capability
6. Grounded Hex-Port
7. Plastic Parameters



AGENDA


- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **OVERVIEW TIME LINE**
- **SYSTEM OVERVIEW**
 - **SWITCH AND CONNECTOR**
- **IS / IS NOT TABLE**
- **CAUSE AND EFFECT DIAGRAMS**
- **THEORIES**
 - **BRAKE FLUID IGNITION**
 - **PLASTIC IGNITION**
- **TEST RESULTS**
- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **ROBUST DESIGN ALTERNATIVES**



- 1. Connector Seal to P/S**
- 2. Power continuously available**
 - A. Operator notifications**
- 3. Switch orientation/location**
- 4. Current limit / fuse**
- 5. Hexport isolation**
- 6. Plastic ignition robustness**
 - A. Nearby fuels**
- 7. Kapton seal of P/S**
- 8. Environmental seal of P/S**



OVERVIEW OF
CONCERN TIME LINE



Attachment



Brake Switch Overview



- **Mounted under hood... 14 inches under master cylinder**
- **Mounted on proportional valve at frame of vehicle**
- **Switch oriented approximately 25 degrees off vertical (connector up)**
- **Switch controls speed control... normally closed, opens at 130 psi**
- **Continuously powered by battery 15 amp connection**



TEXAS
INSTRUMENTS

Brake Pressure Switch


Potential Thermal Event Theory Profile 4/14/99



TMHTBA 013707


© 1999 Texas Instruments

Brake Pressure Switch Potential Thermal Event Theory Profile 4/14/99



TI-NHTSA 013708

Brake Pressure Switch Potential Thermal Event Theory Profile 4/14/99






SEE EXCEL SPREADSHEET



**REFINED BRAKE FLUID IGNITION THEORY
POSSIBLE CAUSE THEORIES
"FEB '99 FOCUS"**



© Motorola/Philips/Infineon


Attachment

TMHTBA 013711



- TI and Ford not successful in creating ignition with "new" brake fluids

Brake Pressure Switch Potential Thermal Event Theory Profile 4/14/99




TI-NHTSA 019713

1. Actual Presentation



Generated by: *ReliaSoft's Weibull++ 5.0* - www.Weibull.com - 888-886-0410

77PSL2-1 COMBINED DATA



Weibull
Data 1
•
P=2, A=RRX-S
F=9 | S=33
CB/FM: 95.00%
2 Sided-B
C-Type 2

User's Name
Texas Instruments
4/7/99
9:31:45 AM

B = 5.83, $\eta = 1.64E+6$, $p = 0.91$

1.00E+05


TMHTSA 013714



- "Town Car" switch meets accelerated/simulated life cycle specification shown by "success" and "end-of-life" testing



**PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS**



Attachment

TI-NHTBA 013716


© 1999 Texas Instruments



5. High current flow to case through water and ionic contamination

2. 12V Battery source to drive corrosion and provide energy

6. Plastic connector melts. Once it opens, oxygen enters the switch cavity. Arm terminal corrosion becomes "RED HOT" igniting the plastic



1. Water and "ionic" contamination (e.g. NaCl or cleaner) enters the switch cavity



4. Contact arm & terminal corrosion increases resistance (acts like heater wire).

3. Hexport grounded accelerates corrosion

Attachment 2



5% Salt Water Ingress Experiment
Test 1



Test 1: Figure 1 and Figure 2.

TI Report PS/99/12
03/15/99


Copyright © 1999 Texas Instruments

TI-NHTSA 013718



5% Salt Water Ingress Experiment
Temperature vs. Time

— Top Temp — Clutch Temp — Bottom Temp




1. Scale: 1000:1

TI-NHTSA 013719



5% Salt Water Ingress Experiment

Voltage - T1 — Voltage - T2 — Ground Voltage — Input Current — Clutch Current — Output Current



TI-NHTSA 015720



**77PS
45° Orientation in 15 Amp Circuit
5% Salt Water Ingress**

Cellanex 4300 Base



Cellanex 3316 Base




TI-NHTSA 013721

1. Method of Inspection




“Corrosion” potential cause time line
Theory Time Line



TI-NHTSA 015722



“Corrosion” potential cause time line
Theory Time Line




Attachment

TX-NHTSA 018723



PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS




TI-NHTSA 015724

© All rights reserved.

Attachment



**PRESSURE SWITCH "FLOW DIAGRAM"
('92, '93, '94 TOWN CAR)**




TI-NHTSA 013726

1. All used, Theory of the



ECONOLINE VS. TOWN CAR P/S



TI-NHTBA 013728

For the TTPS 1.3.2 and not show all shipping facilities - numbers for facilities no longer on file are

Location	SHIP NO LOC	Part Number	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	1974 TOTAL	Notes		
Tampa 1 000	VUL	71742 2 1720C W420 AA	3100	41	63	78	0	0	0	0	0	0	0	0	0	2 (plant 47)	1 (plant 48)	
		71743 2 1720C W420 AA	0	0	0	0	72	84	0	24	25	90	0	0	0	3 (plant 47)	12 (plant 48)	
		71744 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
M3 0000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	2 (plant 47)	1 (plant 48)	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	420	100	104	3 (plant 47)	12 (plant 48)	
		71745 2 1720C W420 AA	142	380	333	186	238	0	0	0	0	0	0	0	0	3 (plant 47)	0 (plant 48)	
		71746 2 1720C W420 AA	142	0	114	18	142	142	0	0	171	0	0	114	0	0	3 (plant 47)	0 (plant 48)
		71748 2 1720C W420 AA	0	220	0	0	0	0	0	0	0	0	0	0	0	0	3 (plant 47)	0 (plant 48)
Tampa 0000000000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	2 (plant 47)	0 (plant 48)	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71745 2 1720C W420 AA	1547	1573	2150	2281	1454	2281	207	3048	2938	1048	2475	207	2	2 (plant 47)	0 (plant 48)	
		71746 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71748 2 1720C W420 AA	2200	1280	1070	207	2380	0	0	0	0	110	0	0	0	0	2 (plant 47)	0 (plant 48)
		71745 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		71745 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tampa 0000	VUL	71742 2 1720C W420 AA	1100	470	53	0	0	0	0	0	0	0	0	0	0	3 (plant 47)	0 (plant 48)	
		71743 2 1720C W420 AA	0	0	0	142	0	0	0	0	0	0	0	0	0	0	0	
		71745 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Tampa 00000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	2 (plant 47)	0 (plant 48)	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Tampa 00000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Tampa 0000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Tampa 0000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Tampa 0000	VUL	71742 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		71743 2 1720C W420 AA	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	


71-NHTBA 013727



Brake Pressure Switch
Potential Thermal Event Theory Profile 4/14/99



77PS Noryl Base
45° Orientation in 15 Amp Circuit
5% Salt Water Ingress




© 1999 Texas Instruments

TI-NHTSA 018728



**77PS Cellanex 4300 Base
Vertical Orientation in 15 Amp Circuit
5% Salt Water Ingress**




1 Actual Presentation

TI-NHTSA 013729



TTPS Proposed Wiring Schematic



© 1999 Ford Motor Company

TM-NHTSA 015730




1. Connector Seal to P/S
2. Power continuously available
 - A. Operator notifications
3. Switch orientation/location
4. Current limit / fuse
5. Hexport isolation
6. Plastic ignition robustness
 - A. Nearby fuels
7. Kapton seal of P/S
8. Environmental seal of P/S



200-mAmp Current Limit Circuit Test Setup

14.5 Volts DC



77PIR-1 COMPONENT	DESCRIPTION	GROSS QTY		COMPLETE		BEGIN	IMPACT	COMMENTS/CONCERNS
		REQUIRED	SUPPLIER	10K	20K			
27406-1	CONVERTER	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY
27439-1	WASHER / ARA	2,040,000	DIEMASTER	10 WKS	18 WKS	2 WKS	NONE	MATERIAL AVAILABILITY
27713-1	CUP 77PS	2,040,000	VALENTINE	6 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
36456-27	57PS	2,040,000	DISC DEPT	12+ WKS	24 WKS	3 WKS	TOOL \$7	POSSIBLE CAPACITY ISSUE
36900-1	HEXPOR 77PS	2,040,000	ELCO	10 WKS	25 WKS	3 WKS	NONE	RAW MATERIAL AVAILABILITY
74224-1	KAPTON	204	EI DUPONT	2 WKS	2 WKS	2 WKS	NONE	
27225-1	KAPTON STRIP	1,102	EI DUPONT	3 WKS	3 WKS	2 WKS	NONE	
74353-1	GASKET	2,040,000	JBL PARKER	8 WKS	18 WKS	3 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL BY 10%
36888-1	STATIONARY T	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY/ REELS
28744-1	CONTACT-SIEV	2,040,000	DERRINGER	4 WKS	8 WKS	1 WK	NONE	MATERIAL AVAILABILITY
36887-1	MOVABLE TERM	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY/REELS
27736-1	RE/CU ISSUE	449	BRUSHWELLMAN	1 WK	2 WKS	1 WK	NONE	NONE
74914-1	RIVET	2,040,000	JOHN HASSAL	8 WKS	11 WKS	4 WKS	NONE	RAW MATERIAL AVAILABILITY
46515-2	PRESSURE SWI	2,040,000	LMT/MOLDING	16 WKS	32 WKS	4 WKS	NONE	RAW MATERIAL CHANGEOVER/PRESS CAPACITY
74078-143	CERAMIN PINS	2,040,000	PARATECH	7 WKS	15 WKS	2 WKS	NONE	
74247-4	BLUE O'RINGS	2,040,000	JBL PARKER	6 WKS	10 WKS	2 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL BY 10%
74797-1	CRIMP RING	2,040,000	VALENTINE	6 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
74888-1	RED THREAD C	2,040,000	MARK IV CAPLUG	3 WKS	6 WKS	1 WK	NONE	

77PS

SWITCH

TI

7/15,8/1,9/1 250K/MONTH

7 day weeks, thru summer vacations, 'std' plastic mold

TI-NHTSA 013738



AGENDA

- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **OVERVIEW TIME LINE**
- **SYSTEM OVERVIEW**
 - **SWITCH AND CONNECTOR**
- **IS / IS NOT TABLE**
- **CAUSE AND EFFECT DIAGRAMS**
- **THEORIES**
 - **BRAKE FLUID IGNITION**
 - **PLASTIC IGNITION**
- **TEST RESULTS**
- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **ROBUST DESIGN ALTERNATIVES**

TI-NHTBA 013734



Brake Pressure Switch
Potential Thermal Event Theory Profile 3/24/99




1. Connector Seal to P/S
2. Power continuously available
3. Switch orientation
4. Current limit / fuse
5. Hexport isolation
6. Plastic ignition robustness
7. Kapton seal of P/S
8. Environmental seal of P/S

TI-NHTSA 018736



**OVERVIEW OF
CONCERN TIME LINE**



TI-NHTSA 013736



Brake Switch Overview

- **Mounted under hood... 14 inches under master cylinder**
- **Mounted on proportional valve at frame of vehicle**
- **Switch oriented approximately 25 degrees off vertical (connector up)**
- **Switch controls speed control... normally closed, opens at 130 psi**
- **Continuously powered by battery 15 amp connection**