

**EA02-025**

**TEXAS INSTRUMENTS, INC.'S**

**9/10/03**

**REQUEST NO. 7**

**BOX 9**

**PART A - R**

**PART E**

Brake Pressure Switch Test Log, Updated 5/20/90

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Vary water concentration in 'new' Brake Fluid 14Vdc to one terminal, heupost grounded Water Cont: 4%, 8%, 16%, 32%	250+ hours. Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, heupost grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heupost Grounded	> 200 hours into test, max current 7mA No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heupost Grounded. Ambient at 100 C	10 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 10 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	6a	AVT	'new' Brake Fluid in Switch approx. 60 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat 80 wires, include spooling. (1) w/ solution of Brake Fluid and 8 wt. % H <sub>2</sub> O	3 tested. Smoke observed, ignition observed on part w/ water Best attachment Test complete Brake fluid in cavity slopes down heat build-up Smoke observed at 675 F, Best wire and fails off at 800 F
	6a	TI	Create heater by coarsing spring arm Salt water solution, 14V between spring and heupost	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or megohms It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignites with repeated 5% water solution into switch Current path is through heupost. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TL-NHTSA 013728

Brake Pressure Switch Test Log, Updated 5/20/00

				conclusion
Life Cycle Reliability of Pressure Switch	7	TI	D-1400 only pressure pulses at 130C per BS	First leak observed at 720,000 cycles. Test Completed. See attached Wettest Chart.
Discharge Wear	8	TI	D-1400 only pressure pulses at 130C.	Leak observed every 200k cycles, characterized for wear.
Field vs Lab Correlation	8	Control Labs	Field vehicle, from driver logs, hydrostatic	Parts in Control Labs, use Ford spreadsheet
Design Of Experiments (1)	10	TI	Very water concentrations in 'new' Brake Fluid	Test Report being written investigation continues.
Excluding Factors			12 amp + 12 quid switches w/ 5% water in BF	Suspended at 1.3 million cycles with no leaks observed.
Effecting Discharge Wear			12 amp + 12 quid switches w/ 5% water in BF	Swap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quail sample suspended at 100k cycles to assess fitting procedure.
On-Vehicle Characterization of Pressure & Temperature Profile in Test Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS loading events.	Test at AVT... see Fuel charts... >500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (MBC), used brake fluid at the caliper (UCA) and rear brake fluid (RWB) for metal and water content.	Test complete. MBC: Cu = 415 (ppm), Fe = 6.5 (ppm), Cr = 0.88 (ppm), 1.1% H <sub>2</sub> O. UCA: Cu = 582 (ppm), Fe = 2.5 (ppm), Cr = 1.3 (ppm), 1.1% H <sub>2</sub> O. RWB: Cu = 48.01 (ppm), Fe = 0.82 (ppm), Cr = <.01 (ppm), 0.5% H <sub>2</sub> O.
Spark Arc Study	12	Control Labs	Determine if arcing forms in switch using clock loads and high speed video. Use dry switches as well as switches with various brake fluid water ratios.	Equipment set-up in progress at Control Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field hydrostatic & other stresses	13	Control Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Impact Tests	13a	TI	Repeat ignition simulation with different fluids. All long tests: 5% NaCl in tap water rain water 100 hour tests: tap water	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples draw less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples draw <10 mAmps and showed some signs of corrosion.

TL-NHTSA 013730

Brake Pressure Switch Test Log, Updated 5/20/99

			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Vary water concentrations in 'new' Brake Fluid	Test suspended. Analysis in process to assess test findings.
Repeat of test 10			10 swep + 28 quiet switches w/ 0 % water in BF	
			10 swep + 28 quiet switches w/ 5 % water in BF	
Compatibility of Kapton with Oxalic Acid	14	Deport	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects that water has on Kapton properties.
Evaluation of Plastics Materials with Improved Performance	15	TI	Assess properties and suitability of alternate grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl tested 30 and 25 trials ZYTEL samples tested 105 ignitions
Long duration brake fluid ingress test.	15a	TI	(1) samples with new brake fluid (2) samples with used brake fluid	Test suspended (550) hours completed. Used brake fluid current dropped off to <1/10 mAmp. New BF ingress current can increase w/ time under cont. power.
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Simulated switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 13a in Ford relay circuit for (400) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (180) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Inefficient power in circuit to create or move toward ignition in lab. Heater element was warm to the touch.
Long duration brake fluid ingress test number 2.	17	TI	(50) samples filled with new brake fluid (1) hour of vibration per day (1) hour soak at 180 deg C per day	Test suspended. (312) hours completed. Average heater current is 1.5 mAmp (std deviation = 1.8 mAmp)

TI-NHTSA 013740

**Brake Pressure Switch  
Potential Thermal Event Theory Profile 5/20/99**




77pa12-1		GROSS QTY		COMPLETE	COMPLETE	BEGIN	IMPACT	COMMENTS/CONCERNS
COMPONENT	DESCRIPTION	REQUIRED	SUPPLIER	1WK	2WK	PARTIAL	TO TI	
27406-1	CONVERTER	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY
27639-1	WASHER/A	2,040,000	DEMASTER	10 WKS	18 WKS	2 WKS	NONE	MATERIAL AVAILABILITY
27713-1	CUP 77PS	2,040,000	VALENTINE	8 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
36856-27	57PS	2,040,000	DISC DEPT	12+ WKS	24 WKS	3 WKS	TOOL \$?	POSSIBLE CAPACITY ISSUE
36900-1	HEXPORT 7	2,040,000	ELOO	10 WKS	25 WKS	3 WKS	NONE	RAW MATERIAL AVAILABILITY
74224-1	KAPTON	204	EDUPONT	2 WKS	2 WKS	2 WKS	NONE	
27225-1	KAPTON ST	1,102	EDUPONT	3 WKS	3 WKS	2 WKS	NONE	
74363-1	GASKET	2,040,000	JEL PARKER	8 WKS	18 WKS	3 WKS	NONE	ELIMINATE COPES WILL INCREASE DEL. BY 10%
36888-1	STATIONAR	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/FELS
28744-1	CONTACT-S	2,040,000	DEFFINGER	4 WKS	8 WKS	1 WK	NONE	MATERIAL AVAILABILITY
36887-1	MOVABLE T	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/FELS
27718-1	BEFCU ISLE	448	BRUSHWELL	1 WK	2 WKS	1 WK	NONE	NONE
74916-1	RIVEI	2,040,000	JOHN HASS	8 WKS	11 WKS	4 WKS	NONE	RAW MATERIAL AVAILABILITY
46515-2	PRESSURE S	2,040,000	MTI MOLDING	16 WKS	32 WKS	4 WKS	NONE	RAW MATERIAL CHANGED OVER PRESS CAPACITY
74078-143	CERAMIN PR	2,040,000	PARATECH	7 WKS	15 WKS	2 WKS	NONE	
74247-4	BLUE OTING	2,040,000	JEL PARKER	8 WKS	10 WKS	2 WKS	NONE	ELIMINATE COPES WILL INCREASE DEL. BY 10%
74787-1	CRIMPING	2,040,000	VALENTINE	6 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
74888-1	RED THREA	2,040,000	MARK N. CA	3 WKS	6 WKS	1 WK	NONE	
77PS	SWITCH		TI	7/15, 8/1, 8/15	250K/MONTH			7 day weeks, thru summer vacations, 'skd' plastic mold

TI-NHTSA 013741



**200 mAmp Current Limit Circuit**  
**Test Setup**


14.5 Volts DC



Worst case scenario is when the switch is actuated, which puts T2 at full voltage. To facilitate testing, T1 is floating which keeps T1 and T2 at full voltage but limits current draw to .2 Amps (This test is harsher than worst case scenario).



### "Corrosion" potential cause time line Theory Time Line




TI-NHTSA 013748

Copyright © 1999 Texas Instruments



Generated by: ReliaSoft's Weibull++ 5.0 - www.Weibull.com - 888-886-0410

**77PSL2-1 COMBINED DATA**




$\beta=5.83, \eta=1.64E+6, \rho=0.91$





**77PS Noryl Base  
45° Orientation in 15 Amp Circuit  
5% Salt Water Ingress**



TI-NHTSA 019749

C:\McQuint\99\presentation\Fwd


**INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST PS99/13 Attachment**

**TEXAS  
INSTRUMENTS**

**Brake Pressure Switch  
Potential Thermal Event Theory Profile 5/20/99**



**77PS Cellanex 4300 Base  
Vertical Orientation in 15 Amp Circuit  
5% Salt Water Ingress**




C:\McQuib99\presentations\Ford **INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST PS99W13' Attachment**

TI-NHTSA 013761

# Brake Pressure Switch Potential Thermal Event Theory Profile 5/20/99



## 5% Salt Water Ingress Experiment





C:\McGraw\99\operational\Ford INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST '95/99/13' Attachment



- TI and Ford not successful in creating ignition with "new"  
brake fluids




Lab Experiment-5% NaCl/H<sub>2</sub>O and Continuous Power



- Contact arm (Cu) corrodes - chemical analysis shows presence of Na, Cl, Cu, and O on the cup surface



77PS Noryl Base  
45° Orientation in 15 Amp Circuit  
5% Salt Water Ingress



TL-NHT&A 013758

C:\ok\ok\99\ps\ok\ok\Ford

INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST PS/99/13 Attachment



**77PS Cellanex 4300 Base**  
**Vertical Orientation in 15 Amp Circuit**  
**5% Salt Water Ingress**




Not Enough Printer Memory -- See User's Guide

TI-NHTSA 013761



## 5% Salt Water Ingress Experiment




TI-NHTSA 013763





Hexport Current vs. Time  
(3) Hour Fluid Ingress Experiment  
(0.015 Amp Full Scale)

— New Brake Fluid	— New Brake Fluid w/ 5% water	— Used Brake Fluid w/ 5% Water
— Tap Water	— Used Brake Fluid	— Rain Water
— 5% Salt Water	— 100 per. Mov. Avg. (5% Salt Water)	



TI-NHTSA 013765

Brake Pressure Switch Test Log, Updated 8/22/98

				conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per FS	Field leak observed at 775,000 cycles Test Complete. See attached Weibull Chart.
Diaphragm Wear	8	FI	0-1400 psig pressure pulses at 135C	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Central Labs	Field returns, from docks lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear Impulse test	10	TI	Vary water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0% water in DF 12 snap + 12 quiet switches w/ 5% water in HF	Test Report being written. Investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess tubing assemblies.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVI	Monitor Pressure and Temperature of Switch Location for ABS and non-ABS braking events.	Test at AVI....see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder	11a	TI	Analyze used brake fluid of the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content	Test complete. UMC: Cu = 416 (ppm), Fe = 5.6 (ppm), Cr = 0.08 (ppm), 1.1 %H2O UCA: Cu = 582 (ppm), Fe = 6.8 (ppm), Cr = 1.0 (ppm), 1.1 %H2O NEW: Cu = 4.01 (ppm), Fe = 0.92 (ppm), Cr = 4.81 (ppm), 0.3 %H2O.
Spark Arc Study	12	Central Labs	Determine if arcing forms in switch using chitch loads and high speed video. Use dry switches as well as switches with various brake fluid water ratios.	Equipment set-up in progress at Central Labs. TI Experimental with no 'significant' sparks observed
Characterization of switches retrieved from field junkyards & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Fluid Ingress Tests	13a	TI	Repeat Ignition simulation with different fluids. (3) hour tests 0% NaCl in tap water rain water (24) hour tests tap water	Test complete. 0% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mAmps and showed some signs of corrosion.

TI-NHTSA 013767

## Brake Pressure Switch


Potential Thermal Event Theory Profile 6/02/99



5. High current flow to case through water and ionic contamination

2. 12V Battery source to drive corrosion and provide energy

6. Plastic connector melts. Once it opens, oxygen enters the switch cavity. Arm terminal/corrosion becomes "RED HOT" igniting the plastic




1. Water and "ionic" contamination (e.g. NaCl or cleaner) enters the switch cavity

4. Contact arm & terminal corrosion increases resistance (acts like heater wire).

3. Hexport grounded accelerates corrosion

TI-NHTSA 013769


# Brake Pressure Switch Potential Thermal Event Theory Profile 6/02/99



TI-NHTSA 013771

Attachment

# Contributing Factors




1. Connector Seal
2. Kapton Life
3. Continuous Power
4. Switch Orientation
5. Current Capability
6. Grounded Hex-Port
7. Plastic Parameters

TI-NHT8A 013773

# Brake Pressure Switch Potential Thermal Event Theory Profile 5/20/99




	CR	TI	Full Year '98 Brake Fluid with initial analysis	Other elements do not contribute significantly to brake fluid condition
Life Cycle Fatigue of Pressure Switch	7	TI	0-1400 psig pressure pulses at 1200 per hr	Test limit observed at 700,000 cycles. Test Completed. See attached Thermal Chart.
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 1200	Parts in laboratory every 2000 cycles, of wear noted for wear
Field on Lab Correlation	9	Central Labs	Field returns, manufacturer info, lab work	Parts in Central Labs, see field correspondence
Desktop Cl Experiments (1) Evaluating Factors Effecting Diaphragm Wear Replicate test	10	TI	Very to test concentrations in 'new' Brake Fluid 12 amp + 12 quat w/ 0% water to Br 12 amp + 12 quat w/ 20% w/ 8% water to BP	Test Flapout being shown from material condition. Suspended at 1.3 million cycles with no leaks observed. Swap complete completed at 1.2 million cycles with 2 leaks observed at 1.2M. Cycle complete suspended at 600k cycles to evaluate diaphragm condition.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at the both Location for ABS and non-ABS landing events.	Test at AVT, see Ford charts, 2-2000 in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (MCA), used brake fluid at the cylinder (MCA) and new brake fluid (MCA) for metal and water content.	Test complete. MCA: Cu = 410 ppm, Fe = 8.0 ppm, Cr = 0.00 ppm, 1.1 % H <sub>2</sub> O MCA: Cu = 800 ppm, Fe = 6.2 ppm, Cr = 1.0 ppm, 1.1 % H <sub>2</sub> O MCA: Cu = 2000 ppm, Fe = 0.00 ppm, Cr = 0.00 ppm, 0.2 % H <sub>2</sub> O
Spent Run Study	12	Central Labs	Determine if arcing/spark forms in any lab using clutch tests and high speed video. Use dry particles on wall on surfaces with various brake fluid w/ other oils.	Equipment set-up in progress at Central Labs. TI Experimented with no 'dry' based sparks observed
Characterization of surfaces exhibited from field lab work & other sources	13	Central Labs	Characterize chemical, mechanical and chemical aspects of removed surfaces	Data log and analysis procedures set up complete. Analysis of dry lab in progress.
Field types tests	13a	TI	Repeat ignition simulation with different fluids. 5% H <sub>2</sub> O in top water top water used brake fluid new brake fluid w/ 5% H <sub>2</sub> O new brake fluid new brake fluid w/ 5% H <sub>2</sub> O	Test complete. 5% H <sub>2</sub> O sample handled in dry lab. No leaks that complete tests. Long term 2 setups. No corrosion visible on tubes that complete. Fluo w/ air and top w/ air samples clear <10 ppm and showed some degree of corrosion. Chemical analysis in progress.



TI-NHTSA 013777




**PROCESS FLOW DIAGRAM  
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS**








**REFINED BRAKE FLUID IGNITION THEORY  
POSSIBLE CAUSE THEORIES  
"FEB '99 FOCUS"**



TI-NHTSA 012781

© Dale Clark, 99 presentation Ford

Attachment




TI-NHTSA 015763

C:\Mc\ah\99\presentat\ford

Attachment



**PRESSURE SWITCH "FLOW DIAGRAM"**  
**('92, '93, TOWN CAR)**



TI-AMHTBA 013788



**Brake Pressure Switch  
Potential Thermal Event Theory Profile 5/20/99**



Today's Date: UPDATED 04/21/99

Scope or Effect Description


Attachment

1. Operational Definition (Problem Statement): TOWN CAR UNDERHOOD FIRE			
2. Description	IS	IS NOT	Get Information
WHAT	Town Car MY '91, '93, '94	Crown Victoria? Cavalier Marquette? TR Super Coupe? MY '91, '93, '94? '92, '93 Impala?	COMPARE PLATFORMS
	<p>WREN...</p> <ul style="list-style-type: none"> <li>Electrical pressure switch</li> <li>Coilover</li> <li>Servo system</li> <li>Electrical Distribution</li> </ul> <p>SYSTEM ISSUES...</p> <ul style="list-style-type: none"> <li>Cruise inoperative</li> <li>Locked in park</li> <li>ECM inoperative</li> <li>Brake lights inoperative</li> <li>Discharged battery</li> <li>Door lock?</li> <li>Blower fan?</li> </ul>	<p>Not only pressure switches</p> <p>Other circuits</p>	<p>COLLECT/TEST OTHER SYSTEM COMPONENTS FOR "SYNERGY"</p> <p>COMPARE VEHICLE OPTIONS FOR SYNERGY</p> <p>COMPARE WARRANTY</p>
WHERE	Driver side hood Medium height in engine compartment	Passenger side hood Dash - pass compartment Not high in engine compartment Not low in engine compartment	EVALUATE HEAT SOURCE
WHEN	1-60 hours after parking Ignition off  After 4-8 years After XXX miles  After AAA switch cycles	Not while driving Not while ignition on  Not before 5 years? Not before YYY miles  Not Before BBB cycles	EVALUATE POWER AND HEAT AND WIND SOURCES REVIEW MILES
HOW BIG	149 cars / 213,000 units  "waffle size" size	Not all cars?  Not "topical"	COMPARE PLATFORMS READ FINE PRINT
	Several pressure switches	Not all vehicles have Not all pressure switches	VARIETY UNDERHOOD

Case:04041899:pressswitches:Part



**OVERVIEW OF  
CONCERN TIME LINE**



TI-NHTSA 013789

C:\McCall\Presentations\Ford

Attachment



1. Connector Seal to P/S
2. Power continuously available
  - A. Operator notifications
3. Switch orientation/location
4. Current limit / fuse
5. Hexport isolation
6. Plastic ignition robustness
  - A. Nearby fuels
7. Kapton seal of P/S
8. Environmental seal of P/S

Copyright © 1999 Texas Instruments

Attachment

77P8L2-1: Imputed Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-
<b>Totals units</b>	<b>268,600</b>	<b>600</b>	<b>-</b>

TI-NHTSA 013793



## NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids

TI-NHTSA 013798



Brake Pressure Switch Test Log, Updated 5/21/00

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in 'new' Brake Fluid 24VDC to one terminal, heasport grounded Water Conc: 4%, 6%, 10%, 75%	250+ hours, Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Initial Analysis suspended.
	2	TI	New Brake Fluid 5 Amp through switch terminals 14Vdc to one terminal, heasport grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heasport Grounded	> 300 hours into test, max current 7mA No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heasport Grounded, Ambient at 100 C	18 hours into test max current 6mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 18 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	6a	AVT	'new' Brake Fluid in Switch approx. 50 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Solid Insulator elements into Switch. Heat BF failure, include sparking. (1) of solution of Brake Fluid and 5 wt. % H <sub>2</sub> O	3 tested. Smoke observed, ignition observed on part reheater See attachment Test complete Brake fluid in cavity stress down heat build-up Smoke observed at 675 F, Base melts and falls off at 800 F
	6a	TI	Coarse heater by coarsing spring over Salt water solution, 14V between spring and heasport	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or megohms It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand capability and current path.	Switch ignites with repeated 5% water solution into switch Current path is through heasport. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings don't contribute significantly to BF conductivity.

TI-NHTSA 013797

Brake Pressure Switch Test Log, Updated 5/21/89

			(24) hour tests	Rain water and tap water samples draw <18 m/amp and showed some signs of corrosion.
			tap water	
			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Very water concentrations in 'new' Brake Fluid	Test suspended. Analysis in process to assess test failure.
Repeat of test 10			10 amp + 20 quat solution w/ 5 % water in BF	
			10 amp + 20 quat solution w/ 5 % water in BF	
Compatibility of Kapton with Oxalic Acid	14	Dupont	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects that water has on Kapton properties.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and availability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl graded 305 and 205 trials ZYTEL samples tested 165 ignitions
Long duration brake fluid repeat test.	16a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test suspended (800) hours completed. Used brake fluid cannot dropped off to <1/10 m/amp. New BF heated cannot can increases w/ time under coal. power.
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	17	TI	Repeat test 12a in Ford relay circuit for (40) hrs. Relay switch to impedance ignition in (15) Amp circuit then place in relay circuit for (15) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Available power in circuit to create or grow toward ignition in lab. Heater element was warm to the touch.
Long duration brake fluid repeat test number 2.	17	TI	(50) samples filled with new brake fluid (3) hour of vibration per day (1) hour soak at 100 deg C per day	Test suspended. (312) hours completed. Average input current is 1.0 m/amp (allowance = 1.5 m/amp)

TI-NHTSA 013789

Currey, Pat

---

From: Proia, Stephen [s-proia@small.mc.ti.com]  
Sent: Tuesday, May 18, 1999 3:21 PM  
To: Beringhouse, Steven  
Cc: McGuirk, Andy; Peabodis, John; Dague, Bryan  
Subject: 77PSL2\_1.xls



77PSL2\_1.xls

<<77PSL2\_1.xls>>

Steve,

I've summarized the data per our discussion. I have also reviewed the files in marketing without success. Please let me know if you need anything else.

Regards,

Steve

TI P/N: 77PRL2-1  
 Ford P/N: F2VC-9F924-AB

Date	Lot Size	Qty Inspected Tested	Qty Pass	Qty Leak	Comments
25-Nov-91	4,000	10	10	-	
25-Nov-91	4,000	10	10	-	
5-Dec-91	4,000	10	10	-	
5-Dec-91	4,000	10	10	-	
9-Dec-91	4,000	10	10	-	
9-Dec-91	2,000	5	5	-	
11-Dec-91	4,000	10	10	-	
11-Dec-91	4,000	10	10	-	
13-Dec-91	4,000	10	10	-	
14-Dec-91	4,000	10	10	-	
16-Dec-91	4,000	10	10	-	
16-Dec-91	4,000	10	10	-	
2-Jan-92	4,000	10	10	-	
6-Jan-92	4,000	10	10	-	
7-Jan-92	2,000	5	5	-	
8-Jan-92	4,000	10	10	-	
8-Jan-92	4,000	10	10	-	
14-Jan-92	4,000	10	10	-	
14-Jan-92	4,000	10	10	-	
15-Jan-92	4,000	10	10	-	
28-Jan-92	2,000	5	5	-	
31-Jan-92	4,000	10	10	-	
2-Feb-92	1,650	5	4	-	Broken spring
4-Feb-92	4,000	10	10	-	
5-Feb-92	4,000	10	10	-	
6-Feb-92	4,000	10	10	-	
10-Feb-92	4,000	10	10	-	
11-Feb-92	4,000	10	10	-	
12-Feb-92	4,000	10	10	-	
12-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
15-Feb-92	4,000	10	10	-	
24-Feb-92	4,000	10	10	-	
25-Feb-92	4,000	10	10	-	
25-Feb-92	4,000	10	10	-	
25-Feb-92	4,000	10	10	-	
25-Feb-92	4,000	10	10	-	
28-Feb-92	4,000	10	9	-	Continuity failure, terminal inside of base is not sealed. Date code 2037. Sorted for 100%.
6-Mar-92	4,000	10	10	-	

TI-NHT8A 013801

10-Mar-92	4,000	10	10	.
11-Mar-92	4,000	10	10	.
12-Mar-92	4,000	10	10	.
18-Mar-92	4,000	10	10	.
23-Apr-92	2,000	5	5	.
2-May-92	2,000	5	5	.
5-May-92	2,000	5	5	.
6-May-92	2,000	5	5	.
14-Sep-92	2,000	5	5	.
22-Sep-92	4,000	10	10	.
30-Sep-92	4,000	10	10	.
7-Oct-92	4,000	10	10	.
7-Oct-92	4,000	10	10	.
16-Oct-92	4,000	10	10	.
21-Oct-92	2,000	5	5	.
20-Oct-92	4,000	10	10	.
28-Oct-92	4,000	10	10	.
29-Oct-92	4,000	10	10	.
30-Oct-92	4,000	10	10	.
4-Nov-92	4,000	10	10	.
10-Nov-92	4,000	10	10	.
10-Nov-92	4,000	10	10	.
11-Nov-92	4,000	10	10	.
17-Nov-92	2,000	5	5	.
20-Nov-92	4,000	10	10	.
4-Dec-92	2,000	5	5	.
9-Dec-92	2,000	5	5	.
14-Dec-92	2,000	5	5	.
16-Dec-92	4,000	10	10	.
16-Dec-92	4,000	10	10	.
16-Dec-92	4,000	10	10	.
21-Dec-92	2,000	5	5	.
21-Dec-92	4,000	10	10	.

<b>Totals</b>	<b>26,400</b>	<b>665</b>	<b>663</b>	<b>.</b>
---------------	---------------	------------	------------	----------

**CHEVY, Pat**

---

**From:** Proia, Stephen [s-proia@esmail.mc.tl.com]  
**Sent:** Tuesday, May 18, 1999 3:35 PM  
**To:** Beringhouse, Steven  
**Cc:** Pecheois, John; McGuirk, Andy; Dagus, Bryan  
**Subject:** 77PSL2\_1.xls



77PSL2\_1.xls

Revised version of spreadsheet.

<<77PSL2\_1.xls>>

Regards,

Steve

TI-NHTSA 013803

## 77PBL2-1: Impulse Data Results 11/01 - 12/92

preliminary draft summary of TI record search findings of May 14-17 1999

summary by Steve Berghman & Andy McGrath May 19th 1999

TI P/N: 77PBL2-1

Ford P/N: FZVC-9F924-AB

Tested at 'room temp' per manufacturing ES requirements

Date	Lot #/kt	Qty Impulse Tested	Qty Leak
25-Nov-91	4,000	10	-
25-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
15-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	5	-
31-Jan-92	4,000	10	-
2-Feb-92	1,450	5	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
25-Feb-92	4,000	10	-
25-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 013804

77PBL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
28-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Totals units</b>	<b>265,000</b>	<b>663</b>	<b>-</b>
---------------------	----------------	------------	----------

TI-NHTSA C13805



**Pechonis, John**

---

**From:** Proia, Stephen  
**Sent:** Tuesday, May 18, 1999 4:21 PM  
**To:** Beringhouse, Steven  
**Cc:** McGuirk, Andy; Pechonis, John; Dague, Bryan  
**Subject:** 77PBL2\_1.xls



Steve,

I've summarized the data per our discussion. I have also reviewed the files in marketing without success. Please let me know if you need anything else.

Regards,

Steve

TIP/N: 77PSL2-1  
 Ford P/N: FZVC-8F924-AB

Rate	Lot Size	Qty Impulse Tasted	Qty Pass	Qty Leak	Comments
26-Nov-91	4,000	10	10	-	
26-Nov-91	4,000	10	10	-	
3-Dec-91	4,000	10	10	-	
5-Dec-91	4,000	10	10	-	
9-Dec-91	4,000	10	10	-	
9-Dec-91	2,000	5	5	-	
11-Dec-91	4,000	10	10	-	
11-Dec-91	4,000	10	10	-	
13-Dec-91	4,000	10	10	-	
14-Dec-91	4,000	10	10	-	
16-Dec-91	4,000	10	10	-	
16-Dec-91	4,000	10	10	-	
2-Jan-92	4,000	10	10	-	
6-Jan-92	4,000	10	10	-	
7-Jan-92	2,000	5	5	-	
8-Jan-92	4,000	10	10	-	
8-Jan-92	4,000	10	10	-	
14-Jan-92	4,000	10	10	-	
14-Jan-92	4,000	10	10	-	
15-Jan-92	4,000	10	10	-	
28-Jan-92	2,000	5	5	-	
31-Jan-92	4,000	10	10	-	
2-Feb-92	1,650	5	4	-	Broken spring
4-Feb-92	4,000	10	10	-	
5-Feb-92	4,000	10	10	-	
6-Feb-92	4,000	10	10	-	
10-Feb-92	4,000	10	10	-	
11-Feb-92	4,000	10	10	-	
12-Feb-92	4,000	10	10	-	
12-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
14-Feb-92	4,000	10	10	-	
15-Feb-92	4,000	10	10	-	
24-Feb-92	4,000	10	10	-	
26-Feb-92	4,000	10	10	-	
26-Feb-92	4,000	10	10	-	
28-Feb-92	4,000	10	10	-	
28-Feb-92	4,000	10	10	-	

77PBL2-1: Impulse Data Results 11/91 - 12/92

Date: 12-May-99

TI P/N: 77PBL2-1

Ford P/N: F2VC-9F924-AB

Date	Lot Bin	Qty Impulse Trend	Qty Leak
26-Nov-91	4,000	10	.
26-Nov-91	4,000	10	.
5-Dec-91	4,000	10	.
5-Dec-91	4,000	10	.
9-Dec-91	4,000	10	.
9-Dec-91	2,000	5	.
11-Dec-91	4,000	10	.
11-Dec-91	4,000	10	.
13-Dec-91	4,000	10	.
14-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
16-Dec-91	4,000	10	.
2-Jan-92	4,000	10	.
6-Jan-92	4,000	10	.
7-Jan-92	2,000	5	.
8-Jan-92	4,000	10	.
8-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
14-Jan-92	4,000	10	.
15-Jan-92	4,000	10	.
28-Jan-92	2,000	5	.
31-Jan-92	4,000	10	.
2-Feb-92	1,600	5	.
4-Feb-92	4,000	10	.
5-Feb-92	4,000	10	.
6-Feb-92	4,000	10	.
10-Feb-92	4,000	10	.
11-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
12-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
14-Feb-92	4,000	10	.
15-Feb-92	4,000	10	.
24-Feb-92	4,000	10	.
25-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
26-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
28-Feb-92	4,000	10	.
6-Mar-92	4,000	10	.
10-Mar-92	4,000	10	.

TI-NHTSA 013808

77PBL2-1: Impulse Data Results 11/91 - 12/92

11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-
18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,800	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,800	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,800	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Total</b>	<b>268,600</b>	<b>648</b>	<b>-</b>
--------------	----------------	------------	----------

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
11-2/11-1	77PS L2-3	4:00 PM	5:00 AM	11-07-91 (stand?)
11-3	77PS L2-3	5:15 AM		11-8-91
11-4	77PS L2-2	11:00 AM		11-12-91
11-7/11-6	77PS-	3:30 PM	4:30 AM	11-19-91 11-20-91
11-5	77PS L2-3	5:00 AM		11-20-91
11-8/11-11	77PS L2-1	6:45 P.M.	8:10 AM	11-25-91 11-26-91
11-9/11-10	77PS L2-1	11:45 AM	10:30 PM	11-26-91 11-26-91

TN-NHTSA 019610

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
12-1/12-2	77P-21	6:00 AM	9:30 PM	12/5/91
12-3/12-4	77PS L2-1	9:30 PM	11:00 AM	12-5-91 12/6/91
12-6/12-8	77PS L2-1	8:10 AM	7:55 AM	12/7/91 12/9/91
12-5	77PS L2-1	8:00 AM		
12-10/12-11	77PS L2-1	6:00 PM	9:30 AM	12-11-91 12-11-91
12-7/12-9	77PS L2-1	8:00 AM		
12-12/12-13	77PS L2-1	5:30 PM	6:50 AM	12-12-91 12-13-91
12-14/12-15	77PS L2-1	8:30 AM		
12-16/12-17	77PS L2-1	10:05 PM		12-13-91
12-18/12-19	77PS L2-1	1:00 AM	1:10 PM	12-16-91 12-17-91
12-23	57PS-F3-5	4:50 PM		

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
1-1/1-7	77PSL2-1	10:25 PM	11:45 AM	1-1-92 1-2-92
1-1/1-2	77PSL2-1	4:30 PM	5:30 AM	1-2-92 1-3-92
1-5/1-6	77PSL2-1	" " PM	11:45 AM	1-5-92 1-6-92
1-3	77PSL2-1	2:30 PM	5:30 AM	1-6-92 1-9-92
1-7/1-8	77PSL2-1	11:17 PM	12:45 PM	1-7-92 1-8-92
1-9/1-10	77PSL2-1	12:50 PM	2:00 AM	1-8-92 1-9-92
11-20/11-21	77PS F3.3	6:00 PM	7:25 AM	1-9-92 1-10-92
1-11/1-12	77PSL2-1	10:30 A.M.	12:15 AM	1-14-92 1-15-92
1-15/1-16	77PSL2-1	8:40 AM	1:45 PM	1-15-92 1-16-92
1-17/1-18	77PSL2-1	2:00 PM	11:55 AM	1-15-92 1-20-92
1-14	77PSL2-1	11:50 A.M.	1:45 AM	1-20-92

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
1-22	L2-1	4:45 PM	1:15	1-20-92 1-31-92
1-23	L2-1	↓	7:15	1-31-92
1-21	L2-1	4:00 PM 9:25 AM	6:30 AM	2-1-92 2-4-92
1-24/1-25	L2-1	9:25 AM	10:45	2-4-92
1-26/1-27	L2-1	11:00 PM 1:15 PM	12:20 PM	2-5-92 2-5-92
1-28/1-29	L2-1			2-10-92
2-4/2-3	L2-1	12:00 PM	1:00 AM	2-11-92
2-5/2-6	L2-1	1:45 AM		2-11-92
2-9/2-10	L2-1	8:00 AM		2-12-92
2-7/2-8	L2-1	9:35		2-13-92
2-12/2-11	L2-1	6:15 PM	9:20 AM	2-14-92

TI-NHTBA 013813



# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
2-13/2-14	77PS	8:00 AM	9:30 PM	2-14-92
2-6/2-15	L2-2	10:00 PM		2-14-92
2-1/2-16	X2-3 / X2-1	4:25 AM		2-14-92
2-5/2-19	L2-3 / L2-1	6:45 PM	8:00 AM	2-17-92
2-5/2-4	L2-3	8:10 AM		2-18-92
2-6	X2-3	10:00 PM		2-18-92
			11:45 AM	2-21-92
			1:15 AM	2-22-92
2-20/2-21	L2-1	3:30 PM		2-22-92
1-20	X2-3	1:20 AM		2-24-92
2-24/2-27	77PS	2:40 PM	5:50 AM	2-25-92
2-24/2-25	77PS	3:00 PM		2-27-92
2-28/2-29	77PS L2-1	11:45 AM	11:10 PM	2-28-92

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
5-26/5-27	L3-1	5:30 PM	5:05 <sup>AM</sup>	5-27-92 5-28-92
3-24/3-25	L2-3	9:00 AM	11:00 <sup>PM</sup>	6-02-92 6-29-92
3-26/5-30	23-3 / 23-1	11:00 PM	12:05 PM	6-03-92
5-31	L3-1	4:45 PM		06-3-92
6-2 & 6-3	L2-3	11:30 AM	12:30 AM	06-04-92 6-5-92
6-4	L2-3	11:30 AM	12:30 AM	06-05-92 6-6-92
5-29/5-32	L3-1	9:50 AM	9:00 <sup>PM</sup>	06-09-92
6-6	L3-3	2:00 PM	3:00 <sup>PM</sup>	06-16-92
6-7/6-9	L3-3	6:15 PM	8:05 AM	6-17-92 06-18-92 06-19-92
6-10/6-9	L3-3	9:10 PM	10:00 AM	6-22-92 6-23-92
6-11/6-12	L2-3	9:00 AM		6-25-92

# 7PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
6-13 & 6-14	L3-3	9:00 AM	10:10 PM	6-29-92
6-15	L3-3	6:23 PM	11:14 AM	6-29-92
6-16	+ 5PS L3-3 ENG. SAMPLE	3:25 PM		6-30-92
		3:25 PM		6-30-92
7-3 / 7-2	L2-3	2:00 PM	approx 11:30 AM	7-08-92
7-4	L2-3	4:45 AM		7-9-92
				7-9-92
100 / 102	L3-1	8:45 AM		7-23-92
101 / 103	L2-3	10:30 PM	11:55 PM	7-23-92
103 / 104	L3-1	12:40 PM		7-24-92
105 / 101	L3-1	9:10 AM		7-27-92
109 / 111	L3-1	9:00 AM		7-28-92

TL-NHTSA 013918

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
112 / 113	L3-1	8:15 AM		7-29-92
114	L3-1	10:22 <sup>PM</sup>	1:50 PM	7-29-92 7-30-92
115 / 116	L3-1	2:00 PM	5:50 <sup>AM</sup>	8-04-92 8-5-92
117 / 118	L2-3 / L3-3	6:30 PM	8:00 AM	8-5-92 8-06-92
119 / 120	L3-1	5:45 PM	7:30 AM	8-07-92
121 / 122	L3-3 / L2-3	3:15 PM	5:00 <sup>AM</sup>	8-10-92 8-11-92
123 / 124	L2-3 /	5:30 PM	9:00 AM	8-11-92 8-12-92
126 / 130	L3-3 / L3-1	5:30 PM	7:00 AM	8-12-92
129	L3-1	7:00 AM		8-13-92
128 / 133	L3-3 / L3-1	2:25 PM		8-19-92
134	L3-1	5:00 <sup>AM</sup>		8-20-92

# 77PS

## IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
249	L2-3	7:15 PM	8:46 AM	10-26-92 10-27-92
250A / 251A	L3-3	3:30 PM	5:15 AM	10-27-92
253 / 254	L2-1	2:30 PM	3:45 AM	10-28-92
252 / 255	L2-1	3:50 AM		10-29-92
256 / 257	L3-3	8:00 PM	9:30 AM	10-29-92 10-30-92
258 / 259	L3-3	9:45 AM		
260	L2-3	10:00 PM	11:10 AM	11-1-92 11-27-92
262 / 261	L2-1	2:30 PM	3:48	11-4-92
263	L5-2	5:10 AM		11-5-92
265 / 266	L3-3	7:00 PM	8:05 AM	11-5-92
267 / 268	L3-3	7:00 PM	8:10 AM	11-05-92 11-06-92

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
243	X 3	10:00 PM	11:10 AM	11-27-92 11-27-92 11-30-92
297/298	L3.3	6:45 PM	8:25 AM	12-1-92
300	L3.3	9:00 PM	1:15 PM	12-2-92 12-01-92
303/302	L2.3 / L2.3	3:30 PM	4:15 AM	12-03-92 12-12-92
306 AA	L5-2	4:50 AM		12-03-92
305/306	L3.3	6:15 PM	7:40 AM	12-04-92 12-03-92
307	L2-1	8:00 AM	9:30 PM	12-04-92
308-309	L2.3	10:00 PM	10:55 AM	12-05-92
310	L2-1	10:55 AM	12:30 AM	12-08-92 12-9-92
312/316	77PS L3.3	10:15 AM	11:35 AM	12-7-92 12-11-92
317/318	L3.3 / L2-1	2:35 PM		12-11-92

# 77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
325/319	X3-3 / X2-1	10:15 PM	11:40 AM	12-15-92
321/322	L2-1	11:50 AM	approx 1:00 PM	12-16-92
323/331	X2-1 / X2-3	1:00 AM	2:50 PM	12-17-92
320/324	L2-1	3:00 PM	approx 4:15 AM	12-17-92
326A/327A	L3-3	5:15 AM	7:00 PM	12-18-92
332/333	L3-3	7:30 P.M.	3:50 AM	12-19-92
334/335	L2-3 / L2-1	11:00 AM	12:30 AM	12-19-92
336/337	L2-1	10:15 PM	11:45 AM	12-20-92
296AA	L5-2	6:00 PM	7:20 AM	12-21-92
3-30	L3-3	7:40 AM	11:30 AM	12-22-92
338A/349A	L3-3	10:15 PM	11:30 AM	1-3-93
				1-4-93

## 77 PS Heater Coil Tests

### Abstract


The purpose of this test was to investigate the possibility of switch ignition caused by excessive heat dissipation in the contact cavity of 77PS switches. The intention was to determine the conditions necessary to nucleate a switch ignition. A heater coil was installed in the contact cavity of (3) 77PS switches. The contact cavity of (1) switch was filled with a solution of brake fluid with 6 wt. % water, the contact cavities of the other (2) switches remained dry. Power was applied to each heater coil until the switch base began to melt. A spark was then generated inside the contact cavity of the switch. All (3) switches ignited during the test. In each ignition, contact cavity temperature exceeded 600°F when 5 Watts of power (approximate) was dissipated in the heater coil.

### Procedure

#### Sample Preparation

(3) 77PSL2-1 switches were prepared for testing, as follows. (Refer to Figure 1 below).

Figure 1.  
77PS test switch cross-section



TI-NM78A 013821



The electrical contact arm was removed from the switch base assembly. The rivet, holding the contact arm to the movable terminal, was ground off. A small hole was drilled through the stationary contact. A resistive wire coil was placed in the switch contact cavity, where the contact arm normally resides. The ends of the coil were crimped to the stationary and movable terminals.

A small hole was drilled through the side of the switch base (to accommodate a thermocouple). To facilitate use of an high voltage ignition source, an additional hole was drilled through the base at a 45° angle.

The modified base assembly was crimped into final assembly.

Wet device: Brake fluid with 6 wt. % water was injected into the contact cavity of only (1) of the (3) test switches.

A K-type thermocouple was inserted into the contact cavity through the previously drilled hole.

#### Test Setup

Each of the (3) switches was tested separately.

Each test switch was mounted in a manifold which was electrically connected to ground. A .042 Torrington pin was inserted into the base of the switch leaving a gap of 0.030 inches (approximate) between the end of the pin and the cup of the switch. The pin was connected to the hot lead of a Hy-Pot tester without power. (When the Hy-Pot tester is powered, arcing occurs between the pin at 2500 Volt potential and the grounded cup of the switch). The Hy-Pot tester electric circuit is shown in Figure 1, above.

A variable output DC power supply was connected to the heating coil, through the switch mating connector leads.

The thermocouple was connected to a Fluke meter.

#### Test Procedure

Power was slowly applied to the heater coil in the switch. Voltage, current and temperature were recorded at regular intervals. Heater coil power was slowly increased during the test.

When localized base melting occurred, the Hy\_Pot tester was powered to create a spark in the contact cavity of the switch.

Proprietary Information: Attorney-Client Privilege Invoked  
 PS/9908 Rev. A  
 3/18/99  
 Date

The data obtained on test switch 1 is shown in Table 1, below.

Table 1.

Test Switch 1- Wet Device (readings made at (1) minute intervals (approximate))

Heater Voltage (Volts)	Heater Current (Amps)	Heater Power (Watts)	Internal Temperature (°F)	Notes
.27	1.0	0.3	100	
.50	2.0	1.0	176	
.80	2.8	2.3	220	Gas visible. Hissing sound audible.
.90	3.0	2.7	248	Smoke visible. Gases venting from side of base.
.96	3.2	3.1	349	
1.8	2.0	3.2	300	
.97	3.1	3.0	340	
1.1	3.6	4.0	480	
1.2	3.6	4.6	482	
1.1	3.8	4.2	488	
1.3	4.0	5.2	531	
1.1	3.6	4.0	571	
1.4	4.1	5.7	647	
1.4	4.0	5.6	680	Large hole developed in base. Power shut down. Internal spark deliberately generated. Ignition covered.

The data obtained on test switch 2 is shown in Table 2, below.

Table 2.

Test Switch 2- Dry Device (readings made at (1) minute intervals (approximate))

Heater Voltage (Volts)	Heater Current (Amps)	Heater Power (Watts)	Internal Temperature (°F)	Notes
1.0	3.1	3.1	501	
1.09	3.0	3.3	743	
-	-	-	-	Connection failed. Test interrupted.
1.06	3.02	3.2	598	
1.09	3.09	3.3	620	Smoke became visible from terminal area.
1.12	3.18	3.6	680	
1.13	3.08	3.5	681	
1.13	3.28	3.7	692	A small burn through area in the base. Smoke began venting from burn through area.
1.13	3.18	3.6	707	
1.13	3.38	3.8	722	
1.20	3.52	4.2	766	
1.34	3.98	5.4	808	Base flopped over.
1.38	4.00	5.4	875	
-	-	-	1230	Base flopped over. Internal spark deliberately generated. Ignition covered.

Data obtained on test switch 3 is shown in Table 3, below.

Table 3.

Test Switch 3- Dry Device (readings made at (28) second intervals (approximate))

Heater Voltage (Volts)	Heater Current (Amper)	Heater Power (Watts)	Internal Temperature (°F)	Notes
1.0	3.8	3.8	300	Sparks emitted from terminal area.
1.2	4.0	4.8	350	
1.2	3.8	4.6	423	Gases vented from the side of switch base.
1.3	3.7	4.8	480	
1.3	3.7	4.8	500	
1.3	3.7	4.8	525	
1.3	3.7	4.8	597	
			1435	Base flopped over. Internal spark deliberately generated. Ignition occurred. The heater burned out and the fire was extinguished.

#### Results and Discussion

This was not a very controlled experiment due to difficulties in modifying the base assembly to accommodate a heater coil. Several unsuccessful attempts were made to install a heater coil prior to arrival at the aforementioned procedure. In this test, as the temperature of the heater coil increased, the coil tended to droop and make contact with the base of the switch. At the point of contact, localized base melting occurred and a hole breached the base. The spark, generated with the Hy-Pot tester, ignited the fumes within the contact cavity which then engulfed the base material of the switch.

From the data of Table 1 through 3, above, ignition occurred under the following conditions:

- 5 Watts of power dissipated in the heater coil.
- Contact cavity temperature exceeded 600°F.
- Hole breached in switch base.
- Spark generated in contact cavity of the switch.

Brake fluid did not appear to contribute to the ignition process and did not ignite in this test.

#### Conclusions

5 Watts of power dissipated into the contact cavity of 7TPS switches is sufficient to cause the switch base to outgas and melt. The heated vapor byproducts (fumes) of the base material melting, have proven to be combustible. When a spark is generated in the contact cavity of melting switches, where fumes have accumulated, the fumes ignite and engulf the switch. A solution of brake fluid with 6 wt. % water, in the contact cavity of (1) switch, did not contribute to the ignition process.

**Currey, Pat**

---

**From:** McGuirk, Andy [a-mcguirk@emall.msa.ti.com]  
**Sent:** Wednesday, May 19, 1999 11:46 AM  
**To:** Sharpe, Robert  
**Cc:** Baumann, Russ  
**Subject:** my first draft 77PSL2\_1.xls



77PSL2\_1.xls

**AUTOMOTIVE SENSORS AND CONTROLS QA MANAGER**  
34 FOREST ST W/S 23-05  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 604-2044

<<77PSL2\_1.xls>>

Regards,

andy

TI-NHTSA 013825

TI PN: 77PSL2-1  
 Ford P/N: F2VC-8F824-AB

Date	Lot Size	Qty Inspected	Qty Pass	Qty Leak	Comments
26-Nov-91	4,000	10	10	.	
26-Nov-91	4,000	10	10	.	
5-Dec-91	4,000	10	10	.	
5-Dec-91	4,000	10	10	.	
5-Dec-91	4,000	10	10	.	
9-Dec-91	2,000	3	3	.	
11-Dec-91	4,000	10	10	.	
11-Dec-91	4,000	10	10	.	
13-Dec-91	4,000	10	10	.	
14-Dec-91	4,000	10	10	.	
16-Dec-91	4,000	10	10	.	
18-Dec-91	4,000	10	10	.	
2-Jan-92	4,000	10	10	.	
4-Jan-92	4,000	10	10	.	
7-Jan-92	2,000	3	3	.	
8-Jan-92	4,000	10	10	.	
8-Jan-92	4,000	10	10	.	
14-Jan-92	4,000	10	10	.	
14-Jan-92	4,000	10	10	.	
15-Jan-92	4,000	10	10	.	
28-Jan-92	2,000	3	3	.	
31-Jan-92	4,000	10	10	.	
2-Feb-92	1,650	5	4	.	Broken spring
4-Feb-92	4,000	10	10	.	
5-Feb-92	4,000	10	10	.	
6-Feb-92	4,000	10	10	.	
10-Feb-92	4,000	10	10	.	
11-Feb-92	4,000	10	10	.	
12-Feb-92	4,000	10	10	.	
12-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
14-Feb-92	4,000	10	10	.	
15-Feb-92	4,000	10	10	.	
24-Feb-92	4,000	10	10	.	
26-Feb-92	4,000	10	10	.	
26-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	10	.	
28-Feb-92	4,000	10	9	.	Continuity failure, terminal inside of base is not staked. Date code 2137. Sorted lot 100%.
6-Mar-92	4,000	10	10	.	

TI-NHTSA 013826

10-Mar-92	4,000	10	10	-
11-Mar-92	4,000	10	10	-
12-Mar-92	4,000	10	10	-
18-Mar-92	4,000	10	10	-
23-Apr-92	2,000	5	5	-
2-May-92	2,000	5	5	-
5-May-92	2,000	5	5	-
6-May-92	2,000	5	5	-
14-Sep-92	2,000	5	5	-
22-Sep-92	4,000	10	10	-
30-Sep-92	4,000	10	10	-
7-Oct-92	4,000	10	10	-
7-Oct-92	4,000	10	10	-
16-Oct-92	4,000	10	10	-
21-Oct-92	2,000	5	5	-
29-Oct-92	4,000	10	10	-
29-Oct-92	4,000	10	10	-
29-Oct-92	4,000	10	10	-
30-Oct-92	4,000	10	10	-
4-Nov-92	4,000	10	10	-
10-Nov-92	4,000	10	10	-
10-Nov-92	4,000	10	10	-
11-Nov-92	4,000	10	10	-
17-Nov-92	2,000	5	5	-
20-Nov-92	4,000	10	10	-
4-Dec-92	2,000	5	5	-
9-Dec-92	2,000	5	5	-
14-Dec-92	2,000	5	5	-
16-Dec-92	4,000	10	10	-
16-Dec-92	4,000	10	10	-
16-Dec-92	4,000	10	10	-
21-Dec-92	2,000	5	5	-
21-Dec-92	4,000	10	10	-

<b>Totals</b>	<b>268,690</b>	<b>648</b>	<b>643</b>	<b>-</b>
---------------	----------------	------------	------------	----------

TI-NHTSA 013827

**Curry, Pat**

---

**From:** McGuirk, Andy [a-mcguirk@mail.mc.ti.com]  
**Sent:** Wednesday, May 19, 1999 11:55 AM  
**To:** Sharpe, Robert  
**Cc:** Beringhaus, Steven  
**Subject:** FW: my second draft 77PSL2\_1.xls



77PSL2\_1.xls

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST N/S 21-05  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 504-2044

-----  
**From:** McGuirk, Andy  
**Sent:** Wednesday, May 19, 1999 12:45 PM  
**To:** Sharpe, Robert  
**Cc:** Bauradin, Russ  
**Subject:** my first draft 77PSL2\_1.xls

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST N/S 23-C5  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 504-2044

<<77PSL2\_1.xls>>

Regards,

andy

TI-NHTSA 013826

## 77PBL2-1: Impulse Data Results 11/91 - 12/92

Date: 19-May-99  
 TI record search findings of May 14-17 '99  
 TI P/N: 77PBL2-1  
 Ford P/N: FZVC-9F924-AB  
 Tested at 'room temp' per manufacturing ES requirements

Date	Lot Size	Impulse Tested	Qty Leak
26-Nov-91	4,000	10	-
26-Nov-91	4,000	10	-
5-Dec-91	4,000	10	-
5-Dec-91	4,000	10	-
9-Dec-91	4,000	10	-
9-Dec-91	2,000	5	-
11-Dec-91	4,000	10	-
11-Dec-91	4,000	10	-
13-Dec-91	4,000	10	-
14-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
16-Dec-91	4,000	10	-
2-Jan-92	4,000	10	-
6-Jan-92	4,000	10	-
7-Jan-92	2,000	5	-
8-Jan-92	4,000	10	-
8-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
14-Jan-92	4,000	10	-
15-Jan-92	4,000	10	-
28-Jan-92	2,000	3	-
31-Jan-92	4,000	10	-
2-Feb-92	1,650	3	-
4-Feb-92	4,000	10	-
5-Feb-92	4,000	10	-
6-Feb-92	4,000	10	-
10-Feb-92	4,000	10	-
11-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
12-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
14-Feb-92	4,000	10	-
15-Feb-92	4,000	10	-
24-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
26-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
28-Feb-92	4,000	10	-
6-Mar-92	4,000	10	-
10-Mar-92	4,000	10	-
11-Mar-92	4,000	10	-
12-Mar-92	4,000	10	-

TI-NHTSA 013820



77PBL2-1: Impulse Data Results 11/91 - 12/92

18-Mar-92	4,000	10	-
23-Apr-92	2,000	5	-
2-May-92	2,000	5	-
5-May-92	2,000	5	-
6-May-92	2,000	5	-
14-Sep-92	2,000	5	-
22-Sep-92	4,000	10	-
30-Sep-92	4,000	10	-
7-Oct-92	4,000	10	-
7-Oct-92	4,000	10	-
16-Oct-92	4,000	10	-
21-Oct-92	2,000	5	-
20-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
29-Oct-92	4,000	10	-
30-Oct-92	4,000	10	-
4-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
10-Nov-92	4,000	10	-
11-Nov-92	4,000	10	-
17-Nov-92	2,000	5	-
20-Nov-92	4,000	10	-
4-Dec-92	2,000	5	-
9-Dec-92	2,000	5	-
14-Dec-92	2,000	5	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
16-Dec-92	4,000	10	-
21-Dec-92	2,000	5	-
21-Dec-92	4,000	10	-

<b>Total mths</b>	<b>249,488</b>	<b>448</b>	<b>-</b>
-------------------	----------------	------------	----------

TI-NHTSA 013830

5/26/99  
B. Lyner

# Procedure

I Visual Inspection

II Signs of Connector Leak      yes    no

III Leak Check?      pass/Fail

IV Current Draw (Terminal to Header) (#)

V Open Crimp Rings

VI Connector Leak?      yes    no

VII Environmental Seal Leak      pass/Fail

VIII Open Cup Crimp

IX Krypton Inspection  
- Full bag  
- moisture

X Krypton Leak Check?      0, 0.1, 2, 3 Percent?



XI Gasket Inspection	yes	no
	- pressure	
- nitrogen		
- compression seal		

XII Package + Store



Objective:

- 1) Is/are PS defective?
- 2) Leak → i → % Fire → How does PS Leak?
- 3) How does PS wear?



5/25/99

B. Dwyer

# Results

- \* L ?  
- corrosion
- \* Connector Leak ?
- \* Environmental Seal ?
- \* Kipton Leak ?
- \* Kipton Breakdown/Condition <sup>Kipton</sup> Leak <sup>check?</sup> 1, 2, or 3?



## Possible Leak Paths

- Connector
  - Down Band - 2
  - Insulation/Seal - 2
  - Seal/corruption - 1
  - Seal/switch - 1
- Environmental Body Seal -
- Process cavity
  - gasket
  - Kiptons

Brake Pressure Switch Test Log, Updated 6/28/09

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Vary water concentrations in 'new' Brake Fluid 14Vdc to one terminal, heeport grounded Water Conc: 4%, 6%, 10%, 75%	250+ hours, Current draw in line 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	'new' Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, heeport grounded	260+ hours, Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heeport Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heeport Grounded, Ambient at 700 C	18 hours into test max current 6mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 60 Amps through Switch Terminals	Temperature rose to approx. 270 F. No sparks. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat 50 tubes, include sparking. (1) ml solution of Brake Fluid and 8 wt. % H <sub>2</sub> O	5 tested. Sparks observed, ignition observed on part subvector See attachment Test complete Brake fluid in cavity steam down heat build-up Sparks observed at 675 F, base metal and tube off at 800 F
	6a	TI	Create heater by co-welding spring with ball water solution, 14V between spring and heeport	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or megohms It took about 100 hours to reach the 5 ohm stage. The 5 ohm device failed under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through heeport. See plots and video.
	6c	TI	Pass 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

71-NHTSA 013834

Brake Pressure Switch Test Log, Updated 5/28/89

Topic	Phase	Location	Description	Notes
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psi pressure pulses at 135C per ES	conductivity First leak observed at 725,000 cycles. Test Completed. See attached Wetbulb Chart.
Diaphragm Wear	8	TI	0-1400 psi pressure pulses at 135C.	Parts withdrawn every 250k cycles, characterized for wear
Field vs Lab Correlation	9	Central Labs	Field returns, from dealer lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors	10	TI	Vary water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0 % water in BF 12 snap + 12 quiet switches w/ 5 % water in BF	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 800k cycles to assess leakage anomalies.
Effecting Diaphragm Wear Replicate test				
On-Vehicle Characterization of Pressure & Temperature Profile in Your Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT...see Ford charts...>800k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. UMC: Cu=418 (ppm), Fe=5.8 (ppm), Cr=0.08 (ppm), 1.1 %H2O. UCA: Cu=282 (ppm), Fe=5.8 (ppm), Cr=1.9 (ppm), 1.1 %H2O. NEW: Cu=<0.01 (ppm), Fe=0.02 (ppm), Cr=<0.01 (ppm), 0.3 %H2O.
Spark Plug Study	12	Central Labs	Determine if arcing occurs in switch using clutch leads and high speed video. Use dry switches as well as switches with various brake fluid water levels.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches returned from field	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Ignition Tests	13a	TI	Repeat ignition structure with different fluids. 0.5 hour tests: 5% NaCl in tap water rain water 0.01 hour tests: tap water	Test complete. 5% NaCl samples resulted in no ignition. All brake fluid samples drew less than 3 mA/amp. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mA/amps and showed some degree of corrosion.

TI-NHTSA 013935

Brake Pressure Switch Test Log, Updated 02/20/99

			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Vary water concentrations in 'new' Brake Fluid 10 amp + 20 quiet switches w/ 0 % water in BF 10 amp + 20 quiet switches w/ 5 % water in BF	Test suspended. Analysis in process to assess test findings.
Compatibility of Kapton with Oxalic Acid	14	Dupont	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects but water has on Kapton provides.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and availability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl tested 245 and 246 trials ZYTEL samples tested 145 trials
Long duration brake fluid storage test.	15a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test suspended (500) hours completed. Used brake fluid current dropped off to <1/100 mA/amp. New BF transport current can increase w/ time under coast, power.
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. switched switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 13a in Ford relay circuit for (48) hrs. Relay switch to impending ignition in (18) Amp circuit then place in relay circuit for (24) hrs. Apply max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or more ionized ignition in this fluor element was seen in the track.
Long duration brake fluid storage test number 2.	17	TI	(10) samples filled with new brake fluid (1) hour of vibration per day (1) hour soak at 100 deg C per day	Test suspended. (312) hours completed. Average transport current is 1.8 mA/amp (standard deviation = 1.8 mA/amp)

TI-NHTSA 013836

## TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can be created in the laboratory.

- Test 1

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating.  
(No electrical load across switch terminals).  
Switch housing electrically grounded.

**Results:**

- (8) samples were tested total:
- (2) with 4% H<sub>2</sub>O in brake fluid.
- (2) with 6% H<sub>2</sub>O in brake fluid.
- (2) with 10% H<sub>2</sub>O in brake fluid.
- (2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013937



• Test 2

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.  
14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor which is tied to ground. (1 Amp load across switch terminals).  
Switch hexport electrically grounded.

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A (1) Amp load through switch terminals did not ignite brake fluid in the contact cavity of switches.

• Test 6

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.  
Power applied to the heater element until plastic base melts.  
Spark generated in contact cavity of switch.  
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

**Wet device:** The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Dry device:** The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.  
5 watts of power dissipated in heating element.  
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 013838

**Level 2: Objective:** Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• Test 6a

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5  $\Omega$ . A solution of 5 wt. % NaCl in H<sub>2</sub>O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H<sub>2</sub>O is injected into contact cavity of a switch.  
Continuous 14 Volt power applied to the switch.  
Hexport is grounded.  
Current is limited at 15 Amps.

• Test 6c

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• Test 7

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

TI-NHTSA 013839

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

**Objective:** Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

**Results:** Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

**Conclusion:** Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm and an increase in hexport current.

• **Test 17**

**Objective:** Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.  
Switches at continuous 14 Volts power.  
Switches subjected to vibration for (1) hour per day.  
Switches subjected to 100°C for (1) hour per day.

**Results:** Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. These results are consistent with results previously found in Test 15a at the 300 hour point.

TI-NHTSA 013840

**Conclusion:** New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

**Level 3: Objective:** Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

- Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H<sub>2</sub>O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.

- Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H<sub>2</sub>O

The switch filled with 5 wt. % NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps export current draw and showed no signs of corrosion over the (24) hour test.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition within a 3 hour lab test. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O can cause an ignition in a 3 hour lab test exposure..

• **Test 15**

**Objective:** Compare the ignition characteristics of various plastics as switch base material.

**Results:** When 5 wt. % NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

• **Test 15b**

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

**Conclusion:** Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

**Level 5 Objective:**

**Test 16**

• **Objective:** Test proposed relay circuit.

**Results:** (1) switch was injected with a solution of 5 wt. % NaCl in H<sub>2</sub>O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

**Conclusion:** 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition.

TI-NHTSA 013843

## 77PS Fluid Ignition Test

### Abstract


The purpose of this test was to investigate brake fluid ingress as a possible source of ignition in 77Ps switches in continuous power applications. The contact cavities of (10) normally closed switches were filled with solutions of brake fluid and various concentrations of water. The switches were torqued into a common test manifold, which was electrically grounded. Continuous, (14) volt power was applied to one terminal of all switches. (This condition allowed the fluid, in the contact cavity to become the conductive path to the electrically grounded hexport body of the switch). On (2) switches, 1 Amp of current was conducted through the switch contacts. No current was conducted through the terminals of (B) of the switches. No significant increase in temperature was observed on all switches. Visual analysis of the switch internal components showed a buildup of sooty deposits but no corrosion. This test provided no evidence that brake fluid ingress into the contact cavity of 77PS switches can cause an ignition.

### Procedure

#### Sample preparation:

A small hole was drilled through the base of (10) 77PS switches (as shown in Figure 1, below).

Figure 1.



(5) solutions of a brake fluid, with different concentrations of tap water, were injected into the contact cavity of the switches as outlined in Table 1, below.

Table 1.

Test Device #	1A	1B	2A*	2B	3A	3B	4A	4B	5A*	5B
% tap water in brake fluid (by weight)	0	0	4	4	6	6	10	10	75	75

\* 1 Amp conducted through the switch terminals of (2) samples.

A K-type thermocouple was placed into the fluid of (5) of the switches, to monitor fluid temperature.

#### Test Setup:

The switches were all torqued into a manifold which was electrically grounded.

14 Volts was applied to the one terminal of all switches. A 12  $\Omega$  resistor was wired from the second terminal to ground on devices 2A and 5A only. (This was done to create an electric path through the switch contact as a source of heat in those (2) devices). The second terminals, of the remaining switches, were left electrically floating. To facilitate continuous testing, switches were placed in an oven and powered over several days. The oven was used only as a safety precaution for unattended testing.

#### Test Procedure:

A temperature data logger was used to record the peak fluid temperature of the switches over (24) hour intervals. Ambient and oven temperatures were recorded daily. Fluid levels were monitored and replenished as required. The hexport current draw of switch 5B was also recorded.

At the completion of this test, switch 3A was exposed to a salt water solution and powered at 14 volts for an additional 60 hours (approximate). (This was an effort to quantify salt water corrosion).

All the switches were disassembled for post testing analysis.

#### Data

The temperature data, collected during testing, is shown in Table 3, below. The Running Temperature is the switch fluid temperature at the time of measurement. The Peak Temperature is the peak temperature recorded, via data logger, over a (24) hour period.



Table 3.

Date: Time: Ambient Temp. (°F): Oven Temp. (°F):	Temperature	Device #				
		1A	2A	3A	4A	5A
2/11/99 14:40 84 86	(°F) Running	86	85	89	84	83
	((°F) Peak)	(87)	(95)	(86)	(83)	(98)
2/12/99 11:05 79 83	(°F) Running	98	94	89	99	100
	((°F) Peak)	(112)	(99)	(93)	(104)	(106)
2/13/99 9:30 NA NA	(°F) Running	87	96	107	88	103
	((°F) Peak)	(88)	(101)	(111)	(91)	(108)
2/16/99 13:30 81 81	(°F) Running	83	81	105	82	96
	((°F) Peak)	(99)	(103)	(121)	(97)	(117)
2/16/99 12:00 78 78	(°F) Running	76	84	109	84	81
	((°F) Peak)	(79)	(100)	(120)	(90)	(119)

Note: Running temperature is the temperature at the time of reading.  
 Peak temperature is the peak temperature recorded between readings.

Photos, of the dissected switches, are shown in Figure 2 and Figure 3 of the Appendix.  
 (Note: the test switch identifying marks were lost when the switches were disassembled.  
 Therefore, photos can not be tied to particular switches).

Hexport current measurements, on switch 5B, fluctuated daily and dropped from 5 mAmps at the start of the test to 0.2 mAmps at the end of the test.

### Results

Temperature measurements show that brake fluid ingress into the connector cavity of 77PS did not cause an ignition when powered at continuous, 14 Volts power. The peak temperature recorded during the test was 121°F, which is well below the flash temperature of brake fluid. Switches 2A and 5A, which had (1) Amp of current conducted through the switch contact, showed no additional increase in temperature when compared with the other switches. This may be attributed to a very low contact resistance resulting in insignificant additional power dissipation in switches 2A and 5A. Visual analysis all switches showed a buildup of black deposits but no corrosion.

At completion of the brake fluid test, switch 3A was injected with salt water and continuously powered with (14) volts for (60) hours. The switch was disassembled for post test analysis. An internal photo of switch 3A shows a high level of corrosion of internal components where the contact arm is completely corroded away (see Figure 3 of the Appendix).

### Conclusions

This test has provided no evidence to indicate brake fluid ingress as a possible source of ignition of 77PS switches in continuous power applications. (120) hours of testing showed no significant increase in temperature and no visible corrosion of internal components. Results showed that varying the concentration of water in the brake fluid between 0% to 75% did not affect temperature measurements or corrosion during the (120) hours of testing. Internal analysis of the switches showed varying amounts of deposits. However, due to a loss of identifying marks, no conclusions can be made with regard to deposits versus %water.

(1) switch, subjected to salt water ingress, for (60) additional hours of testing, showed a high degree of corrosion.

Appendix

Figure 2.



## Appendix

Figure 3.



Salt water corrosion of switch 3A.