

EA02-025

TEXAS INSTRUMENTS, INC.'S

9/10/03


REQUEST NO. 7

BOX 9

PART A - R


PART H

**DRAWINGS AVAILABLE UPON
REQUEST**



77-3

TI-NHT8A 014051



Hydraulic Power Unit

SAFETY VALVE - 100 PSI (5.0 MPa)

FORCE OF DISC

WASHER

SPRING

DISC

WASHER

FORCE OF DISC - 100 PSI (5.0 MPa)

EFFECTIVE AREA OF DISC - 0.7854 x (D² - d²) x 0.07854 x (D² - d²) x 0.07854 x (D² - d²)
AND THE AREA OF THE SPRING - 0.7854 x (D² - d²) x 0.07854 x (D² - d²) x 0.07854 x (D² - d²)

TI-NHTSA 014082

TI-NHTSA 014003







Hydraulic Pressure Switches Design Overview

PRESSURE SWITCH LOGIC

NORMALLY CLOSED



NORMALLY OPEN




TI-NHT8A 014064




Hydraulic Pressure Switches Design Overview

USING DISC MOTION TO MAKE / BREAK CONTACTS

BEFORE SNAP



AFTER SNAP




TI-NHTBA 014068

23 Jun 99 8:13 0300357 HPSdesign.ppt




Hydraulic Pressure Switches Design Overview


PRESSURE SWITCH ASSEMBLIES



**L - SHAPED SPRING
NORMALLY CLOSED**



**S - SHAPED SPRING
NORMALLY CLOSED**



**S - SHAPED SPRING
NORMALLY OPEN**

TI-NHTSA 014068



SNAP SENSOR CHARACTERISTIC CURVES

Hydraulic Pressure Switches
Design Considerations

QUIET VS SNAP SENSORS




TI-NHTSA 014087

15 Jul 99 ED 650637 ERM




Hydraulic Pressure Switches Design Overview



TI-NHTSA 014088

Hydraulic Pressure Switches Design Overview




TL-NHTBA 014089

Overview

- The CCPS is a redundant safety device designed for use in a vacuum-less electronic cruise control system.
- Functionally, it replaces the present vacuum damp valve by de-energizing a clutch which connects the throttle to an electronic actuator.
- It is plumbed into the brake line. When the driver applies pressure to the brake pedal, the normally-closed switch opens, disconnecting the actuator from the throttle butterfly.

Specifications:


Actuation:	125 PSI +/- 35 250 PSI +/- 50
Release:	20 PSI min 40 PSI min
Burst:	7000 PSI
Proof:	3000 PSI 4000 PSI
Cycles:	500K, 0 - 1450 PSI, 2 Hz
Voltage:	Battery
Current:	0.75 AMP Inductive





Automotive Sensors & Controls Cruise Control Pressure Switch


1991 Next Generation Speed Control System



TI-NHTSA 014081




Lab Experiment-5% NaCl/H₂O and Continuous Power



- **Contact arm (Cu) corrodes - chemical analysis shows presence of Na, Cl, Cu, and O on the cup surface**




**Lab Experiment- "New" Brake Fluid and
Continuous Power (300 hours)**



- **Contact arm (Cu) corrodes - chemical analysis shows presence of Cu, C, and O on the cup surface.**



**Lab Experiment "New" Brake Fluid and
Continuous Power (550 hours)**



- **Contact arm (Cu) corrodes - chemical analysis shows presence of Cu, C, and O on the cup surface.**



Memphis Switch Analysis



- **Chemical analysis reveals K, S, Cu, C, and O.**

TI-NHT&A 014086

TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

Level 1 Objective: Determine if a switch ignition can be created in the laboratory.

- Test 1

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H₂O.
14 volts applied to one terminal, second terminal electrically floating.
(No electrical load across switch terminals).
Switch housing electrically grounded.

Results:

- (8) samples were tested total:
- (2) with 4% H₂O in brake fluid.
- (2) with 6% H₂O in brake fluid.
- (2) with 10% H₂O in brake fluid.
- (2) with 75% H₂O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 014085

• **Test 2**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.
14 volts applied to one terminal, second terminal connected to a 14 Ω resistor which is tied to ground. (1 Amp load across switch terminals).
Switch hexport electrically grounded.

Results: (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

Conclusion: A (1) Amp load through switch terminals did not ignite brake fluid in the contact cavity of switches.

• **Test 6**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.
Power applied to the heater element until plastic base melts.
Spark generated in contact cavity of switch.
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

Results: (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Conclusion: A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.
5 watts of power dissipated in heating element.
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 014067

Level 2: Objective: Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• **Test 6a**

Objective: Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

Results: (1) out of (15) samples tested increased resistance to 5 Ω s. A solution of 5 wt. % NaCl in H₂O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H₂O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

Conclusion: A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H₂O is injected into contact cavity of a switch.
Continuous 14 Volt power applied to the switch.
Hexport is grounded.
Current is limited at 15 Amps.

• **Test 6c**

Objective: Determine if brake fluid with metal shavings is conductive enough to create an ignition.

Results: (3) devices with various size metal particles were tested. No significant current increase detected.

Conclusion: Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• **Test 7**

Objective: Determine if switch meets cycle life specification.

Results: Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

TI-NHTSA 014068

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

Conclusions: Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• Test 15a

Objective: Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

Results: Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid draw very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

Conclusion: Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm and an increase in hexport current.

• Test 17

Objective: Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

- Contact cavity of switch flooded with new brake fluid.
- Switches at continuous 14 Volts power.
- Switches subjected to vibration for (1) hour per day.
- Switches subjected to 100°C for (1) hour per day.

Results: Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. These results are consistent with results previously found in Test 15a at the 300 hour point.

TI-NHTSA 014069

Conclusion: New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

Level 3: Objective: Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H₂O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

Conclusion: A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H₂O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

Level 4: Objective: Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

Objective: Compare various fluids in the established ignition method.

Results: The following fluids were tested.

- (1) NaCl in H₂O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H₂O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H₂O

The switch filled with 5 wt. % NaCl in H₂O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

Conclusion: Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition within a 3 hour lab test. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H₂O can cause an ignition in a 3 hour lab test exposure.

• Test 15

Objective: Compare the ignition characteristics of various plastics as switch base material.

Results: When 5 wt. % NaCl in H₂O was injected into switches with different base materials, the following results were obtained: Callanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusions: All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

Objective: Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

Results: Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

Level 5 Objective:

Test 16

• Objective: Test proposed relay circuit.

Results: (1) switch was injected with a solution of 5 wt. % NaCl in H₂O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition.

TI-NHTSA 014072

Brake Pressure Switch Test Log, Updated 6/20/00

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in 'new' Brake Fluid 14Vdc to one terminal, heaport grounded Water Conc: 4%, 6%, 10%, 70%	250+ hours, Current draw in the 4.5mA to 6mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, heaport grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heaport Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heaport Grounded, Ambient at 100 C	10 hours into test max current 6mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 30 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps Through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Boiled heater elements into Switch. Heat oil failure, include sparking. (1) w/ solution of Brake Fluid and 6 wt. % H ₂ O	3 tested. Smoke observed, ignition observed on post witness See attachment Test complete Brake fluid is easily slows down heat build-up Smoke observed at 675 F, Base melts and falls off at 800 F
	6a	TI	Crane heater by corroding spring wire Salt water solution, 14V between spring and heaport	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or magnifera It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through heaport. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include lap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TI-NHTSA 014073

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@small.mot.com]
Sent: Tuesday, June 29, 1999 3:55 PM
To: Epstein, Sally
Subject: FW: Ford foil



AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST N/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: McGuirk, Andy
Sent: Tuesday, June 01, 1999 12:49 PM
To: Heringhaus, Steven; Paola, Stephen
Subject: FW: Ford foil

Maybe for your use ?

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER
34 FOREST ST N/S 23-05
ATTLEBORO, MA 02703
TEL : (508) 236-3080
FAX : (508) 236-3745
MOBILE: (508) 208-6119
PAGE: (800) 467-3700 PIN 604-2044

From: Wellman, Stacey
Sent: Thursday, May 20, 1999 11:27 AM
To: Warner, Pam
Cc: Sharpe, Robert; McGuirk, Andy
Subject: Ford foil

At the request of Andy McGuirk, I am sending the following attachment to you:

<<Andy.ppt>>

Regards,
Stacey

TI-NHTSA 014074



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids



AGENDA

- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **OVERVIEW TIME LINE**
- **SYSTEM OVERVIEW**
 - **SWITCH AND CONNECTOR**
- **IS / IS NOT TABLE**
- **CAUSE AND EFFECT DIAGRAMS**
- **THEORIES**
 - **BRAKE FLUID IGNITION**
 - **PLASTIC IGNITION**
- **TEST RESULTS**
- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **ROBUST DESIGN ALTERNATIVES**

TL-NHTSA 014078

CONFIDENTIAL

Attachment




1. Connector Seal to P/S
2. Power continuously available
 - A. Operator notifications
3. Switch orientation/location
4. Current limit / fuse
5. Hexport isolation
6. Plastic ignition robustness
 - A. Nearby fuels
7. Kapton seal of P/S
8. Environmental seal of P/S

Copyright © 1999 Texas Instruments

Attachment



**OVERVIEW OF
CONCERN TIME LINE**



TI-NHTSA 014078

C:\4\014078\specimen\Ford

Attachment




Brake Switch Overview

- **Mounted under hood...14 inches under master cylinder**
- **Mounted on proportional valve at frame of vehicle**
- **Switch oriented approximately 25 degrees off vertical (connector up)**
- **Switch controls speed control...normally closed, opens at 130 psi**
- **Continuously powered by battery 15 amp connection**

TI-NHTSA 014079


Brake Pressure Switch Potential Thermal Event Theory Profile 5/20/99



TI-NHTSA 014080

Call Call @ Systematic Ford

Attachment




© 1989 Texas Instruments

Attachment

TI-NHTBA 014081



REFINED BRAKE FLUID IGNITION THEORY
POSSIBLE CAUSE THEORIES
"FEB '99 FOCUS"



TJ-NHTSA 014082

C:\McGill\89\presentation\Ford

Attachment



**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99**



Excel spreadsheet

TI-NHTSA 014083

© 1999 Texas Instruments


Attachment



- TI and Ford not successful in creating ignition with "new"
brake fluids

TI-AHTBA 014084

Brake Pressure Switch Potential Thermal Event Theory Profile 5/20/99



TI-NHTSA 014085


CS&G/CS&G/Separation/Prod

Attachment



Generated by: *ReliaSoft's Weibull++ 5.0 - www.Weibull.com - 888-885-0410*

77PSL2-1 COMBINED DATA




$\beta=5.83, \eta=1.64E+6, \rho=0.91$



- "Town Car" switch meets accelerated/simulated life cycle specification shown by "success" and "end-of-life" testing



PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS




TI-NHTSA 014088



5. High current flow to case through water and ionic contamination

2. 12V Battery source to drive corrosion and provide energy

6. Plastic connector melts. Once it opens, oxygen enters the switch cavity. Arm terminal/corrosion becomes "RED HOT" igniting the plastic





1. Water and "ionic" contamination (e.g. NaCl or cleaner) enters the switch cavity

4. Contact arm & terminal corrosion increases resistance (acts like heater wire).

3. Hexport grounded accelerates corrosion



**5% Salt Water Ingress Experiment
Test 1**



Test 1: Figure 1 and Figure 2.


TI-MHTBA 014090

TI Report PS/99/12
03/15/99



5% Salt Water Ingress Experiment
Temperature vs. Time

----- Top Temp ——— Clutch Temp Bottom Temp




INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST PS/99/13' Attachment

TI-NHTSA 014091



5% Salt Water Ingress Experiment





**77PS
45° Orientation in 15 Amp Circuit
5% Salt Water Ingress**

Cellanex 4300 Base



Cellanex 3316 Base



TI-NHTSA 014098


INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST PS/99/13'

C:\McQuis\99\ps\ps99\014098.tif

Attachment




“Corrosion” potential cause time line
Theory Time Line






77PS Cellanex 4300 Base
Vertical Orientation in 15 Amp Circuit
5% Salt Water Ingress



TI-NHTSA 014095




PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS






77PS Noryl Base
45° Orientation in 15 Amp Circuit
5% Salt Water Ingress



TI-NHTSA 014087




ECONOLINE VS. TOWN CAR P/S



TI-NHTSA 014008



“Corrosion” potential cause time line
Theory Time Line




TI-NHTBA 014099



77PS Proposed Wiring Schematic

14 Volts DC




TI-NHTSA 014100



200 mAmp Current Limit Circuit
Test Setup

14.5 Volts DC



Worst case scenario is when the switch is actuated, which puts T2 at full voltage. To facilitate testing, T1 is floating which keeps T1 and T2 at full voltage but limits current draw to .2 Amps (This test is harsher than worst case scenario).

TI-NHTSA 014101




See low current stuff from sean

TL-NHTBA 014102



**PRESSURE SWITCH "FLOW DIAGRAM"
('92, '93, TOWN CAR)**



TI-NHTSA 014103



NA Hydraulic Switch History

Time Period:	'83	'87	'90	'91	'98	'99
Application:	Power Steering	Power Steering Suspension	Power Steering Suspension Transmission	Power Steering Suspension Transmission Cruise	Power Steering Suspension Transmission Cruise Clutch	Power Steering Suspension Transmission Cruise Clutch
Fluid:						

- TI has some 16 years and 130 million units accumulated experience in hydraulic applications using multiple fluids
- TI has some 12 years of brake system application experience working with brake fluids



1. Operational Definition (Problem Statement): TOWN CAR UNDERBOOD FUSES			
2. Description	IS	IS NOT	Get Information
WHAT	Town Car MY '92, '93, '94	Crown Vic/Grand Marquis TD Super Coupe MY '91, '93, '95? '92, '94 Executive	COMPARE PLATFORMS
	FUSES... - Electrical pressure switch - Camshaft - Servo system - Electrical Distribution	Not only pressure switches	COLLECT/TEST OTHER SYSTEM COMPONENTS FOR "ENERGY" COMPARE VEHICLE OPTIONS FOR ENERGY
	SYSTEM ISSUES... - Cruise Inoperative - Lockset in park - Hvac Inoperative - Brake lights Inoperative - Discharged battery - Door lock(s) - Horn(s) Inop?	Other checks	COMPARE WARRANTY
WHERE	Driver side hood Master's bolt(s) in engine compartment	Passenger side hood Dash - fuse compartment Not high in engine compartment Not low in engine compartment	EVALUATE HEAT SOURCES
WHEN	1-24 hours after parking Ignition off After 4-5 years After XXX miles After AAA switch cycle	Not while driving Not while ignition on Not before 3 years? Not before XXX miles Not before HEB cycle	EVALUATE POWER AND HEAT AND WIND SOURCES REVIEW MILES
HOW BIG	149 cars / 223 units "omnibus" issue	Not all cars? Not "application"	COMPARE PLATFORMS READ FIRE RPTS
	Lowest pressure switches	Not all unlabeled fuses Not all pressure switches	FAIRLY UNDERBOOD



**Texas Instruments
Automotive Design & Controls
80 Report**

Attachment


Customer Title 77 PW Thermal Events		Open Date 3/99	
TI CAR Report Number OAR 99-09		Update# 421/99	
Make/Model Volvo S40	Year 1999	Part Name Electric Ignition Control Deactivation Pressure Switch	Part No. 7721 B-1
1. Team & Designers R. Dugas A. McQuirk G. Baker		2. Problem Description Under load condition	
3. Customer Activity: Under motor, resulting stalling speed control system		% Effectiveness	Implementation Date
4. Root Cause See attachment 1, 2 - is NOT Table, (Theater of 3/15/99) <ul style="list-style-type: none"> Water contamination with the connector Continuously poor drive circuitry Continual overage high resistance Redundancy causing local loading Several exposures over time (?) Local loading igniter pressure switch and connector joints Operator protection violation 		% Contributor	Unknown
5. Check Potential Corrective Action See attachment 3, 4 Under Review: <ul style="list-style-type: none"> Early launch Continuator Crack ground ball pressure Improve connector seal Eliminate contact power Change PE calibration Provide power backup power reduction Modify plastic pressure Operator policy Move to ground potential 		Verification TBD by lab experiments	% Effectiveness Unknown
6. Supplemental Potential Corrective Action		Implementation	
7. Activity to Prevent Recurrence Maintain contact power, release power to function and, get code for "Egas" electrical function		Implementation	
8. Completion Team	Case No.	Reported By Dept. Name Telephone No.	A. McQuirk QRA Manager (512) 231-2000

CallMe@texasinstruments.com



77psB-1		GROSS QTY		COMPLETE	COMPLETE	BEGIN	IMPACT	COMMENTS/CONCNS
COMPONENT	DESCRIPTIVE	REQUIRED	SUPPLIER	1WK	2WK	PARTIAL	TO TI	
27406-1	CONVERTER	2,040,000	KF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY
27639-1	WASHER/A	2,040,000	DIEMASTER	10 WKS	18 WKS	2 WKS	NONE	MATERIAL AVAILABILITY
27713-1	CLIP77PS	2,040,000	VALENTINE	6 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
38668-27	57PS	2,040,000	DISC DEPT	12+ WKS	24 WKS	3 WKS	TOOL \$?	POSSIBLE CAPACITY ISSUE
38820-1	HEXPORT 77	2,040,000	BLOD	10 WKS	25 WKS	3 WKS	NONE	RAW MATERIAL AVAILABILITY
74224-1	KAPTON	204	BIDUFONT	2 WKS	2 WKS	2 WKS	NONE	
27226-1	KAPTON ST	1,102	BIDUFONT	3 WKS	3 WKS	2 WKS	NONE	
74363-1	GASKET	2,040,000	JEL PARKER	8 WKS	18 WKS	3 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
38888-1	STATIONAR	2,040,000	KF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/REELS
28744-1	CONTACT-S	2,040,000	DEFFINGER	4 WKS	8 WKS	1 WK	NONE	MATERIAL AVAILABILITY
38887-1	MOVABLET	2,040,000	KF BASSLE	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME MATERIAL AVAILABILITY/REELS
27718-1	BERCU 85UM	480	BFLUSHWEL	1 WK	2 WKS	1 WK	NONE	NONE
74816-1	PIVET	2,040,000	JOHN HASS	8 WKS	11 WKS	4 WKS	NONE	RAW MATERIAL AVAILABILITY
48616-2	PRESSURE S	2,040,000	MIRACLDON	14 WKS	32 WKS	4 WKS	NONE	RAW MATERIAL CHANGE OVER PRESS CAPACITY
74076-143	CERAMIN PF	2,040,000	PAPA TECH	7 WKS	25 WKS	2 WKS	NONE	
74247-4	ELLIE OTRG	2,040,000	JEL PARKER	8 WKS	18 WKS	2 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
74787-1	CRIMP RING	2,040,000	VALENTINE	6 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
74888-1	RED THREAD	2,040,000	MARK IV CA	8 WKS	8 WKS	1 WK	NONE	
77PS	SWITCH		TI	775,071,0715	250K/MONTH			7 day weeks, thru summer vacations, 'not plastic mold


TI-NHTBA 014107



TI-NHTSA 014106

Call Date/Time/Location/Time

Attachment



TI-NHTSA 014109

C:\nhtsa\99\poten\poten.ford

Attachment

**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99**



Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Serbik	1	TI	Very water concentrations in "new" Brake Fluid 1-4Vdc to one terminal, lampout grounded Water Conc: 4%, 8%, 10%, 70%	250+ hours. Current draw in the 0.5mA to 2mA range Fluid was discarded. No significant temperature rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through serbik terminals 1-4Vdc to one terminal, lampout grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	new Brake Fluid in Serbik, 24 VDC to one terminal. Lampout grounded	> 200 hours into test, some current 7mA No significant changes with time. Test ongoing
	4	AVT	new Brake Fluid in Serbik, 24 VDC to one terminal. Lampout Grounded, Ambient at 100 C	10 hours into test, some current 2mA No significant temperature rise with time. Test suspended.
	5	AVT	new Brake Fluid in Serbik, 16 Amps through serbik terminals	Temperature rise of 20 Celsius occurring. Using T reached steady state at 30 C. Test completed.
	5a	AVT	new Brake Fluid in Serbik approx. 60 Amps through serbik terminals	Temperature rose to approx. 220 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Serbik. Heat all terminals, include spalling. With Fluid & Dry	2 tested. Smoke observed, ignition observed on part w/ heater See attachment Test complete Smoke RMI in cavity shows clear heat build-up Smoke observed at 400 F, flame paths and hole off at 600 F
	6a	TI	Create heater by connecting spring and steel washer sections, 14V between spring and lampout	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or magnetic It took about 100 hours to reach the 5 ohm stage. The 5 ohm device failed under conditions similar to test 6.
	6b	TI	Pin-run ignition test to understand repeatability and current path.	One hole ignition with required 5% water solution into serbik Current path is through lampout. See photo and video. Additional heat includes top water, old EF, new EF and other.

TI-NHTSA 014110

**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99**



Test Name	SN	TI	Test Item / Test Conditions	Test Results / Comments
Life Cycle Reliability of Pressure Switch	7	TI	D-1400 poly pressure pulses at 1400 psi	First leak observed at 228,000 cycles. Test completed. See attached Writing Chart.
Discharge Rate	8	TI	D-1400 poly pressure pulses at 1400 psi	Test to determine energy 2000 cycles, discharge rate for water
Flow in Lab Duration	9	Control Labs	Flow volume, flowmeter rate, discharge	Flow in Control Labs, see flow measurements
Change of Characteristics (1) Discharging Pressure	10	TI	Very water contaminated in lower pressure field	Test report being prepared in future laboratory conditions.
Discharge Temperature			12 cups = 12 gal water in 20% water in BP	Completed at 1.2 million cycles with no leaks observed.
Discharge Rate			12 cups = 12 gal water in 20% water in BP	Temp increase accompanied at 1.2 million cycles with 2 leaks observed at 1.2M. Child pressure accompanied at 1.2M cycles to determine discharge pressure.
On-Vehicle Observation of Pressure & Temperature Profile in Tank or Car	21	AVI	Initial Pressure and Temperature at Tank Location for AMI and non-AMI	Test at AVI... see flow chart... 1.2M in test?
Water field analysis Used field in reactor cylinder.	11/22	TI	Apply on small field at the reactor cylinder (LUC), test water field at the reactor (LUC) test water field (LUC) for metal and water content.	Test complete. WFO: G ₁ = 4.18 gpm, R ₂ = 5.5 gpm, C ₁ = 0.02 gpm, 1.1 MPM WFO: G ₁ = 2.92 gpm, R ₂ = 5.5 gpm, C ₁ = 1.9 gpm, 1.1 MPM WFO: G ₁ = 0.01 gpm, R ₂ = 0.02 gpm, C ₁ = 0.01 gpm, 0.2 gpm
Block Flow Study	12	Control Labs	Determine if backflow occurs in any job using which type and this speed valve.	Completed test up in progress of Control Labs.
Characterization of Discharge Volume	23	Control Labs	Characterize electrical, mechanical and chemical aspects of released air lines	Test log and complete program set up complete. Analysis of no flow in progress.
Field Inspection Log	11/22	TI	Inspect location of valve in the flow field.	Test complete.
			48 hour test.	WFO test results attached flow chart.
			976 MACH in top water	All tests will complete after two days. No complete results on today field analysis.
			with water	Test trailer and top of air sample after 100 cycles and showed some change of pressure.
			48 hour test.	Completed analysis in progress.
			use water	
			used water field	
			used water field w/ 87% H ₂ O	
			water sample field	
			water sample field w/ 87% H ₂ O	

Copyright © 1999 Texas Instruments

TI-NHTSA 014114

**Brake Pressure Switch
Potential Thermal Event Theory Profile 5/20/99**




Compatibility of Kapton with Oxalic Acid	14	Report	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Compatibility of Kapton with Oxalic Acid	14	Report	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and suitability of different grades of plastic resin with additives to improve plastic part performance.	Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and suitability of different grades of plastic resin with additives to improve plastic part performance.
Long duration brake fluid ingress test.	15a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Long duration brake fluid ingress test.	15a	TI	(4) samples with new brake fluid (2) samples with used brake fluid
Evaluation of Switch Orientation	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Evaluation of Switch Orientation	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.
Relay Circuit Test	16	TI	Repeat test 12b in Ford relay circuit for (40) hrs. Bring switch in separating ignition in (15) Amp circuit then place in relay circuit for (15) hrs. Input max. circuit power into heater on switch.	Relay Circuit Test	16	TI	Repeat test 12b in Ford relay circuit for (40) hrs. Bring switch in separating ignition in (15) Amp circuit then place in relay circuit for (15) hrs. Input max. circuit power into heater on switch.

TRANSTRON 014112



5% Salt Water Ingress Experiment Temperature vs. Time

— Top Temp — Clutch Temp — Bottom Temp



TI-NHTSA 014113



CM-QuickPresentation

INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST

Brake Pressure Switch Potential Thermal Event Theory Profile 5/6/99



**Hotspot Current vs. Time
Fluid Ingress Experiment**



INTENTIONAL IGNITION CREATED THRU TI FLUID INGRESS LAB TEST