

EA02-025

TEXAS INSTRUMENTS, INC.'S

9/10/03

REQUEST NO. 7

BOX 9

PART A - R

PART J



**TEXAS
INSTRUMENTS**

.1999

FACSIMILE TRANSMITTAL

TO:

Name: *Sally*
Location:
Mail Station:
Phone Number:
FAX Number:

FROM:

Andy McQuirk

TEXAS INSTRUMENTS MS 23-07
Phone Number: (508) 236-
FAX Number: (508) 236-2430

Total number of pages (including header page): *11*

COMMENTS:

TI-NHTSA 014201

TEXAS INSTRUMENTS INCORPORATED • PO BOX 2964 • 34 FOREST STREET • ATTLEBORO, MA 01703

JUN 29 '99 16:48

5082361598 PAGE 001

4.5. IMPULSE

4.5.1

PROCEDURES:

Per the engineering specification.

4.5.2

EQUIPMENT:

- Thermocon environmental chamber, model S - 4.
- Twenty-four station manifold.
- Mating electrical connectors.
- Trygon Electronics Dual Power Supply, DL40-1A for the loads.
- Acopian power supply, SE25D-DISECS for Sensotec transducer.
- Customized designed and built pressure cyclor.
- Enerpac hydraulic pump.
- TI 315 Programmable Logic Controller.
- Moog servo valve, 760-552-A.
- Moog controller, MA-X-50.
- Simpson signal generator.
- Sensotec transducer, T8E-744-03, 0-2,500 psig, calibrated semi-annually.
- Nicolet oscilloscope, 310, calibrated semi-annually.

4.5.3

REQUIREMENTS:

At the completion of this test all switches shall meet the Voltage Drop, Current Leakage, and Creep Time requirements outlined in the engineering specification (See Appendix 3.1). Additionally, the post-impulse calibration requirements are not define; results of this test will be used to set this requirement.

4.5.4

RESULTS:

All switches met the requirements outlined in the engineering specification. Data is presented in Appendix 3.4.2.

TEST LOT NO.	TEST	DEVISE
TESTED BY	TEXAS INSTRUMENTS	ENG.
APPROVED BY		MATERIALS & CONTROLS GROUP
DATE 1/14/92		ATLANTA, GA 30388

FORM 0000

TI-NHTSA 01

5082381598 PAGE.

JUN 28 '99 16:45

3.9 IMPULSE

3.9.1 Devices tested: 207-15-1 thru -24.

3.9.2 Procedure: Performed per the ES.

3.9.3 Equipment: same as 3.8.3.

3.9.4 Results/Discussion: Four devices (#207-15-1,-5,-9,-11) were found to have a slightly elevated release transfer time (Creep Check, ES frame 9 of 13, section III. M.). Note that other Ford Engineering Specifications which cover hydraulic pressure switches produced by Texas Instruments, specifically ES-E53C-3N824-AA, allow up to 30 milliseconds for transfer time after the Impulse test. The four devices noted fell well within 30 msec. This issue will be addressed by communication with the responsible engineering office at Ford, to determine if a slight increase in transfer time at the end of life should be included in the ES.

92005
4/24/99
E75C 3N824-AA

TEST LOT NO.	TEST	REVISE
TESTED BY		
APPROVED BY		
DATE		
TEXAS INSTRUMENTS		MATERIALS CONTROL GROUP ATLANTA, GA 30102
		PAGE

FORM 888

JUN 29 '99 10:48

586201588 PAGE.003

TI-NHTSA 014203

3.10 IMPULSE

3.10.1 Devices tested: 156-15-81 thru -104.

3.10.2 Procedure: 24 virgin devices were run as opposed to 12 virgins and 12 from Fluid Resistance. This is discussed in detail in section 3.0. The parameters given in the ES (frame 7 of 18, section III. E. 1.) are followed explicitly.

3.10.3 Equipment: same as 3.8.2 with the addition of a 12-station inductive load bank, per the schematic found in the ES (frame 18 of 18; figure 4.) used in the last 25K cycles.

3.10.4 Results/Discussion: Pre-characterization was not performed. After completion of the 500K cycles, all 24 devices passed the acceptance criteria found in the ES (frame 7 of 18, section III. E. 2).

This test may be regarded as the one of the most rigorous. This test is run at elevated temperature (135 C fluid), elevated pressure (1450 psig, 2 Hz), and total cycles (applying brakes 3 times per mile for 100,000 miles) which exceed conditions typically found in actual motor vehicles.

TEST LOT NO.	TEST	DEVICE
TESTER BY		
APPROVED BY		
DATE	TEXAS INSTRUMENTS	MATERIALS CONTROL GROUP ATTLEBORO, MA 01735
FORM 8000		DOC. PAGE 14

3.6 IMPULSE

- 3.6.1 Devices tested: 172-15-01 thru -24
173-15-01 thru -24.
- 3.6.2 Procedure: 172-15-13 thru -24 and 173-15-13 thru -24 were run together on the Impulse test per the IS. Devices 172-15-01 thru -12 and 173-15-01 thru -12 were subject to the fluid resistance test first, then run together on the Impulse test.
- 3.6.3 Equipment: Thermotron model 3-4 Mini-Max environmental chamber capable of -55 C to +200 C, humidity uncontrolled. Custom TI designed and built cycler, utilizing Enerpak integrated hydraulic pressure source, TI315 Programmable Logic Controller, Moog servovalve and controller, Simpson signal generator, and opposing-piston fluid isolators, to produce a hydraulic-fluid flow-type primary with a brake-fluid dead-end-type secondary terminated with a 24-station manifold equipped with internal heaters. Capability to 5 Hz at 0-1450 psig cycle. Custom TI designed and built 24 station Switch Monitor Circuit which automatically stops the cycler in the event of abnormal switch action, defined as continuity change which does not track the signal from the signal generator. Thermocouple readouts calibrated quarterly. 12-station inductive load bank, per the schematic found in the IS (frame 18 of 18; figure 4.) used in the last 25K cycles.
- 3.6.4 Results: All devices passed.

TEST LOT NO.	TEST	DEVICE	
TESTED BY	TEXAS INSTRUMENTS	MATERIALS CONTROLS GROUP ATTLEBORO, MA 01730	
APPROVED BY			DEL.
DATE			PAGE

JUN 28 '88 16:58

5082361588 PAGE.009

TI-NHTSA 014208

3.10

3.10.1 Devices tested: 85-15-01 thru 85-15-12 from Fluid Resistance test 3.9 and 85-15-63 thru 85-15-74 virgin devices.

3.10.2 Procedure: All 24 devices actually ran 525,000 pressure cycles. The first 475,000 is done unpowered, with the Switch Monitor Circuit functioning. From 475,000 thru 500,000 cycles one-half of the 24 devices are powered. This is due to the fact that the Load Bank only has 12 stations for cost, size, and weight considerations. From 500,001 thru 525,000 cycles the other half are powered.

3.10.3 Equipment: same as 3.8.2 with the addition of a 12-station inductive load bank, per the schematic found in the ES (frame 18 of 18; figure 4.) used in the last 25K cycles.

3.10.4 Results/Discussion: All twenty-four devices passed the acceptance criteria found in the ES (frame 7 of 18; section III. E. 2.).

This test may be regarded as the one of the most rigorous. This test is run at elevated temperature (135 C fluid), elevated pressure (1450 psig, 2 Hz), and total cycles (applying brakes 5 times per mile for 100,000 miles) which exceed conditions typically found in actual motor vehicles.

TEST LOT NO.	TEST	DEVICE
TESTED BY		
APPROVED BY		
DATE 10-11-81		MATERIALS & CONTROLS GROUP ATTLESON, CA 94520
FORM 8004		PAGE 15

JUN 29 '88 10:51

5082361598 PAGE.008

TI-NHTSA 014206

3.10 IMPULSE

- 3.10.1 Devices tested: 157-15-01 thru -12 from Fluid Resistance test 3.8 and 157-15-67, -69 thru -74, -76 thru -80 virgin devices.
- 3.10.2 Procedure: Virgin devices were run separately, before the Fluid Resistance devices. In each case, the procedure given in the ES (frame 7 of 18, section III. E. 1.) was followed explicitly.
- 3.10.3 Equipment: same as 3.8.2 with the addition of a 12-station inductive load bank, per the schematic found in the ES (frame 18 of 18; figure 4.) used in the last 25K cycles.
- 3.10.4 Results/Discussion: All twenty-four devices passed the acceptance criteria found in the ES (frame 7 of 18; section III. E. 2.).

This test may be regarded as the one of the most rigorous. This test is run at elevated temperature (135 C fluid), elevated pressure (1450 psig, 2 Hz), and total cycles (applying brakes 5 times per mile for 100,000 miles) which exceed conditions typically found in actual motor vehicles.

TEST LOT NO.	TEST	DEVICE
TESTED BY	TEXAS INSTRUMENTS 	ecc. TI-001097
APPROVED BY		PAGE
DATE 01-08-52		11

FORM 5206

JUN 28 '52 18:52

5092361586 PAGE.007

TI-NHTSA 014207

25:01 05, 52 NIT

Ford

The following represents a rough usage matrix over time:

MY82	MY83	MY84	MY85	F	MY81	MY80
Econoline	Econoline	Econoline	Econoline	Econoline	Econoline	Econoline
Club Wagon	Club Wagon	Club Wagon	Club Wagon	Club Wagon	Club Wagon	Club Wagon
Town Car	Town Car	Town Car	Town Car	Town Car	Town Car	
Crown Vic	Crown Vic	Crown Vic	Crown Vic	Crown Vic	Crown Vic	
Grand Marquis	Grand Marquis	Grand Marquis	Grand Marquis	Grand Marquis	Grand Marquis	
	F Series	F Series	F Series	F Series	F Series	F Series
	Bronco	Bronco	Bronco	Bronco		
	SHO Taurus	SHO Taurus	SHO Taurus??			
		Capri	Capri	Capri??		
		Windsor	Windsor	Windsor	Windsor	Windsor
			Falcon	Falcon	Falcon	Falcon
				Explorer??	Explorer	Explorer
				Ranger??	Ranger	Ranger
					Expedition	Expedition
						Navigator

TLNHITSA 014209

508281598 PAGE 008


JUN 29 '99 16:52



**Brake Pressure Switch
Potential Thermal Event Theory Profile 4/21/99**



FORD TOWN CAR ISSUES



NOTES: Ford data as of 4/14/99

1-800-445-6200

TI-NHTSA 014209


5862361598 PAGE 089

JUN 29 '99 10:54

TEXAS INSTRUMENTS Brake Pressure Switch Potential Thermal Event Theory Profile 3/15/99



1991 Next Generation Speed Control System



TI-NHTSA 014210

5882381598 PAGE.010

C:\ACT\...

Attachment

JUN 28 '58 10:55

Sample	Condition	Impact, Weather, Corrosion, and Stress	Switch	Cup	Intermittent Contact (Switch)
1 1958 Form C, Working	Fairly normal	Black residue consisting glycol based material (probably brake fluid) and a metal particle. Indistinct presence of brake fluid on flat end switch side of switch.	Electromechanical and good general contact and appear to have had good working. All three elements seem to be located and visible from the contact which most likely formed a path. Damage appears to have initiated in seal chamber's outer Drums and Upper chamber and controlled by automatic mechanism.	Green. Depends on face of cup certain elements have been replaced indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.	Open separated below sample ring. Terminal pin and movable contact missing. Secondary contact exhibits loss of material due to corrosion, evidence of disintegration, slight corrosion cracking. Loss of movable contact contact which was believed between switch and terminal contact. Appears to have occurred in later stages of event. Evidence of terminal movement with black and green deposits which appear to be either contaminants of the terminal contacts.
2 1958 Form C, Working	Normal	Elements from contact material detached at filling end of impact. Indistinct possible flow of fluid back through seal.	Good and electromechanical and working. Cleared fragments Upper seal remains.	Deposits on face of cup certain elements from lower contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Open, stationary contact, movable contact, and terminal missing.
3 1958 Form C, Working	Good	Elements from contact material detached at filling end of impact. Indistinct possible flow of fluid back through seal.	Not possible to disassemble switch.	Deposits on face of cup certain elements from lower contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Terminal pin and movable contact missing. Secondary contact exhibits crack in other location as that in Redlich sample.
4 1958 Form C, Working	Normal	Elements from contact material detached at filling end of impact. Indistinct possible flow of fluid back through seal. Black deposit in cup cavity being analyzed (probably stored glycol).	Goodly system cleared. Electromechanical and working. Damage to Upper seal entirely being overlooked.	Deposits on face of cup certain elements from lower contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Open, stationary contact, movable contact, and terminal missing.
5 1957 Open Working	Apparent leakage.	Black residue consisting glycol based material (probably brake fluid) and a metal particle. Indistinct presence of brake fluid on flat end switch side of switch.	Electromechanical seal and general defect and appear to have had good working. Upper seal exhibit damage similar to that found in Redlich sample. All three visible from the contact which most likely formed a path.	Dark green deposits on face of cup certain elements from lower contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid is believed and on face of cup in glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Contacts appear intact. Dark green deposits on movable and stationary contacts certain elements from lower contact material. Terminal appear clear the apparent deposits or corrosion.
6 1951 Open Working	No leaks or other apparent problems	Black residue consisting glycol based material (probably brake fluid) and a metal particle. Indistinct presence of brake fluid on flat end switch side of switch.	Electromechanical seal and general defect and appear to have had good working. Upper seal exhibit disintegration and working similar to that found in Redlich sample. Corrosion on surfaces suggest material change in corrosion.	Face of cup appears clean and dry.	Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
7	Apparent leakage	Black residue consisting glycol based material (probably brake fluid) and a metal particle. Indistinct presence of brake fluid on flat end switch side of switch.	Electromechanical seal and general defect and appear to have had good working. Upper seal exhibit damage similar to that found in Redlich sample. All three visible from the contact which most likely formed a path.	Dark green deposits on face of cup certain elements from lower contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid is believed and on face of cup in glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Secondary contact is intact, but also shows some corrosion cracking in progress or ledge area (same location as in Redlich sample). Elements cannot appear to have separated on a small amount of material (~50% of thickness) due to corrosion. No evidence of heating or use damage. Dark green deposits on movable and stationary contacts upper chamber heat from contact material, as well as oxide. Terminal exhibit green deposits (probably being analyzed). Deposits material is from both sides of ballhead however switch and terminal contacts, but do not work.

8092061580 PAGE 011

71-NHTBA 014211

Brake Pressure Switch Test Log, Updated 6/30/08

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Vary water concentrations in 'new' Brake Fluid 14Vdc to one terminal, harness grounded Water Conc: 4%, 8%, 18%, 78%	200+ hours, Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, harness grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Harness Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Harness Grounded, Ambient at 100 C	18 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 15 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps Through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat oil failure, include sparking (1) w/ solution of Brake Fluid and 6 wt. % H ₂ O	3 tested. Smoke observed, ignition observed on part vehicle See attachment Test complete Brake fluid in cavity slows down heat build-up Smoke observed at 575 F, Base metal and falls off at 800 F
	6a	TI	Create heater by corroding spring pin Salt water solution, 14V between spring and harness	One out of 18 devices increased resistance to 5 ohms. Others either very low resistance or megohms It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 8% water solution into switch Current path is through harness. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test includes tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

TI-NHTSA 014212

Brake Pressure Switch Test Log, Updated 8/30/90

				conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psi pressure pulses at 135C per EB	First leak observed at 725,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psi pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Central Labs	Field returns, from dealer jobs, jerkyrides	Parts in Central Labs, use Ford spreadsheet
Design Of Experiments (6) Evaluating Factors Effecting Diaphragm Wear Impulse test	10	TI	Very water concentrations in 'new' Brake Fluid 12 amp + 12 quiet switches w/ 0 % water in BF 12 amp + 12 quiet switches w/ 5 % water in BF	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess leaking anomalies.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT... see Ford charts... >500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. UMC: Cu = 415 (ppm), Fe = 3.5 (ppm), Cr = 0.05 (ppm), 1.1 %H2O. UCA: Cu = 582 (ppm), Fe = 5.5 (ppm), Cr = 1.8 (ppm), 1.1 %H2O. NEW: Cu = <0.01 (ppm), Fe = 0.02 (ppm), Cr = <0.01 (ppm), 0.5 %H2O.
Spark Arc Study	12	Central Labs	Determine if arcing forms in switch using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water rates.	Experiment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field networks & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches.	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Ingress Tests	13a	TI	Repeat ignition simulation with different fluids. (B) 1hr tests: 5% NaCl in tap water rain water (24) 1hr tests: tap water	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples draw less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples draw <10 mAmps and showed some signs of corrosion.

Brake Pressure Switch Test Log, Updated 8/30/99

			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H ₂ O	
			new brake fluid	
			new brake fluid w/ 5% H ₂ O	
Design Of Experiments (2) Repeat of test 10	13b	TI	Very water concentrations in 'new' Brake Fluid 10 amp + 20 quiet switches w/ 0 % water in BF 10 amp + 20 quiet switches w/ 5 % water in BF	Test suspended. Analysis in process to assess test failure.
Compatibility of Kapton with Oxalic Acid	14	Deposit	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects that water has on Kapton properties.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and availability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Cabrane and Noryl tested 50 and 25 trials ZYTEL samples tested 1/6 gallons
Long duration brake fluid ingress test.	16a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test suspended (500) hours completed. Used brake fluid current dropped off to <1/10 mAmp. New BF support current was increase w/ time under const. power.
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Simulated switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 13a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (36) hrs. Input motor circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or move toward ignition in lab F-tester element was warm to the touch.
Long duration brake fluid ingress test number 2.	17	TI	(50) samples filled with new brake fluid (1) hour of vibration per day (1) hour soak at 100 deg C per day	Test suspended. (312) hours completed. Average support current is 1.9 mAmp (deviation = 1.8 mAmp)

PS/99/07

77PS Life Cycle Test to Leakage

Abstract

The purpose of this life cycle test was to quantify the life expectancy of 77PS hydraulic pressure switches. A sample of switches was cycled under specified conditions until leakage occurred. Upon leakage, the suspect switch was removed and the number of cycles recorded. Weibull Failure Analyses were then performed on the data.

Procedure

(36) 77PS switches were used as a test sample. The switches were placed in an oven where a temperature of 135°C was maintained. The switches were cycled from 8 psi to 1500 psi at a frequency of 2 Hz. When a leaky switch was detected, the test was suspended and the switches were allowed to cool to ambient temperature. The leaky switch was removed and the number of cycles noted. The remaining switches were brought back up to 135°C and testing resumed.

Data

Summary:	Temperature:	135°C
	Pressure (low):	8 psi
	Pressure (high):	1500 psi
	Frequency:	2 Hz

Table 1. below, shows the raw data obtained.

Table 1.

Quantity of samples	Cycles to Leakage (*indicates switches did not leak to specified cycles)
1	728000
2	1075000
3	1095000
1	1200925
1	1208509
2	1212896
26	1212896*

Note: Some switches leaked at the same time; this is reflected in the above table where there are multiple quantities for the same cycles to leakage.

Results

All (36) switches passed the specified 500,000 cycle requirement. Only (1) leakage occurred below 1,000,000 cycles.

The leakage mode of the switch at 728K (K = 1000) cycles, appears to be unrelated to the leakage modes of switches above 1000K cycles. An investigation is ongoing to gain an understanding. It is unclear at this time whether it is valid to use this data point as part of the analysis. Therefore, two separate analyses were performed; one including the 728K data point and one excluding the 728K data point.

Weibull Failure Analyses were performed on the data.

Figure 1 (page 4 of this report) shows the results where the 728K data point was included in the analysis. It shows a 90% Reliability at 1,000,000 cycles.

Figure 2 (page 5 of this report) shows the results where the 728K data point was excluded in the analysis. It shows a 98% Reliability at 1,000,000 cycles.


(Note: Due to software constraints, only (30) data points were used to perform the Weibull analysis instead of the (36) available).

Table 2, below, was constructed using the Weibull Failure Analyses of Figures 1 and 2. Percent reliability was obtained as a function of life cycles. The results are displayed graphically in Figure 3 below.

Table 2.
% Reliability vs. Life Cycles

728K point included in analysis		728K point not included in analysis	
Life Cycles	% Reliability	Life Cycles	% Reliability
500000	100	500000	100
750000	98	750000	100
1000000	90	1000000	98
1250000	76	1250000	65
1500000	59	1500000	3

Figure 3.



Discussion of Weibull Failure Analysis

For each set of data entered into a Weibull Analysis, the set of parameters α , β and R^2 are determined. Values for the data used in this test may be seen in Figure 1 and Figure 2.

α is the Characteristic Life which determines the spread of the distribution. The higher the number, the greater the spread.

For example, Figure 1 shows a calculated $\alpha = 1,302,169$ while Figure 2 shows a value of 841,858. In Figure 1, the 728K point is included in the analysis and causes a greater spread of the distribution than that of Figure 2, where the 728K point is not included in the analysis.

β is the Shape Factor which determines the shape of the distribution curve.

R^2 is the Coefficient of Determination

Conclusion


Reliability of PS77 switches to 500,000 cycles is 100%.

Reliability of PS77 switches to 1,000,000 cycles is at least 90%. Reliability is as high as 98% when (1) separate leakage mode at 728,000 cycles is not included in the analysis.

Report Authored by Sean Mulligan

Figure 1.


2 and 3 parameter WEIBULL FAILURE ANALYSIS



NOTES: 77P8 - 725K cycle data point included in analysis

OVCA = 135°C

2-13-99
Fond Testing
7715



TI-NHTSA 014220

3/30/99

1

DOE 2

Group	Switch	% Water PUMP
G1	77PSL2-1	0
G2	77PSL3-1	0
G3	77PSL4-1	0
G4	77PSL2-1	5
G5	77PSL3-1	5
G6	77PSL4-1	5

TI-NHT8A 014221

3/30/99

measured
val. exist
in an. fold

DOE 1

GROUP: G1
DESCRIPTION: 77PBL2-1 w/ 0% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S
G1-	1027		S

GROUP: G2
DESCRIPTION: 77PBL3-1 w/ 0% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G2-	851		
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S
G2-	1027		S

GROUP: G3
DESCRIPTION: 77PBL4-1 w/ 0% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G3-	481		
G3-	710		
G3-	737.8		
G3-	788.1		
G3-	804.1		
G3-	909		
G3-	919		S
G3-	919		S
G3-	919		S
G3-	919		S

3/30/99

DOE 2

GROUP: G4
 DESCRIPTION: 77P8L3-1 w/ 8% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G4-	432.6		
G4-	438.1		
G4-	478		
G4-	481.8		
G4-	487.8		
G4-	518.8		
G4-	518.8		g
G4-	518.8		g
G4-	518.8		g
G4-	518.8		g

GROUP: G5
 DESCRIPTION: 77P8L3-1 w/ 8% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G5-	297		
G5-	297		
G5-	308		
G5-	337		
G5-	347.5		
G5-	374.5		
G5-	388		
G5-	409.5		
G5-	412		
G5-	518.8		g

GROUP: G6
 DESCRIPTION: 77P8L4-1 w/ 8% water in brake fluid

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G6-	243		
G6-	281		
G6-	287		
G6-	297		
G6-	308.2		
G6-	324.7		
G6-	337.2		
G6-	337.2		
G6-	337.2		g
G6-	337.2		g



Figure 2.

2 and 3 parameter WEIBULL FAILURE ANALYSIS

CHECK here to recalculate if failure data or "Minimum life" input value is altered

117000		50000
1181000		
1192000		
1193000		
1187000		
1189000		100000 100%
1207000		
1207000		60% 118000.700
1208000	e	
1220000	e	
1220000	e	

Calculated Outputs



NOTE: DOE 1 Group 2: 77PBL4-1 (no snap) w/ 0% water in brake fluid.

Figure 2.

2 and 3 parameter WEIBULL FAILURE ANALYSIS

CLICK here to recalculate if failure data or "Weibull fit" input values is altered



155418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8
185418	8

38000

100000 #RUM

6% #RUM

Calculated Outputs



NOTES: DOE 1 Group 1: 77P6L2-1 (w/ wrap) w/ Oils water in brake fluid.

Figure 2.

2 and 3 parameter WEIBULL FAILURE ANALYSIS



CLICK here to recompute if failure data or "Minimum life" input value is altered

10000	
12000	
15000	
18000	
22000	
27000	
32000	
38000	
45000	
52000	
60000	
68000	
78000	
88000	
100000	
115000	
130000	
150000	
175000	
200000	
225000	
250000	
275000	
300000	
325000	
350000	
375000	
400000	
425000	
450000	
475000	
500000	
525000	
550000	
575000	
600000	
625000	
650000	
675000	
700000	
725000	
750000	
775000	
800000	
825000	
850000	
875000	
900000	
925000	
950000	
975000	
1000000	

80000 6%

80 % 1077620810

Calculated Outputs





NOTES: DOE 1 Group 4: 77PBLA-1 (no snap) w/ 6% water in brake fluid.


Figure 2.

2 and 3 parameter WEIBULL FAILURE ANALYSIS

CLICK here to rerun analysis if failure data or "Database list" input value is altered		<input type="checkbox"/>
<input type="text" value="1187000"/>	<input type="text" value="300000"/>	<input type="checkbox"/>
<input type="text" value="1187000"/>		<input type="checkbox"/>
<input type="text" value="1187000"/>		<input type="checkbox"/>
<input type="text" value="1187000"/>		<input type="checkbox"/>
<input type="text" value="1187000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>
<input type="text" value="1307000"/>		<input type="checkbox"/>



NOTE: DOE + Group 3: 77P8L2-1 (w/ wrap) w/ 0% water in brake fluid.




3/30/99

1mV: 1psi

TI-NHT8A 014229

2/19/94
0950HRS




75% brake fluid solution
c 70 Top F.O

$P_{max} = 175 \text{ psi}$

T-NHTSA 014230

3/18/99
0945 HRS




100% brake fluid

1mV = 1psi

7-NHTSA 014231


3/15/99
Doc 0905



10% Brake

1 mV = 1 psi

TI-NHTSA 014232



3/18/99
Time 0915

5% H₂O (br)
95% brak, fluid




1-1



1-1
2-1 (10x)




1-1





TI-NHTSA 014234

Hazport Current vs. Time
Noryl BASE_1 5% Salt Water Ingress Experiment




TI-NHTSA 014235

**DRAWINGS AVAILABLE UPON
REQUEST**

7-18-99

LF1


7.0



TIANHTBA 01A237


7-19-99

LF2



TI-NHTSA 014238

LF3



TI-NHTSA 014239

7-19-59


LF 4



7-19-98


LF5

TI-NHTSA 014241



7-16-99

LF 96




2.574242
cm

.001/cm

LF7

Ind Plot in Rad was able to get some
negative movement.


TJ-NHTSA 014243



LF8


RANGES	4.500V	10.00V	2.500V
OFFSETS	0.0V	0.0V	0.0V
TOTAL TIME	1.00S		
POST-TRIG	0.0S		
TRIGGER	MAN		

TI-NHT9A 014244




LF9

TJ-NHTSA 014245




LF 10

TJ-NHTSA 014240




LF 11

TI-NHTSA 014247




LF12

TI-NHTBA 014248




LF 13

TI-NHTSA 014249




LF 14

TI-NHTSA 014260




LF15

TI-NHTSA 014261



LF16



TI 77PS Test Synopsis Draft 7/22/99

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

Level 1 Objective: Determine if a switch ignition can be created in the laboratory.

- **Test 1**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H₂O.
14 volts applied to one terminal, second terminal electrically floating.
(No electrical load across switch terminals).
Switch harness electrically grounded.

Results:

- (8) samples were tested total:
- (2) with 4% H₂O in brake fluid.
- (2) with 6% H₂O in brake fluid.
- (2) with 10% H₂O in brake fluid.
- (2) with 75% H₂O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

• **Test 2**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.
14 volts applied to one terminal, second terminal connected to a 14 Ω resistor which is tied to ground. (1 Amp load across switch terminals).
Switch housing electrically grounded.

Results: (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

Conclusion: A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• **Test 6**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.
Power applied to the heater element until plastic base melts.
Spark generated in contact cavity of switch.
Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

Results: (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Conclusion: A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.
5 watts of power dissipated in heating element.
Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

Level 2: Objective: Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

• **Test 6a**

Objective: Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

Results: (1) out of (15) samples tested increased resistance to 5Ω . A solution of 5 wt. % NaCl in H_2O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H_2O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

Conclusion: A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H_2O is injected into contact cavity of a switch.
Continuous 14 Volt power applied to the switch.
Hexport is grounded.
Current is limited at 15 Amps.

• **Test 6c**

Objective: Determine if brake fluid with metal shavings is conductive enough to create an ignition.

Results: (3) devices with various size metal particles were tested. No significant current increase detected.

Conclusion: Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• **Test 7**

Objective: Determine if switch meets cycle life specification.

Results: Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

occurred at 725,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

Conclusions: Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

Objective: Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

Results: Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

Conclusion: Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

Objective: Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

- Contact cavity of switch flooded with new brake fluid.
- Switches at continuous 14 Volts power.
- Switches subjected to vibration for (1) hour per day.
- Switches subjected to 100°C for (1) hour per day.

Results: Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

Conclusion: New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power

Level 3: Objective: Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H₂O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current versus time show an increase in current until the point of ignition.

Conclusion: A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H₂O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

Level 4: Objective: Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

Objective: Compare various fluids in the established ignition method.

Results: The following fluids were tested.

- (1) NaCl in H₂O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H₂O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H₂O

The switch filled with 5 wt. % NaCl in H₂O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps leakage current draw and showed no signs of corrosion over the (24) hour test.

Conclusion: Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its significantly higher conductivity, an ionic rich fluid such as NaCl in H₂O is necessary to cause an ignition.

• Test 15

Objective: Compare the ignition characteristics of various plastics as switch base material.

Results: When 5 wt. % NaCl in H₂O was injected into switches with different base materials, the following results were obtained: Collmax 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusion: All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

Objective: Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

Results: Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

Level 5 Objectives

Test 16

• Objective: Test proposed relay circuit.


Results: (1) switch was injected with a solution of 5 wt. % NaCl in H₂O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for 18 hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.



77P84-1 LEAKY SWITCHES ANALYSIS

AVE IN	stdev.	AVE OUT	stdev.	AVE TOT.	stdev	Delta	stdev.
0.1824	0.0003	0.1832	0.0002	0.1828	0.0005	0.0018	0.0008
0.1823	0.0003	0.1830	0.0002	0.1829	0.0006		
0.1825	0.0004	0.1829	0.0003	0.1827	0.0004		
0.1824	0.0003	0.1830	0.0003	0.1828	0.0005		
0.1830	0.0004	0.1828	0.0003	0.1829	0.0006	0.0018	0.0008
0.1830	0.0005	0.1828	0.0005	0.1829	0.0007		
0.1831	0.0008	0.1829	0.0004	0.1830	0.0007		
0.1830	0.0004	0.1829	0.0003	0.1829	0.0006		
0.1831	0.0001	0.1836	0.0003	0.1833	0.0003	0.0012	0.0004
0.1831	0.0002	0.1837	0.0002	0.1834	0.0004		
0.1830	0.0002	0.1836	0.0002	0.1833	0.0004		
0.1831	0.0001	0.1836	0.0003	0.1834	0.0004		
0.1827	0.0003	0.1829	0.0002	0.1828	0.0003	0.0023	0.0004
0.1826	0.0002	0.1829	0.0002	0.1827	0.0004		
0.1826	0.0003	0.1830	0.0003	0.1828	0.0005		
0.1828	0.0002	0.1829	0.0003	0.1828	0.0004		

77P84-1 FROM PRODUCTION LINE ANALYSIS

AVE IN	stdev.	AVE OUT	stdev.	AVE TOT.	stdev	Delta	stdev.
0.1838	0.0003	0.1844	0.0003	0.1841	0.0006	0.0018	0.0008
0.1837	0.0003	0.1844	0.0001	0.1841	0.0006		
0.1838	0.0003	0.1844	0.0002	0.1841	0.0005		
0.1838	0.0002	0.1844	0.0003	0.1841	0.0006		
0.1838	0.0002	0.1843	0.0002	0.1841	0.0003	0.0014	0.0008
0.1841	0.0002	0.1848	0.0002	0.1844	0.0004		
0.1838	0.0003	0.1841	0.0001	0.1838	0.0005		
0.1838	0.0003	0.1844	0.0005	0.1841	0.0006		
0.1831	0.0003	0.1834	0.0003	0.1833	0.0003	0.0028	0.0004
0.1828	0.0002	0.1830	0.0002	0.1829	0.0003		
0.1828	0.0002	0.1829	0.0002	0.1828	0.0003		
0.1828	0.0003	0.1831	0.0005	0.1830	0.0004		

TYPE 2-1 FROM THE LINE ANALYSIS

AVE IN	stdev.	AVE OUT	stdev.	ave lot	stdev	Delta	stdev.
0.1880	0.0006	0.1888	0.0003	0.1883	0.0007	0.0031	0.0007
0.1848	0.0004	0.1887	0.0004	0.1882	0.0007		
0.1881	0.0004	0.1880	0.0004	0.1885	0.0008		
0.1848	0.0004	0.1887	0.0007	0.1883			
				0.0087			
0.1888	0.0008	0.1888	0.0004	0.1888	0.0008	0.0031	0.0008
0.1887	0.0006	0.1888	0.0004	0.1888	0.0009		
0.1887	0.0003	0.1882	0.0001	0.1888	0.0008		
0.1888	0.0004	0.1887	0.0006	0.1887			
				0.0008			
0.1888	0.0002	0.1888	0.0002	0.1884	0.0007	0.0031	0.0008
0.1881	0.0002	0.1887	0.0002	0.1884	0.0008		
0.1880	0.0002	0.1887	0.0002	0.1883	0.0008		
0.1880	0.0002	0.1887	0.0008	0.1884			
				0.0088			

DOE1

1,120,428

+204,000

1,324,428

GROUP:
DESCRIPTION:

G1
77PSL2-1 (w/ snap, 0% water)

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			
G1-			

Start 2/24/99

→ No Leaks

GROUP:

G2

DESCRIPTION:

77PSL4-1 (no snap, 0% water)

DEVICE #	CYCLES (K)	FORD LOAD APPLIED (Y/N)	LEAKAGE MODE
G2-	1,175	Yes	
G2-	1,181	Yes	
G2-	1,192		
G2-	1,193		
G2-	1,197		
G2-	1,199		
G2-	1,199		
G2-	1,207	Yes	
G2-	1,207	N	
G2-	1,324		
G2-	1,324		
G2-	1,324		

TI-NHTSA 014284

GROUP:
DESCRIPTION:

G3
77PBL2-1 (w snap, 5% water)

DEVICE #	CYCLES (S)	FOND LOAD APPLIED (Y/N)	LEAKAGE MODE
03	1199	✓	
03	1199	-	
03	1199	-	
03	1199	-	
03	1201	-	
03	1207	✓	
03	1207		
03	1207		
03	1207		
03	1207		
03	1207		
03	1207		
03	1207		
03	1207		
03	1207		

DOE1 77PSL2-1 AND 77PSL4-1

Sample	ppm H2O	ppm H2O	ppm H2O	Avg	Std Dev	%RSD	Wt % H2O
Clean	2829	3900		3065			0.31
Caliper	11289	11328	11054	11221	118.76	1.19	1.11
Mixer	11888	11008	11288	11301	294.01	2.84	1.13
Cylinder #1	7794	7443	7488	7605	198.48	1.98	0.75
Cylinder #2	27102	28583	26785	26707	298.67	3.60	2.82
Reference*	4085						0.41

should be same as clean sample

should be 5%

reference cor takes 0.38 to 0.42 % H2O

Fluid samples taken at the end of the test

TH-NHTSA 014288

DOE-1

Test Log


Start	2-26		
200K	3-1		
289K	Failure	5%	3-2
328K	Failure	5%	3-2
325K	"	"	"
335K	"	5%	3-2
348	"	"	3-2
376K	"	"	3-3
380K	3 Failures	5%	3-3 (2 Powered Switches)
387K	Failure	5%	3-3
1,175K	Failure	0%	3-8
1,181K	"	"	3-9
1,192K	2 Failures	"	3-9
1,197K	3 Failures	5%	3-9
1,198K	1 Failure	0%	3-9
1,199K	2 Failures	0%	3-9 @ 5:00
1,199K	1 Failure	5%	
1,201	5% Stop Failure		
1,207	4 5%	5%	

77ps_partlist.xls

77PS part differences.

	77P82-1	77P83-1	77P84-1	
description	part number	part number	part number	EFFECT
CLIP	27713-1	27713-1	27713-2	Spacer seat to bump height 4/1000 lower on -1 than on -2
EXPORT	38880-1	38880-1	37887	4-1 C-Bore is .330 (.13 deeper than 2-1)
DISC	38888-27	38888-38	38888-35	-38 measured height = .0275 +/- .0003"
	(OR) 38888-38	38888-41	38888-41	-41 measured height = .0281 +/- .0003"
				-27 measured height = .0288 +/- .0003"
				-28 measured height = .0310 +/- .0003"
				Cross height on 4-1 are - 2/1000 to 4/1000 lower than 2-1 (measured)
base	48815-2	48815-3	48815-3	
DATE stamp	8288	7184	8048	

TLNHTSA 014288



1 - 77-8-1 - 1

TI-NHTSA 014269

Date
CROWN Height

12/3/99

Measurements

77PS62-1 : .027, .028
 " 3-1 : .035, .041
 " 4-1 : .035, .041

36656

77PS Discs

		CROWN	
36656 -27	1	.0297	1-2/22
	2	.0295	
	3	.0300	
	4	.0299	
	5	.0299	
-28	1	.0311	2/1000
	2	.0308	
	3	.0307	
	4	.0311	
	5	.0311	
-35	1	.0276	2/1000
	2	.0277	
	3	.0273	
	4	.0275	
	5	.0274	
-41	1	.0299	
	2	.0290	
	3	.0291	
	4	.0291	
	5	.0291	




Sample Cup

77A5L2-1

POE1

09/03/91

Decrimped (3) unused units
placed on spacer
→ zeroed on character



NO MARKS
NO MARKS
NO MARKS
NO MARKS

S1	1	2	3	4	5	6	7	8
	-.0030	-.0039	-.0018	-.0030	-.0031	-.0060	-.0037	-.0045
S2								
S3								



77A5L3-1



Slight pressure applied by
wobblie on cup

	H	1	2	3	4	5	6	7	8
SAMPLES DOWN		.1948	<u>.1947</u>	.1957	.1966	.1950	.1957	.1945	.1950
		.1944	.1946	<u>.1960</u>	.1942	.1952	.1951	.1952	.1962
		.1993	.1949	<u>.1961</u>	.1954	.1962	.1959	.1945	.1951
S2		.1953	.1949	.1954	.1953	.1952	.1956	.1962	.1965
		.1990	.1956	.1947	.1951	.1959	.1957	.1955	.1962
		.1990	.1953	.1956	.1958	.1968	.1956	.1961	.1957
S3		.1957	.1960	.1962	<u>.1978</u>	.1959	.1967	.1959	.1967
		.1970	.1962	.1965	.1962	<u>.1977</u>	.1958	.1963	.1960
		.1979	.1959	.1964	.1959	<u>.1967</u>	.1959	.1964	.1963
				<u>77A5L4-1</u>					
S1		.1938	.1953	.1933	.1938	.1936	.1939	.1941	.1997
		.1954	.1931	.1952	.1937	.1945	.1936	.1939	.1935
		.1954	.1936	.1947	.1942	.1949	.1937	.1940	.1939
S2		.1940	.1942	.1936	.1942	.1943	.1936	.1939	.1941
		.1954	.1944	.1930	.1940	.1944	.1943	.1942	.1941
		.1954	.1939	.1949	.1934	.1939	.1943	.1949	.1939
S3		.1929	.1932	.1934	.1927	.1931	.1939	.1935	.1970
		.1950	.1929	.1934	.1925	.1924	.1927	.1932	.1930
		.1950	.1927	.1930	.1926	.1922	.1928	.1930	.1930

bottom
wobblie
down

779524-1

DOE1

08/03/99

G4 measurement unringed

Converter



washer on



$\pm \frac{3}{10,000}$

converter measurements

weight
(1) Sample

K	H	1	2	3	4	5	6	7	8	avg	std
222	.1846	.0804	.0812	.0801	.0813	.0813	.0812	.0801	.0810	.0807	.0
349	.1844	.0801	.0814	.0805	.0815	.0809	.0815	.0805	.0814	.0805	.0
380	.1851	.0813	.0818	.0807	.0819	.0801	.0817	.0807	.0813	.0807	.0
335	.1844	.0808	.0809	.0819	.0814	.0813	.0817	.0805	.0809		
S1	.1892	.0850	.0850	.0850	.0850	.0849	.0849	.0849	.0845		
S2	.1874	.0844	.0851	.0844	.0844	.0844	.0844	.0844	.0849		

WASHER ON CONVERTER

washer on converter

K	H	1	2	3	4	5	6	7	8	avg	std
222	.1846	.1819	.1829	.1832	.1828	.1822	.1834	.1822	.1832	.1825	.0005
349	.1844	.1825	.1834	.1826	.1834	.1829	.1839	.1829	.1839	.1825	.0005
380	.1851	.1828	.1827	.1824	.1829	.1822	.1822	.1826	.1827	.1825	.0005
335	.1844	.1832	.1831	.1829	.1821	.1823	.1822	.1831	.1830	.1821	.0005
S1	.1892	.1870	.1877	.1862	.1863	.1868	.1867	.1860	.1875	.1871	.0005
S2	.1874	.1859	.1857	.1846	.1875	.1871	.1864	.1870	.1877	.1867	.0005

77P54-1 Leaks

0081

09/03/99

58

	H	I	J	3	4	5	6	7	8
<u>322</u>	.1946	.1922	.1930	.1927	.1934	.1924	.1933	.1924	.1930
	.1945	.1924	.1928	.1922	.1929	.1919	.1924	.1921	.1929
	.1946	.1923	.1932	.1926	.1932	.1922	.1929	.1923	.1929
<u>335</u>	.1949	.1927	.1922	.1926	.1919	.1934	.1938	.1932	.1933
	.1947	.1931	.1929	.1923	.1918	.1933	.1921	.1924	.1926
	.1949	.1933	.1931	.1929	.1915	.1932	.1931	.1924	.1926
<u>349</u>	.1945	.1931	.1936	.1931	.1937	.1930	.1938	.1930	.1929
	.1946	.1930	.1936	.1933	.1939	.1932	.1941	.1929	.1933
	.1945	.1931	.1937	.1928	.1934	.1930	.1932	.1932	.1939
<u>280-3</u>	.1950	.1925	.1931	.1926	.1926	.1924	.1924	.1928	.1924
	.1950	.1927	.1935	.1926	.1926	.1922	.1923	.1926	.1932
	.1950	.1927	.1932	.1920	.1926	.1924	.1924	.1922	.1926

|||||

|||||

|||||

|||||




←

2 1/2

77P5L4-1

10/3/79



POE V


	H	1	2	3	4	5	6	7	8
387	.1952	.1932	.1892	.1831	.1838	.1934	.1944	.1930	.1934
	.1951	.1932	.1939	.1934	.1941	.1937	.1829	.1931	.1938
	.1951	.1933	.1944	.1931	.1937	.1929	.1928	.1946	.1933

11111
 2222
 3333
 4444
 5555
 6666
 7777
 8888
 9999
 0000

TI-NHTSA 014274

F

G4 in Cup



322K convert to outside of disc Δ

- ⊕ → 322K
 - ① + 0.0012
 - ② + 0.0005
 - ③ + 0.0001
 - ④ + 0.0003
- } repeatable

- ⊖ → 350K
 - ① - .0003
 - ② - .0000
 - ③ - .0005
 - ④ - .0011
- } repeatable = .0002

- 399K
 - ① .0029
 - ② .0025
 - ③ .0032
 - ④ .0008
- } "

Had trouble duplicating results
is abandoned



02/23/99 SM

time 11:50

alt V	PS	V	U
		14.07	7100
25%		14.07	7100
		14.07	7100
		14.07	7100
5%		14.07	7100
		14.07	7100
		14.06	7100
		14.06	7100
10%		14.06	7100
		14.06	7100

16R

supply current limited



$$= \frac{V}{R}$$

02/22/99

SM

77AS salt + H₂O mix

(3) units	w/	2.5%	Salt/H ₂ O	mix
(3) units	w/	5%	Salt/H ₂ O	mix
(3) units	w/	10%	Salt/H ₂ O	mix

injected w/ mixtures 18:00



02/22/99

cup = 10.51 g

need 56.5 g of 5% mix = 2.925 g salt

$$\frac{2.925}{x} = .025 = 113 \text{ g}$$

113 g measured adding to water

71.9 g of 5% = 3.595 g salt

$$\frac{x \text{ g salt} + 113 \text{ g}}{(71.9 + x)} = .1 \quad | \quad 7.19 + .1x = x + 3.595$$

$$.9x = 7.19 - 3.595$$

$$.9x = 3.595$$

$$x = 3.99$$


$$\frac{3.99 + 3.595}{75.9}$$

initial
reading

% salt	v	u
2.5%		
3.5		
4.5		
5		
5		
5		
10		
10		
10		

TI-NHTSA 014278


1000 1000 1000 1000



1000 1000 1000 1000



TI-NHTSA 014278




021


ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

Polaroid 3 JB1479A10703A

572




573



TI-NHTSA 014261

TI-NHTSA 014262



Polaroid 3 J81479A1078JA

2 5 3