

EA02-025

TEXAS INSTRUMENTS, INC.'S

9/10/03

REQUEST NO. 7

BOX 9

PART A – R

PART K

Brake Pressure Switch Test Log, Updated 7/22/98

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Very water concentrations in 'new' Brake Fluid 14Vdc to one terminal, lampout grounded Water Conc: 4%, 5%, 10%, 20%	200+ hours. Current draw in the 0.5mA to 5mA range Field has discolored No significant temperature rise. Test Suspended. Internal Analysis suspended
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, lampout grounded	200+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Lampout Grounded	> 300 hours into test, max current 7mA No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Lampout Grounded, Ambient at 100 C	10 hours into test max current 6mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 10 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 80 Amps Through Switch Terminals	Temperature rose to approx. 275 F. No smoke. No ignition Test suspended.
	6	TI	Small heater elements into Switch. Heat oil bath, include sparking (1) wt solution of Brake Fluid and 5 wt. % H ₂ O	3 tested. Smoke observed, ignition observed on post oil-water See attachment Test complete Smoke still in cavity above device heat build-up Smoke observed at 675 F, 6000 volts and temp off at 800 F
	6a	TI	Crown heater by covering spring with salt water solution, 14V between spring and lampout	One out of 16 devices increased resistance to 5 ohms. Others either very low resistance or no response It took about 200 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	No-run ignition test to determine repeatability and current path.	Switch ignited with repeated 5% water solution into switch Current path is through lampout See photo and video. Additional test include tap water, old BF, new BF and other.

TI-NHTSA 014283

Brake Pressure Switch Test Log, Updated 7/22/09

	6c	TI	Pure 'new' brake fluid with metal shavings	Metal shavings do not contribute significantly to brake fluid conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psi pressure pulses at 130C per ES	First leak observed at 720,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psi pressure pulses at 130C.	Pain withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Control Labs	Field returns, from dealer lots, judgments	Pain in Control Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear Impulse test	10	TI	Very water concentrations in 'new' brake fluid 12 wrap + 12 quiet switches w/ 0 % water in air 12 wrap + 12 quiet switches w/ 1 % water in air	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess failure scenarios.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature of Switch Location for ABS and non-ABS braking events.	Test of AVT.....see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. UMC: Cu = 415 (ppm), Fe = 9.0 (ppm), Cr = 8.0 (ppm), 1.1 %H2O UCA: Cu = 502 (ppm), Fe = 6.5 (ppm), Cr = 1.0 (ppm), 1.7 %H2O NEW: Cu = <0.01 (ppm), Fe = 0.00 (ppm), Cr = <.01 (ppm), 0.5 %H2O
Spunk Acc Study	12	Control Labs	Determine if spunk-like forms in switch using clutch levers and high speed video. Use dry switches as well as switches with various brake fluid water mixes.	Equipment set-up in progress at Control Labs. TI Experimented with no 'significant' spunk observed
Characterization of switches retrieved from field analysis & other sources	13	Control Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Impact Tests	13a	TI	Repeat impact simulation with different fluids. (a) low tests: 0% NaCl in tap water rain water	Test complete. 0% NaCl sample resulted in no corrosion. All brake fluid samples show less than 3 wraps. No corrosion visible on brake fluid samples.

Brake Process Switch Test Log, Updated 7/22/98

			(24) hour tests:	Rain water and tap water samples show <18 mAmps and showed some signs of corrosion.
			tap water	
			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H ₂ O	
			new brake fluid	
			new brake fluid w/ 5% H ₂ O	
Design Of Experiments (2) Repeat of test 18	13b	TI	Tap water concentrations in 'new' Brake Fluid 30 amp + 28 quib solution w/ 5 % water in BF 30 amp + 28 quib solution w/ 5 % water in BF	Test suspended. Analysis in process to ensure test flowring.
Compatibility of Kapton with Sulfuric Acid	14	Discont	Characterize change in properties of Kapton with various % sulfuric acid in brake fluid.	Test in progress (100) hours completed. Oxidic acid shows similar effects that water has on Kapton padding.
Examination of Plastic Materials with Improved Performance	15	TI	Assess properties and suitability of different grades of plastic resin with addition to improve plastic part performance	Test suspended. Calsonic and Noryl tested 30S and 20S trials ZYTEL samples tested 18 quibrun
Long duration Brake fluid exposure test.	16a	TI	(1) samples with new brake fluid (2) samples with used brake fluid	Test suspended (100) hours completed. Used brake fluid cannot dropped off to <170 mAmp. New BF exposed current can increase w/ time under test power.
Examination of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test additional sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Standard switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	18	TI	Repeat test 13a in Ford relay circuit for (10) hrs. Using switch in impending ignition in (10) Amp circuit from place in relay circuit for (10) hrs. Repeat test, circuit power into breaker on switch.	Test complete. No ignition. Current rate steadily reduced. Insufficient power in circuit in worse or more toward ignition in 100 Heater element was warm to the touch.
Long duration brake fluid exposure test number 2.	17	TI	(10) samples that with new brake fluid (1) hour of oxidation per day (1) hour soak at 140 deg C per day	Test suspended. (100) hours completed. Average exposed current is 1.8 mAmp (standard deviation = 1.8 mAmps)

TI-NHTSA 014286

Data Code	Device	Source	Rate	Pin	Offset	Incoming	Vacuum	P.T.
8120	77-2					No Continuity	N/A	Pass
8102	77-3	0.048	0.0608	0.143	-0.0025	No Continuity	N/A	Pass
9095	77-4	0.0485	0.0601	0.143	-0.0025	Good	N/A	Pass
9093	77-5	0.04845	0.0614	0.144	-0.00285	No Continuity	N/A	Pass
9075	77-6	0.04825	0.0629	0.1448	-0.00355	Good	No Continuity	Pass
9099	77-7	0.0489	0.0612	0.144	-0.0031	No Continuity	No Continuity	Pass
9096	77-8	0.0487	0.0609	0.1435	-0.0031	Good	Intermittent	Pass
9095	77-9	0.0485	0.0605	0.1434	-0.0016	Good	Good	Pass
9096	77-10	0.04825	0.0604	0.1428	-0.00285	No Continuity	No Continuity	Pass
9096	77-11	0.0489	0.0614	0.1427	-0.0048	Good	No Continuity	Pass
9096	77-12	0.0625	0.0699	0.1422	-0.0072	No Continuity	Intermittent	Pass
9096	77-13	0.0492		0.1441		No Continuity	No Continuity	Pass
9095	77-14	0.0484	0.062	0.1436	-0.0048	No Continuity	Good	Pass
9042	77-15	0.0612	0.0696	0.1437	-0.0073	Good	Good	Pass
9088A	77-16	0.0493	0.0612	0.1437	-0.0058	No Continuity	No Continuity	Pass
8140	77-17	0.0471	0.0616	0.1417	-0.004	Good	Good	Pass
9088A	77-18	0.0518	0.0616	0.1417	-0.0085	No Continuity	No Continuity	Pass
9088A	77-19	0.0518	0.0698	0.1435	-0.0086	No Continuity	No Continuity	Pass

Pin - (Sec + Rev + A)

<u>Device</u>	<u>Sumner</u>	<u>Mass</u>	<u>Pin</u>	<u>Offset</u>	
1	0.0452	0.0902	0.14	-0.0024	
2	0.0453	0.0919	0.1413	-0.0039	
3	0.0453	0.0902	0.1407	-0.0028	
4	0.0452	0.0917	0.1411	-0.0034	
5	0.0453	0.091	0.1411	-0.0032	
6	0.0455	0.0923	0.1417	-0.0031	
7	0.0454	0.0915	0.141	-0.0039	
8	0.0508	0.0885	0.141	-0.0059	Kapton encapsulator
9	0.0455	0.0912	0.1409	-0.0038	
10	0.0454	0.091	0.1411	-0.0033	
11	0.0496	0.0913	0.141	-0.0071	Kapton encapsulator
12	0.0454	0.0911	0.1408	-0.0037	
13	0.0458	0.0918	0.1416	-0.003	
14	0.0475	0.0915	0.1424	-0.0036	
15	0.0458	0.0918	0.1417	-0.0029	
16	0.0457	0.0915	0.142	-0.0022	

LF

<u>Devion</u>	<u>Sensor</u>	<u>Pressure</u>	<u>Mass</u>	<u>Pto</u>	<u>Offset</u>	
1	0.0452	0.0455	0.0902	0.14	-0.0024	-0.0027
2	0.0453	0.0464	0.0919	0.1413	-0.0039	-0.004
3	0.0453	0.0456	0.0902	0.1407	-0.0029	-0.0031
4	0.0456	0.0462	0.0917	0.1411	-0.0034	-0.0036
5	0.0463	0.0466	0.091	0.1411	-0.0032	-0.0035
6	0.0455	0.0458	0.0923	0.1417	-0.0031	-0.0034
7	0.0484	0.0487	0.0915	0.141	-0.0039	-0.0042
8	0.0508	0.0487	0.0885	0.141	-0.0033	-0.0012 Kapton snap/rattler
9	0.0465	0.0466	0.0912	0.1409	-0.0038	-0.0041
10	0.0464	0.0487	0.091	0.1411	-0.0033	-0.0036
11	0.0468	0.0484	0.0913	0.141	-0.0071	-0.0037 Kapton snap/rattler
12	0.0464	0.0466	0.0911	0.1408	-0.0037	-0.0039
13	0.0459	0.0482	0.0918	0.1416	-0.003	-0.0034
14	0.0475	0.0484	0.0916	0.1424	-0.0036	-0.0025
15	0.0459	0.048	0.0918	0.1417	-0.0029	-0.0031
16	0.0457	0.048	0.0915	0.142	-0.0022	-0.0025

Customer Returns			
Switch ID	Atmosphere	Vacuum open (in. of water)	Atmosphere
11	closed	13.00	11.50
12	closed	closed *	closed
13	closed	11.00	8.50
14	closed	8.00	7.50
15	closed	closed *	closed
16	closed	7.50	6.50
Average:		9.88	8.78
STD		2.21	2.22
MAX		13.00	11.50

Procedure:

- 1) Subject switch to 60psig.
- 2) Check cont at atmoc pressure.
- 3) Subject to vacuum.
- 4) Record vacuum pressure at cont loss.
- 5) Decrease vacuum and record pressure at cont.
- 6) Measure cont at atmoc pressure.

* max vacuum of 29.9 inches achieved.

Line Pullout			
Switch ID	Atmosphere	Vacuum open (in. of water)	Atmosphere
LP1	closed	15.00	15.00
LP2	closed	13.00	10.50
LP3	closed	12.50	11.50
LP4	closed	14.50	13.50
LP5	closed	12.00	8.00
LP6	closed	13.00	11.50
LP7	closed	23.00	20.00
LP8	closed	closed*	closed
LP9	closed	11.00	8.00
LP10	closed	9.00	6.00
LP11	closed	14.00	OPEN
LP12	closed	23.00	21.00
LP13	closed	14.00	10.00
LP14	closed	28.00	14.00
LP15	closed	27.00	25.00
LP16	closed	30.00	19.00
Average:		16.67	14.04
STD		6.16	5.56
MAX:		30.00	25.00

"STUDY" OF THE PROCESS

- WHAT COULD CAUSE A FIRE
- CAN LEAKAGE SOURCE FLUID
- HIGH RAMP → SOU F-SYSTEM
- O₂ → ILLUMINATION
- SPARK

→ H₂O → CONVERSION → HEAT → MELT RATIO

→ SOURCE OF POWER

- H₂O
- CHEMICAL
-

[Power -

[

[

CY 91

CY 92

CY 93

Disc Δ_i \leftarrow

PLASTIC Δ_i $\left\{ \begin{array}{l} \text{GENERAL} \\ \text{CLEARER} \end{array} \right.$

GTX 830

EQUIVALENT?

46415
BASE
H574

QUIET → L3-1

SNAP → L2-1

PARTIC



TI-NHTSA 014293

3

- Another) . Penus → Ground. w/ LEAK

DOCUMENTED DOW STATE PARK
OLD BRAKE FLUID - INHIBITORS -
WILL CORRODE METALS -
- USE OLD FLUID?

93 TOWNS CAN SAMPLES

PROVIDE TOUGH TO LIVE AT
BF

PLASTIC PROPERTIES 2 U
ENTER

MINIMUMS VEHICLE

EXILAD / SUICIDE

??
Goli

↓

→ TUBE
CANT
PARENTS

OXALIC ACID

(2)

LA Anion — m/c Thermo

Can wash SPD. Purify

OXALIC ACID — Purify

PHOSPHATE WASHES FOR m/c

MAYBE CAN WASH WITH

MAYBE INTO OXALAN Thermo

Process

Sci Measurement — Test Area m/c —

FOIL Lined SIFT — Ba Hydroxide —
SLURRY SEMS NOT MEMPHIS
REIN FORCE TESTS N. LATENT SAMPLE?

JOB WORK → STA → ELECTRICAL

- FIELD
- LAB IMPROVEMENT
- FROM IMPROV

FFF - MDCRN

C/A - TRAINING

CONC MGT

- FINEST
- JURAZ

IPDs
PLANS

REPAIRS

COACHING

TRAIN COMMUNICATION

TI-NHTSA 014297

were seen @ cycles
@ events

12/100
12/100

5

QUANTITATIVE WAY TO
CHARACTERIZE ~~THE~~ ~~SYSTEM~~

VEHICLE HISTORY

~~LIST OF ~~ITEMS~~~~

~~FI~~

What happens to the contacts with
high current contacts
C-100 in speed

**DRAWINGS AVAILABLE UPON
REQUEST**

TI-NHTSA 014304

McGuirk, Andy

From: ~~Rahman, Ash~~
Sent: ~~Thursday, February 11, 1999 11:55 AM~~
To: **70** McGuirk, Andy; Beringhaus, Steven; Baumann, Russ; Dague, Bryan; Douglas, Charles; Sharpe, Robert; Sullivan, Martha; Rowland, Thomas; Baker, Gary **RAHMAN, Ash**
Subject: 77PS Day 2, 2/10/99 Summary

Day 2, 2/10/99 Highlights

Main event of the day was a team meeting to prep for the Executive Technical Review on 2/11. Joe Nemi of Large Vehicle Safety Group led the meeting. There were a lot of participants, including Fred Porter, Tom Masters from Engineering, Norm LaPointe AVT Design Analysts, Steve LaRouche from CRL, Ford legal folks, wiring, connector etc. TI was the only supplier represented.

TI is not invited to the Tech Rev. (whew?!)

Tech Rev will be a high level, broad overview of Town Car Underhood Fires Numbers Joe has thus far:

149 Underhood Fires, Thermal Anomalies, Thermal Events

39 with engine off, 9 with engine on, no information on the rest

5 possible related to the Brake Pressure Switch (BPS), 17 potential other root causes, no information on the rest

Other root causes from above line: 42 way connector, EEC wire harness, Relay pack.

At this point NHTSA response required on BPS, F2VC part only. Others may follow

Lengthy discussion on approach for the review. General consensus that presentation from technical side should be broad based, since sufficient info is not available for any deep dive.

General consensus that we need a lot more parts back from the field that were involved in these events. Cost message discussed.

Someone inquired about TI answers to questions from last meeting. I responded that I had provided the information to Fred and Steve Raimers, and they acknowledged. Two other questions for TI:

Does TI sell the switch directly to aftermarket, like auto part stores. I replied that most probably not. We

would go through Ford Service Parts for service parts. **Is that accurate Charlie?**

Does TI have fire experts on site who can determine origin of fires, as in experts who work on structural fires. I replied in the negative, but said I would follow up. Any inputs? Intent was to answer repeatedly asked question: Do we know where the fire originated. Outside - in, inside - out, what burned first, brake fluid, or plastic base??

Joe's meeting was followed by a vigorous brainstorming session with Fred, Tom, Norm, Steve & Lea. This was all technical and I actively participated.

I reviewed TI report PS/98/14 on wetbulb life of quiet switch showing first leak at 900k+ cycles. Gave copy to Norm.

Bryan, need wetbulb data quickly on pass-car snap switch.

I reviewed our finding that the 92 through 97 Town Car, Grand Marquis, Crown Vic platforms had prop valve mounted switches and that in vehicles with ABS option, the prop valve is located downstream of the ABS module.

There was considerable discussion on pressure profile at such a location with Len saying that the switch probably sees full pressure reversals. We agreed that I would contact Teves for more info.

We discussed formation of electrolytic cell with Brake Fluid in the base cavity, and how a low resistance path to ground could be formed. Discussed the wattage available with a 15A fuse and 14Vdc system. Is that sufficient to generate enough heat through the ground path.

Discussed CRL analysis of Memphis part, and gave copy of AI's report to Norm. Bryan, per Norm, AI retained "spoonfuls" of the corrosion residue. Do you know if AI has done any compositional analysis (IR) as opposed to elemental only?

Kept getting back to source of fire. Ford has not yet been able to create a fire in a switch. Team decided that pulling in Dow Chemical was key to understand if we can create a fire with given constraints.

I will start exposing the resistivity test here to temperature 2/11.

to Lewis

TEVES - Pressure wave @
Pump valve

WE CAN DESIGN AN IMPROVED
SWITCH

intent of testy process

TEVES - Pressure wave @
Prop wave

WE CAN DESIGN AN IMPROVED

SWITCH

w/ out a fishy process

currently pending contract
get test data -

W95

- C&E diagram
 - try to joint the brake fluid
 - plastic
 - letter #1 - e-mail
 - letter #2 over view e-mail
 - (C&E?) ←
- focus on 2 ways 100°C 0.1 m@
f part w @ fwd. on...

my 39 - No B&E for 2014

3 switches from Dunxianos
(TERMS?) which do NOT show
SIGNS OF ELECTRICAL OPERATION

~~Q~~ IS THIS SOMETHING NEW?

~~A~~ CONTRIBUTION THEN CAN
SEEK
CONCLUSION

~~A~~ RUBBER BOOT AROUND
CONNECTION BODY.....

— WISH WE COULD HAVE
EXTRA INSULATION IN SWITCHES

~~A~~ FUSE / LIMIT ELECTRICITY ✓

~~A~~ — FIRE RESISTANT / H temp ✓

8/2/99

Derivatives

DUPONT'S KNOWN INFO] - Steve/Andy - IP
TOP / WEBS

Higher MELT Temp] ← Bryan -] Weir
KORAN -]

Higher IGNITION Temp]

* INSULATE CUP] - MEMO TO FIND 40 Andy
DERIVATIVE UPPER / FORWARD

TEST OXALIC ACID] - Steve/Andy/A
10 AM -

* CONNECTION BODY] - ?? WHAT DID THEY DO?

OOD P/S ... JUNKYARD?] H2O INTO
CONNECTION BODY ...
25-35 - Ω

- OBTAIN BATTERY W/O INHIBITORS - Andy

QUIET / SPD SWITCH -] WITH WTS
92 93 SUPPLY CHAIN?
- Andy

IMPROVED LIFE SWITCH DEVICE] - ERIC

* ELIMINATE GROUND] - Andy
HOSE IDEA ← DIRECT
ELECTROLYSIS

* CURRENT LIMIT TO 3KA] - Andy
& OFF POWER PROVISION

Stack notes
Shows balance of
current items - Spring
future?

TI Looking into
Good on this -

TI Cause?
or something?
- No - not that
thinking that
- No 10 B\$
CLOVO
BANKING
- BUILT TO
8% - 22C
50% -
PARTS

- PUE SWITZ

- EXTENSION -

- HOW SWITCH INVENTION

- BRACE POINT

Other things
CAUSING INVENTION
FINET @ FOND

CONNECTION - ?

- NOT ONLY CONNECTION

13 G deceleration a few can
foot pressure - FLUID PRESSURE
- SEV SW TAIL SWAP
- PRESSURE PROTECT SWAP

300 PSI NORMAL STOP

MEMPHIS - MAX CONTACT
BROKER

PRICE CUT - SPAIN BROKER

BRAND FLOOR - COMPANY &
BANK OF

CAUSES LOW RESISTANCE TO GROWTH
(NOT CONTACT)

1800 OFF 18/F - 17/11/17

MERT - 16/11/17

-
- ✓ 18
 - ISOLATE FROM GROUND
 - NO KNOWN POTENTIAL < 500V?
 - 10 NEG CONNECTION BATH
 - CURRENT LIMITING?
-

DEC

TJ-NHTSA 014916

Dow - USE OLD FLUID.....

- W/O RUST INHIBITORS

↳ BANNER

USE FINE RETARDERS PLASTIC FOR SWITCH HEADS....

IMPROVED LIFE -

INSURATIVE CUP

- RETARDERS / LAMINATE

IMPROVING
LOR

- CONE / WOODS

OXALIC ACID

WED

MELT TEMP
GE FINE RETARDERS

INSULATE CUP

CHLORIDE TO B/F

ESTIMATES INHIBITORS

- SWITCH CAN CONTAIN

- 020, NO REST INITIATIONS

- PART N GROWS...

F

"BB"

1280A

91 280A

BROWN
NATURAL

313 845 3722

SWAMP
QUIET



TI-NHTSA 014320


	1			2			3			w/connector			w/o connector			TOTAL		
	F	K	C	F	K	C	F	K	C	F	K	C	F	K	C	F	K	C
group 1	2	2	2	2	2	2	2	2	2	5	7	7	5	7	7	5	7	7
1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1	2	2	2	2	2	2	2	2	2	9	9	9	9	9	9	9	9	9
1	2	2	2	2	2	2	2	2	2	0	0	0	2	2	2	2	2	2
1	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
TRG	8	15	8	8	8	8	9	9	9	21	25	21	8	8	8	29	33	32
group 2	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0
1	2	2	2	2	2	2	2	2	2	2	2	2	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
TRG	11	15	8	8	8	8	9	9	9	4	4	4	7	8	5	11	12	12
group 3	0	0	0	0	0	0	0	0	0	2	2	2	1	0	2	1	0	2
1	2	2	2	2	2	2	2	2	2	0	0	0	2	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	2	2	2	2	2	2	2	2	2	0	0	0	1	2	2	2	2	2
1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0
1	2	2	2	2	2	2	2	2	2	3	4	5	6	4	5	6	5	6
1	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	1	0	0
1	2	2	2	2	2	2	2	2	2	5	6	6	5	6	6	5	6	6
TRG	11	15	8	8	8	8	9	9	9	10	11	14	7	8	8	17	19	22

F: fluid side
 K: Kapton
 C: converter side
 Kapton 1: fluid
 Kapton 2: middle
 Kapton 3: converter

group 1: virgin parts
 group 2: live vacuum
 group 3: Rapid vacuum


Scores:
 1 = delam & holes
 2 = Cracks/Leaks (minor)
 3 = Cracks/Leaks (major)

*A minor crack/leak covers less than ~30% of perimeter



* = w/ connector L = leaked

TI-NHTSA 014323

Burn Test :Procedure :

- ① Measure R_b w/Power disconnected.
- Terminal to Terminal
- ② Fill w/5% solution
- ③ Record all (A)
- ④ Record Temperature
- ⑤ Run till Dry (2-5 hours?)
- ⑥ Go to ① until loss of contact or Thermal Event

Objective :

- ① Determine where the current goes.
- ② Start a Thermal Event.


Repeat w/ old Dirty Break Fluid

1st attempt

8/8/79

Test # 8

Device Filled with 5% salt/water solution and connector cavity dried
 Temp. cycle method used to fill device



14.5 VDC

100 AMP = 100 MV shunts used for tests

Readings every 2 min.



	Meter 1 line IN		METER 2 current to ground		Meter 3 clutch coil		Temp. °F
0	.8		.2		.6		83.9 °F
1	1.2		.7		.5		113.3 °F
2	1.4		1.0		.5		130.7 °F
3	1.2		.7		.5		127.6 °F
4	1.3		.8		.5		123.4 °F
5	.9		.4		.5		117.8 °F
6	.9	Cavity (dry)	.4	Refilled	.5		113.6 °F
7	.7		.3		.5		89.6 °F
8	1.6		1.0		.4		109.2 °F
9	1.4		.9		.4		118.7 °F
10	1.0	Cavity	.6	Refilled	.4		123.4 °F
11	1.3		.9		.5		100.8 °F
12	1.1		1.3	Contact ARM	.0	Failure	136.0 °F

Start of Terminal event shown, smoke started coil Pulled in
 smoke stopped coil DROPPED out smoke Puff and amps DROPPED off
 to .1 to ground o coil TEMP 146° F

Kept test going, Refilled Device

①	②	③	Temp
.7	.4	.0	control INTAKE Hd
1.1	.6	.5	coil IN 113.5° F
.7	1.1	.9	" " 120.1° F
.4	0	.4	" " 133.1° F
	DEVICE Filled		

DEVICE REMOVED FROM TEST FOR CONTACT ARM INSPECTION

Summary:

Found TEARINGS LEADING FROM TERMINAL to TERMINAL This could be
 a possible CURRENT LEAK PATH
 Post test disassembly showed that contact arm was NON-EXISTENT

Test #8

Abstract

The purpose of this experiment was to corrode contact terminals of 77PS switches in an attempt to cause ignition when power is applied to the switch

Procedure

The contact cavity of a switch was filled with a 5% salt/ water solution.
A power source was connected to terminal 1 of the switch

Meter 1 measured the current supplied to terminal 1 of the switch.

Meter 2 measured the current traveling to ground through the aircraft body

Meter 3 measured the current from terminal 2 of the switch through the Ford clutch assembly (inductive load)

Time (minutes)	Meter 1	Meter 2	Meter 3	Temperature (°F)
0	.8	.2	.6	83.9
2	1.2	.7	.5	113.3
4	1.4	1.0	.5	130.7
6	1.2	0.7	.5	127.6
8	1.3	0.8	.5	123.4
10	0.9	0.4	.5	119.8
12	0.9	0.4	.5	113.6
14	0.7	0.3	.5	84.6
16	1.6	1.0	.4	109.2
18	1.4	0.9	.4	118.7
20	1.0	0.6	.4	123.4
22	1.3	0.9	.5	100.8
24	1.4	1.3	0	136

Brake Pressure Switch Test Log, Updated 08/10/1999

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Vary water concentrations in 'new' Brake Fluid 14Vdc to one terminal, heqport grounded Water Conc: 4%, 6%, 16%, 75%	250+ hours, Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	New Brake Fluid 1 Amp through switch terminals 14Vdc to one terminal, heqport grounded	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heqport Grounded	> 300 hours into test, max current 7mA No significant change with time. Test suspended
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heqport Grounded, Ambient at 300 C	66 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps. through Switch Terminals	Temperature rose to approx. 279 F. No smoke. No Ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat all failure, include opening. (1) w/ solution of Brake Fluid and 8 wt. % H ₂ O	3 tested. Smoke observed, Ignition observed on part w/ water See attachment Test complete Brake fluid in cavity slows down heat build-up Smoke observed at 675 F, Base melts and falls off at 636 F
	6a	TI	Create heater by connecting spring and Salt water solution, 14V between spring and heqport	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or megohms. It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run Ignition test to understand repeatability and current path.	Switch Ignition with repeated 5% water solution into switch Current path is through heqport. See plots and video.
	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid

T-NHTSA 014328

Brake Pressure Switch Test Log, Updated 06/10/1999

				conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per ES	First leak observed at 726,000 cycles. Test Completed. See attached Weibull Chart.
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Central Labs	Field returns, from dealer lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear pulse test	10	TI	Vary water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 8 % water in BF 12 snap + 12 quiet switches w/ 5 % water in BF	Test Report being written investigation continues. Suspended at 1.3 million cycles with no leaks observed. Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess factory anomalies.
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT....see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (LMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. LMC: Cu = 415 (ug/ml), Fe = 5.8 (ug/ml), Cr = 0.08 (ug/ml), 1.1 %H2O. UCA: Cu = 592 (ug/ml), Fe = 5.5 (ug/ml), Cr = 1.9 (ug/ml), 1.1 %H2O. NEW: Cu = <0.01 (ug/ml), Fe = 0.92 (ug/ml), Cr = <0.01 (ug/ml), 0.3 %H2O.
Spent Arc Study	12	Central Labs	Determine if arcing forms in switch using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water mixes.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field junkyards & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Fluid Ingress Tests	13a	TI	Repeat ignition simulation with different fluids. (3) hour tests: 5% NaCl in tap water rain water (24) hour tests: tap water used brake fluid	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples draw less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples draw <10 mAmps and showed some signs of corrosion. Chemical analysis in process.

TI-NHTSA 014330

Brake Pressure Switch Test Log, Updated 08/10/1988

			used brake fluid w/ 5% H ₂ O	
			new brake fluid	
			new brake fluid w/ 5% H ₂ O	
Design Of Experiments (2) Repeat of test 18	13b	TI	<p>Very water concentrations in 'new' Brake Fluid</p> <p>10 amp + 20 quiet switches w/ 5 % water in BF</p> <p>10 amp + 20 quiet switches w/ 5 % water in BF</p>	Test suspended. Analysis in process to assess test filtering.
Compatibility of Kapton with Oxalic Acid	14	Dupont	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Test in progress (100) hours completed. Oxalic acid shows similar effects that water has on Kapton properties.
Evaluation of Plastic Molecules with Improved Formulations	15	TI	Assess properties and moldability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Colonac and Meryl tested 3/5 and 2/5 tests ZYTEL samples tested 1/5 ignitions
Long duration brake fluid ignition test.	15a	TI	<p>(4) samples with new brake fluid</p> <p>(2) samples with used brake fluid</p>	<p>Test suspended (550) hours completed.</p> <p>Used brake fluid current dropped off to <1/10 mAmp.</p> <p>New BF hexport current can increase w/ time under cont. power.</p>
Evaluation of Switch Orientation	15b	TI	<p>Assess ignition sensitivity to switch orientation.</p> <p>Test vertical versus 45 degree.</p> <p>Test rotational sensitivity in 45 deg. orientation.</p>	<p>Test complete. Ignition is independent of switch orientation.</p> <p>Simulated switch ignition can occur in vertical or 45 degree angle.</p> <p>Ignition appears not sensitive to switch rotational alignment.</p>
Relay Circuit Test	16	TI	<p>Repeat test 13a in Ford relay circuit for (48) hrs.</p> <p>Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (18) hrs.</p> <p>Input max. circuit power into heater on switch.</p>	<p>Test complete. No ignition. Corrosion rate drastically reduced.</p> <p>Inadequate power in circuit to create or expose toward ignition in lab.</p> <p>Heater element was warm to the touch.</p>
Long duration brake fluid ignition test number 2.	17	TI	<p>(50) samples filled with new brake fluid</p> <p>(1) hour of vibration per day</p> <p>(1) hour soak at 100 deg C per day</p>	<p>Test suspended. (312) hours completed.</p> <p>Average hexport current is 1.9 mAmp (std deviation = 1.8 mAmp)</p>

TI-NHTSA 014331

TI 77PS Test Synopsis

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a laboratory switch ignition without any restrictions on methods.
- Level 2: Create a laboratory switch ignition using only conditions found in the switch operating environment.
- Level 3: Understand the laboratory ignition mechanism.
- Level 4: Compare factors contributing to laboratory ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

Level 1 Objective: Determine if a switch ignition can be created in the laboratory.

- **Test 1**

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact cavity flooded with brake fluid mixed with varying amounts of % H₂O.
14 volts applied to one terminal, second terminal electrically floating.
(No electrical load across switch terminals).
Switch hexport electrically grounded.

Results:

- (8) samples were tested total:
- (2) with 4% H₂O in brake fluid.
- (2) with 6% H₂O in brake fluid.
- (2) with 10% H₂O in brake fluid.
- (2) with 75% H₂O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 014332

• Test 2

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.

14 volts applied to one terminal, second terminal connected to a 14 Ω resistor which is tied to ground. (1 Amp load across switch terminals).
Switch hexport electrically grounded.

Results: (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

Conclusion: A (1) Amp load through switch terminals cannot ignite brake fluid in the contact cavity of switches.

• Test 6

Objective: Determine if switch ignition can occur under the following laboratory conditions:

Heater element installed in contact cavity of the switch.

Power applied to the heater element until plastic base melts.

Spark generated in contact cavity of switch.

Brake fluid present in the contact cavity (wet device) and absent in the contact cavity (dry device).

Results: (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

Wet device: The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The applied spark ignited the fumes in the contact cavity of the switch and engulfed the base material of the switch.

Conclusion: A switch ignition can occur under the following laboratory conditions:

Heater element installed in the switch contact cavity.

5 watts of power dissipated in heating element.

Spark generated in the contact cavity of the switch.

Brake fluid did not contribute to the ignition process.

TI-NHTSA 014333

Level 2: Objective: Determine if a laboratory ignition can occur using only switch components and elements found in the switch environment.

- Test 6a

Objective: Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch, which may lead to an ignition.

Results: (1) out of (15) samples tested increased resistance to 5 Ω s. A solution of 5 wt. % NaCl in H₂O can corrode the electrical components of the switch and cause an increase in electrical resistance. Repeated injections of the solution of 5 wt. % NaCl in H₂O into the contact cavity of a switch, with the switch continuously powered at 14 Volts, can cause an ignition.

Conclusion: A switch ignition can occur under the following laboratory conditions:

A solution of 5% NaCl in H₂O is injected into contact cavity of a switch.
Continuous 14 Volt power applied to the switch.
Hexport is grounded.
Current is limited at 15 Amps.

- Test 6c

Objective: Determine if brake fluid with metal shavings is conductive enough to create an ignition.

Results: (3) devices with various size metal particles were tested. No significant current increase detected.

Conclusion: Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

- Test 7

Objective: Determine if switch meets cycle life specification.

Results: Tests conducted during the first quarter of 1999 show that switches exceed cycle life specification.

In the first quarter of 1999, a total of (42) 77PSL2-1 map switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles, which

TI-NHTSA 014334

occurred at 728,000 cycles. A Weibull analysis showed 99.9% reliability at 500,000 cycles at 95% confidence level.

Conclusions: Switches meet cycle life specification. First quarter, 1999 tests confirm impulse test findings made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to 500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level.

• **Test 15a**

Objective: Determine the long term corrosive effects of brake fluid on the electrical components of switches which are continuously powered at 14 Volts.

Results: Test was suspended after 550 hours of testing. (6) samples were tested with continuous 14 Volts power. The contact cavity of (4) switches contained new brake fluid and (2) switches contained old brake fluid. Switches with old brake fluid drew very little hexport current and showed a decrease in hexport current over time to less than 1/10 mAmp. Samples with new brake fluid showed an increase in hexport current to over 20 mAmps toward the end of the 550 hours of testing. Analyses of (1) sample with new brake fluid and (1) sample with old brake fluid revealed electrolytic corrosion of the contact arm of both switches. There was a much lower level of corrosion in the sample with used brake fluid than the sample with new brake fluid.

Conclusion: Brake fluid in the contact cavity of switches, which are at 14 Volts continuous power for over 500 hours, can cause electrolytic corrosion of the switch contact arm. It is unknown if this corrosion, under continuous power conditions, can eventually lead to sufficient current draw to drive an ignition.

• **Test 17**

Objective: Quantify the long term corrosive effects of new brake fluid on the electrical components of switches under the following laboratory conditions:

Contact cavity of switch flooded with new brake fluid.
Switches at continuous 14 Volts power.
Switches subjected to vibration for (1) hour per day.
Switches subjected to 100°C for (1) hour per day.

Results: Test suspended after (312) hours. (50) samples tested. The average hexport current draw after (312) hours is 1.9 mAmps with a standard deviation of 1.8 mAmps. There has been no increase in hexport current. These results are consistent with results previously found in Test 15a.

TI-NHTSA 014836

Conclusion: New brake fluid in the contact cavity of switches, has not caused an increase in hexport current after (312) hours at continuous 14 Volts power.

Level 3: Objective: Understand the laboratory ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at laboratory ignition, via injection of a solution of 5 wt. % NaCl in H₂O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current versus time show an increase in current until the point of ignition.

Conclusion: A repeatable laboratory method for switch ignition was established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a solution of 5 wt. % NaCl in H₂O is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminal results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

Level 4: Objective: Compare and contrast variables influencing ignition using the established laboratory ignition method.

• Test 13a

Objective: Compare various fluids in the established ignition method.

Results: The following fluids were tested.

- (1) NaCl in H₂O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5 wt. % H₂O
- (1) new brake fluid
- (1) new brake fluid with 5 wt. % H₂O

The switch filled with 5 wt. % NaCl in H₂O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of

corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion over the (24) hour test.

Conclusion: Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H₂O is necessary to cause an ignition.

• Test 15

Objective: Compare the ignition characteristics of various plastics as switch base material.

Results: When 5 wt. % NaCl in H₂O was injected into switches with different base materials, the following results were obtained: Callanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusions: All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

Objective: Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

Results: Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation verses 45° orientation nor to rotational angle in the 45° orientation.

Level 5 Objective:

Test 16

- Objective: Test proposed relay circuit.

Results: (1) switch was injected with a solution of 5 wt. % NaCl in H₂O and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained mostly intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built

up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for (18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dissipated in the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is insufficient to cause substantial electrolytic corrosion or significant switch terminal heating, which is necessary to create an ignition. In previous tests, using a resistor as the heating element (see Test 6), approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

TI-NHTSA 014338

TECHNICAL SERVICE LABS

LOG NO. _____
TEST NO. **152744**

TEST NO. **152744**

PCC ID	137	NOTE YOUR PROBLEM SAMPLE IDENTIFICATION	INFORMATION
REPAIRMAN	137		
DATE	11/29		
TIME	11:00		
NO. OF SAMPLES	1		
NO. OF TESTS	1		
NO. OF PARTS	1		
NO. OF HOURS	1		
NO. OF DAYS	1		
NO. OF WEEKS	1		

SEE ATTACHED

REPORT OF RESULTS:

DATE RECEIVED _____ DATE OUT _____

TECHNICIAN		
HOURS WORKED		
PROCEDURE USED		

*PCC I.D.

- MC-325
- TM-431
- CLKE-122
- FACIL-514
- PC-127
- WIRE-432
- CAN-864
- FACIL-521
- VERB-168
- EPD-821
- AD DEV-888
- FACIL-531
- AFCC-489
- PEP-822
- EMCD-877
- STAFF-868
- MD-430
- CSD-835

77PS Impulse Test

- 30 devices 77PS

T: 135°C S=2Hz

- 3 APT 3CP2-1 devices

P_{min}: 0-50psi P_{max}: 1450±50psi

medium: New brake fluid.



- = 77PS devices
- ⊙ = APT 3CP2-1 device
- = Surface mounted thermocouple
- ⊗ = Suspended (Ambient) Thermocouple

- 10 connectors w/counters randomly placed on devices.

- APT's were used to verify pressure profiles along the circuit. Pressures adjusted/set using a 5000psi matched sensor set up so that 1mV output = 1psi of pressure. The APT's were placed as follows:

- APT #1 = start of circuit
- APT #2 = middle of circuit
- APT #3 = end of circuit


APT's were used for reference only. Only accurate to 3.4%.

Formula for Pressure reading using an APT.

$$\text{Actual Pressure} = \frac{\text{APT voltage} - 0.3}{0.00188}$$

Sensor Rec Reading


8-9-99



TI-NHTSA 014341

APT 1 (Bottom)


8-9-99



TI-NHTSA 014342

2 (cont)


8-9-99



T1-NHTSA 014343

APT 3 (TOP)

8-9-99



TI-NHTSA 014314

Senotee


10:01:00 09 AUG 99



TI-NHTSA 014346

APT 1


10:07:57 09 AUG 89



TI-NHTSA 014346

APT 2


10/13/27 89 AUG 89



T-NHTSA 014347

APT #3


10:17:21 09 AUG 99



TI-NHTSA 014348

SensoTel

18:06:44 08 AUG 99




TI-NHTSA 014349

APT #1

18:04 08 AUG 99


2.98V, 0.860S

0.917V, 0.635S



TI-NHTSA 014360


APT #2



TI-NHTSA 014361

APT #3

16:17:28 06 AUG 99



TI-NHT9A 014382

4

5 Ksig Sensotec

CTRL # P4451

RANGES:	2.000V	10.000V	10.000V
OFFSETS:	0.0V	0.0V	0.0V
TOTAL TIME:	2.50S		
POST-TRIG:	0.0S		
TRIGGER:	MAN		
09:48:57	08 AUG 99		


x = 1 grid = 0.1 sec

y = 1 div = 1psi 1 grid = 100 psi



71NHT8A 014963


APT #1




TI-NHTSA 014354

APT #2

RANGES: 3.500V 10.00V 10.00V
OFFSETS: 0.0V 0.0V 0.0V
TOTAL TIME: 2.50S
POST-TRIG: 0.0S
TRIGGER: MAN 2.99V, 0.81DS
10.00.55.06 AUG 99



TI-NHTSA 014386



RANGES: 3.500V 10.00V 10.00V
OFFSETS: 0.0V 0.0V 0.0V
TOTAL TIME: 2.50S
POST-TRIG: 0.0S
TRIGGER: MAN
10.08.98 08 AUG 99

T-NHT8A 014386

**DRAWINGS AVAILABLE UPON
REQUEST**

PART: _____

QUAN: _____



77PS Impulse Test

T: 135 °C

P_{min}: 0.50psi

P_{max}: 1450 ± 50 psi

f: 2.0 Hz

medium: New brake fluid

30 devices split into 3 groups:

group 1: Virgin parts

group 2: Production vacuum tested

group 3: Rapid vacuum done in lab (1.5-2.0 sec from atmospheric to ~29.2 in/hg)

P monitored by: Sensotec 0.5kpsi CTRL # PR451

and using 3 APT device # 3CP2-1 strategic

placed along P circuit. Actual P: APT voltage - 0.

APT1 - placed @ start of circuit

APT2 - placed ~ middle of circuit

APT3 - placed @ end of circuit

- output read on Nicolet scope CTRL # 4125

Steps: 1- get parts (32 virgin parts, 16 line vacuum test)

2 prep chamber + cycler (purge out old fluid)

3- F/D curve tops each group


4- Rapid vacuum group 3 parts

Temp monitored w/ OMEGA 672A digital thermometer and using

J-Type Thermocouples. 1- ambient (in chamber) suspended; 1-

mounted to a manifold.

- Arrows indicate direction of




9, 7 PPS devices

⊙: APT 3CP2-1

⊕: Suspended Thermocouple

⊠: Surface mounted thermo couple



G1-1

G1-2

G1-3

8-11-99

$x: 0.005/cm$ $y: 2009/cm$ Same for all


51-6


51-7

51-8

51-9

51-10





GP-6

GP-7

GP-8


GP-9

GP-10

Pre-Vacuum Test

7 0.005 / cm

3: 2021



TRANTRA 014370

3.2

3.3

3.4

3.5

3.6

3.7

Pre-vacuum Test

TRANSBA 014371

