

EA02-025

TEXAS INSTRUMENTS, INC.'S

9/10/03


REQUEST NO. 7

BOX 9

PART A – R


PART L

6(7)




TI-NHTSA 014372

5(4)



T-NHT8A 014374

4 (3)



T1-NHTSA 014376

3(8)


RANGES: 200.0mV 10.00V 2.400V
OFFSETS: 0.0V 0.0V 0.0V
TOTAL TIME: 1.00S
POST-TRIG: 0.0S
TRIGGER: MAN
17.25.10 00 JUL 99

0.500psig SansoTec


y: 10mV/div

TI-NHTBA 014379

x: 10ps/div



4(5)



TI-NHTSA 014380

3(14)

RANGES: 200.0mV 10.00V 0.500V
OFFSETS: 0.0V 0.0V 0.0V
TOTAL TIME: 1.008
POST-TRIG: 0.00
TRIGGER: MAN
17-28-24 00 JUL 99

0.500 sig SenseTec

x = 100ns/div
y = 10mV/div

TI-NHTSA 014383

**DRAWINGS AVAILABLE UPON
REQUEST**

Attorney Client Privileged Communication
77PGL3-1 Life Test Report
"Bubbled" Diaphragms
Bryan Degan 8/17/99

Purpose:

The purpose of this test is to determine if there is a significant difference in diaphragm life when "bubbled" Diaphragms are exposed to pressure cycles.

Procedure:

- 1) 3 groups of switches (77PGL3-1) that were previously used to generate wellbore plots were obtained. These 3 groups contained a total of 25 switches. Of these 25 switches 9 had been cycled to produce leaks for the wellbore analysis.
- 2) The previous wellbore tests were suspended at 1,307,000 cycles.
- 3) The 25 switches were opened to obtain a clear view of the diaphragm.
- 4) The opened switches were sorted into 2 groups: those with a visually detectable bubbled diaphragm and those with no sign of a bubbled diaphragm.

Results:

The sort produced 11 switches with bubbled diaphragms, and 14 without bubbled diaphragms. Moreover 4 out of the 11 and 3 out of the 14 had leaked during the previous cycle test.

Since there was less than 6 leaks in each group a wellbore plot was not possible. Therefore, the average number of cycles each group was calculated and used to compare the two groups.

As can be seen from the data, the group with bubbles had an average of 1.27 million cycles, and the group without bubbles in the kapton diaphragm had an average of 1.25 million cycles.


	Bubbles in Kapton Diaphragm		No Bubbles in Kapton Diaphragm	
	1187000	leaked	1078547	leaked
	1187000	leaked	1078547	leaked
	1187000	leaked	1178000	leaked
	1212888	leaked	1200288	leaked
	1307000		1212000	leaked
	1307000		1307000	
	1307000		1307000	
	1307000		1307000	
	1307000		1307000	
	1307000		1307000	
	1307000		1307000	
	1307000		1307000	
Average:	1286448		1307000	
Std	77782		1307000	
		Average:	1280918	
		Std	188874	

Conclusion:


Based on the above results, there does not seem to be any significant difference in cycle life between switches built with bubbled diaphragms and switches built without bubbled diaphragms.

End of document.

No Description	9
Brake Fluid Leak	6
Administrative Parts Return	4
Engagement Troubles	2
Disengagement Troubles	2
ABS Warning Light	1
Other Electrical Accessory Trouble	1




Time	Supply Cui	Hotspot C1	Terminal C	Check
2	0.6	0.2	0.5	0.0
4	1.2	0.7	0.5	0.0
6	1.4	1.0	0.5	-0.1
8	1.2	0.7	0.5	0.0
10	1.3	0.8	0.5	0.0
12	0.9	0.4	0.5	0.0
14	0.9	0.4	0.5	0.0
16	0.7	0.3	0.5	-0.1
18	1.6	1.0	0.4	0.2
20	1.4	0.9	0.4	0.1
22	1.0	0.8	0.4	0.0
24	1.3	0.9	0.5	-0.1
26	1.4	1.3	0.0	0.1
28	0.7	0.8	0.0	-0.1
30	1.1	0.6	0.5	0.0
32	0.9	0.4	0.4	0.1
34	0.4	0.0	0.4	0.0
36				
38				
40				



Current Flow vs Time

Texas Instruments 77PS Brake Switch



TI Switch ID #	RQ #	TI Date Code	YRLE	Car Build Date
700-8	32364	2128		
700-8	32377	2048		
700-8	32407	2120		
700-4	32382	2029		
700-3	32400	2059		
700-7	32110	9140		
E	32087	2082		
S	31607	2082		
D	32114	2082		
612-17	88271	2104		
612-21	88345	2038		
612-28	88386	2082		
612-30	88972	2059		
612-18	88458	2008		
612-19	88974	1282		
612-24	88878	1331		
612-25	88268	2008		
612-22	88888	2088		
612-8	88445	2013		
612-8	87089	1347		
612-8	88890	2097		
612-4	88848	2088		

LAST REVISED 1988 by CR & LM

PRESSURE SWITCH CROSS-REFERENCE LIST
TO BE USED FOR REFERENCE ONLY

Minor changes

TI INTERNAL DATA

TI PN	CUSTOMER PART NO.	CUSTOMER	Func	Actuation Pressure		Inlet color/flag/content	port fitting/cap details				
				- 150C calibration (psig)	- 150C calibration (psig)		type/transition	thread	hex	paint	flag
1 77PBL3-1	F2VD-8F824-AB	Ford FIC	brake	90-180	20 min	bead/psw 2	J51200000-1	3/8-24 M	816	Zn/yellow	wrap
2 77PBL3-3	F2LC-8F824-AA	Hills Ind.	brake	200-300	40 min	black/pearl	J51200000-1	3/8-24 M	816	Zn/yellow	wrap
3 77PBL3-1	F2AC-8F824-AA	PVC - EN83	brake	60-280	20 min	red Nipon 2	J51200000-1	3/8-24 M	816	Zn/yellow	wrap
4 77PBL3-2	F2BA-8F824-AA	Ford WINGS	brake	90-180	20 min	gray Nipon 1	J51200000-1	3/8-24 M	816	Zn/yellow	quat
5 77PBL3-3	F3TA-8F824-CA	LT - F-union	brake	200-300	40 min	red Nipon 1	J51200000-1	3/8-24 M	816	Zn/yellow	quat
6 77PBL4-1	84EM-8F824-AA	Austr - Falcon	brake	90-180	20 min	red Nipon 2	e-ring30007-1	3/8-24 M	14mm	Zn/clear	quat
7 77PBL5-2	F3DC-8F824-AA	Travis SHO	brake	90-180	20 min	red Nipon 2	wash30007-1	3/8-24 M	816	Zn/clear	quat
8 77PBL5-1	94JA-8F824-AB	Austr - Capri	brake	90-180	20 min	dk gry Nipon 1	e-ring30017-1	3/8-24 M	816	Zn/yellow	quat

TI-NHTSA 014384

Used on:

Cover Mo, Grand Marquis, Mark, Temi Car
Scorpio, Club Wagon
Cover Mo, Grand Marquis, Mark, Temi Car
Wilder
Barns, F-Series, Ranger, Explorer, Navigator, Expedition, Excursion, Club Wagon
Falcon
BHO Trucks
Capri

Used Model:

Callaver 4300
Callaver 4300
GE Naryl GTX 830
GE Naryl GTX 830
GE Naryl GTX 830
GE Naryl GTX 830
GE Naryl GTX 830
GE Naryl GTX 830

TI-NHTSA 014398


Morris, Irene

From: Beringhaus, Steven
Sent: Thursday, September 02, 1999 7:56 AM
To: Baumann, Russ
Subject: FW: Field Campaign Analysis Report

From: Beringhaus, Steven
Sent: Wednesday, September 01, 1999 6:31 PM
To: Steve Reimer
Subject: Field Campaign Analysis Report

Steve,

Here is the summary document you requested. We were able to complete the analysis on all forty parts. Why don't you call me in the morning so we can discuss this in more detail.


FieldCampaign.doc

Regards,
Steve 605-236-3375

(2) Teardrops were seen on roughly 60% of the switches. No correlation between level of wear and teardrops.




Figure 1. Ceramic pin with wear marks seen on top and around the sides.



Figure 2. Wear marks can be seen as a flat spot on the bump and curved discoloration on the arm.



Figure 3. Delamination of the Teflon from the Kypson can be seen as a circular bubble.

Epstein, Sally

From: DeGus, Bryan
Sent: Monday, August 30, 1999 3:29 PM
To: Beringhaus, Steven
Subject: TTPS FA summary

Steve,

Here is the latest summary sheet:

<<TTPS SUMMARY- Sorted 8-30-99>>

I hope this sent OK.

Regards,
Sry

TI-NHTSA 014401

TI 8018689

Corrective Action Notice

0010429

Auditor: Renee Machado
Supervisor: Mary Milkey
Mfg. Eng.: Bob Gildea
QA Engineer: Jim Watt

PC: 88
CC: 294
BO: B40
OP: 700

Audit Date: 4/20/99
Spec Code/Number: B 11
Severity: 2
Checklist: Yes
Dev#:

Product Line: HYDRAULIC PRESSURE SWITCH

Operation: 302577 PILOT-MAKER

Specification: Process Specification/Prin Requirement: Etc.4.09 The process spec describes the operation/process steps.

Condition Found: The Quality Dept is no longer responsible for the product in this cost center. Mfg. personnel are now responsible for their own quality and final inspection of the product. Through out the document QC is referenced. The document needs to be updated to reflect the change. This does not conform to Etc. 4.09, Process Control and Etc. 4.05 Document and Data Control. Copies attached and hi-lighted.
ALL HI-LIGHTED AREAS MUST BE COMPLETED

Case#:

Corrective Action:

updated document to reflect change in responsibilities.

A Target Date:

Completed ~~10/27/99~~ 9/30/99

C.A. By:

Sign:

Date:

Chris Salzman
9/27/99

Forward to for Signature & Date:

Supervisor:

Mary Milkey

Date:

9/27/99

Mfg. Eng.:

Bob Gildea

Date:

9/27/99

QA Eng:

Date:

Return To: Auditing MS 12-33 By:

5/4/99

Verification:

10/27/99 Follow up

Correction Made, Current Rev. A B at the operation, includes changes

02480 Form 02/03

Renee

RECEIVED
SEP 7 1999

#####

DEV: 77/87PS
 CC: 294
 SO: 840
 OP: 700
 LR: 5700

PILOT MAKER

QUALIFY FAILURE DISPOSITION:

- QR1. SALVAGE/SCRAP AS REQUIRED.
- QR2. WEAR SMOCK AND HAINNET.
- QR3. HOLD FOR ENGINEERING EVALUATION

PREVENTIVE MAINTENANCE SUMMARY:

CODE #	EQUIPMENT #	DESCRIPTION
D22293-W.PM	122293	WAREHOUSE VACUUM LIFTER
121681-W.PM	121681	AMI SENSOR ASSEMBLY
D21980-W.PM	121980	FINAL ASSEMBLY AMI MACHINE (FAM)-DAILY
121980-W.PM	121980	FINAL ASSEMBLY AMI MACHINE (FAM)-WEEKLY
121980-M.PM	121980	FINAL ASSEMBLY AMI MACHINE (FAM)-MONTHLY
121981-N.PM	121981	BASE AMI MACHINE-MONTHLY
D21981-W.PM	121981	BASE AMI MACHINE-DAILY
121981-W.PM	121981	BASE AMI MACHINE-WEEKLY
D21983-W.PM	121983	FINAL FUNCTION TESTER #3
S40390-W.PM	140390	FINAL FUNCTION TESTER #2
D21429-W.PM	121429	MATTHEWS MODEL 2610 CODER

SPC FILE/CA SUMMARY:

SPC FILE	CORRECTIVE ACTION FILE	DESCRIPTION
77TORQUE	77TORQUE.CAL,2,3)	BASE SENSOR TORQUE AFTER CRIMP.
77CRHT	77CRHT.CAL,2,3)	DEVICE CRIMP HEIGHT AFTER CRIMPING.
77SENHTA	77SENHTA.CAL,2,3	77/87PS SENSOR CRIMP HEIGHT
77KTPC	77KTPC.CAL,2,3	77PS SENSOR CRIMP HEIGHT-GOLD CUP

OPERATION DESCRIPTION - (SWAP SWITCHES):

NOTE: THIS PROCEDURE IS TO BE USED FOR THE FOLLOWING DEVICE TYPES ONLY:
 87PS-ALL
 77PSL2-1
 77PSL2-3
 ALL OTHER DEVICES NOT LISTED ABOVE MUST BE PILOTED USING THE QUIET SWITCH PROCEDURES.

1. DETERMINE THE TARGET DISC ACTUATION CALIBRATION AS FOLLOWS:
 - A. DETERMINE THE AVERAGE ACTUATION AMPLIFICATION FOR THE STACK-UP COMBINATION BEING PILOTED. IF THE STACK-UP IS NEW, TRY TO CHANGE TO A USED ONE - OR - SELECT THE MOST RECENTLY USED COMBINATION DATA.
 - B. WITH THE AVERAGE AMPLIFICATION DATA SELECT THE TARGET DISC ACTUATION CALIBRATION USING THE DISC SELECTION CHART.
 - C. FROM THE DISC INVENTORY SELECT A DISC LOT CLOSEST TO THE TARGET CALIBRATION DETERMINED IN (1B). -----
 - D. REVIEW THE DISC INVENTORY AND DETERMINE IF THE CURRENT DISC DEPARTMENT ORDER PRESSURE IS CORRECT. CONTACT SUPERVISOR/COACH IF PRESSURE IS OUTSIDE OF KANBAN.

21. WHEN A DISC LOT HAS BEEN SELECTED FOR QUALIFICATION PROCEED WITH THE BUILD PROCESS. SELECT 24 DISCS AND 24 SAMPLES FROM EACH LOT CONTROLLED COMPONENT, (WASHER, CONVERTER, AND CUP). ASSEMBLE SENSOR ASSEMBLIES USING APPROVED MANUAL BUILD PROCEDURES. CRIMPED SENSOR ASSEMBLIES MUST PASS SPC REQUIREMENTS. REFER TO SECTION #2 FOR DETAILS.
3. ALL BOXES OF HEX PORTS, CONVERTERS, WASHERS, ETC.... MUST BE RESEALED AFTER PARTS HAVE BEEN REMOVED. INITIAL AND DATE THE OUTSIDE OF THE BOX AND INDICATE THE NUMBER OF PARTS REMOVED.
4. WHEN THE PILOT SENSORS ARE COMPLETE, THE PILOT MAKER MUST FINAL ASSEMBLE USING STANDARD PRODUCTION FINAL ASSEMBLY PROCEDURES. USE THE CALIBRATION SET-POINTS CHART TO DETERMINE PROPER BASE AND PIN SIZE TO USE FOR FINAL BUILD OF THE PILOT.
5. FINAL ASSEMBLE THE PILOT LOT USING STANDARD BUILD PROCEDURES. CRIMPED DEVICES FULLY USING THE FINAL ASSEMBLY MACHINE CRIMP STATIONS. CRIMP FINAL ASSEMBLIES MUST PASS SPC REQUIREMENTS. REFER TO SECTION #2 FOR CODE MAKE-UP.
6. THE PILOT SAMPLE MUST BE FINAL TESTED ON THE APPROPRIATE TESTER PER THE FUNCTION TESTER MATRIX. THE TESTER MUST BE FULLY OPERATIONAL DURING USE. UNDER NO CIRCUMSTANCES CAN ANY PORTION OF THE TESTER OR UNLOAD SYSTEM BE DISABLED OR BYPASSED DURING OPERATION. ALL PILOT SWITCHES MUST BE UNLOADED ONTO THE UNLOAD CONVEYOR AND SUCCESSFULLY PASS THE O-RING PRESENT/ABSENT CHECK AND CRIMP HEIGHT CHECK. ANY FAILURE IS CAUSE FOR REJECTION OF THE PILOT SWITCHES FOR ENGINEERING REVIEW. AFTER TESTING ALL PILOT SAMPLES, PRINT OUT A LOT SUMMARY FOR USE IN DETERMINING LOT APPROVAL. ENTER THE PILOT RESULTS ONTO THE STACK-UP DATABASE LOG FOR FUTURE REFERENCE.
7. FINISHED PILOT PIECES MUST BE PLACED, REPORT UP, IN A FOAM HOLDER AND VISUALLY INSPECTED FOR REPORT CORRECTNESS AND O-RINGS PRESENCE, IF REQUIRED.
8. USE THE PILOT SAMPLE ACCEPTANCE CHART TO DETERMINE IF THE LOT IS ACCEPTABLE FOR PRODUCTION RELEASE. TAKE THE FOLLOWING ACTION(S) BASED ON WHICH ZONE THE SAMPLE IS IN:

ZONE	ACTION(S)
TARGET	<ul style="list-style-type: none"> - APPROVE THIS SAMPLE IF ALL OTHER REQUIREMENTS ARE MET PER THE ACCEPTANCE CHART. - APPROVE UP TO (5) ADDITIONAL DISC LOTS (BONUS LOTS) FOR USE WITH THE SAME STACK-UP ONLY IF THE ADDITIONAL LOTS HAVE DISC ACTUATION MEANS WITHIN +/- .5 PSI OF THIS SAMPLE LOT. EACH ADDITIONAL DISC LOT MUST PASS REQUIRED ACCEPTANCE CHART CRITERIA. ADDITIONAL DISC LOT ACTUATION AND RELEASE SIGMAS MUST BE LESS THAN PILOTTED DISC SIGMAS. NO "RED X" DISCS LOTS MAY BE USED AS BONUS LOTS.
GO (OUTSIDE TARGET)	<ul style="list-style-type: none"> - APPROVE THIS SAMPLE ONLY IF ALL OTHER REQUIREMENTS ARE MET PER THE ACCEPTANCE CHART. - USE THE ACTUATION MEAN CENTERING PROCEDURE TO SELECT NEW DISC CALIBRATION TO TRY FOR THE NEXT SAMPLE. (SEE SAMPLE ACCEPTANCE CHART)
STOP	<ul style="list-style-type: none"> - REJECT THIS SAMPLE. - USE THE ACTUATION MEAN CENTERING PROCEDURE TO SELECT NEW DISC CALIBRATION TO TRY FOR THE NEXT SAMPLE. (SEE SAMPLE ACCEPTANCE CHART)

ONCE ACCEPTED, THE LOT MUST BE LOGGED INTO THE PILOT LOG BOOK. Q.C. ACCEPTANCE MAY BE REQUIRED PRIOR TO RELEASE. IF Q.C. ACCEPTANCE IS REQUIRED, LOT

- MAY NOT BE RELEASED TO BE KITTED AND BUILT UNTIL Q.C. TESTING IS COMPLETE AND LOT PASSES. IF LOT FAILS Q.C. TESTING, IT IS REJECTED AND MAY NOT BE USED UNTIL DISPOSITIONED BY ENGINEERING. REFER TO SECTION #3 FOR Q.C. SAMPLE SUBMISSION PLAN.
- 9. ALL BOXES OF "RED X" DISCS LOTS MUST BE SUBMITTED TO Q.C. FOR ACCEPTANCE. NO SENSORS MAY BE ASSEMBLED UNTIL IMPULSE TESTING IS COMPLETE AND ALL SENSOR ASSEMBLIES HAVE PASSED.
- 10. ONLY HEXPORTS FROM SEALED BOXES MAY BE KITTED.
- 11. ALL PILOT SWITCHES MUST BE RETESTED WITH THE ASSOCIATED PRODUCTION LOT WHENEVER POSSIBLE. IF NOT POSSIBLE, THE PILOT SWITCHES MUST AT A MINIMUM BE RETESTED WITH A PRODUCTION LOT OF THE SAME DEVICE TYPE PRIOR TO PACKING.

OPERATION DESCRIPTION - (QUIET SWITCHES):

NOTE: THIS PROCEDURE IS TO BE USED FOR THE FOLLOWING DEVICES:

- 77PSL3-1 - 77PSL5-2
- 77PSL3-2 - 77PSL6-1
- 77PSL3-3 - 77PSL4-1

1. DETERMINE THE TARGET DISC ACTUATION CALIBRATION AS FOLLOWS:
 - A. DETERMINE THE AVERAGE ACTUATION AMPLIFICATION FOR THE STACK-UP COMBINATION BEING PILOTTED. IF THE STACK-UP IS NEW, TRY TO CHANGE TO A USED ONE - OR - SELECT THE MOST RECENTLY USED COMBINATION DATA.
 - B. WITH THE AVERAGE AMPLIFICATION DATA SELECT THE TARGET DISC ACTUATION CALIBRATION USING THE DISC SELECTION CHART.
 - C. FROM THE DISC INVENTORY SELECT A DISC LOT CLOSEST TO THE TARGET CALIBRATION DETERMINED IN (1B.).
 - D. REVIEW THE DISC INVENTORY AND DETERMINE IF THE CURRENT DISC DEPARTMENT ORDER PRESSURE IS CORRECT. CONTACT SUPERVISOR/COACH IF PRESSURE IS OUTSIDE OF KANBAN.
2. WHEN A DISC LOT HAS BEEN SELECTED FOR QUALIFICATION PROCEED WITH THE BUILD PROCESS. SELECT 24 DISCS AND 24 SAMPLES FROM EACH LOT CONTROLLED COMPONENT, (WASHER, CONVERTER, AND CUP). ASSEMBLE SENSOR ASSEMBLIES USING APPROVED MANUAL BUILD PROCEDURES. REFER TO SECTION #1 FOR DETAILS. SENSOR ASSEMBLIES MUST BE CRIMPED USING STANDARD PRODUCTION PROCEDURES.
3. ALL BOXES OF HEX PORTS, CONVERTERS, WASHERS, ETC... MUST BE RESEALED AFTER PARTS HAVE BEEN REMOVED. INITIAL AND DATE THE OUTSIDE OF THE BOX AND INDICATE THE NUMBER OF PARTS REMOVED.
4. WHEN THE PILOT SENSOR ASSEMBLIES ARE COMPLETE THE PILOT MAKER MUST DETERMINE THE SENSOR CODE. REFER TO SECTION #4 FOR DETAILED INSTRUCTIONS. THE PILOT MAKER MUST USE THIS CODE, AND THE PRODUCTION VALID FINAL ASSEMBLY MATRIX CHART, TO DETERMINE THE PROPER BASE AND PIN SIZE TO USE FOR FINAL BUILD OF THE PILOT.
5. FINAL ASSEMBLE THE 24 PIECE PILOT AS FOLLOWS:
 - A. BUILD EACH PILOT DEVICE COMPLETELY, EXCEPT FOR THE BASE, IN A WOOD OR FOAM PLATFORM.
 - B. SELECT 24 CALIBRATED BASE ASSEMBLIES FROM THE PILOT SAMPLE BOXES WHICH HAVE SIGNED AND DATED BASE ASSEMBLY SLIPS ENCLOSED. MEASURE 3 OF THE ASSEMBLIES ON THE SPC GAGE. EACH MUST MEASURE WITHIN TOLERANCE ANNOTATED ON THE BOX.

- C. PROGRAM F.A.M. LIMITS TO THE VALUES SPECIFIED FOR THE SENSOR CODED/PIN COMBINATION YOU ARE USING. REFER TO THE F.A.M. OPERATORS CHART.
- D. LOAD DISABLE THE CRIMP RING LOADER. ENABLE THE SENSE FIN, LOAD AND SENSE BASE, CRIMPERS, AND UNLOAD STATIONS. LEAVE OTHER STATIONS DISABLED.
- E. FILL BASE LOAD TRACK WITH SPC CERTIFIED BASE ASSEMBLIES. LOAD PILOT DEVICES, LESS THE BASE ASSEMBLY, THREE AT A TIME JUST BEFORE THE SENSE FIN STATION. CYCLE THE F.A.M. UNTIL ALL ARE CRIMPED AND UNLOADED. VERIFY ASSEMBLIES TO CRIMP HEIGHT SPC REQUIREMENTS BY PERFORMING THE CRIMP HEIGHT SPC PROCESS. SAMPLES MUST PASS SPC. ANY PIN HEIGHT FAILURES MUST BE SEPARATED AND HELD FOR ENGINEERING.
6. THE PILOT SAMPLE MUST BE FINAL TESTED ON THE APPROPRIATE TESTER PER THE FUNCTION TESTER MATRIX. THE TESTER MUST BE FULLY OPERATIONAL DURING USE. UNDER NO CIRCUMSTANCES CAN ANY PORTION OF THE TESTER OR UNLOAD SYSTEM BE DISABLED OR BYPASSED DURING OPERATION. ALL PILOT SWITCHES MUST BE UNLOADED ONTO THE UNLOAD CONVEYOR AND SUCCESSFULLY PASS THE O-RING PRESENT/ABSENT CHECK AND CRIMP HEIGHT CHECK. ANY FAILURE IS CAUSE FOR REJECTION OF THE PILOT SWITCHES FOR ENGINEERING REVIEW.
7. FINISHED PILOT PIECES MUST BE PLACED, HEXPORT UP, IN A FOAM HOLDER AND VISUALLY INSPECTED FOR HEXPORT CORRECTNESS AND O-RING PRESENCE, IF REQUIRED.
8. USE THE PILOT SAMPLE ACCEPTANCE CHART TO DETERMINE IF THE LOT IS ACCEPTABLE FOR PRODUCTION RELEASE. TAKE THE FOLLOWING ACTION(S) BASED ON WHICH ZONE THE SAMPLE IS IN:

ZONE	ACTION(S)
TARGET	<ul style="list-style-type: none"> - APPROVE THIS SAMPLE IF ALL OTHER REQUIREMENTS ARE MET PER THE ACCEPTANCE CHART. - APPROVE UP TO (5) ADDITIONAL DISC LOTS (BONUS LOTS) FOR USE WITH THE SAME STACK-UP ONLY IF THE ADDITIONAL LOTS HAVE DISC ACTUATION MEANS WITHIN +/- .5 PSI OF THE SAMPLE LOT. EACH ADDITIONAL DISC LOT MUST PASS REQUIRED ACCEPTANCE CHART CRITERIA. ADDITIONAL DISC LOT ACTUATION AND RELEASE SIGNALS MUST BE LESS THAN PILOTTED DISC SIGNALS. NO "RED X" DISC LOTS MAY BE USED AS BONUS LOTS.
GO (OUTSIDE TARGET)	<ul style="list-style-type: none"> - APPROVAL THIS SAMPLE ONLY IF ALL OTHER REQUIREMENTS ARE MET PER THE ACCEPTANCE CHART. - USE THE ACTUATION MEAN CENTERING PROCEDURE TO SELECT NEW DISC CALIBRATION TO TRY FOR THE NEXT SAMPLE. (SEE SAMPLE ACCEPTANCE CHART)
STOP	<ul style="list-style-type: none"> - REJECT THIS SAMPLE. - USE THE ACTUATION MEAN CENTERING PROCEDURE TO SELECT NEW DISC CALIBRATION TO TRY FOR THE NEXT SAMPLE. (SEE SAMPLE ACCEPTANCE CHART)

ONCE ACCEPTED, THE LOT MUST BE LOGGED INTO THE PILOT LOG BOOK. Q.C. ACCEPTANCE MAY BE REQUIRED PRIOR TO RELEASE. IF Q.C. ACCEPTANCE IS REQUIRED, LOT MAY NOT BE RELEASED TO BE RITTED AND BUILT UNTIL Q.C. TESTING IS COMPLETE AND LOT PASSES. IF LOT FAILS Q.C. TESTING, IT IS REJECTED AND MAY NOT BE USED UNTIL DISPOSITIONED BY ENGINEERING. REFER TO SECTION #3 FOR Q.C. SAMPLE SUBMISSION PLAN.

9. ALL BOXES OF "RED X" DISCS MUST BE SUBMITTED TO Q.C. FOR ACCEPTANCE. NO SENSORS MAY BE ASSEMBLED UNTIL IMPULSE TESTING IS COMPLETE AND ALL SENSOR ASSEMBLIES HAVE PASSED.
10. WHEN THE PRODUCTION SENSOR LOT IS RECEIVED FROM THE SENSOR ASSEMBLY PROCESS THE PILOT MAKER MUST DETERMINE THE SENSOR CODE OF THE PRODUCTION LOT. REFER TO SECTION #4 FOR DETAILED INSTRUCTIONS. THE PILOT MAKER MUST USE THIS CODE, AND THE PRODUCTION VALID FINAL ASSEMBLY MATRIX CHART, TO DETERMINE THE PROPER BASE AND PIN SIZE TO USE FOR PRODUCTION FINAL BUILD. THE COMMUNICATION CHART MUST BE COMPLETED FOR EACH LOT PRIOR TO RELEASE TO PRODUCTION.
11. ONLY HEXPORTS FROM SEALED BOXES MAY BE KITTED.
12. ALL PILOT SWITCHES MUST BE RETESTED WITH THE ASSOCIATED PRODUCTION LOT WHENEVER POSSIBLE. IF NOT POSSIBLE, THE PILOT SWITCHES MUST AT A MINIMUM BE RETESTED WITH A PRODUCTION LOT OF THE SAME DEVICE TYPE PRIOR TO PACKING.

SECTION #1 - MANUAL SENSOR BUILD PROCEDURE:

THE PILOT MAKER MUST VISUALLY INSPECT COMPONENTS AND SUB-ASSEMBLIES 100% FOR VISUAL DEFECTS. REFER TO VISUAL AIDS. HATNETS AND SOCKS MUST BE WORN DURING THE BUILD PROCESS. SENSORS MAY BE CRIMPED ON EITHER AM12 OR THE MANUAL SENSOR CRIMPER.

1. ASSEMBLE O-RING TO HEXPORT GLAND IF REQUIRED PER PARTS LIST. O-RING MUST SEAT FULLY AGAINST HEX SHOULDER.
2. PLACE HEXPORT, THREADS DOWN, INTO WOOD BUILD PLATFORM. ASSEMBLE GASKET INTO GLAND. VERIFY GASKET IS FULLY SEATED.
3. ASSEMBLE SEALS CONCENTRIC WITH ASSEMBLY. REPLAY SEALS SO THAT ALL CORNERS ARE VISIBLE. USE CAUTION NOT TO DISPLACE GASKET DURING ASSEMBLY. ENSURE PROPER NUMBER OF SEALS ARE USED PER PARTS LIST.
4. PLACE CHAMFER SIDE OF WASHER FACING DOWN AGAINST SEALS. WASHER MUST BE CONCENTRIC WITH HEXPORT.
5. INSTALL SPACER INTO CONVERTER. SPACER MUST FULLY SEAT INTO CONVERTER.
6. PLACE DISC, CROWN FACING UP, ONTO CONVERTER SEAT OVER THE SPACER.
7. PLACE THE CONVERTER ASSEMBLY, CONVERTER BUTTON DOWN AND DISC FACING UP, INTO WASHER HOLE.
8. CAREFULLY PLACE CUP OVER ASSEMBLY USING CARE NOT TO DISPLACE ANY COMPONENTS. CUP MUST FULLY SEAT OVER HEXPORT.
9. SEQUENTIALLY LOAD SENSOR ASSEMBLIES INTO CRIMP TABLE NEST USING CARE NOT TO DISPLACE ANY COMPONENTS. VERIFY SENSOR ASSEMBLIES TO CRIMP HEIGHT SPC REQUIREMENTS BY PERFORMING THE CRIMP HEIGHT SPC PROCESS FOR THE DEVICE TYPE BEING BUILT. SAMPLES MUST PASS SPC.

SECTION #2 - CODE MAKE-UP:

FOR ALL 77PS AND 87PS DEVICES TYPES:

SAMPLE XX-XX 4256A

TI-NHT&A 014408

EX: XX-XX = CUSTOMER PART #
 4XXXX = LAST DIGIT OF CURRENT YEAR
 X256X = DAY OF THE YEAR
 XXXXA = SEQUENTIAL LOT IDENTIFICATION (A, B, C, ETC)

SECTION #3 - Q.C. SAMPLE SUBMISSION PLAN:

THE FOLLOWING Q.C. SUBMISSION SCHEDULE IS TO BE FOLLOWED FOR ALL 77PS AND 87PS PRODUCTION LOTS.

SUBMISSION TYPE	SUBMISSION FREQUENCY	
	77PS	87PS
IP2 FUNCTIONAL TESTING. (NO IMPULSE) (SEE NOTE BELOW FOR SAMPLE AND BONUS LOTS)	4 DEVICES FROM EACH DISC LOT ** SEE BELOW	4 DEVICES FROM FIRST PILOT LOT OF EACH WEEK
IP2 DURABILITY TESTING (IMPULSE)	5 DEVICES FROM FIRST PILOT LOT OF EACH WEEK OR IF CHANGING TO A NEW LOT # OF WASHERS, CONVERTERS OR CUPS.	5 DEVICES FROM FIRST PILOT LOT OF EACH DEVICE OF EACH WEEK OR IF CHANGING TO A NEW LOT # OF WASHERS, CONVERTERS OR CUPS.

** IF DISC LOT EXCEEDS 4,000, 4 MORE DEVICES FROM EACH SUCCESSIVE 4,000 DISCS MUST BE TESTED.

BASE ASSEMBLIES MUST BE FROM RAW NEW WORK - NOT SAFETY STOCK.

MEASURE ALL BASES AND PINS USED FOR Q.C. SAMPLES TO ENSURE THEY ARE CORRECT PRIOR TO ASSEMBLY.

NOTE: SAMPLE LOT IS THE INITIAL ACCEPTED PILOT. THIS MUST BE SUBMITTED TO Q.C. AND PASS ALL TESTING BEFORE LOT CAN BE FITTED AND BUILT FOR PRODUCTION. BONUS LOT SAMPLES MUST BE SUBMITTED TO Q.C. AFTER FUNCTION TEST AND BEFORE PACKING. NO LOTS MAY BE SEALED OR SHIPPED UNTIL Q.C. TESTING IS COMPLETE AND ALL SAMPLES PASS.

SECTION #4 - SENSOR LOT CODE DETERMINATION (QUIET SWITCHES)

THE FOLLOWING PROCEDURE MUST BE USED FOR THE FOLLOWING DEVICES ONLY:

-77PSL3-1	-77PSL4-1
-77PSL3-2	-77PSL5-2
-77PSL3-3	-77PSL6-1

THIS PROCEDURE IS TO BE USED TO DETERMINE A SENSOR CODE FOR THE FOLLOWING SITUATIONS:

PILOT LOT READY FOR PIN AND BASE SELECTION.
PRODUCTION SENSOR LOT READY FOR FINAL ASSEMBLY SET-UP.

PROCEDURE FOR PILOT LOT:

1. FULLY ASSEMBLE AND CRIMP THE PILOT SENSORS USING MANUAL BUILD PROCEDURES IN THIS SPECIFICATION.
2. USING THE PILOT MAKER SENSOR DEPTH GAGE MEASURE AND RECORD THE DEPTH DIMENSION ON ALL 24 SENSORS.
3. ADD ALL 24 DEPTH DIMENSIONS TOGETHER AND FIND THE AVERAGE BY DIVIDING THE TOTAL BY 24.
4. VERIFY THAT THE DIFFERENCE BETWEEN THE HIGHEST AND LOWEST SENSOR DEPTH DIMENSION IS NOT MORE THAN .003". IF THE DIFFERENCE IS GREATER THAN .003" PLACE LOT ON HOLD AND NOTIFY ENGINEERING.
5. DETERMINE THE LOT SENSOR CODE USING THE CORRECT FINAL ASSEMBLY MATRIX CHART.
6. RETURN TO PILOT OPERATION DESCRIPTION FOR QUIET SWITCHES.

PROCEDURE FOR PRODUCTION LOT:

1. SAMPLE 24 PRODUCTION SENSORS FROM EACH SENSORS LOT. A FEW SENSORS FROM EACH TOTE WILL ENSURE A THOROUGH SAMPLING.
2. USING THE PILOT MAKER SENSOR DEPTH GAGE MEASURE AND RECORD THE DEPTH DIMENSION ON ALL 24 SENSORS.
3. ADD ALL 24 DEPTH DIMENSIONS TOGETHER AND FIND THE AVERAGE BY DIVIDING THE TOTAL BY 24.
4. VERIFY THAT THE DIFFERENCE BETWEEN THE HIGHEST AND LOWEST SENSOR DEPTH DIMENSION IS NOT MORE THAN .003". IF THE DIFFERENCE IS GREATER THAN .003" PLACE LOT ON HOLD AND NOTIFY ENGINEERING.
5. DETERMINE THE LOT SENSOR CODE USING THE CORRECT FINAL ASSEMBLY MATRIX CHART.
6. RETURN TO PILOT OPERATION DESCRIPTION FOR QUIET SWITCHES.

Process Specification

Document # 502577

Revision: AB

Page 1 of 13

Title: Pilot Disc Lot	Link Number: 3840	
Product Code: 088	Device Type: 77/87PS	Doc #: 502577
Shop Order: 840	Operation Number: 700	Hrs/K: 100
Cost Center: 294	Standard Number: 5700	Pcs/Hr: 10
Copies: 1	Date: 08/31/99	Revision: AB

Part Number Information	Component/Subassembly Description	Number Required
See Parts List	77PS Final Assembly	1
See Parts List	87PS Final Assembly	1

1.0 SAFETY PERSONAL PROTECTIVE EQUIPMENT REQUIRED

1. Safety glasses with side shields (when Function Testing devices).
2. Safety shoes must be worn when kitting components for pilots or lots.
3. Vacuum Lifter must be used when lifting boxes of components in warehouse.
4. Hearing Protection.

2.0 TOOLS AND/OR EQUIPMENT

Function Tester #2, Eq. # 140380	Calibration Setpoints Chart	Wood/ Foam Building Platform
Function Tester #3, Eq. # 121983	KanBan Disc Calibration Status Log	Route Cards, Labels
Enerpak Rc104 Press/2k psi Gage	Disc matrix Calibration Data	Flanger Cots
Mathews Coder Model 2610 Eq. # 121681	Stackup Data Base Logs	Visual Aids
AMI Sensor Assy Crimper Eq. #121681	Lot Control Documents	Yellow salvage totes
Warehouse Vacuum Lifter Eq. # 122293	Actuation Mean Centering Chart	Red scrap tote
SPC Fixture DWG # 145575 Device Crimp Height (57PS only)	Sample Acceptance Charts	Operator Helmet and Smock
SPC Fixture DWG # 150421 Sensor Crimp Height	Final Assembly Matrix Charts	Pilot Computer Software

TI-NHTSA 014411

TEST WORKSHEET

P/N:		77PBL-1		DATE:		12/2/98	
A. CALIBRATION SPEC				POST TEST			
ACT		90-100		A.S.M.P.			
REL		30 MIN		A.S.M.P.		LAB TEST # 825-10-84	
B. MILLIVOLT DROP < 200				A.S.M.P.			
C. CURRENT LEAKAGE				A.S.M.P.			
D. PROOF				500ms A.S.M.P.			
PRE TESTS:				P-SI TEST		POST TESTS:	
DEVICE #	PROOF	ACT	REL	MVD	CURLK	VIBRATION	A,B,C,D
1	OK	137.8	87.2	0.08	OK	# 1-6	
2	OK	131.3	48.8	0.08	OK		
3	OK	138.4	60	0.08	OK		
4	OK	131.2	60	0.08	OK		
5	OK	128.8	81.1	0.08	OK		
6	OK	136.3	82.4	0.08	OK		
7	OK	131.8	83.4	0.08	OK	VACUUM	A,B,C,D
8	OK	138.8	88.4	0.11	OK	# 7-12	
9	OK	121.4	84.2	0.1	OK		
10	OK	120.2	82.2	0.08	OK		
11	OK	128.8	88.4	0.08	OK		
12	OK	128.2	81.2	0.08	OK		
13	OK	128.8	88.8	0.08	OK	TEMP CYCLE	A,B,C,D
14	OK	132.3	83.2	0.07	OK	# 13-18	
15	OK	131.3	88.2	0.08	OK		
16	OK	121.2	88.7	0.08	OK		
17	OK	134.4	88.4	0.08	OK		
18	OK	131.8	88.4	0.07	OK		
19	OK	127.3	83.4	0.08	OK	FLUID RES.	B,C,D
20	OK	128.7	88.8	0.07	OK	# 19-24	A,B,C,D
21	OK	138.2	88.8	0.08	OK	# 25-30	
22	OK	133	88.4	0.08	OK		
23A	OK	130.8	88.4	0.08	OK		
24	OK	130.7	88.8	0.08	OK		
25	OK	134.4	88.8	0.08	OK		
26	OK	128.8	88.8	0.07	OK	# 25A & 30A	REPLACEMENT PCB
27	OK	130.2	83.4	0.08	OK	DUE TO TEST SETUP ERROR	
28	OK	128.8	88.4	0.08	OK		
29	OK	128.8	87.1	0.07	OK		
30A	OK	124.8	70.4	0.08	OK		
31	OK	128.1	84	0.08	OK	TERM.ATH	A,B,C,D
32	OK	123.3	89.8	0.08	OK	# 31-42	
33	OK	127.2	84.3	0.08	OK		
34	OK	127.8	88.8	0.08	OK		
35	OK	123.3	80.4	0.08	OK		
36	OK	138.8	48.8	0.08	OK		
37	OK	123.1	87.7	0.08	OK		
38	OK	138.2	88.1	0.07	OK		

TEST WORKSHEET

PRE TESTS:						POST TESTS:	
DEVICE #	PROOF	ACT	NEL	IVD	OUR/LK		
38	OK	128	87.8	0.08	OK		
40	OK	127.8	84.1	0.08	OK		
41	OK	128.8	81.2	0.08	OK		
42	OK	132.8	88.1	0.08	OK		
43	OK	134.5	85.4	0.08	OK	HUMIDITY	A,B,C,D
44	OK	127.4	89.8	0.08	OK	243-45	
45	OK	132.2	80.1	0.07	OK		
46	OK	128.1	80.1	0.17	OK		
47	OK	128.8	80.4	0.08	OK		
48	OK	138.4	84.4	0.08	OK		
49	OK	124.5	81.3	0.08	OK	SALT SPRAY	A,B,C,D
50	OK	131.8	88.3	0.08	OK	348-54	
51	OK	138.1	87.1	0.07	OK		
52	OK	138.6	81.8	0.08	OK		
53	OK	137.8	88.4	0.08	OK		
54	OK	131.1	88.8	0.08	OK		

**CIRCUITS THAT REMAIN ENERGIZED AT ALL TIMES - 1980-83 LINCOLN TOWN CAR
ON THE LEFT HAND SIDE OF THE ENGINE COMPARTMENT**

CKT #	CIRCUIT NAME / DESCRIPTION	CKT COLOR	WIRE HARNESS
10	IGNITION SWITCH TO HEADLIGHTS SWITCH	BLK	14251
278	IGNITION SWITCH TO	BLK	14251 / 14252
414	IGNITION SWITCH TO ENGINE CRUISE CONTROL A VIEW	BLK	14251
437	IGNITION SWITCH TO ENGINE CRUISE CONTROL B VIEW	BLK	14251
454	IGNITION SWITCH TO ENGINE CRUISE CONTROL C VIEW	BLK	14251 / 14252
787	IGNITION SWITCH TO ENGINE CRUISE CONTROL D VIEW	BLK	14251 / 14252

POST TESTS

P/N:		77F131		DATE:		1/14/87	
A. CALIBRATION SPEC				POST TEST			
ACT		90-100		A.S.M.P.			
REL		20 MIN		A.S.M.P.		LAB TEST # 812-15-81	
B. MILLIVOLT DROP < 200				A.S.M.P.			
C. CURRENT LEAKAGE				A.S.M.P.			
D. PROOF 3000psi				A.S.M.P.			
POST TESTS:				POST TESTS:			
DEVICE #	PROOF	ACT	REL	MVD	CURLK	VERIFICATION	A,B,C,D
1	OK	134	88.8	0.18	OK	#1-2	
2	OK	121.4	88.8	0.32	OK		
3	OK	134.7	88.8	0.31	OK		
4	OK	131.8	78.4	0.31	OK		
5	OK	129.4	60.4	0.32	OK		
6	OK	131.8	81.3	0.28	OK		
7	OK	133.8	88.4	0.28	OK	VACUUM	A,B,C,D
8	OK	134.4	88.7	0.31	OK	#7-12	
9	OK	128.8	80	0.28	OK		
10	OK	122.4	88.3	0.28	OK		
11	OK	127.8	88.8	0.21	OK		
12	OK	121.7	82.8	0.19	OK		
13	OK	113.8	87.8	0.18	OK	TEMP CYCLE	A,B,C,D
14	OK	121.4	81.7	0.28	OK	#13-18	
15	OK	128.4	54.4	0.31	OK		
16	OK	118.8	68.8	0.18	OK		
17	OK	121.8	81.8	0.31	OK		
18	OK	118.8	43.2	0.28	OK		
19	OK	128.1	88.4	0.27	OK	FLUID REL.	A,B,C,D
20	OK	114.4	84.8	0.32	OK	#19-24	INCH 1/16 ONLY
21	OK	114.8	81.2	0.38	OK		INCH 1/16
22	OK	117.1	83.1	0.33	OK		
23	OK	114.4	88.1	1.18	OK		
24	OK	117.4	83.4	0.33	OK		
25	OK	118.8	88.8	0.71	OK		
26	OK	114.8	84.4	0.5	OK		
27	OK	121.8	87.8	0.38	OK		
28	OK	120.8	88.8	0.31	OK		
29	OK	112.1	88.4	0.34	OK		
30	OK	128.8	72.8	0.38	OK		
31	OK	130.8	85.8	0.31	OK	TEMPLETR	A,B,C,D
32	OK	124.8	88.8	0.32	OK	#31-41	
33	OK	128.8	81.2	0.32	OK		
34	OK	131.8	83.4	0.32	OK		
35	OK	128.1	88.8	0.27	OK		
36	OK	121.8	84.8	0.38	OK		
37	OK	124.4	88.8	0.28	OK		
38	OK	127	85.8	0.37	OK		

Return Analysis on 77P3L2-1

10/8/99

Background:

25 switches were reported to have failed during the change-out procedure currently being conducted by Ford Dealers. These returns were all built in 1999 and supplied to Ford as part of the *Brake Repair Kit* (XW7Z-9G652-AA).

Objective:

Find any functional deficiencies with the 25 switches returned.

Visual Inspection:

Upon receipt of the 25 switches, TI did a visual inspection. Twenty-three of the switches appeared to be in like new condition. However, 2 of the switches showed obvious signs of abuse. These 2 switches appeared to have been installed or removed with pliers by applying torque to the crimp ring and base, not the hex flat. The results of this inspection are summarized below:

Indications of proper installation	17
No signs of installation	4
Improper installation techniques used	2
Damaged threads	1

Only 2 switches were returned with caps and still had brake fluid retained in the pressure cavity of the switches. We were able to obtain 2 small samples of this fluid.

It should be noted that the switches were returned with yellow tags containing information about why the switch was replaced. The tags listed the following reasons for return:

No Description	9
Brake Fluid Leak	6
Administrative Parts Return	4
Engagement Troubles	2
Disengagement Troubles	2
ABS Warning Light	1
Other Electrical Accessory Trouble	1

Calibration and Electrical Testing:

All 25 switches were checked for actuation and release as defined by the specification. All were within specified limits.

In addition to the normal electrical parameters defined in the product specification, TI also measured current leakage from the terminal to the housing. This test was done by applying a current limited 14 Vdc power supply to the terminals of the switch. While a voltage is applied to terminal and the housing is held at ground, the current flow into the switch is measured. All switches measured 0.0 mA.

During the calibration check the switch is pressurized to 200psi with air. All switches sealed properly during this test.

Dissection:

Since no issues were discovered, it was determined that only a sub set would be dissected and internally inspected. Removing the crimp ring and the base would allow internal inspection and direct leak check of the sensor. Six switches were selected for dissection (2 from the Brake Fluid Leak group, 1 from Administrative Parts, 1 from Disengagement Troubles, 1 from other Electrical Accessory Trouble, and 1 from Brake ABS Warning Light Trouble).

TI-NHTSA 014417

The internal inspections confirmed no fluid leakage into the connector cavity, no contamination, and good electrical contacts. Further leak testing of the sensor using refrigerant and a leak detector confirmed no leakage. It is possible that brake fluid leakage may occur on the vehicle due to insufficient installation torque, contaminated threads, contaminated seating surface, or damaged components.

Summary:

- > All switches were within specification.
- > No current path to ground was detected.
- > No leaks were discovered.
- > 2 switches were wire-banded during the install/removal cycle.

End of Document.

Impact of these modifications. Meanwhile, attention has shifted away from the switch as the root cause of the thermal event.

Dague, Bryan

From: Dague, Bryan
Sent: Thursday, November 11, 1999 3:25 PM
To: Beringhouse, Steven
Subject: DOE follow-up summary

**77PS Life Cycle DOE
Follow Up Test Summary
10/28/99**

Purpose:

The objective of this series of tests was to determine why the 77PS2-1 switches used in the "77PS Life Cycle DOE Test to Leakage" did not perform as expected. Cycle expectations for this switch in the specified conditions should easily exceed 500K cycles.

Procedure:

As mentioned in the previous report, converter height was believed to be the cause of the early life cycle failures. Tests were run in which converter heights were varied and the life was measured. Converter heights were varied beyond the dimensions called out on the component prints.

Results/Conclusions:

Upon completion of these tests, it was clear that the converter height was not a significant factor in the cycle life obtained. Three different cyclers were used during this test. As a result, switch life was seen to vary with the cycler used, and not the switch group being tested.

Upon reviewing of the data, Cycler # 4 was instrumented with high-speed transducers, thermal couples, and set-up procedures were reviewed. Cycler #4 was the cycler used in the original DOE. This investigation revealed there are several differences and problem areas with this cycler. These discoveries include an inability to bleed the air from the system, difficulty obtaining a true zero pressure on the low side of the cycle, water content of the brake fluid contained in the system, and different oven temperatures being used during the test.

Corrective Actions:

Cycler #4 is now being redesigned, over hauled, brake fluid changed, and components cleaned. In addition, the set-up procedures are being reviewed to determine the best method of setting pressures and temperatures.

Upon completion of these improvements, a confirmation test run will be conducted to verify the cycler was the root cause of the early failures.

End of document.

77PS Vacuum Dependency Matrix

TI Part Number	Entered	Sell out	% Sell out	Disc type	sup PTE	sup labels
77PS1-1	1100	0	0.00	snap	27713-1	.000 - .002
77PS1-3	no inventory			snap		
77PS1-4			NOV01	quiet	27713-1	.000 - .002
77PS1-2	14000	18	0.13	quiet	27713-1	.000 - .002
77PS1-3	1500	0	0.00	quiet	27713-1	.000 - .002
77PS1-4	no inventory			quiet		
77PS1-1			NOV01	quiet	27713-2	.000 - .000
77PS1-3	no inventory			quiet	27713-2	.000 - .000
77PS1-1	no inventory			quiet	27713-2	.000 - .000

77PS
Documents 129

11:19 AM 12/10/99


TI-NHTBA 014420


Voltage vs- Current with monitored temperature

Vdc

Vdc	I (amps)	Temp deg F
13	0.524	79.2
12	0.468	80.3
11	0.422	81.3
10	0.381	81.9
9	0.342	82.9
8	0.308	83
7	0.268	83.3
6	0.231	83.8
5	0.184	82.7
4	0.187	82.9
3	0.119	83
2	0.081	83.1
1	0.042	82.9
1	0.044	82.9
2	0.083	82.1
3	0.124	82.9
4	0.184	82.4
5	0.269	82.7
6	0.342	83.4
7	0.278	83.8
8	0.318	83.2
9	0.387	83.3
10	0.387	87.2
11	0.419	86.8
12	0.482	85.7
13	0.484	86.8

misc. note: closes at 7.0 Vdc, and opens @ 0.2Vdc.





Voltage vs- Current at 130 deg. C

Vdc

Vdc	I (amps)
13	0.413
12	0.371
11	0.337
10	0.308
9	0.274
8	0.246
7	0.212
6	0.182
5	0.163
4	0.122
3	0.098
2	0.062
1	0.033
0.007	0.008
1	0.032
2	0.062
3	0.092
4	0.122
5	0.152
6	0.181
7	0.208
8	0.238
9	0.268
10	0.292
11	0.32
12	0.347
13	0.371

77P6 Vacuum Dependency Matrix

TI Part Number	\$ stocked	fill out	% fill out	class type	can PTH	can height
77P6L3-1	1100	0	0.00	wrap	27713-1	.000 - .002
77P6L3-2	no inventory			wrap		
77P6L3-1			NOI/01	cut	27713-1	.000 - .002
77P6L3-2	14000	16	0.13	cut	27713-1	.000 - .002
77P6L3-3	1000	0	0.00	cut	27268-1	.003 - .005
77P6L3-4	no inventory			cut		
77P6L4-1			NOI/01	cut	27713-3	.000 - .000
77P6L5-2	no inventory			cut	27713-3	.000 - .000
77P6L6-1	no inventory			cut	27713-3	.000 - .000

TI-NH78A 014424


0:00 AM 12/16/99

Voltage vs Current with monitored temperature


V_{ds}

V _{ds}	I (amps)	Temp (deg F)
13	0.254	79.2
12	0.265	80.3
11	0.282	81.3
10	0.301	81.8
9	0.322	82.8
8	0.344	83
7	0.368	83.2
6	0.391	82.8
5	0.414	82.7
4	0.437	82.9
3	0.470	83
2	0.501	82.1
1	0.542	82.8
1	0.584	82.8
2	0.603	82.1
3	0.624	82.8
4	0.644	82.4
5	0.668	82.7
6	0.692	82.4
7	0.719	81.8
8	0.745	81.2
9	0.761	81.3
10	0.787	81.2
11	0.818	80.8
12	0.852	80.7
13	0.884	80.8

min. max. values at 7.5 V_{ds} and open @ 0.2 V_{ds}.



Voltage Vs Current



TI-NHTSA 014428

Voltage -vs- Current at 130 deg. C

Vdc

Vdc	J (amps)
13	0.413
12	0.371
11	0.337
10	0.303
9	0.274
8	0.243
7	0.212
6	0.183
5	0.162
4	0.122
3	0.093
2	0.083
1	0.083
0.007	0.083
1	0.083
2	0.083
3	0.083
4	0.122
5	0.162
6	0.183
7	0.206
8	0.213
9	0.243
10	0.283
11	0.32
12	0.347
13	0.371

Switch ID	Alarms/Status	Challenge Return	
		Max/min, open, # of cycles	Alarms/Status
11	closed	12.00	11.00
12	closed	closed *	closed
13	closed	11.00	9.00
14	closed	9.00	7.00
15	closed	closed *	closed
16	closed	7.00	6.00
Average		9.65	8.75
STD		2.21	2.52
MAX		12.00	11.00

Procedure:

- 1) Subject switch to 50psi.
- 2) Close curt at stress pressure.
- 3) Subject to vacuum.
- 4) Record vacuum pressure at curt loss.
- 5) Determine vacuum and record pressure at curt.
- 6) Measure curt at stress pressure.

* max vacuum of 28.0 inches achieved.

Switch ID	Alarms/Status	Line Failure	
		Max/min, open, # of cycles	Alarms/Status
LP1	closed	16.00	16.00
LP2	closed	12.00	10.00
LP3	closed	12.00	11.00
LP4	closed	14.00	13.00
LP5	closed	12.00	9.00
LP6	closed	12.00	11.00
LP7	closed	22.00	20.00
LP8	closed	closed*	closed
LP9	closed	11.00	9.00
LP10	closed	9.00	8.00
LP11	closed	14.00	OPEN
LP12	closed	20.00	21.00
LP13	closed	14.00	10.00
LP14	closed	20.00	14.00
LP15	closed	27.00	26.00
LP16	closed	20.00	19.00
Average		16.67	14.04
STD		6.19	6.29
MAX:		28.00	26.00

TI-NHTSA 014428

8-15 AM 12/1985

7770 Model
TO BE USED FOR REFERENCE ONLY

GENERAL DATA

LINE	CUSTOMER	PART NO.	DESCRIPTION	Acting		Inch color	port fitting/backup details				
				Size	Length		Specification	Serial	Qty	Notes	Mat.
1	FANC-SPEN-AA	Fant PIC	85-528	28 inch	Inventory 2	JR-200000-1	28-24 M	870	Zepher	spk	
2	FANC-SPEN-AA	Mini ind.	280-288	48 inch	Inventory	JR-200000-1	28-24 M	870	Zepher	spk	
3	FANC-SPEN-AA	PIC-EMR	90-288	28 inch	MRN Nigma 2	JR-200000-1	28-24 M	870	Zepher	spk	
4	FANC-SPEN-AA	Fant backup	90-588	28 inch	gray Nigma 1	JR-200000-1	28-24 M	870	Zepher	spk	
5	FANC-SPEN-AA	LT - F-voice	280-288	48 inch	red Nigma 1	JR-200000-1	28-24 M	870	Zepher	spk	
6	FANC-SPEN-AA	Mark - F-voice	90-288	28 inch	red Nigma 2	e-4000000-1	28-24 M	14mm	Zachar	spk	
7	FANC-SPEN-AA	Trans MFD	85-288	28 inch	red Nigma 2	0-4000000-1	28-24 M	870	Zachar	spk	
8	FANC-SPEN-AA	Asst - Copd	85-288	28 inch	dk gray Nigma 1	e-4000000-1	28-24 M	870	Zepher	spk	

71-NHTBA 014429

Model no :	Year Model	Specification
Crown Vc, Grand Marquis, Mustang, Town Car	Chrysler 4000	ES-F20C-8F804-AA
Executive, Club Wagon	Chrysler 4000	ES-F20C-8F804-AA
Crown Vc, Grand Marquis, Mustang, Town Car	GE Inspi QTX 600	ES-F20C-8F804-AA
Wagon	GE Inspi QTX 600	ES-F20C-8F804-AA
Bronco, F-Series, Ranger, Explorer, Expedition, Excursion, Club Wagon	GE Inspi QTX 600	ES-F20C-8F804-AA
Passat	GE Inspi QTX 600	ES-F20C-8F804-AA
BMW 7 Series	GE Inspi QTX 600	ES-F20C-8F804-AA
Cadillac	GE Inspi QTX 600	ES-F20C-8F804-AA

7L-NHTSA 014430

12/18/2007 07 AM

Switch ID	Atmosphere	Customer Returns	
		Maximum seen (in. of water)	Atmosphere
11	closed	12.00	11.50
12	closed	closed *	closed
13	closed	11.00	9.50
14	closed	8.00	7.50
15	closed	closed *	closed
16	closed	7.50	6.50
Average:		8.59	8.75
STD		2.21	2.22
MAX		12.00	11.50

Procedure:

- 1) Subject switch to 50psig.
- 2) Check sort at static pressure.
- 3) Subject to vacuum.
- 4) Record vacuum pressure at sort loc.
- 5) Decrease vacuum and record pressure at sort.
- 6) Measure sort at static pressure.

* max vacuum of 28.9 inches achieved.

Switch ID	Atmosphere	Line Failure	
		Maximum seen (in. of water)	Atmosphere
LF1	closed	18.00	15.00
LF2	closed	12.00	10.50
LF3	closed	12.50	11.50
LF4	closed	14.50	13.50
LF5	closed	12.00	8.50
LF6	closed	13.00	11.50
LF7	closed	22.00	20.00
LF8	closed	closed*	closed
LF9	closed	11.00	8.00
LF10	closed	9.00	8.00
LF11	closed	14.00	OPEN
LF12	closed	25.00	21.00
LF13	closed	14.00	10.00
LF14	closed	29.00	14.00
LF15	closed	27.00	25.00
LF16	closed	20.00	19.00
Average:		16.67	14.04
STD		6.15	5.29
MAX:		29.00	28.00

TI-NHTSA 014431

R-18 AM121859

Shower Test

Visual results

D1 (vertical)
on assembly

wet on exterior of switch
mating connector area.

there is a ring of wet on seal
in mating connector.

no evidence of
corrosion or fluid
ingress.

2 black spots are on terminal

2 black spots

near top, part way down

black spots appear to
be arcing.

D2. vertical, ~~rocked~~ connector

connector



no oxidation tab on this side

connector: ring of moisture on sponge seal.
moisture on outside of ring left
by switch.

switch: terminals ~~to~~ a bit of blue on terminal
blade cavity dry; except were noted



drops of
water


C1 not rocked, vertical

connector: typical ring of moisture

switch: inside of blade cavity dry. terminals
down dry. switches opposite from mating
connector. water appears to be on

C1 continues . . . some debris appears to be held to the terminal block by a drop of water (clear liquid)


C2



~~interior of~~
blade cavity soaked w/ water.
blades wet
plastic wet
mating connector wet at seal interface

E2: rocked vertical

interior ~~at~~ completely soaked
no o.t.



switch & terminals are completely soaked


F2: not rocked vertical

mating connector wet. switch wet.
partially, the cavity was soaked.
corrosion evident

E1 & F1 vertical not checked.

Both looked dry no microscopic exam done. The locking tab on E2 broke during removal.

B2 checked, horizontal



top view

water on outside of locking tab surface on top of interior wall, opposite side. water is present. This is damp water surrounding pool! at terminal tips, none on the top surface, many spots or visible as well as corrosion.

B1 not checked, horizontal

switch of ~~connect~~ appear dry, microscopic ~~exam~~


evaluator revealed that some corrosion is on the terminal a colored thread is at the terminal bottom too.

A1 not checked, horizontal

not. horizontal face between connector & switch. The switch is dry & no evidence of

A1 continued


corrosion on terminal block
connector in dry ~~after~~ ^{with} compression ring




A2

water has gone inside compression ring

TOP



water is here



some residues corrosion in present
on this terminal near
the tip

- PHASES OF APPLICATION... MODIFY & NAME CUSTOMY
SUMMARY

(ANNEX/WAT) WHAT PART USED WITHIN? FREQUENT?

DEB
BONIES
(WAT)

CELESTIA 4300/3316/ALORAY 140110N TESTS SATISD
0 AS, 0 FIVE, 0 VICE/THAT, SALL ABAY, 5 25 0 NOT BURE

- CYCLE PROFILE OF TESTER FOR WETBULL
0 LONG COMPART TO VEHICLE WATTS...

- SOME CONNECTIONS... UTA?

...DT, AP

0 -> 300 PR .36
K 300
0 -> 400 PR .74

ANNEX
VIEW: - TEST CONNECTIONS FROM TESTAT < 5005
i DIR: 5000/100) STARS

* - AL HOPKINS MESSAGES OF WINDOSIN (PAPA 200)

- BOE UPDATE < WETBULL OR QUIET
WETBULL OR ALORAY

->

- COPY OF WINDOSIN DATA
- COPY OF DECISION MATRIX
-

2008 6 17 9 10
GIC
7/1/08 5 08 018

BRAND - BRAKE FLUID & JET TESTING (4300)

(Signature)



- ✓ TEST & PROFILE UPDATE - AER
- ✓ REEVALUATE OUR PLANS - SAVE
 - DISPOSITION - d-H₂O
 - NEW DATA
 - H₂O
- PLASTIC PROCESS UPDATE - SAVE
 - ✓ HIGHER TEMP - PLAN BOUND
 - ✓ FLOW SPECS
- SALT VS OTHER IONS - SAVE
 - SMT - WHAT IS CYCLIC / AC
- BRACKE FLUID INHIBITORS - ACID
 - GIVE US OLD FLUID - 92 EXPAN
- PRESENTATION WEBS - AER
 - COIL ISSUE (IV)
 - LAMPENS EXPLAN.
- TEST / IGNITION PROCESS
 - VIDEO TAPE ✓ - SAVE
 - FLOW THICKS ✓

~~93 P/S~~

- SYS FMEA... WHY PARTS?
- ACT ON
- SWITCH
- ME PLAN →
- GOOD RATE

Date
CROWN Height

10/3/44 54

Measurements

77PSL2-1 : -27, -28 } 36656
 " 3-1 : -35, -41 }
 4-1 : -35, -41 }

77PS Discs

		CROWN	
36656 - 27	1	.0297	}
	2	.0295	
	3	.0300	
	4	.0299	
	5	.0299	
-28	1	.0311	}
	2	.0308	
	3	.0307	
	4	.0311	
	5	.0311	
-35	1	.0276	}
	2	.0277	
	3	.0273	
	4	.0275	
	5	.0274	
-41	1	.0299	}
	2	.0290	
	3	.0291	
	4	.0291	
	5	.0291	

50 SHEETS
100 SHEETS
200 SHEETS
25-101
25-102
25-103
25-104




Sample Cup

77ASL2-1

POE1

09/03/99

Decrimped (3) unused units
 placed on spacer
 → avoid on converter




22-103
 22-102
 22-104
 22-105

	1	2	3	4	5	6	7	8
S1	.0030	.0029	.0012	.0030	.0031	.0060	.0037	.0045
S2								
S3								



77ASL2-1



Slight pressure applied by a
 wobble on cup.

SAMPLE
 3022

H	1	2	3	4	5	6	7	8
.1955	.1948	.1947	.1957	.1964	.1950	.1957	.1945	.1950
.1984	.1946	.1960	.1942	.1962	.1930	.1951	.1952	.1862
.1983	.1949	.1961	.1954	.1962	.1954	.1959	.1945	.1851
.1990	.1953	.1949	.1954	.1953	.1952	.1956	.1962	.1865
.1890	.1936	.1947	.1951	.1959	.1957	.1955	.1962	.1862
.1940	.1953	.1956	.1958	.1968	.1956	.1961	.1959	.1862
.1890	.1957	.1960	.1962	.1979	.1959	.1967	.1959	.1967
.1890	.1962	.1965	.1962	.1977	.1958	.1963	.1960	.1864
.1879	.1959	.1964	.1959	.1967	.1859	.1964	.1963	.1972

77ASL4-1

2416 comb.
 hammer test.

S1

.1957	.1938	.1953	.1935	.1938	.1936	.1939	.1941	.1947
.1956	.1941	.1952	.1937	.1945	.1936	.1939	.1935	.1940
.1956	.1936	.1947	.1942	.1949	.1937	.1940	.1939	.1941
	Av. 1939	.1950	.1937	.1947	.1936	.1939	.1938	
.1955	.1940	.1942	.1936	.1942	.1939	.1942	.1941	.1895
.1854	.1941	.1930	.1940	.1949	.1943	.1949	.1934	.1944
.1854	.1938	.1949	.1934	.1939	.1934	.1938	.1932	.1936
.1950	.1929	.1932	.1929	.1927	.1931	.1939	.1935	.1070
.1950	.1929	.1934	.1925	.1924	.1927	.1932	.1930	
.1950	.1927	.1930	.1926	.1922	.1928	.1932	.1930	

S3

77PS Vacuum Dependency Matrix

TI Part Number	# sorted	fail out	% fail out	disc type	sup PT#	sup helots
77PBL3-1	1100	0	0.00	snap	27713-1	.090 - .092
77PBL3-3	no inventory			snap		
77PBL3-1			#DIV/0!	quiet	27713-1	.090 - .092
77PBL3-2	14000	18	0.13	quiet	27713-1	.090 - .092
77PBL3-3	1000	0	0.00	quiet	27288-1	.083 - .085
77PBL3-4	no inventory			quiet		
77PBL4-1			#DIV/0!	quiet	27713-2	.088 - .088
77PBL5-2	no inventory			quiet	27713-2	.088 - .088
77PBL6-1	no inventory			quiet	27713-2	.088 - .088

10:22 AM 12/10/99

TI-NHTSA 014440

77PBL-1 Return Analysis Sheet (Revised for Ford RTNs)
Revised 10/2000

Device ID: _____ Date: _____ Ford Part # _____

Operator's Name: _____ Ser Date Code: _____ Technician _____

VIN #: _____

1 Visual Inspection

General condition of Switch: Good Bad
 Signs of leakage into connector? No Yes
 Mating connector seal/ Foam Silicone
 connector? Yes No
 Wire harness repaired? Yes No
 Wire insulation connector? Yes No

2 Extract Bulb from pressure pot.

Activation pd No
 Polarity pd No
 Crimp time pd No
 Leak during and check? Yes No

3 Current draw:

Terminal to Terminal? Clrns m/A
 Terminal to Harness? m/A m/A
 14 Wire supply Current limited to 10 amps.

4 STOP for engineering review.

4 Open Oring Fling

5 Visual Inspection

Connector Leak? No Yes
 Component wear? None Light Medium Heavy
 IP leak? No Yes
 Environment seal condition? Good Bad
 If seal bad, Why?
 Connector? Yes No
 Pictures

6 Leak Test Sensor Assembly

Pass Fail

7 Open Out Oring.

8 Discharge Inspection

	Nearest Plug			Middle			Nearest Connector		
	Plug	#1	Connector	Plug	#2	Connector	Plug	#3	Connector
	Y/N	Reason	Y/N	Y/N	Reason	Y/N	Y/N	Reason	Y/N
Yellow wires									
Yellow ground									
Yellow communication									
Green wires									
Black wires									
White wires									
Wire harness condition									

9 Contact Inspection

Present Yes No
 Nickel/plating material Yes No
 Contact thickness Insuff Excess

10 Package and Store

77PBL-2-1 Return Analysis Sheet

Device ID: _____ Date: _____ Ford Part # _____

Operator's Name: _____ SW Date Code: _____ Technician: _____

1 Visual Inspection

General condition of SW/blk: Good Bad
 Signs of leakage into converter? No Yes
 Missing connector seal? Pass Stops
 compressor? Yes No
 Wire harness returned? Yes No
 Wire insulation compromised?

2 Current data:

Terminal to Terminal? Ohms
 Terminal to Harness? mA 14 Volt supply Current limited to 10 amps.

3 Open Oring Ring

4 Visual Inspection

Connector Leak? No Yes
 Component wear? None Light Medium Heavy
 BF leak? No Yes
 Environment seal condition? Good Bad
 Road test, VBY? Yes No
 Corrosion? Yes No
 Pictures

5 Leak Test Sensor Arm.

Pass Fail

6 Open Cup Oring.

7 Diaphragm Inspection

	Harvest Field			6846s			Harvest Converter		
	Field	#1	Converter	Field	#1	Converter	Field	#1	Converter
	Yellow	Green	Yellow	Yellow	Green	Yellow	Yellow	Green	Yellow
Yellow oring									
Yellow oring									
Yellow oring									
Green oring									
Green oring									
Yellow oring									

8 General Inspection

Present? Yes No
 Missing/missing material? Yes No
 General Malfunction

9 Package and Store

10 Analysis Summary: NTP None Observed

Employee Name		TITLE		GRADE		CLASSIFICATION		JOB DESCRIPTION		LOCATION		STATUS	
EMP ID	LAST NAME, FIRST	ORGANIZATION	POSITION	GRADE	CLASSIFICATION	JOB CODE	JOB TITLE	LOCATION	STATUS	START DATE	END DATE	REASON	REMARKS
1000001	SMITH, JOHN
1000002	SMITH, JOHN
1000003	SMITH, JOHN
1000004	SMITH, JOHN
1000005	SMITH, JOHN
1000006	SMITH, JOHN
1000007	SMITH, JOHN
1000008	SMITH, JOHN
1000009	SMITH, JOHN
1000010	SMITH, JOHN

TI-NM-TSA 014449