

EA02-025

**TEXAS INSTRUMENTS,
INC.'S 9/10/03
ATTACHMENT**

REQUEST NO. 7

BOX 8

PART A-U

PART F

-MSG# 50055 PA=MJS2 TO=COPY SENT=05/13/93 07:11 AM
ST=C DIV=0050 CC=00134 BY=MJS2 AT=05/13/93 07:11 AM

TO: ED KADISEVSKIS EKAD
GENE WEBER STEL
LOU ROCHA MAYR

CC: BILL SWEET WS4
DICK GRIEPEY RWG3
TERRY RODRIGUEZ TER7
JIM GRAMMER JB01
DAVE PERIPOLI ELTL
BOB BASILIERE ELTL

FR: MATT SELLERS MJS2

SJ: 57PS TESTER UPGRADE SCHEDULE

WE PLAN TO RESERVE 5/20/93 AND 5/21/93, (THUR. & FRI.), AS DOWNTIME
TO ALLOW COMPLETION OF YOUR INSTALLATION WORK FOR MWO # 6248.200.
5/22 AND 5/23 CAN BE USED AS NEEDED. THIS UPGRADE WILL ALLOW US TO
TEST ALL 77PS AND 87PS PRODUCT ON THE 57PS TESTER. ADDITIONALLY,
WE WILL WANT TO COMPLETE TABLE MODIFICATIONS THAT WILL ALLOW
INTERFERENCE FREE UNLOAD OF DEVICES WITH THE LONGER 34917-1
HEXPORT. i.e. 77PSL6-1, 57PSL11-2, 57PSL8-1, ETC. PLEASE SEE LOU
ROCHA OR ME FOR DIMENSIONAL DETAILS RELATED TO THIS CHANGE.

REGARDS . . . MATT
X1245

TI-NHTSA 011747

MECHANIZATION WORK ORDER

SHT. 1 OF 1

☐ Proposal
☐ Design
☒ Build

Date Requested

Origin

Requested By name

Matt Sellers 11/10/92 1237/245

Approved By

B. Hunt 11/13/92

Approved By 7 TPS

Date Entered

By MECHANIZATION

Project No.

253088011

Product Code

CC

REC'D. PRODUCT PRINT NOS.
SUPPLIED LIST

PROJECT DESCRIPTION

TPS FTM programming per memo # 306740
dated 11/10/92

Estimated 1 day work

Not to exceed 8 hours work

ADDITIONAL REMARKS, INFORMATION, SKETCH

MECH. TITLE

MECHANICAL

EST. HRS.

ELECTRICAL

EST. HRS.

PROJ. MGR.

PROJ. MGR.

ENG.

ENG.

DES.

TECH/DRAFT

BUILD EST. HRS.

BUILD EST. HRS.

BUILD CC

BUILD CC

DESIGN REVIEW

☐ DATE

DWG. SIGN OFF

☐ DATE

DESIGN CLOSED TO BUILD DATE

BY

ORDER CLOSED

DATE

BY

GEN. ASSY. DWG. NO. ASSIGNED

BUILD CLOSED

DATE

WHITE - MECHANIZATION COPY

YELLOW - ORIGINATOR'S COPY

TAMTSA 011748

P. 02

EC: Not signed
91
QUOTATION

May 17, 1964

34 Forest Avenue
Salem, MA 01970

James M. James Gordon

Form 44-1 (Rev. 10-1-65) (Use for all reports) (Page 1 of 1)
 Name: John A. Smith Address: 1234 Main St.
 City: Anytown, N.Y. State: N.Y. Zip: 10001
 Date: 10-1-65 Time: 10:00

File Name: 202505-000-1, Subtype: 24andover

Vertrieb: APL Ort: Arad Nr. 841

We quote you on the above part, subject to immediate acceptance and to the clauses printed below and on the back of this copy.

- Copying on Thick Paper
 A. 1 Sheet of 200 lb cover Cost \$20.00 per Sheet, Net
 B. The estimate delivery of 200 lb cover will be made after receipt of order.
 C. Quantity on Order Form
 A. In lots of 2,000,000 lb cover Sheet
 1,000,000 lb cover Sheet
 500,000 lb cover Sheet
 250,000 lb cover Sheet
 B. Taxes on paper are Net, F.O.B. NEW YORK, 1962
 C. The present stock on hand is 10,000,000 lb cover and has
 10,000,000 lb cover Sheet
 D. The estimated production per 8-hour shift per mold is 10,000 lb cover
 Sheet. We normally will run the mold equipment 2 shifts 4 days per week, and will try to run at least two shifts
 if conditions warrant doing so.
 E. Shipping weight per 10 sheets approximately 25 lb cover Sheet.
 1. Prototype sheet is necessary.
 2. Please see attached sheet with flash and tolerances necessary.
 3. The above-down price quotation is based upon current costs, subject to change
 recommended by value adjustments to material, labor and/or energy costs.
 4. Tool prices will be subject for review after thirty days.

**Power Vapors Truly
ACQUAINTS YOU WITH CIGARETTES**




Elizabeth Walsh, Sales Service Representative

THESE QUOTATIONS AND ACCEPTANCE THEREOF ARE SUBJECT TO ALL THE TERMS AND CONDITIONS CONTAINED ON THE RE

We maximize the opportunity of

TI-NHTSA 011749

Rev 1 EX34-23-68 Rubber Diaphragm 3/1/93 A4



Proof Pressure 4000 psi
 Burst Pressure 7000 psi
 Stroke .010" to .015" for diaphragm area (φ .474/.466)
 Working Fluid DOT 3 Brake Fluid on High Pressure Side
 Air on Low Pressure Side
 Cycle Life 500K cycles, 0-1450 psi, 2 Hz, 135°C
 in fluid with minimum reliability of
 91% at 90% confidence.
 Material E-Fluoro Propylene, DuPont 7045 Stone
 Fabric Reinforcement T-50


ZNR

 W2 00:20 00:10:00
 TOTAL P.03

TI-NHTSA 011750

THICKNESS - $\pm .003"$ $\Rightarrow$ 133 CPK
 $\pm .004"$ $\Rightarrow$ 2.00 CPK

DIAMETERS $\pm .005"$ $\Rightarrow$ 133 CPK
 $\pm .008"$ $\Rightarrow$ 2.00 CPK



TI - EX3423-68

EST # 8911

ACUSHNET CO.

J. A. T. [Signature]
10 MAY 93

SPC001
800201
#SPEC#

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
PARAMETER SPECIFICATIONS

SYID: IPC0781
DATE: 93/05/26
TIME: 12:49:57

process: 52SH2

description: SENSOR HEIGHT

employee id: 64009

maximum records: 1500 file full: STOP CONTINUE pct full: 100

usl: 0.30200 x ucl: 0.28874 r ucl: 0.00600

lsl: 0.27400 x lcl: 0.27738 r lcl: 0.00000

unnatural pattern checks: CURRENT EXTENDED NONE

use calculated limits: YES NO halt pending process change: YES NO

min observations: 5 max observations: 5

input format: NORMAL p-CHART (BAD/GOOD BAD/TOTAL)

control: X-RANGE X-SIGMA

f12

SPC001
S00201 Z
SPEC

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
PARAMETER SPECIFICATIONS

SYID: IPC0781
DATE: 93/05/26
TIME: 12:51:32

process: 57PS-HZ

description: SENSOR HT. AMI

employee id: 752025

maximum records: 1000 file full: STOP CONTINUE pct full: 100

ucl: 0.30200 x ucl: 0.29674 r ucl: 0.00600

lcl: 0.27400 x lcl: 0.27738 r lcl: 0.00000

un-natural pattern checks: CURRENT EXTENDED NONE

use calculated limits: YES NO halt pending process change: YES NO

min observations: 3 max observations: 5

input format: NORMAL p-CHART (BAD/GOOD BAD/TOTAL)

controls: X-RANGE X-SIGMA

f12

SPC001
S00201 TA
SPEC

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
PARAMETER SPECIFICATIONS

SYID: IPC0781
DATE: 93/05/26
TIME: 12:52:41

process: 77SENHTA

description: 77PS SENSOR HEIGHT employee id: 752025

maximum records: 1500 file full: STOP CONTINUE pct full: 62

usl: 0.30200 x ucl: 0.28874 r ucl: 0.00600

lsl: 0.24700 x lcl: 0.27738 r lcl: 0.00000

un-natural pattern checks: CURRENT EXTENDED NONE

use calculated limits: YES NO halt pending process change: YES NO

min observations: 5 max observations: 5

input format: NORMAL p-CHART (BAD/GOOD BAD/TOTAL)

control: X-RANGE X-SIGMA

F12

$$\bar{X} = 0.28306$$

$$\bar{R} = 0.00274$$

$$\sigma = 0.00189$$

$$3\sigma = 0.00568$$

Title: 57PS-HZ

SPC File Name: 57PS-HZ

* 0.2812		0.2860	*
* 0.2820	0.0032 Range	0.2830	0.0048 Range
* 0.2844	0.2829 X Bar	0.2820	0.2833 X Bar
* 0.2840		0.2812	
* 0.2828	1	0.2842	6

* 0.2816		0.2832	*
* 0.2802	0.0048 Range	0.2822	0.0032 Range
* 0.2824	0.2825 X Bar	0.2854	0.2831 X Bar
* 0.2832		0.2824	
* 0.2850	2	0.2822	7

* 0.2836		0.2804	*
* 0.2838	0.0024 Range	0.2804	0.0054 Range
* 0.2836	0.2830 X Bar	0.2834	0.2821 X Bar
* 0.2826		0.2806	
* 0.2814	3	0.2858	8

* 0.2848		0.2876	*
* 0.2808	0.0040 Range	0.2810	0.0076 Range
* 0.2838	0.2833 X Bar	0.2810	0.2820 X Bar
* 0.2838		* 0.2800	
* 0.2832	4	0.2804	9

* 0.2834		0.2834	*
* 0.2824	0.0058 Range	0.2830	0.0040 Range
* 0.2840	0.2844 X Bar	0.2824	0.2841 X Bar
* 0.2848		0.2864	
* 0.2832	5	0.2852	10


*****Total*****			
*Range Bar	0.0040	Range Bar	0.0050
*X Db1 Bar	0.2832	X Db1 Bar	0.2829

*****Sigma*****			
*3 Sigma	0.0048	3 Sigma	0.0063
*5 Sigma	0.0080	5 Sigma	0.0105

*****Control Limits*****			
*UCL X bar	0.286	UCL X bar	0.286
*LCL X bar	0.281	LCL X bar	0.280

*UCL Range	0.009	UCL Range	0.011
*LCL Range	0.000	LCL Range	0.000

*USL	0.2904	USL	0.2924
*LSL	0.2760	LSL	0.2734



(o)perator (p)lot overlay (e)very n (l)imits (z)ones (q)uit

E:\SP6872\^C

E:\SPC872\SPC

SPC005
S00501 Z
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC0781
DATE: 93/05/24
TIME: 13:32:23

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
93/05/24	08:51:04	725933	0.2812	0.0020 ✓	
93/05/24	05:23:12	749916	0.2820	0.0020 ✓	
93/05/21	18:55:31	750386	0.2844	0.0030 ✓	
93/05/21	17:50:32	750386	0.2840	0.0040 ✓	
93/05/21	16:46:37	750386	0.2828	0.0040 ✓	
93/05/21	03:17:21	749916	0.2816	0.0080 ✓	
93/05/21	01:57:51	749916	0.2802	0.0050 ✓	
93/05/21	01:05:19	749916	0.2824	0.0010 ✓	
93/05/20	19:04:33	750386	0.2832	0.0030 ✓	
93/05/20	18:06:08	750386	0.2850	0.0020 ✓	
93/05/20	17:00:28	750386	0.2836	0.0020 ✓	
93/05/20	11:35:17	724550	0.2838	0.0040 ✓	
93/05/20	10:39:53	725933	0.2836	0.0020 ✓	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6 f12

SPC005
S00501 Z
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC0781
DATE: 93/05/24
TIME: 13:33:40

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
93/05/20	03:32:17	749916	0.2826	0.0010 ✓	
93/05/20	01:27:22	749916	0.2814	0.0030 ✓	
93/05/19	13:03:56	724550	0.2848	0.0030 ✓	
00/05/19	00:59:05	749916	0.2808	0.0020 ✓	
00/05/18	23:44:44	750386	0.2838	0.0040 ✓	
00/05/18	22:52:06	750386	0.2838	0.0020 ✓	
00/05/18	21:16:14	750386	0.2832	0.0020 ✓	
00/05/18	17:23:05	750386	0.2834	0.0030 ✓	
00/05/18	13:55:52	724550	0.2824	0.0030 ✓	
00/05/18	11:41:29	724550	0.2840	0.0040 ✓	
00/05/18	10:50:21	724550	0.2840	0.0030 ✓	
00/05/18	09:36:05	724550	0.2882	0.0040 ✓	
00/05/18	08:39:40	724550	0.2860	0.0030 ✓	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6 f12

SPC005
S00501 Z
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC0781
DATE: 93/05/24
TIME: 13:34:08

TI-NHTSA 011757

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
00/05/18	05:05:36	749916	0.2830	0.0020	✓
00/05/18	04:05:47	749916	0.2820	0.0080	✓
00/05/18	00:54:19	749916	0.2812	0.0030	✓
00/05/17	23:52:44	750386	0.2842	0.0010	✓
00/05/17	16:14:30	750386	0.2832	0.0020	✓
00/05/17	14:17:16	725933	0.2822	0.0030	✓
00/05/17	07:59:48	725933	0.2854	0.0010	✓
00/05/17	05:01:02	749916	0.2824	0.0020	✓
00/05/17	04:06:30	749916	0.2822	0.0020	✓
00/05/17	02:17:34	749916	0.2804	0.0010	✓
00/05/17	01:26:48	749916	0.2804	0.0020	✓
00/05/15	16:58:22	750386	0.2834	0.0030	✓
00/05/15	14:51:59	750386	0.2806	0.0030	✓

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6

f12

SPC005
S00501 Z
DATA

STATISTICAL PROCESS CONTROL — 8087
RELEASE 2.86
EDIT DATA

SYID: IPC0781
DATE: 93/05/24
TIME: 13:34:36

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
00/05/14	09:20:01	724550	0.2858	0.0020	✓
00/05/14	08:01:32	724550	0.2876	0.0040	✓
00/05/14	05:07:55	749916	0.2810	0.0020	✓
00/05/14	03:49:34	749916	0.2810	0.0020	✓
00/05/14	02:31:15	749916	0.2800	0.0020	✓
00/05/14	01:00:07	749916	0.2804	0.0020	✓
00/05/13	23:51:29	750386	0.2834	0.0030	✓
00/05/13	22:32:07	750386	0.2830	0.0020	✓
00/05/13	16:16:16	750386	0.2824	0.0040	✓
00/05/13	15:08:55	57	0.2864	0.0060	✓
00/05/13	13:00:17	724550	0.2852	0.0050	✓
00/05/13	10:31:46	725933	0.2826	0.0010	✓
00/05/13	05:50:59	749916	0.2814	0.0010	✓

WRONG DATA P.WEE

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6

f12

THNTSA 011758

$$\bar{X} = 0.28430$$

$$\sigma = 0.00179$$


$$3\sigma = 0.00537$$

$$R = 0.00302$$

```

Title: 77SENHTA                      SPC File Name: 77SENHTA
*****
* 0.2828                                | 0.2850                                *
* 0.2836 0.0028 Range                    | 0.2854 0.0036 Range                    *
* 0.2828 0.2841 X Bar                    | 0.2838 0.2857 X Bar                    *
* 0.2856                                | 0.2874                                *
* 0.2858 1                               | 0.2868 6                               *
*****
* 0.2866                                | 0.2836                                *
* 0.2838 0.0028 Range                    | 0.2872 0.0044 Range                    *
* 0.2844 0.2850 X Bar                    | 0.2834 0.2841 X Bar                    *
* 0.2860                                | 0.2834                                *
* 0.2842 2                               | 0.2828 7                               *
*****
* 0.2860                                | 0.2822                                *
* 0.2832 0.0028 Range                    | 0.2818 0.0030 Range                    *
* 0.2836 0.2840 X Bar                    | 0.2838 0.2828 X Bar                    *
* 0.2836                                | 0.2816                                *
* 0.2836 3                               | 0.2846 8                               *
*****
* 0.2844                                | 0.2856                                *
* 0.2832 0.0012 Range                    | 0.2838 0.0060 Range                    *
* 0.2838 0.2837 X Bar                    | 0.2796 0.2832 X Bar                    *
* 0.2834                                | 0.2826                                *
* 0.2836 4                               | 0.2846 9                               *
*****
* 0.2838                                | 0.2852                                *
* 0.2842 0.0052 Range                    | 0.2814 0.0046 Range                    *
* 0.2866 0.2864 X Bar                    | 0.2834 0.2841 X Bar                    *
* 0.2882                                | 0.2846                                *
* 0.2890 5                               | 0.2860 10                              *
*****
*****Total*****Total*****
*Range Bar 0.0030                      |Range Bar 0.0043                      *
*X Dbl Bar 0.2846                      |X Dbl Bar 0.2840                      *
*****
*****Sigma*****Sigma*****
*3 Sigma 0.0049                        |3 Sigma 0.0056                        *
*5 Sigma 0.0081                        |5 Sigma 0.0093                        *
*****
*****Control Limits*****Control Limits*****
*UCL X bar 0.286                        |UCL X bar 0.286                        *
*LCL X bar 0.283                        |LCL X bar 0.281                        *
*****
*UCL Range 0.006                        |UCL Range 0.009                        *
*LCL Range 0.000                        |LCL Range 0.000                        *
*****
*USL 0.2919                            |USL 0.2923                            *
*LSL 0.2773                            |LSL 0.2756                            *
*****

```



(s)cale (o)perator XXXXXXXXXX (e)very n (l)imits (z)ones (q)uit

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
10/05/14	22:40:45	750386	0.2854	0.0050	
10/05/14	19:23:37	750386	0.2838	0.0020	
10/05/14	11:12:29	724550	0.2874	0.0030	
10/05/14	10:06:28	724550	0.2868	0.0010	
10/05/13	21:05:49	750386	0.2836	0.0030	
10/05/13	19:50:53	750586	0.2872	0.0040	
10/05/13	18:34:33	750386	0.2834	0.0030	
10/05/13	17:35:17	750386	0.2834	0.0030	
10/05/12	21:23:21	750386	0.2828	0.0020	
10/05/12	20:43:06	750386	0.2822	0.0020	
10/05/12	04:17:19	749916	0.2818	0.0030	
10/05/12	01:47:39	749916	0.2838	0.0010	
10/05/12	00:49:17	749916	0.2816	0.0010	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6 f12

PC005 STATISTICAL PROCESS CONTROL -- 8087
 00501 RELEASE 2.86
 DATA* EDIT DATA
 SYID: IPC07814
 DATE: 93/05/24
 TIME: 13:42:55

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
00/05/10	18:08:36	750386	0.2846	0.0010	
00/05/10	17:06:47	750586	0.2856	0.0070	
00/05/10	15:57:17	750386	0.2838	0.0030	
00/05/08	00:52:16	749916	0.2796	0.0030	
93/05/07	23:10:42	750386	0.2826	0.0050	
93/05/07	22:03:31	750386	0.2846	0.0010	
93/05/07	20:15:55	750386	0.2852	0.0020	
93/05/07	18:48:01	750386	0.2814	0.0020	
93/05/07	00:44:54	749916	0.2834	0.0010	
93/05/06	23:22:16	750586	0.2834	0.0050	
93/05/06	22:30:33	750386	0.2860	0.0050	
93/05/06	21:35:51	750586	0.2846	0.0040	
93/05/05	17:44:36	750386	0.2816	0.0040	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6 f12

TI-NHTSA 011762

SPC005
S00501 TA
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC0781
DATE: 93/05/24
TIME: 13:38:40

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
93/05/21	22:20:04	750386	0.2828	0.0020	
93/05/21	21:35:38	750386	0.2836	0.0040	
93/05/21	20:30:52	750386	0.2828	0.0020	✓
93/05/21	15:47:07	750386	0.2856	0.0050	
93/05/21	14:37:07	724550	0.2856	0.0030	
93/05/21	12:55:38	724550	0.2866	0.0030	
93/05/21	12:04:18	724550	0.2838	0.0040	✓
93/05/20	22:48:44	750386	0.2844	0.0040	
93/05/20	21:52:05	750586	0.2860	0.0050	
93/05/20	20:53:27	750386	0.2842	0.0040	
93/05/20	10:39:34	725933	0.2860	0.0020	
93/05/19	23:13:32	750386	0.2832	0.0020	
93/05/19	22:17:50	750386	0.2836	0.0040	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6

f12

E:\SPC87>SPC#4

SPC005
S00501
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC07814
DATE: 93/05/24
TIME: 13:41:42

DATE	TIME	EMPLOYEE ID	MEAN	RANGE	COMMENT
93/05/19	21:23:50	750386	0.2836	0.0040	✓
93/05/19	20:15:09	750586	0.2866	0.0050	
00/05/17	22:38:14	750386	0.2844	0.0030	
00/05/17	21:39:39	750386	0.2832	0.0020	
00/05/17	20:40:54	750386	0.2838	0.0020	✓
00/05/17	18:40:24	750386	0.2834	0.0030	
00/05/15	13:47:42	750386	0.2836	0.0040	
00/05/15	12:54:37	750386	0.2838	0.0020	
00/05/15	11:30:29	725933	0.2842	0.0030	
00/05/15	10:41:21	725933	0.2866	0.0030	
00/05/15	09:36:43	725933	0.2882	0.0030	
00/05/15	08:15:25	725933	0.2890	0.0030	
00/05/14	23:34:55	750386	0.2850	0.0020	

(e)dit (g)raph (t)op (b)ottom (q)uit

f5 f6

f12

SPC005
S00501
DATA

STATISTICAL PROCESS CONTROL -- 8087
RELEASE 2.86
EDIT DATA

SYID: IPC07814
DATE: 93/05/24
TIME: 13:42:22

TI-NHTSA 011763

JUNE 2, 1993

MNO #253060218

TO: MATT SHILLERS

CC: BILL SWEET
TIM SPOONER
LOU ROCHA
JOHN KOURTESIS

BOB BARTOSH
STEAN STELIGA
BOB VIENS

FROM: ANDRE CHARPENTIER
ED RADISEVSKIS

SUBJ: PROPOSAL TO MODIFY 57PS ROTARY PRESSURE TESTER (UPGRADE OF PREVIOUS PROPOSAL OF NOV. 19, 1992)

DESCRIPTION MECHANICAL

THE OBJECT IS TO CONVERT THIS INTO A "UNIVERSAL" TESTER TO ACCEPT 52, 57, 77, 78, 87, NISSAN, HONDA, AND FUTURE PS DEVICES WITH LARGER BASES, WITH MINIMUM SET-UP CHANGES.

THE FOLLOWING MODIFICATIONS WILL BE REQUIRED:

1. LONGER STROKE SEAL CYLINDERS, AND LONGER SEAL HOLDERS TO ACCOMMODATE A GREATER VARIETY OF HEXPORT LENGTHS.
2. NEW HST INSERTS (12), (PERMANENT, NOT TO BE CHANGED FOR DIFFERENT PRODUCTS).
3. NEW HOLD-DOWNS (12), WITH INSERTS (12). THESE INSERTS MAY HAVE TO BE CHANGED FOR SOME FUTURE BASES.
4. MODIFIED TEST STATION FRAME MEMBERS.
5. ADDED PROBE CYLINDERS (4), WITH MOUNTS.
6. NEW "QUICK-CHANGE" PROBE INSULATORS WITH GUIDE SYSTEM.
7. NEW HIGHER "BREAD BOX" GUARD (SIMILAR TO THE ONE ON THE 77PS TESTER). THIS REQUIRES MODIFYING THE FRAME WEDGMENT.

DESCRIPTION ELECTRICAL

THIS PROPOSAL COVERS THE CONVERSION OF THE 57PS, TM990 CONTROLLED ROTARY PRESSURE TESTER TO VAXELN BASED CONTROL SIMILAR TO THE 77PS PRESSURE TESTER. THE CONTROLLING COMPUTER WILL BE CHANGED AS WELL AS THE TOUCH SCREEN CRT AND THE PRINTER. MOST OF THE EXISTING GNT I/O WIRING WILL BE LEFT INTACT AND THE GNT RACKS INTERFACED TO THE NEW COMPUTER. THE PRODUCT CONTINUITY AND CRIMP DETECTION CIRCUITS WILL BE CHANGED TO BE THE SAME AS THE 77PS TESTER. THIS TESTER WILL ONLY HAVE THE FEATURES THAT ARE PRESENTLY ON THE 77PS TESTER. ANY OTHER FEATURES WILL HAVE TO BE QUOTED.

ESTIMATED COST

MECHANICAL

ENGINEERING	50 HRS @ \$57	\$2.8K	
DESIGN	190 HRS @ \$46	8.7	
PURCHASE PARTS			2.0
BUILD	750 HRS @ \$39		29.2
DEBUG	20 HRS @ \$57		1.1
		<u>\$11.5K</u>	<u>\$32.3K</u>

TI-NHTSA 011785

ESTIMATED COST FOR CONTROL CONVERSION FOR 57PS TESTER:

ELECTRICAL

DESIGN	200 HRS @ \$57	\$11.4K	
DRAFTING	25 HRS @ \$46	1.2	
PURCHASE PARTS			20.0
BUILD	180 HRS @ \$39		7.0
DEBUG	40 HRS @ \$57		2.3
		<u>\$12.6K</u>	<u>\$29.3K</u>

TOTALS:	EXPENSE \$24.1K	CAPITAL \$61.6K
ADD 10% CONTINGENCY:	<u>2.4</u>	<u>6.2</u>
TOTALS:	EXPENSE \$26.5K	CAPITAL \$67.8K

THIS MODIFICATION WILL ENABLE THE MACHINE TO TEST ALL ABOVE-LISTED DEVICES WITHOUT MECHANICAL SET-UP CHARGES, EXCEPT THE 78PS.

78PS

THE 78PS DEVICE WILL REQUIRE A SEAL CHANGE, PLUS INSERT LINERS FOR BOTH THE NIBS AND THE HOLD-DOWNS. THESE LINERS WILL BE HELD IN BY MAGNETS. 78PS WILL BE UNLOADED BY THE OPERATOR.

ESTIMATED COST TO TEST 78PS:

DESIGN	20 HRS @ \$46	\$.9K	
MATERIAL			.6
BUILD	280 HRS @ \$39	<u>\$.9K</u>	<u>7.0</u>
			<u>\$7.6K</u>
TOTALS:		\$.9K	\$7.6K
ADD 5% CONTINGENCY:			.4
TOTALS:	EXPENSE	<u>\$.9K</u>	CAPITAL <u>\$8.0K</u>

VOLVO AND 88PS

THESE DEVICES WILL REQUIRE THEIR OWN INSERT LINERS FOR THE HOLD-DOWNS ONLY.

DESIGN	20 HRS @ \$46	\$.9K	
MATERIAL			.5
BUILD	140 HRS @ \$39	<u>\$.9K</u>	<u>5.5</u>
			<u>\$6.0K</u>
TOTALS:		\$.9K	\$6.0K
ADD 5% CONTINGENCY:			.5
TOTALS:	EXPENSE	<u>\$.9K</u>	CAPITAL <u>\$6.5K</u>

TEST PNEUMATICS UPGRADE**THE REASONS FOR DOING THIS ARE:**

1. REDUCE DOWNTIME AND R/M COST BY REPLACING OLD SKINNER VALVES WITH NEW ROTARY VALVES.
2. ADD LOW PRESSURE CAPABILITY BY ADDING A 100PSI TRANSDUCER AND SMC VOLTAGE CONTROLLED REGULATOR TO GET RELIABLE PRESSURE RAMP.

ENGINEERING	10 HRS @ \$57	\$.6K	
DESIGN	15 HRS @ \$46	.7	
PARTS			5.0
BUILD	60 HRS @ \$39		<u>2.3</u>
		\$1.3K	\$7.3K
	TOTALS:	\$1.3K	\$7.3
	ADD 5% CONTINGENCY:		<u>.4</u>
	TOTALS:	EXPENSE \$1.3K	CAPITAL \$7.7K

GRAND TOTALS OF ALL ITEMS: EXPENSE \$29.6K CAPITAL \$90.0K

THIS IS NOT A FIXED COST PROPOSAL DUE TO THE UNKNOWN INHERENT IN REBUILDING AN EXISTING MACHINE. FIVE TO SEVEN WEEKS DOWNTIME WILL BE REQUIRED. THAT INCLUDES INSTALLING ALL ABOVE OPTIONS.

APPROVALS:

 6/2/93
JOHN KOURTESIS

 6/2/93
JOHN GORNLEY

 6/2/93
STAN STELIGA

TI-NHTSA 011767

MEMORANDUM

JUNE 9, 1993

F-5.4

TO: ANDY NOGURIK
MIKE DEMATTIA
JIM MATT
NORM FRED
STEVE MAJOR
GARY SNYDER
MARSHA SULLIVAN
DAN KOST

FM: JIM WOOD

SJ: FORD Q1 QUALITY SYSTEM SURVEY REPORT

Attached, for your records, is a copy of the Ford Q1 Report for the June 2-4 Q1 Survey.

Regards,


Jim Wood

Attachment

TI 0019125

TI-NHTSA 011768

Quality System Survey Report

Sheet of 7

Company/Department Group CCD/ELD		System Survey Rating - 196	Survey No. 93-1	Date 6/4/93
To		Producer personnel contacted		
Producer name Texas Instruments		Wood, McGuirk, Watt, DeMattis, Forsyth, Garlepy, Sweet, Chamberker, Bartosh, Congdon, Strott, Charboneau, Sullivan, Beringhouse, Czarn, Lesser, Freda, Kost		
Product Precision Controls		Description of product Pressure Switches and Switches		
Address 34 Forest Street				
City and state Attleboro, MA				
Producer in conformance with Ford Q-101		Survey representative signature(s)		
Corrective action required		Mike Hamm CCD		
Purchasing assistance required		Joan Florian CCU		
Producer acknowledgment signature <i>Paul Perry</i>		San Khoury ELD		
Copies to John Bros Purchasing: Larry Klemczak Product Engineering: Fred Schroeder Customer Parts:				
For each question, provide complete descriptive comments. Then assign a rating using the System Survey Scoring Guidelines.				Rating
PLANNING FOR QUALITY				
1. Is the responsibility for quality planning on new products clearly defined? Does the definition of responsibility make sense for the processes involved?				
• Describe the responsible organization.				
• Indicate reporting relationships.				
• Indicate the key contact personnel/department for quality planning and quality concern resolution.				10
2. Are Control Plans, Process Failure Mode and Effects Analyses, and other documented methods used as a basis for establishing quality programs for new (and specifically-identified existing) products?				
• Does the producer perform feasibility analysis on potential new products?				10
• Assess the adequacy of the producer's quality planning effort.				
3. Does the producer have available and use a procedure for reviewing design and process changes prior to implementation?				
• Are FMEAs and Control Plans reviewed and updated as part of this procedure?				
• Is customer approval obtained prior to implementing change?				
• Is there a procedure for updating operator instructions and visual aids for process and product changes?				10
TOTAL PLANNING FOR QUALITY (Total points available = 30) =				30
STATISTICAL METHODS				
4. Is Statistical Process Control (SPC) utilized for significant and Critical () product characteristics and process parameters?				
• How are the significant characteristics chosen?				
• Describe the SPC methods used? Are they appropriate to the processes being controlled?				
• Evaluate the producer's reaction to out-of-control conditions. Is the reaction as specified in the Control Plan? What is the role of the operators? Of the supervisors?				
Evaluate the producer's application of SPC, based on the evidence of the control charts, process logs, and other appropriate documentation.				10

T: 0619126

Quality System Survey Report

Sheet 2 of 7

Producer	Date
STATISTICAL METHODS (Continued)	
5. Are preliminary statistical studies conducted on new product characteristics and process parameters?	Rating <u>10</u>
6. Are control charts being used effectively to monitor the processes? Do the charts indicate that statistical control has been achieved and that process capability has been demonstrated? • In all cases where process capability has not yet been demonstrated, is there a plan to improve the process? Is appropriate interim action (i.e., 100% inspection) being taken to prevent shipment of nonconforming parts.	<u>9</u>
7. Does the producer have a definite program to bring about continual improvement in quality and productivity? • Describe the program. Indicate the statistical methods and other tools used to promote continual improvement. • Are there improvement priorities identified and project teams established?	<u>10</u>
8. Does the producer have an effective system for assuring the quality of incoming products and services (e.g., plating, heat treating). • Are suppliers encouraged to meet Q-101 requirements? • Are suppliers encouraged to use SPC? Is evidence of statistical control and capability required from producers? • Assess the adequacy of the incoming material quality system?	<u>10</u> <u>49</u>
TOTAL STATISTICAL METHODS (Total points available = 50) —	
GENERAL	
9. Are process/product auditing functions and responsibilities clearly defined? • Indicate which plant activities conduct process/product auditing (e.g., quality inspectors, production operators, laboratory technicians). Assess the adequacy of the producer's auditing program.	<u>10</u>
10. Are written procedures defining the significant quality-related functions available (i.e., a quality manual)? • Are these procedures appropriate to and adequate for the producer's operations? (e.g., is there an adequate procedure for reacting to ES test failures?) • Are the procedures implemented as written? • Is there a formal review system to verify implementation?	<u>10</u>
11. Are written process monitoring and control instructions available for incoming, in-process, laboratory, layout inspection and outgoing auditing? • Are all Critical and Significant characteristics included, specifically those affecting function, durability and appearance? • Are Control Items, their Critical Characteristics and related operations identified with the inverted delta symbol? • Are sample sizes and frequencies adequate? • Is appropriate statistical analysis specified?	<u>10</u>
12. Are appropriate gages, measuring facilities, laboratory equipment, and test equipment available to facilitate process control? • Is the selection of significant characteristics effectively incorporated in gage planning and design? • Are gages and test equipment and personnel appropriately located throughout the producer's operations? • Are adequate, well-lighted areas available for gaging, measuring, and testing the product? Evaluate the producer's gage planning and execution.	<u>10</u>

T1055F127

Quality Sec 25 2955-1

T1-NHTSA 011770



Quality System Survey Report

Sheet 3 of 7

Producer		Date
GENERAL (Continued)		Rating
13. Does the producer have an effective gage and test equipment maintenance program? - Are new gages/test equipment inspected to design specifications, calibrated and approved before being used? - Do records indicate that gages and test equipment are periodically inspected and calibrated? - Does the producer use statistical methods to determine the stability and capability of gages, measuring, and test equipment? Assess the adequacy of the producer's gage and test equipment maintenance program.		10
14. What controls does the producer use to indicate the processing and inspection status of products throughout the producer's system? - Are effective controls in place to provide accurate part number identification throughout processing, storage, packaging and shipping? - Are controls adequate to prevent movement of rejected incoming materials into the production system? - Are nonconforming products separated from the stream of production? Are there effective controls to prevent their movement?		9
15. Does the producer have complete records supporting initial sample certifications?		10
16. Does the producer react appropriately to customer concerns? - Are in-plant and customer quality concerns effectively communicated to all members of the organization? - Are nonconforming parts returned by customers analyzed? Is the root cause of failure determined, verified, and corrective action taken? - Is a disciplined method of problem solving (the Eight Discipline Method) utilized?		10
TOTAL GENERAL (Total points available = 50) =		49
IN-PROCESS AND OUTGOING		79
17. Are inspections, measurements, and tests being performed according to the instructions? Are there adequate records of inspections, measurements, and tests?		10
18. Are documented rework and/or scrap procedures and standards available? Are reworked or sorted products audited for conformance to all customer requirements? Assess the adequacy of rework and sorting operations.		9
19. Are the handling, storage and packing adequate to preserve product quality? - For production and service parts, does the producer meet applicable packaging specifications? - Are effective controls in place to assure correct service part identification?		10
20. Are plant cleanliness, housekeeping, environmental, and working conditions conducive to quality improvement? - Are there working conditions that could be detrimental to quality improvement? - What actions have been taken to mitigate these factors?		9
TOTAL INCOMING, IN-PROCESS and OUTGOING (Total points available = 40) =		38
TOTAL RATING POINTS FROM QUESTIONS 1-20 (Maximum = 200 points) =		196

TI-NHTSA 011771

SQA Survey Report

Sheet 5 of 7

Supplier	Texas Instruments	Survey No.	93-1	Date	6/4/93
----------	-------------------	------------	------	------	--------

Item/Ref. No.	Supplemental Remarks and Supplier Commitments
---------------	---

14 Improper labeling of boxes found, out of place boxes found, wrong color code bins used for questionable status stock.

- Institute across the board uniform color coded stock bins.
- Awareness of possible mishandling of bad or questionable stock while production area is in a reorganizational/transition status.
- More refined reject tracability (i.e., to operator level)
- In interim suggest use of red bins in reject area (APT line) or paint cardboard red.


TI-NHTSA 011773

Page 6 of 7

[illegible]

TI-NHTSA-011774

2955-2



Ford Motor Company
Climate Control Division
Supplier Quality Report Card



TEXAS INSTRUMENTS

34 FOREST ST

ATTLEBORO, MA 01703 A9HZE

Quality Expectation

Zero Defects

Quality Tools

Advanced Quality Planning
Quality Operating System
Management Involvement
Correlation to Customer Requirements
Minimizing Parts per Million
Quality Driven Compensation

Number of Parts Sourced	SQC Engineer	Buyer	Q-1	System Survey Score	System Survey Date	1991 Rejections	1992 Rejections	1993 Rejections
5	Mike Hume (313) 451-9820	Larry Klamczak (313) 451-9890	Yes	196	930611			

For your 1993 Quality Performance, Ford Motor Company appreciates your persistence and your continued effort toward quality improvement.

1993 Quality Reject Summary

TEXAS INSTRUMENTS A9HZE

Quality Rejection Origin	Quality Rejection Number	Part Number	Reject Date	Remarks

TI-NHTSA 011776

TO: BILL SWEET 12-29
 MARY SWEET 12-29

CC: JOHN GORMLEY 20-25
 JOHN KOURTESIS 20-25
 LOUIS ROCHA 12-20
 STAN STELIGA 20-01

FROM: ANDRE CHARPENTIER 20-25

SUBJECT: PROPOSAL FOR CONVERTING THE 55PS/56PS TM990 CONTROLLED
 PRESSURE TESTER TO A VAXELN CONTROLLED TESTER

This proposal covers the conversion of the 55PS/56PS, TM990 controlled rotary pressure tester to VAXELN based control similar to the 77PS pressure tester. The controlling computer will be changed as well as the touch screen crt and the printer. Most of the existing 6MT i/o wiring will be left intact and the 6MT racks interfaced to the new computer. The product continuity and creep detection circuits will be changed to be the same as the 77PS tester. This tester will only have the features that are presently on the 77PS tester. Any other features will have to be quoted.

Estimated cost for control conversion for 55PS/56PS tester:

DESIGN	RATE HRS	
ELEC DES TOTAL	\$58 300	\$17,400
DRAFTING	\$47 40	\$1,880
EXPENSE TOTAL		\$19,280

DESIGN	RATE HRS	
DEBUG	\$58 120	\$6,960
BUILD	\$40 220	\$8,800
PARTS		\$31,460
CAPITAL TOTAL		\$47,220

PROJECT TOTAL	\$66.5K
---------------	---------

APPROVALS:

JOHN GORMLEY

JOHN KOURTESIS

STAN STELIGA

John Gormley 6/7/93
John Kourtesis 6/2/93
Stan Steliga 6/8/93

TI-NHTSA 011777

MECHANIZATION WORK ORDER

SHT. 1 OF 1

Date Entered

FORM 20222

- ☐ Proposal
☒ Design
☐ Build

Date Requested

Requested By (Print)

Date Mail Sls. Tel. Ext.

By MECHANIZATION

Project No.

mtt Sellers 6-30-93 1239 1245

Approved By

K. Sweet 7/1/93

DEPARTMENT 15705

Product Code 060

CC 253

REQ'D. PRODUCT PRINT NOS.
SUPPLIED LIST

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	

PROJECT DESCRIPTION

Design work only for 5705 Tester upgrades
 per Ed K. proposal 253060218 dated 6-2-93

MECH. TITLE

MECHANICAL

EST. HRS.

ELECTRICAL

EST. HRS.

PROJ. MGR.

PROJ. MGR.

ENG.

ENG.

DRA.

TECH/DRAFT

BUILD EST. HRS.

BUILD EST. HRS.

BUILD CC

DATE

BUILD CC

DATE

DESIGN REVIEW

☐

DATE

DWG. SIGN OFF

☐

DATE

DESIGN CLOSED TO BUILD DATE

BY

ORDER CLOSED

DATE

BY

GEN. ASSY. DWG. NO. ASSIGNED

BUILD CLOSED

DATE

ADDITIONAL REMARKS, INFORMATION, SKETCH

TI-NHTSA 011778

WHITE - MECHANIZATION COPY

YELLOW - ORIGINATOR'S COPY

77PS BASE ASSEMBLY MACHINE LOT REPORT

LOT ID:6-15
 DEVICE ID:77PSL2-1
 LOT STARTED:14-JUN-1993 23:35:29.80
 LOT FINISHED:15-JUN-1993 02:35:08.76
 DURATION: 0 02:59:38.96

CALIBRATION SETUP PARAMETERS

INITIAL CAL -84.25 MILS
 MODIFIED CAL -84.25 MILS CAL TOLERANCE: 0.20 MILS
 CHK POINT: -88.25 MILS CHK TOLERANCE: 1.75 MILS
 CHECK MEAS SORT LIMIT: DISABLED
 CAL/CHK DIFFERENCE LIMIT: DISABLED

SPRINGBACK AT MODE DISABLED

CHECK FEEDBACK AT MODE DISABL
 DEFAULT SPRINGBACK: 1.00 MILS FINAL SPRINGBACK: 0.00 MILS

TOTAL PIECES CYCLED	2637	
PIECES GOOD	2594	98.37 %
PIECES GOOD (STA DISABLED)	0	0.00 %
PIECES BAD	43	1.63 %
NO BASE	9	0.34 %
NO STA TERM	23	0.87 %
NO STAKE STA TERM	0	0.00 %
NO MOV TERM	2	0.08 %
NO STAKE MOV TERM	0	0.00 %
NO CONTACT	0	0.00 %
FAILED CALIBRATION	0	0.00 %
FAILED CAL CHECK	9	0.34 %
CAL/CHK DIFF FAILURE	0	0.00 %
FAILED UNLOAD	0	0.00 %
EMERGENCY STOP	0	0.00 %
SPRING ARM MISFEEDS	28	
CALIBRATION CYCLES	0	
EFFECTIVITY		48.14 %

INITIAL MEAS DATA	MEAN	SIGMA	COUNT
	-75.12	0.78	2603

CALIBRATED DATA	MEAN	SIGMA	CPK	COUNT
-----------------	------	-------	-----	-------

TL-NHTSA 011779

77PS BASE ASSEMBLY MACHINE DOWNTIME REPORT

LOT ID: 6-15
 DEVICE ID: 77PSL2-1
 START TIME: 14-JUN-1993 23:35:29.80
 FINISH TIME: 15-JUN-1993 02:35:05.76
 DURATION: 0 02:59:35.96

CODE	DOWNTIME REASON	OCCURENCES	AVG	TOTAL	% OF RUN	% OF DOWN
✓3	STATION 3 LOAD STA-TERM	16	2.51	40.12	22.3	63.1
41	CYCLE STOP	12	0.83	9.98	5.6	15.7
✓9	STATION 9 LOAD MOV-TERM	10	0.88	8.76	4.9	13.8
✓13	STATION 13	6	0.38	2.31	1.3	3.6
✓2	STATION 2 SENSE BASE	2	0.64	1.28	0.7	2.0
37	ZONE GUARD INTRUSION	1	0.77	0.77	0.4	1.2
31	MACHINE SETUP	1	0.34	0.34	0.2	0.5
TOTAL DOWNTIME OCCURENCES		48	1.32	63.56	35.4	100.0

- 134
 63.56

**FORD NEXT GENERATION SPEED CONTROL (77PS)
MANUFACTURING CONTROL PLAN
77PSL QUIET SWITCH**

PROCESS STEP DESCRIPTION	PRODUCT CHARACTERISTICS	EVALUATION METHOD	CONTROL METHOD	FREQUENCY OF TEST	REACTION PLAN
BASE ASSEMBLY (AMP AUTOMATION)	TERMINAL HEIGHT	DIAL INDICATOR	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	TERMINAL PUSHOUT	FORCE GAGE/ DIAL INDICATOR	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	TERMINAL SEPARATION/ ALIGNMENT	PLUG GAGE	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	SPRING ANGLE (B)	COMPARATOR	X/R	5pc/4Hr.	SORT SINCE LAST CHECK
	SPRING CONTACT WIDTH	CALIPERS	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	SPRING TORQUE	FORCE GAGE	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	SPRING BUMP HIGHT (B)	CALIPERS	X/R	5pc/4Hr.	SORT SINCE LAST CHECK
	PIVOT HEIGHT	DIAL INDICATOR	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	CALIBRATION DEFORMATION	CUSTOM CONTINUITY SYSTEM	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	VISUAL QUALITY (C)	VISUAL	P	5pc/Hr.	SORT SINCE LAST CHECK
SENSOR ASSEMBLY	CRIMP DIAMETER	CALIPERS	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	CRIMP HEIGHT	CALIPERS	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	VISUAL QUALITY	VISUAL	P	5pc/Hr.	SORT SINCE LAST CHECK

Revision: C

13 July 1993 MJS/cnr 77CONTLF.XLS 050-0134

TT-NHTSA 011781

**FORD NEXT GENERATION SPEED CONTROL (77PS)
MANUFACTURING CONTROL PLAN
77PSL QUIET SWITCH**

PROCESS STEP DESCRIPTION	PRODUCT CHARACTERISTICS	EVALUATION METHOD	CONTROL METHOD	FREQUENCY OF TEST	REACTION PLAN
FINAL ASSEMBLY (AME AUTOMATION)	CRIMP DIAMETER (B)	GO/NO-GO GAGE	P	5pc/Hr.	SORT SINCE LAST CHECK
	CRIMP HEIGHT (B)	GO/NO-GO GAGE	P	5pc/Hr.	SORT SINCE LAST CHECK
	BASF TORQUE	TORQUE GAGE	X/R	5pc/Hr.	SORT SINCE LAST CHECK
	CODE CRIMP RING/ DIAMETER-LEGIBILITY	PLUG-VISUAL	P	5pc/Hr.	SORT SINCE LAST CHECK
	PIN HEIGHT (B)	DIAL INDICATOR	P	100%	SEPARATE FAILED LOT, PRODUCT TEAM REVIEW
FUNCTION TESTER (CUSTOM)	ACTUATION/RELEASE POINTS (Ford Significant Char.)	MASTERS	X/R	EACH SHFT	E N G I N E E R I N G EVALUATIONS
	ACTUATION/RELEASE POINTS (C) (Ford Significant Char.)	RAMP THROUGH PRESSURE RANGE	P	100%	YIELD TRACKING/ SCRAP CONTROL
PRODUCT AUDITS (PRODUCTION)	HIGH PINNING (B)	CUSTOM HYPOT SYSTEM/P		20PC/LOT	SEPARATE FAILED LOT, PRODUCT TEAM REVIEW
	LOW PINNING (B)	OVER/CONT METER	P	10pc/Lot	SEPARATE FAILED LOT, PRODUCT TEAM REVIEW
Q C AUDITS (C)	- OUTLINED IN DETAIL IN TEXAS INSTRUMENTS (QAS 208), FMC (THREADS / Ford Significant Char.) - ELEVATED TEMP IMPULSE CYCLING AUDITS. FREQUENCY TBD. PER DELTA ES-F2VC-9F924-AA SEC III-E				

Revision. C

13 July 1993 MJS:mjs 77QCONT.B.XLS 050-0134

714NHTSA 011782

-MSG# 74242 FR=MJS2 TO=COPY SENT=07/15/93 10:40 AM
ST=C DIV=0050 CC=00134 BY=MJS2 AT=07/15/93 10:40 AM

TO: JIM WATT JWO2

CC: ELAINE ROSE GARY CHARLIE DOUGLAS CMP1
BILL SWEET WS4 DAVE CZARN ZARN
DICK GARTY RAG3 AZIZ RAHMAN ZIZ

FR: MATT SELLERS MJS2

RE: 77PS/87PS IMPULSE TESTING

JIM,

PLEASE EVALUATE THE FOLLOWING PROPOSAL FOR REORGANIZING THE
SUBMISSION PLAN FOR ALL 77PS AND 87PS DEVICES. THE NEED IS
TO STREAMLINE THE PROCESS WHILE MAINTAINING ADHERENCE TO ES
GUIDELINES AND ENGINEERING CONCERNS OVER SPRING & DISC LIFE.

IF THE PLAN OUTLINED BELOW DOES NOT SATISFY ES OR GAS REQUIREMENTS,
PLEASE HIGHLIGHT THE AREAS OF CONFLICT AND RETURN. I AM CONFIDENT
THAT THIS NEW PLAN WILL SATISFY ENGINEERING CONCERNS AND ACTUALLY
WILL IMPROVE THE REAL TIME ASPECT OF REPORTING.

PROPOSED SAMPLE SUBMISSION PLAN

CONCERNED ES SPECIFICATIONS: 9F924 (77PS) & 3N824 (87PS)

IP-2 FUNCTIONAL TEST

RECOMMEND SUBMISSION OF (4) DEVICES FROM EACH ASSIGNED SENSOR LOT,
(2000 DEVICES). G.C. TO PERFORM ALL REQUIRED FUNCTIONAL TEST AND
REPORT RESULTS BACK TO PRODUCTION.

NOTE: THIS SUBMISSION FREQUENCY ACTUALLY SURPASSES 3N824
REQUIREMENT.

IP-2 DURABILITY TEST

RECOMMEND SUBMISSION OF (5) MINIMUM DEVICES EACH QUARTER FOR
IMPULSE TESTING IN ACCORDANCE WITH ES SPECIFICATION GUIDELINES.
DEVICE TYPES SUBMITTED NEEDS TO BE DETERMINED BY MRB.

ALSO RECOMMEND SUBMISSION OF (1) 77PS SENSOR LOT EACH WEEK FOR
TRADITIONAL IN-PROCESS IMPULSE TESTING TO MONITOR CHRONIC LEVEL OF
DISC CRACKING.

ENGINEERING DURABILITY TEST

(5) DEVICES MINIMUM PER OPERATING DAY, OR UPON ANY MAJOR TERMINAL ASSEMBLY MACHINERY
TOOL WORK - (AS DEFINED BY ENGINEERING). SAMPLE
BUILD AS FOLLOWS:

- * BASE ASSEMBLIES NEWLY MANUFACTURED ON THE SUBMISSION DAY.
- * 87PS L-2 SENSOR ASSEMBLIES (WORST CASE).
- * OFFSET CALIBRATION PER ENGINEERING REQUIREMENTS.
- * FUNCTIONALLY TESTED FOR PROPER OPERATION BY PRODUCTION.

TI-NHTSA 011783

Customer Count Summary

77PS + 57PS

7/20/93

	<u>CY 1993</u>		<u>CY 1992</u>		<u>CY 1991</u>	
	<u>77PS</u>	<u>57PS</u>	<u>77PS</u>	<u>57PS</u>	<u>77PS</u>	<u>57PS</u>
Misaligned Bracket	5	1	0	1	0	2
Threads	1	4	0	3	0	3
Wiring Components	1	2	0	1	0	0
Rated Thru Connector	1	1	0	0	0	0
Misaligned/Not Terminated	0	1	1	0	0	0
Vacuum	0	0	1	0	0	0
Flake	0	0	1	0	0	0

TI-NHTSA 011784

Send to J. Pelkey 7/22/93
via Commailing

CUSTOMER RETURNS SUMMARY					
STPS					
DATE RETURNED	DATE CODE	T.J. PIN	RETURNED FROM	REASON FOR RETURN	COMMENTS
930115	2308	L2-2	KELSEY HAYES	WRONG COMPONENTS	INCORRECT HEXPORT
930115	2316 - 2328	L2-2	"	DAMAGED THREADS	UNREROLLED THREADS
930125	2329	L2-2	"	WRONG COMPONENTS	INCORRECT HEXPORT
930125	2128 - 2308	L2-2	KELSEY HAYES	DAMAGED THREADS	UNREROLLED THREADS
930310	3047 - 3048	L2-2	KELSEY HAYES	DAMAGED THREADS	"
930317	2213 - 3081	L2-2	"	INOP & BAD THREADS	INOP NOT DUPLICATED
930331	2202	F8-5	PITTS INDUS.	LOW LEVEL AIR LEAK	MISPLACED GASKET
930427	2205	L11-2	J PELKEY/TI ENGG	INGRESS BY CONNECTOR SEAL	SWITCH DIMENSIONS IN SPEC
930521	3111	L2-2	ANCHOR SWAN	O-RING GLAND	DIMENSIONS IN SPEC, NTF.
930531	1275	L5-2	J. PELKEY	INOP SPEED CONTROL	INOP NOT DUPLICATED
90823	8272 - 1172	L2-2	DEALERS	LEAKS OIL	MISALIGNED GASKET
920206	N/A	F8-8P	FORD U.K.	N/A	
920823	1058	L2-2	KIRBY AUST	NOISE	LOOSE CRIMP
920702	N/A	L11-1	FORD U.K.	INOP	NTF
920723	1089 - 1183	L2-2	KIRBY AUST	NOISE	LOOSE CRIMP
921007	2210	L2-2	ANCHOR SWAN	DAMAGED HEXPORT	O-RING GLAND NOT FORMED
921102	N/A	L2-2	PTG	THREADS TIGHT	DAMAGED THREADS
921104	2280 - 2298	L2-2	KELSEY HAYES	BAD THREADS	UN RE-ROLLED THREADS
910701	8237	L3-1/L2-2	DEALERS	LEAKS	MISALIGNED THREADS
910320	1040	F8-5	PITTS INDUS.	PLATING	COSMETIC
910820	1162	L2-2	UNITED TECH.	BAD THREADS	
910705	1188	L2-2	UNITED TECH.	BAD THREADS	
911010	179	L2-2	FORD USA	BAD THREADS	

TI-NHTSA 011785

CUSTOMER RETURNS SUMMARY					
77PB					
DATE RETURNED	DATE CODE	T.I. PM	RETURNED FROM	REASON FOR RETURN	COMMENTS
920908	2008	L2-1	ITT TEVES	FLAKES	CARDBOARD DUST/DIRT
920908	2052	L2-3	FORD	BENT TERMINAL	
920910	2028	L2-1	DANA	CALIBRATION	CALIBRATION CORRELATION
921118	2242	L3-3	FORD	LEAK	NTF
921124	2224 - 2261	L2-2	FORD	VACUUM SENSITIVITY	REDERIGNED SENSOR
930129	2346	L2-1	PITTS	LEAKS	MISALIGNED GASKET
930129	2352	L2-1	PITTS	WRONG HEXPORT	
930204	2353	L2-1	PITTS	LEAKER	MISALIGNED GASKET
930211	3005	L2-1	PITTS	LEAKER	MISALIGNED GASKET
930217	3011	L2-1	PITTS	LEAKER	MISALIGNED GASKET
930312	3217	L2-3	TI ENGG	SNOP	LEAKED THRU CONNECTOR
930318	3025	L2-1	PITTS	LEAKER	MISALIGNED GASKET
930802	3104 - 3108	L2-1	PITTS	BAD THREADS	

TI-NHTSA 011786

MANUFACTURING PROCESS REVIEW FOR TIME PERIOD JUNE 82 TO JAN. 83			
ASSUMPTION	WARRANTY PROBLEMS OBSERVED IN THE FIELD ARE RELATED TO INGRESS INTO CONTACT ZONE		
MAJOR COMPONENT CHANGES :			
	CHANGED PLASTIC BASE FROM BLACK CELANEX TO RED NORYL		
	RED BASE SHIPMENTS STARTED MY 83		
	PARALLEL SHIPMENTS EXISTED FOR THIS TIME FRAME		
	NORYL PROVIDES BETTER DIMENSIONAL STABILITY AND STRENGTH		
	OVER EXTENDED TEMP. RANGE		
	CHANGED DISC FROM SNAP TO QUIET		
	QUIET DISC SHIPMENTS STARTED JAN. 83		
	QUIET SWITCHES' FINISH IS BASED TO COMPENSATE FOR TEMP. SHIFT		
POSSIBLE PROCESS/TOOLING MALFUNCTION WHICH COULD RESULT IN INGRESS INTO CONTACT ZONE			
	MISSING/REPLACED ENV. SEAL		
	UPGRADED SEAL HANDLING 8/83		
	CRACKED PLASTIC BASE DURING CRIMPING		
	ROOT CAUSE-EXCESSIVE CRIMP FORCE		
	CRIMP FORCE MONITORED ON SPC VIA CRIMP HT AND TORQUE		
	SPC DATA FOR THAT TIME FRAME UNDER EVALUATION; ETA 82		
	PLASTIC BASE DIMENSIONAL ANOMALIES		
	SEAL SURFACE FINISH INSPECTED 100% AT FINAL PKG.		
	DIMENSIONAL CHECKS AT EACH MOLDING RUN		
	DIMENSIONAL ANALYSIS OF ISH SUBMISSIONS AND RETURNED PARTS		
	MOLDING SPC DATA FOR THAT TIME FRAME UNDER EVAL. ETA 82		

TI-NHTSA 011787

-MSG MH= 454513 FR=JN02 TO=HJS2 SENT=07/28/93 10:54 AM
 RH=078 ST=C DIV=0050 CC=00149 BY=JN02 AT=07/28/93 10:54 AM

Memorandum

July 28, 1993

TO:	Bill Sweet	WS4	Dave Czarn	ZARN
	Aziz Rahman	ZII	Matt Sellers	HJS2
	Andy McGuirk	PCDA	Charlie Douglas	CMP1
	Elaine Rose	QAMY	Jim Grammer	JQ01
	Dick Gariepy	RWD3	Rick Conlin	RAC1

FROM: Jim Watt JN02

SUBJ: 77PS/87PS Impulse Testing

The proposed sample submission plan for the 77PS/87PS pressure switches will meet the requirements of specification 9F924(77PS) and 3N824 (87PS):

Test	9F924	3N824	Sub Plan
----	-----	-----	-----
IP -2 Functional tests (Voltage drop, proof, burst)	4/lot	3/3 mos	4/sensor lot 77PS 4 week 87PS
IP-2 Durability tests (Impulse testing)	3/3 mos	3/3 mos	3/ quarter
Engineering Durability (Vacuum, temp cycle, Humidity, vibration)	6/6 mos	6/6 mos	5 devices impulse per operating day

Regards,

Jim Watt MEG: JN02 Ext: 1719 H/S: 12-27

Equipment Effectiveness Summary

PC088 Base Assembly Machine

* Report Date: 8 August, 1993 10:00am
 * Data Period: (8-8-93 to 9-8-93) or "Last 10 lots"
 * Exclusions: - Lots less than 1000 pcs.
 - Lots less than 1 hr. duration
 - Codes _____
 * Devices Included: 77PSL 2-1, 87PSL 2-2, etc.
 * Shifts included: All, 1st only, 2nd only, 2nd only, etc.

Downtime Summary Info.

Cause Description	Code	Avg. occ. per 1000 cycles	Avg. % of total lot Duration
Pareto Sorted by % of Downtime			
Sub-Total		Σ of Col.	Σ of Col.

Yield Summary Info.

Cause Description	Average % of Total Cycled
Pareto Sorted by % of total Cycled	
Sub Total	Σ of Col.

Terminal Assembly Machine Performance

Total Spring Arm Mis-feeds :	A
Total B.A.M. Cycles :	B
T.A.M. Yield loss % :	$A+B$

Through Put Performance

Total PCS. Cycled :	A
Total PCS. Good :	B
Total lot Duration :	C
Total Excluded lot Dur. :	D
Total Optime % :	E

Data Period Yield % : $B+A$
 Average throughput (PCS./hr.) : $B+C$
 Equipment Effectiveness % : $E+(B+A)$

Downtime Yield Program

* Include some kind of default Selection Screen to show:

- Selected Codes for OEE Calc.
- Selected Devices
- Time Period
- Shift Selection
- Criteria for Assignment of lots to Shifts.
- When does daily data get summarized into weekly and then discarded.

~~-----~~

Questions

1. How will individual lot summary reports be handled.
 - where stored.
 - How long will they remain as individual reports.
 - When will weekly, monthly, quarterly, annual reports be generated and how will they be stored.
 - If reports are crunched weekly how will part numbers, shift, etc. be kept separate.Organized.

2. Visual Graphs

- Downtime pareto of time period
- Yield loss pareto "
- Trending
 - what's possible. Could we see trending of codes over time, etc.
 - Trending of throughput prof.

3. 1st lots started From 7:01am to 3:00pm
- " " 3:01pm to 11:30pm

Example

Base Assembly Machine (BAM)

<u>Person Desc</u>	<u>Code</u>	<u>Average Occurrences Per 1000 Cycles</u>	<u>Average % of Total Lot Duration</u>
Cycle Stop	41	5.6	17.7 %

5 reports Summary

<u>Code</u>	<u>Total # Occur</u>	<u>Total min Down</u>
41	109	286.07

<u>Total pcs Cycled/Good</u>	<u>19316</u>
<u>Good</u>	<u>18,234</u>
<u>%</u>	<u>94.40</u>

Excluded Codes

- ① Total downtime must be bracketed of total run duration prior to any % calculations

②

TI-NHTSA 011791

126.67 minutes excluded

Total Downtime minutes AFTER exclusion of select Codes

770.35 minutes vs. 897.00

Total Duration After exclusions of select Codes
 1747.126.67
 = 11620.33 duration minutes after exc.

MATT SELLERS

C.BALTHAZAR

27288-1	SHELF/BUMP	BUMP HEIGHT	CONCENTRICITY	
#1	0.0872	0.0188	0.1558	
	0.0874	0.0184	0.1537	
	0.0872	0.0180	0.1553	
	0.0875	0.0157	0.1541	
#2	0.0878	0.0188	0.1483	
	0.0882	0.0188	0.1457	
	0.0880	0.0188	0.1447	
	0.0879	0.0167	0.1447	
#47158	0.0888	0.0188	0.1531	
	0.0880	0.0154	0.1548	
	0.0873	0.0180	0.1549	
	0.0871	0.0158	0.1588	
#52112	0.0873	0.0165	0.1537	
	0.0871	0.0153	0.1528	
	0.0883	0.0161	0.1548	
	0.0871	0.0150	0.1543	
#51321	0.0878	0.0181	0.1583	
	0.0874	0.0185	0.1583	
	0.0879	0.0180	0.1583	
	0.0878	0.0181	0.1583	
28858-23	O.D.	BURR	CROWN HEIGHT	WEAR MARK
#1	0.7490	0.0012	0.0283	
		0.0008		
#2	0.7490	0.0006	0.0284	
		0.0006		
#47158	0.7488	--	0.0285	0.0827
#52112	0.7490	--	0.0300	0.0854
				0.0884
				0.0888
				0.0843
#51321	0.7488	--	0.0299	0.0862
				0.0862
				0.0848
				0.0870

77PS RETURNS

8/12/88

TI-NHT8A 011792

**DRAWINGS AVAILABLE UPON
REQUEST**

8/19/93

Forest City Tech Jack De Ruyter

Make Sponge + Silicone Seals

(Sponge Seal is also made out of silicone)

Silicone Seal process is: liquid silicone injection.

Sponge : 38-50% Comp

Silicone : 10-15% Comp (to reduce installation load).

Seal designed originally for injector connector.

Ron Fouts (Ford Release Engineer)

Rocking Motion has been seen to cause leak problems.

TEXAS INSTRUMENTS

ATTENTION: MASSACHUSETTS 08703

PAGE _____ OF _____

SAMPLE REPORT

REASON FOR REPORT	PART NO. Part # 46575	P.O.	PART NO.	REV. E
NEW PART	REPORT REC'D BY Jim Watt	DATE 8/27	INSPECTED BY M. L. Godbout	DATE 7/2
REPLACEMENT TOOL				
CORRECTED TOOL				
REPAIRED TOOL				
REVIEW				
OTHER				

THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)						DISPOSITION	
		Black	Red	Brown	Gray		
1.	766-780	.771	.780	.771	.777		
2.	.652-.660	<u>.650</u>	.653	<u>.652</u>	.654	measured under load	
3.	.459-.467	.4575	.463	<u>.452</u>	.460		
4.	.114-.118	.115	.115	<u>.113</u>	.115		
	2 p/c's	.115	.116	<u>.1135</u>	.115		
5.	.016-.024	.0233	.0199	.0206	.0217		
	4 p/c's	.0200	.0206	.0196	.0209		
		.0222	.0190	.0214	.0179		
		.0224	.0205	.0204	.0202		
6.	.327-.343	.3343	.3319	.3322	.3362		
	2 p/c's	.3307	.3327	.3321	.3331		
7.	.085-.095	.0874	.0838	.0872	.0870		
	2 p/c's	.0871	.0894	.0857	.0852		
8.	23°-27°	24	24	25	24		
	2 p/c's	25	25	25	25		
9.	Flatness	.0043	.0012	.0034	.0038	Top of Base	
10.	Parallelism	.004	.0027	.0011	.0014	Locking Tabs	

REMARKS AND/OR INSTRUCTIONS:

DISPOSITION: TOOL APPROVED FOR PROD.	RESUBMISSION REQ'D
Mr. G. ENG.:	QRA ENG.:
	PURCH. AGENT:

TI-NHTBA 011795

-MSG M# 430213 FR=JW02 TO=MJS2 SENT=07/27/93 04:02 PM
R#-077 ST=C DIV=0050 CC=00149 BY=JW02 AT=07/27/93 04:02 PM

Memorandum

July 27, 1993

TO: Bill Sweet WS4 Dave Czarn ZARN
Aziz Rahman ZIZ Matt Sellers MJS2
Andy McGuirk PCGA Charlie Douglas CMP1
Elaine Rose GMY

FROM: Jim Watt JW02

SUBJ: 77PSL2-3/77PSL3-2 (Base No. 46515 Assessment)

We characterized the p.n. 46515 base for the 77PS pressure switches and found the pertinent base dimensions for connector fit to be within specification. The black base is from the field return unit (77PSL2-3), while the red base is from the field return unit (77PSL3-2). The brown and grey bases were selected from production bases in the production area. Two additional measurements (not on the component base drawing) were also completed:

Measurement -----	Black base (Field PBT) -----	Red Base (Field PBT) -----	Brown Base (Prod PBT) -----	Grey Base (Prod PBT) -----
Flatness (top of base)	.0043 "	.0012 "	.0034 "	.0038 "
Parallelism of top of base to locking tab feature	.004 "	.0027 "	.0011 "	.0014 "

Regards,

Jim Watt MSG: JW02 Ext: 1719 M/S: 12-27

TI-NHTSA 011786



SAMPLE REPORT

REASON FOR REPORT	VENDOR T I	P.O.	PART NO. 27639-1	REV. D
NEW PART	REPORT REQ BY ELAINE ROSE	DATE	INSPECTED BY RITA SALOIS	DATE 8/12/9
REPLACEMENT TOOL				
CORRECTED TOOL				
REPAIRED TOOL				
REVIEW				
OTHER DIM ANALYSIS ☒				

THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)					DISPOSITION	
					INST METHOD	
	DIM	A51321	A47156	A81804		
1	D.294-.298	X.296	X.296	X.296	T mic	
	SIDE A	Y.2961	Y.2961	Y.2963		
	SIDE B	X.3015	X.3006	X.3007		
		Y.3002	Y.3007	Y.3010		
	MAX PLUG	.295	.296	.296	Plug	
2	.005^R-.012^R					
3	.001 MAX DIA					
	.002^R MAX IF					
	TUMBLER					
4	D1.059-1.063	X1.0603	X1.0609	X1.0615	T mic	
		Y1.0607	Y1.0606	Y1.0607		
5	FLAT TO .006 T.I.R.	.002	.002	.001	100^u End	
6	LONGITUD. .004	.001	.0007	.0012	Comp	
	T.I.R.					
7+8	C 40-60 HARDNESS	average. Engineer decided to retain all samples and not have them sectioned to show customer per Eng design engineer.				
9	PER NOTE #5					

REMARKS AND/OR INSTRUCTIONS:

DISPOSITION: TOOL APPROVED FOR PROD.

RESUBMISSION REQ'D

PG. ENG.:

QRA ENG.:

PURCH. AGENT:

TI-NHTSA 011797

ATTENTION: MANAGING EDITOR OF THE

SAMPLE REPORT

THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.

REMARKS AND/OR INSTRUCTIONS:

TI-NHTSA 011798

**DRAWINGS AVAILABLE UPON
REQUEST**

SAMPLE REPORT

REASON FOR REPORT		VENDOR T. I.		P.O.	PART NO. 27406-1	REV. F
NEW PART		REPORT REQ. BY	DATE	INSPECTED BY		DATE
REPLACEMENT TOOL		ELAINE ROSE	8-7-93	RITA SALAS		8-12-9
CORRECTED TOOL						
REPAIRED TOOL						
REVIEW		THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.				
OTHER DIM ANALYSIS X						

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)						DISPOSITION	
	DIM	189	194	200	203	1/16"	
1	.500-.506	X .5028	X .5029	X .5027	X .5023	T-mil	
		Y .5020	Y .5023	Y .5025	Y .5024		
2	.287-.293	X .2914	X .2897	X .2905	X .2894	Comp	
		Y .2918	Y .2905	Y .2913	Y .2919		
3	.162-.168	.1637	.1648	.1652	.1657	DIAL	
4	.101-.107	.1035	.1034	.1027	.1046		
5	.020-.025	.0224	.0209	.0221	.0216		
6	.012-.018	.0138	.0151	.0142	.0138		
7	.755-.759	X .7567	X .7570	X .7572	X .7571	T-mil	
		Y .7577	Y .7575	Y .7571	Y .7575		
8	.707-.720	X .7129	X .7125	X .7123	X .7126	Comp	
9	.015 DIA	See note below					
10	.010"-.035"	See note below					
11	CONCENTRIC .008	.0007	.0006	.001	.0008		
	TLR	.0016	.0030	.0021	.0016		

REMARKS AND/OR INSTRUCTIONS: **SAMPLES TO BE RETAINED WITHOUT SECTIONING TO BE SHOWN TO CUSTOMER PER A312 DESIGN ENGINEER**

POSITION: TOOL APPROVED FOR PROD.	RESUBMISSION REQ'D
MFG. ENG.:	QRA ENG.:
	PURCH. AGENT:

TEXAS INSTRUMENTS

ATTENTION: MASSACHUSETTS SETCO

PAGE 2 OF 2

SAMPLE REPORT

REASON FOR REPORT		VENDOR		P.O.	PART NO.	REV.
NEW PART		TI			27406-1	F
REPLACEMENT TOOL.		REPORT REC. BY	DATE	INSPECTED BY		DATE
CORRECTED TOOL.		ELAINE ROSE	8-10-93	BITH SAKOLS		8-12-93
REPAIRED TOOL.						
REVIEW						
OTHER: DIM ANALYSIS X		THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.				

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)						DISPOSITION	
	DIM	SECTION 1	SECTION 2	SECTION 3	SECTION 4	INSP	
1	.800-.816	X .814	X .812	X	X .814	T-mic	
		Y .811	Y .812	Y	Y NA		
2	.287-.293	X .291	X .290	X	X .291	T-mic	
		Y .291	Y .291	Y	Y NA		
3	.162-.168	.162	.164	.162	.164	NA	
4	.101-.107	.103	.103	.101	.103		
5	.020-.025	.021	.022	.021	.021		
6	.012-.018	.014	.014	.012	.014		
7	.755-.759	X .754	X .751	X	X .750	T-mic	
		Y .754	Y .750	Y	Y NA		
8	.707-.720	X .710	X .712	X	X .711	T-mic	
9	.015-MAX	SEE DRAWING	SEE DRAWING	.015		T-mic	
10	.010 ^R -.035 ^R	SEE DRAWING	SEE DRAWING	.030 ^R			
11	CONCENTRIC .008	.0017	.0012			T-mic	
	T.I.R.	.0014	.0013				

REMARKS AND/OR INSTRUCTIONS:

DISPOSITION: TOOL APPROVED FOR PROD.

RESUBMISSION REQ'D

MFG. ENG.:

QRA ENG.:

PURCH. AGENT:

TI-NHTSA 011801

**DRAWINGS AVAILABLE UPON
REQUEST**

SAMPLE REPORT

REASON FOR REPORT		VENDOR		DATE	PART NO.	REV.
NEW PART					77PS Converter	
REPLACEMENT TOOL		REPORT REC'D BY	DATE	INSPECTED BY	DATE	
CORRECTED TOOL		A212	7-29-73	ELAINE	7-29-73	
REPAIRED TOOL		THE DIMENSIONS INDICATED BELOW REPRESENT TEXAS INSTRUMENTS' FINDINGS REGARDING THE ACTUAL VALUES FOR ALL CHARACTERISTICS MEASURED. IN CASES WHERE ACTUAL VALUES DEVIATE FROM THE SPECIFIED DIMENSIONS, THE DISPOSITION MUST INDICATE THE REQUIRED ACTION FOR EACH NON-CONFORMANCE IN THE APPROPRIATE COLUMN.				
REVIEW						
OTHER						

(CIRCLE ALL OUT OF TOLERANCE DIMENSIONS)					DISPOSITION	
Part	Bump Width	Dip	Radius			
27406 L202	.2822 .2859 .2872	L .446 R .914			52-3	Identified
27389 L262	.2912 .2962 .3291	.029 .029				
A47156	.2825 .2862	.029 .029			V	CUT
A52112 A	.2906 .2875 .3304	.047 .027				
	.2867 .2801 .3207	.029 .029				
Curr. Part. A	.2816 .2843 .2962	L .262 R .240				
	.2893 .2916 .2966	L .264 R .280				

REMARKS AND OR INSTRUCTIONS:

* DIMENSIONS ARE IN INCHES

DISPOSITION: TOOL APPROVED FOR PROD.	RESUBMISSION REQ'D
--------------------------------------	--------------------

Q.A. ENG.:	QRA ENG.:
------------	-----------

TI-NHT8A 011803

		0.309	0.301	0.299	0.297	0.296	0.293	0.291	0.289	0.285
L199		.071	.070	.071	.070	.069	.068	.068		
L200		.071	.070	.072	.072	.071	.070	.069		
L201		.070	.071	.071	.071	.070	.070	.069		
L202		.070	.070	.071	.071	.069	.068	.065		
L258		.071	.071	.071	.070	.069	.068	.066		
L259		.071	.071	.071	.071	.070	.068	.066		
L260		.071	.070	.070	.069	.069	.067	.065		
L261		.070	.070	.070	.070	.069	.069	.065		
L262		.073	.072	.072	.069	.069	.069	.066		
AS1804		.072	.071	.070	.069	.067	.067			
AS2112		.069	.068	.067	.067	.068	.067	.064		
A47156		.070	.069	.069	.068	.067	.066			
AS1321		.072	.072	.069	.068	.068	.068	.063		
AS2578		.071	.069	.068	.067	.066	.066	.063		
		0.308	0.301	0.299	0.297	0.296	0.293	0.291	0.289	0.285
L199		.000	-.001	.000	-.001	-.002	-.003	-.003		
L200		.000	.000	.001	.001	.000	-.001	-.003		
L201		.000	.001	.001	.001	.001	.000	-.004		
L202		.000	.000	.001	.000	-.001	-.002	-.003		
L258		.000	.000	.000	-.001	-.002	-.003	-.003		
L259		.000	.000	.000	.000	-.002	-.003	-.003		
L260		.000	-.001	-.001	-.002	-.003	-.004	-.003		
L261		.000	.000	.000	.000	-.001	-.002	-.003		
L262		.000	-.001	-.001	-.003	-.004	-.004	-.007		
AS1804		.000	.000	-.001	-.003	-.004	-.004	-.015		
AS2112		.000	-.001	-.002	-.002	-.002	-.002	-.003		
A47156		.000	-.001	-.001	-.002	-.003	-.004	-.020		
AS1321		.000	.000	-.003	-.004	-.005	-.005	-.008		
AS2578		.000	-.002	-.003	-.003	-.004	-.005	-.007		
		0.308	0.301	0.299	0.297	0.296	0.293	0.291	0.289	0.285
L199		.000	.001	.000	.001	.002	.003	.005		
L200		.000	.000	.001	.001	.000	.001	.003		
L201		.000	.001	.001	.001	.001	.000	.004		
L202		.000	.000	.001	.000	.001	.002	.005		
L258		.000	.000	.000	.001	.002	.003	.005		
L259		.000	.000	.000	.000	.002	.003	.005		
L260		.000	.001	.001	.002	.003	.004	.005		
L261		.000	.000	.000	.000	.001	.002	.005		
L262		.000	.001	.001	.003	.004	.004	.007		

GAGE1.XLS

A81804		.000	.000	.001	.003	.004	.004	.015		
A52112		.000	.001	.002	.002	.002	.002	.005		
A7160		.000	.001	.001	.002	.003	.004	.020		
A81321		.000	.000	.003	.004	.005	.005	.008		
A52578		.000	.002	.003	.003	.004	.005	.007		

	285	287	289	291	293	295	297	299	301	303
27319 L238		← C.I.	65.7	68.1	69.5	70.7	71.1	71.1	71.1	71.1
27320 L238		← W.R.E.	66.1	68.1	69.4	70.4	71.1	71.0	71.0	71.0
27321 L238		← N/A	.0655	.0686	.0688	.0694	.0715	.0718	.072	.072
27322 L238		← N/A	.0671	.0671	.0685	.0704	.0712	.0715	.0715	.0715
27323 L238		← N/A	.0626	.0644	.0671	.0677	.0668	.0670	.0683	.069
27324 L238		← N/A	.0657	.0666	.0682	.0692	.0693	.0693	.0693	.0693
27325 L238		← N/A	.0633	.0664	.0664	.0679	.0691	.0715	.0715	.0715
27326 L238		← N/A	.0646	.0678	.0684	.0691	.0700	.0701	.0701	.0701
27327 L238		← N/A	.0650	.0685	.0692	.0697	.0699	.0697	.0697	.0697
27328 L238		← N/A	.0657	.0680	.0688	.0697	.0705	.0702	.0702	.0702
27329 L238		← N/A	.0658	.0697	.0710	.0715	.0716	.0703	.0706	.0706
27330 L238		← N/A	.0664	.0695	.0704	.0712	.0707	.0709	.0709	.0709
27331 L238		← N/A	.0652	.0683	.0694	.0705	.0706	.0700	.0700	.0700
27332 L238										
27333 L238										
27334 L238										
27335 L238										
27336 L238										
27337 L238										
27338 L238										
27339 L238										
27340 L238										
27341 L238										
27342 L238										
27343 L238										
27344 L238										
27345 L238										
27346 L238										
27347 L238										
27348 L238										
27349 L238										
27350 L238										
27351 L238										
27352 L238										
27353 L238										
27354 L238										
27355 L238										
27356 L238										
27357 L238										
27358 L238										
27359 L238										
27360 L238										
27361 L238										
27362 L238										
27363 L238										
27364 L238										
27365 L238										
27366 L238										
27367 L238										
27368 L238										
27369 L238										
27370 L238										
27371 L238										
27372 L238										
27373 L238										
27374 L238										
27375 L238										
27376 L238										
27377 L238										
27378 L238										
27379 L238										
27380 L238										
27381 L238										
27382 L238										
27383 L238										
27384 L238										
27385 L238										
27386 L238										
27387 L238										
27388 L238										
27389 L238										
27390 L238										
27391 L238										
27392 L238										
27393 L238										
27394 L238										
27395 L238										
27396 L238										
27397 L238										
27398 L238										
27399 L238										
27400 L238										
27401 L238										
27402 L238										
27403 L238										
27404 L238										
27405 L238										
27406 L238										
27407 L238										
27408 L238										
27409 L238										
27410 L238										
27411 L238										
27412 L238										
27413 L238										
27414 L238										
27415 L238										
27416 L238										
27417 L238										
27418 L238										
27419 L238										
27420 L238										
27421 L238										
27422 L238										
27423 L238										
27424 L238										
27425 L238										
27426 L238										
27427 L238										
27428 L238										
27429 L238										
27430 L238										
27431 L238										
27432 L238										
27433 L238										
27434 L238										
27435 L238										
27436 L238										
27437 L238										
27438 L238										
27439 L238										
27440 L238										
27441 L238										
27442 L238										
27443 L238										
27444 L238										
27445 L238										
27446 L238										
27447 L238										
27448 L238										
27449 L238										
27450 L238										
27451 L238										
27452 L238										
27453 L238										
27454 L238										
27455 L238										
27456 L238										
27457 L238										
27458 L238										
27459 L238										
27460 L238										
27461 L238										
27462 L238										
27463 L238										
27464 L238										
27465 L238										
27466 L238										
27467 L238										
27468 L238										
27469 L238										
27470 L238										
27471 L238										
27472 L238										
27473 L238										
27474 L238										
27475 L238										
27476 L238										
27477 L238										
27478 L238										
27479 L238										
27480 L238										
27481 L238										
27482 L238										
27483 L238										
27484 L238										
27485 L238										
27486 L238										
27487 L238										
27488 L238										
27489 L238										
27490 L238										
27491 L238										
27492 L238										
27493 L238										
27494 L238										
27495 L238										
27496 L238										
27497 L238										
27498 L238										
27499 L238										
27500 L238										
27501 L238										
27502 L238										
27503 L238										
27504 L238										
27505 L238										
27506 L238										
27507 L238										
27508 L238										
27509 L238										
27510 L238										
27511 L238										
27512 L238										
27513 L238										
27514 L238										
27515 L238										
27516 L238										
27517 L238										
27518 L238										
27519 L238										
27520 L238										
2752										

F8ERDM.XLS

SWITCH #	TOP OF CONVERTER BUTTON	BOTTOM OF CONVERTER BUTTON	TOP OF WASHER 15 DEG CHFR	BOTTOM OF WASHER SHARP EDGE	WASHER I.D. OFFSET WITH .296 PIN
A47155	.281	.287	.296	.299	.005
A51321	.280	.301	.296	.299	.005
A52575	.280	.300	.296	.299	.005
A51804	.280	.287	.296	.299	.005
PROD 1	.288	.295	.296	.300	.005
PROD 2	.280	.298	.296	.300	.005
PROD 3	.289	.298	.296	.300	.005
PROD 4	.288	.293	.296	.300	.005

TI-NHTSA 011807

Diemasters

MANUFACTURING, INC.

FAX COVER SHEET

Date: 8/11/93 Number of Pages: _____ (Including cover sheet)

TO: _____
Mr./Ms. Mr. H. Sullivan

FROM: _____
Mr./Ms. Mike Acant

Company: _____
FAX # _____

Company: DIEMASTERS MFG. INC.
FAX # _____

COPY TO:

SPECIAL INSTRUCTIONS:

- ☐ Confidential
- ☐ Urgent
- ☐ Please reply
- ☐ Responding to your fax
- ☐ For your information

MESSAGE:

Met, here is information regarding
any questions please call


TKS

Mike Acant


If not received correctly, please call: (708) 834-7400

TI-NHTSA 011808

767 Industrial Drive • Elmhurst, Illinois 60126 • (708) 834-7400 • FAX (708) 834-6029



PRIORITY 2.0



PRIORITY 4.0

TO: DAVE CZARN
CC: MATT SELLERS
PAUL KOTCH
CHARLIE DOUGLAS
ANDY MCCUIRK
FR: AZIZ RAHMAN
RE: DIEMASTERS TRIP REPORT
DT: 11/5/93

MONDAY, 11/1/93 - DIEMASTERS
1 PM - 5 PM

T.I. AZIZ RAHMAN
DIEMASTERS MIKE ARBENT, PROJECT ENGINEER
GLENN MARCANTONI, TOOLING SUPERVISOR
JIM BAUMBACH, DIRECTOR OF OPERATIONS

THE OBJECTIVE OF THE VISIT WAS TO CONDUCT A FINAL DESIGNING REVIEW OF THE PROPOSED CHANGES TO WASHER 27639-1. THE DESIGN CHANGE INVOLVES CORNING A CHAMFER ON THE BACK SIDE OF THE WASHER TO PROVIDE A RELIEF FOR THE RADIUS AT THE BASE OF THE CONVERTER. THIS CHANGE PROPOSAL IS THE RESULT OF THE 8-D ON 77FEL3-3 F-SERIES FIELD RETURNS.

DIEMASTERS IS A \$12M STAMPING HOUSE INVOLVED IN STAMPED PRODUCTS FOR THE AUTOMOTIVE AND CONSUMER INDUSTRY. TYPICAL PRODUCTS MANUFACTURED HERE INCLUDE LEAD-FRAMES, HOUSINGS, SMALL ASSEMBLIES, CASINGS etc. THEY HAVE 90 EMPLOYEES AND ARE LOCATED IN ELMHURST, IL. THE PRESSES ON SITE RANGE FROM 40 TONS TO 120 TONS. THE T.J. HYDRAULIC WASHER IS RUN ON A 60-TON PRESS. DIEMASTERS FABRICATE MOST OF THEIR DIES IN-HOUSE IN AN ADEQUATELY EQUIPPED TOOL SHOP.

DURING 993 DIEMASTERS HAD FABRICATED A SINGLE STATION PROTOTYPE TOOL TO EVALUATE MANUFACTURING FEASIBILITY OF THE DESIGN CHANGES. THEY ARE CONFIDENT THAT THIS CAN BE DUPLICATED IN PRODUCTION. THE INITIAL THOUGHT WAS TO CORN THE CHAMFER IN THE IDLE STATION AND RE-PERFORATE THE FINAL I.D. TO REMOVE THE ROLL-OVER TIPS. GLENN VOICED HIS CONCERNS THAT THIS WOULD ALMOST BE A SHAVING PROCESS RESULTING IN SMALL CHIPS DISPERSING ALL OVER THE PUNCHES. HIS PROPOSAL INVOLVED USING IDLE STATIONS IN THE DIES TO INCORPORATE A PILOTED CHAMFER CORNING PUNCH FOR THE REVERSE CHAMFER. THE RADIUS ON THE TOP CHAMFER WOULD BE CORNED IN THE NEXT STATION WITH A PILOTED PUNCH. THE PILOTED PUNCHES WOULD PREVENT MATERIAL ROLL-OVER INTO THE I.D. DIEMASTERS NEEDS TO GET BACK TO T.I. WITH A FINAL PROPOSAL.

THE ABOVE CHANGES TO THE TOOL WOULD BE REVERSIBLE. THE DIES ARE "CLASS C" DIES, AS IN "CHEAPEST IN CLASS", MEANING THERE IS NOT MUCH SOPHISTICATION IN HOW THEY ARE PUT TOGETHER. (CLASS "A" DIES WOULD BE FULLY BUSHED AND DOWELED, WITH TIGHT CLEARANCES, THICKER BASE BLOCKS ETC.) THE ONLY LONG TERM PROCESS CONCERN MIKE HAD WAS REGARDING TOOL WEAR AND INCREASED CYCLE TIME, BOTH OF WHICH PROBABLY TRANSLATE TO INCREASED PIECE PRICE.

TI-NHTSA 011811

THERE ARE THREE DIES WHICH PRODUCE THIS PART. IT SEEMED LIKE ONLY ONE OF THE DIES HAD SUFFICIENT IDLE STATIONS TO INCORPORATE THE ADDITIONAL COINING PUNCH. DIEMASTERS WILL HAVE TO ADDRESS HOW THEY WILL MEET VOLUMES IF ONLY ONE DIE IS RE-TOOLED.

WE ALSO DISCUSSED MODT'S SUGGESTIONS OF INCORPORATING AN I.D. GAGING SCHEME IN THE DIE ITSELF. THIS WOULD ENSURE THAT THE I.D. WAS LARGER THAN THE MMC OF THE CONVERTER ON EACH WASHER. THOUGH MIKE WAS RECEPTIVE TO THE IDEA, HE WAS HESITANT TO INCORPORATE A GAGE PIN IN THE DIE. HE AGREED TO GO RESEARCH NON-PROBING TECHNIQUES TO ACHIEVE THE SAME.


THE FOLLOWING ACTION ITEMS WERE GENERATED FOR FOLLOW-UP:

FORWARD FINAL PRINT AND RFQ TO DIEMASTERS	RAHMAN/KOTCH	11/5 ✓
REVIEW DESIGN CHANGE STRATEGY AND QUOTE	ARRENT	11/12
PROPOSE IN-DIE I.D. GAGING SCHEME	ARRENT	12/1
KEY DIMS CAP STUDY ON PARTS FROM 3 DIES	ARRENT	11/19
OBTAIN DESIGN CHANGE APPROVAL FROM FORD	RAHMAN/DOUGLAS	11/19
RELEASE DESIGN CHANGE	SELLERS	12/1


REGARDS
AZIZ

TI-NHTSA 011812

**DRAWINGS AVAILABLE UPON
REQUEST**



8-2-13
Attachment #2



MATT SELLERS

C.BALTHAZAR

27288-1	SHELF/BUMP	BUMP HEIGHT	CONCENTRICITY
#1	0.0872	0.0158	0.1559
	0.0874	0.0154	0.1537
	0.0872	0.0160	0.1553
	0.0875	0.0157	0.1541
#2	0.0878	0.0169	0.1483
	0.0882	0.0169	0.1457
	0.0890	0.0169	0.1447
	0.0879	0.0157	0.1447
#47158	0.0889	0.0158	0.1531
	0.0890	0.0154	0.1545
	0.0873	0.0160	0.1549
	0.0871	0.0159	0.1555
#52112	0.0873	0.0155	0.1537
	0.0871	0.0153	0.1528
	0.0889	0.0161	0.1549
	0.0871	0.0150	0.1549
#51321	0.0878	0.0161	0.1553
	0.0874	0.0166	0.1555
	0.0879	0.0160	0.1559
	0.0878	0.0161	0.1533

38858-33	O.D.	BURR	CROWN HEIGHT	WEAR MARK
#1	0.7490	0.0012	0.0293	
		0.0008		
#2	0.7490	0.0008	0.0294	
		0.0008		
#47158	0.7490	--	0.0298	0.0827
#52112	0.7490	--	0.0300	0.0854
				0.0864
				0.0866
				0.0843
#51321	0.7485	--	0.0299	0.0862
				0.0862
				0.0849
				0.0870

7798 RETURNS

8/12/83

TI-NHTBA 011810

Final Assembly Machine
LVDT station correlation exercise
100 piece sample comparison with f.a.m. actuals
77PBL3-S quiet switch

A2.2.
Your copy
Matt

Lot # 798			
8/2/83			
47.3	47.0	47.3	46.8
47.0	46.7	47.0	46.9
47.0	46.7	47.0	47.0
46.9	47.4	47.3	47.2
47.2	47.0	47.1	46.8
46.9	47.4	47.2	47.0
47.0	47.1	47.2	47.2
47.1	47.2	46.8	47.2
47.2	46.8	47.1	47.0
47.0	47.3	47.2	46.7
47.2	47.1	47.0	46.7
47.0	47.0	47.1	47.2
47.0	47.1	46.9	47.0
47.0	47.3	46.8	47.1
47.1	46.9	47.0	47.1
47.6	47.0	47.1	47.1
47.1	46.7	46.7	46.7
47.1	47.1	47.2	47.4
47.0	47.0	47.1	46.7
47.1	46.9	46.9	47.2
47.1	47.1	47.3	47.1
47.1	47.2	47.2	47.1
47.0	47.2	47.0	47.1
47.1	46.9	47.3	47.1
46.9	46.9	46.9	47.0
X-BAR			47.0
SIGMA			0.18
HI PIN			146.0
LO PIN			144.0
MANUAL X-BAR W/HI PIN			99.0
MANUAL X-BAR W/LO PIN			97.0
LVDT X-BAR W/HI PIN			98.4
LVDT SIGMA W/HI PIN			0.47
LVDT X-BAR DELTA			-0.6

LVDTCORR.XLS

TI-NHTSA 011817

F ser.

Content

- ① Review LVDT correlation MS/KA
- ② Fall out Analysis - MS/KA
 - sensor ht - KA
 - p.d. curve - KA
- ③ Audit Check - MS/KA/AR
 - sensor ht - KA
 - p.d. curve - KA
 - horizontal loading JD
 - sensor ht - KA
 - p.d. curve - KA
 - review results AR/AR

Discussion

- ✓ ① Visually Inspect Production Impulse AR
- ② Visually Inspect DV Test Impulse AR/AR
- ③ Dimensional Analysis MS/CR
 - Functional Logic Analysis
 - Returns
 - Production
- ④ FAI/Out & Recondition Work/Impulse
 - Returns
 - Production
- ⑤ Rebuild known correlation return & check for hang up AR/ID
- ⑥ Build off c.i. work/imp + j.d. AR/ID
- ⑦ Cycle stick block return in horiz position AR/ID
- ⑧ Update DFM/EA AR

7/29

A/C vs non-A/C

- last pull res. the same as



+ Connector is the same as
in November

+ OPEN: Speed control wiring changes

→ ...
... in green and
leaking

... at ...
...
...

→ hot line has been ...
to ...



BLUE-GREEN RESIDUE ALONG
EDGE OF TERMINAL AND SPRING
TAB IS VISIBLE IN THE CONNECTOR
CAVITY



TWO OTHER SWITCHES HAVE THE BLUE-GREEN
RESIDUE ALONG THE TERMINAL AND
IN ONE CORNER OF THE CONNECTOR
CAVITY, SHOWING THAT THE LIQUID
PUDDLED IN ONE AREA

ANOTHER SWITCH HAS THE RESIDUE
COVERING ABOUT 1/2 OF THE
CONNECTOR CAVITY, CLEARLY FROM
LIQUID THAT FORMED A PUDDLE
AFTER INGRESS THROUGH THE
CONNECTOR

-MSG MH- 507944 F [REDACTED] SENT=08/19/93 09:45 AM
ST=C DIV=050 CC=00134 BY=MJS2 AT=08/19/93 09:45 AM
TO: TERRY RODRIGUEZ TER7
CLAUDE RICHARDSON CER
JIM GRAMMER JG01
PAUL FERREIRA PJF4
77PS SMWT MFPC
CC: DICK GARIEPY RWG3
FR: MATT BELLERS MJS2
RE: Q.C. SAMPLE SUBMISSIONS
=====

THE REVISED Q.C. SAMPLE SUBMISSION PLAN FOR 77PS AND 87PS LOTS HAS BEEN PLACED INTO TYPING TO BE ADDED TO THE 77PS PILOT MAKER PROCESS SPECIFICATION. FOR YOUR CONVENIENCE I HAVE PROVIDED THE LINE WITH A HAND WRITTEN COPY OF THE REVISION FOR IMMEDIATE IMPLEMENTATION. PLEASE ENSURE THAT ALL OPERATORS ARE TRAINED ON THIS NEW PROCEDURE AND UNDERSTAND IT. PLEASE CALL IF THERE ARE ANY QUESTIONS REGARDING THE NEW PLAN.

THANKS & REGARDS. . .MATT
MJS2
EXT. 1245

TI-NHTSA 011820

-MSG NM= 187988 FR-MAYR TO-MJB2 SENT-09/17/93 03:48 PM
R#-038 ST-C DIV-0050 LC-00869 BY-MAYR AT-09/17/93 03:48 PM

TO: BILL SWEET W64
MATT SELLERS MJB2

FR: LOU ROCHA

SU: CONVERTING 52PS PRESSURE TESTER TO RUN 57, 67, 77 PS
DEVICES

WE TOOK A LOOK AT THE TESTER AND MADE THE FOLLOWING
OBSERVATIONS:

1. 57PS DEVICES WILL NOT FIT IN NESTS DUE TO THE OVERALL THICKNESS AT THE NECK. THE THICKNESS INCLUDES THE VERTICAL TAB WHICH IS THE PROBLEM.
2. THE 67PS DEVICE WILL FIT IF A SMALL RADIUS CUT IN THE NESTS TO CLEAR THE CORNERS. THE PRESSURE RANGES ALSO SEEM TO BE COMPATIBLE WITH THE 52 PS DEVICES, AND THE UNLOADER SHOULD BE NO PROBLEM.
THE 67'S ARE PROGRAMMED DIFFERENTLY ON THE 77 TESTER THAN WHAT THE 52 TESTER WILL ALLOW, SO YOU WOULD HAVE TO CHANGE YOUR PROCESS SPECS.
IE: LA, HA, LR, HR, MIN DIFF ON 77PS TESTER
LA, HA, LR, MIN DIFF ON 52PS TESTER.
3. THE 77PS DEVICE WILL ALSO FIT IF THE NESTS ARE MODIFIED FOR ABOVE, HOWEVER THE LOW RELEASE VALUES ARE PRETTY LOW, 20PSI, THIS MAY RESULT IN A LONG CYCLE TIME, SINCE THE RAMP RATES ARE SET FOR THE HIGHER 52PS RANGES. THE LIMITS HERE ARE PROGRAMMED DIFFERENTLY AS WELL.
IE: LA, HA, LR, HR, MAX DIFF ON THE 77PS TESTER.
LA, HA, LR, MIN DIFF ON THE 52PS TESTER. *O.K. - Lower volume on 77PS*
4. PRINTED LOT REPORTS WILL NEED TO HAVE 52PS PART NUMBERS SINCE MECHANIZATION CANNOT CHANGE PROGRAMS. *O.K.*
5. I DID CHAMFER THE CORNERS ON SOME 77PS AND 67PS DEVICES AND RAN THEM THROUGH, WITH 52PS LIMITS. THEY DID SEAL AND CONTACT, BUT OF COURSE DID NOT PASS THE TEST.

IN SUMMARY, IT APPEARS A MINOR CHANGE TO THE 52PS TESTER WOULD GIVE US 67PS CAPABILITY. WE NEED TO DO A LITTLE FURTHER TO SAY THE SAME FOR 77PS CAPABILITY.

LET ME KNOW WHAT YOU WANT TO DO.

LOU X3690, RADIO #149

Actions
* Release by MWD needs req'd to
Allow testing of 87/57PS
Product.
* ASAP Conduct Correlation Study
between testers.

TI-NHTSA 011822

MECHANIZATION WORK ORDER

SHT. 1 OF 1

Date Entered

FORM 2022

Date Requested _____

☐ Proposal _____

☒ Design _____

☐ Build _____

Requested By (print) Matt Sellers Date 2/27/2018

Approved By [Signature]

Department PREC 57PS

By MECHANIZATION

Product Code

Project No. 252060218

Expense 6041.0

CC

REQ'D. PRODUCT PRINT NOS.
SUPPLIED LIST

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	

PROJECT DESCRIPTION

* Design + Build of required modifications
to the 57PS function tester to allow full
testing capability for the 87PS device.

Ref. Proposal dated 1/19/93 mmo 252060218

MECH. TITLE _____

MECHANICAL EST. HRS. ELECTRICAL EST. HRS.

PROJ. MGR. _____ PROJ. MGR. _____

ENG. _____ ENG. _____

DESK. _____ TECH/DRAFT _____

BUILD EST. HRS. BUILD EST. HRS.

BUILD CC DATE _____ BUILD CC DATE _____

DESIGN REVIEW ☐ DATE _____

DWG. SIGN OFF ☐ DATE _____

DESIGN CLOSED TO BUILD DATE _____ BY _____

ORDER CLOSED DATE _____ BY _____

GEN. ASSY. DWG. NO. ASSIGNED _____

BUILD CLOSED DATE _____

ADDITIONAL REMARKS, INFORMATION, SKETCH

Edk.
Please forward a detailed
time line ASAP outlining
when downtime will
be required.

[Signature]

7766-1
5768
5768-2

TI-NHTSA 011823

WHITE - MECHANIZATION COPY

YELLOW - ORIGINATOR'S COPY

-MSG MH= 256021 FR=MJS2 TO=COPY SENT=09/21/93 08:46 AM
ST=C DIV=0050 CC=00134 BY=MJS2 AT=09/21/93 08:46 AM

TO: LOU ROCHA MAYR
BILL MILLARD PCME

CC: BILL SWEET WS4
DENNIS NATALE DJN1
77PS SMWT MFPC

FR: MATT SELLERS MJS2

RE: 52PS PRESSURE TESTER MODS

PLEASE USE THIS MEMO AS AUTHORIZATION TO COMPLETE DESIGN AND BUILD
OF 52PS TESTER NEXT MODIFICATIONS TO ENABLE TESTING OF THE 77PS AND
87PS BASED PRODUCTS. WE WILL NEED TO EVALUATE PROBLEMS ASSOCIATED
WITH THE LOW RELEASE PRESSURES ON THE 77PS PRODUCT AFTER WE DEVELOP
THE CAPABILITY OF AT LEAST TESTING THEM.

REF: LOU ROCHA MEMO # 187988 DATED 9-17-93.

THANKS & REGARDS, MATT
EXT. 1245
MSG. MJS2

TI-NHTSA 011824

-MSG NM= 59559 FR=MAYR [REDACTED] 10/04/93 08:51 AM
RM=071 ST=C DIV=0050 CC=00889 BY=MAYR AT=10/04/93 08:51 AM

TO: BILL SWEET
MATT SELLERS

CC: BOB BABILIERE
DAVE PERIPOLI
BILL MILLARD

FR: LOU ROCHA

SU: 52PS PRESSURE TESTER MODIFICATION

AS YOU REQUESTED A COUPLE OF WEEKS AGO, THE 52PS PRESSURE TESTER NESTS HAVE BEEN MODIFIED TO ACCEPT 77PS AND 97PS DEVICES BY CUTTING A RADIUS INTO THE NESTS. THIS CHANGE HOWEVER, WILL NOT ACCOMMODATE 57PS DEVICES.

ALSO, WE HAVE PROTOTYPED AND TESTED THE TABLE SEAL IDEA WITH SOME SUCCESS. THAT IS, A POLYURETHANE SEAL THAT FITS IN A STEEL INSERT AND INSTALLS IN THE DIAL TABLE HOLES AT EACH FIXTURE. THE ADVANTAGES WE SEE ARE LONGER LIFE SINCE EACH SEAL ONLY SEES ONE THIRD THE SERVICE AND THE ABILITY OF THE OPERATORS TO CHANGE SEALS. WE PLAN ON DESIGNING A UNIVERSAL SEAL SO THAT ALL TESTERS USE THE SAME ONE AND THEN ADDING THIS FEATURE TO THE 77PS TESTER. I WILL ALSO SEE THAT ED K. INCORPORATES THIS ON THE 52PS TESTER UPGRADE.

REGARDS

LOU

*Claire
Let's discuss
I was a pilot to
run through SAPS
tester for Correlation*
*Thp
Matt
PS 733*

RISK ANALYSIS REPORT

INTRODUCTION/BACKGROUND:

* In early June 1992 Ford Australia asked TI if the speed control deactivate pressure switch could withstand a vacuum of 0.2 millibar. The explanation was that this level of vacuum is needed during factory fill to avoid spongy pedal feel. TI's initial response was that the ES calls for 4 - 8 mBar, and we had never characterized the device at harder vacuum levels.

* In mid-June, 0.2 mBar was revised to 0.4 mBar by Brent Franks.

* In late June, TI completed some initial testing down to 1.3 mBar, which was the vacuum capability limit of equipment available at the time. Inspection of these test devices revealed that the diaphragm (forming the fluid containment cavity) was being displaced by the vacuum. This was cause for concern since the wrinkled condition observed had been previously associated with shortened diaphragm life. A failed diaphragm results in a brake fluid leak.

* In early July, it was learned that Ford-Australia was doing work to confirm the vacuum requirement, taking actual vacuum readings with a calibrated gauge. A fax from John Peck dated 4 Aug 92 confirmed that actual measured readings ranged from 0.4 to 1.0 mBar across the vehicle population. This fax also contained milestone dates of 1 Nov 92 MRD for PPB, and 14 Apr 93 MRD for PCB which John indicates is the latest possible OTS submission.

* TI immediately began to put together a plan to scope the issue, including characterization testing of the present design, as well as simultaneously prototyping possible modifications, plus comprehension and scheduling of sample and validation requirements.

STATUS:

At this point, the present design has been characterized for diaphragm life after exposure to 0.4 mBar, with a control lot (no vacuum), plus four prototype designs. While all devices in all test lots actually passed the 500K cycle requirement, results indicate statistically that the high vacuum level has a detrimental effect on the life of the present design. It was confirmed that the wrinkled condition theorized to cause reduced life was again present, as also seen in the initial testing in late June.

Two of the four prototype lots produced excellent results, exceeding the life of the standard diaphragm configuration by a significant amount. These are the full-round Kapton and the rubber diaphragm. The full-round Kapton prototype lot differs from the standard design only in that it is round in shape, whereas the standard design is the inscribed square of the full-round circle. The full-round design gives much greater clamping area, hence greater resistance to vacuum exposure. The rubber diaphragm basically replaces the standard lathe-cut internal gasket with a solid rubber disc, having the same thickness and O.D. as the gasket (hence fitting in the same gland). It uses the standard 3 pieces of square Kapton.

ALTERNATIVES:

Option 1: Use the standard design, unmodified, and the high-vacuum assembly plant fill procedure.

Benefits: * The standard design is fully production tooled, ISR'ed, and in full-scale production for various applications

* No cost or schedule impact related to diaphragm redesign

Risks: * It has been shown in a controlled experiment that the Ford-Australia vacuum level has a negative impact on diaphragm life. Weibull analysis of the data indicates high vacuum exposure also results in decreased statistical certainty about diaphragm life; i.e. diaphragm life becomes less predictable, and demonstration of a given life expectancy during an ISR test may not correlate well with field experience.

Option 2: Use the standard design, unmodified, and reduce the vacuum level of the assembly plant fill procedure.

Benefits: * The standard design is fully production tooled, ISR'ed, and in full-scale production for various applications

* No cost or schedule impact related to diaphragm redesign

* No issues with diaphragm life are expected to arise, which is backed up by field experience.

Risks: * The spongy pedal issue will result, according to information from Ford. Therefore, this is not considered a real option.

Option 3: Use the rubber diaphragm design approach

Benefits: * In one experiment, this design has shown a dramatic improvement in diaphragm life under high vacuum. Test aborted at 2.7KK cycles with no failures in this lot.

* This design could be built on existing automated production equipment, with certain modifications.

Option 3: Use the rubber diaphragm design approach (continued)

- Risks:**
- * The performance over the full range of expected conditions must be further quantified
 - * The impact of any variability of material properties over time must be quantified
 - * The impact of production process variability must be quantified
 - * Bench-testing only; no on-vehicle experience exists.

Option 4: Use the full-round Kapton design approach

- Benefits:**
- * In one experiment, this design has shown a significant improvement in diaphragm life under high vacuum, but not as good as the rubber diaphragm.
 - * This design represents essentially no departure from the standard design in terms of pressure- and fluid-exposed materials and geometries.
- Risks:**
- * The performance over the full range of expected conditions must be further quantified
 - * The impact of production process variability must be quantified
 - * Bench-testing only; no on-vehicle experience exists.
 - * To automate this design would require major tooling modifications to existing equipment, which is unfeasible due to the fact that other applications also use this equipment.

77PS Data Collection

10/14/93

* Real time "Monitor" or "Flags" to watch for poor effectivity #'s

* Daily download of data for use in program (original
vs
real time availability in program)

* Data Storage Area

* SQL
CART ASK → Development of the system
- mach

-MSG MH= 19086 FR=MAYR TO=MJS2 SENT=10/21/93 07108 AM
R#155 ST=C DIV=0050 CC=00869 BY=MAYR AT=10/21/93 07108 AM

TO: MATT SELLERS MJS2

CC: BILL SWEET WS4
BILL MILLARD MAYR

FR: LOU ROCHA MAYR

SU: CONVERTING 52PS TESTER TO TEST 57/77/87 DEVICES

A. THE FOLLOWING CHANGES ARE REQUIRED TO BE ABLE TO TEST 57/77/87 DEVICES. ITEMS 1 THRU 4 ARE NEEDED BECAUSE THE EXISTING 52 PROBE ASSEMBLIES DO NOT REACH THE LOWER 77/87 DEVICES. ITEM 5 IS TO ACCEPT THE LARGER ALUMINUM CRIMP RING FOR THOSE DEVICES THAT USE THOSE RINGS.

1. MODIFY PROBE MOUNTING PLATE TO ALLOW PROBES TO REACH 77/87 DEVICES. (140438-12)
2. MAKE 8 NEW GUIDE POSTS. (140438-20)
3. ALTER PROBE TIPS TO ELIMINATE INTERFERENCE WITH 77/87 BASES. (140438-12)
4. ALTER CONTACT BLOCK HOLDER TO ACCOMMODATE LONGER SPRINGS. (140438-19)
5. MAKE 12 NEW NEST INSERTS TO ALLOW FOR LARGER DIAMETER ALUMINUM CRIMP RINGS. (140437-14)

B. THE FOLLOWING CHANGES ARE OPTIONAL, BUT RECOMMENDED TO MAINTAIN ORIENTATION. I AM CONCERNED THAT THE OPERATOR MAY HAVE DIFFICULTY IN KEEPING THE TIGHT ORIENTATION NEEDED FOR THE PROBES TO HIT THE 77/87 DEVICES. I AM MAKING A SOFT PROTOTYPE FOR YOUR EVALUATION.

1. MAKE 12 NEW NEST ORIENT BLOCKS WITH FEATURES TO ORIENT 52, 57, 77, 87 DEVICES. (140437-13)

C. THE FOLLOWING CHANGE MAKES EACH PROBE AREA INDIVIDUALLY SERVICEABLE RATHER THAN THE CURRENT SITUATION WHERE ALL FOUR PROBE ASSEMBLIES NEED TO COME APART TO WORK ON ONE.

1. CUT PROBE CYLINDER MOUNT PLATE INTO FOUR SECTIONS. (140438-18)

ESTIMATED COSTS (PARTS & LABOR):

PART A.....	\$3700
PART B.....	\$3600
PART C.....	\$ 300

REGARDS

LOU, 3680, PAGE 148

TI-NHTSA 011630

TO: TED BREDIKIN
TED BALLARD

CC: MATT SELLERS
77PS SMWT

FR: AZIZ RAHMAN

RE: 77PS DISCS

DT: 11/22/93

PER OUR DISCUSSION LAST FRIDAY, PLEASE FIND AN UPDATED SPECIFICATION TABLE FOR 77PS DISCS. THE ACTUATION AND RELEASE MEANS WILL BE SPECIFIED VIA THE KANBAN PULL YOU MAY ENTER AN ECN PER THIS TABLE.

IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT MATT OR MYSELF.

REGARDS

AZIZ

TI-NHTSA 011831

RETURNED DEVICE ANALYSIS REPORT

CUSTOMER P/N: F2VC - 9F924 - AB T.I. P/N: 779SL2-1
 VEHICLE: NY 95 TOWN CAR DATE CODE: 2281
 FIELD HISTORY: DEVELOPMENT VEHICLE RETURNED: 12/13/92
 MILEAGE: N/A TEST CONDITIONS: N/A
 REASON FOR RETURN: INOPERATIVE SWITCH

SWITCH ANALYSIS

THE SWITCH WAS CONFIRMED TO BE OPEN CIRCUIT IN UN-PRESSURIZED STATE ON RECEIPT. THE SWITCH SHOULD BE NORMALLY CLOSED IN THE UN-PRESSURIZED STATE.

THE SWITCH CRIMP RING SHOWED SIGNS OF HANDLING DAMAGE BUT THERE WAS NO FUNCTIONAL IMPACT TO THE CRIMP RING. THOROUGH VISUAL OBSERVATION INDICATED FLUID INGRESS BY THE MATING CONNECTOR END OF THE SWITCH, AS EVIDENCED BY BRASS CORROSION PRODUCTS ON THE TERMINALS AND IN THE PLASTIC CAVITY. THE SWITCH PLASTIC BASE CONNECTOR LATCH WAS IN NORMAL CONDITION. SEE ATTACHED PHOTOGRAPHS. AN X-RAY OF THE SWITCH INDICATED THAT THE SPRING CONTACT ARM WAS COMPLETELY CORRODED. THE SWITCH WAS DISASSEMBLED FOR INTERNAL EVALUATION.

INTERNAL INSPECTION OF THE PLASTIC BASE INDICATED MASSIVE CORROSION OF THE CONTACT ARM. THERE WAS EVIDENCE OF FLUID INGRESS BY THE TERMINALS FROM THE CONNECTOR CAVITY. THE ENVIRONMENTAL SEAL WAS IN A NORMAL STATE AND THERE WAS NO INDICATION OF LEAKAGE BY THE SEAL.

ROOT CAUSE


THE SWITCH WAS INOPERATIVE DUE TO LACK OF ELECTRICAL CONTINUITY BETWEEN TERMINALS. THE LACK OF CONTINUITY WAS DUE TO MASSIVE CORROSION OF THE CONTACT ARM CAUSED BY FLUID INGRESS BY THE MATING CONNECTOR. THE CONDITION OF THE SWITCH WAS IDENTICAL TO THAT OBSERVED ON BODOLINE WARRANTY RETURN IN SUMMER/FALL '93. AFTER EXTENSIVE TESTING AND THOROUGH ANALYSIS, THE ROOT CAUSE FOR THOSE SWITCHES WAS CONCLUDED TO BE FLUID INGRESS THROUGH THE CONNECTOR BECAUSE OF A COMBINATION OF A "ROCKED" CONNECTOR AND VERTICAL ORIENTATION OF THE SWITCH IN THE APPLICATION. THE 8-D FOR THAT FAILURE MODE WAS COMPLETED AND CLOSED IN CONJUNCTION WITH FORD LIGHT TRUCK ENGINEERING AND IS ATTACHED FOR REFERENCE. (REPORT 9 FB/CAR/93-3).

CONCLUSION


THE SWITCH WAS INOPERATIVE DUE TO MASSIVE CORROSION OF THE CONTACT ARM CAUSED BY FLUID INGRESS INTO THE SWITCH THROUGH THE MATING CONNECTOR.

TI-NHTSA 011832

TEST LOT NO. 12-21-92-01	TEST: RETURNED DEVICE ANALYSIS	DEVICE 779SL2-1
TESTED BY DDOMENGO	 MATERIALS & CONTROLS GROUP ATTLEBORO, MA 01915	DOC. FB/CAR/93-37
APPROVED BY RAHMAN		PAGE NO. 1
DATE 12/20/92		NO. OF PAGES 1



2281



228

ELCO INDUSTRIES, INC. CAPABILITY ANALYSIS


CUST: TOSM INDUSTRIES
 P/N: 38900-1
 CHAR: COURTESY: CHAMBER
 ELCO P/N: 304-087-007070
 DATE: 12-16-90
 SPEC: UPPER: 0.030
 LOWER: 0.020 TOL: 0.010

RAW DATA

CELL1	CELL2	CELL3	CELL4	CELL5	CELL6	CELL7	CELL8	CELL9	CELL10
0.0291	0.0297	0.0294	0.0293	0.0297	0.0291				
0.0291	0.0298	0.0297	0.0297	0.0293	0.0294				
0.0297	0.0293	0.0297	0.0293	0.0293	0.0293				
0.0293	0.0293	0.0294	0.0293	0.0293	0.0297				
0.0293	0.0297	0.0293	0.0297	0.0297	0.0294				

SIGMA: 0.00064
 CV: 2.92
 SPEC: 2.08
 CP: 0.17%
 STANDARD: 0.005
 MEASURE: -0.005
 AVERAGE: 0.0293

HISTOGRAM



77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
881	L2-1	6:00 PM	7:40 AM	8-25-93 8-26-93
886 / 887	L3-3	6:00 PM	7:20 AM	8-26-93
888	L3-3	11:15 AM		8-30-93
884-890	L3-3	9:30 AM	1:35 AM	9-7-93 9-7-93
891 + 892	L3-3	1:10 AM	5:45 PM	9-7-93
893 + 894	L3-3	6:00 PM	7:15 AM	9-8-93 9-2-93
892 + 895	L3-4	7:30 AM		9-8-93
896 - 903	L3-3	10:00 PM <i>with no test</i>	10:30 AM <i>last to be started</i>	9-03-93 9-07-93
904 - 905	L3-3	10:35 AM	11:45 PM	9-7-93
909	L2-1	11:50 AM	12:30 PM	9-8-93 9-7-93
914 - 920	L3-3	8:55 PM	10:00 AM	9-8-93

77PS

IMPULSE TEST LOG SHEET

[illegible]

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
342/343	L3-3	2:40 PM	1:34 ^{AM} 45	12-2-93 12-1-93
344/345	X3-3	3:50 ^{AM}	approx 5:00 PM	12-2-93
346/347	L3-3	5:30 PM	approx 7:00 AM	12-2-93 12-3-93
348/349	X3-3 TAN BASES	7:20 AM	8:25 PM	12-3-93
353/354	X3-3	8:30 PM	10: AM	12-4-93 12-3-93
355/356	L3-3	10:10 AM	approx 11:15 PM	12-4-93
378/379	L3-3	7:20 PM	8:30 AM	12-15-93 12-14-93
374/377	L3-3	8:40 AM	9:40 PM	12-15-93
405	L2-1	12:45 AM	approx 1:20 PM	12-27-93 12-28-93
412/414	L3-3	9:02 PM	10:30 AM	12-22-93
418/419	L3-3	10:40 AM	approx 10:40 PM	12-23-93

7PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
90+97	L3-3	7:20 AM	approx. 8:30 PM	10-11-93
105/106	L3-3	9:30 PM	7:30 AM	10-12-93
162/163	L3-3	10:10 PM	11:25 AM	10/11/93 P. 20-93 10-19-93
145	L3-3	2:00 PM	3:30 AM	10-21-93 10-20-93
172	L3-3	5:30	7:00 AM	10-21-93 10-22-93
177	L3-3	12:00 PM	1:45 PM	10-23-93 10-22-93
179-161	L3-3	2:15 AM	Stop at 3:25 when I went to camp in P. Sat 10-23-93	10-23-93
180A/186	L3-3	10:00 PM	11:15 AM	10-25-93 10-24-93
188	L3-3	11:30 AM	12:40 AM	10-26-93 10-25-93
209	L3-2	9:00 AM	10:10 PM	10-26-93
208/209	L3-3	9:00 AM	approx. 10:30 PM	10-28-93

7PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
922/923	L3-3	10:30 AM	approx 12:30 AM	9-10-93 9-5-93
936	L3-3	10:00 PM	approx 11:00 AM	9-10-93 9-13-93
951/952	L3-3	10:30 PM	approx 12:00 AM	9-16-93 9-15-93
969/970	L3-3	12:25 AM	approx 1:00	9-16-93 9-6-93
975/977	L3-3	6:15 AM	approx 7:30 PM	9-21-93 9-21-93
978	L3-3	9:00 AM	10:20 PM	9-22-93 9-22-93
992/993	L3-3	10:30 PM	12:00 PM	9-23-93 9-22-93
994/995	L3-3	12:10 PM	approx 1:00 AM	9-23-93 9-27-93
9410	L3-3	11:00 PM	12:00 PM	9-26-93
15	L3-3	250 AM	approx 3:30 PM	9-28-93
95	L3-3	11:30 AM	approx 12:45 AM	10-1-93 9-30-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
777/778	L3-3	12:30 PM	1:25 AM	7-27-93
779/780	L3-3	1:45 AM	3:00 PM	7/26/93
784/789	L2-1/L3-3	3:00 PM	4:30 AM	7-27-93
790/	L3-3	4:45 AM	5:50 PM	7-28-93
791/799	L3-3	10:00 AM	11:05 PM	7-28-93
801/802	X3-3	11:25 PM	12:25 AM	7-29-93
806	L3-3	4:45 PM	4:10 AM	7-30-93
811	L3-3	3:15 PM	4:30 AM	8-03-93
812/813	L3-3	12:30 PM	1:45 AM	8-04-93
814	L3-1	1:55 AM	3:00 PM	8-5-93
819/816	L3-1/L3-3	3:15 PM	4:10 AM	8-05-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
644/645	L2-1	4:00 PM	5:00 AM	6-15-93
646/647	L2-1	5:10 AM	6:10 PM	6-14-93
648/651	L3-3	6:45 PM	7:45 AM	6-15-93
652	L3-3	8:15 AM	9:45 PM	6-16-93
661	L3-3	9:50 PM	12:00 PM	6-17-93
665	L3-3	10:20 PM		6-18-93
673	L3-3	10:00 AM	11:15 PM	6-22-93
678	L2-1	7:00 PM	8:00 AM	6-24-93
685/686	L3-3	10:00 AM	11:00 PM	6-23-93
688/694	L3-3	11:35 PM	12:45 PM	6-24-93
696/695	L3-3	1:10 PM	2:25 AM	6-25-93
				6-29-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
481-483	L3-3	5:15 PM	6:00 AM 10:00 AM	4-7-93 4-6-93
484	L3-3	11:15 AM	12:40 PM	4-7-93 4-8-93
485/486	L3-3	10:45 AM	12:00 AM	4-9-93 4-8-93
489/491	L3.3 / L2.1	11:15 PM	10:15 PM	4-13-93 4-12-93
495	L3.3	10:15 PM	12:00 AM	4-13-93
492-493	L3.3	3:15 PM	4:35 AM	4-15-93 4-14-93
502/503	L3-3	4:45 AM	6:15 PM	4-15-93
504/	L2.1	6:30 PM	8:00 PM	4-16-93
510/511	L3-3	11:20 PM	11:10 AM	4-18-93 4-19-93
518/519	L3-3	2:00 PM	3:20 AM	4-20-93 4-21-93
516 A/520	L3-3	3:25 AM		4-21-93

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
456/457	L3-3	6:45 PM	8:00 AM	3-17-93 3-20-93
454/455	L2-1	8:45 AM	10:00 AM	3-20-93
458/459	L2-1	2:50 PM	3:55 AM	3-23-93 3-22-93
440/461	L3-3	1:30 PM	3:00 AM	3-24-93 3-23-93
462/463	L3-3	3:30 PM	4:50 AM	3-24-93 3-25-93
465/466	L2-1	3:30 PM	5:00 AM	3-27-93 3-31-93
464/467	L5-2 / L2-1	11:30 AM	12:15 AM	3-30-93 3-31-93
468/469	L3-3	10:15 AM	11:00 PM	3-31-93 3-31-93
472/473	L2-1	8:45 AM	10:00 PM	4-1-93 4-1-93
474/475	L3-3	4:00 PM	5:30 AM	4-01-93 4-3-93
479/480	L3-3	5:30 PM		4-01-93

①

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
737	L3-3	9:45 PM	11:50 PM	7-14-93
743/744	L3-3	9:15 AM		7-16-93
742/740	L3-3 / ^{no gun} L3-2	10:05 PM	11:15 AM	7-18-93
748	L3-3	11:30 AM	12:37 AM	7-20-93
751/752	L2-1	12:40 AM	145 PM	7-20-93
753/757	L2-1	1:50 PM	3:10 AM	7-21-93
759/760	L3-3	3:20 AM	3:20 7:00 PM	7-21-93
761/762	L3-3	7:35 PM	9:30 AM	7-22-93
763/764	L3-3	8:45 AM	^{approx} 10:10 PM	7-21-93
773/774	L3-3	10:00 PM	11:25 AM	7-22-93
775/776	L3-3	11:30 AM	1:00 PM	7-25-93
767/768	L2-1	11:15 AM	12:20 PM	7-25-93
				7-26-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
817/818	X3-3	4:18 AM	6:00 PM	8-6-93
821/822	X3-3	10:20 PM	11:30 AM	8-6-93
832	L3-1	1:30 PM	11:50 PM	8-7-93
824/825	X3-3			8-9-93
829/830	L3-3	12:00 AM	1:15 PM	8-9-93
830	L3-3	2:00 PM	3:15 AM	8-10-93
839/840	X2-1	3:22 AM	4:30 PM	8-11-93
841/842	X2-1	4:45 PM	7:00 AM	8-10-93
831/843	L3-1/L2-1	7:40 AM	8:50	8-11-93
844/845	L2-1	9:05 PM	10:15	8-12-93
846	L2-1	10:35 AM	11:50 PM	8-12-93
857	L2-1	2:30 PM	3:45 AM	8-16-93

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
41/42	L3-3	9:20 AM	approx 11:00 PM	10-1-93
46	L3-3	3:10 AM	4:15 PM	10-4-93
49/54	L3-3	4:30 PM	5:30 AM	10-5-93
56	L3-3	5:33 AM		10-4-93
55	L3-3	8:30 PM	9:45 AM	10-5-93
65/66	L3-3	10:00 AM	11:05 PM	10-6-93
67/69	L3-3	11:12 PM	12:30 PM	10-7-93
68/70	L3-3	12:55 PM	2:01 AM	10-6-93
78/79	L3-3	10:50 AM	approx 12:00 PM	10-7-93
91/92	L3-3	4:45 AM	approx 6:00 PM	10-8-93
88+89	L3-3	Run 106055 OK Restarted 10:00 PM	approx 1:00 AM	10-9-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
607-608	L2-1	7:05 PM	8:15 AM.	6-2-93 6-1-93
613-614	L3-3	10:05 PM	11:30 AM	6-3-93 6-2-93
615-616	L2-1	11:40 AM	approx 12:30 AM	6-3-93
617	X3-3	1:30 AM	2:30 PM	6-4-93 6-3-93
619/620	L2-3	1:30 PM	2:30 AM	6-4-93 6-7-93
621/622	L2-1	1:10 PM	approx - 2:10 AM	6-8-93
624/625	L3-3	7:35 PM		6-8-93
632/633	L3-3	3:30 PM	4:40 AM	6-11-93 6-10-93
637	L2-1	3:30 PM	approx - 4:40 AM	6-12-93 6-11-93
639	L2-1	7:45 AM	2:15 AM	6-14-93 6-12-93
643/642	L3-3	2:25 AM		6-14-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
555/556	L3-2	9:30 AM	10:30 PM	5-5-93 5-5-93
558/559	L3-1 / L3-3	12:15 AM	1:45 PM	5-6-93
559/560	L3-3	2:00 PM	3:15 AM	5-10-93 5-11-93
563/564	L2-3	6:05 PM	7:15	5-11-93 5-12-93
569/570	L3-3	7:45 PM	9:00 PM	5-12-93
569	L2-1	9:50 PM	11:30 PM	5-12-93 5-13-93
567/568	L6-1	1:00 PM	2:00 AM	5-13-93 5-14-93
571	L3-3	2:10 AM	3:15 PM	5-14-93
565/566	L5-2	3:30 PM	4:40 AM	5-14-93 5-15-93
572	L2-1	4:45 AM	5:15 PM	5-15-93 5-15-93
574/575	L3-3	6:00 PM	7:15 AM	5-17-93 5-12-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
363/364	L3-3	3:45 PM	8:15 AM	1-19-93 1-20-93
969/370	L5-2	12:25 PM	4:30 PM not used	1-20-93 1-20-93
972	L3-3	12:30 PM	1:45 AM not used	1-21-93 1-25-93
373/374	L2-1	2:00 PM	3:32 AM	1-26-93
375/376	X2-1	3:36 AM	5:00 PM approx	1-26-93
378	L3-3	8:00 PM	9:30 AM Rem 28.000 cycles	1-27-93 1-28-93 1-29-93
380/381	L5-2	5:00 PM		2-1-93
382/383	L2-2	10:00 PM	11:15 AM	2-2-93
384	L2-1	11:30 AM	12:45 AM approx	2-2-93 2-3-93
385/386	L3-3	1:05 AM	2:45 PM	2-3-93
387/388	L3-3	7:00 PM	8:15 AM	2-3-93 2-4-93

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
332A/333A	QUIET SWFTON L3-3	4:00 PM	5:15 AM	1/05/93
342/343	L3-3	2:00 PM	APPROX. 3:20 AM	1-6-93 1-7-93 1-8-93
344/345	L3-3	4:00 PM	APPROX 5:00 AM	1-8-93
347/348	L3-3 / L2-1	7:10 AM	2:10 AM	1-09-93 1-11-93
349/350	L2-1	2:20 AM		1-11-93
348/351	L3-3 / L3-3	11:00 AM	12:15 AM	1-13-93 1-12-93
348/355	L2-1 / L3-3	5:30 PM	8:00 PM	1-14-93 1-15-93
353/354	L2-1	9:45 PM		1-15-94 1-15-93
357/358	L3-3	10:30 PM		1-18-93 1-19-93
359/361	L2-1 / L3-3	11:30 AM	12:30 AM	1-19-93 1-19-93
360A	L2-1	12:55 AM	2:00 PM	1-19-93 1-19-93

7PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
435	L2-1	12:00 PM	approx 1:00 AM	3-9-93 ends 3-8-93
437/438	L3-3	11:35 AM	3:00 PM	3-9-93 3-9-93
436	L5-2	12:00 PM	approx 1:00 AM	3-10-93
440/441	L9-3	10:00 AM	approx 11:30 AM	3-11-93
439/442	L3-3 / L2-1	11:40 AM	1:00 PM	3-12-93
443/444	L9-2	1:30 PM	2:30 AM	3-13-93 3-12-93
445	L6-1	3:00 AM	approx 4:00 AM	3-13-93 3-15-93
446/447	L3-3	6:40 PM	9:15 AM	3-15-93 3-16-93
448/449	L9-3	11:10 AM	approx 2:00 AM	3-16-93 3-17-93
450/451	L9-3	10:45 AM	1:30 AM	3-18-93
452/453	L2-1	1:35 AM	2:45 PM	3-19-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
389/390	L3-3	8:30 AM	approx. 10:00 PM	2-4-93 2-4-93
391	L5-2	10:15 PM	11:35 AM	2-4-93 2-5-93
392/393	L3-3	11:30 AM	12:45 AM	2-9-93 2-10-93
394/395	L3-3	12:50 AM	2:30 PM	2-10-93 2-10-93
396/397	L3-3	9:00 AM	approx. 11:00 PM	2-11-93
398	L3-3-3	3:15 PM	4:00 AM	2-15-93 2-16-93
400	L3-3	01:15 PM	2:45 AM	2-16-93
401/402	L3-3	12:00 PM	approx. 1:00 AM	2-18-93 2-19-93
405/406	L2-1	2:30 AM	4:00 PM	2-18-93
404/407	L3-3	4:15 PM	5:40 AM	2-18-93 2-19-93
409	L3-3	5:45 AM		2-19-93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
403/410	L3-3	2:00 PM	9:30 AM	2-19-93 2-20-93
413	L9-9	2:15 PM	4:30 AM	2-23-93 2-24-93
414	L3-3	11:30 PM	12:00 PM	2-24-93 2-26-93
420/421	L9-1	1:00 PM	2:30 AM	2-26-93
415/416	L9-3	7:30 AM	1:50 AM	2-27-93
417/418	L3-3	2:00 AM	3:15 PM	3-1-93
422/423	L2-1	6:45 PM	8:15 AM	3-01-93 3-2-93
424/430	L5-2/L3-3	3:30 PM	4:45 AM	3-02-93 3-4-93
431	L3-3	4:50 AM		3-4-93
433	L3-3	7:00 PM	8:15 AM	3-5-93 3-4-93
434	L8-9	10:45 AM		3-5-93

TMHNTSA 011853

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP AM	DATE
521	L2-3	5:00 P.M.	6:00 AM	4/21/93
522	L2-1	5:00 P.M.		4/21/93
523/527	L2-1/L3-3	6:30 AM	7:30 PM	4-22-93
528/525	L6-1/L3-3	2:15 PM	3:30 AM	4-23-93
533/534	L3-3	7:15 PM	8:30 AM	4-24-93
535/537	L2-1/L3-3	8:45 AM		4-26-93
538/540	L3-3/L2-1	11:00 PM	2:30 PM	2-27-93
539/541	L2-1	2:40 PM	4:00 AM	4-28-93
543	L3-3	4:05 AM		4-29-93
548	L3-3	11:25 PM	12:12	4-30-93
546	L5-2	6:15 PM	7:45 AM	5-03-93
551	L3-3	6:15 PM	7:30 AM	5-04-93

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
576	L3-3	2:45 PM	3:25 AM	5-18-93 5-19-93
579	L3-3	7:15 PM	8:15 AM	5-20-93 5-19-93
580-581	L3-3	1:45 PM	2:45 AM	5-20-93 5-21-93
584-585	L3-3	2:50 AM	5:30 PM	5-21-93 5-21-93
586-587	L3-3	5:45 PM	approx 6:50 AM	5-22-93 5-21-93
588/590	L3-3	6:45 PM	7:45 PM	5-25-93 5/24/93
592/591	L3-3	8:00 AM	7:00 PM	5-25-93 5-26-93
593/594	L2-1	10:10 PM	11:00 PM	5-25-93 5-27-93
600	L3-3	6:30 PM	7:45 AM	5-26-93 5-27-93
601/02	L3-3	5:30 PM	6:45 AM	5-27-93 5/27/93
625/606	L2-1	5:00 PM	9:00 AM	5/28/93

77PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
699 / 698	L2-1 / L3-3	2:30 AM	3:30 PM	6-30-93
700 / 703	L2-1 / L3-3	3:45 PM	5:00 AM	7-1-93 6-30-93
704 / 705	L3-3	5:05 AM	6:30 PM	7-1-93
706	L3-3	6:45 PM	8:00 AM	7-2-93
707 A / 708 A	L3-3	10:10 PM	11:30 AM	7-1-93 7-6-93
712	L3-3	9:00 PM	approx 3:30 AM	7-6-93 7-7-93
711 A	L3-3	3:25 AM	5:00 PM	7-7-93
715	L2-1	11:45 AM	approx 1:00 AM	7-8-93 7-9-93
722-723	L2-1	9:15 PM	4:20 AM	7-13-93
721 -	L2-1	4:25 AM	approx 6:00 PM	7-13-93
728 / 729	L3-3	8:00 PM	8:45 AM	7-14-93 7-13-93

7PS

IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
210/211	L3-3	10:45 PM	11:55 AM	10-28-93
225	L3-1	9:30 PM	11:00 AM	11-2-93 11-01-93
234/235	L3-3	9:45 PM	11:15 AM ^{approx}	11-02-93 11-4-93
236/238	L3-3	11:30 AM	12:40 AM	11-3-93 11-4-93
237/239	L3-3	1:00 AM	2:15 PM	11-4-93 11-4-93
248/249	L3-3	2:30 PM	3:30 AM	11-4-93 11-5-93
250/251	L3-3	3:30 AM	4:30 PM ^{approx}	11-5-93
253/254	L3-3	6:00 PM	7:00 AM ^{approx}	11-05-93
245	L3-1	9:00 AM	10:15 PM	11-10-93
269	L2-3	9:10 PM		11-10-93
271 & 272	L3-3	11:30 PM		11-11-93

77PS IMPULSE TEST LOG SHEET

DISC LOT	DEVICE	START	STOP	DATE
274	✓ 3-3	4:45 PM	5:40 AM	11-13-93
283	29-1	12:10 PM	approx 1:30 AM	11-12-93
290/291	29-3	2:15 PM	approx 3:30 AM	11-17-93
292/293	✓ 3-3	3:45 AM	4:50 PM	11-12-93
294/295	✓ 3-3	5:30 PM	6:30 AM	11-18-93
296/303	✓ 3-3	10:35 AM	approx 11:00 PM	11-19-93
304	✓ 3-3	2:30 PM	9:45 AM	11-20-93
315/311	✓ 3-3	1:40 PM	approx 2:45 AM	11-18-93
333/334	✓ 3-3	6:45 PM	8:00 AM	11-24-93
339	✓ 3-3	8:15 AM	9:30 PM	11-30-93
340 & 341	✓ 3-3	12:15 AM	approx 1:30 PM	12-1-93