

EA02-025

**TEXAS INSTRUMENTS,
INC.'S 9/10/03
ATTACHMENT**

REQUEST NO. 7

BOX 8

PART A-U

PART H

HILITE INDUSTRIES, INC.
1671 SOUTH BROADWAY
CARROLLTON, TX 75006
PHONE: (214) 242-2116 FAX: (214) 242-2902

NON-CONFORMING MATERIALS ADVISORY NOTICE

T.I.
REF #1-8

DATE: 1/12/95 HILITE DIVISION: PITTS
SUPPLIER: TEXAS INSTRUMENTS MAPCO
PART NUMBER: 2-06495-00 (F2AC-9F924-AA) ☒ SURFACES
PART DESCRIPTION: SWITCH- TRACE #: R 3 6 6

THIS ADVISORY IS TO ALERT YOU TO A CONDITION WHICH IS NON-CONFORMING TO SPECIFICATION; YET WE ARE ACCEPTING THE PARTS "AS IS" AT THIS TIME. CORRECTIVE ACTION IS REQUIRED TO PREVENT REJECTION OF THE MATERIAL IN THE FUTURE. YOUR RESPONSE ON THE ATTACHED CORRECTIVE ACTION REPORT IS REQUIRED WITHIN FIVE WORKING DAYS.

LOT NUMBER ASSIGNMENT: 209775 TYPE OF DEFECT: DIMENSIONAL
DATE RECEIVED: 9/29/94 TEST MATERIAL
SAMPLE SIZE: SLIP NO 6 STAND PACKAGING
OF DEFECTIVES IN SAMPLE: 0 4 FAILED ☒ DOCUMENTARY
QUANTITY RECEIVED: 7616 OTHER
P.O. NUMBER: 62324

DESCRIPTION OF NON-CONFORMING CONDITION(S): REACTION TIME IS
EXCESSIVE - FAILED TEST STAND -
NORMALLY CLOSED SWITCH - OPEN WHEN
PRESSURE APPLIED - REMAIN OPEN AND THEN
FINALLY CLOSE - RETESTED IN LAB - SEE
ATTACHED RESULTS

GA Coniskey
QA REPRESENTATIVE

MANUFACTURING REPRESENTATIVE

ENGINEERING REPRESENTATIVE

1/14/95 8-D.

-MSG M#- 460538 FR-GAMY TO-JW02 SENT=01/17/95 06:28 AM
R#-194 ST-C DIV-0050 CC-00149 BY-GAMY AT=01/17/95 06:20 AM

To: Jim Watt JW02
Copy: Chris D. Wagner CDW3 Matthew J. Sellers MJS2
Timothy R Spooner TRS1
From: Elaine Rose GAMY
Subj: ~~ELITE~~ RETURNS

RECEIVED 8 77PSL3-1 FROM GEORGE COMISKY ON 1/13/95 FOR FAILING ON THEIR
TEST STAND. TI REF # 1-4 WERE RETURNED AS GOOD; TI REF # 5-8 WERE
REPORTEDLY REMAINING OPEN.

ALL DEVICES WERE TESTED ON OUR AUTOMATED EQUIPMENT AND PASSED.

TROUBLE NOT FOUND AT THIS TIME.

REGARDS,

ELAINE

LET'S GET
THE DESIGN
GUYS TO LOOK
FOR CLEARANCES/
HYPOS ETC.

[Signature]

TLNHT8A 011829

-MSG N#- 460538 FR=GAMY TO=COPY SENT=01/17/95 06:28 AM
ST=C DIV=0050 CC=00149 BY=GAMY AT=01/17/95 06:20 AM

To: Jim Watt

JW02

Copy: Chris D. Wagner
Timothy R Spooner

CDW3
TR81

Matthew J. Sellers

MJS2

From: Elaine Rose

GAMY

Subj: HILITE RETURNS

RECEIVED 8 77PSL3-1 FROM GEORGE COMISKY ON 1/13/95 FOR FAILING ON THEIR
TEST STAND. TI REF # 1-4 WERE RETURNED AS GOOD; TI REF # 5-8 WERE
REPORTEDLY REMAINING OPEN.

ALL DEVICES WERE TESTED ON OUR AUTOMATED EQUIPMENT AND PASSED.

TROUBLE NOT FOUND AT THIS TIME.

REGARDS,

ELAINE

TI-NHTSA 011830

-MSG M#- 461662 FR=TRSI TO=GAMY SENT=01/17/95 07:14 AM
R#-189 ST=C DIV=0050 CC=00134 BY=TRSI AT=01/17/95 07:14 AM

To: "Rose, Elaine GAMY" (GAMY@mimi)
"Watt, Jim" (JWatt@klixon.itg.ti.com)

Copy: "Amore, Alan 12-29" (alan.amore@a1@mimi)
"Wagner, Chris 12-29" (chris.wagner@cdw3@mimi)
"Snyder, Gary 12-33" (gary.snyder@gjs1@mimi)
"Sellers, Matthew 12-29" (matthew.sellers@mjs2@mimi)

From: "Spooner, Tim" TRSI (tspooner@klixon.mo.ti.com)

Subj: RE: HILITE RETURNS

JIM / ELAINE:

DO WE UNDERSTAND MODE OF FAILURE AT CUSTOMER? BEFORE WE RESPOND 'TMP',
LNT'S BE PREPARED TO WALK GEORGE THROUGH POSSIBLE REASONS FOR HIS FINDING
AND HOW HE MIGHT FIX IT. PLEASE LET ME KNOW HOW I CAN HELP WITH THIS
PROCESS. MY THINKING IS BASED ON CUSTOMER'S SENSITIVITY TO WORDS TO THE
EFFECT OF "IT'S NOT US".

THANKS,
TIM

To: GAMY@mimi
From: tspooner
Subject: HILITE RETURNS
Date: Tuesday, January 17, 1995 6:28AM

-MSG M#- 460538 FR=GAMY TO=TRSI SENT=01/17/95 06:28 AM
R#-186 ST=C DIV=0050 CC=00149 BY=GAMY AT=01/17/95 06:20 AM

To: Jim Watt JW02

Copy: Chris D. Wagner CDW3 Matthew J. Sellers MJ82
Timothy R Spooner TRS1

From: Elaine Rose GAMY

Subj: HILITE RETURNS

RECEIVED 8 77FSL3-1 FROM GEORGE COMISKY ON 1/13/95 FOR FAILING ON THEIR
TEST STAND. TI REF # 1-4 WERE RETURNED AS GOOD; TI REF # 5-8 WERE
REPORTEDLY REMAINING OPEN.

ALL DEVICES WERE TESTED ON OUR AUTOMATED EQUIPMENT AND PASSED.

TROUBLE NOT FOUND AT THIS TIME.

REGARDS,

ELAINE

TI-NHTSA 011931

1-25-95

(5013 -) D/C

5016 5 pcs.

5019 5 pcs.

5025 10 pcs.

5025A 5 pcs.

PRESSURE SWITCH DATA

FORM 21605

TEST NO.

DEVICE 77PSL3-1	DATE REQUESTED 1-27-95	REQUESTED BY	REQUESTED COMPL. DATE
PERFORMED BY ELAINE ROSE	DATE STARTED 1-27-95	DATE COMPLETED	APPROVED BY
PROJECT TITLE: Release Test Failure			

CUSTOMER: **HiLite Ind.**PURPOSE OF TEST: **Sample finished Goods; test in Life test
Various Date Codes**

PROCEDURE:

D/C	Act	Rel	Diff	Cont.				
5016	146	120	26	✓				
"	145	122	23	✓				
"	146	122	24	✓				
"	144	112	32	✓				
"	138	115	23	✓				
5019	140	118	22	✓				
"	138	108	30	✓				
"	135	126	9	✓	120/105	138/122	140/110	
"	145	126	19	✓				
"	140	115	25	✓				
5025	130	98	32	✓				
"	132	110	22	✓				
"	145	120	25	✓				
"	146	118	28	✓				
"	138	106	32	✓				
"	138	115	23	✓				
"	134	100	34	✓				
"	136	102	34	✓				
"	134	102	32	✓				
"	130	105	25	✓				
5025A	125	98	27	✓				
"	132	105	27	✓				
"	122	94	28	✓				
"	124	102	22	✓				
"	138	110	28	✓				

(OVER)

TI-NHTSA 011933

MSG# 797998 FR-GAMY TO-COPY SENT=01/25/95 09:42 AM
ST-C DIV=0050 CC=00149 BY-GAMY AT=01/26/95 09:29 AM

To: Chris D. Wagner CDW3 Matthew J. Sellers MJS2
Timothy R Spooner TRS1 *Jim*
Copy: Andrew McGuirk ACM1 Gary J. Snyder GJS1
From: Elaine Rose GAMY
Subj: HILITE RETURNS

WE HAVE RECEIVED ANOTHER 7pcs. FROM GEORGE COMISKY FOR TEST FAILURE.
THESE WERE TESTED ALONG WITH THE 8pcs. ORIGINALLY RETURNED, IN LIFE TEST.
THERE WAS 1 DEVICE WITH A CONTINUITY ANOMALY. I WINDOWED THE DEVICE &
TOGETHER WITH CHRIS, WE CHECKED IT UNDER THE SCOPE. THERE APPEARS TO BE
FLUID BETWEEN THE CONTACT & TERMINAL AREA AS WELL AS PARTICLE CONTAMINATION

I HAVE SUBMITTED THE BASE ASSEMBLY TO TSL FOR ANALYSIS. I WILL SEND
YOU THE RESULTS AS SOON AS BETH COMPLETES TESTING.

GEORGE COMISKY IS EXPECTING AN 8D ON THESE DEVICES.

REGARDS,

ELAINE

TI-NHTSA 011934

**TEXAS INSTRUMENTS INCORPORATED
CORRECTIVE ACTION REPORT**

Report Number: PSCAR95_XX
Date Opened: 01/26/95
Updated: 01/26/95
Customer: HILITE INDUSTRIES
TI p/n (s): 77PSL3-1
Customer p/n (s): F2AC-9F924-AA
CAR description: UNUSUALLY LOW RELEASE SIGNAL

#1-8
#7-15

(Step 1) Champion and Team Members

Matt Sellers	Mfg. Engineering (Champion)
Jim Watt	QRA Engineering
Elaine Rose	QRA Technical Support
Chris Wagner	Product Design Engineering

(Step 2) Problem Description

On January 13, 1995, 8 switches were returned to TI Attleboro, with test data for each. From the paperwork submitted, it appears that 4 which had passed Hilite's end of line test and 4 which had exhibited unusually low release (cut-in) signals were all retested by a man named Doug in Hilite's lab. The results of the retest are included, which 1) confirmed the 4 'normal release' switches as normal and 2) showed 3 of the 4 'low release' switches to be normal. A single device was shown in the lab retest results to have no continuity change on release.

Upon arrival of the 8 switches at TI Attleboro, they were tested on production equipment and were found to meet specification.

On January 23, 1995, 7 additional switches were returned to TI Attleboro for the same problem. There was no lab retest or retest results indicated.

Upon arrival of the 7 additional switches at TI Attleboro, they were tested in the design engineering laboratory and were found to meet specification. The 7 additional switches were then retested on production equipment and again found to meet specification.

The second incidence of the occurrence (at, we believe, the end of Hilite's process) prompted us to retest the first eight switches on January 25, 1995. The single switch which was recorded by the Hilite lab as having no continuity change was again found to operate within specification, with solid continuity change above 20 psi, but some dithering in the continuity signal was observed just below the release point. After cutting a window in side of the switch, a contaminant was observed on the stationary contact surface. This contaminant is now being analyzed for composition at the TI Technical Service Laboratory. We are also subjecting the other returned devices to analysis to ensure no contaminants are present on them.

It is TI's judgement at this time that the end-of-line test anomaly seen is not related to the contamination discovered in the single device. The contamination found must be addressed and permanently eliminated from recurrence. The performance of the single device with dithering on release as observed would not have a negative effect in the vehicle, and the signal would likely improve with repeated contact actuation.

(Step 3) Containment and Short Term Corrective Actions

Samples were removed from finished goods for verification in the design engineering lab. All devices met specification. No anomalous behavior was observed.

COMP

ZPLF ("zero pressure logic failure) fallout samples from the manufacturing line's 100% function test are being reverified as failures and analyzed for failure cause, in search of more contaminant as a contributor.

1/27/95

(Step 4) Definition and Verification of Root Cause

1) Contamination on the single device: Origin of contamination may be ascertainable after composition is understood.

2) Balance of returns: We do not know why 10 other switches were identified as faulty by Hilite's test. An important fact to consider is that the Hilite lab result and TI lab result matched closely. The Hilite lab test appears to be a good check for the end-of-line process.

(Step 5) Permanent Corrective Actions

TBD following root cause determinations for 1) and 2) above.

(Step 6) Verification of Permanent Corrective Actions

TBD

(Step 7) Prevent Recurrence

TBD

Sellers, Matt

From: Ras, Ann Marie
To: Rooha, Lou; Sellers, Matt; Lapante, Bill W.J.
Subject: Cost Update of Function Tester Upgrades
Date: Monday, April 08, 1996 7:02AM

There will be a meeting to discuss the costing/progress of the 3 pressure tester upgrades on Wednesday, April 8 at 1:00pm in the cafeteria. If the cost information has not been completed at that time, please let me know so that I can reschedule. Thank you.

Ann

Pressure Tester #1 (52PS)

Currently Funded Items:

- 1) Computer Upgrade
- 2) Pneumatic Upgrade
- 3) Conveyor Motor Speed Upgrade
- 4) Conveyor Belt/Rail Modification
- 5) O-Ring Station Plug Modification
- 6) Guard Modification
- 7) Sonalert Addition to O-Ring Station
- 8) Automatic Defaults for All Unload Stations

Currently Nonfunded Items:

- 1) Conveyor Unload System
- 2) Scribe Relocation (numeric symbol 1)
- 3) Thread Cap Load Station
- 4) Centralized Database for Bldg 12 Easy access

Pressure Tester #2 (57PS)

Currently Nonfunded Items:

- 1) 90PS Compatibility
 - Seals
 - Programming
 - Pneumatics?
- 2) Centralized Database for Bldg 12 Easy Access

Pressure Tester #3 (77PS)

Currently Nonfunded Items:

- 1) O-Ring Station Upgrade
- 2) Scribe Relocation (numeric symbol 3)
- 3) Thread Cap Load Station Simplification
- 4) Conveyor Unload Station
- 5) Centralized Database for Bldg 12 Easy Access
- 6) Automatic Defaults for All Unload Stations
- 7) Guarding Upgrade

52 /57 /77 PRESSURE TESTER UPGRADE PLAN

52PS PRESSURE TESTER

COMPL DATE

- | | | |
|--|----------|---------|
| 1. BUILD & INSTALL NEW O-RING CHECK STATION | DAN/DOUG | 1/31/95 |
| 2. DESIGN, BUILD, INSTALL CRIMP RING SCRATCH STATION | DAN/DOUG | 1/31/95 |

77PS PRESSURE TESTER (CDS784)

- | | | |
|---|------------------|---------|
| 1. LAYOUT, DETAIL DWGS & PARTS LIST FOR UNLOAD SYSTEM | DAN/BILL M | 1/31/95 |
| STELCON UNLOAD STATION | BILL M. | |
| O-RING STATION | DAN | |
| CAP INSERT STATION | BILL M. | |
| SCRATCH STATION | DAN | |
| CONVEYOR SYSTEM | BILL M. | |
| FRAME | DOUG M. | |
| 2. MARK UP ELEC DRAWINGS AND SUBMIT TO B20 FOR SW DES | DOUG | 2/10/95 |
| RELEASE WORK ORDER FOR B20 SW DESIGN | AND | 2/10/95 |
| 3. BUILD FABRICATED PARTS FOR | DAVE F. | 3/31/95 |
| O-RING CHECK STATION, | | |
| CRIMP RING SCRATCH STATION | | |
| CONVEYOR COMPONENTS | | |
| CONVEYOR FRAME | REUTE CO. | |
| 4. ORDER ALL COMMERCIAL PARTS FOR ABOVE | DAN/BILL M./DOUG | 2/10/95 |
| STELCON UNLOADER | | |
| CONVEYOR MOTOR/CONTROLLER | | |
| VALVES, CYLINDERS | | |
| ELECTRICAL COMPONENTS | | |
| 5. ORDER HENDRICKS BOWL SYSTEM FOR CAP INSERT | DAN/BILL M. | 1/13/95 |
| 6. ASSEMBLE STATIONS AND MOUNT ON FRAME | DAN | 4/28/95 |
| O-RING CHECK | | |
| CRIMP RING SCRATCH | | |
| CONVEYOR ASSY | | |
| STELCON UNLOADER | | |
| 8. SHUT DOWN PRESSURE TESTER AND START INSTALLATION | DAN/DOUG/LOU C | 5/1/95 |
| O-RING CHECK | | |
| CRIMP RING SCRATCH | | |
| CONVEYOR ASSY | | |
| STELCON UNLOADER | | |
| 9. COMPLETE DESIGN AND RELEASE TO PRODUCTION | DAN/DOUG/LOU C | 5/15/95 |
| 10. BUILD CAP INSERT STATION | DAN | TBD |
| 11. INSTALL CAP BOWL & INSERT STATION | DAN | TBD |

77PS PRESSURE TESTER

- | | | |
|--|---------|-----|
| 1. UPDATE DWGS FOR NEW O-RING AND SCRATCHER STATION | BILL M. | TBD |
| 2. BUILD O-RING CHECKER AND CRIMP RING SCRATCH STATION | DAVE F. | TBD |
| 3. UPDATE CAP INSERT STATION | DAN | TBD |
| 4. INSTALL O-RING CHECKER AND SCRATCHER STATIONS | DAN | TBD |

NOTE: FOR THE 57 UNLOAD CONVEYOR, SINCE THE OPERATOR HAS TO REMOVE BAD O-RING PARTS, WE RECOMMEND THE 52PS CONVEYOR ORIENTATION, NOT THE 77PS ORIENTATION. THIS WILL NECESSITATE MOVING THE ENTIRE SYSTEM ABOUT 2 FEET IN AND 2 FEET LEFT SO THE CONVEYOR DOES NOT OVERLAP EITHER ISLE. ALSO, A SECTION OF ISLE WALL SHOULD BE REMOVED FOR BETTER OPERATOR ACCESS IN AND OUT OF LOAD STATION.

LOU ROCHA, REV A 12/09/95

TI-NHTSA 011938

Sellers, Matt

From: Sellers, Matt
To: Roche, Lou; Laplante, Bill W.J.
Cc: Res, Ann AMR2; Sweet, Bill WS4; Arseneault, Stephen SFA2; McNamara, Margaret MPMA
Subject: Hyd PS tester upgrades - status meeting
Date: Thursday, April 06, 1995 8:56AM

Let's plan to meet as we decided:

Monday April 10 @ 3:00pm in the cafeteria.

We will need to review the following information at this meeting:

Pressure Tester #1 (52PS)

- * Timing to complete computer and pneumatic upgrades. (SC65)?
- * Status of oring station flag modification.
- * Status of solenoid addition to oring station.
- * Status of scribe relocation, (all 3 testers).
- * Thread cap installation station. Plan to determine \$ and timing.

Pressure Tester #2 (57PS)

- * 5/1 installation date OK?
- * \$ for new unload system on within budget?
- * Status of scribe relocation, (all 3 testers).
- * Status of centralized data base for defaults. Bldg. 12 access.
- * Status of 60PS capability development.

Pressure Tester #3 (77PS)

- * Status of oring station build. Have we started building along with tester 2 station?
We need \$/timing to allow for capital/expenditure arrangements.
- * Scope of changes required to thread cap installer to simplify after oring station add.
- * Status of scribe relocation, (all 3 testers).
- * Status of centralized data base for defaults. Bldg. 12 access.

See you Monday!

Regards,
Matt

Sellers, Matt

From: Rea, Ann Marie
To: Rooha, Lou; Sellers, Matt; Laplante, Bill W.J.
Subject: Cost Update of Function Tester Upgrades
Date: Monday, April 03, 1985 7:02AM

There will be a meeting to discuss the costing/progress of the 3 pressure tester upgrades on Wednesday, April 5 at 1:00pm in the cafeteria. If the cost information has not been completed at that time, please let me know so that I can reschedule. Thank you.

Ann

Pressure Tester #1 (52PS)

Currently Funded Items:

- 1) Computer Upgrade
- 2) Pneumatic Upgrade
- 3) Conveyor Motor Speed Upgrade
- 4) Conveyor Belt/Fall Modification
- 5) O-Ring Station Flag Modification → when ready
- 6) Guard Modification →
- 7) Borelert Addition to O-Ring Station
- 8) Automatic Defaults for All Unload Stations

Currently Nonfunded Items:

- 1) Conveyor Unload System → Hard
- 2) Scribe Relocation (numeric symbol 1) → Dg.
- 3) Thread Cap Load Station → 1/2" + 1/4" + 1/8"
- 4) Centralized Database for Bldg 12 Easy access →

Pressure Tester #2 (57PS)

Currently Nonfunded Items:

- 1) 50PS Compatibility → Dwg to Bill Schedule/1st upgrade Tester unload v/g 5/1 install
 - Seals
 - Programming
 - Pneumatics?
- 2) Centralized Database for Bldg 12 Easy Access →

Pressure Tester #3 (77PS)

Currently Nonfunded Items:

- 1) O-Ring Station Upgrade →
- 2) Scribe Relocation (numeric symbol 3) →
- 3) Thread Cap Load Station Simplification
- 4) Conveyor Unload Station → 1/2" + 1/4" + 1/8"
- 5) Centralized Database for Bldg 12 Easy Access →
- 6) Automatic Defaults for All Unload Stations →
- 7) Guarding Upgrade →

P-2 TESTS							
	FORD						
	SA-TEST 1	SA-TEST 2	SA-TEST 3	CHEVROLET	SA-TEST 4	CHEVROLET	SA-TEST 5
	PPA-4000-AA	PPA-4000-AA	PPA-4000-AA	PP-4000	PP-4000	PP-4000	PP-4000
	POWER STYS	BRACE	BRACE	POWER STYS	POWER STYS	BRACE	POWER STYS
	800PS	80PS	77PS	800PS	800PS	800PS	800PS
CALIBRATION	100%	100%	100%	100%			
CREEP CHECK	100%	4LOT	N/A	100%			
LEAK CHECK	100%	N/A	N/A				
VOLTAGE DROP	8000	4LOT	4LOT	4LOT			
CURRENT LEAKAGE	8000	4LOT	4LOT	4LOT			
PROOF	8000	4LOT	4LOT	4LOT			
BURST	8000	4LOT	4LOT	4LOT	6MONTH		
TERMINAL STRENGTH	8000	4LOT	4LOT	4LOT			
VIBRATION	8000	8000	8000				
VACUUM	8000	8000	8000				
TEMP CYCLE	8000	8000	8000				
FLUID RESISTANCE	NA	NA	8000	NA			
IMPULSE	8000	8000	8000	4MONTH			
HUMIDITY	8000	8000	8000				
SALT SPRAY	8000	8000	8000				
TEMP CORRELATION	NA	NA	NA	NA	WEEKLY		
ISOLATION RESISTANCE	NA	NA	NA	4LOT			
--- CURRENT TEST STATUS ---							
CALIBRATION	100%	100%	100%	100%	100%	100%	100%
CREEP CHECK	100%	100%	N/A	100%	N/A		
LEAK CHECK	100%						
VOLTAGE DROP	PER PILOT	PER PILOT	PER PILOT	PER PILOT			
CURRENT LEAKAGE	PER PILOT	PER PILOT	PER PILOT	PER PILOT			PER PILOT
PROOF	PER PILOT	PER PILOT	PER PILOT	PER PILOT		PER PILOT	PER PILOT
BURST	PER PILOT	PER PILOT	PER PILOT	PER PILOT	6MON	PER PILOT	PER PILOT
TERMINAL STRENGTH	PER PILOT	PER PILOT	PER PILOT	PER PILOT			
VIBRATION			3/14/88				
VACUUM			3/17/88				
TEMP CYCLE			4/2/88				
FLUID RESISTANCE			5/10/88				
IMPULSE			5/10/88				
HUMIDITY			5/10/88				
SALT SPRAY			5/10/88				
TEMP CORRELATION	NA	NA	5/10/88	NA			
ISOLATION RESISTANCE	NA	NA	NA	NA	NA		
							POST TEST QUAL
							88/8-9-88

TT-NHTSA 011941

PRESSURE SWITCH DATA

Form 21605

TEST NO. 473-15-35

DEVICE

77PS

DATE REQUESTED

9/25/95

REQUESTED BY

KEITH ROTELLO

REQUESTED COMPL.

DATE

PERFORMED BY

DATE STARTED

9/23/95

DATE COMPLETED

APPROVED BY

PROJECT TITLE:

77PS VACUUM DEPENDENCY

CUSTOMER:

PURPOSE OF TEST:

DETERMINING EFFECTIVE PERIOD POST VACUUM

OF NORMAL PRODUCTION COMPONENTS

PROCEDURE:

CLIP TYPE -01 -01 -02 -02

3-1 / 3-2 / 4-1 / 6-1

50% 8 OF EACH.

RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.9V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSITIVITY: 500 PVI


10 PVI
 1

0.005V

77PSL3-1
 DEVICE
 1 BLUE
 2 GREEN
 3 ORANGE
 4 RED

TI-NHTSA 011843


1 of 2



RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.5V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSITIVITY: 800 psig

↓
 10 psi
 ↑

TI-NHTSA 011844



TPSL3-1

DEVICE	COLOR
5	BLUE
6	GREEN
7	ORANGE
8	RED

2 of 2

RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.5V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.05
 TRIGGER: MAN
 SENSITIVITY: 500 PSI


FS Y 300

10 psi
 1.00V

770513-2

CH	NAME
1	BLUE
2	GREEN
3	ORANGE
4	RED

TI-NHTSA 011945




RANGES: 3.000V 10.00V .250V
 OFFSETS: 0.0V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SP-STEP: 500 psig

10 psi
 4

77PSLB-2


CH	COLOR
5	BLUE
6	GREEN
7	ORANGE
8	RED

TI-NHTBA 011946



RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.9V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSITIVITY: 500 psig

↓
 10 psi
 4



77ASLY-1

CH	NAME
1	CH1
2	CH2
3	CH3
4	CH4

TI-NHTSA 011947

RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.3V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSITIVITY: 500 PSIG


10 PSI
 ↓
 ↑

TPS-4-1

5
 6
 7
 8

BLUE
 GREEN
 ORANGE
 RED

TI-NHTSA 011949




RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.5V 0.8V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSIT: 500 ppi

10 ppi
 1000V

T-NHTSA 011849

TIPS 6-1

DRIVE
 1
 2
 3
 4
 COMP
 TIME
 SPEC
 RUN &
 RES



RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.5V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SENSIT: 500 psig


10 psi
 ↑

0.005V

77PSLG-1

5	RED
6	BLUE
7	GREEN
8	PINK

TI-NHTSA 011850



RANGES: 3.000V 10.00V 1.250V
 OFFSETS: 0.5V 0.0V 0.05V
 TOTAL TIME: 1.00S
 POST-TRIG: 0.0S
 TRIGGER: MAN
 SMOOTH: 500 Hz

10 psi
 1

1.000V

70PSIG

#5 RETEST (BLUE)

#2 RETEST (RED)

TI-NHTSA 011951

**DRAWINGS AVAILABLE UPON
REQUEST**

-MSG M#- 017721 FR-JW02 TO-JSP1 SENT=10/09/95 09:40 AM
 R#-035 ST-C DIV-0050 CC-00149 BY-JW02 AT=10/09/95 09:40 AM

TO:	DICK GARTNEY	WJ03	MATT SELLORS	NJ01
	CHRIS WAGNER	CDW3	PEGGY ALLEN	MRMA
	ELAINE ROSE	SAMY	KEITH ROBIELLO	KROB
	TERRY RODRIGUEZ	TER7	BILL ISAACSEN	WAT
	PAUL FERREIRA	PJF4	ANN REA	AMR1
CC:	GARY SNYDER	GJ01	ANDY MCSUIRK	ACM1
	NORM FREDA	NTF	JOHN PECHONIS	JSP1
	LINDA BARBOZA	BOZA	TOM CHARBONEAU	TC
	MARTHA SULLIVAN	MNS	BRIAN DAGUE	DAGU
	RUSTY STRUBLE	RCS2	JOHN MAYER	JONS
	JIM WOOD	JWW3		
FM:	JIM WATT	JW02		

SUBJ: ALLIED-SIGNAL GALLATIN, TN 10/03/95 VISIT (77PBL3-3/L3-1PRSW)

Personnel Contacted:

Mike Ross	Supplier Quality Engineer
Mark Holland	Gage Calibration Lab Quality Engineer
Charles Wiley	Manufacturing Engineering Technologist
Lloyd Johnson	Product Engineer
Ray Kosarski	Senior Project Engineer, South Bend, IN
Eric Johnson	Gaging Engineer, Johnson Gage Company, Bloomfield, CT
Jim Watt	Texas Instruments QRA

The Allied-Signal Plant in Gallatin, Tennessee assembles master cylinder brake assemblies for Ford, Chrysler, Nissan, and Hyundai. They have a three shift operation, employing approximately 400 people. They plan on QS9000 registration by June '96, but do not currently require their suppliers to be ISO9000 or QS9000 registered.

The 77PBL3-3 cruise control pressure switch is mounted directly onto the master cylinder port housing assembly for the Ranger/Explorer cruise control platforms. Total Ranger/Explorer volumes are at 1kk/yr. The 77PBL3-1 switches are used on the Crown Vic series cruise control platforms. Total Crown Vic volumes are at 200k/yr. The pressure switch is initially installed by hand, and finish torqued with an open-end torque wrench. The purpose of the visit was to assess the reported pressure switch installation difficulties onto the mating master cylinder. The master cylinders are drilled at .335 +/- .001" (thru hole), and tapped with H5 taps. Plug gage used to check tapped hole is .3479".

The approximately (25) samples directly off of the Allied-Signal production line L3-3 and L3-1 switches checked with the TI ring gage (3A00) and torque wrench all passed; specifically, they did not trip the 4.5 in-lbf torque wrench. All of the hexports exhibited drag; none of the samples spun on freely.

The approximately (25) samples directly off of the Allied-Signal production line L3-3 and L3-1 switches checked with the Allied-Signal ring gage (3A00, mfg. Almeida) and the TI torque wrench had (4) switches trip the 4.5 in-lbf torque wrench. The Johnson Gage representative subsequently measured some samples that had not been previously gaged that showed .3479" (basic) & .002"

A comprehensive discussion ensued on the origin of the 3A-80 ring gage specification (ANSI B1.1 for plated external threads), as well as the origin for the 4.5 in-lbf applied torque (General Motors 4102 Surface Discontinuities & Finish Irregularities On Bolts & Screws), recommended tap sizes and allowances.

Though Allied Signal now understands what the pressure switch print specification means, they were not receptive to the specifications, specifically the 4.5 in-lbf torque allowance based upon a GM 4102 document.

The following actions were agreed to on 10/05/95:

1. TI-A and Allied Signal need to agree on a consistent method to assess threads. (The timing of this action is TBD based upon Allied-Signal's discussions with Ford Engineering on thread specifications.) - TBD
2. Allied-Signal will develop a plan by 10/09/95 to generate variable data on the master cylinder pitch diameter tapped hole. - Mike Ross (AS) 10/09/95
3. TI-A to recommend to Allied Signal a tap size and pitch diameter limits to avoid installation difficulties attributable to threads, with the current provisions of 3A-80 ring gage allowance and 4.5 in-lbf torque. - Brian Dague/ Jim Watt - 10/09/95
4. TI-A to communicate the .3479" tolerance specification call-out issue to Ford Engineering, John Pelkey. - Jim Watt 10/09/95
5. Characterize pitch diameter with variable data on Allied-Signal samples. Measurement of (24) sample L3-3 hexports shows pitch diameter average = .34789, cpk = .027; without using the 4.5 in-lbf. - Ann Rea (completed)
6. Follow-up and follow-on actions with Allied Signal will be based upon the above results. - Jim Watt 10/15/95

A sample master cylinder for the Light Truck (L3-3) switch and one for the Pass Car (L3-1) were brought back to TI-A for engineering evaluation.

Summary Points:

1. Hexport supplier (Elco Industries) is not capable to the 3/8 x 24 UNF Thread Standard.
2. 4.5 in-lbf torque allowance is a GM 4102 standard, not Ford or ANSI.
3. TI-A is meeting the current specification and gaging method on print.

Please let me know if anyone has any questions on the visit.

Regards,

Jim Watt

ext 1719

msgid:

JW02

ms 12-27

TI-NHTSA 011956

	PS REPORT LOG - 1995		
REPORT	DESCRIPTION	TESTED BY	DATE

TI-MHTSA 011987

1998 PRESSURE SWITCH REPORT INDEX

REPORT	DESCRIPTION	TESTED BY
PS/98/14	LIFE TESTING (TO FAILURE) OF 77PS STYLE DEVICE	HA
PS/98/15	PV TEST REPORT - 77PSL3-4 LANDROVER CLUTCH PRESSURE SWITCH	HA
PS/98/25	PV Test Report- John Hassall, Inc. Rivet (PN 74816-1) used in 77PS, 87PS	Misch
PS/97/14	HYDRAULICS IP-2 TEST SUMMARY 77PS	WATT
PS/97/28	77PS DERINGER CLAD CONTACT PV TEST REPORT	HA
PS/97/28	77PS DERINGER CLAD CONTACT PV TEST REPORT	HA
PS/98/01	IP-2 77PSL3-2 TEST SUMMARY	J.WATT
PS/98/20	77/87 SPRING ARM ANOMOLY STUDY	ROSIELLO
PS/98/30	RDA FORD AUSTRALIA 77PSL4-1 CORE# 1948276	HA
PS/98/52	IP-2 77PSL5-2 TEST SUMMARY	WATT
PS/98/83	IP-2 77PSL(3-3) test summary	WATT
PS/98/72	Elimination of vac dep. continuity loss on 77PS cruise control switch	ROSIELLO

TI-NHTSA 011958

DATE

4/3/96

4/5/96

6/26/96

4/4/97

5/5/97

5/5/97

1/31/98

3/3/98

7/10/98

8/18/98

8/8/98

10/13/98

TI-NHTSA 011959

Device12 Failed @ 2,728,196 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)




Diaphragm #3 (Washer/Converter Side)

TI-NHTSA 011980

Device 2 Pass 3,000,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 7 Failed @ 2,990,868 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)




Diaphragm #3 (Washer/Converter Side)

TI-NHTSA 011981

Device 5A Failed @ 2,925,825 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 12A Failed function test after 3,000,000 cycles. Number of cycles til leakage unknown.



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 3A Pass 3,000,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 4A Failed @ 2,865,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

TI-NHTSA 011063

Device 1A Failed @ 2,962,662 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 2A Pass 3,000,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device #4B Failed @ 2,999,015 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 6B Failed @ 2,725,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

TI-NHTBA 011986

Device 2B Pass 3,000,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)

Device 3B Pass 3,000,000 cycles



Diaphragm #1 (Fluid Side)



Diaphragm #2 (Middle Layer)



Diaphragm #3 (Washer/Converter Side)



34 Forest Street
P.O. Box 2984
Andover, MA 02703-0984
(508) 238-8800

November 14, 1995

Mr. Bob Manavi
Ford Oakville Assembly
P.O. Box 1300
Oakville, On L6J5C9
Canada

Subject: Vacuum Dependent Continuity Loss of 77PS Cruise Control Switches.

Dear Mr. Manavi,

Thank you very much for your assistance, it was a pleasure working with you. Your effort and timely response enabled us, as a team, to promptly bring closure to this issue.

Per our telephone conversation on Friday November 3, 1995, I have summarized the results of the investigation into your recent experience with the phenomena of vacuum dependent continuity loss.

The switches returned to T.I. were analyzed and tested according to the Ford Specification ES-F2VC-9F24-AA. The test results show all returned devices to be TNF (Trouble Not Found). Ford Oakville's investigation established that the continuity loss fallout at final test was probably caused by a dry-fill of the brake system. The corrective action implemented at Ford Oakville eliminates vacuum dependent continuity loss fallout, supports the root cause determination and brings this issue to a close.

Once again thank you for your assistance and cooperation. I look forward to working with you on future projects and strengthening our strategic partnership.

Sincerely,

A handwritten signature in black ink, appearing to read "Keith Rosiello".


Keith Rosiello
Design Engineering
Precision Controls

cc: Bryan Dague TI
John Pecton TI
Steve Proia TI

TERMINAL ASSEMBLY MACHINE (T.A.M.)

% REJECT AT B.A.M.

TI-NHT8A 011988




FILE

TERMINAL ASSEMBLY MACHINE (T.A.M.)

% REJECT AT B.A.M.

TI-NHTSA 011989



Rose, Elaine

From: postmaster
To: eross
Subject: ACTION COMPLETED - SEE RESPONSE
Date: Friday, December 29, 1995 9:17AM

-MSG #1= 12948 FR-GAMY TO-GAMY SENT-12/29/95 09:16 AM
R#115 ST=C DIV=0050 CC=00149 HY=GAMY AT-12/29/95 09:16 AM
TO: ELAINE S ROSE GAMY << CUSTOMER ACTION REQUEST >>
FR: ELAINE S ROSE GAMY << C U S T O M E R # 1 >>
CC: *PRIA TI Internal Data

RE: ACTION COMPLETED - SEE RESPONSE

Action Subject: CONTINUITY
Customer Name : HILITE IND.
Request Date : 06/20/94
14:22 Priority : NORMAL

Action #: 969464
STATUS: COMP
Added: 06/20/94
Type: R/PA
Org/LBN: PRMCA
ProdType: PC88-77
Device: 77PSL2-1

Sender Request by : ELAINE S ROSE

Userid: A66877

TI REF # 72 RETURNED FROM WILSON PLANT !!!

PARAMETERS

Customer part number	C F2VC-9F924-AB
TI part number	C 77PSL2-1
Unit price	C 2.21
Mark (S.R.)	C N/A
Date code/serial number	Q 3363
Reason for return	Q NO CONTINUITY
Customer count pcs	Q 1
TI count pcs	Q 1
# defective	Q 1
Inspection findings	Q NO CONTINUITY
Returned as received	M 0
Rework-return to cust	M 0
Rework-return to stock	M 0
Return to stock	M 0
Replace	M 0
Scrap	M 0
Hold for disposition	M 0
Customer location	C WILSON
Customer contact	C N/A
Phone number	C N/A
Customer rejection#	C QC REQUEST
Sold to #	C 616128
Ship to #	C 616136
Bill to #	C 616128
P.O. #	C VARIOUS
TI order #	C 0
Date returned	C 06/20/1994
Return type (R/F/D/P)	Q P
Cust C/A required?(Y/N)	Q Y
Cust C/A date due	Q
Root cause	Q TRAPPED DISC

Corrective action	Q
C/A complete date	Q
Defect code	Q G01
Quality return	Q 1
Unjustified return	Q 0
Service quality return	Q 0
Marketing return	Q 0
Document type	C A

***** END OF MESSAGE *****

Rose, Elaine

From: postmaster
To: eross
Subject: ACTION COMPLETED - SEE RESPONSE
Date: Friday, December 29, 1995 9:34AM

-MSG N# 13428 FR=GAMY TO=GAMY SENT=12/29/95 09:32 AM
R#139 ST=C DIV=0050 CC=00149 HY=GAMY AT=12/29/95 09:32 AM
TO: ELAINE S ROSE GAMY << CUSTOMER ACTION REQUEST >>
FR: ELAINE S ROSE GAMY << C U S T O M E R # 1 >>
TI Internal Data

CC: *PRIA

RE: ACTION COMPLETED - SEE RESPONSE

Action Subject: ELECTRICAL RETEST	Action #: 1103464
Customer Name : PITES	Status: COMP
Request Date : 11/08/94	Added: 11/08/94
13:22 Priority : NORMAL	Type: R/FA
	Org/LBE: FRECA
	ProdType: PC88
	Device: 77PSL3-1

Sender Request by : ELAINE S ROSE

Userid: A66877

TI REF # 86

HAVE BEEN LOST IN A WAREHOUSE SOMEWHERE !!!
DID NOT PRINT

PARAMETERS

Customer part number	C 21006064951/F2AC-9F924-AA
TI part number	C 77PSL3-1
Unit price	C 2.36
Mark (S.R.)	C NA
Date code/serial number	Q 4160A
Reason for return	Q ELECTRICAL RETEST; POSSIBLE WASHER/CONVERTER BINDING ISSUE {16 BOXES @ 238 HA}
Customer count pcs	Q 3808
TI count pcs	Q 3808
# defective	Q 0
Inspection findings	Q
Returned as received	N 0
Rework-return to cust	N 0
Rework-return to stock	N 0
Return to stock	N 0
Replace	N 0
Scrap	N 0
Hold for disposition	N 0
Customer location	C DALLAS, TX
Customer contact	C CHARLENE
Phone number	C 214-242-2116 EXT. 175
Customer rejection#	C
Sold to #	C 616128
Ship to #	C 616136
Bill to #	C 616128
P.O. #	C
TI order #	C 0
Date returned	C 10/27/1994

Return type (E/F/D/P)	Q P
Cust C/A required?(Y/N)	Q Y SEE CAR 94_18 DOC. DATED 6/21/94
Cust C/A date due	Q
Root cause	Q
Corrective action	Q
C/A complete date	Q
Defect code	Q
Quality return	Q 0
Unjustified return	Q 0
Service quality return	Q 0
Marketing return	Q 0
Document type	C A

***** END OF MESSAGE *****

Ross, Elaine

From: postmaster
To: sross
Subject: ACTION COMPLETED - SEE RESPONSE
Date: Friday, December 15, 1995 12:08PM

-MSG M#- 645234 FR=GAMY TO=GAMY SENT=12/15/95 12:07 PM
R#058 ST=C DIV=0050 CC=00149 BY=GAMY AT=12/15/95 12:07 PM
TO: ELAINE S ROSE GAMY << CUSTOMER ACTION REQUEST >>
FR: ELAINE S ROSE GAMY << C U S T O M E R # 1 >>
TI Internal Data
CC: *PRIA

RE: ACTION COMPLETED - SEE RESPONSE

Action Subject: CALIBRATION	Action #: 1267501
Customer Name : HILITE INDUSTRIES	Status: COMP
Request Date : 01/14/95	Added: 01/14/95
14.06 Priority : NORMAL	Type: R/FA
	Org/LBN: PRECA
	ProdType: PC88
	Device: 77P9L3-1

Sender Request by : ELAINE S ROSE

Userid: A66877

TI REF # 1-8

PARAMETERS

Customer part number	C F2AC-9F924-AA
TI part number	C 77P9L3-1
Unit price	C 2.36
Mark (S.R.)	C MA
Date code/serial number	Q 4294-4313B
Reason for return	Q FAILED CALIBRATION; 4PASSED;4FAILED; CUSTOMER WANTS ANALYSIS & SD REPORT !!!
Customer count pcs	Q 8
TI count pcs	Q 8
# defective	Q 1
Inspection findings	Q IPC HAD INT. CONTINUITY.7 WERE TROUBLE NOT FOUND
Returned as received	M 0
Rework-return to cust	M 0
Rework-return to stock	M 0
Return to stock	M 0
Replace	M 0
Scrap	M 0
Hold for disposition	M 0
Customer location	C DALLAS, TX
Customer contact	C GEORGE COMISKY
Phone number	C 214-242-2902
Customer rejection#	C R386
Sold to #	C 616128
Ship to #	C 616136
Bill to #	C 616128
P.O. #	C 62324
TI order #	C 2435778
Date returned	C 01/13/1995
Return type (R/F/D/P)	Q F
Cust C/A required?(Y/N)	Q Y
Cust C/A date due	Q 01/26/1995

Root cause	Q CONTACT CONTAMINATION (MINERAL OIL/CARDBOARD FIBERS)
Corrective action	Q CLEANLINESS IMPROVEMENT
C/A complete date	Q
Defect code	Q C18
Quality return	Q 1
Unjustified return	Q 7
Service quality return	Q 0
Marketing return	Q 0
Document type	C A

***** END OF MESSAGE *****

Pechonis, John

From: Rea, Ann Marie
Sent: Wednesday, February 14, 1996 5:23 AM
To: Pechonis, John
Cc: Sellers, Matt
Subject: RE: Highlights Week Ending 2/14/96

AM12 Improvements

The kapton spacer station is still waiting modification of one part. It is currently at Precision Products and is expected by the end of this week. Bill Lapante is planning on assembling and mechanically testing the station by next week. The station will not be installed, though, until the floor has built enough inventory to sustain them during the shutdown.

The crimp table unload conveyor has been designed to improve hexport handling. The assembly should be ready for installation next month.

Parts for the standardization of the three kapton feed stations are 70% complete but still must be hardened. This should eliminate the possibility of the kapton feed problems we were experiencing in December.

#12 Pressure Tester

Lou Camara has made several programming changes to improve the cap feed station. The changes have helped, but the bowl must still be moved above the conveyor table to allow the operator to clear jams. We have scheduled the mechanical improvements to the #12 cap feed station for the first week in March. The line will not have use of the tester from March 2 through March 7. This should improve access to the bowl and reduce the jamming that is occurring. The line is not currently running the bowl consistently. Most of the parts have been completed by the toolroom.

The material has been ordered for the new contact probes on the #12 tester. This will eliminate the false ZPLF readings we are experiencing on all devices. Tooling should be complete by March.

Hexport ID Station

The mechanical tooling for the hexport ID station is expected in-house within 2 weeks. The programmable controller will not be complete until the beginning of April. Once all validation testing has been completed, Jim Wood will be notifying strategic customers. After this has happened, we will be changing over to the new design regardless of whether the tooling is installed.

Q88000

Claire Balhazar and I have been helping Jim Wood to develop the documentation linkage program.

INVESTIGATION OF 77PS / 87PS SWITCHES BUILT WITH ANOMALOUS SPRING ARMS

GENERAL INFORMATION


Customer: Ford
 TI P/N: 77PS, 87PS
 TI Test Series Number: 497 - 15 - 24

OBJECTIVE

The objective of this study was to determine the risk associated with shipping devices containing anomalous spring arms. The devices are used in brake systems for cruise control de-activation and in power steering systems for high steering load idle-up activation.

DESCRIPTION OF PROBLEM

The spring anomaly is best described as a scoring or scraping, and/or material necking of the spring at the bend location.



ROOT CAUSE

The spring arm anomaly was created during the bending operation. It was caused by a loose tooling fixture. The problem was sporadic in nature. At times the tooling fixture was correctly aligned producing "good springs". At other times the tool was mis-aligned creating various levels of spring arm scoring, scraping, and necking.

DESCRIPTION OF TESTING

TYPE OF TEST	REMARKS
Production Impulse Testing	10 Hz rate // 0-1500 psig cycle Fluid: ATF
Rockertace Testing	Per Ford Spec ES-FZVC-9F924-AA 2 Hz rate // 0-1600 psig cycle Fluid: ATF, no electrical load
Determination of Spring Arm Stiffness	Group 1 - normal production springs with no cycles Group 2 - normal production springs with 400K cycles on impulse tester Group 3 - anomalous springs with 400K on endurance test Group 4 - anomalous springs with 400K on impulse tester

CUSTOMER: Ford	REPORT NUMBER: 77PS/87PS SWITCHES BUILT WITH ANOMALOUS SPRING ARMS	PAGE 1 OF 1
TESTING BY: Ted Cagle	TEXAS INSTRUMENTS INCORPORATED	DATE: 7/27/96
APPROVED BY: Edie Boudin	MANUALS & CONTROLS GROUP	DOC#: 15022
DATE: March 1, 1996	ATLANTIC, MASSACHUSETTS 01915	REVISION: 000

TABLE 1 SWITCH BUILD DESCRIPTION

QTY	DEVICE	ACT / Min. REL	TEST	SPRING CONDITION
10	77PSL3-1	150 / 20 (quiet)	Production Impulse	anomalous
10	77PSL3-1	150 / 20 (quiet)	Production Impulse	good
8	77PSL3-1	150 / 20 (quiet)	Endurance	anomalous
10	87PSL11-2	450 / 200 (snap)	Production Impulse	anomalous
10	87PSL11-2	450 / 200 (snap)	Production Impulse	good
8	87PSL11-2	450 / 200 (snap)	Endurance	anomalous
10	87PSL2-3	350 / 120 (snap)	Production Impulse	anomalous
10	87PSL2-3	350 / 120 (snap)	Production Impulse	good
8	87PSL2-3	350 / 120 (snap)	Endurance	anomalous
10	87PSL2-3	350 / 120 (snap)	Noise (control grp.)	good

- All switches were assembled on the production floor using standard build practices.
- Spring arm stiffness tests were completed using three piece samples from the above groups.

TEST PROCEDURE

1. All switches were subjected to an overpressure of 1300 psi during the sensor build on the AML.
2. All switches were subjected to a function test consisting of two cycles of 0-800 psi, followed by a calibration cycle.
3. All switches were backfilled with ATF and mounted on a manifold.
4. The switches were cycled on either the production impulse tester or endurance test setup in lifetest.
5. The switches were checked for proper function every 100K cycles, all switches were tested for a total of 400K cycles.

Results from above test are shown in Table 2

6. The switches from all groups were disassembled and visually inspected for excessive spring wear, spring fatigue, and crack propagation.
7. Force / deflection curves were taken on three samples of each test group.
8. The spring arms from each of the anomalous groups were studied to determine if they were representative of a worst case condition.

Results from above test are shown in Table 3

Initiated by: Paul	THIS DOCUMENT CONTAINS UNCLASSIFIED INFORMATION	Page 3 of 4
Reviewed by: Bob	THIS DOCUMENT IS UNCLASSIFIED	Switch 176/020
Approved by: Bob Smith	MANUAL REVIEWED	Rev. 10000
Date: March 1, 2004	ATLANTA, GEORGIA 30303	REVISIONS

TI-NHTSA 011978

TABLE 2 SUMMARY OF IMPULSE AND ENDURANCE TEST RESULTS

DEVICE	TEST	SPRING CONDITION	POST 400K FUNCTION TEST	REMARKS
77PSL3-1	Production Impulse	anomalous	100 % PASS	
77PSL3-1	Production Impulse	good	100 % PASS	
77PSL3-1	Endurance	anomalous	100 % PASS	
87PSL11-2	Production Impulse	anomalous	60 % PASS	1 of 10 had broken spring post 100K 3 of remaining 9 had broken spring post 400K
87PSL11-2	Production Impulse	good	100 % PASS	
87PSL11-2	Endurance	Anomalous	100 % PASS	
87PSL2-3	Production Impulse	anomalous	60 % PASS	1 of 10 had broken spring post 200K 1 of remaining 9 had broken spring post 300K 2 of remaining 8 had broken spring post 400K
87PSL2-3	Production Impulse	good	100 % PASS	
87PSL2-3	Endurance	anomalous	88 % PASS	1 of the 8 broke a spring between 155K - 280K

- Function test consisted of checking calibration and transfer time.

TABLE 3 SUMMARY OF SPRING ARM STIFFNESS TEST RESULTS

DEVICE	SPRING CONDITION	VISUAL INSPECTION	SPRING ARM STIFFNESS	VERIFICATION OF SPRING ARM ANOMALY
87PSL2-3	good	N/A	CONTROL GRP.	N/A
77PSL3-1	anomalous (impulse)	Normal wear	No reduction in stiffness	anomalies present
77PSL3-1	good (impulse)	Normal wear	No reduction in stiffness	No anomalies present
77PSL3-1	anomalous (endurance)	Normal wear	No reduction in stiffness	anomalies present
87PSL11-2	anomalous (impulse)	Normal wear	No reduction in stiffness	anomalies present
87PSL11-2	good (impulse)	Normal wear	No reduction in stiffness	No anomalies present
87PSL11-2	anomalous (endurance)	Normal wear	No reduction in stiffness	anomalies present
87PSL2-3	anomalous (impulse)	Normal wear	No reduction in stiffness	anomalies present
87PSL2-3	good (impulse)	Normal wear	No reduction in stiffness	No anomalies present
87PSL2-3	anomalous (endurance)	Normal wear	No reduction in stiffness	anomalies present

- Verification of the anomaly was done by over-bending the spring arm through 100° rotation until failure. Failure within two cycles verified the presence of an anomaly.

- Force - deflection plots are shown in Appendix A.

Character: PSL	THIS DOCUMENT CONTAINS UNCLASSIFIED INFORMATION	PAGE 3 OF 5
Source: DoD, DoC, DoS	THIS DOCUMENT IS UNCLASSIFIED	DATE: 10/1/99
Approved for: John Smith	MANUAL & CONTROL GROUP	DOC: 10000
DATE: 10/1/99	ATTENTION: 10/1/99	REVISION: 10/1/99

GENERAL STATISTICAL RISK ANALYSIS OF 87PS DEVICES

- 8 of 20 (40%) 87PS devices broke spring arms during production impulse testing (400K total cycles), the earliest failure was post 100K.
- 1 of 16 (6%) 87PS devices broke it's spring arm during endurance testing at about 200K.
- Based upon a Honda power steering trace (T.S. # 75-15-05), switch actuation will most often occur during parking lot situations characterized by no vehicle movement and near full lock turning.
- Assuming a 10 year vehicle life and that the vehicle is driven 365 days / year.
 - 400K cycles / 10 yr life = 110 cycles per day
 - 200K cycles / 10 yr life = 55 cycles per day
 - 100K cycles / 10 yr life = 27 cycles per day
- The two possible failure modes would be a continuous high idle condition caused by a broken spring arm, or a no idle-up condition caused by the broken spring arm bridging the gap between the terminals. The no idle-up condition may allow the vehicle to stall under high steering load conditions.

CONCLUSIONS

The results of this study show that there is no risk associated with using 77PS devices containing anomalous spring arms. The results also show that there is very little risk associated with using 87PS devices containing anomalous spring arms. The lack of a reduction in spring arm stiffness indicates that the spring is being cycled within it's elastic range. Consequently, the fatigue limit of the spring arm remains high enough to withstand the full life cycle of the switches.

77PS DEVICES

- The 77PS devices are used in brake systems for cruise control de-activation.
- The results show that the spring anomaly causes no difference in function between the control and test groups.
- The results also show that the spring anomaly causes no reduction in spring stiffness or switch life.


87PS DEVICES

- The 87PS devices are used in power steering systems for high steering load idle-up activation.
- The results show that in the vast majority of the devices the spring anomaly causes no difference in function between the control and test groups.
- The results also show that the spring anomaly causes no reduction in spring stiffness and that the switch life is not significantly compromised.

Customer Part	TESTING OF 77PS AND 87PS DEVICES ANOMALOUS SPRING ARMS	PAGE 4 OF 5
Customer P/N: 87-0000	TESTING INSTRUMENTS INCORPORATED	SWITCH 77PS / 87PS
Approved By: Edith Smith	MANUFACTURE & CONTROL GROUP	NO. 1: 100000
Date: March 1, 1994	ATTACHED DOCUMENTS: 87PS	EXAMINATION: 100000

APPENDIX A

CUSTOMER: Ford	MANUFACTURER: Ford Motor Company	PAGE 1 OF 1
PROJECT: 2000 Ford	MODEL: 2000 Ford	DATE: 1/1/00
APPROVED BY: John Smith	APPROVED BY: John Smith	DATE: 1/1/00
DATE: March 1, 2000	DATE: March 1, 2000	DATE: March 1, 2000



ANALYSIS OF SENSOR CUP'S HEIGHT EFFECT ON VACUUM DEPENDENT DISPLACEMENT

OBJECTIVE

This study investigates whether or not changing the sensor cup height will alleviate the problem of vacuum dependent displacement. In addition, this report will address the feasibility of implementation.

DESCRIPTION OF PROBLEM

At the customer site, a vacuum is pulled during their routine evacuation and fill of the brake cylinders. The pulling of the vacuum causes the Kapton diaphragm to "suck" and pull away from the converter/washer. The converter, washer, spacer, and disc are then free to displace in the same direction as the Kapton. In case of a high vacuum, the looseness of the components would cause the spring arm to unload and result in an open circuit condition. The device will return to normal operation after a light positive pressure is applied.

The corrective action was to decrease the cup step height, thereby allowing less movement of the components under high vacuum. Two sensor cup types with varying step heights are presently being used:

Part Number	Cup Step Height (in)
27713-1	.090-.092
27713-2	.086-.088

The -2 cup solved the problem of vacuum dependent displacement but resulted in disc preload. In addition, the devices exhibited lower actuation and wider σ 's on the actuation and sensor dimensions.

PREVIOUS EXPERIMENTATION

Engineering Test Report PS/93/72 studies vacuum dependent displacement as a function of cup step height. Cup step heights from 0.086 to 0.092 were created using shims between the washer and the T. The study showed that as step height increased, so did the vacuum displacement. It was determined that a cup step height of 0.087 to 0.089 would eliminate vacuum dependent continuity loss without causing disc preload.

A new tool was made by Valentine Tool & Stamping to manufacture the 27713-3 cup, with a cup step height of 0.087-0.089.

CUSTOMER: Ford	TEST: Vacuum Dependent Displacement	PAGE 1 of 3
TESTED BY: Paul Andrade	TEXAS INSTRUMENTS INCORPORATED MATERIALS & CONTROLS GROUP ATLHORO, MASSACHUSETTS 02703	DEVICE: 77PS
APPROVED BY: D.T. Ha		DOC.: PS/96/
DATE: March 11, 1996		FILE NAME: PS_96_

Note: The study described in PS/95/72 was performed using stack-ups from Ford Oakville returned devices.

TEST PROCEDURE & RESULTS

Test #1: Repeat Keith Rosiello's previous study on vacuum dependency (see Eng Test Report PS/95/72) using -2 sensor cups with Oakville stack-ups.

- A single 27713-2 cup with a step height of 0.0869" was used in the first phase of testing. Shims were made of .001" and .002" thickness to simulate step heights ranging from 0.0869 (no shim) to 0.0899. Sensor crimp was simulated using a lab test fixture.

Results:

The results summarized in the table below show that an effective cup step height of 0.0879" will eliminate vacuum dependent continuity loss without causing disc preload. A cup step height of 0.0889" exhibits too much vacuum displacement and could possibly lead to continuity loss.

P/N	Cup Step Height w/o Shim (in)	Total Shim Thickness (in)	Effective Cup Step Height (in)	Exp. Vacuum Displacement (in)
77PSL3-2	0.0869	0	0.0869	0.0006 (some preload)
77PSL3-2	0.0869	0.001	0.0879	0.0016
77PSL3-2	0.0869	0.002	0.0889	0.0031
77PSL3-2	0.0869	0.003	0.0899	0.0041

Note: Used -2 cup #1

Test #2: Using results from Test #1, a -2 cup with a measured cup step height of 0.087" + 0.001" shim was built on the production line (production crimp) into a sensor assembly using Ford Oakville stack-ups. This was then compared with a 77PSL3-2 sensor assembly in inventory. PD curves were generated twice for each case.

Results:


P/N	Cup Step Height w/o Shim (in)	Total Shim Thickness (in)	Effective Cup Step Height (in)	Exp. Vacuum Displacement (in)
77PSL3-2 Trial 1		N/A		0.001
77PSL3-2 Trial 2				0.001
77PSL3-2 Trial 1	0.087	0.001	0.088	0.028
77PSL3-2 Trial 2				0.028

CUSTOMER: Ford	TEST: Vacuum Dependent Displacement	PAGE 2 of 3
TESTED BY: Paul Anzola	TEKAS INSTRUMENTS INCORPORATED	DEVICE: 77PS
APPROVED BY: D.T.H.	MATERIALS & CONTROLS GROUP	DOC: PS/96/
DATE: March 11, 1996	ATTLEBORO, MASSACHUSETTS 01705	FILE NAME: PS_96_

TABLE 2 Correlation Between Cup Step Height and Vac. Dependent Disc.

P/N	STEP HEIGHT w/o SHIM	TOTAL SHIM THICKNESS	EFFECTIVE CUP STEP HEIGHT	EXP. VAC DISPL.
77PSL3-1#5	0.086	0	0.086	0 (Preloaded)
77PSL3-1#5	0.086	0.001	0.087	0.0001
77PSL3-1#5	0.086	0.002	0.088	0.0003
77PSL3-1#5	0.086	0.003	0.089	0.0010
77PSL3-1#5	0.086	0.004	0.090	0.0020
77PSL3-1#5	0.086	0.006	0.092	0.0040
77PSL4-1#4	0.086	0	0.086	0 (Preloaded)
77PSL4-1#4	0.086	0.001	0.087	0.0002
77PSL4-1#4	0.086	0.002	0.088	0.0010
77PSL4-1#4	0.086	0.003	0.089	0.0017
77PSL4-1#4	0.086	0.004	0.090	0.0032
77PSL4-1#4	0.086	0.005	0.091	0.0040
77PSL4-1#4	0.086	0.006	0.092	0.0052

- Preloading refers to the disc being initially deformed by forces created during the assembly process.



CONCLUSIONS

The results of this study show that a cup step height of 0.087 to 0.089 will eliminate vacuum dependent continuity loss without causing disc preload.

Customer Part	NOTE: THE DISC HEIGHT OF 0.086 IS THE MINIMUM CONTINUITY LOSS	PAGE 2 OF 3
Disc Step Height	SEE THE DISC HEIGHT OF 0.086	DISC: 77PS
Assembly Step Height	SEE THE DISC HEIGHT OF 0.086	DISC: 77PS
With Offset, 1.00	SEE THE DISC HEIGHT OF 0.086	SEE THE DISC HEIGHT OF 0.086

PS/95/72

THE ELIMINATION OF VACUUM DEPENDENT CONTINUITY LOSS ON 77PS CRUISE CONTROL SWITCHES

GENERAL INFORMATION

Customer: Ford
 TI PN: 77PS
 TI Test Report Number: PS/95/72
 TI Test Series Number: 478-15-35

OBJECTIVE

The objective of this study was to determine the cup step height which eliminates vacuum dependent continuity loss without causing disc preload.

SENSOR BUILD DESCRIPTION

QTY	T.I. PART NUMBER	CUP PART NUMBER	CUP STEP HEIGHT RANGE
8	77PSL3-1	27713-01	.090 - .092
15	77PSL3-2	27713-01	.090 - .092
8	77PSL4-1	27713-02	.086 - .088
8	77PSL5-1	27713-02	.086 - .088

- All sensors were built on the AMI using standard production procedures.

TEST PROCEDURE

Determine Vacuum Dependent Displacement in Production Sensors.

- All sensors were probed with a torxington pin to determine diaphragm position.
- All sensors were function tested using two cycles of 0-600 psi.
- All sensors were exposed to an increasing vacuum level to 2 mbar maximum and held for 60 seconds. Simultaneously, the vacuum dependent displacement was monitored and plotted, as shown in Appendix A.
- Immediately after the vacuum cycle described in step 3, a positive pressure cycle of 0 - 300 psi was applied to the sensor and plotted as shown in Appendix A.
- Representative sensors from each product group were disassembled and their components measured using a dial indicator.

Customer: Ford	REF: THE ELIMINATION OF VACUUM DEPENDENT CONTINUITY LOSS ON THE CRUISE CONTROL SWITCHES	PAGE 1 OF 3
Workshop Job Order	TEXAS INSTRUMENTS INCORPORATED	REVISED 7/78
Approved by: Edm. Rios	MANUFACTURE & CONTROLS GROUP	DOC.1 10/9/95
DATE: October 5, 1995	ATLANTA, GEORGIA 30308	WORKSHEET

TI-NHTSA 011986

Determine Correlation Between Cup Step Height and Vacuum Dependent Displacement.

6. A senior cup, P/N 27713-02, with the minimum step height of .086" was located and labeled.
7. Sensors were assembled in a test fixture using the cup identified in step 6 and the components measured in step 5.
8. The test fixture clamping force was correlated to the AMI crimping station as shown in Appendix B.
9. The repeatability of the test method, specifically the clamping together of components, was verified, as shown in Appendix B.
10. Several shims of different thickness were produced to enable cup step height variation.
11. Steps 1 through 4 were repeated using sensors made from various thickness shims to create sequential cup step heights. All other sensor components and parameters remained constant. Results are shown in Appendix C.

RESULTS

TABLE 1 Component Measurements

P/N	CUP BUMP HEIGHT	CUP BUMP TO STEP HEIGHT	CONV / SPACER / DISC HEIGHT	THEORETICAL VAC DISPL	EXP. VAC DISPL
77PSL3-1 #3	0.0145	0.090	0.0850	0.0050	0.0025
77PSL3-1 #5	0.0135	0.092	0.0850	0.0070	0.0040
77PSL3-2 #3	0.0140	0.090	0.0850	0.0030	0.0015
77PSL3-2 #8	0.0145	0.090	0.0850	0.0030	0.0020
77PSL3-2 #70	0.0145	0.092	0.0850	0.0070	0.0050
77PSL3-2 #71	0.0145	0.092	0.0850	0.0070	0.0055
77PSL3-2 #72	0.0145	0.092	0.0850	0.0070	0.0050
77PSL3-2 #73	0.0145	0.092	0.0850	0.0070	0.0050
77PSL3-2 #74	0.0145	0.092	0.0850	0.0070	0.0050
77PSL3-2 #75	0.0145	0.092	0.0850	0.0070	0.0040
77PSL3-2 #76	0.0145	0.092	0.0850	0.0065	0.0035
77PSL4-1 #4	0.0135	0.087	0.0850	0.0020	0.0000
77PSL4-1 #6	0.0140	0.089	0.0850	0.0040	0.0020
77PSL6-1 #1	0.0135	0.087	0.0850	0.0020	0.0000
77PSL6-1 #5	0.0135	0.087	0.0850	0.0020	0.0000

- Theoretical vacuum displacement = Effective cup step height - (Effective converter height + Spacer thickness + Effective disc height).
- Experimental vacuum displacements were obtained from the plots provided in Appendix A.

Customer: Ford	Work: THE RELATIONSHIP OF VACUUM DEPENDENT DISPLACEMENT	Page: 3 of 3
Customer: Am. Can.	Customer: Am. Can.	Rev: 7716
Approved: Robt. Smith	THESE INSTRUMENTS WERE FOR THE	Rev: 1987/72
Date: October 5, 1988	MODEL 6 & CONTROL GROUP	REVISION: 1988
	ATLANTA, GEORGIA 30303	

ANALYSIS OF SENSOR CUP'S HEIGHT EFFECT ON VACUUM DEPENDENT DISPLACEMENT

OBJECTIVE

This study investigates whether or not changing the sensor cup height will alleviate the problem of vacuum dependent displacement. In addition, this report will address the feasibility of implementation.

DESCRIPTION OF PROBLEM

At the customer site, a vacuum is pulled during their routine evacuation and fill of the brake cylinders. The pulling of the vacuum causes the Kapton diaphragm to "snap" and pull away from the converter/washer. The converter, washer, spacer, and disc are then free to displace in the same direction as the Kapton. In cases of a high vacuum, the looseness of the components would cause the spring arm to unload and result in an open circuit condition. The device would return to normal operation after a light positive pressure is applied.

The initial corrective action was to decrease the cup step height, thereby allowing less movement of the components under high vacuum. Two sensor cup types with varying step heights are presently being used:

Part Number	Cup Step Height (in)
27713-1	.090-.092
27713-2	.086-.088

The -2 cup solved the problem of vacuum dependent displacement but resulted in disc preload. In addition, the devices exhibited lower actuation and wider's on the actuation and sensor dimensions.

PREVIOUS EXPERIMENTATION

Engineering Test Report PS/93/72 studies vacuum dependent displacement as a function of cup step height. Cup step heights from 0.086 to 0.092 were created using shims between the washer and the ???. The study showed that as step height increased, so did the vacuum displacement. It was determined that a cup step height of 0.087 to 0.089 would eliminate vacuum dependent continuity loss without causing disc preload.

A new tool was made by Valentine Tool & Stamping to manufacture the 27713-3 cup, with a cup step height of 0.087-0.089.

CUSTOMER: Ford	TEST: Vacuum Dependent Displacement	PAGE 1 of 4
TESTED BY: Paul Arruda	TEXAS INSTRUMENTS INCORPORATED MATERIALS & CONTROLS GROUP ATLANTIC, MASSACHUSETTS 02703	DEVICE: 77PS
APPROVED BY: D.T. Ha		DOC.: PS/94
DATE: September 11, 1996		FILE NAME: PS_96_

Note: The study described in PS/95/72 was performed using stack-ups from Ford Oakville returned devices.

TEST PROCEDURE & RESULTS

Test #1:

Repeat Keith Rosiello's previous study on vacuum dependency (see Bag Test Report PS/95/72) using -2 sensor cups with Oakville stack-ups.

A single 27713-2 cup with a step height of 0.0869" was used in the first phase of testing. Shims were made of 0.001" and 0.002" thickness to simulate step heights ranging from 0.0869" (no shim) to 0.0899". Sensor crimp was simulated using a lab test fixture.

Results:

The results summarized in the table below show that an effective cup step height of 0.0879" will eliminate vacuum dependent continuity loss without causing disc preload. 0.088" is the optimal nominal cup step height. A cup step height of 0.0889" exhibits more vacuum displacement, is closer to the pinning window, and may lead to continuity loss.

P/N	Cup Step Height w/o Shim (in)	Total Shim Thickness (in)	Effective Cup Step Height (in)	Exp. Vacuum Displacement (in)
77PSL3-2	0.0869	0	0.0869	0.0006 (some preload)
77PSL3-2	0.0869	0.001	0.0879	0.0016
77PSL3-2	0.0869	0.002	0.0889	0.0031
77PSL3-2	0.0869	0.003	0.0899	0.0041

Note: Used -2 cup #1

Test #2:

Using results from Test #1, -3 cups with a measured cup step height of 0.0872 were built on the production line (production crimp) into a sensor assembly using Ford Oakville stack-ups. Since the -3 cup was measured on the low side of dimensional spec, a 0.001" shim was used in one of the devices. PD curves were generated twice for each case to ensure repeatability.

Results:

The results from this test corroborate results from Test #1. A cup step height of 0.0872 results in very little vacuum dependent displacement, but causes disc preload. A cup step height of 0.0882" exhibits vacuum dependent displacement within the allowable limits such that the disc is not preloaded and continuity loss is not possible.

P/N	Cup Step Height w/o Shim (in)	Total Shim Thickness (in)	Effective Cup Step Height (in)	Exp. Vacuum Displacement (in)
77PSL3-2 Trial 1	0.0872	N/A	0.0872	0.0005 (Preload)
77PSL3-2 Trial 2				0.0005 (Preload)

CUSTOMER: Ford	TYPE: Vacuum Dependent Displacement	PAGE 2 of 4
TESTED BY: Paul Arruda	TEXAS INSTRUMENTS INCORPORATED	DEVICE: 77PS
APPROVED BY: D. T. Ha	MATERIALS & CONTROLS GROUP	DOC.: PS/96
DATE: September 11, 1996	ATLANTIC, MASSACHUSETTS 02708	FILE NAME: PS_96

77PSL3-2	0.0872	0.001	0.00882	
Trial 1				0.022
Trial 2				0.022

Test #3:

Up to this point all testing of parts were performed using Ford Oakville stack-ups. Current production parts from August 96 were obtained and built into sensor assemblies. Six P/N 27713-3 cups were built into sensor assemblies on the production line/crimper.

Results:

All six sensor assemblies exhibited no vacuum dependent displacement, but did exhibit extensive preload. These results varied greatly from those in Test #2. It appears that component stack-up can cause great variation in results.

DIMENSIONAL STACK-UP ANALYSIS

Theoretical:

All components located in the sensor cup were examined to look at dimensional stack-up. Results showed that the total stack-up of components could vary as much as 0.0068".

Component	Dimension (in)
Diaphragm Seal (3 layers)	0.015 ± 0.0015
Washer	0.099 ± 0.002
Converter	0.165 ± 0.003
Spacer	0.002 ± 0.0003
Disc	Info not available on detail drawing
Total:	0.281 ± 0.0068

Looking at just those components (converter, spacer, disc) that sit in the cup step area, the dimensional variation would be 0.167 ± 0.0033".

Experimental:

Stack-up differences were measured using a micrometer to compare the stack-ups between the Ford Oakville stack-ups and the current production lot. Results are summarized in the table below.

	Converter/Spacer /Disc Stackup	Washer Thickness	Washer Concavity
Ford Oakville Samples			
#1	0.09100	0.10000	0.0009

CUSTOMER: Ford	TEST: Vacuum Dependent Displacement	PAGE 3 of 4
TESTED BY: Paul Arruda	TEXAS INSTRUMENTS INCORPORATED	SERVICE: 77PS
APPROVED BY: D.T. Ha	MATERIALS & CONTROLS GROUP	DOC.: PS/96/
DATE: September 11, 1996	ATTLEBORO, MASSACHUSETTS 01903	FILE NAME: PL_01

#2	0.08040	0.10020	0.0011
#3	0.08120	0.10010	0.0013
#4	0.08085	0.09960	0.0006
#5	0.08120	0.09995	0.0012
AVERAGE:	0.08093	0.09997	0.0011
Current Production Samples			
#1	0.08440	0.10175	0.0014
#2	0.08360	0.10080	0.0006
#3	0.08225	0.10115	0.0008
#4	0.08210	0.10065	0.0013
#5	0.08250	0.10010	0.0011
AVERAGE	0.08297	0.10009	0.0012
Δ in Averages:	0.00294	0.00092	

+ 0.00296



CUSTOMER: Ford	TEST: Vacuum Dependent Displacement	PAGE 4 of 4
TESTED BY: Paul Aranda	TEXAS INSTRUMENTS INCORPORATED MATERIALS & CONTROLS GROUP ATTLEBORO, MASSACHUSETTS 01903	DEVICE: 77PS
APPROVED BY: D. T. Ha		DOC.: PS/96/
DATE: September 11, 1996		FILE NAME: PS_96_

TI-NHTSA 011991

5

4

3

2

1


STRIP
WIDTHFOR THE
CISCORECEIVED TO THE
FNS. 11.11.1966

3-50 AUG 15 1966

RECEIVED FROM THE
FNS. 11.11.1966RECEIVED FROM THE
FNS. 11.11.1966

NOTES:

1. STRIP TO BE INSPECTED FOR TEFLON COATING, THICKNESS, DEFORMITIES, BUBBLES, AND LAMINATE SEPARATION.
2. EACH KAPTON STRIP ROLL MUST BE LABELED WITH T.I. PART NO. ON INSIDE OF CORE.
3. NO MORE THAN 2 SPLICES PER COIL PERMITTED. SPLICES TO BE CLEARLY MARKED WITH YELLOW TYLAR.
4. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.
5. ROLLS SLITTED FROM END OF MASTER COIL NOT ACCEPTABLE.
6. BECKLING OF THE CORE ALLOWED UP TO 1/4" MEASURED RADIALLY AWAY FROM THE CORE.
7. BENT RIP OR JAMMED EDGES ON MATERIAL NOT ALLOWED.
8. ROLLS ARE TO BE SHIPPED WITH PROTECTIVE INSERT CORES IN THE PACKING BOX.
9. ROLLS TO BE SHIPPED IN CLOSED PLASTIC BAGS.
10. END OF REEL TO HAVE A 6" OPAGUE TAPE END-OF-REEL MARKER.
11. MATERIAL SUPPLIED FOR THIS PRINT MUST MEET T.I. MATERIAL SPECIFICATION #72225.




27225-5	DUPONT 300NM PERFLUOROKETON	3 x 4 MILS	0.0	5	0.0	.252-.284	6 x 6 1/2	PLASTIC (WHITE)
27225-4	DUPONT 300NM PERFLUOROKETON	3 x 3 MILS	0.0	3	0.0	.734-.766	6 x 6 1/2	PLASTIC (WHITE)
27225-3	DUPONT 300 PERFLUOROKETON	3 x 4 MILS	0.3	2	0.3	.252-.284	3 x 6 1/2	PLASTIC (WHITE)
27225-2 (NOTE 10)	DUPONT 300 PERFLUOROKETON	3 x 4 MILS	1	3	1	.252-.284	6 x 6 1/2	PLASTIC (WHITE)
27225-1	DUPONT 300 PERFLUOROKETON	3 x 4 MILS	1	3	1	.734-.766	6 x 6 1/2	PLASTIC (WHITE)
PART NO.	MATERIAL (SEE NOTE 11)	THICKNESS(MILS)	TEFLON (A) KAPTON (B) TEFLON (C)	STRIP WIDTH (IN.)	PAD CUT UP (I.D.) (O.D.) (IN.)	CORE MATERIAL		

THIS ONE. SUPERSEDES 27225 REV. "Y" DATED 5-19-55

DESIGNED BY E. C. VERRAS		DATE 8-5-64	CHECKED BY J. H. GALE		DATE 8-5-64	APPROVED BY J. H. GALE		DATE 8-5-64	SIGNATURES ON FILE. REFER TO ELECTRONIC CHANGE NOTICE.		
TITLE KAPTON STRIP SPECIFICATION		SIZE B		CAGE CODE NO. 82647		PART NO. 27225		Q1= P37			

TI-NHTSA 011892



NOTES:

1. PART MUST BE FLAT TO WITHIN .006 T.I.R..
2. DIAMETERS MARKED WITH * MUST BE CONCENTRIC TO WITHIN .004 T.I.R..
3. PARTS TO BE SHIPPED, ISSUED, AND STORED WITH APPLIED RUST PREVENTIVE BRINE PLATING. AFTER PLATING, PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.
4. NO TOOL MARKS ALLOWED IN THE SHIPPED AREA ON REVELED SIDE OF WASHER.
5. THE PARTS THICKNESS IS MEASURED AFTER A .008-.010 THICK SKIN IS REMOVED.
6. THIS PART IS LOT CONTROLLED. ANY PROCESS CHANGE, NEW SETUP, PUNCH CHANGE, MAJOR TOOL WORK OR MATERIAL LOT CHANGE WILL SIGNIFY START OF A NEW LOT. NO MINIMUM LOT SIZE. EACH BOX WILL HAVE A LOT NUMBER. EACH LOT WILL HAVE IT'S OWN PACKING SLIP WITH LOT IDENTIFICATION.
7. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.
8. STAMP IDENTIFICATION CODE AS REQUIRED TO IDENTIFY SUPPLIER TOOL. CODE SHALL BE CLEARLY VISIBLE AFTER PLATING. NO MARK OR STAMP MARKS PERMITTED. (-S ONLY)
9. DIM. "A" TO BE MEASURED WITH STANDARD WIRENIP GAUGE.
10. IDENTIFICATION MARKS ALLOWED BETWEEN .410-.470.
11. THESE SURFACES MUST BE SMOOTH AND FREE OF ANY PLATING ASPERITIES OR INCLUSIONS. (I.E. NO PROVED EFFECTS OR PARTICULATE CONTAMINATION IN THE PLATING.)

THIS Dwg. SUPERSEDES 27639 REV. "D" DATED 3-80-80

REVISIONS				
REV	DATE	DESCRIPTION	DATE	APPROVED
1	11-8-80	SEE NOTE 4 WAS "SEE NOTE 8"		
2		SEE NOTE 8 WAS "SEE NOTE 9"		
3		SEE NOTE 10 WAS "SEE NOTE 11"		
4		SEE NOTE 11 WAS "SEE NOTE 12"		
OF 180038 C.F.				

FOR THE U.S. GOVT
CRS. 1000-100000
PARTS MADE TO THE DRAWING CONFORM TO
ENG. STD. 100000 REV. E
Date AUG 15 1986
EXAMINED AND FOUND TO BE IN ACCORDANCE WITH
SPECIFICATIONS AND DRAWINGS
DATE 10-15-86 BY J. J. JONES
QUALITY CONTROL

27639-1	1000 CRS	ZINC PLATE .0002 - .0008 THK	HEAT TREAT TO ROOMELL 68-90	.007 - .001
PART NO	MATERIAL	FINISH	HEAT TREAT	"A" DIM.
SPECIAL REQUIREMENTS SPECIFIED TOLERANCES AND FINISHES TOLERANCES AND FINISHES TOLERANCES AND FINISHES				
DATE 10-15-86 BY J. J. JONES FOR THE U.S. GOVT		TEXAS INSTRUMENTS ATTENTION: QUALITY CONTROL 27639-1		
DATE 10-15-86 BY J. J. JONES FOR THE U.S. GOVT		WASHER		
DATE 10-15-86 BY J. J. JONES FOR THE U.S. GOVT		CODE 82647 27639		

TI-NHTBA 011993

74224



KAPTON TAPE

REV.
F

74224

NOTES:

1. ROLLS SLITTED FROM ENDS OF MASTER COIL NOT ACCEPTABLE.
2. BUCKLING OF THE CORE ALLOWED UP TO 1/4" MEASURED RADIALLY AWAY FROM THE CORE.
3. DENTS, RIPS, OR JAGGED EDGES ON MATERIAL NOT ALLOWED.
4. ROLLS ARE TO BE SHIPPED WITH PROTECTIVE INSERT CORES IN THE PACKING BOX.



74224-1	DUPONTS, KAPTON 200H	.0017/.0023
PART NUMBER	MATERIAL	THICKNESS

THIS DWG. SUPERSEDES 74224 REV. "E" DATED 10-14-65

REV.

BY TOM DALL 10-14-65

CH.

ENG. H. H. H. 10-16-90

MAKEPAGE

TEXAS INSTRUMENTS
ATTLEBORO, MASSACHUSETTS 01735CENTRAL PRODUCTS
DIVISIONQWS
SIZE
A

FIG. NO.

74224

TI-NHTSA 011994

Wagner, Chris

From: KIL, Elizabeth(SMTP:ekil@steelh.mo.tl.com)
Sent: Friday, September 13, 1996 7:33 AM
To: Wagner, Chris
Subject: TSL # 140396, Examine etched Kapton

Objective:

Determine what has attacked the Kapton in a APT during cyclic salt spray testing.

Results:

FT-IR spectroscopy confirmed that the undamaged edge of the Kapton seal is a polyimide material. The top match from the spectral library was with a reference sample of Kapton with a match factor of 89.8%.

The spectrum of the blackened Kapton gives a very trace. The top match is with "polyamide-imide" at 70.6%. This is quite different than the polyimide alone. There is also some evidence of hydrolysis, as you suspected. I mathematically subtracted the water peaks from the spectrum, but came up with the same match. It is possible that this is a degradation product of the polyimide.

I attempted to scrape the surface on the blackened area to isolate the attacking compound, but there were no strong matches from the library. The top match is shown as "Nest (Nujol)" at 61%. This is another name for mineral oil. You will see in the spectral printout that it is not a good match. The surface of the degraded Kapton is probably a mixture of materials making identification of the individual components difficult.

This is why we aren't getting any strong matches with any one compound.

Al's message mentioned a high level of iron and chloride, so I scanned a sample of iron chloride for comparison. It does not match any of the spectra from the Kapton sample.

I will forward the spectral data by internal mail. Please call if you have any questions.

Regards,

Beth x3069



**TEXAS
INSTRUMENTS**

September 24, 1996

FACSIMILE TRANSMITTAL

TO: **Name:** **Ed McKenzie**

 Location: **DuPont Circleville**

 Mail Station: **N/A**

 Phone Number: **(614) 474-0730**

 FAX Number: **(614) 474-0680**

FROM: **Chris Wagner**

 TEXAS INSTRUMENTS MS 12-29

 Phone Number: **(508) 236-3170**

 FAX Number: **(508) 236-3586**

Total number of pages (including header page): 9

COMMENTS:

Ed:

Attached are the FTIR scans performed here at TI. We did several scans, in two different runs. The sample descriptions are below.

The first battery of scans were run on the switch as TI Attleboro received it. (Switch # 22-2 was received.)

Undamaged edge of Kapton as a control.
Blackened edge of Kapton.
Blackened debris scrapped from the Kapton

TI-NHTSA 011986

We then removed the disc from the disc seat and continued the analysis. We analyzed

Debris which fell from the switch when the disc was removed.
Debris under the disc in the assembly.


Please review the scans and provide your opinion. If you would like the data sent electronically, please let me know. Thanks for your help in this matter.

Best Regards,



Chris D. Wagner
Mechanical Design
Design Engineering Department

TI-NHTSA 011997



OMNIC Search


Spectrum: TSL # 140396, Undamaged edge of Kapton

Thu Sep 12 10:00:48 1996

Region: 3993.83 649.98

Search type: Correlation

Comment:



Index	Match	Compound name	Library
14	89.88	Kapton	TSL
39	79.07	Kapton 100FN088	TSL
1076	76.77	Polyimide IV	Hansen Polymer and Additives
274	47.67	Poly(trimesitimide imide), pyrol.	Hansen Polymer and Additives
904	46.42	Poly(phosphazene diphenyl ether)	Hansen Polymer and Additives
1241	45.26	4,4'-bis(phenylthio)benzophenone, Bisphenol A	Hansen Polymer and Additives
471	46.12	Epoxy resin ester, 40% bisphenol A	Hansen Polymer and Additives
1781	45.02	4,4'-bis(phenylthio)benzophenone	Hansen Polymer and Additives
1088	44.98	Polyimide	Hansen Polymer and Additives
748	43.93	Poly(4-hydroxyphenyl)	Hansen Polymer and Additives

OMNIC Search


Spectrum: *TSL # 140396, Blackened edge of Kapton

Thu Sep 12 09:42:35 1996

Region: 3995.83 649.98

Search type: Correlation

Comment:



Index	Match	Compound name	Library
919	79.39	Polyamide-imide, aromatic	Hansen Polymer and Additives
901	61.70	Poly(1,4-phenylenedicyclopentasilane)	Hansen Polymer and Additives
3480	55.70	4-Fluorobenzylamine, 97+%	Alkalis Condensed Phase
3183	55.40	4-Aminophenyl ether, 99+%	Alkalis Condensed Phase
3823	54.39	4-Fluorophenyl isothiocyanate, 98%	Alkalis Condensed Phase
920	53.64	Polyamide-imide, aromatic	Hansen Polymer and Additives
720	53.35	Poly(4-fluorobenzene)	Hansen Polymer and Additives
342	53.30	Poly(trimellitic anhydride)	Hansen Polymer and Additives
1048	52.26	Poly(5-oxobenzoyl)isophthalanide	Hansen Polymer and Additives
344	52.18	Poly(trimellitic anhydride)	Hansen Polymer and Additives

OMNIC Search

Spectrum: *Subtraction Result:**TSL # 140396, Blackened edge of Kapton


Thu Sep 12 10:07:05 1996

Region: 3995.85 649.98

Search type: Correlation

Comment:

(water subtracted)



Index	Match	Compound name
939	68.19	Polyamide-imide, aromatic
901	51.30	Poly(1,4-phenyleneoxydiphenylsilane)
1097	52.83	Flactol H D/S powder
201	50.76	Flactol H
344	50.22	Poly(triacetamide imide)
5751	49.43	4-Aminobiphenyl acid, sodium salt .H2O,
342	49.33	Poly(triacetamide imide)
3322	49.28	2-Chloro-1,4-phenyleneoxydiphenylsilane, 9
920	49.26	Polyamide-imide, aromatic
3823	48.70	4-Fluorophenyl isothiocyanate, 98%

Library
Hemmel Polymer and Additives
Hemmel Polymer and Additives
Hemmel Polymer and Additives
Rubber Compounding Materials
Hemmel Polymer and Additives
Aldrich Condensed Phase
Hemmel Polymer and Additives
Aldrich Condensed Phase
Hemmel Polymer and Additives
Aldrich Condensed Phase

TI-NHTSA 012001

OMNIC Search


Spectrometer: *TSL #A 140396, Scraped from the surface of the blackened Kapton

The Sep 12 09:50:50 1996

Region: 3995.85 649.98

Search type: Correlation


Comment:



Index	Match	Compound name
1	61.41	NaCl (NaCl)
9335	61.07	Sodium nitrate, 99.999%
75	60.89	Bar soap
788	59.48	Carboxylic acid amine salt
330	59.00	Poly(styrene-co-propylene-diene)
328	58.17	Poly(styrene-co-propylene-diene)
491	57.58	Poly(styrene-co-methyl-1-pentene), 77% E
337	57.48	Poly(styrene-co-propylene-diene-co-butadiene)
9486	57.46	Magnesium(II) acetate 4H2O, 99.99%
329	56.97	Poly(styrene-co-propylene-diene-co-butadiene)

Library
Commercial Materials Polystyrene Additives
Aldrich Condensed Phase
TSL
Hummel Polymer and Additives
Hummel Polymer and Additives
Hummel Polymer and Additives
Hummel Polymer and Additives
Hummel Polymer and Additives
Aldrich Condensed Phase
Hummel Polymer and Additives

TI-NHTSA 012002



OMNIC Search


Spectrum: *TSL # 141784, Debris from 142 PS after disc removal

Sat Sep 14 16:12:53 1996

Region: 3995.85 649.98

Search type: Correlation

Comment:



Index	Match	Compound name	Library
1898	72.11	1-Decanol	Hussel Polymer and Additives
854	71.43	1-Tetradecanol, 97%	Aldrich Condensed Phase
92	71.13	Weston TLTP	Rubber Compounding Materials
609	71.07	Poly(2-decyne)	Hussel Polymer and Additives
343	70.95	Neopack Antioxidant 451	Rubber Compounding Materials
9286	70.92	Tungstic acid	Aldrich Condensed Phase
1522	70.53	Decylamine	Hussel Polymer and Additives
1111	70.49	Poly(1-octene)	Hussel Polymer and Additives
1329	69.92	2-Undecanol	Hussel Polymer and Additives
1931	69.45	1-Ethynoctadecane	Hussel Polymer and Additives

Kill, Elizabeth

From: Kill, Elizabeth
To: Wagner, Chris CDW3
Cc: Su, Rose RSU; Hopkins, Al
Subject: TSL # 141784, Debris from 142 PS base
Date: Tuesday, September 17, 1996 4:24PM

Objective:

Identify the debris that fell from the device as the disc was removed.

Results:

FT-IR spectroscopy did not produce any strong matches for this material. It's spectrum is close to that of the blackened Kapton seal examined under TSL # 140390.

I reviewed the series of photos and SEM-EDAX spectrums from the base. I did not see strong evidence of organic contamination present there. I don't see any benefit in taking any additional FT-IR scans. But I will, if you want them. Just let me know.

We discussed sending the FT-IR spectra of this material to DuPont for analysis. Have you had any feedback from them on the format they would prefer? Printouts or diskette?

Regards,

Beth x3069

Kill, Elizabeth

From: Kill, Elizabeth
To: Wagner, Chris CDWS
Subject: TSL # 140396, Examine etched Kapton
Date: Friday, September 13, 1996 10:33AM

Objective:

Determine what has attacked the Kapton in a APT during cyclic salt spray testing.

Results:

FT-IR spectroscopy confirmed that the undamaged edge of the Kapton seal is a polyimide material. The top match from the spectral library was with a reference sample of Kapton with a match factor of 89.8%.

The spectrum of the blackened Kapton gives a very trace. The top match is with "polyamide-imide" at 70.8%. This is quite different than the polyimide alone. There is also some evidence of hydrolysis, as you suspected. I mathematically subtracted the water peaks from the spectrum, but came up with the same match. It is possible that this is a degradation product of the polyimide.

I attempted to scrape the surface on the blackened area to isolate the attacking compound, but there were no strong matches from the library. The top match is shown as "Nest (Nujol)" at 61%. This is another name for mineral oil. You will see in the spectral printout that it is not a good match. The surface of the degraded Kapton is probably a mixture of materials making identification of the individual components difficult. This is why we aren't getting any strong matches with any one compound.

Al's message mentioned a high level of iron and chloride, so I scanned a sample of iron chloride for comparison. It does not match any of the spectra from the Kapton sample.

I will forward the spectral data by internal mail. Please call if you have any questions.

Regards,

Beth x5069

JAL SERVICE LABS

LOG NO.

7406

TEST NO.

140396

REPORT OF RESULTS:

DATE RECEIVED

DATE OUT

9-13-96 7406

TECHNOLOG	EC		
HOURS WORKED			
PROCEDURE USED	TSL-C-060		
	FTIR#2	96-7406-519	

FCC I.D.

MC-325

TM-431

CLKE-122

FACIL-514

PC-127

WIRE-432

OAN-854

FACIL-521

VER9-168

EPD-821

AD DEV-208

FACIL-531

AFCC-483

PEP-822

EMCD-877

STAFF-855

MD-430

CSD-835

TI-NHTSA 012007

DISTRIBUTION: White and Yellow - Lab - Pink - Recovery

10/12/96 10:12 AM
K 12/12/96

Memo

To: Chris Wagner
Texas Instruments
From: Ed McKenzie
DuPont

Date: September 19, 1996
Re: 3004N Kapton®

Chris: attached please find results of the analysis of sample diaphragms sent to Toray-DuPont Corp. By TI-Japan.

Beckley while unable to identify a possible material, TDC felt that evidence of chemical attack was present, especially since another plastic part (PBT) in the construction also showed evidence of attack.

Please review and lets discuss when you get the chance. I will be out of the office tomorrow, Friday 9/20, but back in all next week.

Regards,





CIRCLEVILLE PLANT

P.O. Box 89
Circleville, OH 43113

HPF - SP Resin

Date 9-19-96

FACSIMILE TRANSMISSION COVER SHEET

ADDRESSEE(S):

NAME	COMPANY/BUSINESS/GROUP	FAX NUMBER
<u>CHRIS WAGNER</u>	<u>TEXAS INSTR. MS 12-29</u>	

SENDER:

BUSINESS SECTOR

LOCATION

ED MCKENZIEDUPONTCIRCLEVILLE OHTotal Number of Pages (including Cover Sheet) 3

DuPont, Circleville HPF - SP Resin Fax No - 614-474-0680, Verification No. 614-474-0443

SPECIAL INSTRUCTIONS/INFORMATION TO RECIPIENT:

*** CONFIDENTIALITY NOTE ***

The documents accompanying this teletype transmission contain information from DuPont which is confidential and/or legally privileged. The information is intended only for the use of the individual or entity named on this transmission sheet. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or the taking of any action in reliance on the contents of the teletype information is strictly prohibited, and that the documents should be returned to DuPont immediately. In this regard, if you have received this teletype in error, please notify us by telephone (614-474-0443) immediately so that we can arrange for the return of the original documents to us at no cost to you.

cshs,113

TI-NHTSA 012009

Charting a Course for Excellence

2-000 (04/27/91) REV. 4/91

HPF SP

6144740680

09/19/96 16:15 [N]:03/03 NO:163

From: YOKOYAH --YOVX00
To: MCKENZEC--ISDCVMS

Date and time 09/17/96 06:37:50

From: YOKOYAH --YOVX00 TKKVKP::A1::YOKOYAH
Subj: TI Claim

From: NAME: Hirokazu Yokoyama
FUNC: TOKAI KAPTON
TEL: 81-52-603-5181

<YOKOYAH AT A1 AT TKKVKP>

To: See Below
CC: See Below

Ed, the following is my report to TI-Japan. Please let me know your comment and recent your communication with TI in the U.S.. I think we did everything in TDC site. If the discussion advances to the process condition, this is your turn. I can support the communication but you should be involved more with TI-Japan.

Our analysis revealed that Kapton* was hydrolysed by a strong base even though no suspect material was found in the assembly. FT-IR of Kapton* in the diaphragm showed carboxylic acid group with a lot of volume. And a white powder in the connector was identified as a terephthalic acid salt which might be a degradation of PBT. The connector was made with PBT and it is very stable toward any solvents but alkali and boiled water. This is also the reason why a strong base was existed at the assembly. Not only Kapton* but also PBT was hydrolysed. Other investigation for the claim is to check the pH. But everything is normal. 5%NaCl solution: pH6.0-6.7 NaCl powder was dissolved with distilled water as 5% solution: pH5.8-6.7 ATF oil: couldn't measure pH. Water extraction for every parts in the assembly was conducted and MS analysis was applied to the analysis. Only Na+ and Cl- were detected. No NH4+, a little K+ but the majority was Na+ and Cl-

	pH	(micron-g/g)	Na+ (m-mol/g)	(m-g/g)	Cl- (m-mol/g)	Na+/Cl- (mole/mole)
Connector	8.79	340	14.8	230	6.48	2.3
Sensor	7.36	360	15.7	190	5.35	2.9
O-ring	7.40	18	0.78	14	0.39	2.0
Body(stainless)	6.45	17	0.74	25	0.70	1.1

Excess Na+ at connector and sensor might indicate alkali solution as theoretical number of Na+/Cl- = 1.0 but a suspect material couldn't be caught by our analysis.

Regards,

...Hiro

To Distribution List:

MCKENZEC@ISDCVMS@CDCIL1@YOVX00@MRGATZ@YOVX00

TI-NHTSA 012010

ENVIRONMENTAL TEST LAB REQUEST FORM

(ONE TEST PER REQUEST)

DATE Aug 27 1996REQUESTED BY Chris WagnerREQUIRED COMPLETION DATE Sept. 4, 1996EXTENSION 3170 M/S 12 20DEVICE Kepton diaphragm stripsCHARGE DEPT NO. 127 I.O. NO. 10160REFERENCE SPEC. NO. ASTM B117SOURCE OF TEST SAMPLES Design Eng.QUANTITY OF TEST SAMPLES 20REPORT NO. 0524086TESTED BY L2bCOMPLETION DATE 9-4-96

TEST REQUIREMENTS: (TO BE FILLED IN BY REQUESTER)

Please conduct the salt spray test ASTM B117 on these samples until the morning of Sept 4, 1996.

TEST PERFORMED:

IN: 0930 8-28-96 280

OUT: 1000 9-4-96

TEST RESULTS:

EQUIPMENT USED:

CALIBRATION DATE:

NEXT DUE DATE:

ENVIRONMENTAL TEST LABORATORY TEST SET-UP DOCUMENTATION		EVT NUMBER <u>0524-086</u> SET-UP DATE <u>8-28-96</u>		
	ID/CTRL #	CAL DATE	OVER DUE	OPERATOR
DYNAMIC TEST EQUIPMENT				
VIBRATION TABLE				
VIBRATION CONTROLLER				
ACCELEROMETER				
CHARGE AMPLIFIER				
SHOCK TABLE				
ROTARY ACCELERATOR				
CLIMATIC TEST EQUIPMENT				
TEMPERATURE CHAMBER				
DIGITAL THERMOMETER				
TEMPERATURE RECORDER				
SALT FOG				
SALT SPRAY	4099	8-8-96	3-97	JR
ALTITUDE				
HUMIDITY CHAMBER				
OTHER EQUIPMENT				
DIGITAL MULTIMETER				
OSCILLOSCOPE				
OSCILLOGRAPH				
POWER SUPPLY				
FFT ANALYZER				
FORCE GAGE				
SHUNT				

ENVIRONMENTAL TEST LAB REQUEST FORM

(ONE TEST PER REQUEST)

DATE Aug 27 1996REQUESTED BY Chris WagnerREQUIRED COMPLETION DATE Sept. 4, 1996EXTENSION 3170 M/S 12 29DEVICE Kapton diaphragm stripsCHARGE DEPT NO. 127 I.O. NO. 10180REFERENCE SPEC. NO. 2800Z-P&H, pg 18/18SOURCE OF TEST SAMPLES Design Eng.QUANTITY OF TEST SAMPLES 20REPORT NO. 0526-086TESTED BY L2bCOMPLETION DATE 9-4-96

TEST REQUIREMENTS: (TO BE FILLED IN BY REQUESTER)

Please conduct the salt spray test per page 18/18 on the attached Honda specification 2800Z-P&H. Please conduct only 7 cycles or as many as can be completed by Sept 4.

TEST PERFORMED:

Start	07:30	8-29-96
Out:	1000	9-4-96

TEST RESULTS:

EQUIPMENT USED:

CALIBRATION DATE:

NEXT DUE DATE:


3.4 ENDURANCE PERFORMANCE

11: SALT SPRAY

AFTER TEST THE FOLLOWING SHALL BE SATISFIED:

1. GENERAL PERFORMANCE EXCEPT TEMPERATURE PERFORMANCE
2. STRENGTH PERFORMANCE


CYCLE TEST: 60 CYCLES



TEST MODE

WET	SST	DRY	WET	DRY	WET	DRY	SOAK
40°C	35°C	60°C	50°C	60°C	50°C	60°C	-20°C
95%RH	-	-	95%RH	-	95%RH	-	-
2 Hr	2 Hr	1 Hr	6 Hr	2 Hr	6 Hr	2 Hr	3 Hr

WATER PROOF
CONNECTOR



SAMPLE

THREAD CAP

TEST AS SHOWN

TI-NHTSA 012014

DWG. NO.

2860Z - P6H -

18/
18

ENVIRONMENTAL TEST LABORATORY TEST SET-UP DOCUMENTATION		EVT NUMBER <u>0526-086</u> SET-UP DATE <u>8-29-96</u>			
	ID/CTRL #	CAL DATE	OVER DUE	OPERATOR	
DYNAMIC TEST EQUIPMENT					
VIBRATION TABLE					
VIBRATION CONTROLLER					
ACCELEROMETER					
CHARGE AMPLIFIER					
SHOCK TABLE					
ROTARY ACCELERATOR					
CLIMATIC TEST EQUIPMENT					
TEMPERATURE CHAMBER					
DIGITAL THERMOMETER					
TEMPERATURE RECORDER					
SALT FOG					
SALT SPRAY					
ALTITUDE					
HUMIDITY CHAMBER #4	5031	7-9-96	11-96	ggs	
OTHER EQUIPMENT					
DIGITAL MULTIMETER					
OSCILLOSCOPE					
OSCILLOGRAPH					
POWER SUPPLY					
FFT ANALYZER					
FORCE GAGE					
CHUNT					

2800 PROGRAMMING FORM

DESCRIPTION _____

INITIAL VALUE 1 40

INITIAL VALUE 2 95

INTERVAL	FINAL VALUE 1	FINAL VALUE 2	INTERVAL TIME	CONTINUE DEVIATION	AUX.	NEXT INTERVAL	LOOPS
<u>1</u>	<u>40°C</u>	<u>95%</u>	<u>2:30</u>			<u>2</u>	
<u>2</u>	<u>40°C</u>	<u>95%</u>	<u>2:00</u>			<u>3</u>	
<u>3</u>	<u>60°C</u>	<u>15%</u>	<u>00:10</u>	<u>≠</u>		<u>4</u>	
<u>4</u>	<u>60°C</u>	<u>15%</u>	<u>00:50</u>			<u>5</u>	
<u>5</u>	<u>50°C</u>	<u>95%</u>	<u>00:10</u>			<u>6</u>	
<u>6</u>	<u>50°C</u>	<u>95%</u>	<u>05:50</u>			<u>7</u>	
<u>7</u>	<u>60°C</u>	<u>15%</u>	<u>00:10</u>			<u>8</u>	
<u>8</u>	<u>60°C</u>	<u>15%</u>	<u>00:50</u>			<u>9</u>	
<u>9</u>	<u>50°C</u>	<u>95%</u>	<u>00:10</u>			<u>10</u>	
<u>10</u>	<u>50°C</u>	<u>95%</u>	<u>05:50</u>			<u>11</u>	
<u>11</u>	<u>60°C</u>	<u>15%</u>	<u>00:10</u>			<u>12</u>	
<u>12</u>	<u>60°C</u>	<u>15%</u>	<u>00:50</u>			<u>13</u>	
<u>13</u>	<u>-20°C</u>	<u>15%</u>	<u>00:30</u>			<u>14</u>	
<u>14</u>	<u>-20°C</u>	<u>15%</u>	<u>02:30</u>			<u>15</u>	
<u>15</u>	<u>40°C</u>	<u>95%</u>	<u>00:30</u>			<u>1</u>	<u>100</u>

TM-NHTSA 012016

22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS



1) SST of Teflon coated K.

2) Dupont - H₂O & Kapton

~~Have Cracks tho?~~

- Acetic

When Cd calls back.


- What does cause chemical attack?




NO. 1 - FRONT SIDE



NO. 1 - BACK SIDE



NO. 3 - FRONT SIDE







NO. 3 - BACK SIDE

TI-NHTSA 012019



TI-NHTSA 012020

<GCT TEST機外観写真>



TI-NHT8A 012021

<CCT TEST AREA>



Wagner, Chris

From: AHOP%nmil@magic.fg.tl.com[SMTP:AHOP%nmil@magic.fg.tl.com]
Sent: Thursday, September 12, 1996 5:45 PM
To: Wagner, Chris
Subject: RE: 142PS BASE ASM FROM TJ: TSL # 141784

MSG.M= 989805 FR=AHOP TO=CDW3 SENT=09/12/96 04:08 PM
R#191 ST=C DIV=0050 CC=00673 BY=AHOP AT=09/12/96 04:08 PM

MEMORANDUM:
96-579

TO: CHRIS WAGNER CDW3
CC: AMY ANDRES AMY
ROSE SU RSU
GEORGE OLEAR AETL
BETH KILL EKIL
HANK GRIFFIN HG1
BRYAN DAGUE DAGU
JOHN BRENNAN U2JB
TOM CHARBONEAU TC1
FR: AL HOPKINS AHOP

SUBJECT: RE: 142PS BASE ASM FROM TJ: TSL # 141784

After receiving your request for inputs on my MSG, I realized that I had focused too narrowly on answering the original objective that you posed. The following are some additional observations.


Both the "Coppery" appearing area on the brass and "Degraded Kapton" area on the disc are areas of wholesale corrosion while the area that looked like oxidized brass wasn't (it was only surface oxidized).

Corrosion of brass often occurs by a dezincification mechanism (Bob Babolian would know more details). This zinc has to go somewhere, and it often winds up on the surface. In other words, it wasn't surprising that we saw so much zinc on the surface, what was surprising to me is that the deposit looked "coppery".

Just as the zinc can be separated from the copper in the brass, chlorine can separate from sodium if the starting point is sodium chloride. In particular, the majority of the iron-rich corrosion deposit on the disc showed large amounts of chlorine, iron and oxygen but it didn't show clear-cut evidence of any sodium.

The situation on the "coppery" appearing brass is more difficult to discern because the secondary line of zinc obscures the only line of

Page 1



TI-NHTSA 012023

sodium. Overall, the ratio of the two peaks of zinc seems to show that just zinc and not sodium is present but we can't rule out the possibility of some sodium being present. After I sent out the first MSG I asked Rose to go back and do a painstaking search for any areas that we could say definitely had sodium present. She was only able to find a few small crystals over the whole surface. Surprisingly, she also found some calcium in these crystals that were mainly sodium chloride.

If there are any other points that need clarification, please let me know.

ORIGINAL MSG FOLLOWS:

From: "Wagner, Chris" <cwagner@email.motl.com>
To: "Clear, George" <AETL@mag.ig.tl.com>,
"Kil, Elizabeth" <EKIL@mag.ig.tl.com>,
"Griffin, Hank HG1" <HG1@mag.ig.tl.com>,
"DeGue, Bryan" <bdegue@email.motl.com>,
"Bremen, John" <j750288@pen.motl.com>
Cc: "Hopkins, Al" <a825009@mail.motl.com>,
"Charbonneau, Tom" <t-charbonneau@email.motl.com>
Subject: FW: 142PS BASE ASM: TSL # 141784
Date: Thu, 12 Sep 1996 10:36:12 -0400
Encoding: 85 TEXT

Ladies and Gents,

When we took the Kapton off the disc sent on the salt spray/etched Kapton return from TJ, it had some colored "rings" on it, concentric with the disc.

Al has taken a look at the rings and his results are below. Any thoughts?

Chris

From: AHOP%mini@mag.ig.tl.com[SMTP:AHOP%mini@mag.ig.tl.com]
Sent: Thursday, September 12, 1996 9:57 AM
To: Wagner, Chris
Subject: 142PS BASE ASM: TSL # 141784

-MSG MI- 000761 FR-AHOP TO-CDW3 SENT-09/12/96 09:51 AM
RI-188 ST-G DIV-0060 CC-00673 BY-AHOP AT-09/12/96 09:51 AM

MEMORANDUM:
96-579

TO: CHRIS WAGNER CDS

Page 2

TI-NHTSA 012024

CC: AMY ANDRES AMY
ROSE SU RSU

FR: AL HOPKINS AHOP

SUBJECT: 142PS BASE ASM: TSL # 141784

OBJECTIVE:

Determine composition of areas marked on photograph.

CONCLUSIONS:

The area that appeared to have a normal, oxidized brass color was oxidized brass. We saw copper, zinc, lead and a small amount of oxygen (editorial correction).

The area that appeared coppery in color contained very large amounts of chlorine and oxygen. Surprisingly, we actually saw more zinc than copper in this area; also we saw a small amount of iron.

The area which you had thought might be kapton actually showed mostly iron, chlorine, and oxygen. We also, however, saw some tin and zinc.

The data will be sent by Bernadette Maynard through the internal mail.

AL HOPKINS X3040 MS: 10-16 FAX: 1670

Wagner, Chris

From: AHOP%mini@magic.its.tl.com[SMTP:AHOP%mini@magic.its.tl.com]
Sent: Thursday, September 12, 1996 9:57 AM
To: Wagner, Chris
Subject: 142PS BASE ASM: TSL # 141784

-MSG MI= 900761 FR=AHOP TO=CDWS SENT=09/12/96 08:51 AM
RI=188 ST=C DIV=0050 CC=00673 BY=AHOP AT=09/12/96 08:51 AM

MEMORANDUM:
DS-572

TO: CHRIS WAGNER CD3
CC: AMY ANDRES AMY
ROSE SU RSU
FR: AL HOPKINS AHOP
SUBJECT: 142PS BASE ASM: TSL # 141784

OBJECTIVE:

Determine composition of areas marked on photograph.

CONCLUSIONS:

The area that appeared to have a normal, oxidized brass color was oxidized brass. We saw copper, zinc, lead and a small amount of lead.

The area that appeared coppery in color contained very large amounts of chlorine and oxygen. Surprisingly, we actually saw more zinc than copper in this area; also we saw a small amount of iron.

The area which you had thought might be kapton actually showed mostly iron, chlorine, and oxygen. We also, however, saw some tin and zinc.

The data will be sent by Bernadette Maynard through the internal mail.

AL HOPKINS X3040 MS: 10-16 FAX: 1670

TECHNICAL SERVICE LABS

LOG NO. 7406TEST NO. 140396TEST NO. 140396

PCC I.D.	<u>127</u>	STATE YOUR PROBLEM/ SAMPLE DESCRIPTION	INFORMATION DESIRED:
REQUESTOR COST CENTER	<u>101</u>		
PRODUCT CODE	<u>88</u>	The sample has been etched.	Please determine what etched the Kapton. <u>FTIR</u>
REQUESTOR	<u>C. Wagner</u>		
MAIL ROOM	<u>12/2/9</u>		
EXTENSION	<u>3170</u>		
MED ID	<u>C.D.W.3</u>		
DATE SUBMITTED	<u>Sept 9/96</u>		
DATE REQUIRED	<u>ASAP</u>		
NO. OF SAMPLES	<u>1</u>		
COMPOSITION	<u>Kapton: Polyimide Film</u>		

REPORT OF RESULTS:

DATE RECEIVED _____

DATE OUT 9-13-96 7406

TECHNICIAN	<u>CK</u>		
HOURS WORKED			
PROCEDURE USED	<u>TSL-C-060</u>		
	<u>FTIR#2</u>	<u>96-7406.spg</u>	

*PCC I.D.

MC-325
PC-127
VERS-168
AFCC-483
IMD-430

TM-431
WIRE-432
EPD-821
PEP-822
CSD-835

CLKE-122
CAN-854
AD DEV-286
EMCD-877

FACIL-514
FACIL-521
FACIL-531
STAFF-855

Kill, Elizabeth

From: Kill, Elizabeth
To: Wagner, Chris CDWS
Subject: T&L # 140396, Examine etched Kapton
Date: Friday, September 13, 1996 10:33AM

Objective:

Determine what has attacked the Kapton in a APT during cyclic salt spray testing.

Results:

FT-IR spectroscopy confirmed that the undamaged edge of the Kapton seal is a polyimide material. The top match from the spectral library was with a reference sample of Kapton with a match factor of 59.8%.

The spectrum of the blackened Kapton gives a very trace. The top match is with "polyamide-imide" at 70.8%. This is quite different than the polyimide alone. There is also some evidence of hydrolysis, as you suspected. I mathematically subtracted the water peaks from the spectrum, but came up with the same match. It is possible that this is a degradation product of the polyimide.

I attempted to scrape the surface on the blackened area to isolate the attacking compound, but there were no strong matches from the library. The top match is shown as "Nesl (Nujol)" at 61%. This is another name for mineral oil. You will see in the spectral printout that it is not a good match. The surface of the degraded Kapton is probably a mixture of materials making identification of the individual components difficult. This is why we aren't getting any strong matches with any one compound.

Al's message mentioned a high level of iron and chloride, so I scanned a sample of iron chloride for comparison. It does not match any of the spectra from the Kapton sample.

I will forward the spectral data by internal mail. Please call if you have any questions.

Regards,

Beth x3069

Pretat work done. what is it?

Better definition of test (Salt used)

look at it.

bubble! why: solvent: absorbance makes
heat & contract
cut hole in fluid?

organic?


TIJ: Why from inductor.

Solution Ph

↑

22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS





NO-1 DIAPHRAGM & DISC.



NO-1 HEXPORT SIDE.



NO.3 DIAPHRAGM & DISC.



NO.3 HEXPORT SIDE.



NO.22-2. DIAPHRAGM & DISC.



NO.22-2: HEXPORT SIDE.



NO.22-3 . DIAPHRAGM & DISC.



NO.22-3 HEXPORT SIDE.



NO. 2 DIAPHRAGM & DISC.



NO. 4 HEXPORT SIDE.



NO. 5 DIAPHRAGM & DISC.




NO. 5 HEXPORT SIDE.



< CCT TEST 後外觀写真 >



current design vs disc capabilities.



crown HT
.0155
REF

Air Bag: .472
.467

PRESSURES (ACT, REL) likely

OO

FORM D.

~~LIFE~~

THICKNESS


LIFE

- CYCLES TO FAIL
- FAILURE MODE
- DRIFT OVER LIFE

MAT'L 17-7 OK

20K for new die act
14 1/8 or 3/4

Air Bag P/N: 75839-1



142 PS Salt Spray Test

George O'Leary
27-Aug-96



- pH 6.5 - 7.2 - salt spray spec
- > 11 pH for this reaction (confirm)

- Salt Spray test - Water in

- leak out
- pull in on leak
- relation to time $\Rightarrow$ any leaks

- Dissolving Kapton

- high pH ($\sim$ > 11 pH)
- result fog high
- high once in switch.
- bases in other equipment (humidity)

Test Questions

- what salt
- concentration
- power
- any damage before.

142 PS - Salt Spray

Call w/ John B.

Aug 27, 1976

From photos

- Not hydrolysis
- Mat'l appears degraded, then dissolved.
- DuPont info correct

Suggestions.

- Run salt spray @ 60°C.
- Try NaOH @ 60°C

Wagner, Chris

From: Charboneau, Tom
Sent: Tuesday, August 13, 1996 9:06 AM
To: Sweet, Bill
Cc: Dague, Bryan; Wagner, Chris
Subject: FW: TJ INFO for 142PS ISSUE AT HONDA

Bill, we should ask TJ to send photos of the parts including the kapton. Also, it doesn't sound like they have the mating connectors (caplars). These would have evidence of leakage if they were at fault as we suspect.

Still not clear to me why the kapton would be broken.

Tom

From: Sweet, Bill
Sent: Tuesday, August 13, 1996 8:46 AM
To: Snyder, Gary; Kost, Don; Pechonik, John; Bucklar, Jim; Charboneau, Tom; Dague, Bryan; Wagner, Chris; Butler, Stephen; Sweet, Bill
Subject: RE: TJ INFO for 142PS ISSUE AT HONDA

Ryo's response FYI....
Bill x-3488 pager-0650

From: IWA@mini@magic.tg.tl.com@MIP:IWA@mini@magic.tg.tl.com
Sent: Tuesday, August 13, 1996 8:28AM
To: Sweet, Bill
Subject: 142PS ISSUE AT HONDA
To: BILL SWEET WS4

Copy: TAKEBHI TANAKA JATO OSAMI KUSHIDA KUBI
KAZUHIKO NAKANISHI KAZN

From: RYO IWASAKI IWA

Subj: 142PS ISSUE AT HONDA

I HAVE TELEPHONED TO SEVERAL PERSONS OF ENGINEER/MARKETING/FSE WHO ARE ALL IN SUMMER VACATION, AND I COULD CONTACT OUR FSE WHO IS REPORTING TO ME AND HAD A TALK WITH HIM.

THIS PROBLEM WAS HAPPENED AT THE MEETING ON 142PS QUALITY ISSUE RELATING TO A KAPTON FAILURE ON AUGUST 9.

FOLLOWINGS ARE THE TEST RESULT OF 142PS AT HONDA

- FACT 1. HONDA TESTED 7 UNITS OF 142PS (N=7)
IN CASE OF OIL PRESSURE IS ZERO, THERE IS CONTINUITY.
2. WE CAN SEE SOME WET INSIDE CAPLER OF 142PS
3. WE CAN SEE A BROKEN KAPTON, AND THE ROOM AROUND CONTACT TURNED INTO BLACK COLOR, AFTER WE CHECKED THE DAMAGED SAMPLE WHICH WAS GIVEN BY HONDA.

4. WE CANNOT SEE ANY LIQUID INDICATION WHICH RAN INTO A SPACE BETWEEN DISK SHEET AND HEXPORT.

OUR ENGINEER'S VIEW ON THE FAILURES ARE;

VIEW 1. SOME SALT WATER COULD BE ENTERED INTO THE SPACE OF CAPLER RUNNING THROUGH A BALANCE HOLE OF CONNECTOR ASSY OF 142PS DUE TO SOME FAILURE OF CAPLER WATER PROOF.

2. BASED ON FACT 4, SILICON SEALANT SEEMS KEEPING HERMATIC, HOWEVER WE NEED TO RECONFIRM IT.

WHAT OUR ENGINEER IS GOING TO DO ARE;

A. SPECIFY THE REASON WHY SALT WATER RAN INTO THE ROOM OF SWITCH FUNCTION TO SPECIFY THE REASON, WE NEED TO CLARIFY THE ROUTE THROUGH WHICH SALT WATER RAN INTO THE ROOM OF SWITCHING FUNCTION.

- SALT WATER RUNNING ROUTE CAN BE ESTIMATED AS FOLLOWINGS ;

(a) FAILURE OF CAPLER SEAL → CAPLER → BALANCE HOLE → ROOM OF SWITCH FUNCTION.

(b) FAILURE OF SILICON SEALANT → THE SPACE BETWEEN HEXPORT AND DISK SHEET → ROOM OF SWITCH FUNCTION.

(c) FAILURE OF SILICON SEALANT → THE SURFACE BETWEEN DISK SHEET AND CONNECTOR

IN ORDER TO CLARIFY SALT WATER RUNNING ROUTE INTO THE ROOM OF SWITCHING FUNCTION, FOLLOWINGS THOUGHTS WAS CONSIDERED BY OUR ENGINEER.

THOUGHT 1. WE CAN SAY THE ABOVE (b) OF SALT WATER RUNNING ROUTE CANNOT BE HAPPENED AS THE RESULT OF ANALYSIS THAT SAYS NO CORROSION CAN BE SEEN IN THE SPACE BETWEEN HEXPORT AND DISKSHEET

THOUGHT 2. IN ORDER TO PROVE THAT THE ABOVE (c) CANNOT BE HAPPENED, WE NEED THE TEST BY PUTTING A PRESSURE ON THE CAPLER.

THOUGHT 3. IN CASE WE CAN CONFIRM THAT THOUGHT 1 AND 2 ARE NOT THE CAUSE OF SALT WATER RUNNING ROUTES, WE CAN SPECIFY THAT THE SALT WATER RUNNING ROUTE COULD BE THE ABOVE (a)

THOUGHT 4. NEED OCT TEST THE SEALING OF 142PS USING PERFECT SAMPLE WHOSE CAPLER SEALING IS PERFECT FOR THE CONFIRMATION.
OCT: CYCLIC CORROSION TEST (HONDA'S TEST METHOD)

THROUGH 5. START SALT SPRAY TEST (5% NaCl) UNDER 60 DEG. TO CONFIRM A DAMAGE OF KAPTON.

OUR ENGINEERS SCHEDULE FOR THE ANALYSIS.

WHAT	WHO	WHEN
A.OCT ANALYSIS		
- MEASURE THE INSULATION RESISTANCE AT THE OFF TIMING.	O.KUSHIDA	TBD(8/19)
- KAPTON SEALING(10KG/CM2 PRESSURE BY ATP)	O.KUSHIDA	TBD(8/19)

Page 2

TI-NHTSA 012039

- SILICON SEALING (PUT PRESSURE FROM KAPLER)

B. CCT TEST (PERFECT HERMETIC/SEALING) HONDA 8/30/98

C. KAPTON IN THE SALT WATER O.KUSHIDA TBD(8/19)

OUR ENGINEERS' RECOMMENDATION TO HONDA AT PRESENT WILL BE

RECOMMENDATION 1. WE WILL CHANGE KAPTON MATERIAL FROM H-TYPE KAPTON
TO F-TYPE KAPTON WHICH IS COVERED TEFLON COATING

RECOMMENDATION 2. WE WILL PUT SOME MATERIAL ON THE BALANCE HOLE THROUGH
WHICH AN AIR CAN RUN THROUGH BUT LIQUID CANNOT BE RUN.

BILL, THANK YOU FOR YOUR ATTENTION ON OUR ISSUE AT HONDA. THIS IS ALL I COULD
GET CONTACTING OUR PSE BY PHONE. I HOPE THIS MSG HELP YOU TO UNDERSTAND OUR CRITICAL
SITUATION OF 142PS AT HONDA. YOUR ANY RECOMMENDATION OR SUGGESTIONS OR IDEAS
ARE VERY MUCH APPRECIATED. REGARDING THE DAMAGED SAMPLE (KAPTON FAILURE) OF
142PS WHICH WAS GIVEN BY HONDA, WE CANNOT SEND IT NOW SINCE OUR ENGINEER WAS
TOLD BY HONDA TO SHOW IT TO HONDA EARLY NEXT WEEK. IN FACT OSAMI KUSHIDA BROKE
IT INTO PARTS IN ORDER TO CHECK HOW MUCH KAPTON IS DAMAGED.

THANK YOU AND BEST REGARDS,
RYO IWABAKI IWA

-MSG IN= 448529 FR=IWA TO=EVE SENT=08/12/98 03:36 PM
RF=162 ST=C DIV=0072 CC=06822 BY=WS4 AT=08/12/98 01:48 PM

Thank you for attending today's meeting. We brainstormed potential causes and
laid out areas for further investigation. Summary below.

Ryo,

Our understanding is that it is CONFIRMED that the part leaked through the
vent hole. Potential causes:

1> Leak past the connector seal
Is base housing to print with good surface finish
Is connector & connector seal to print?
Are there any cracks in connector or housing

2> Leak down wire - If the wire lead from the connector is in the seal bath
or has any type of splice or connection in the bath we have seen significant
amounts of water drawn into the switch THROUGH THE WIRES.

3> Leak past the wire grommet in the connector
Part to print and not under strain?

We would like to understand more about the "failures".

A> How did they fail? Did they leak or did they fail one or more of the other
general characteristics required after salt spray such as current leakage,
dielectric, sealability, calibration, etc.

B> Were the parts tested under electrical current load?

C> What is the part orientation during the test? Conn up/down?

D> What did Takashi mean when he noted the Kapton was melted? Does it have holes that might be evidence of chemical attack or is it wrinkled? Could it have leak IN the port and OUT the connector vent?

E> Could TIJ send TIA one failed part for our analysis?

There are two problems in these failures. First the Kapton degradation but more importantly that the part leaked at all. It is very important that we separate these issues As Soon As Possible. Laminated Teflon can be used as a barrier on the Kapton such as 1-8-1 or .5-2-.5 to improve resistance to water but the part will still fail electrically. Chris Wagner at TIA will investigate the improved resistance of teflon coated Kapton against salt water. However, the goal needs to be to fix the leak and avoid providing Saginomiya with the possible differentiator of "No Kapton".

We often see such water intrusion due to test set up problems, particularly cause #2 above. Based on the limited info we have today that appears to be a high possibility. Please send us a failed sample as soon as possible to allow a more thorough failure analysis here at TIA.

Regards,
Bill x-3469 Pager-0650 MSG - W84

Wagner, Chris

From: Sweet, Bill
Sent: Monday, August 12, 1996 2:48 PM
To: Tanaka, Takeshi; Iwasaki, Ryochi; Nakamichi, Kazu
Co: Bryder, Gary; Koel, Dan; Pechonis, John; Buckler, James; Charboneau, Thomas; Dagus, Bryan;
Wagner, Chris; Butler, Stephen
Subject: 142PS Failure Brainstorming

Thank you for attending today's meeting. We brainstormed potential causes and laid out areas for further investigation. Summary below.

Ryo,

Our understanding is that it is CONFIRMED that the part leaked through the vent hole. Potential causes;

- 1> Leak past the connector seal
 - Is base housing to print with good surface finish
 - Is connector & connector seal to print?
 - Are there any cracks in connector or housing
- 2> Leak down wire - If the wire lead from the connector is in the salt bath or has any type of splice or connection in the bath we have seen significant amounts of water drawn into the switch THROUGH THE WIRES.
- 3> Leak past the wire grommet in the connector
 - Part to print and not under strain?

We would like to understand more about the "failures".

A> How did they fail? Did they leak or did they fail one or more of the other general characteristics required after salt spray such as current leakage, dielectric, sealability, calibration, etc.

B> Were the parts tested under electrical current load?

C> What is the part orientation during the test? Conn up/conn down?

D> What did Takeshi mean when he noted the Kapton was melted? Does it have holes that might be evidence of chemical attack or is it wrinkled? Could it have leak IN the port and OUT the connector vent?

E> Could TIJ send TIA one failed part for our analysis?

There are two problems in these failures. First the Kapton degradation but more importantly that the part leaked at all. It is very important that we separate these issues As Soon As Possible. Laminated Teflon can be used as a barrier on the Kapton such as 1-3-1 or .5-2-.5 to improve resistance to water but the part will still fail electrically. Chris Wagner at TIA will investigate the improved resistance of teflon coated Kapton against salt water. However, the goal needs to be to fix the leak and avoid providing Segnomia with the possible differentiator of "No Kapton".

We often see such water intrusion due to test set up problems, particularly cause #2 above. Based on the limited info we have today that appears to be a high possibility. Please send us a failed sample as soon as possible to allow a more thorough failure analysis here at TIA.

Regards,

Bill x-3488 Pager-0680 MSG - WS4

From: Sweet, Bill
Sent: Friday, August 09, 1996 1:47PM
To: Charbonneau, Tom; Dague, Bryant; Wagner, Chris; Buller, Stephen
Cc: Snyder, Gary; Kost, Dan; Pechonka, John; Buckler, Jim
Subject: 142P8 Mtg Mon @ 1PM
Importance: High

Gentlemen,

Takeshi called me at lunch time to pass along that 6/6 parts failed HGT's salt spray testing. HGT's spec is quite aggressive calling for salt spray cycling between salt spray and drying at 60 degrees C.

All parts failed with salt water entering into the contact zone apparently through the vent hole. Takeshi noted that the Kapton was also "melted" or "disolved" where the water reached the Kapton. Honda is very concerned with the Kapton degradation. Salt in the contact will fail the device but Kapton failure will cause a transmission leak. Note that Seginomia's approach is a welded disc design w/ no Kapton.

Takeshi has asked that our engineering group draw together and brainstorm potential solutions and forward to Ryo early next week. TLJ has a FYI mtg at HGT on 8/6.

PLEASE PLAN TO MEET MONDAY 8/12 AT 1:00 PM IN CONF ROOM 12-1B TO DEVELOP A RESPONSE

Please be prepared to discuss:

- The salt spray test spec (wagner)
- What type of Kapton is used (wagner)
- Brainstorm potential cause / fix (team)

Regards, Bill x-3488 pager-0680

From: JATO%mini@maglo.ig.tl.com@MTP:JATO%mini@maglo.ig.tl.com)
Sent: Friday, August 09, 1996 1:26PM
To: Sweet, Bill
Subject: 142P8

To: BILL SWEET WS4
Copy: RYO IWABAKI IWA
From: TAKESHI TANAKA JATO
Subj: 142P8

BILL, SORRY FOR BAD NEWS. PLEASE ADVISE RYOICHI ON THIS. I HAVE A PERSONAL APPOINTMENT FROM 08/12 THRU 08/15 AND UNABLE TO BE IN CONTACT WITH YOU DURING THE PERIOD.

REGARDS, TAKESHI TANAKA

Wagner, Chris

From: Sweet, Bill
Sent: Friday, August 08, 1998 1:46 PM
To: Charbonneau, Thomas; Dagus, Bryan; Wagner, Chris; Butler, Stephen
Cc: Snyder, Gary; Kost, Dan; Pechonis, John; Buckler, James
Subject: 142PS Mtg Mon @ 1PM
Importance: High

Gentlemen,

Takeshi called me at lunch time to pass along that 6/8 parts failed HGT's salt spray testing. HGT's spec is quite aggressive calling for salt spray cycling between salt spray and drying at 60 degrees C.

All parts failed with salt water entering into the contact zone apparently through the vent hole. Takeshi noted that the Kapton was also "melted" or "dissolved" where the water reached the Kapton. Honda is very concerned with the Kapton degradation. Salt in the contact will fail the device but Kapton failure will cause a transmission leak. Note that Saginomiya's approach is a welded disc design w/ no Kapton.

Takeshi has asked that our engineering group draw together and brainstorm potential solutions and forward to Ryo early next week. TJ has a FYU mtg at HGT on 8/8.

PLEASE PLAN TO MEET MONDAY 8/12 AT 1:00 PM IN CONF ROOM 12-1B TO DEVELOP A RESPONSE>

Please be prepared to discuss:

- The salt spray test spec (wagner)
- What type of Kapton is used (wagner)
- Brainstorm potential cause / fix (team)

Regards,
Bill x-3489 pager-0660

From: JATO%mini@magic.ilg.it.com(MTP:JATO%mini@magic.ilg.it.com)
Sent: Friday, August 09, 1998 1:26PM
To: Sweet, Bill
Subject: 142PS

-MSG M#- 4099514 FR-JATO TO-WB4 SENT-08/08/98 11:47 AM
RF-084 ST-C DIV-0072 CC-08029 BY-JATO AT-08/10/98 01:44 AM

To: BILL SWEET W/S4

Copy: RYO IWASAKI IWA

From: TAKESHI TANAKA JATO

Subj: 142PS

BILL, SORRY FOR BAD NEWS. PLEASE ADVISE RYOICHI ON THIS. I HAVE A PERSONAL APPOINTMENT FROM 08/12 THRU 08/15 AND UNABLE TO BE IN CONTACT WITH YOU DURING THE PERIOD.

REGARDS,
TAKESHI TANAKA

Wagner, Chris

From: Wagner, Chris
Sent: Monday, August 28, 1996 11:23 AM
To: Nakanishi, Kazuhiko KAZN; Kuahida, Oosmi KUSI; Tanaka, Takashi JATO
Cc: Dague, Bryan; Sweet, Bill; Buckler, James JBUC; Butler, Stephen; Charboneau, Tom; Brennan, John; Stander, Richard ELB
Subject: 142PS Kapton and Salt Spray Test

Nakanishi-san,

Thank you for calling me today regarding the Honda salt spray test - Kapton failure. My notes on our call are below. Please let me know if there is anything I missed.

BACKGROUND

Honda ran the same test on earlier designs of the switch. Earlier designs passed. The only difference is the vent or balance hole in the base.

The test was run with the mating connector installed. The wires on the connector were at least 1 mm long.

The Kapton was black when the switches were taken apart. It looked like they had been burned. A sample will be sent tomorrow. Dupont of Japan is analyzing.

The next meeting with Honda is September 5.

TIA COMMENTS

The photos do not look like hydrolysis alone was the failure mode. The Kapton looked dissolved which is not typical of hydrolysis. The black color is also unusual.

TIA would like to ask Honda some questions about the test.

1. Were the switches pressure cycled during the test? If yes, what were the cycle parameters:

- cycle pressure
- number of cycles
- temperature while cycling
- cycling fluid
- cycle rate and pressure wave description

2. How fast did the switch change temperature during the test? The temperature profile calls out 0 time for temperature change. How much time did it take for the switch to go from:

- 40 to 35?
- 35 to 60?
- 60 to 50?
- 50 to 60?
- 60 to -20?
- 20 to 40?

3. What was the condition of the salt water solution?
What was the solution pH?

What was the quality of the incoming water?
Were any chemicals besides salt added to the water?
What salt was used?

4. How long were the wires on the mating electrical connector?
You said they were at least 1 mm long. Could you find out please?
Were the wire ends in the chamber or out?
Does TIJ have a theory explaining how the water entered the switch?

I think #1 and #4 are the two most important questions.

In regards to question 4, TIA knows that if the ends of the wires are in the salt spray chamber, water will enter the switch. Capillary action will draw water through the wires to the crimp at the coupler. Pressure differences will pump the water into the switch from the wires. The test MUST be run with the wire ends OUT of the salt spray chamber.

During the conversation, you asked our (TIA) opinion for a countermeasure. Although I suggested Teflon coated Kapton, I STRONGLY URGE that we do not propose ANY countermeasures to Honda until the root cause is identified. Without a root cause known, we can not guarantee a solution. It would be very embarrassing to fail this test again.

You asked if TIA thought the vent hole could be eliminated or moved. TIJ data shows that the hole is needed for calibration stability. I can not now think of a better place for it. I also recommend NOT putting a filter in it.

ACTIONS

Salt spray test Kapton	TIA
Ask Honda questions 1-4 above	TIJ
Evaluate failed Kapton	Dupont of Japan
Send failed Kapton sample to TIA	TIJ
Arrange next phone call	Kazu


I look forward to talking with you again soon. I will keep you updated on TIA progress.

Regards,
Chris

143/PSA SALT SPRAY

CCT

- Dupont noted NaOH
- George O.
- add to make pH correct. (0117) 6.5 - 7.2 dilute NaOH .
- some labs need this due to poor H_2O quality



Na^+ & OH^- ion associate/dissociate.

- Honda: What is your test like?
- Salt sol pH
- Resistivity of incoming water. seimens, Ohms
- Quality of incoming H_2O $\Rightarrow$
- Salt Re-agent.
- What was Temp Rate of T.
- Was the Sen. Cycled
- Paramiters.

Bkg

- Dupont has TDC. Turn Dupont ~~etc~~
- T1J met w/ them
- Background of 142PS
of test
- Krypton rubber meltout w/ black
- no pressure
- " same form
- Check pH of NaOH 5% ?
" ATP
- Check structure of assembly
could you get a base with solution
white crystal in connector

Why NaOH attacks Krypton
Breaking Polymer 20.

- polymeric acid in H₂O
- Krypton not really effected by NaCl.
- used in military many
- no real effect.

Attention talk of KOH

- OH the important radical ?
- T & P to increase sticking
- alcohol seems to accelerate 80/20 H/H₂O !
" in catalyst.

Potassium OH : ~~3% / 100%~~ ~~20/80~~
1 normal solution

- NaOH content
- ~~What is~~ Will pH 7.2 etc.
- Send Photos
- Test Parameters.
- Limit & color?

~~10/12~~

8575 Salt Spray

When Dupont Calls

- What info do you have?
copy of fax?
- Do they want photos?
- What is it about Na OH that attacks Kapton.
- Is more basic, more prone to attack.

Also

Will 2 mil meet it

could do it, but depends on volume.
maybe under something out.

automotive films get special flags.
need to negotiate.

Hydrolytic Stability

Kapton® polyimide film is made by a condensation reaction; therefore, its properties are affected by water. Although long-term exposure to boiling water, as shown in this curves in Figures 3 and 4, will reduce the level of film properties, sufficient tensile and elongation

remain to ensure good mechanical performance. A decrease in the temperature and the water content will reduce the rate of Kapton® property reduction, whereas higher temperature and pressure will increase it.

Figure 3. Tensile Strength After Exposure to 100°C (212°F) Water, Type HN Film, 25 μ m (1 mil)





Figure 4. Ultimate Elongation After Exposure to 100°C (212°F) Water, Type HN Film, 25 μ m (1 mil)



142PS Salt Spray Failure

Generally Mo-Yr to hydralysis.

do not expect in water
stems should accelerate.


perhaps other damage. horn/edge. etc.

if stressed, can crack from just hydralysis

unlikely that NaCl accelerated.


25-141 20 SHEETS
25-142 100 SHEETS
25-143 200 SHEETS
25-144 400 SHEETS






Hydrogen bonds link the chains by connecting $\text{C}=\text{O}$ with $\text{N}-\text{H}$ of different chains. Since nylon has no bulky side chains, the molecules can pack closely together, giving the resulting fiber the characteristics of silk.

Nylon is made from the six-carbon dicarboxylic acid, adipic acid,



and hexamethylenediamine,




This acid and amine react to form nylon salt (see Section 16) which is polymerized

with the evolution of water into polymer molecules or polyamides. The polyamide is melted, extruded, and hardened by cooling.

Nylon fibers are strong and elastic. These fibers, made extra strong by stretching, are used for tire cord and other industrial uses. Regular nylon filament yarns are used for lightweight, dense, wind resistant apparel. Special filament nylon yarns with extra bulk are prepared for knit goods and carpet pile, while nylon monofilaments are used for sheer hosiery.

NITRILES

20. Nitriles. Nitriles are alkyl derivatives of hydrogen cyanide, HCN . They have the general formula RCN . Acrylonitrile,



Test ID #	Description	Part Number	YC #	Date
521-15-5	AIR CALIBRATE MARKETING SAMPLES	87PSL11-2	R. STANER	11/1/96
522-15-31	Ford TP-2 Tests	77PSL2-1	E. ROSE	11-4-96
523-01-26	87PS Samples - Production Parts	87PSL11-2	R. STANER	12-2-96
524-15-12	87PSL2-2 P-D curves	87PSL2-2	K BROWN	6-26-97
525-15-20	87PSL2-2 Calibration	87PSL2-2	K BROWN	7/2/97
526-15-39	Derringer Clad Contact Validation	77PS	K BROWN	8/10/97
527-15-45	Derringer Clad Contact Validation	87PS	K BROWN	8/10/97
528-15-20	Special Sample Order T.I. Holland/mr	87PS	K BROWN	8/29/97
529-01-04	Sample build Ford Cruise control 97-097	77PSL3-2	K BROWN	8/29/97
530-01-00	Sample build Ford Cruise Control 97-097	77PSL3-2	K BROWN	9/23/97
531-05-200	Quiet Disc Evaluation	87PSL2-5	K BROWN	10/2/97
532-15-70	Quiet Disc Evaluation Δ Pin heights	87PSL2-5	K BROWN	10/2/97
533-01-40	Quiet Disc Sample Order 97-097	87PSL2-5	K BROWN	10/2/97
534-12-25	Impulse Data comparison w/ Production Line	87PSL	K BROWN	10/11/97
535-01-35	Sample 1354 P.D. 97-49	77PSL3-3	K BROWN	10/16/97
536-01-20	Sample Order 97-051	87PS spec.	K BROWN	10/30/97
537-01-02	Sample Order *CD97-79 Ford Motor Co	77PSL3-2	K BROWN	11/10/97
538-15-50	Ford TP-2 Test	77PSL3-3	D. HAY	11/12/97
539-01-205	Sample Order *CD97-81 PTG	87PSL2-5	K BROWN	11/18/97
540-01-30	Sample # 97-82 THH/Land Rover 12 pc. sent	87PS spec	D. HAY	12/1/97
541-12-30	Impulse testing / Quiet disc development	87PS	WBS	12/25/97
542-13-20	Air Cal @ Hi, low temp	87PSL2-5	WBS	12/23/97
543-13-44	Air Cal @ Hi, low temp / Maryl	87PSL2-5	WBS	12/27/97
544-15-01	Air Cal @ Room & Humidity Return	77PSL3-2	WBS	12/2/97
545-12-28	Impulse per 87PSL2-5 Quiet Disc Test Plan	87PSL2-5	WBS	1/6/98
546-01-10	87PSL11-2 Sample Order *CD98-01	87PSL11-2	WBS	1/11/98

Test ID #	Description	Part Number	YC #	Date
547-01-76	Sample Order # 98-01	87PS-Quint	Special	1/14/98 MS
548-15-28	Tam I Validation Control	77PS	MS	1/13/98
549-15-28	Tam II Validation Control	87PS	MS	1/13/98
550-15-64	Tam II Validation	87PS	MS	1/14/98
551-07-12	TAM II Validation Temp Cycling	87PS	MS	1/14/98
552-12-36	TAM II Val. Impulse	87PS	MS	1/14/98
553-08-12	TAM II Val. Vibration Test	77PS	MS	1/14/98
554-12-36	TAM II Val. Impulse	77PS	MS	1/14/98
555-01-40	Land Rail Replacement Samples 77PSL3-3w/eng	77PS	PM	2/1/98
556-01-44	LR Replacement Samples 77PSL3-3w/eng only 77PS	77PS	MS	2/1/98
557-01-20	Replacement Samples	87PS	MS	2/1/98
558-01-4	Sample Build	87PS	MS	2/1/98
559-15-24	Land Rail Replacement Test	77PS	MS	3/12/98
560-01-25	Sample Order #197 77PSL2-3 (25)	77PS	MS	4/23/98
561-15-18	Validation of New Raw Mat'l Supplier for All Crimp Rings	77PS	LM	5/20/98
562-01-60	Sample order # 291 77PSL3-4	77PS	MS	4/6/98
563-01-14	87PSL2-5 PV Impulse Test	87PSL2-5	MS	4/17/98
564-15-10	87PSL2-5 ORPP # 236		MS	4/21/98
565-15-11	87PSL2-5 Production Validation Sample Test	87PSL2-5	MS	5/6/98
566-15-84	Sample order # 839	77PSL3-4	MS	5/4/98
567-15-60	IP-2 Testing	77PSL3-3	MS	5/21/98
568-15-38	Hassell Pinet + Contact Validation Test Sample 77PSL3-3	77PSL3-3	MS	6/2/98
569-01-02	77PSL3-4 Sample for IT	77PSL3-4	MS	6/12/98
570-15-1	Land Rail Replacement	77PS	MS	7/6/98

[illegible]

P-2 TESTS							
	FORD						
	TEST #	TEST #	TEST #	CHEVROLET	GM-SPS	CHRYSLER	HONDA SPS
	P27A-0000-00	P27C-0000-00	P27D-0000-00	PT-0000	100000	00000-1 000	00000-000
	POWER STRG	BRAKE	BRAKE	POWER STRG	POWER STRG	BRAKE	POWER STRG
	SPRNG	SPRNG	TYPE	SPRNG 2-4			
CALIBRATION	100%	100%	100%	100%			
CREEP CHECK	100%	4LOT	NA	100%			
LEAK CHECK	100%	NA	NA				
VOLTAGE DROP	0000	4LOT	4LOT	4LOT			
CURRENT LEAKAGE	0000	4LOT	4LOT				
PROOF	0000	4LOT	4LOT	4LOT			
BURST	0000	4LOT	4LOT	4LOT	000000		
TERMINAL STRENGTH	0000	4LOT	4LOT	4LOT			
VIBRATION	0000	10000	0000				
VACUUM	0000	0000	0000				
TEMP CYCLE	0000	0000	0000				
FLUID RESISTANCE	NA	NA	000000	NA			
IMPULSE	0000	0000	0000	400000			
HUMIDITY	0000	0000	0000				
SALT SPRAY	0000	0000	0000				
TEMP CORRELATION	NA	NA	NA	NA	WEEKLY		
ISOLATION RESISTANCE	NA	NA	NA	4LOT			
--- CURRENT TEST STATUS ---							
CALIBRATION	100%	100%	100%	100%	100%	100%	100%
CREEP CHECK	100%	100%	NA	100%	NA		
LEAK CHECK	100%						
VOLTAGE DROP	PER PILOT	PER PILOT	PER PILOT	PER PILOT			
CURRENT LEAKAGE	PER PILOT	PER PILOT	PER PILOT	PER PILOT			PER PILOT
PROOF	PER PILOT	PER PILOT	PER PILOT	PER PILOT		PER PILOT	PER PILOT
BURST	PER PILOT	PER PILOT	PER PILOT	PER PILOT	0000	PER PILOT	PER PILOT
TERMINAL STRENGTH	PER PILOT	PER PILOT	PER PILOT	PER PILOT			
VIBRATION			000000				
VACUUM			000000				
TEMP CYCLE			0000				
FLUID RESISTANCE			000000				
IMPULSE			000000				
HUMIDITY			000000				
SALT SPRAY			000000				
TERMINAL STRENGTH			000000				
TEMP CORRELATION	NA	NA	NA	NA			
ISOLATION RESISTANCE	NA	NA	NA	NA	NA		
							POST TEST QUAL
							000/0000

TI-NHTBA 012000

TEST WORKSHEET

PM:		77PSL2-1		DATE:		12/6/98	
A. CALIBRATION SPEC				POST TEST			
ACT		90-180		A.S.M.P.			
REL		20 MIN		A.S.M.P.		LAB TEST # 522-15-54	
B. MILLIVOLT DROP < 200				A.S.M.P.			
C. CURRENT LEAKAGE				A.S.M.P.			
D. PROOF 3000psi				A.S.M.P.			
PRE TESTS:				P-2 TEST		POST TESTS:	
DEVICE #	PROOF	ACT	REL	MVD	CURLK	VIBRATION	A,B,C,D
1	OK	137.8	51.2	0.08	OK	#1-8	
2	OK	131.3	46.8	0.08	OK		
3	OK	135.4	69	0.06	OK		
4	OK	131.2	60	0.08	OK		
5	OK	129.9	61.1	0.08	OK		
6	OK	138.3	52.4	0.08	OK		
7	OK	131.8	63.4	0.08	OK	VACUUM	A,B,C,D
8	OK	138.9	68.4	0.11	OK	#7-12	
9	OK	121.4	54.4	0.1	OK		
10	OK	120.2	63.2	0.08	OK		
11	OK	128.8	68.4	0.08	OK		
12	OK	129.2	61.2	0.08	OK		
13	OK	128.2	66.8	0.08	OK	TEMP. CYCLE	A,B,C,D
14	OK	132.2	63.3	0.07	OK	#13-18	
15	OK	131.3	68.4	0.08	OK		
16	OK	121.2	59.7	0.08	OK		
17	OK	134.4	68.4	0.08	OK		
18	OK	131.9	68.4	0.07	OK		
19	OK	127.8	63.4	0.06	OK	FLUID RES.	E,G,H,I
20	OK	129.7	58.8	0.07	OK	#19-54	IMPULSE
21	OK	128.2	68.5	0.06	OK		#19-30
22	OK	133	65.4	0.06	OK		
23A	OK	130.8	66.4	0.08	OK		
24	OK	130.7	65.5	0.08	OK		
25	OK	134.4	69.5	0.08	OK		
26	OK	129.9	69.9	0.07	OK	*23A & 30A	REPLACEMENT PCS.
27	OK	130.2	63.4	0.08	OK		DUE TO TEST SET-UP ERROR
28	OK	123.8	66.4	0.08	OK		
29	OK	128.8	67.1	0.07	OK		
*30A	OK	134.8	70.4	0.08	OK		
31	OK	128.1	64	0.08	OK	TERM. STR	A,B,C,D
32	OK	139.3	68.5	0.06	OK	#31-42	
33	OK	127.2	64.3	0.08	OK		
34	OK	127.9	68.5	0.06	OK		
35	OK	123.5	60.4	0.08	OK		
36	OK	139.9	49.8	0.08	OK		
37	OK	123.1	67.7	0.08	OK		
38	OK	139.2	68.1	0.07	OK		

TEST WORKSHEET

P/N:		DATE:			
A. CALIBRATION SPEC		POST TEST			
ACT		A.S.M.P.			
REL		A.S.M.P.			
B. MILLIVOLT DROP		A.S.M.P.			
C. CURRENT LEAKAGE		A.S.M.P.			
D. PROOF		A.S.M.P.			
PRE TESTS:		(F-3 TEST)		POST TESTS:	
DEVICE #	PROOF	ACT	REL	MVD	CUR.LK
39	OK	126	87.8	0.05	OK
40	OK	127.9	84.1	0.06	OK
41	OK	128.8	81.2	0.06	OK
42	OK	132.8	88.1	0.06	OK
43	OK	134.5	83.4	0.06	OK
44	OK	127.4	88.9	0.05	OK
45	OK	132.2	80.1	0.07	OK
46	OK	129.1	80.1	0.17	OK
47	OK	129.9	80.4	0.08	OK
48	OK	138.4	84.4	0.08	OK
49	OK	124.5	82.3	0.06	OK
50	OK	131.8	88.3	0.06	OK
51	OK	138.1	82.1	0.07	OK
52	OK	135.5	81.8	0.09	OK
53	OK	131.6	86.4	0.05	OK
54	OK	131.1	88.5	0.08	OK
HUMIDITY A.B.C.D					
#43-48					
SALT SPRAY A.B.C.D					
#49-54					

POST TESTS

P/N:		77PBL2-1		DATE:		1/14/97	
A. CALIBRATION SPEC				POST TEST			
ACT		90-180		A.S.M.P.			
REL		20 MIN		A.S.M.P.		LAB TEST # 822-18-84.	
B. MILLIVOLT DROP < 200				A.S.M.P.			
C. CURRENT LEAKAGE				A.S.M.P.			
D. PROOF		3000psi		A.S.M.P.			
POST TESTS:				IP-2 TEST		POST TESTS:	
DEVICE #	PROOF	ACT	REL	MVD	CUR.LK	VIBRATION	A,B,C,D
1	OK	134	59.6	0.19	OK	# 1-6	
2	OK	121.4	58.9	0.32	OK		
3	OK	134.7	69.9	0.21	OK		
4	OK	131.8	78.4	0.21	OK		
6	OK	129.4	80.4	0.22	OK		
8	OK	131.3	61.3	0.25	OK		
7	OK	133.8	65.4	0.29	OK	VACUUM	A,B,C,D
8	OK	134.4	68.7	0.21	OK	# 7-12	
9	OK	125.6	60	0.29	OK		
10	OK	122.4	65.3	0.22	OK		
11	OK	127.8	69.6	0.21	OK		
12	OK	124.7	62.8	0.19	OK		
13	OK	113.8	57.5	0.19	OK	TEMP.CYCLE	A,B,C,D
14	OK	123.4	59.7	0.28	OK	# 13-18	
15	OK	128.4	54.4	0.41	OK		
16	OK	116.9	60.6	0.19	OK		
17	OK	121.9	61.9	0.21	OK		
18	OK	118.5	63.2	0.25	OK		
19	OK	120.1	66.4	0.27	OK	FLUID RES.	E,G,H,J N/A. 1/YR. ONLY
20	OK	114.4	64.8	0.24	OK	# 19-24	IMPULSE: A,B,C,D
21	OK	114.8	61.2	0.26	OK		#19-30
22	OK	117.1	63.1	0.53	OK		
23	OK	114.4	68.1	1.18	OK		
24	OK	117.4	63.4	0.83	OK		
25	OK	118.2	65.8	5.71	OK		
26	OK	114.5	64.4	0.3	OK		
27	OK	114.5	67.8	0.36	OK		
28	OK	110.6	68.6	0.31	OK		
29	OK	112.9	68.4	0.34	OK		
30	OK	123.8	72.8	0.32	OK		
31	OK	130.8	65.8	0.31	OK	TERM.STR	A,B,C,D
32	OK	134.8	68.9	0.24	OK	#31-42	
33	OK	128.9	60.2	0.22	OK		
34	OK	131.8	63.4	0.22	OK		
35	OK	128.1	68.9	0.27	OK		
36	OK	121.6	64.6	0.58	OK		
37	OK	124.4	66.8	0.23	OK		
38	OK	137	63.9	0.37	OK		

POST TESTS

P/N:		DATE:					
A. CALIBRATION SPEC		POST TEST					
ACT		A.S.M.P.					
REL		A.S.M.P.					
B. MILLIVOLT DROP		A.S.M.P.					
C. CURRENT LEAKAGE		A.S.M.P.					
D. PROOF		A.S.M.P.					
PRE TESTS:		IP-2 TEST	POST TESTS:				
DEVICE #	PROOF	ACT	REL	MVD	CURLK		
39	OK	132.2	61.4	0.19	OK		
40	OK	136.4	70.1	0.22	OK		
41	OK	132.8	69.8	0.20	OK		
42	OK	136.9	67.4	0.19	OK		
43	OK	141.4	70.3	0.6	OK	HUMIDITY	A,B,C,D
44	OK	141.1	53.3	0.21	OK	#43-48	
45	OK	140.2	68.3	0.27	OK		
46	OK	132.4	68.8	0.32	OK		
47	OK	138.8	62.2	0.23	OK		
48	OK	154.4	68.7	0.23	OK		
49	OK	123.7	69.7	0.19	OK	SALT SPRAY	A,B,C,D
50	OK	133.4	68.1	0.53	OK	#49-54	
51	OK	146.8	48.8	0.51	OK		
52	OK	141.2	54.6	0.28	OK		
53	OK	130.4	60.4	0.23	OK		
54	OK	144.3	68.4	0.22	OK		