

**EA02-025**

**TEXAS INSTRUMENTS,  
INC.'S 9/10/03  
ATTACHMENT**

**REQUEST NO. 7**

**BOX 8**

**PART A-U**

**PART L**

Tests Currently in Progress  
Last updated: 2/15/99

**Ignition Re-creation:**

Objective - to recreate the conditions that caused an engine fire in the application.

Description:

- 1. 10 switches are filled with a mix of brake fluid, water, and detergent. 2 switches are filled with each of the following concentrations: 0%, 4%, 6%, 10%, and 75%. 14 volts is being applied to 1 terminal and the hexport is grounded. Current flow varies from about 0.5 mA to a high of about 5.0 mA. 0% switches were removed for #3 called out below.
- 2. On 2 of the above switches, approximately 1 amp is being conducted through the terminals in order to create heat in the switch.

Results to date:

Re-filled the 75% device. Current flows have decreased. Fluid has discolored. Temperatures are stable. Occasionally we have to refill the switches with solution.

**Wearball Testing:**

Objective - To determine if snap discs have a characteristic life similar to quiet discs.

Description:

A population of 30 77PSI2-1 (snap discs) is being cycled to failure.

Results to date:

Results to date:

First failure at 725,000.

Population now has 800,000 cycles.

**Wear Correlation:**

Objective - To develop a spectrum of dimensions and visual cues that can be used to estimate the % of life left on switches returned from the field.

Description:

Switches are being removed from the cyeler at increments of 200K cycles. 2 switches at each interval. These switches will be disassembled and wear at the following points will be characterized:

1. Kapton degradation
2. Pin
3. Pin guides
4. Arm bump
5. Converter/washer interface

Results to date:

900K cycles.

2 with 200K cycles were removed - Currently being photographed

2 with 400K cycles were removed - Currently being photographed

2 with 600K cycles were removed - Currently being photographed

2 with 800K cycles were removed - Currently being photographed

2 with 900K cycles were removed - Currently being photographed

**Future Plans**

**DOE:**

In order to run multiple moisture levels the pressure cycle needs to be modified. Parts needed for the modification are being ordered today. The goal is to have this DOE running by the end of the week. Factors being investigated on the first pass are moisture and snap vs quiet. Future passes will include temperature and pressure.

Initial load - 10 parts

Material

**Auto-ignition testing:**

**Ignition via heating element:**

Objective is to get a fire started within the switch by installing a very small electrical heating element. With a small heating element built into a switch, we will fill the connector cavity with brake fluid, and slowly increase the current in the heating element. We will increase the current until ignition, or until the heating element burns out (continuity is lost).

**Samples to test:**

- 1) Dry
- 2) Pure brake fluid with metal shavings
- 3) 6% brake fluid solution

**Results:**

We have had significant trouble building reliable heaters within the pressure switch. However, two out of several attempts has created great amounts of smoke. Next step is to add a mechanism to create a spark while the heavy smoke is being produced.

**Creating a heating element with corrosion:**

The purpose of this test is to increase the contact's arm enough to generate significant heating.

Filling the switch with salt water and holding the arm at 14 volts and respect at ground will generate corrosion.

**Results:**

N/A

End of document.

- Vehicle Integration  
(Brake master)
- Brake System - (pedal position)
- Deployment calls
- Dual
- Brake Fluid Contaminant

**Morris, Irene**

---

**From:** Daigle, Bryan  
**Sent:** Monday, February 15, 1999 3:54 PM  
**To:** Rushman, Aziz  
**Cc:** Beringhaus, Steven; Baumann, Russell; McGuirk, Andrew  
**Subject:** Monday update

**Tests Currently in Progress**  
Last updated: 2/15/99

**Ignition Re-creation:**

**Objective** - To recreate the conditions that caused an engine fire in the application.

**Description:**

1. 10 switches are filled with a mix of brake fluid, water, and detergent. 2 switches are filled with the following concentrations: 0%, 4%, 6%, 10%, and 75%. 14 volts is being applied to 1 terminal and the housing is grounded. Current flow varies from about 0.5 mA to a high of about 5.0 mA.
2. On 2 of the above switches approximately 1 amp is being conducted through the terminals in-order to create heat in the switch.

**Results to date:**

No failures in 75% device. Current flows and temperatures are stable, but have decreased during the last couple of days.

**Wearout Testing:**

**Objective** - To determine if snap discs have a characteristic life similar to quiet discs.

**Description:**

A population of 30 77783/2-1 (snap discs) is being cycled to failure.

**Results to date:**

No failures at 600K cycles.

**Wear Correlation:**

**Objective** - To develop a spectrum of dimensions and visual cues that can be used to estimate the % of life left on switches removed from the field.

**Description:**

Switches are being removed from the cycles at increments of 200K cycles. 2 switches at each interval. These switches will be disassembled and wear at the following points will be characterized:

1. Kapton degradation
2. Pin
3. Pin galls
4. Arm bend
5. Cover/washer damage

**Results to date:**

600K cycles.

2 with 200K cycles were removed - awaiting dissection.

2 with 400K cycles were removed - awaiting dissection.

2 with 600K cycles were removed - awaiting dissection.

**Future Plans:**

**DOE:**

In order to run multiple moisture levels the pressure cycle needs to be modified. Parts needed for the modifications are being ordered today. The goal is to have this DOE running by the end of the week. Factors being investigated on the first pass are moisture and snap vs quiet. Future passes will include temperature and position.

**Auto-Ignition testing:**

**Objective** is to get a fire started within the switch by installing a very small electrical heating element. With a small heating

element built into a switch, we will fill the connector cavity with brake fluid, and slowly increase the current in the heating element. We will increase the current until ignition, or until the heating element burns out (continuity is lost).

Other:

Potential design changes will be addressed under a separate cover.

End of document

7745

## Wear Correlation

07/16/99

JAN

SENSOR	Rapton layer 1 (Fluid side)	Rapton layer 2 Plated side	Rapton layer 3 Fluid side	Pin	Pin	Bump A/P	Disc
300K #1	300K01#1	300K01#2	300K02#3	300K01#1	300K01#2	300K01#3	300K01#01
300K #2							
300K #3							
400K #1							
400K #2							
600K #1	600K01#1						
600K #2							

Suction for  
Fluid

TI-NHTBA 012340

## Ford 77 ps Fluid Temperature Testing

Technician: LCC Date: 2-16-94 Time: 12:00 PM

### Temperature Readings

Peak	1 76	2 59	3 109	4 84	5 61
	79	110	125	90	119

Current Readings

	1 X	2 X	3 Y	4 Y	5 21ma @ 75% H <sub>2</sub> O

Volt 13.58

NOTES: (please include any information and observations).....

Device still did not show any signs of over heating.  
The 75% water with known contents held steady with only  
fluctuation of +/- 0.5 m.s. Device removed for individual  
overheat test and recorded at 9100 sec. C.R. start  
me was 3.05 min and showed rapid rise in less than 2  
min.

---

---

---

---

---

---

Ambient Temperature

78°

Oven Temperature


75°




TI-NHTSA 012342



TL-NHTSA 012343



TI-NIHTC



TH-NHTSA 012345



TI-NHTSA 012346

Eastein, Sally

---

**From:** McGuirk, Andy [a-mcguirk@mail.mtii.com]  
**Sent:** Tuesday, February 16, 1999 7:18 AM  
**To:** Rowland, Thomas  
**Cc:** Sharpe, Robert; Dodd, Bob; Pechents, John; Baker, Gary; Beringhouse, Steven; Bortoch, Bob  
**Subject:** PW: Brake Pressure Switch Log  
**Importance:** High

tom, by copy of this note we will look to gary baker and bob dodd and steve beringhouse for information about the '99 town car today which reportedly was launched without a p/s in the brake system for cruise system.

we will also determine our analysis protocols for these Texas return units before noon today, tuesday.

AUTOMOTIVE SENSORS AND CONTROLS QA MANAGER  
34 FOREST ST M/S 29-03  
ATTLBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
PAGE: (800) 467-3700 PIN 604-2044

---

**From:** Rahman, Ariz  
**Sent:** Monday, February 15, 1999 8:30 PM  
**To:** Dague, Bryan; Beringhouse, Steven; McGuirk, Andy; Sharpe, Robert; Baker, Gary; Baumann, Russ  
**Subject:** PW: Brake Pressure Switch Log

Received second wave of parts from Texas junkyards. All FAVC parts. Most of them with connector attached. Some of them with prop valves & servos. 2 from underhood figures. Analysis will start tomorrow PM. Please let me know if there are any specifics to look at, before we disassemble these. I was thinking of doing some quick voltage drops, insulation resistance checks. Obviously lots of pictures. Any quick way to test these parts for leaks, prior to disassembly?

By the way, Steve R. did mention that the Electrical System folks were looking into using a Brake Pedal Position Sensor as a replacement for the Brake Pressure Switch as a corrective /containment action. Have we determined what they use in the 99 Town Car?

---

**From:** Rahman, Ariz  
**Sent:** Monday, February 15, 1999 8:32 PM  
**To:** 'Fred Porter ( Ford )'; 'Noma LaPointe ( Ford )'; 'Steve LaRouche ( Ford )'; 'Steve Reinartz ( Ford )'  
**Subject:** Brake Pressure Switch Log

Attached is a log file with information on the devices under review. It also contains switches received today from John McInarney. In addition to Steve L's analysis summary file, I will be using this log to track incoming parts. Please advise if I have missed any data.

TI-NHTSA 012347

i disabled file to conserve space and e-mail time.....

Please let me know if you cannot open the file. Steve/Norm, can you please e-mail me the last update on your analysis summary file? Thanks.

Regards  
Aziz,

TI-NHTSA 012348

Degus, Bryan

---

From: Degus, Bryan  
Sent: Tuesday, February 16, 1999 8:03 AM  
To: Rahman, Aziz  
Subject: RE: Brake Pressure Switch Log

Aziz,

I did get your phone MSG last night, and it sounds like you are on the right track. Although I don't know what kind of environment you are working in, you might try to get some of the following measurements:

- 1) Calibration (actuation and release)? Not sure if you have the equipment there. At the same time you will see if there is a gross leaker.
- 2) Leak down test. Go up pretty high in pressure 200 to 3000 psi. If the kapton is cracked and there is a leak path filled with brake fluid, the brake fluid will seal the leak path at low pressures ( 5 to 10 psi).
- 3) Resistance from each terminal to the hexport. If the contact cavity is filled with brake fluid you will probably not get a stable reading. The voltage and current supplied by the meter is enough to start moving ions around in the solution. The electrodes start charging and the resistance reading starts changing. The right way to do measure impedance. This is done with a fancy meter, and with an AC voltage and current. This is why we were unable to get good readings on our brake fluid resistance experiment.
- 4) The real information will come when you disect the switches. Paying close attention to the following:
  - a) wear on the bumps (lim, converter, end cap)
  - b) wear between the converter and washer
  - c) Kapton degradation
  - d) wear between the pin and the cup.

That is pretty much all I can think of.

Good luck and let me know what you find.

Regards,  
Bry

---

From: Rahman, Aziz  
Sent: Monday, February 16, 1999 8:30 PM  
To: Degus, Bryan; Blotzhouse, Steven; McGaugh, Andy; Sharpe, Robert; Baker, Gary; Baumgard, Russ  
Subject: PW: Brake Pressure Switch Log

Received second wave of parts from Texas junkyards. All P2VC parts. Most of them with connector attached. Some of them with prop valves & servos. 2 from underhood lines. Analysis will start tomorrow PM. Please let me know if there are any specifics to look at, before we disassemble these. I was thinking of doing some quick voltage drops, insulation resistance checks. Obviously lots of pictures. Any quick way to test these parts for leaks, prior to disassembly?

By the way, Steve R. did mention that the Electrical System folks were looking into using a Brake Pedal Position Sensor as a replacement for the Brake Pressure Switch as a corrective containment action. Have we determined what they use in the 98 Town Car?

---

From: Rahman, Aziz  
Sent: Monday, February 16, 1999 8:32 PM  
To: Paul Peeler (Post); Steve LaPointe (Post); Steve Laffosse (Post); Steve Palermo (Post)

**Epstein, Sally**

---

**From:** Beringhausen, Steven [beringhausen@mail.mc.ti.com]  
**Sent:** Tuesday, February 16, 1999 2:13 PM  
**To:** Rahman, Aziz

Aziz,

One comment on the switch testing, the plan looks good for junk yard parts. I would not run as aggressive a test plan on parts that were in a vehicle fire because we do not know what shape the seal is in from the fire and leakage might disrupt clues. My guess is that this matches the plan.

Steve


TI-NHTSA 012350

**Shade Pressure Switch Test Log**  
 (Initial / Final)



Shade	Test	Location	Test Description	Test Results
1	T	Shade Pressure Switch	Switch tested at ambient temperature.	Switch tested at ambient temperature.
2	T	Shade Pressure Switch	Switch tested at ambient temperature.	Switch tested at ambient temperature.
3	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
4	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
5	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
6	T	Shade Pressure Switch	Switch tested at ambient temperature.	Switch tested at ambient temperature.
7	T	Shade Pressure Switch	Switch tested at ambient temperature.	Switch tested at ambient temperature.
8	T	Shade Pressure Switch	Switch tested at ambient temperature.	Switch tested at ambient temperature.
9	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
10	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
11	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC
12	AVT	Shade Pressure Switch	Switch tested at ambient temperature, 24 VDC	Switch tested at ambient temperature, 24 VDC

TI-NHTSA 012351

No Description	9
Brake Fluid Leak	6
Administrative Parts Return	4
Engagement Troubles	2
Disengagement Troubles	2
ABR Warning Light	1
Other Electrical Accessory Troubles	1



TI-NHTSA 012352



Row	Supply	Curr	Highpost	Cr	Tensional C	Check
2	0.8	0.2	0.6	0.0		
4	1.2	0.7	0.5	0.0		
6	1.4	1.0	0.6	-0.1		
8	1.2	0.7	0.5	0.0		
10	1.3	0.8	0.5	0.0		
12	0.9	0.4	0.5	0.0		
14	0.8	0.4	0.5	0.0		
16	0.7	0.3	0.5	-0.1		
18	1.0	1.5	0.4	0.2		
20	1.4	0.9	0.4	0.1		
22	1.0	0.6	0.4	0.0		
24	1.3	0.9	0.5	-0.1		
26	1.4	1.3	0.0	0.1		
28	0.7	0.8	0.0	-0.1		
30	1.1	0.6	0.5	0.0		
32	0.9	0.4	0.4	0.1		
34	0.4	0.0	0.4	0.0		
36						
38						
40						

II Month ID #	R2.E	II Date Code	YR.E	Car Shdld Date
700-6	32364	2125		
700-8	32377	2045		
700-9	32407	2120		
700-4	32362	2020		
700-3	32400	2016		
700-7	32354	0148		
E	32367	2052		
B	32367	2052		
D	32114	2052		
612-17	50271	2104		
612-21	65045	2036		
612-25	65034	2052		
612-30	65072	2050		
612-18	65035	2056		
612-19	65074	1202		
612-24	65070	1301		
612-26	65050	2056		
612-32	65060	2054		
612-6	65445	2013		
612-8	57044	1547		
612-5	55000	2057		
612-4	55045	2055		



**TEXAS  
INSTRUMENTS**

February 17, 1999

***Facsimile Transmittal***

---

**TO:** Name: **AZIZ RAHMAN - TI EMPLOYEE**  
At Company: **FORD MOTOR COMPANY**  
FAX Number: **313-396-4145**

**FROM:** Charlie Douglas  
TEXAS INSTRUMENTS MS 23-1  
Phone Number: **(508) 236-3657**  
FAX Number: **(508) 236-1598**

Total number of pages (including header page): **15**

**COMMENTS:**

Upon receipt of this fax, please pass on to Aziz Rahman (TI Employee), who is visiting your plant today being Wednesday, February 17, 1999.

Thank you.

TI-NHTSA 012356

TEXAS INSTRUMENTS INCORPORATED • 34 FOREST STREET • ATTLEBORO, MA 02703




Table 2.

PSTA-SR204-CA SPEED CONTROL DE-ACTIVATION SWITCH						1011803	
T.L. PW	77PSL5-8						
RESULTS FROM SHOWER TEST							
HOURS OF EXPOSURE TO DATE:						384	
SWITCH #	ACT	REL	WV DROP	TERM TO TERM (@ 300 PSI)	TERM TO CASE (600 VDC MEGGER)	CONNECTOR STATUS	INGRESS
A1	200	182	4	> 20 MEGA-OHM	84 GIGA-OHM	LATCHED	NONE
A2	242	178	4	-	100 GIGA-OHM	ROCKED	MINOR
B1	238	172	4.2	-	88 GIGA-OHM	LATCHED	NONE
B2	206	166	4.2	-	50 GIGA-OHM	ROCKED	MINOR
C1	208	174	4	-	120 GIGA-OHM	LATCHED	NONE
C2	242	178	8.8	> 20 MEGA-OHM	120 GIGA-OHM	ROCKED	MAJOR
D1	245	179	4.3	> 20 MEGA-OHM	120 GIGA-OHM	LATCHED	NONE
D2	205	186	4.1	> 20 MEGA-OHM	110 GIGA-OHM	ROCKED	MAJOR
E1	257	182	4.1	> 20 MEGA-OHM	110 GIGA-OHM	LATCHED	NONE
E2	200	180	4.2	-	107 GIGA-OHM	ROCKED	MAJOR
F1	253	182	4	-	-	LATCHED	NONE
F2	242	178	4	-	-	ROCKED	MAJOR
--- = INTERMITTENT ACTUATION							

ST 3004

5082363745

02-01 66.4T REW



TI-NHTSA 012358

B15

5082363745


11 QUALITY ASSURANCE

100-17-99 MED 434 PM

F2

YOOK Device #1 observations

- Cup wear more on disc side

SOOK Device #1 observations

- There is almost a continuous ring of wear on both cup side and contact side outer edges
- There is also wear on inside surface

SOOK Device #1

- very little sign of wear on disc side
- small areas of wear begin to show on electrical contact side

SOOK Device #2

- Shows almost a continuous ring of wear on disc side and contact side outer edges
- some wear on inner surface as well

magno  
1000YOOK Device #2

- Shows signs of irregular wear: some wear along edge of contact side, some wear on disc side

SOOK Device #3

- continuous ring of wear along contact side, however snapshots
- wear along ~170° of edge on disc side, then line of wear slightly less than toward center the rest of 190°
- some wear in center of place

wear correlation

77 PS

2/17/

- Failed at 729,008 cycles

- uncrimped

↳ fluid in electrical cavity / contacts (not much, not enough  
  coat everything)

↳ very little wear on bump

↳ small piece of metal filing on inside housing



Wear at

Under microscope



439

555

666






TI-NHTSA 01230




TH-NHTSA 012362




TI-NHTSA 012383



TI-NHTSA 012364




TI-NHTSA 012365





TI-NHTSA 012366




TH-NHTSA 012367




TI-NHTSA 012369




TI-NHTSA 012360



TI-NHTSA 012370



TI-NHTSA 012371



TI-NHTSA 012372

Epstein, Sally

From: Watt, Jim (jwatt@mail.mcii.com)  
Sent: Wednesday, February 17, 1999 10:10 AM  
To: Pechonis, John; McGuirk, Andy; Rahman, Aziz  
Cc: Bartosh, Bob  
Subject: RE: 77PS Loose Metal Part?

25

Ford 77PS return  
History.xls

Andy,

I updated the below 77PS return history file, where the one 77PSL3-3 that was returned from Tokico, 11/20/97, was open circuit due to a distorted arm. Upon repeated testing through the pressure tester, the discrepant switch was culled out, which indicates more of an internal discrepant material handling issue.

<<Ford 77PS return history .XLS>>

Jim Watt, QRA, msgid: jw02; mail station 12-33; page (508)236-1010, no. (0696);  
ph (508) 236-1719;  
fax (508)236-3153

---

From: McGuirk, Andy  
Sent: Wednesday, February 17, 1999 9:29 AM  
To: Pechonis, John; Watt, Jim  
Cc: Bartosh, Bob  
Subject: FW: 77PS Loose Metal Part?

is this contact arm rivet related? any history here?

a

AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST M/S 23-05  
WITTLEROBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
PAGE: (800) 467-3700 PIN 604-2044

---

From: Rahman, Aziz  
Sent: Tuesday, February 16, 1999 8:56 PM  
To: Beringhouse, Steven; Dague, Bryan; Baumann, Russ; McGuirk, Andy; Baker, Gary; Sharpe, Robert; Douglas, Charles  
Subject: 77PS Loose Metal Part?  
Importance: High

Please review attached messages. Jack Faskus is Luxury VC Chief Engineer. Do any of you know what the previous history with a "Loose Metal Part" is all about? Could he be talking about the spring arm potentially separating due to corrosion, mechanical fatigue, thermal effects etc and causing shorts? Please advise on effects of an assumed loose metal part in the switch cavity.

Do we know which switch terminal is hot and which is grounded through the module? Is the stationary terminal hot or the movable?

Thanks  
Aziz.

From: Steve Reimers(SMTP:sreimers@ford.com)  
Sent: Tuesday, February 16, 1999 6:13 PM  
To: jname@ford.com; nmpoint@ford.com; rnewiford.com; slarouch@ford.com; Aziz  
Rahman, Texas  
Subject: (U)

Can you help me get smart regarding the "LOOSE METAL PART" mentioned above?

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS sreimers@ford.com fax 39-03286 />  
\*\*\* Forwarding note from SCOLE1 --DRBN005 02/16/99 18:04 \*\*\*  
To: SREIMERS--DRBN007  
cc: DGOEL --DRBN003

From: Sam L. Cole USAET(UTC -05:00)  
Subject: (U)

THE PREVIOUS CONCERN OF THE "LOOSE METAL PART" WAS MENTIONED IN THE LAST MEETING WITH JACK. HE WILL WANT A FOLLOW UP ON THIS AT THIS FRIDAY'S MEETING. PLEASE GET UP TO SPEED ON THE HISTORY OF THIS CONCERN. IF IT TURNS OUT THAT THIS MAY BE A CAUSE, THEN WE WILL NEED TO KNOW WHEN THE ISSUE WAS IN THE FIELD, WHEN IT WAS FIXED AND HOW MANY ARE OUT THERE TO BE CONCERNED ABOUT. THANKS.

Thank You,  
Sam  
Ext. 21959  
BLDG. 2, 22731 - MD# 1220 - SCOLE1@FORD.COM  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/16/99 16:52 \*\*\*  
To: SCOLE1 --DRBN005 DGOEL --DRBN005

FROM: Steve Reimers USAET(UTC -05:00)  
Subject: (U)

I have the part to show and a take-apart version too. I am not familiar with the previous problem but a loose metal part in the switch cavity is definitely a potential cause of this concern.

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS sreimers@ford.com fax 39-03286 />  
\*\*\* Forwarding note from DB7ANAYR--DRBN007 02/16/99 13:41 \*\*\*  
Subject: AWAY Facility/VM messages  
This note was generated by the AWAY Facility/VM 5799-FTP (c) IBM Corp.  
DO NOT REPLY TO THIS NOTE

AWA110I This mail item is being routed to you from SCOLE1 at DRBN005 on behalf of FPORTER at DRBN007.

To: FPORTER --DRBN007  
cc: THASTERS--DRBN005  
DGOEL --DRBN005 TDONOVAN--DRBN005

From: Sam L. Cole USAET(UTC -05:00)  
Subject: (U)

I UNDERSTAND THAT THERE WILL BE A FOLLOW UP MEETING WITH JACK RASKUS THIS FRIDAY ON THE TOWN CAR INVESTIGATION. I MET WITH JACK TODAY FOR A 1 ON 1, AND HE REQUESTED SOME SPECIFIC INFO. AT FRIDAYS MEETING, PLEASE BRING A SAMPLE SWITCH TO SHOW JACK.

ALSO, HE IS INTERESTED IN KNOWING OUR PROGRESS AND INVESTIGATING IF THE PREVIOUS PROBLEM WITH THE INTERNAL COMPONENTS BREAKING LOOSE IS A

POTENTIAL CAUSE OF THIS CONCERN. PLEASE BE PREPARED TO DISCUSS THIS ON  
FRIDAY. THANKS.

Thank You,  
Sam  
Ext. 21959  
BLDG. 2, 22J31 - MD# 1220 - SCOLE1@FORD.COM

TT-NHTSA 012375

Ford Motor Company  
77PS Style  
Pressure Switches

# Events - by year of return						
Root Cause Analysis(Corrective Action Reports)						
	1994	1995	1996	1997	1998	Total Events
Contaminated Terminals	0	0	0	0	1	1
Continuity Anomaly(Distorted contact arm assembly)	1	0	0	1	0	2
Wrong Parts Shipped	0	0	3	3	0	6
Damaged Threads/ Hesport	0	5	1	0	0	6
Noisy Switch	0	0	1	0	0	1
Cracked Bases	0	0	1	0	0	1
Vacuum Dependency	0	1	0	0	0	1
Device Leak	0	1	0	0	0	1
Incorrect Code	0	1	0	0	0	1
Low Rel Cal(Contam on Stationary Contact Surface)	0	1	0	0	0	1
(Total)	1	9	6	4	1	
Root Causes Analysis(Return Device Analysis)						
	1994	1995	1996	1997	1998	
Failure Due To Customer	n/a	n/a	0	0	0	0
Contaminated Terminals	n/a	n/a	0	1	0	1
Trouble Not Found	n/a	n/a	0	1	3	4
Damaged Base	n/a	n/a	0	1	0	1
(Total)	n/a	n/a	0	3	3	
(n/a= not available)						
Total 1994 Ford Motor (77PS) customer returns: 1	Total 1997 Ford Motor (77PS) customer returns: 7					
Total 1995 Ford Motor (77PS) customer returns: 9	Total 1998 Ford Motor (77PS) customer returns: 4					
Total 1996 Ford Motor (77PS) year to date customer returns: 6	Total 1999 Ford Motor (77PS) customer returns year to date: none					

Currey, Pat

---

**From:** McGuirk, Andy [a-mcguirk@email.mc.ti.com]  
**Sent:** Wednesday, February 17, 1999 2:44 PM  
**To:** Baker, Gary; Baumann, Russ; Beringhouse, Steven; Dague, Bryan; Hopkins, AL  
**Cc:** Douglas, Charles; Rahman, Aziz; Rowland, Thomas; Sharpe, Robert; Sullivan, Martha  
**Subject:** 77PS UPDATE

**When:** Thursday, February 18, 1999, 2:00 PM - 3:00 PM, (GMT-05:00) Eastern Time (US & Canada)  
**Where:** 23A

\*\*\*\*\*

I WANT TO REVIEW FORD'S ANALYSIS SPREADSHEET (ALL, LED BY STEVE WITH THEORIES), OUR UPDATED CAUSE AND EFFECT DIAGRAM (BRYAN), OUR 'SCIENCE FAIR' EXPERIMENTS RESULTS (STEVE AND BRYAN), AND REVIEW A PROPOSAL FOR OUR RESPONSE TO FORD'S POSSIBLE QUESTION POSED FROM AZIZ ABOUT TI POSITION (ANDY).

ALSO, I WANT TO UNDERSTAND FORD'S DATA ABOUT ABS (C/O AZIZ FROM TEVES) AND PROP VALVE PRESSURE TRACES, AS WELL AS DATA FROM DOM C/O FORD ABOUT BRAKE FLUID AS IT RELATES TO FIRES AS WELL AS KAPTON (C/O AZIZ FROM FORD).

FINALLY, WE SHOULD UNDERSTAND BRAKE SWITCH AND KAPTON WEAR/OUT WITH ANOTHER FORD PLATFORM...STEVE DID WE COLLECT ANY SAMPLES FROM SIMILAR AGE VEHICLES?

WE SHOULD ALSO DISCUSS THE POTENTIAL BRAKE PEDAL POSITION 'SOLUTION' (CHARLIE AND ROB...BRIEF GARY SO HE CAN DELIVER) AND BE PREPARED TO HELP FORD UNDERSTAND THEIR RISKS IN THAT PATH.

A

**McGuirk, Andy**

---

**To:** Sullivan, Martha; Rowland, Thomas; Baumann, Russ; Baker, Gary;  
**Cc:** Seringhouse, Steven; Pechonis, John; Rahman, Aziz; Bartosh, Bob  
**Subject:** Ford overview.... 2018 plans Update

attorney client privileged communication

I have an appointment to talk to Steve Reimers who is acting for Fred Porter at 2:45 Thursday today.

I want to lead us thru discussions:

**REVIEW FORD'S ANALYSIS SPREADSHEET (ALL, LED BY STEVE WITH THEORIES),**

task?, priority ?

**OUR UPDATED CAUSE AND EFFECT DIAGRAM (BRYAN).**

ABS?

**OUR 'SCIENCE FAIR' EXPERIMENTS RESULTS(STEVE AND BRYAN),**

**REVIEW A PROPOSAL FOR OUR RESPONSE TO FORD'S POSSIBLE QUESTION POSED FROM AZIZ ABOUT TI POSITION (ANDY). no results**

**UNDERSTAND FORD'S DATA ABOUT ABS (C/O AZIZ FROM TEVES) AND PROP VALVE PRESSURE TRACES.  
...do we do at TI?**

**DATA FROM DOW C/O FORD ABOUT BRAKE FLUID AS IT RELATED TO FIRES no results**

WELL AS KAPTON (C/O AZIZ FROM FORD). no results

UNDERSTAND BRAKE SWITCH AND KAPTON WEAROUT WITH ANOTHER FORD PLATFORM.. STEVE DID WE COLLECT ANY SAMPLES FROM SIMILAR AGE VEHICLES? no results

WE SHOULD ALSO DISCUSS THE POTENTIAL BRAKE PEDAL POSITION 'SOLUTION' TO HELP FORD UNDERSTAND THEIR RISKS IN THAT PATH.

AUTOMOTIVE SENSORS AND CONTROLS DATA MANAGER  
34. FOREST ST A/B 22-68  
AUSTIN, TX 78701  
TEL : (512) 454-3768  
FAX : (512) 454-3765  
PAGE: (800) 467-3700 FAX 804-2544

**From:** McGuirk, Andy  
**Sent:** Thursday, February 18, 1998 9:52 AM  
**To:** Sullivan, Martha; Rowland, Thomas; Baumann, Russ; Baker, Gary  
**Cc:** Beringhausen, Steven; Pechonka, John; Rahman, Aziz; Barbash, Bob  
**Subject:** Ford overview... 2/18 'status' Update

attorney client privileged communication

Ford has seen switch 'wear out' in several samples where brake fluid is believed to have leaked into the switch cavity (total of 7 switches 'analyzed' to 'complete scientific conclusions' from 1 P/S thermal event, 3 underhood thermal events, 2 cruise loops and 1 reference). There are 24 switches awaiting analysis at Ford, and in fact a faster paced analysis scheme is under review at Ford in order to work thru this backlog. (Steve, do we recommend this approach?..lets respond ASAP)

Ford has concluded the Town Car underhood fire and thermal event and thermal anomaly history (my 92? and my 93?) is comprised of:  
149 total events...broken down by Ford as follows

127 unknown causes

17 potential other causes

8 pressure switch causes.....or said a different way, Ford might say that P/S is the number one known cause

another cut at this.....broken down by Ford

105 events status unknown

38 events with engine off

8 events with engine on..... or said a different way, Ford might say engine on/off has little effect.....

Ford's executive team has established a plan to achieve root cause phase by March 3rd.

We believe Ford has obtained a two-month window from NHTSA.... April 14th 'public disclosure' plan

Ford's executive team seems to be frustrated by the inability to get to root cause....to turn on/off by the 'science fair' type testing being done at both TI and Ford to create the issue

We have presented the concept of de-power of the P/S as a containment mechanism....the Ford 1st line people do not seem to be moving toward this...more Friday

We have also presented the concept of the possible application of the AFT as a containment mechanism...little movement here too.

Ford's current thought seems to be that the preferred containment solution might be to replace the P/S with a Brake Pedal position sensor as is on-board the '99 Town Car. Looks like first line folks are focused here....seems like Ford 1st line guys do not want to 'tap' into brake lines in the future?

Ford continues to move slowly... no Dow or Dupont or Teves involvement 'results' yet...seems like they're still fiddling to get ready

Ford's Fred Porter (my primary contact) is on vacation and I am making plans to connect with his 'acces' either late today (he's out?) or first tomorrow to discuss and direct some of these points. I will publish a 'plan' memo early afternoon today.

**AUTOMOTIVE ADVISORS AND CONTROLS COR. INC.**  
26 FOREST ST #2 23-24  
ATTLEBORO, MA 02703  
TEL : (508) 226-3288  
FAX : (508) 226-3748  
E-Mail: 18801 461-3700 714 401-2044

---

**From:** Rahman, Aziz  
**Sent:** Wednesday, February 17, 1999 6:16 PM  
**To:** Beringhausen, Steven; Dague, Bryan; McGuirk, Andy; Baumann, Russ; Sharpe, Robert  
**Subject:** 2/17 Update

Main event: 2PM core team meeting. Highlights:

- Manager Len Brown agitated that Dow has not shown up yet. Will probably get them on board tomorrow or Friday.
- Exco. meeting at 4.pm Friday. TI not invited. Will present test plan ( copy with Steve B. ).
- Ford team in DC today at NHTSA, asking for two months for public action.
- People surprised that on-vehicle characterization has not yet occurred. Leads provided on expediting this.
- Increasing tempo on getting more parts back for analysis.
- Re-emphasized need to study warranty data more closely for trending, and specific causes.
- Increasing speculation that pure heat is not sufficient to ignite. Need spark.
- Will present brake pedal position sensor to assess as possible containment.

Two tests conducted today at AVT lab:

- Passed about 54 Amps at about 1V, through switch terminals, no fluid. Temp in connector area increased to about 182 F before system went open circuit. Dissection revealed spring arm deformed and twisted away from stationary. Will have pictures tomorrow.
- Passed about 60 Amps at about 1V through switch terminals, with switch base filled with approx 60% Brake Fluid, 40% salt water. Temp in connector area increased to about 270 F and stayed there. No smoke or ignition. Dissection revealed spring arm deformed. Pictures tomorrow.

- Will set up calibration station in Central Lab tomorrow.

- Will be returning to MA Friday 2pm flight. Later flights not available because of vacation week. Per Steve B.'s input, will plan to return next week.

Regards  
Aziz.

## Evaluation Process

### Take Pressure switch / Harness

Date  
Code


Test Description	Spec/Value	Comments

1 Fouch

If not correct conduct X-Ray to determine fit-up between  
base lip and red seal.

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

--

Evaluation Process  
Brake Pressure switch / Harness

port



Do not perform on parts from underhood fires, as may disturb diaphragm/other condition  
Do not perform on parts from underhood fires, as may disturb diaphragm/other condition  
Do not perform on parts from underhood fires, as may disturb diaphragm/other condition

the analysis surface.

loss of contamination during cutting of crimp ring.

est.

LANDUCH

lographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate.

FOR Selected Samples ONLY.

(Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.

10.

1. Particularly look for evidence of corrosion or arcing  
debris and on the indented ring that lines up with interior wall of the switch cavity

debris to try to examine the underlying metal surface.  
Recent surfaces revealed by removal of cup.

Steve Hollister  
AVT Controls C/E System Applications  
19-02266 MACHINES [machines.com](http://machines.com)  
14\* Recording start from 20000001 --000007 02/18/99 19:48 (P)  
To: SPACERED-COMMERCE  
ccc: (PMR224) -m00007

FROM: John Jones  
Subject: (S)Freestyle Test

Building # 30041  
mail drop: 5001  
Box 11-02266

WOMX(WFC -05,00)

None.

I got your note and will be an occasional converser through Wednesday. Here's the info.

The more I think about this, the more I think SC calibration may be the answer.

I am not sure of the order of the valves connected and thus can't determine the low-frequency amplitude of the signals. But the above order is to instrument the 8-220 bar and sample at 1 km or more.

Since I'm not sure of where the pressure switch is located, I have connected the SC pressure to nodes and nodes I do know. The output node for the 8-220 bar would be in the connection between the SCC and the pop valve, which is where I think it is.

This is the low-frequency component of the signal, I'll talk about the high-frequency component further down.

SC - 800 Node

maximum pressure = -175 bar  
achieved by pressing maximum pressure. Only covering engine and slightly closed throttle thus operating at the point we had at your test. I don't remember this number very well. It might be as low as -120 or as high as 200. It also depends on your leg strength. This type of pressure is VARY HIGH at this node. For this car, the driver will typically apply 120 bar and very rarely exceed 18 bar.

HCC - 80000 Node

Standing still - same as SC pressure - see above.

800 Maximum = -110 bar

This is achieved by bracing to one and performing on the stop, you may find that you are pedal effort limited, not limited by ABS control. It's pretty hard to get this high of pressure in this mode.

SC Maximum = -190 bar  
This is a good candidate. On this vehicle because the SCC had no pump through the pop valve to its own torque-sensing control, the pressures coming out of the SCC got very high. The pressure relief valve on the pump was disconnected by the people which would be developing, not the SCC. The peak pressures which would be developed were not limited - put another way, because the pressure at the rear wheels had to restrain the active powertrain (or wheel intervention) and path through a pop valve, it was often possible to drive through the SC - the engine would overdrive the brakes. even though very high pressures were being generated at the SCC. The rules during SC activation in these applications was very dependent upon the pressure relief valve opening point. So the pressure relief valve was changed a few times over the years as performance was sacrificed for ABS. Also the tolerance on the pressure relief valves was fairly large - a total of 40 bar, at that time I believe. The pressure relief valve pressure ranges from 20 to 100 bar depending on part-to-part variation and the design generation that was agreed upon.

You can achieve this easier by putting the rear wheels off the ground and putting the car in drive. Get into the throttle hard, but not so hard that you drive out of first gear or faster than -10 mph. If you maintain this for a while, the thermal would be greatest the rear linkage will disable the traction control. You will then need to wait for them to cool, before the traction will be enabled. You can dramatically reduce the cooling time by applying sufficient braking at about 40 mph.

Typical drivers can rapidly get high pressure in this mode.

SCC WBC - 1000 WBC 3000

Max Maximum Pressure = -19 bar

Used to GCR and perform on 100 step at medium pedal effort.

SCC Maximum Pressure = -19 bar

This pressure level is strongly dependent upon the pressure relief valve level - see above.

Standing still.

Same as HCC Maximum Pressure

High Frequency Output

The high frequency doesn't last too long. If you are out in the air traction control there is effectively no high frequency output - the pressure is constant at -19 bar. This is basically limited by various pressure relief valves and hydraulic damping in the ABS network.

High Frequency Output has 3 modes.  
During HCC/WBC around the pressure is changed in quick steps. Typically it will increase by -10 bar in a few milliseconds, and this type of change occurs about every 10ms. The pressure will decrease about 10 bar every 200 ms. There are quite a lot of variation in these numbers, but these are pretty typical. Potentially the values are assigned once for ABS, and "increase" and "decrease" for SC activation.

High Frequency Output can be short term.

This is a secondary effect from the control. Essentially it is more slight at the center of the SCC. It is damped and dampened the further you go from the SCC. The short step is generated from the cylinder pulsing of the pump as well as the piston which is pressure when a standard value is swapped open or close.

The amplitude of this can be really big - I haven't tested at it in this generation only for a few years, but I think it's about 20 bar peak-peak right at the SCC. It will fall off as you move further away from the SCC.

The frequency is pretty fast and I think some frequencies are above the 1 Hz level. but you can get a very good feel of the characteristics by applying +/- 10bar.

Report,

John Jones

1 Gav \* 106 kPa = 14,60 psj

Ford ES-F24c-9FT24-AA Impulse Test S510 ~ 0-1450 psj/100 Gav/10<sup>4</sup> kPa



Continental  
Automotive Systems  
Business Unit

1 800 248 8645

Telefax


To Joe Evans From Brian Hildebrand  
Company Dept.  
Date Fax No.  
Phone No.  
Date 3/5/99 Paper holding invetation

Typical ABS Rear Axle

Pressure traces.

- Dry asphalt
- SNOW
- ice

Not for  
MY 92 & 93,  
but close  
for



C802 C173

TRANSACTIONS

03 04 99 14 55

1 800 248 8645

Fax 01

1 800 248 8645

1 800 248 8645

Page 32

PRODUCED BY FORD

PRODUCED BY FORD

### 33.11 Brake limiting device and anti-slide systems

As the brakes are initially applied, a minuscule degree of slip occurs between the tyres and road, but the slip as well as the brake torque progressively increase with the load applied to the brake pedal, until the wheels actually lock and the tyres slide along the road. During the last phase of brake application the rate of angular deceleration of the wheels becomes considerably greater than the linear rate of deceleration of the vehicle without any wheel sliding.


It is well known that the coefficient of friction between the tyres and the road is reduced with the onset of slipping, which is therefore to be avoided if the shortest possible braking distance is to be achieved.

The point at which wheel-lock will occur is dependent upon the vertical forces between the tyres and the road. Therefore, application of the brakes transfers, in effect, some of the weight from the rear wheels to the front ones, so during hard braking the rear wheels will tend to slip earlier than those at the front. A vehicle having a static front : rear weight distribution of 60 : 40 would generally have adequate adhesion for all its brakes to perform effectively when its weight distribution ratio coincides with a braking ratio of about 70 : 30. At higher decelerations this level may rise to 80 : 20, so if the rear wheels are not progressively relieved of some of the braking effort they are liable to slide. Sliding rear wheels have no capacity for exerting any additional grip on the road to produce any stabilizing force. Consequently, the vehicle becomes unstable when braked hard and, given the slightest lateral disturbance, its rear end may slide sideways, causing the vehicle to swing round through as much as 180° or more.

To prevent this undesirable condition from arising, a brake pressure apportioning valve can be fitted in the hydraulic system. Its function is to reduce the control pressure applied to the rear brakes relative to that to the front ones and, preferably, it should cater for both the fully laden and driver-only conditions. A whole range of such valves is produced by Lucas Girling, the principles of which are explained later.

In the mid-twenties-sixties it became common practice to insert a simple pressure-limiting valve in the line to the rear brakes only. This allowed the applied pressure to be transmitted up to a predetermined level to both front and rear brakes, after which the pressure in the line to the rear brakes was either held constant or its rate of increase was reduced. However, this pressure characteristic was constant regardless of the load carried, so the rear brakes were significantly under-utilized when the vehicle was fully laden.

Hydraulic pressure from the master cylinder is applied at A, in Fig. 33.18, and transmitted through the axial hole in the centre of the shouldered piston and so through the metering valve D, whence it goes through the outlet B to the rear brakes. At the same time it acts upon the crown of the piston. Because the effective area of the crown is greater than that of the shoulder on the other side of the piston, it progressively pushes the piston back, compressing the spring C, until the metering valve is seated. Then, any further increase acting on the smaller diameter of the shoulder of the piston pushes it to the right as viewed in the illustration, again opening the metering valve. Thus, the pressure applied through outlet B to the rear brakes continues to increase, as shown in Fig. 33.23(a), the front : rear pressure ratio at the brakes being predetermined



A Front master cylinder  
B To rear brakes  
C Spring  
D Metering valve

Fig. 33.18 Diagram of a pressure-limiting valve assembly

by the ratio of the smaller and larger effective areas of the shouldered piston and the force exerted by the internal spring.

# The Motor Vehicle

## Twelfth Edition

### K. NEWTON

MC, BSc, ACOL, AMIEE, MIMechE  
*Lecturer Professor, Mechanical and Electrical Engineering Department,  
The Royal Military College of Science*

### W. STEEDS

CBE, MA, ACOL, FIMechE  
*Lecturer Professor of Mechanical Engineering,  
The Royal Military College of Science*

### T. K. GARRETT

CEng, FIMechE, MIAE  
*Associate Editor of Automobile Engineer*



Published on behalf of:  
Society of Automotive Engineers, Inc.  
400 Commonwealth Drive  
Warrendale, PA 15096-0001  
Twelfth edition 1996

# IN-SERVICE BRAKE PERFORMANCE TEST PROCEDURE

## PASSENGER-CAR AND LIGHT-DUTY TRUCK

### —SAE J301 MAR87

### SAE Recommended Practice

SAE of Brake Committee approved April 1974. Reaffirmed by the SAE Brake Standards Committee 7—Road Test Procedure May 1986 and March 1987.

**Foreword**—This Reaffirmed Document has been changed only to reflect the new SAE Technical Standards Board Format.

**1. Scope**—This SAE Recommended Practice establishes a uniform procedure for testing the brake systems (service and parking) of all passenger cars, light-duty trucks, and multipurpose passenger vehicles up to and including 4,500 kg (10,000 lb) GVWR.

**1.1 Purpose**—The purpose of this test code is to evaluate brake system performance of vehicles in service for compliance with regulations.

1.1.1 The test code is expected to be utilized as a basis for a brake evaluation conducted by State or Federal officials engaged in highway safety programs.

1.1.2 The primary consideration is that this test requires a minimum of instrumentation, time, driver skill, and cost to conduct.

**2. References**—There are no referenced publications specified herein.

**3. Instrumentation**

3.1 Decelerometer (U-tube or equivalent)

3.2 Pedal force indicator

3.3 Pedal travel indicator

3.4 Speedometer

3.5 Stop watch

**4. Installation Details**

4.1 Install and adjust decelerometer on vehicle.

4.2 Install pedal force and travel indicator to manufacturer's procedure and calibrate.

4.3 Brake system is to be tested as received without any changes or adjustments.

**5. Vehicle Test Weight**

5.1 The vehicle is to be tested at the "as received" load excluding passengers. Official observer permissible.

5.2 The load may be repositioned or removed if a hazardous condition exists.

**6. Test Facility**

6.1 Selected test area shall be a paved 3.7 m (12 ft) lane of adequate length, dry, clean, straight, essentially level, and not heavily traveled.

6.2 Provide a 15% grade of sufficient length and solid resistance to support the entire test vehicle.

**7. Test Procedure**

7.1 **Test Notes**—(To be recorded on data sheet—Figure 1.)

7.1.1 Vehicle make, model name, year, and serial number.

7.1.2 Vehicle odometer reading.

7.1.3 Condition of road surface.

7.1.4 Type of brake (disc, drum) (power, manual).

7.1.5 Brake warning lamp operation.

7.1.6 Brake stop lamp operation.

7.1.7 Any change in pedal height when held for 10 s at 29 N (20 lb) pedal force.

7.1.8 Any change in pedal height when held for 10 s at 667 N (150 lb) pedal force and if pedal reaches its limit of travel.

7.1.9 If parking brake application will lock the wheels with the vehicle on the 15% grade.

7.1.10 Any unusual brake or vehicle noises.

7.1.11 Any unusual brake action such as pulsing, roughness, etc.

7.1.12 If wheel slide occurred during the brake tests and designate which wheel.

7.1.13 Maximum sustained deceleration attained.

7.1.14 Maximum pedal force required.

**7.2 Static Checks**

7.2.1 Verify warning lamp operation as indicated by vehicle manufacturer.

7.2.2 If vehicle is so equipped, observe brake warning lamp indicator during stops.

7.2.3 With vehicle stopped and the engine running, apply 29 N (20 lb) force to the brake pedal and hold for 10 s.

7.2.4 Note if there is any change in pedal height during the 10 s.

7.2.5 With vehicle stopped and the engine running, apply 667 N (150 lb) force to the brake pedal and hold for 10 s.

7.2.6 Note if there is any change in pedal height during the 10 s or if the pedal reaches the limit of its travel.

**7.3 Parking Brake**

7.3.1 Drive vehicle up a 15% grade, apply the service brakes to stop, and hold the vehicle.

7.3.2 Place transmission selector in neutral.

7.3.3 Apply the parking brakes up to the regulatory load, but do not exceed 29 N (20 lb) force for a foot-operated mechanism or 443 N (100 lb) for a hand-operated mechanism. Remove foot or hand from the parking brake apply mechanism.

7.3.4 Release the service brakes.

7.3.5 Observe if wheels remain locked.

7.4 Preliminary Brake Test to Appointed Driver with Vehicle—(To be conducted within 3.7 m [12 ft] wide test lane):

**7.4.1 Brakes Engaged—1.**

7.4.1.1 **Initial Speed**—48 to 16 km/h (30 to 10 mph).

7.4.1.2 **Brake Deceleration (Sustained)**—3 m/s<sup>2</sup> (10 ft/s<sup>2</sup>).

7.4.1.3 Moderate apply rate (do not exceed 667 N [150 lb]).

7.4.1.4 Alert test if wheel slide occurs and discontinues test.

**7.4.2 Stays Required—1.**

7.4.2.1 **Initial Speed**—64 to 32 km/h (40 to 20 mph).

7.4.2.2 **Brake Deceleration (Sustained)**—3 m/s<sup>2</sup> (10 ft/s<sup>2</sup>).

7.4.2.3 Moderate apply rate (do not exceed 667 N [150 lb]).

7.4.2.4 Alert test if wheel slide occurs and discontinues test.

7.5 Highway Stopping Test—(To be conducted within the 3.7 m [12 ft] wide test lane):

**7.5.1 Stays Required—1.**

7.5.1.1 **Initial Speed**—80 to 97 km/h (50 to 60 mph) or maximum practical speed attainable while the test area is less than 80 km/h (50 mph).

7.5.1.2 **Desired Deceleration Attainable**—Not to exceed 5 m/s<sup>2</sup> (20 ft/s<sup>2</sup>).

7.5.1.3 **Pedal Force**—667 N (150 lb) maximum.

7.5.1.4 **Brake Apply Rate**—Maximum rate possible when maintaining deceleration constant (not a spiral) up to 5 m/s<sup>2</sup> (20 ft/s<sup>2</sup>).

**7.6 Repeat Testing**

7.6.1 If the vehicle brake system exhibits marginal performance with respect to the regulatory requirements, tests for 7.4 or 7.5 may be repeated.

8. Report Form—General Data and Report Form, Figure 1.

**LIGHT TRUCK**

## CORPORATE PRODUCT ACCEPTANCE SPECIFICATIONS

Version: Initial

**CONFIDENTIAL**

PAGE NO. 00-00-C-3

Dates: 16 Dec 95

### 6. ENVIRONMENTAL — (Reserved)

### 7. DURABILITY

7.1 ACCELERATED DURABILITY: All brake system components must complete accelerated durability without failure, becoming loosened or dislodged. Replacement of worn linings or pads is permissible during this test.

7.2 SPACE TEST — See USA and EAO Level Market Requirements.

#### 7.3 BRAKE WEAR TEST:

7.3.1 Vehicle brake wear rate is to be measured using the Customer Certified Cost of Ownership Checks or

specifications, and the life objective will be defined in the Program Objectives.

7.3.2 Brake wear measurement is to be in accordance with GMPP 94-00-H-601 or equivalent. The metal life of the lining material is considered consumed if the measured thickness falls below the following:

- 0.2 mm above and below load where steel or aluminum rivets are used to fix the linings.
- 0.0 mm i.e., level with disc, loads where copper or brass rivets are used to fix the linings.
- 1.0 mm from shoe platform for solid or bonded linings.
- 1.5 mm from backplate for disc pads.

**LIGHT TRUCK**

## LOCAL MARKET REQUIREMENTS — USA

Version: Initial

**CONFIDENTIAL**

PAGE NO. 00-00-C-4B-A-1

Dates: 16 Dec 95

### BRAKE

#### 8.1 TRAILER TOWING:

8.1.1 Service Brakes: The vehicle's service braking system is capable of stopping the vehicle/trailer combination without exceeding the following stopping distances:

Rated Speed: 90km/h	GCM of 4536 kg	GCM Over 4536 kg
at 20%	4m	8m
64 km/h	6m	10m
56 km/h	14m	17m

The tests are to be conducted on a level, dry, concrete surface as described in GMPP F4-14 or equivalent under the following conditions:

- Stops are to be made with master brake system. Of any type.
- Service brake pedal force must not exceed 60 N static during stop.
- Initial brake temperature is to be 45°C to 120°C initial stop.
- Ambient temperature between 0°C and 30°C required for testing.
- Brake linings are to be installed and in good serviceable condition before test.
- Vehicle/trailer combination must meet handling requirements specified in Section GMPPT (S) for trailer stops.
- heavier GCM loading requirement for vehicle/trailer combination must be sufficient for vehicle/trailer being tested.

— Vehicle is to be loaded to rated GVM, including trailer tongue weight in vehicle weight.

— All stops are to be made with vehicle in gear.

7.3.2 SPARE TEST: The vehicle must be capable of completing 7 cycles of spare stops per GMPP F4-12. The 7 cycles are to be made with vehicle at GVM. The following requirements must be met at the completion of the 7 cycles:

#### 7.3.3 Post Brake Stop Check Checks:

- The brake pedal shall not go to the floor.
- The brake master cylinder fluid shall not be diminished.
- There shall be no wheel lock-up below 3.44 m/sec<sup>2</sup> and the vehicle still moves in a 3.7 m/sec.

#### 7.3.4 Post Check Stop Inspection:

- Each wheel must be capable of being rotated freely by hand power.
- The linings shall not show any significant cracking or lossage relative to the attaching plate.
- The linings shall not show any significant shift relative to the attaching plate.
- There shall be no significant loss of torque at any foundation brake attachment.
- There shall be no significant permanent deformation of any brake component.

TI-NHTSA 012350

Produced by Ford

CORPORATE VEHICLE REQUIREMENTS MANUAL

ENGINEERING AND MANUFACTURING STAFF

Produced by Ford

\*Currently being considered for incorporation as a worldwide requirement.

CORPORATE VEHICLE REQUIREMENTS MANUAL

ENGINEERING AND MANUFACTURING STAFF

## CORPORATE PRODUCT ACCEPTANCE SPECIFICATIONS

CONFIDENTIAL

version: Beta

PAGE NO. 04.00-C-1

DATE: 18/7 Sep 16

## BRAKE

## SYSTEM DESCRIPTION AND CONTENT

This specification covers the requirements of the vehicle Brake System incorporating the following Subsystems:

- 04.01 Front Drum Brake
- 04.02 Rear Drum Brake
- 04.03 Front Disc Brake
- 04.04 Rear Disc Brake
- 04.05 Parking Brake and Actuation
- 04.06 Hydraulic Brake Actuation
- 04.07 Power Brake
- 04.08 Air Brakes
- 04.09 Solid Control
- 04.10 Auxiliary Brakes

In addition to the requirements listed in this specification or in the Subsystems specifications, the Brake System shall comply with all the applicable requirements listed in the Complete Vehicle System (CVS) and all applicable regulatory requirements listed in the specific vehicle Program Feature Description document.

## 1. GENERAL

1.1 JURY EVALUATION: Under all conditions of controlled braking on level asphalt surfaces, the acceptability of the following brake characteristics is to be determined by jury evaluation:

1.1.1 NVH: There shall be no objectionable brake roughness, judder, noise, vehicle derivative or squeak.

1.1.2 Steering Function: The located front wheels must, to a noticeable extent, affect the steering function.

1.1.3 Pedal Feel: Acceptable level for pedal feel is a jury evaluation rating of 7 minimum.粗糙度 is to take place with vehicle at curb mass and at GVM. Steps should be made from various speeds including a 120 km/h deceleration.

1.2 BRAKE DRUM AND DISC LIFE OBJECTIVES: Brake drum and disc thickness, including cracking, shall be evaluated on a Cox. of Depreciation Chart or equivalent, and the life objectives will be defined in the program objectives.

1.3 VEHICLE SYSTEM FAILURE: The Brake System shall provide at least secondary brake performance in the event of a failure in the Suspension, Steering, Chassis or Body Systems, provided the failure does not render the vehicle uncontrollable.

## 2. PACKAGE

2.1 PEDAL TRAVEL: The available pedal travel must be sufficient to allow movement of the piston within the master cylinder with a minimum overshoot of 12 mm (as measured at the pedal and conversion) between the pedal assembly and the shoe/drum/pad, bearing, lever, lever or other travel limiting components. The minimum overshoot requirement must prevail when the master, master cylinder, master and master valve travel and normal body design dimensions are considered. Camper, nose and insulation are defined as travel limiting dimensions at their compressed height. Overshoot is defined as the distance the top face of the pedal pad could move if the pedal assembly were not constrained by the travel limit or master cylinder. Overshoot is the chordal length described by the path connecting the center of the master cylinder and the top center of the pedal pad. The total travel overshoot is the sum of the master cylinder and the pedal pad overshoots, added above, during power-off mode.

2.2 PEDAL COORDINATE: It must be possible to apply 700 N effort to the foot pedal (Floorboard Mounted) and 600 N to the handbrake (Parking Brake) with the controls at their applied position. It must also be possible to apply 700 N effort to the foot brake pedal at the extreme of travel resulting from a failed hydraulic brake line.

## 3. APPEARANCE — (Reserved)

## 4. SERVICE AND ASSEMBLY

4.1 DRUM AND DISC RECONDITIONING: The disc/drum and foundation brake design must be such that all performance requirements are achieved with:

4.1.1 Disc Thickness: Disc thickness reduced by 0.75 mm from new by in-service machining and/or wear.

4.1.2 Drum Diameter: Drum diameter increased by 1 mm from new by in-service machining and/or wear.

## 5. PERFORMANCE

## 5.1 GENERAL

5.1.1 Lining Test Condition: See EAO Level 3a Requirements.

5.1.2 Line Contact: During all performance type vehicle deceleration and break-in any part of the wheel or hub projecting beyond a 3.7 m wide line.

## CORPORATE PRODUCT ACCEPTANCE SPECIFICATIONS

CONFIDENTIAL

version: Beta

PAGE NO. 04.00-C-2

DATE: 18 Jun 16

## 6.2 PERFORMANCE EVALUATION

6.2.1 Mountain Brake Test: All vehicles must complete the Mountain Brake Test for Light Trucks, ETP 74-114 or equivalent with a projected lining service life of 100 cycles for a GVWR equal to or less than 2268 kg with a proportionally reduced projected life requirement based upon the code of the GMVRS, or a GMVRS greater than 2268 kg and less than 4236 kg. For vehicles with a GMVRS equal to or greater than 4236 kg, the minimum projected lining service life must be at least 20 cycles.

6.2.2 City Traffic Wear Test: All vehicles must be capable of completing the City Traffic Wear Test, P3-304, or equivalent, with a minimum projected lining service life of 16 100 km.

6.2.3 Master Cylinder Pressure: Throughout the life cycle portion of the above tests, the master cylinder piston must not bottom out in either primary or secondary cylinder.

6.2.4 STATIC PERFORMANCE: The service brake system requirements must be capable of withstanding a static load of 1700 N without any permanent deformation when the load is applied perpendicular to the center of the pedal pad.

6.2.5 COLD BRAKING: The brake is considered to be cold when the temperature of the disc or drum is below 10°C. Additional service brake tests shall be conducted with disc/drum below 40°C and below 5°C to evaluate the effect of low ambient.

6.2.6 HEAT BRAKING: See EAO Level Master Requirements.

## 6.3 HET BRAKES

6.3.1 Recovery from Pedal: The recovery pressure defined in EATM 04.00-20-02 or equivalent must be exerted on following EEC/11/320 or equivalent load test time detailed in EATM 04.00-10-20 or equivalent. The last recovery step of this pressure must be within +25% of the maximum achieved with cold brakes.

6.3.2 Standard Axle Brake Test: During test, ETP 04.00-21-301 or equivalent, the following requirements must be satisfied:

- The pedal effort must not exceed 700 N.
- The pedal travel must not be exhausted.
- The wear of cable material of pads or linings must not exceed 30% after 100 stops.

TABLE 3.4. CUMULATIVE PERCENT RIGHT FOOT  
FORCE DISTRIBUTION: 276 MALE  
DRIVERS

Pressure (lbs)	STANDARD MOTIVATION		INDUCED MOTIVATION	
	Frequency	Cumulative Percent	Frequency	Cumulative Percent
281+	9	100.00	32	100.00
261-280	14	96.74	21	88.41
241-260	2	91.67	11	80.30
221-240	13	90.94	27	76.81
201-220	27	86.23	33	67.03
181-200	31	74.45	44	55.43
161-180	28	68.22	29	39.49
141-160	36	53.87	32	28.99
121-140	46	42.03	26	17.39
101-120	27	25.34	9	7.97
81-100	21	15.88	5	4.71
61-80	16	7.97	6	2.30
41-60	4	2.17	1	.73
21-40	3	.72	1	.34
	276		276	

50th percentile=152.7

5th percentile= 70.3

50th percentile=193.7

5th percentile=102.3

TABLE 3.5. CUMULATIVE PERCENT RIGHT FOOT  
FORCE DISTRIBUTION: 323 MALE  
DRIVERS

Pressure (lbs)	STANDARD MOTIVATION		INDUCED MOTIVATION	
	Frequency	Cumulative Percent	Frequency	Cumulative Percent
281+	160	100.00	221	100.00
261-280	22	50.46	25	31.30
241-260	25	43.55	16	23.84
221-240	27	34.88	10	16.39
201-220	24	26.83	19	13.31
181-200	25	19.38	15	7.43
161-180	12	11.46	4	2.79
141-160	7	7.74	2	1.55
121-140	5	5.87	1	.43
101-120	3	4.02	0	.62
81-100	3	1.55	1	.43
61-80	1	.62	1	.31
41-60	1	.31	0	-
21-40	0	-	0	-
	323		323	

50th percentile=279.1

5th percentile=133.1

50th percentile=N.A.

5th percentile=193.1

lbs (Table 2.5). Note that these results are very similar to those obtained in the pilot study for the analogous test conditions (see Table 2.1). Performance at the 50th percentile could not be determined for highly motivated males since the majority of male subjects exceeded the 300 lb limit of the force gauge. Figures 2.4 and 2.5 show the cumulative percent of foot-force capability as achieved by females and males in the two trials.

Person Product-Moment correlations performed on a random sample of 100 subjects (57 males and 43 females) showed that foot weight ( $W_f$ ) is highly correlated with total body weight ( $W_b$ ):  $r_{W_b, W_f} = .83$ . However, for this sample of subjects, body weight and right foot force ( $F$ ) with standard motivation had a low correlation of  $r_{W_b, F} = .24$ . A sample of 46 females produced a correlation of  $r_{W_b, F} = 0.26$  between body weight and right-foot force produced with a standard instruction. The same sample attained a correlation of  $r_{W_b, F} = .18$  when body weight was compared with right-foot force produced under an induced motivation.

#### DISCUSSION

A comparison of the above results with those obtained in the Harvard study produces the following findings. The 50 female subjects tested by Stoudt et al., attained a mean force of 201 lbs and a 5th percentile force of 126 lbs, averaged over all five trials. The Harvard subjects were tested five times (all on the right foot) under conditions corresponding to the "induced" motivation condition of this study. The measured forces increased with each successive trial, suggesting that both a learning and motivational effect were present. The subjects in the MSRI study were tested four times. Only two of the tests were on the right foot, the first in the "standard" and the second in the "induced motivation condition.

where, with the cooperation of officials, a greater age range of subjects could be tested. Experimenters followed a procedure identical to that used in the second day of the pilot study. The force gauge was visible. Subjects were given the "standard" instructions and data recorded for the right and left foot. Foot order was alternated across subjects. Right- and left-foot force measurements were then taken with the "induced" instructions. In addition, foot length, body weight, lower leg weight (with subject seated and legs resting on the scale), and lower-leg height were measured.

Subjects. The study sample consisted of 276 female and 323 male drivers. The females were 16 to 79 years of age with a mean age of 32.3 years. Their weights ranged from 89 to 225 lbs with a mean of 135.9 lbs. The males were 16 to 89 years of age with a mean age of 31.8 years. Their weights ranged from 119 to 285 lbs with a mean of 178.1 lbs. The age and weight distribution of subjects is shown in Tables 2.2 and 2.3. It should be noted that younger drivers (16-24 years) are over represented in the sample. Accordingly, the measured distribution is not likely to be an underestimate of the pedal-force capability of the driver population.

#### RESULTS

Tables 2.4 and 2.5 show the cumulative frequency distributions of maximum force achieved by female and male subjects, respectively, with the right foot. (Left-foot data are not shown because of the high correlation that was found for the two feet.) For the standard motivation instruction, the 5th and 50th percentiles of maximum force achieved by the 276 females (Table 2.4) are respectively, 70.3 lbs and 152.7 lbs. For the induced motivation instruction, the 5th and 50th percentiles are equivalent to 102.3 lbs and 193.7 lbs. Males, on being given the standard instruction, attained a 5th percentile force of 133.1 lbs and a 50th percentile level of 279.1

1. Report No.	2. Government Activity No.	3. Originator's Catalog No.	
4. Title and Subject  Brake Force Requirement Study: Driver-Vehicle Braking Performance as a Function of Brake System Design Variables		5. Report Date <b>APRIL 19, 1970</b> 6. Performing Organization Code	
7. Authors R.G. Mortimer, L. Segal, M. Dugoff, J.D. Campbell, C.M. Jorgenson, R.W. Murphy		7. Performing Organization Report No. HuF-6	
8. Performing Organization Name and Address Highway Safety Research Institute University of Michigan Ann Arbor, Michigan 48105		9. Work Unit No.	
		10. Contract or Grant No. FM-11-6952	
11. Type of Report and Period Covered Final Report July 1, 1968-April 18, 1970		12. Sponsoring Agency Code	
13. Supplementary Notes			
<p>M. ABSTRACT: The objective of this study was to define those brake characteristics, within the space bounded by the relationship between brake pedal force and vehicle deceleration, which lead to acceptable driver-vehicle performance. A driver-vehicle braking test was performed in which the deceleration/pedal force ratio, the pedal displacement, the surface-tire friction, and driver characteristics (age, weight) were systematically varied in order to determine the influence of these variables upon minimum stopping distance and other performance variables. The tests that were performed on a low coefficient of friction surface showed that high values of deceleration/pedal force gain result in large number of wheel lockups and lower mean deceleration in bringing the vehicle to a stop, compared to intermediate or low deceleration/pedal force gain levels. Tests conducted on intermediate and high coefficient of friction surfaces showed that high and intermediate deceleration/pedal force gains produced greater mean decelerations and greater frequencies of wheel lockups than lower gain systems. The frequency of loss of lateral control was significantly greater with the high deceleration/pedal force gain brakes on all surfaces than with lower gains. There were minor benefits of 2.5 inch pedal displacement compared to zero inches. Potential brake failures and their effects upon pedal force requirements were analyzed. The implications of the findings for a vehicle braking standard were shown in terms of deceleration/pedal force gain and pedal force.</p>			
14. Key Words  BRAKING, DECELERATION, STOPPING DISTANCE, DRIVER BRAKING, PEDAL FORCE, PAVEMENT FRICTION, BRAKE FAILURE.	15. Distribution Statement  Availability is unlimited. Document may be released to the Clearinghouse for Federal Scientific and Technical Information, Springfield, Va. 22151 for sale to the public.		
16. Author Classification of the report  Unclassified	17. Security Classification of the report  Unclassified	18. No. of Pages xx + 200	19. N/A

\*\*\* Forwarded from AVT-VECHIE -DRIVING 040006 11:01 \*\*\*

To: STEVIE -DRIVING  
TEST/VEHIC-DRIVING

From: M. P. REED  
Subject: Brake Disk Switch Re-location; 1981-1984 TOWN CAR

STEVE, PANTHER SERVICE MANUALS PROVIDE A LITTLE MORE LIGHT:

- 1981 MODEL (IN PAGE 10-45-1, SPEED CONTROL SYSTEM AND 1984 MODEL, ON PAGE 10-61, SPEED CONTROL SYSTEM - ELECTRONIC) MANUALS CONTAIN THIS SENTENCE: "THE SYSTEM OPERATES INDEPENDENTLY OF ENGINE VACUUM, THEREFORE NO VACUUM LINES ARE REQUIRED."

\* I WILL FIND AND CHECK 1981 MODEL MANUAL.  
THIS SOMEWHAT SUPPORTS A SPACE BEING AVAILABLE ON THE TOWN CAR BRAKE PEDAL.  
AND BRACKET ASSEMBLY. I WILL TRY TO BE READY, WHEN SOMEONE COMES TO  
CHECK.

Replies:  
M. P. REED 113-347-7442 (313-421-0725 FAX)  
OVD-LVC -Renee Mail Day 1232 SUBJECT 02 3401

-- Forwarding message received - originator unknown 12:01 \*\*\*

To: STEVIE -DRIVING  
cc: DEIVYDUS -DRIVING  
AZAFARAD -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING  
Subject: Brake Disk Switch Re-location.

Please review Joe Rizzo, Bruce Price, and A. Zepke's when you are ready for  
this. They give considerable info to provide a good analysis.

Steve Balonci Building 3, 3000  
AVT Cruise ETC System Application Mail Day 2001

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 12:02 \*\*\*

To: STEVIE -DRIVING  
cc: DEIVYDUS -DRIVING  
AZAFARAD -DRIVING  
FROM: M. P. REED  
Subject: Brake Disk Switch Re-location.

STEVE, I HAVE NO PROBLEM WITH YOU, WHICH, IS ALL LOOKING AT THE DESIGNERS  
TIME TO GIVE THE SPACE AVAILABLE ABOVE THE SYSTEM TOWNSCAR BRAKE PEDAL  
AND BRACKET ASSEMBLY, AND IN-1. BUT THEY ARE NOT THE RELEASE ACTIVITY THAT  
WOULD TRY TO RELEASE AN ELECTRICAL SWITCH INTO THAT ENVIRONMENT. SPEED  
CONTROL IS THAT RELEASE ACTIVITY.

I WILL REBUT FOR A FEW DAYS. I WILL ASK A CDR ENGINEER TO COORDINATE WITH  
YOU, BRUCE, AND AL. PACKAGE REVIEW MY SPEED CONTROL DESIGN AND RELEASE  
MEWS ABOUT 1984 MODEL TOWN CAR. THE TWO SERVICE MANUALS SHOW THIS FOR THE  
SPEED CONTROL SYSTEM.

\* EARLY PRODUCTION VEHICLES USED A VACUUM DUMP VALVE, ON THE BRAKE PEDAL  
AND  
BRACKET ASSEMBLY. PAGE 10-648-1.

\* LATE PRODUCTION VEHICLES, LIKE 1981 AND 1984 MODEL TOWN CAR.  
THE SYSTEM OPERATES INDEPENDENTLY OF ENGINE VACUUM, THEREFORE NO VACUUM  
LINES ARE REQUIRED.

THIS WAS NOT A JOB OF CHANGE. THAT REPORT I DO NOT HAVE.  
THIS IS ANOTHER PLACE WHERE THE SPEED CONTROL RELEASE ENGINEER COULD HELP,  
THAT IS, EXACTLY WHICH EARLY PRODUCTION SHIPPED AND LATE PRODUCTION  
SHIPPED.

MVA, DATE, ETC.

Replies:  
M. P. REED 113-347-7442 (313-421-0725 FAX)  
OVD-LVC -Renee Mail Day 1232 SUBJECT 02 3401

-- Forwarding message received - originator unknown 12:05 \*\*\*

To: STEVIE -DRIVING  
FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

Subject: Brake Disk Switch Re-location.  
The DATE is five Years. When do you recommend to do the package review of this  
y/s release activation design?

Steve Balonci Building 3, 3000  
AVT Cruise ETC System Application Mail Day 2001  
REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

MSA FROM-TECHNE -DRIVING TO: FREDIE -0404600 01/09/99 01:25:14

To: STEVIE -DRIVING  
cc: TECHNE-VECHIE -VECHIE

FROM: Fred Kahl RE-VAR -DRIVING  
Subject: Brake Disk Switch Re-location

The Speed Control Group did review the old version. Many believe that the packaging  
of the system, including perhaps the pump module was dictated by the basic design.  
This would be in consideration of a standard mechanical pump, but the  
basic responsibility is with the pump and AVT.

Regards, Fred Kahl, Associate System Control Specialist  
Phone 113-347-7442, Email 702, Page: (313) 598-0742, FAX: 313-548-3200

Meeting Address: ETC CTR

Send FROM: RE-VAR-VECHIE -DRIVING TO: FREDIE -0404600 01/09/99 01:31:04

To: FREDIE -0404600  
FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

Subject: Brake Disk Switch Re-location  
This should resolve the issue of which...

Steve Balonci Building 3, 3000  
AVT Cruise ETC System Application Mail Day 2001  
REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: RE-VAR-VECHIE -DRIVING

cc: FREDIE -0404600

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: RE-VAR-VECHIE -DRIVING  
cc: FREDIE -0404600

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: RE-VAR-VECHIE -DRIVING  
cc: FREDIE -0404600

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: RE-VAR-VECHIE -DRIVING  
cc: FREDIE -0404600

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: RE-VAR-VECHIE -DRIVING  
cc: FREDIE -0404600

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

-- Forwarding message received - originator unknown 01/09/99 14:43 \*\*\*

To: FREDIE -0404600  
cc: RE-VAR-VECHIE -DRIVING

FROM: Steve Balonci (F.I.) RE-VAR -DRIVING

REVIEW REQUESTED: 01/02/99 17:00:00 \*\*

\*\*\* Forwarding note from STEPHENS - DODGE/TOWN 08/27/99 16:43 \*\*\*

To: FREDIE  
FROM: Steve Balmer  
SUBJECT: URAET(UTC-05:00)

Subject: Brake Pedal Switch

In the last email mentioned switch a viable replacement for the Towncar switch as far as the speed control elements is concerned? Is the switch input now possible with the speed controls in 92 and 93 Town cars?

Steve Balmer  
Building 3 3C40  
AVT Chassis/EV System Applications mail drop 5H11  
3H-07284 90234-0225 [mbalmer@ford.com](mailto:mbalmer@ford.com) fax 3H-0224 >

RECD FROM: FREDIE - DODGE/TOWN TO: STEPHENS - DODGE/TOWN 08/27/99 08:22:17

cc: STEPHENS - DODGE/TOWN  
TECHNOLOGY - VISTRON

FREDIE - DODGE/TOWN  
FROM: Fred Kahl  
SUBJECT: URAET(UTC-05:00)

Subject: Brake Pedal Switch  
Yes, the push button switch currently used is compatible directly with the 92 and 93 Town Cars.

I do not know of mounting in the vehicle and wiring issues requirements can easily be met. Details would have to answer the mounting / packaging question and EEM's would have to address the wiring harness issue.

The contact Town Car sheet metal engineer is Mike Johnson (DEALANTA) 3H-34247.  
Reported: Fred Kahl, Function Special Control (Pushed)

PROPS ID: FREDIE, Phone TDD Paper 8800 377-0309  
3H-07284 90234-0225

Mailing Address: EVS CTS

\*\*\* Forwarding note from STEPHENS - DODGE/TOWN 08/29/99 16:39 \*\*\*

To: MICHAELE - DODGE/TOWN  
FROM: Steve Balmer  
SUBJECT: Brake Pedal Switch Re-location

Mike, I was asked what the steps of this design work. Here you go my good work I am sure on to my manager! I would like to give both Pavan a sense of where we are at this time, when the concepts are and when they are targeted to complete. My meeting with Pavan is Monday at 2:30.

Goto,  
Steve Balmer  
Building 3 3C40  
AVT Chassis/EV System Applications mail drop 5H11  
3H-07284 90234-0225 [mbalmer@ford.com](mailto:mbalmer@ford.com) fax 3H-0224 >

\*\*\* Forwarding note from STEPHENS - DODGE/TOWN 08/29/99 16:43 \*\*\*

To: STEPHENS - DODGE/TOWN  
cc: TIAZELI - DODGE/TOWN  
FROM: M. P. KIRK  
SUBJECT: Brake Pedal Re-location

I AM OPTIMISTIC ABOUT ABILITY TO PACKAGE THE CURRENT PRODUCTION SWITCH ON THE BRAKE PEDAL AND BRACKET ASSEMBLY IN MOST/THIN TOWN CARS. I WELL KNOW MORE (BUT NOT EVERYTHING) ABOUT THIS AT THE CONCLUSION OF A 9:00 AM MEETING WITH CHASSIS DESIGNERS. GENERAL OPTIMISM COMES FROM THE BRAKE PEDAL AND BRACKET ASSEMBLY DRAWINGS; THEY DO FAIR SHOW EVOLUTION OVER THE MODEL YEARS, AND INVOLVE ONLY ONE SUPPLIER.

WIRS AND HOCHAN ARE NOT IN GOOD SHAPE FOR THIS HIGH/99/1004 MODEL TASK THAT SLOWS THE ADVANCE FACILITATED APPROVAL.  
ALWAYS, I MUST CONSIDER EFFECTS ON PAVAN'S PC. VEHICLE TEST, BRAKE SYSTEM. I INTEND TO CALL YOU, ABOUT NOON ON MONDAY 10/5/99 MAX IL.  
Reported:

M. P. Kirk 313-317-7142 (313-621-6275 FAX)  
OPD LVC - Brakes Mail Drop 1228 Building 3 3H231

\*\*\* Forwarding note from STEPHENS - DODGE/TOWN 08/27/99 16:13 \*\*\*  
To: MICHAELE - DODGE/TOWN  
cc: TIAZELI - DODGE/TOWN

FROM: Steve Balmer  
SUBJECT: Brake Pedal Switch Re-location  
Priority: Please call Fred Kahl with the update from your meeting. I will be at my desk all day.

Steve Balmer  
AVT Chassis/EV System Applications mail drop 5H11  
3H-07284 90234-0225 [mbalmer@ford.com](mailto:mbalmer@ford.com) fax 3H-0224 >

\*\*\* Forwarding note from MICHAELE - DODGE/TOWN 08/29/99 16:34 \*\*\*

To: STEPHENS - DODGE/TOWN  
cc: TIAZELI - DODGE/TOWN  
FROM: M. P. KIRK  
SUBJECT: Brake Pedal Switch Re-location

STEVE, THE RESULT OF THE MEETING THIS MORNING IS THAT WE WILL HAVE A FRAMEUP.

CLEAR SOLUTION FOR SWITCH MOUNTED TO BRAKE PEDAL ASSEMBLY, ON

10/09/99/00/01

TOWN CAR BY NOON FRIDAY 10/9/99.

IN MAKING THIS SOLUTION, WE ARE BEING VERY CAREFUL SO THAT WE DO NOT MAKE SOMETHING WORSE. THE HISTORY IS VAGUE, ANY GOOD NEWS, ABOUT OTHER SOLUTIONS?

Report,

M. P. Kirk 313-317-7142 (313-621-6275 FAX)  
OPD LVC - Brakes Mail Drop 1228 Building 3 3H231

\*\*\* Forwarding note from MICHAELE - DODGE/TOWN 08/29/99 16:43 \*\*\*

To: STEPHENS - DODGE/TOWN  
cc: TIAZELI - DODGE/TOWN  
FROM: M. P. KIRK  
SUBJECT: Brake Pedal Re-location

REPORT: Brake Pedal Re-location - DODGE DESIGN RESULTS

STEVE, THERE IS A PLACE FOR A SWITCH TO BE LOCATED ON THE 10/09/99/00/01 TOWN CAR BRAKE PEDAL ASSEMBLY. IT IS THE "TENNEL" IN THE PEDAL ASSEMBLY'S BRACKET, WORKING WITH THE FLAT SURFACE ON THE PLASTIC ADAPTER ON THE PEDAL ASSEMBLY ARM. THESE FEATURES WERE USED TO MOUNT THE VALVE ASSEMBLY - SPEED CONTROL (ACROSS) AND THE CLIP - SPEED CONTROL VACUUM VALVE (ACROSS) ON OTHER MODELS. TEAMCARLIS PARTNER CARL, SWITCH AND WIRING CLEARANCE TO STEERING COLUMN CROSS ZONE WILL DEPEND ON DIMENSIONS OF SWITCH TO BE USED, AND WIRING POSITION (SEE 10/09 MODEL). SWITCH AT THIS LOCATION, DOES NOT INTERFERE WITH THE CROSS ZONE. A DIFFERENT SIZE SWITCH WILL BE NEEDED.

IT IS TIME FOR THE CHIEF TO VERIFY THESE RESULTS. THAT I REQUESTED DURING THE 10/09/99 MEETING. THE CHIEF IS MISSING, BECAUSE REFERENCED DESIGN LAYOUTS, WHICH, DOOMAN, ETC) THAT WE HAVE AVAILABLE (AND RECOVERED FROM ARCHIVES) ARE NOT PERFECT. I REQUEST REVIEW BY THE APPROVALS DESIGN AND RELEASE SWITCH AND WIRING SPECIFICATIONS. PLEASE RELAY THIS REQUEST.

IF THIS SOLUTION DOES NOT HOLD UP TO THE CHIEF, THEN WE WILL NOT BE ABLE TO ADD A SWITCH ON THE BRAKE PEDAL AND BRACKET ASSEMBLY.

Report,

M. P. Kirk 313-317-7142 (313-621-6275 FAX)  
OPD LVC - Brakes Mail Drop 1228 Building 3 3H231

\*\*\* Forwarding note from MICHAELE - DODGE/TOWN 08/29/99 17:24 \*\*\*

To: STEPHENS - DODGE/TOWN  
cc: TIAZELI - DODGE/TOWN  
FROM: M. P. KIRK  
SUBJECT: Brake Pedal Re-location

Joe, Can you do the drawing that Mike is requesting? Do you know who the design and release engineer(s) is for the brake pedal assembly and the frame?

Steve Balmer  
Building 3 3H108  
AVT Chassis/EV System Applications mail drop 5H11  
3H-07284 90234-0225 [mbalmer@ford.com](mailto:mbalmer@ford.com) fax 3H-0224 >

**Data Log**  
**Brake Pressure Switch**

VIN	Event	Message	Test-Harpoon Resistance	Luster?	Kaption #1	Kaption #2	Kaption #3	Present Status
PY62207	Br. Fire				crack	crack	crack	Anlysis Complete
PY62224	Underhood Fire				no luster	no luster	no luster	Anlysis Complete
MY745119	Underhood Fire							Br. not available
MY745016	Underhood Fire							Anlysis in Progress
VC145373	Cause Stop	41MEGAAHBB	yes	crack	crack	crack	crack	Anlysis Complete
MY745774	Reference	OPEN		no	worn, no crack	worn, no crack	worn, no crack	Anlysis Complete
MY745026	Cause Stop	41MEGAAHBM	yes	crack	crack	crack	crack	Anlysis Complete
MY745028	Reference	70104 OPEN						Anlysis Complete
PT724043	Reference	71037 OPEN						Anlysis in Progress
PY622170	Reference	60007 OPEN						Anlysis in Progress
PT622230	Reference	6049						
PT724011	Reference	40325						
MC28433	Reference	40022 OPEN						
PK160223	Reference	60014 OPEN						
PK627705	Reference	?? OPEN						
PT622075	Reference	62234 OPEN						
PT724005	Reference	91058 OPEN						
PT622074	Reference	60010 OPEN						
MY745008	Reference	53207 OPEN						
PT622072	Reference	90145 OPEN						
PT622074	Reference	?? OPEN						
BY622084	Reference	62199 OPEN						
PT622025	Reference	72114 OPEN						
PT622026	Reference	OPEN						
PT774038	Reference	60449 OPEN						
PT764076	Reference	42021 OPEN						
PK620014	Reference	60331 OPEN						
??	Reference	?? OPEN						
PT622034	Reference	60002 OPEN						
PK620008	Reference	100000						
PK624188	Reference	??						
PK163312	Reference	40042						
PY610364	Reference	73115						
MY724085	Underhood Fire	??						
PY750172	Reference	??						

**Data Log**  
**Brake Pressure Switch**

MY733191	Underhood File	108510
PY768158	Reference	??
PX161140	Reference	72514
MY757405	Reference	??
PY743659	Reference	??
PY7433413	Reference	108548

TI-NHTSA 012366

Page 2 of 2  
printed 3/12/00 6:54 AM  
uncontrolled document

Revised 2/11/99

Epstein, Sally

From: McGuirk, Andy [a-mcguirk@mail.mci.net]  
Sent: Friday, February 19, 1999 7:52 AM  
To: Rahman, Aziz  
Subject: FW: Test up date

**X**  
Brake Pressure Switch  
Test Log  
AUTOMOTIVE SENSORS AND CONTROLS QRA MANGER  
34 FOREST ST P/S 23-03  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3743  
PAGE: (800) 467-3700 PIX 604-2044

-----  
From: Dague, Bryan  
Sent: Friday, February 19, 1999 7:25 AM  
To: Rahman, Aziz 312  
Cc: Bevinghouse, Steven; McGuirk, Andrew; Pechonie, John  
Subject: Test up date

Aziz,

Here is the updated test matrix.

<<Brake Pressure Switch Test Log>>

Please note the following test require a brake fluid pressure cycler:

- 1) the wishbull testing (test # 7)
- 2) the impulse/lab to field correlation study (test #8)
- 3) DOT (tests#10)
- 4) Now maybe a inductive load pressure cycling test (test#12???)

Needless to say we have limited equipment. It takes about 2 weeks to get 1 million cycles. Can you get some input as to what the priority should be?

Regards,  
Bry

**Brake Pressure Switch Test Log**  
Updated 2/16/98

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	T1	Various Levels of Brake Fluid, Water, Detergent 14Vdc to one terminal, Hasport grounded	150+ hours, 5mA draw has reduced to 0.5mA. Fluid has discolored.
	2	T1	Various Levels of Brake Fluid, Water, Detergent 1 Amp through switch terminals	150+ hours. Constant temperature.
	3	AVT	Brake Fluid in Switch, 24 VDC to one terminal Hasport Grounded	No significant temperature rise with time > 200 hours into test, max current 7mA No significant change with time
	4	AVT	Brake Fluid in Switch, 24 VDC to one terminal Hasport Grounded, Ambient at 100 C	16 hours into test max current 5mA. No significant temperature rise with time
	5	AVT	Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp. Delta T reached steady state at 20 C
	6	T1	Build heater element into Switch Heat till failure	2 tested. Sparks observed, no ignition. A sparking device will be added as testing continues.
Life Cycle Reliability of Pressure Switch	7	T1	0-1400 psig pressure pulses at 135C ambient per EB	First failure at 720,000 cycles. Cycle count at 900,000. Continue to failure.
Corrosion Wear Field vs Lab Correlation	8	T1	0-1400 psig pressure pulses at 135C ambient	Parts withdrawn every 200K cycles, characterized for wear
	9	Central Labs	Various Fluid returns, from dealer lots, junkyards	Parts in Central Labs, being processed
Design Of Experiments Evaluating Factors	10	T1	Various Levels of Brake Fluid, Water, Under EB conditions, to failure	Equipment modifications underway. Start expected 2/24.
Electrolytic Discharge Wear				
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Logistics being worked out.

**Pachonis, John**

---

From: Dugay, Bryan  
Sent: Friday, February 19, 1999 8:25 AM  
To: Rummel, Aziz Ziz  
Cc: Benninghouse, Steven; McGuirk, Andrew; Pachonis, John  
Subject: Test up date

Aziz,

Here is the updated test matrix.



Please note the following test require a brake fluid pressure cycler:

- 1) the weibull testing (test #7)
- 2) the impulse/lab to field correlation study (test #6)
- 3) DOE (test#10)
- 4) Now maybe a Inductive load pressure cycling test (test#1277)

Needless to say we have limited equipment. It takes about 2 weeks to get 1 million cycles. Can you get some input as to what the priority should be?

Regards,  
Bry

**Basis Pressure Switch Test Log**  
Updated 2/1/2009

Category	Test	Description	Test Parameters	Test Results
1) Components	1	T1	Microwave Laminator at 600W, Water, Detergent	100+ hours. Stack draw has reduced to 0.5mm.
2) Protected switches			10Vdc to one terminal, bypass grounded	Stack has disengaged.
3) Switches	2	T1	Microwave Laminator at 600W, Water, Detergent	100+ hours. Constant temperature.
			1Amp current switch	No significant temperature rise with time
	3	AVT	Water flow in fixture, 24 VDC to one terminal	> 200 hours into test, max current 7mA.
			Current Grounded	No significant change with time
	4	AVT	Water Flow in fixture, 24 VDC to one terminal	10 hours into test max current 5mA
			Water flow stopped, Ambient at 40°C	No significant temperature rise with time
	5	AVT	Water flow fixture, 30 Amps	100+ hours into test at 40°C shows rapid temp
			Water flow stopped	Water flow stopped rapidly after 100+ hours at 20°C
	6	T1	Water flow fixture, 30 Amps	100+ hours into test no pressure, no ignition.
			Water flow fixture, 30 Amps	No water flow fixture, 30 Amps
<b>TESTS</b>				
1) Components				
2) Protected switches				
3) Switches				
4) Ignition				
5) Protection				
6) Assembly				
7) Other				
8) Summary				
9) Notes				

TI-NHTSA 012402

Eptein, Sally

From: Dague, Bryan [bdague@email.mci.net]  
Sent: Friday, February 19, 1999 11:01 AM  
To: Rahman, Aziz; Rahman, Aziz ZIZ  
Subject: FW: More info

W  
From: Dague, Bryan  
Sent: Friday, February 19, 1999 7:35 AM  
To: 'Rahman, Aziz ZIZ'  
Subject: More info

Aziz,

Here are my notes on what we are doing here. It might offer you a bit more detail than the spread sheet has room for.

<<Ford Tests Currently in Progress>>

Did you get your hands on that pressure station yesterday??

Regards,  
Bry

**Tests Currently In Progress**

Last updated: 2/15/99

**Ignition Re-creation:**

Objective - to recreate the conditions that caused an engine fire in the application.

Description:

1. 10 switches are filled with a mix of brake-fluid, water, and detergent. 2 switches are filled with the following concentrations: 0%, 4%, 6%, 10%, and 75%. 14 volts is being applied to 1 terminal and the hexport is grounded. Current flow varies from about 0.5 mA to a high of about 5.0 mA.
2. On 2 of the above switches approximately 1 amp is being conducted through the terminals in order to create heat in the switch.

Results to date:

No failed the 75% device. Current flows and temperatures are stable, but have decreased during the last couple of days.

**Weibull Testing:**

Objective - To determine if snap discs have a characteristic life similar to quiet discs.

Description:

A population of 10 77PS/2-I (snap discs) is being cycled to failure.

Results to date:

No failures at 600K cycles.

**Wear Correlation:**

Objective - To develop a spectrum of dimensions and visual cues that can be used to estimate the % of life left on switches recovered from the field.

Description:

Switches are being removed from the cycler at increments of 200K cycles. 2 switches at each interval. These switches will be disassembled and wear at the following points will be characterized:

1. Kapton degradation
2. Pla
3. Pla guide
4. Arm bump
5. Converter/washer interface

Results to date:

600K cycles.

2 with 200K cycles were removed - awaiting dissection.

2 with 400K cycles were removed - awaiting dissection.

2 with 600K cycles were removed - awaiting dissection.

**Future Plans:**

**DOE:**

In order to run multiple moisture levels the pressure cycler needs to be modified. Parts needed for the modification are being ordered today. The goal is to have this DOE running by the end of the week.

Factors being investigated on the first pass are moisture and snap vs quiet. Future passes will include temperature and pressure.

**Auto-ignition testing:**

Objective is to get a fire started within the switch by installing a very small electrical heating element. With a small heating element built into a switch, we will fill the connector cavity with brake fluid, and slowly increase the current to the heating element. We will increase the current until ignition, or until the heating element burns out (continuity is lost).

Epsstein, Sally

From: Dague, Bryan [bdeague@email.mci.net]  
Sent: Friday, February 19, 1999 11:04 AM  
To: Rahman, Aziz; Rahman, Aziz ZIZ  
Subject: FW: Test-up date

**25**  
Brake Pressure Switch  
Test Log

---

From: Dague, Bryan  
Sent: Friday, February 19, 1999 7:25 AM  
To: 'Rahman, Aziz ZIZ'  
Cc: Bechinghouse, Steven; McGuirk, Andy; Pachonis, John  
Subject: Test up date

Aziz,

Here is the updated test matrix.

<<Brake Pressure Switch Test Log>>

Please note the following test require a brake fluid pressure cycler:

- 1) the weibull testing (test # 7)
- 2) the impulse/lab to field correlation study (test #6)
- 3) DOZ (test#10)
- 4) Now maybe a inductive load pressure cycling test (test#12???)

Needless to say we have limited equipment. It takes about 2 weeks to get 1 million cycles. Can you get some input as to what the priority should be?

Regards,  
Bry

**Brake Pressure Switch Test Log**  
Updated 2/16/99

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	II	Various Levels of Brake Fluid, Water, Detergent 14Vdc to one terminal, Input port grounded	150+ hours. 5mA draw has reduced to 0.5mA. Fluid has dried-out.
	2	II	Various Levels of Brake Fluid, Water, Detergent 1 Amp through switch terminals	150+ hours. Constant temperature. No significant temperature rise with time
	3	AVT	Heater fluid in Switch, 24 VDC to one terminal Input port Grounded	> 200 hour. auto feed, max current 7mA No significant change with time
	4	AVT	Brake Fluid in Switch, 24 VDC to one terminal Input port Grounded, Ambient at 100 C	16 hours into test max current 5mA. No significant temperature rise with time
	5	AVT	Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C
	6	II	Build heater element into Switch Heat to failure	2 tested. Increditable amounts of smoke, no ignition. A sparking device will be added as heating continues.
Life Cycle Reliability of Pressure Switch	7	II	0-1400 psig pressure pulses at 130C ambient and ES	First failure at 726,000 cycles. Cycle count at 800,000. Continue to failure.
Deployment Wear - Relative Lab Condition	8	II	0-1400 psig pressure pulses at 130C ambient	Parts withdrawn every 200k cycles, characterized for wear
	9	Central Labs	Various Field returns, from dealer lots, junkyards	Parts in Central Lab, being processed
Design Of Experiments - Evaluating Factors	10	II	Various Levels of Brake Fluid, Water, Under ES conditions, to failure	Equipment modifications underway. Start expected 2/24.
Effecting Deployment Wear				
On-Vehicle Characterization of Pressure & Temperature Profile in Transit Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS Profile in Transit Car	Logistics being worked out.

Jayanth, Sathy

From: Rajkumar, Ashw [mailto:[ashwrajan@gmail.com](mailto:ashwrajan@gmail.com)]  
Sent: Friday, February 10, 1995 11:12 AM  
To: Sherpa, Robert  
Subject: Test Log.xls



Test Log.xls

<<Test\_Log.xls>>

TI-NHTSA 012407

**Brake Pressure Switch Test Log**  
Updated 2/14/00

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Failure in Switch	1	T1	Various Levels of Brake Fluid, Water, Dielectric 14Vdc to one terminal, Input port grounded	150+ hours, 5mA draw has reduced to 0.5mA. Fluid has discolored
	2	T1	Various Levels of Brake Fluid, Water, Dielectric 1 Amp through switch terminals	150+ hours. Constant temperature No significant temperature rise with time
	3	AVT	Brake Fluid in Switch, 24 VDC to one terminal Input Grounded	> 200 hours into test, max current 7mA No significant change with time
	4	AVT	Brake Fluid in Switch, 24 VDC to one terminal Input Grounded, Ambient at 200 C	16 hours into test, max current 5mA No significant temperature rise with time
	5	AVT	Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Switch T reached steady state at 20 C
	6	T1	Solid heater element into Switch Heat up failure	2 tested. Heater shattered, no switch A operating times will be added as testing continues.
Life Cycle Reliability of Pressure Switch	7	T1	0-1400 poly pressure pulses at 130C ambient over ESD	First break observed at 720,000 cycles Cycle count at 900,000. Continue to failure.
Brake Line Failure vs Field vs Lab Correlation	8	T1	0-1400 poly pressure pulses at 130C ambient	Part fails every 200k cycles, characterized for wear
	9	Central Lab	Various Fluids, water, brake fluid, oil, hydrocarbons	Parts in Central Lab, being processed
Design Of Experiments Driving Factors	10	T1	Various Levels of Brake Fluid, Water, Under ESD conditions, to failure	Equipment availability pending. Start expected 2/24.
Braking Magnitude Effect				
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Brake Pressure and Temperature at Switch Location for ABS and non-ABS Braking events	Logistics being worked out

Pechonis, John

From: McQuirk, Andy  
Sent: Friday, February 19, 1999 11:44 AM  
To: Dague, Bryan; Watt, Jim; Beringhause, Steven  
Cc: Rahman, Aziz; Baumann, Russ; Pechonis, John  
Subject: MATERIAL FOR AZIZ  
Importance: High

AZIZ WILL COME INTO THE PLANT SATURDAY TO PICK UP FOLLOWING ITEMS:

SAMPLES OF PVB FROM THE KAPTON CHARACTERIZATION TESTING WE HAVE DONE HERE  
(PROVIDES FORD THE 'SAMPLE SAMPLES WE HAVE COLLECTED FROM THE 'EVERY 200,000' CYCLE  
TEST TO CHARACTERIZE WEAR STATES.

.....BRYAN AND STEVE, PLS COORDINATE THESE INTO AZIZ OFFICE FOR HIS PICK UP

OPPSET KEYWAY CONNECTOR TO FIT THE PRESSURE SWITCHES WE ARE ALL TALKING  
ABOUT....PRESSURE TESTER HAS WRONG (?) CONNECTOR AND NEEDS RIGHT CONNECTOR  
HARNESSES

.....BRYAN AND STEVE, PLS COORDINATE INTO AZIZ OFFICE FOR HIS PICK UP

'CORRECT' PRESSURE FITTING TO CONNECT INTO PRESSURE STATION AND INTO SWITCH QUICK  
CONNECT.

.....BRYAN AND STEVE AND JIM WATT, PLS COORDINATE INTO AZIZ'S OFFICE FOR SAT PICKUP

IF THERE ARE ANY QUESTIONS, PAGE AZIZ BEFORE NOON TODAY.....JIM WATT, PLS THOUGHT  
OVER THIS TO ASSURE IT HAPPENS

A  
AUTOMOTIVE SENSORS AND CONTROLS DIV. NUMBER:  
14 FOREST ST N/B 23-99  
MIDTOWN, MI 48163  
TEL : (313) 236-3860  
FAX : (313) 236-3746  
FAX: (313) 427-3700 FAX 424-3844

Dague, Bryan

From: McGuirk, Andy  
Sent: Friday, February 19, 1999 6:21 PM  
To: Sullivan, Martha; Bumann, Russ; Beringhauser, Steven; Baker, Gary  
Cc: Rowland, Thomas; Dague, Bryan; Pechanis, John; Rahneman, Aziz; Douglas, Charles; Wall, Jim; Sharpe, Robert  
Subject: FORD CONF CALL OF 2/19

**ATTORNEY CLIENT PRIVILEGED COMMUNICATION**

STEVE BERINGHAUSER AND I HELD A CONFERENCE CALL WITH STEVE REIMERS OF FORD TO PROVIDE DETAILED BRIEFING TO HIM FOR HIS 4PM EXECUTIVE LEVEL MEETING (HE'S FILLING IN FOR FRED PORTER)

**SUMMARY:**

STEVE REIMERS WAS PREPARED FOR THE FORD EXEC MEETING WITH OUR TEST MATRIX AND UPDATE...HE WAS LEANING TOWARDS KAPTON WEAR OUT AS A KEY CONTRIBUTOR...AND WE HELPED HIM BALANCE WITH LACK OF IGNITION IN THE AGREED UPON TESTS TO DATE POINTING OUT WE THOUGHT SOME ELECTRICAL ANOMALY HAD TO BE HAPPENING TO DRIVE IGNITION.

WE COVERED A NUMBER OF POINTS IN SOME 50 MINUTES OF TELECON:

THE TEST NUMBER 7 RUN WOULD BE DONE MONDAY...THIS WAS SET UP AS A TEST TO LEAK POINT OF SOME 30 UNITS. 1ST ONE LEAKED AT 728,000 CYCLES VS 500,000 SPEC. (THERE WILL BE INTEREST IN A WEBULL STATISTIC STATEMENT FROM THIS TESTING (JIM)

TESTING TO CHARACTERIZE WEAR OUT 'STAGES' OF KAPTON TO CONTINUE...PROVIDE FORD PHYSICAL SAMPLES VIA AZIZ MONDAY.

THERE WERE QUESTIONS ABOUT THE '93 ECONOLINE HARNESS...SWITCH LOCATION AND ORIENTATION

WE WILL ESTABLISH A D.O.E. STARTING MONDAY TO USE QUIET AND SNAP SWITCHES WITH CLEAN AND H2O CONTAMINATED BRAKE FLUID RUNNING SOME 10 UNITS ON AUTO CRUISE SERVO-MOTOR LOADS TO DETERMINE SIGNIFICANT EFFECTS AND WEAR OUT 'ACCELERATORS'. TEST SHOULD RUN FOR 10 DAYS. THIS STARTS TO FORM THE BASIS FOR LONGER CYCLE LIFE SWITCH

DISCUSSED ABS AND TRACTION CONTROL VEHICLE OPTION PACKAGES AND WILL BE GETTING FORD INFO ABOUT THIS 'SOON'

AS WE DISCUSSED H2O CONTAMINATED BRAKE FLUID I ASKED IF IT IS A MATTER OF SERVICE RECORD THAT CAR BRAKE SYSTEMS 'ATTAIN' SUFFICIENT WATER CONTENT TO FREEZE....UNKNOWN AND NOT COMMITTED RESPONSE FROM FORD

STEVE B EXPLAINED OUR UNDERSTANDING OF CAUSES OF KAPTON WEAR-OUT ACCELERATION...H2O, STRESS FROM HIGH PRESSURES, STRESS FROM 'VACUUM' OR HYDRAULIC SHOCK, WEAR-OUT FROM EXCESSIVE CYCLES...THIS LED TO 'DISMISSED' DISCUSSION OF TOWNCAR HYDRAULIC SYSTEM PRESSURES IN THE TRACTION CONTROL EVENTS WHICH WE POINTED OUT AS A POSSIBLE EXAMPLE OF A SIGNIFICANT STRESS RIBER IN THE SYSTEM

STEVE B EXPLAINED WE WERE NOT SEEING THE POSSIBILITY OF IGNITION OF A SWITCH WITH CLEAN

FLUID...LEADING TOWARD OUR BELIEF THAT SOME CONFOUNDING CREATED BY H2O CORROSION OF THE SWITCH AND/OR INTERNAL ARM MIGHT BE PATH TO CREATE HIGH RESISTANCE BUT THAT THE SYSTEM WOULD HAVE TO DRIVE SIGNIFICANT POWER BACK INTO THE SWITCH TOO.... STEVE REIMERS WAS NOT 'LISTENING' TO US VERY MUCH AT THIS TIME..

INTERNAL TI TO-DOS FOR ME TO DRIVE:  
ABIDE FROM ABOVE ACTIONS...

STEVE S AND I AGREED WE WILL NEED TO CREATE THE SITUATION IN LAST PARAGRAPH AND DOCUMENT TO FORD EARLY NEXT WEEK SO WE COULD FOCUS DOWN TO LIKELY AREAS.

TI WILL NEED TO EXPAND THE TEST MATRIX TO COVER MANY OF THE ITEMS WE ARE DOING AND GAIN THE CREDIT THAT WE ARE WORKING IN MANY AREAS

TI NEEDS TO DOCUMENT THE APPROACH TO INCREASED SWITCH LIFE WITH A PLAN WHICH WOULD INCLUDE OUR POSITION AGAINST POWER ON AT ALL TIMES

I WILL RE-ENGAGE WITH FRED PORTER BY TUESDAY MORNING UPON HIS RETURN FROM VACATION

A

AUTOMOTIVE SENSORS AND CONTROLS DIVISION  
34 FOORD ST AVE 21-05  
ATLANTA, GA 30301  
TEL : (404) 236-2080  
FAX : (404) 236-3745  
E-Mail: 16001 487-3700 FDN 604-2844

---

From: McGaugh, Andy  
Sent: Friday, February 16, 1990 10:27 AM  
To: Sullivan, Martha; Baumham, Russ; Brinckhouse, Steven; Baker, Gary  
Cc: Rorland, Thomas; Dugay, Bryan; Peabody, John; Rahm, Alz; Douglas, Charles; Wall, Jim  
Subject: FORD PRESSURE CYCLES (C/O AJ)Pressure Tests

ATTORNEY CLIENT PRIVILEGED COMMUNICATION

I HAVE BRIEFLY REVIEWED AND BOLD NOTED SEVERAL AREAS (AS WELL AS ADDED BLUE NOTES FOR CLARITY) FOR OUR FIRST CONSIDERATION. SEEMS THE TRACTION 'CONTROL' OR, AS IT WAS CALLED THE 'AUGMENTATION', MECHANISMS ARE FINALLY BEING REVIEWED AS CYCLE CONTRIBUTOR IN THE SYSTEM AND THIS FORD NOTE SHOULD MAKE IT A KEY FOCAL POINT BY LATER TODAY...

ONE CAN SEE THERE ARE A LARGE NUMBER OF PRESSURE AND CYCLE COMBINATIONS IN THIS SYSTEM INCLUDING SHOCK WAVES AS WELL AS CONTROL WAVES...MIGHT BE THESE SYSTEMS THAT 'LIMIT' THE WEAR OUT ISSUE TO THIS PLATFORM AND YEARS.

BRIEFLY STATED FOR YOUR REFERENCE BELOW: OUR SWITCH WAS SPEC'D BY FORD TO 'OPERATE' 600,000 CYCLES TO 1450 PSI, AND 'PROOF' (IE, RUN UP TO PRESSURE AND 'STILL' FUNCTION AFTER EXPOSURE) TO 3000 PSI, AND 'BURST' (IE, NOT RUPTURE DURING 30 SECONDS EXPOSURE) AT 7000 PSI.

A.

AUTOMOTIVE SENSORS AND CONTROLS DIVISION  
14 ROBERT ST P.O. BOX 25-08  
AFTONWOODS, MI 48373  
TEL : (888) 236-3000  
FAX : (888) 236-3748  
PAGE: (888) 467-3700 RIN 664-2046

From: Rehman, Asif.  
Sent: Friday, February 19, 1999 8:57 AM  
To: McGuire, Andy; Binghamton, Steven; Dague, Byers; Braunton, Russ; Shupe, Robert; Balow, Gary; Douglass, Charles  
Subject: PW: (U)Pressure Tests

GOOD INFO.

From: Steve Reimers<SMTP:reimers@ford.com>  
Sent: Friday, February 19, 1999 8:18 AM  
To: Asif Rehman, Texas  
Subject: (U)Pressure Tests

Fyi... I gave him a copy of your test plan and asked what pressure range and frequency we should instrument for.

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SRHIMERS . reimers@ford.com fax 39-03286 :>  
\*\*\*Forwarding note from JJOYCE1 --DRBN007 02/18/99 19:40 \*\*\*  
To: SRHIMERS--DRBN007  
cc: FPORTER --DRBN007

FROM: John Joyce  
Subject: (U)Pressure Tests

02APR(UTC -05:00)

Steve,

I got your note and will be on vacation tomorrow through Wednesday. Here's the info.

The more I think about this, the more I think FRACTION CONTROL activation may be the mechanism (? CYCLES AND LINE PRESSURE?).

I am not sure of the order of the things connected and that can influence the low frequency amplitude of the signals. (WE HAVE INDICATED THE PW LOCATION COULD BE KEY IN THIS ISSUE. MASTER CYLINDER VS PROP VALVE MOUNTING BEING ONE POINT I HAVE TRIED TO MAKE CLEAR). But the short answer is to instrument for 0-250 bar and sample at 1 kHz or more.

Since I'm not sure of where the pressure switch is hydraulically connected I'll give you pressures at nodes and states I do know. worst case for the switch would be to be connected between the ECU and the prop valve , which is where I think it is.

This is the low frequency component of the signal. I'll talk about the high-frequency component further down.

MC = MCU NODE

Maximum Pressure - ~175 Bar (16BAR IS 14.5 PSI, 2537 PSI)

Achieved by getting maximum vacuum (high revving engine and suddenly close throttle) then standing on the pedal as hard as you can. I don't remember this number very well it might be as low as ~130 or as high as 220 (3180! PSI). It also

depends on your leg strength. This type of pressure is ~~VERY~~ RARE at this node. For this car, the driver will typically apply <20 bar and very rarely exceed 50 bar.

#### HCU - PROP VALVE MODE

Standing Still - Same as MC pressure - see above.

ABS Maximum - ~110 Bar (1655 PSI)

This is achieved by loading to GWE and performing an ABS stop, you may find that you are pedal effort limited, not limited by ABS control. It's pretty rare to get this high of pressure in this mode.

TCS Maximum - ~180 Bar(2610 PSI)

This is a good candidate. On this vehicle because the HCU had to pump through the prop valve to do the brakes-only traction control, the pressures coming out of the HCU got very high. The pressure relief valve on the pump VERY OFTEN dictated the peak pressure which could be developed - not the control - put another way, because the pressure at the rear brake had to restrain the entire powertrain (no engine intervention) and push through a prop valve, it was often possible to drive through the TC - the engine could overpower the brakes, even though very high pressures were being generated at the HCU. The noise during TC activation in these applications was very dependent upon the pressure relief valve opening point. So the pressure relief valve value got changed a few times over the years as performance was sacrificed for NOISE VIBRATIONS ARSHNESS. Also the tolerance on the pressure

relief valves was fairly large - a total of 40 bar, at that time I believe. The pressure relief valve pressure might be anywhere from 90 to 180 bar depending on part-to-part variation and the design generation that was agreed upon.

You can achieve this easiest by getting the rear wheels off the ground and putting the car in drive. Get into the throttle hard, but not so hard that you drive out of first gear or faster than ~15 mph. If you maintain this for a while, the thermal model to protect the rear linings will disable the Traction Control. You will then need to wait for them to cool, before the function will be reenabled. You can dramatically accelerate the cooling time by cruising (without braking) at about 40 mph.

Typical drivers can regularly get high pressures (2610 PSI)  
in this mode.

#### PROP VALVE - REAR BRAKE MODE

ABS Maximum Pressure -70 Bar

Load to GROSS VEHICLE WEIGHT and perform an ABS stop at maximum pedal effort.

TCS Maximum Pressure -100 Bar

This pressure level is strongly dependent upon the pressure relief valve level - see above.

Standing Still

Same as ABS Maximum Pressure

#### High Frequency Content

The high frequency content has two parts. If you are NOT in ABS or Traction Control there is practically no high frequency content - the pressure is modulated at <10 Hz. This is basically limited by Booster response times and hydraulic damping in the ABS orifices.

#### High Frequency Content Due To Control

During ABS/TC events the pressure is changed in quick steps(CYCLES?). Typically

it will increase by ~10 Bar in a few milliseconds, and this type of change occurs about every 10ms. The pressure will decrease by about 20 Bar every 300 ms. There can be quite a bit of variation in these numbers, but those are pretty typical. (Actually the numbers I assigned were for ABS, swap "increase" and "decrease" for TRACTION CONTROL activation.)

#### High Frequency Content Due to Shock Waves

This is a secondary effect from the control. Generally it is worst right at the outlet of the HCU. It is damped and dissipated the further you get from the HCU. The shock wave is generated from the cyclical pulsing of the pump as well as the sudden changes in pressure when a solenoid valve is snapped open or shut.

The amplitude of this (Shock Waves) can be really big - I haven't looked at it in this generation unit for a few years, but I think it's about 50 bar peak-peak (725 PSI) right at the HCU. It will fall off as you move further away from the HCU.

The frequency is pretty high and I think some components are above the 1 kHz level, but you can get a very good idea of the disturbances by sampling at 1kHz.

Regards,  
John Joyce

time 11:30

02/03/79

SPM

alt ↓	PS	V	
2.5%	1	14.03	1400mA 100% 10.70V 100% 14.07 ~930
	2	14.05	~930
	3	14.05	~930
5%	4	14.04	~900
	5	14.05	~900
	6	14.06	~100
10%	7	14.06	1200
	8		>1900
	9		

supply current limited

16/16

54



02/22/99

SPM

77PS salt + H<sub>2</sub>O mix.

(3) units w/ 2.5% salt/H<sub>2</sub>O mix  
(3) units w/ 5% salt/H<sub>2</sub>O mix  
(3) units w/ 10% salt/H<sub>2</sub>O mix

injected w/ mixtures 18.00

666  
444  
555  
666



TI-NHTSA 012416

08/22/99

$$cup = \underline{10.51\text{ g}}$$

$$\text{need } \frac{56.5\text{ g}}{56.5\text{ g}} \text{ of 5% mix} = 2.825\text{ g salt}$$

$$\frac{2.825}{x} = .025 = 113\text{ g}$$

113 g measured adding tap water

$$71.9\text{ g of 5\%} = 3.595\text{ g salt}$$

$$\frac{x\text{ g salt} + 3.595}{(71.9 + x)} = .1 \quad 7.19 + .1x = x + 3.595$$

$$.9x = 7.19 - 3.595$$

$$.9x = 3.595$$

$$x = 3.99$$

initial  
conditions:

% salt  
2.5%

v

ü

2.5

2.5

2.5

5

5

5

10

10

10

TJ-NHTSA 012418

**Breke Phillips Switch Test Log**  
Updated 2020-08-06

Category	Test	Location	Test Procedure	Test Results
No. 1 of Potential in Switch	1	T1	Various Levels of Brake Fluid, Water, 1 Amp through switch terminals, 1000°C Cyclic, 0%, -40°, 0%, 100%, 70%	Switch passes. Current draw at 1000°C is 1.0A. No damage.
	2	T1	Various Levels of Brake Fluid, Water, 1 Amp through switch terminals	2000hrs. Constant temperature. No damage. Temperature stays with flow. Test suspended.
	3	AVT	Brake Fluid in Switch, 24 VDC to one terminal, Negative Grounded, Ambient at 100°C	> 1000 hours with heat, more current 100A. No damage. Current stays with flow. Test complete.
	4	AVT	Brake Fluid in Switch, 24 VDC to one terminal, Negative Grounded, Ambient at 100°C	100 hours later back to normal 100A. No damage. Current stays with flow. Test suspended.
	5	AVT	Brake Fluid in Switch, 10 Amps through switch terminals	1000 hours later at 100°C, 1000hrs. No damage. Current stays with flow at 100°C. Test suspended.
	6	AVT	Brake Fluid in Switch approx. 20 Amps through switch terminals	1000 hours later at approx. 200°F. No damage. No current.
	7	T1	Wind tunnel exposure into Switch with & w/o Fluid (No air flow, wind not blowing)	Switch passes. Slight discoloration, but no damage with water flow. No damage.
			Dry	1000hrs.
			Wind tunnel test with water flow	1000hrs. No damage from heat building up. Current stays with flow at 100°C. Current stays with flow at 200°F.
	8	T1	Conductivity test by connecting switch terminals	Test in progress.
	9	T1	Conductivity test by connecting switch terminals	Test in progress.
No. 2 of Cyclic Repetitive of Pressure & Temp.	7	T1	0-7000 psi pressure pulses at 1000°C	First half, observed at 7000psi cycles. Test completed.
	8	T1	0-1000 psi pressure pulses at 1000°C	Test completed. Then started 1000°C.
Repetitive Pressur Field vs. No. Cycles	9	T1	0-1000 psi pressure pulses at 1000°C	Test continues every 1000 cycles, characterized by noise levels in Control Log, until 10000.
	10	T1	Various Levels of Brake Fluid, Water, 1000°C Cyclic, 0%, -40°, 0%, 100%, 70%	Test completed. Temperature stays with flow. Test suspended.
Design Life Testing & Load Sharing (Capacitor Wheel)	11	T1	12 amp switches, and 0% voltage on the other load, 12 amp switches, and 0% voltage on the other load, 12 amp switches, 50% voltage on the better load, 12 amp switches, 50% voltage on the better load, 12 amp switches, 50% voltage on the better load	Temperature stays with flow. Test suspended.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
			12 amp switches, 50% voltage on the better load	Test completed.
On-Wheel Characteristics	11	AVT	Brake Fluid and Temperature, and Conductivity Logics for 1000 and 1000°C cycling events	Conductivity logics worked well.
No. 3 of Pressure & Temperature Profile in Tires Car	12	Control Log	Temperature & pressure logics are reliable in the above cycling conditions, and logic repeatable, and the tire pressures are good in comparison with previous cycling and earlier events.	Temperature set-up 10 minutes at Control Log. Temperature after 2000.
Brake Ave Study	13	Control Log	Temperature & pressure logics are reliable in the above cycling conditions, and logic repeatable, and the tire pressures are good in comparison with previous cycling and earlier events.	Temperature set-up 10 minutes at Control Log. Temperature after 2000.
Pressure Measuring of various materials from field samples & other sources	14	Control Log	Temperature & pressure logics are reliable in the above cycling conditions, and logic repeatable, and the tire pressures are good in comparison with previous cycling and earlier events.	Temperature set-up 10 minutes at Control Log. Temperature after 2000.

Eptstein, Sally

---

From: Cagno, Lorraine (lcagno@mail.mc.dti.com)  
Sent: Wednesday, February 24, 1999 10:03 AM  
To: Beringhausen, Steven  
Subject: Ford1.ppt



File1.ppt  
**<<Ford1.ppt>>**


Here you go!!!!

Lorraine



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive corrosion and provide energy
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any erosion is present a fire can start, burning the plastic.



Koesten, Sally

From: Beringhouse, Steven (beringhouse@metal.mc.tl.com)  
Sent: Wednesday, February 24, 1999 10:08 AM  
To: Rahman, Aziz  
Subject: FW: Ford1.ppt

2001.mt

-----  
From: Cagno, Lorraine  
Sent: Wednesday, February 24, 1999 11:03 AM  
To: Beringhouse, Steven  
Subject: Ford1.ppt

<<Ford1.ppt>>

Here you go!!!!!!


Lorraine

TI-NHTSA 012421



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive corrosion and provide energy
1. Water enters the switch cavity
3. Contact arm corrosion increases resistance (heater wire).



CONFIDENTIAL

- 2-29-77

L. Cambray

## 77 PS Heated Device Testing

### I . Purpose

To determine if auto ignition can occur from the build up of excessive heat in the device . Leading to and igniting a fire to the device itself as well as the conditions and temperatures to cause results of this nature .

### II . Procedure

Several attempts were made at reproducing auto ignition of the 77 PS device . A heater wire coil was installed into the base of the device in the area that the contacts and arm assembly normally occupy . The wire was attached to the terminals and connected firmly to the terminals by removing the contact arm and grinding away the rivet and drilling in the stationary contact and crimping with a small wire cutter . The heater wire used along with the coils had a total resistance of .5 ohms .

A small hole was drilled into the terminal cavity to facilitate use of a type k thermo couple wire .

The testing consisted of powering the heater coil with a variable output DC power supply to the leads of the mating connector . Temperature , voltage to the coil and current draw were monitored during testing . Device was placed in a fire proof enclosure (heat treating oven) and allowed to stabilize to room temperature of 70 degrees f .

Three devices were tested one with brake fluid and 6% water and two device's dry . Devices were given provisions for a external source if ignition by drilling a .040 hole on a 45 degree angle through base and inserted a .042 torrington pin to be inserted allowing a small gap for a spark to jump . This spark was accomplished by the use of a hy-pot tester that is used to test the dielectric breakdown of electrical devices . The use of this caused a arc to be created when device base failed and allowed the entrance of oxygen to the switch cavity and smoke from the plastic had to be present to induce flame .

### **III : Results / Discussions**

#### **Test 1- Wet Device (readings at appx.1 min. intervals)**

<b>Volts</b>	<b>Heater Current</b>	<b>Internal Temperature (F)</b>
.27	1.0	100
.50	2.0	175
.80	2.9	220
.90	3.0	246
.98	3.2	349
1.6	2.0	300
.97	3.1	340
1.1	3.6	460
1.2	3.8	462
1.1	3.8	488

1.3	4.0	531
1.1	3.6	571
1.4	4.1	647
1.4	4.0	660

Out gassing of fluids began at 220 F a noticeable hissing sound was present at this point . Smoke was visible and base was venting from side at a temperature of 246 F . And smoke was being vented till failure of base at 660 F at this point power to heater was shut down and spark from hy-pot applied . Ignition of gasses occurred at this point and fire was extinguished .

#### Test 2 (dry device with spark)

Test 2		
Volts	Heater Current	Internal Temperature (F)
1.0	3.1	501
1.09	3.0	743
Connection failed and reconnected		
1.06	3.02	596
1.06	3.09	626
1.12	3.15	650
1.13	3.08	681

1.13	3.26	692
1.13	3.18	707
1.13	3.36	722
1.20	3.52	758
1.36	3.95	806
1.36	4.00	875

The dry device did not emit smoke or outgas until 626 F and at this time it was a light smoke emanating from terminal area . At 692 F a small burn thru area was created in the base and venting smoke this continued to 806 F where base failed and fell over . Power was left on at this point and spark applied to furnes where they ignited and extinguished quickly . The upper portion did not ignite despite 1230 F temperature .

#### Test 3 (rapid temp. rise)


Volts	Heater Current	Internal Temperature (F)
1.0	3.6	300
1.2	4.0	360
1.2	3.8	643
1.3	3.7	650
1.3	3.7	800
1.3	3.7	930
1.3	3.7	967

Smoke emitted at 300 F this was a fast happening event as the internal temperature rise was so rapid . Device vented at side of base at 643 F and base did not fail till 1436 F was achieved at this point spark was applied and fumes ignited . Heater instantly burned out and fire was extinguished . Reading for this test were in approximately 20 second intervals .

#### IV . Conclusions .

Devices will not ignite with heat alone , not allowing it to be a self sustaining thermal event . There must be smoke present from the plastics and a spark for the ignition of the device to be realized . The device must be open to atmosphere for the introduction of Oxygen to sustain ignition .

#### Terminal / Heater Attachment



T1-NHTSA 012427



TI-NHTSA 012428

~ 7-8-91  
L. Cambra

### Voltage Resistance Test

Test : Using one device measure resistance in Ohms using a standard VOM and record reading.

While observing exposed contacts at T2 and support ring through a microscope increase voltage with hy-pot test equipment until breakdown of resistance is seen and record voltage.

Repeat this sequence three time and record results

Resistance	Hy-pot
1) OPEN CIRCUIT	400 VOLTS
2) OPEN CIRCUIT	450 VOLTS
3) OPEN CIRCUIT	400 VOLTS
4) 13.9 Ohms	INSTANT

Conclusion : Device contacts proved to be open but exhibiting a very small gap between ring and contact terminal . After three voltage cycles contacts seemed to weld together causing a closed circuit . Post test inspection could not determine place that actual contact was established .

Epsstein, Sally

---

From: Poelache, Gerhard [mailto:[gpoelache@mail.mci.net](mailto:gpoelache@mail.mci.net)]  
Sent: Wednesday, February 24, 1999 3:24 PM  
To: Rahman, Aziz  
Subject: PW: Search Results

Aziz -

I found only two references, and I'm not sure they apply to what you wanted. I find no published ignition temperature information - but would not flammable fluids (e.g. ATF, etc.) burn before plastic if ignition were prone?

<<SpecificMaterial.asp>> Meryl GTX 830 (you asked for 430, which is no longer listed...)  
<<SpecificMaterial.asp>> Celanex 4300

Are you sure we're not using the flame retardant grades of these polymers? Or the Heat Stabilized grades? These modifiers can make a huge difference in thermal capability / flame performance.

Call if you need more info. I did what I could on short notice, but our database link to Texas is down without a new account number. I'm looking into it for future use...

Regards, Best of Luck, and Good Health - Andy, #1242.

---

From: Andy Poelache [SMTP:[afoelache@ti.com](mailto:afoelache@ti.com)]  
Sent: Wednesday, February 24, 1999 2:33 PM  
To: [afoelache@ti.com](mailto:afoelache@ti.com)  
Cc: [rahman@ti.com](mailto:rahman@ti.com)  
Subject: Search Results

<http://www.matls.com/SpecificMaterial.asp?baseenum=0&ES31&group=General>

Advertise

on M&M

and many other companies

## NORYL GTX® 830 PPE+PA, 30% Glass Filler

**Category:** Polymer

**Subcategory:** Polyphenylene Ether/PPO; Thermoplastic; Nylon

**Close Analogs:**

Machinable sheet, rod, and tube (not moldable resin) are available from Boedeker Plastics, Inc., (800) 444-3483; E-mail: bpi@boedeker.com; [www.boedeker.com](http://www.boedeker.com).

**Key Words:** NORYL GTX 830 PPE+PA, 30% Glass Filler; Polyphenylene Ether; Polyamide; GE Plastics;

**Composition:**

**Material Notes:** Data provided by GE Plastics.

[Click here to see a list of companies that sell this material.](#)

PHYSICAL PROPERTIES	VALUES	COMMENTS	
Density, g/cc	1.33	ASTM D792	<a href="#">See other units</a>
Linear Mold Shrinkage, cm/cm	0.003	0.002-0.003 at 3.2 mm.	
MECHANICAL PROPERTIES	VALUES	COMMENTS	
Tensile Strength, Ultimate, MPa	198	ASTM D638	<a href="#">See other units</a>
Elongation %, break	7	ASTM D638	
Flexural Modulus, GPa	8.578	ASTM D790	<a href="#">See other units</a>
Flexural Yield Strength, MPa	248	ASTM D790	<a href="#">See other units</a>
Impact Strength, Izod, in J, J/cm, or J/cm <sup>2</sup>	1.05	J/cm; Notched, 23°C	
THERMAL PROPERTIES	VALUES	COMMENTS	
Deflection Temperature at 0.45 MPa, °C	254	ASTM D648	
Deflection Temperature at 1.6 MPa, °C	240	ASTM D648	

TM-NHTSA 012431

Vicat Softening Point, °C	248	ASTM D1525
Maximum Service Temperature, Air, °C	50	RTI Mechanical without Impact. RTI Mechanical with Impact is 50°C. RTI Electrical is 50°C.
UL RTI, Electrical, °C	50	
UL RTI, Mechanical with Impact, °C	50	
UL RTI, Mechanical without Impact, °C	50	
Flammability, UL94 (HB-V-0; 4W-V-1; 3W-V-2; 1W-HB)	1 (HB)	HB UL94 Rating, V-Series at 1.6 mm.
<b>ELECTRICAL PROPERTIES</b>	<b>VALUES</b>	<b>COMMENTS</b>

Advertising with  
The Web  
www.mouser.com/PropertiesListings

[Click here to see a list of companies that sell this material.](#)

[Return Home](#)

[Return to Search Page](#)

# Aeronautic Composites, Inc.

Supplier of Composite Materials

## Ticona Celanex® 4300 Polyester (PBT), 30% Glass-Fiber

**Category:** Polymer

**Subcategory:** Polyester, TP; Thermoplastic; Polybutylene Terephthalate (PBT)

**Close Analogs:**

Machinable sheet, rod, and tube (not moldable resin) are available from Boedeker Plastics, Inc., (800) 444-3483; E-mail: bpi@boedeker.com; [www.boedeker.com](http://www.boedeker.com).

Data provided by Ticona.

**Key Words:** Ticona Celanex 4300 Polyester (PBT), 30% Glass-Fiber; Polybutylene Terephthalate; Hoechst Celanese Corporation;

**Composition:**

**Material Notes:** Good impact strength

[Click here to see a list of companies that sell this material.](#)

PHYSICAL PROPERTIES	VALUES	COMMENTS	
Density, g/cc	1.53	ASTM D792	See other units
Linear Mold Shrinkage, inches	0.004	Flow Direction	
Water Absorption, %	0.01	ASTM D570	
Hardness, Rockwell M	91	ISO 2039-2	
MECHANICAL PROPERTIES	VALUES	COMMENTS	
Tensile Strength, Ultimate, MPa	130	ISO 527	See other units
Elongation %; break	3	ASTM D638	
Flexural Modulus, GPa	9	ISO 178	See other units
Flexural Yield Strength, MPa	205	ISO 178	See other units

TI-NHTSA 012433

Impact Strength, Izod, In J, N/cm, or J/cm <sup>2</sup>	1.15	J/cm <sup>2</sup> ; Notched; ISO 180/1A	
<b>THERMAL PROPERTIES</b>	<b>VALUES</b>	<b>COMMENTS</b>	
Deflection Temperature at 0.48 MPa, °C	220	ISO 75	
Deflection Temperature at 1.8 MPa, °C	200	ISO 75	
Maximum Service Temperature, Air, °C	200	Deflection Temperature at 1.8 MPa load	
Flammability, UL94 (5-V-0; 4-V-1; 3-V-2; 1-HB)	1 (HB)	HB At 0.6 mm; UL94	
<b>ELECTRICAL PROPERTIES</b>	<b>VALUES</b>	<b>COMMENTS</b>	
Electrical Resistivity, Ohm-cm	1E+16	Lower Limit; ASTM D237	See other entry
Dielectric Constant, Low Frequency	3.8	100 Hz	
Dielectric Strength, kV/mm	22	3.2 mm; 50% RH; ASTM D149	See other entry
Dissipation Factor, Low Frequency	0.002	100 Hz	
Comparative Tracking Index, V	500	ASTM D3635	



[Click here to see a list of companies that sell this material.](#)

[Return Home](#)

[Return to Search Page](#)

TRANSA 01243



TEXAS  
INSTRUMENTS

FEB 24 1999 11:14

PAGE.01

38295153

**FACSIMILE TRANSMITTAL**

**TO:**

Name: Aziz Rahman  
Location: (at Ford)

Mail Station:

Phone Number:

FAX Number:

**FROM:**

Steve Beingshaw  
TEXAS INSTRUMENTS INC

Phone Number:

FAX Number:

Total number of pages (including header page): 3

**COMMENTER:**



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99


4. Down stream short to ground causes high current to pass through the switch

2. 12V Battery source to drive corrosion and provide energy

5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.


1. Water enters the switch cavity

3. Contact arm corrosion increases resistance (heater wire).




## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
1. Water enters the switch cavity
2. 12V Battery source to drive corrosion and provide energy
3. Contact arm corrosion increases resistance (heater wire).
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch



1. Water enters the switch cavity

2. 12V Battery source to drive corrosion and provide energy
3. Contact arm corrosion increases resistance (heater wire).

4. Down stream short to ground causes high current to pass through the switch
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.



TEXAS  
INSTRUMENTS


\* Apply  
In 3d format  
Ford can control

(10% propylene)

## Brake Pressure Switch

Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive corrosion and provide energy
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any scaling is present a fire can start, burning the plastic.



1. Water enters the switch cavity

3. Contact arm corrosion increases resistance (heater wire).

Epsenin, Sally

---

From: Dague, Bryan [bdague@mail.mt.edu]  
Sent: Wednesday, February 24, 1999 10:17 AM  
To: Rahman, Aziz  
Subject: test report update

**Test Notes**

Last updated: 2/23/99

**Ignition Re-creation:**

Objective - to recreate the conditions that caused an engine fire in the application.

**Description:**

1. 10 switches are filled with a mix of brake fluid, water, and detergent. 2 switches are filled with each of the following concentrations: 0%, 4%, 6%, 10%, and 75%. 14 volts is being applied to 1 terminal and the hexport is grounded. Current flow varies from about 0.5 mA to a high of about 5.0 mA. 0% switches were removed for #3 called out below.

2. On 2 of the above switches approximately 1 amp is being conducted through the terminals in-order to create heat in the switch.

**Results to date:**

Repeated refills yielded no significant temperature increase. In fact, current flows have decreased. Fluid has discolored. This test was suspended on 2/21/99. Internal inspection is planned for later today.

**Weibull Testing:**

This testing is complete. See specific test report.

**Short to ground (inside switch):**

This test is complete. See specific test report.

**Weac Correlation:**

This testing is complete. See specific test report.

**Auto-ignition testing:**

**Ignition via heating element:**

Objective is to get a fire started within the switch by installing a very small electrical heating element. With a small heating element built into a switch, we will fill the connector cavity with brake fluid, and slowly increase the current in the heating element. We will increase the current until ignition, or until the heating element burns out (continuity is lost).

**Samples tested:**

- 1) Dry
- 2) Pure brake fluid with metal shavings
- 3) 6% brake fluid solution

**Results:**

If a reliable heating element can be constructed inside the contact cavity, we have been able to increase the internal temperature of the switch to a high of 800 degrees F. Typically, we see smoke around 675 degrees F, and the base melts and falls off to the side as it approaches 800F.

By adding an ignition source (arc or open flame), we have been able to ignite the smoke and plastic.

**Conclusions:**

- 1) heat alone will not create a fire - must have a spark or open flame to ignite.
- 2) Brake fluid in the cavity actually slows the ignition process down - probably due to cooling effects.
- 3) 2 to 4 watts is required to attain the temperatures mentioned above.

Creating a heating element with corrosion:  
The purpose of this test is to increase the contact's arm enough to generate the 2 to 4 watts needed to start smoking.

Filling the switch with salt water and holding the arm at 14 volts and export at ground is generating corrosion.

Results:

Resistance is being measured today.

DOE:

The equipment needed to modify the cycles arrived this morning. We are working to get the following parts on cycle today:

12 switches with snap discs and 0% water in the brake fluid

12 switches with cut snap and 0% water in the brake fluid.

12 switches with snap disc and 5% water in the brake fluid.

12 switches with cut snap and 5% water in the brake fluid.

2 switches from each group will have the Ford loads applied.

Estimated running time for this test is 2 weeks. Results will be presented in Weibull plot format.

End of document.



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99



4. Down stream short to ground causes high current to pass through the switch

2. 12V Battery source to drive convection and provide energy

5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any oxygen is present a fire can start, burning the plastic.

1. Water enters the switch cavity

2. Contact arm corrosion increases resistance (heater wire).



CONFIDENTIAL

## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99


4. Down stream short to ground causes high current to pass through the switch

2. 12V Battery source to drive corrosion and provide energy

6. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.

1. Water enters the switch cavity

3. Contact arm corrosion increases resistance (heater wire).



Preliminary Report - Texas Instruments  
February 24, 1999

**PRELIMINARY**

Ford '92 Town Car Thermal Event

Per Ford's request to try to recreate ignition of a fire in a TI brake pressure switch we have completed the following analysis:

A minimum of the following components are needed to cause a fire:

Energy Source  
Fuel  
Oxygen  
Ignition source (spark)

One prevailing theory by Ford has been that if a fire was to start within the brake pressure switch, the energy source would be from the voltage applied to the switch (directly connected to battery) and excessive current flowing through the switch due to an electrical short. There are three known ways an electrical short can occur and result in high current through the switch:

1. By a highly conductive fluid shorting the electrical switch terminals to the internal cup, which is connected to the vehicle chassis ground.
2. By the contact arm detaching from the terminal and shorting the terminal to the same cup mentioned above.
3. By a short outside of the switch that results in high current through the switch terminals.

Initial testing was focused on number 1 above. By loading various switches with brake fluid, brake fluid with water, and brake fluid with water and metal filings, we have not been able to get high enough conductivity within the fluid to get more than about 5ms of current to flow. This current is not high enough to cause any significant heating of the pressure switch (less than 5 degrees F delta T from our tests).

Conclusions: We have not been able to get enough conductivity through contaminated brake fluid to provide enough current for a high delta T.

Number two above seems unlikely because analysis of the Reddick switch, which was in a fire, showed no arcing marks on the cup. In our experience the presence of arcing marks would indicate that metal was shorting to the cup.

Conclusions: The contact arm did not cause a short in the switch

Initial testing of number three above included driving about one amp of current through the switch terminals. This resulted in very little heating due to the low resistance of the contact arm and switch terminals (about 30F delta T). We then added a heater wire into the switch (about 0.5 ohms resistance) and two wires spaced a small gap apart and tied to a hypot tester to create a spark. About three volts and one amp powered the heater (this condition varied as the temperature increased). The heater boiled off the brake fluid and then started to melt the plastic connector. As the plastic connector melted smoke came out of the switch. The hypot tester was turned on to generate a continuous sparking condition but no fire started. Eventually the plastic melted to the point that it broke open exposing room air to the inside of the switch. It was at this point that the fire started, burning the connector. This test was repeated on a switch without brake fluid in the connector with essentially the same results.

**Conclusions:**

1. With enough heat and a spark for ignition the plastic can ignite.
2. Brake fluid in the connector slows down the process keeping the system cool.
3. There is not enough oxygen in the sealed switch to ignite the plastic.

Based on the results of these tests, our theory of what could cause a brake pressure switch to ignite is as follows:


1. The contact arm becomes corroded (probably through water entering the connector cavity) increasing its resistance.
2. There is an electrical short outside the switch that drives high current through the switch.
3. The high current through the contact arm dissipates power due to the increased resistance causing the switch to heat up melting the plastic.
4. Eventually the plastic opens allowing oxygen into the switch.
5. Arcing occurs either across the switch contacts or within the corroded contact arm.

We are currently running tests where we are trying to reproduce the fire using the contact arm as the heater.

**PRELIMINARY**

TI Proprietary Information: Attorney-Client Privilege Invoked

Figure 3.




REV. 24. 98. 12115

5082163153

PAGE .64

TI-NHTBA 012448

Figure 1.



FEB 24 '95 12:14

500000153

PAGE. 02

TI-NHTSA 012447


FEB-24-99 WED 6:18 PM TEXAS INSTRUMENTS

FAX NO. 5082363153

P.03

TI Proprietary Information: Attorney-Client Privilege Invoked

Figure 2.



FEB 24 '99 12:18

5082363153

PAGE.03

TI-NHTSA 012446



TEXAS  
INSTRUMENTS

**FACSIMILE TRANSMITTAL**

**TO:** Name: Azz Rahman  
Location: (at Ford)  
Mail Station:  
Phone Number:  
FAX Number:

**FROM:** Steve Bevington  
TEXAS INSTRUMENTS MS  
Phone Number:  
FAX Number:


Total number of pages (including header page): 3

**COMMENTS:**



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive corrosion and provide energy
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.



1. Water enters the switch cavity


2. Contact and corrosion increases resistance (faster melt).

CONFIDENTIAL



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

1. Water enters the switch cavity
2. 12V Battery source to drive corrosion and provide energy
3. Contact arm corrosion increases resistance (heater wire).
4. Down stream short to ground causes high current to pass through the switch
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any smoke is present a fire can start, burning the plastic.



CONFIDENTIAL


TI-HHTSA 012451




## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive corrosion and provide energy
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.

1. Water enters the switch cavity
3. Contact arm corrosion increases resistance (heater wire).



CONFIDENTIAL



Corrosion - Internal terminals to case ground

Q - could it happen w/o case ground  
 Q - could it happen w/o brake fluid (old & dirty)

What's the Heater R?

- 1. Thru corroded ~~term~~ & contact & terminal
- 2. Thru remains of ~~the~~ Spring arm between terminals
- 3. Thru remains of spring arm to case
- 4. Between terminals in final part

What does the high:

- Current
- To case too
- \* ① #3 above
  - \* ② clutch coils burns out.
  - ↳ plot V vs i for coil

If what happened to quick/soaker switches / brake fluid at water

- new parts / 1985?


g. High temp plastic



## Brake Pressure Switch Potential Thermal Event Theory - 2/24/99


L00000005

4. Down stream short to ground causes high current to pass through the switch
2. 12V Battery source to drive connection and provide energy
5. Plastic connector melts. Once it opens, oxygen enters the switch cavity. If any arcing is present a fire can start, burning the plastic.
1. Water enters the switch cavity.
3. Contact arm corrosion increases resistance (heater wire).



## **Brake Pressure Switch Function-**

- Provide power to Speed Control Clutch circuit.  
Clutch engages servo-motor to pull throttle cable.
- Provide redundant sensing of brake application independent of the primary system deactivation mode by disconnecting power to clutch circuit causing servo-motor to release throttle cable.
  - Under Hard Braking only
  - Stop lamp signal to primary (normal braking)



TM-NHTSA-012456