

EA02-025


**TEXAS INSTRUMENTS,
INC.'S 9/10/03
ATTACHMENT**

REQUEST NO. 7


BOX 8

PART A-U


PART S



TL-NHTSA 013245




TI-NHTSA 013248




TI-NHT8A 013247




TI-NHTSA 013248




TI-NHTSA 013249



TI-NHTSA 013250





TI-NHTSA 013252


1999 3 31 11:46:21 AM MVC-FD91

Digital Mavica images

5 mavica images		889 Kbytes free	
<u>MVC-001X.JPG</u>	1999 3 31 11:45:40 AM		
<u>MVC-002X.JPG</u>	1999 3 31 11:45:50 AM		
<u>MVC-003X.JPG</u>	1999 3 31 11:45:58 AM		
<u>MVC-004X.JPG</u>	1999 3 31 11:46:10 AM		
<u>MVC-005X.JPG</u>	1999 3 31 11:46:20 AM		

C020

TI-NHTSA 013253



TI-NHTSA 013254




TI-NHTSA 013255



TI-NHTSA 013256



TI-NHT8A 013257



TI-NHTSA 013258

TI-NHTSA 013289

131



4/10/99 10:00 AM


TI-NHTBA 019260



4/7/99 10:01 AM



TI-NHTSA 013261



TXNH78A 013262

131

3/1/99 9:57 AM

TECHNICAL SERVICE LABS

LOG NO. 12800
TEST NO. 152762

TEST NO. 152762

PGC I.D.	<u>127</u>	STATE YOUR PROBLEM OR SAMPLE DESCRIPTION	INFORMATION DESIRED:
REQUISITOR	<u>357</u>		
PRODUCT CODE	<u>089</u>	Metals and water in brake fluid may effect switch performance.	① Water content ② Metal Content Cu Fe Cr
REQUISITOR	<u>S. Mulligan</u>		
FAIL STATION	<u>12-29</u>		
EXTENSION	<u>2535</u>		
MSB ID	<u>SEAM</u>		
DATE SUBMITTED	<u>03/23/99</u>		
DATE REQUIRED			
NO. OF SAMPLES	<u>(3)</u>		
COMPOSITION	<u>Used Brake Fluid</u>		

REPORT OF RESULTS:

DATE RECEIVED 3-23-99

DATE OUT 4-6-99

TECHNICIAN	<u>72</u>		
HOURS WORKED			
PROCEDURE USED	<u>TSS-C-181, general 1/2 pg. 109</u>		

*PGC I.D.

MC-325	TM-431	CLKE-122	FACIL-514
PC-127	WIRE-432	CAN-854	FACIL-521
VERS-188	EPO-821	AD DEV-258	FACIL-531
APGC-483	PEP-822	EMCD-877	STAFF-885
IMD-430	CSD-835		

TECHNICAL SERVICE LABS

LOG NO. 12800

TEST NO. 152762

TEST NO. 152762

DATE	03/11/99	DESCRIPTION OF WORK	INFORMATION DESIRED
TIME	07:00	Water in brake fluid may affect switch performance	②
MAKE	Milliken		
MODEL	42-29		
YEAR	2535		
TESTER	SEBA		
DATE	6/23/99		
TIME	08:00		
MAKE	USA		
MODEL	Brake Fluid		

REPORT OF RESULTS:

DATE RECEIVED 3.11.99 DATE OUT 4.6.99 *John C. J.*

TECHNICIAN	
HOURS WORKED	
PROCEDURE USED	<u>TSL-6-181, General TX pg. 69</u>

PCC I.D.

- | | | | |
|----------|----------|------------|-----------|
| MC-388 | TM-431 | CLKE-122 | FACIL-514 |
| PC-187 | WRIS-432 | CAN-854 | FAGIL-521 |
| VERB-188 | EPD-521 | AD DEV-288 | FAGIL-531 |
| AFCC-453 | PEP-522 | EMCD-577 | STAFF-555 |
| MD-430 | CSD-535 | | |

Epstein, Sally

From: Mulligan, Sean [smulligan@gmail.com]
Sent: Wednesday, April 27, 2005 8:51 AM
To: Rahman, Aziz
Subject: Ford Relay



relay.ppt



relay_testsetup.ppt

Hi Aziz,

Here are the proposed relay schematics.
relay.ppt shows the Ford application
relay_testsetup is our test setup.


I am getting confirmation from Fred Porter that this is indeed the proposed setup. I will notify when I get results.

All the best,

Sean

<<relay.ppt>> <<relay_testsetup.ppt>>


TI-NHTSA 013265



TI-NHTSA 013266

TI Test Setup

14 Volts DC



TI-NHTSA 013267

Epstein, Sally

From: Roy, Norman [nroy@email.mc.ti.com]
Sent: Thursday, April 08, 1999 8:08 AM
To: McGuirk, Andy
Subject: FW: Materials Recommendations for Flammability Issue

Andy,

Attached is the reply from Ticona regarding material pedigree with additional info regarding effect of colorants. The current runnerless system in the 46515 mold uses heat pipe technology that is not recommended for LCP materials. We are also getting an answer on its compatibility with the Zytel material.

Regards,

Norm

From: Dunn, Kevin
Sent: Tuesday, April 06, 1999 9:52 AM
To: Roy, Norman
Subject: FW: Materials Recommendations for Flammability Issue

From: kprice@ticona.com[SMTP:kprice@ticona.com]
Sent: Tuesday, April 06, 1999 9:45 AM
To: kdunn@email.mc.ti.com
Cc: rfyurachek@ticona.com
Subject: RE: Materials Recommendations for Flammability Issue

Mr. DUNN,

The samples sent to you labeled as Celanex 3316 were in fact Celanex 3316. A non-technical test, such as exposing a sample to a single kitchen match under non-controlled conditions, will yield misleading results. The UL-94 flammability tests are very specific in nature. Items which must be carefully controlled include sample orientation (vertical or horizontal), sample size and thickness, burner size and regulator, type of gas used to supply burner, flame height, temperature and relative humidity. The time that the flame is applied and the relative orientation of the flame to the specimen are also carefully controlled.

I can send you a copy of the procedure, but in order to perform the test properly, you must have the right equipment. If you want a copy, please provide your fax number.

The tensile bar probably behaved better because it was thicker. Colorants can have an effect on the flammability. We have pre-colored materials which have been rated in the UL-94 test. For example, Celanex 3316 natural is rated V-0 down to 0.38 mm thickness, while all other colors are rated V-0 down to 0.75 mm thickness. The natural material is more robust in its flame retardancy.

Celanex 3316 has been successfully used in hot runner systems.

Ken Price

TI-NHTSA 013268

-----Original Message-----

From: Yurachek, Robert, TP/US
Sent: Tuesday, April 06, 1999 12:55 AM
To: Price, Kenneth, TP/US
Subject: FW: Materials Recommendations for Flammability issue
Importance: High

Ken:

Please contact Kevin and respond to his request. Thanks and please copy me.

Bob

-----Original Message-----

From: Dunn, Kevin (mailto:kdunn@email.mc.ti.com)
Sent: Monday, April 05, 1999 2:52 PM
To: rfyurachek@ticona.com
Subject: FW: Materials Recommendations for Flammability issue

Hi Bob, Would you please verify that the test bars were 3316 material. Also please check for alternatives.

As you can see, things are getting more attention at the customer.

Kevin

From: Roy, Norman
Sent: Monday, April 05, 1999 9:00 AM
To: Dunn, Kevin
Subject: FW: Materials Recommendations for Flammability issue

Kevin,

Would you please follow-up with Ticona to insure the sample of Celanex 3316 was indeed that. Also would adding colorant reduce the V-0 flammability rating of the sample Ticona submitted. Feedback from our customer is that the 3316 was no better than the 4300 material when subjected to a non-technical type of flammability test, i.e., "the kitchen match test". However, it was reported that the tensile bars behaved better.

The customer is now getting input to move to a higher melt temperature material such as an LCP that would, in addition to a V-0 rating, provide the flammability resistance they need. Another material being suggested is Dupont Zytel HTW FR52G30BL which is lower cost. Does Ticona have any recommendations keeping in mind that the mold is equipped with a Kona hot runner system?

Please get a response from Ticona on these questions ASAP.

Regards,

Norm

From: McGuirk, Andy
Sent: Thursday, April 01, 1999 5:44 PM
To: Porter, F.D.; 'Steve Reimers'
Cc: Roy, Norma; Dague, Bryan
Subject: RE: Materials Recommendations for Flammability issue

Steve, got your voice mail and did act upon it.

norm roy is our in-house plastic molding coordinator and has
initiated considerations of various plastics. our first concern was 'knit
line' integrity of the LCP which might create a mechanical weakness issue.
alternates were being reviewed.


also, norm was going to review our celanex 3314 pedigree to assure
it was what it should have been as it 'acted' too similar to 4300.

1999 4 8 7:50:44 AM MVC-RD91

Digital Mavica Images

8 mavica images		40 Kbytes free	
<u>MVC-001K.JPG</u>	1999 4 7	3:05:46 PM	
<u>MVC-002K.JPG</u>	1999 4 7	3:05:56 PM	
<u>MVC-003K.JPG</u>	1999 4 7	3:06:04 PM	
<u>MVC-004K.JPG</u>	1999 4 7	3:06:14 PM	
<u>MVC-005K.JPG</u>	1999 4 7	3:06:20 PM	
<u>MVC-006K.JPG</u>	1999 4 8	7:48:46 AM	
<u>MVC-007K.JPG</u>	1999 4 8	7:50:08 AM	
<u>MVC-008K.JPG</u>	1999 4 8	7:50:44 AM	

TI-NHTSA 013271




TI-NHTSA 013272



TI-NHTSA 013273




TI-NHTSA 013274




TI-NHT8A 013275




TI-NHTSA 013278



TI-NHTSA 013277



TI-NHTSA 013278



TI-NHTSA 013279


1999 4 8 8:18:56 AM MVC-FD91

Digital Mavica Images

1 mavica image 1210 Kbytes free

MVC-001X.JPG 1999 4 8 8:18:56 AM

TI-NHTSA 013280



TI-NHTSA 013281

1999 4 12 2:17:24 PM MVC-FD91


Digital Mavica images

8 mavica images		14 Kbytes free	
<u>MVC-001X.JPG</u>	1999	4 9	3:33:26 PM
<u>MVC-002X.JPG</u>	1999	4 9	3:33:50 PM
<u>MVC-003X.JPG</u>	1999	4 9	3:34:32 PM
<u>MVC-004X.JPG</u>	1999	4 9	3:36:08 PM
<u>MVC-005X.JPG</u>	1999	4 12	2:00:48 PM
<u>MVC-006X.JPG</u>	1999	4 12	2:01:02 PM
<u>MVC-007X.JPG</u>	1999	4 12	2:01:38 PM
<u>MVC-008X.JPG</u>	1999	4 12	2:17:24 PM

This document contains the following shortcuts:

Shortcut Text	Internet Address
MVC-001X.JPG	file:///F:/Disc%2025/MVC-001X.JPG
MVC-002X.JPG	file:///F:/Disc%2025/MVC-002X.JPG
MVC-003X.JPG	file:///F:/Disc%2025/MVC-003X.JPG
MVC-004X.JPG	file:///F:/Disc%2025/MVC-004X.JPG
MVC-005X.JPG	file:///F:/Disc%2025/MVC-005X.JPG
MVC-006X.JPG	file:///F:/Disc%2025/MVC-006X.JPG
MVC-007X.JPG	file:///F:/Disc%2025/MVC-007X.JPG
MVC-008X.JPG	file:///F:/Disc%2025/MVC-008X.JPG


TI-NHTSA 013282




TI-NHTSA 013283




TI-NHTSA 013284




T1-NHTSA 013285



TI-NHTSA 013288



TI-NHTSA 013287



TI-NHTSA 013288



TI-NHTSA 013289



TI-NHTSA 013290

1999 4 12 2:18:44 PM MVC-FD91

Digital Mavica images


3 mavica images 924 Kbytes free

<u>MVC-001X.JPG</u>	1999	4	12	2:18:08	PM
<u>MVC-002X.JPG</u>	1999	4	12	2:18:18	PM
<u>MVC-003X.JPG</u>	1999	4	12	2:18:44	PM

This document contains the following shortcuts:

Shortcut Text	Internet Address
MVC-001X.JPG	file:///F:/Disc%2026/MVC-001X.JPG
MVC-002X.JPG	file:///F:/Disc%2026/MVC-002X.JPG
MVC-003X.JPG	file:///F:/Disc%2026/MVC-003X.JPG


TI-NHTSA 013201



TI-NHTSA 013292



TI-NHTSA 013293



TI-NHTSA 013294

1999 4 13 12:37:50 PM MVC-FD91

Digital Mavica images

4 mavica images 512 Kbytes free

<u>MVC-001X.JPG</u>	1999	4	13	12:25:12	PM
<u>MVC-002X.JPG</u>	1999	4	13	12:25:38	PM
<u>MVC-003X.JPG</u>	1999	4	13	12:25:58	PM
<u>MVC-004X.JPG</u>	1999	4	13	12:37:50	PM

This document contains the following shortcuts:

Shortcut Text	Internet Address
MVC-001X.JPG	file:///F:/Disc%2027/MVC-001X.JPG
MVC-002X.JPG	file:///F:/Disc%2027/MVC-002X.JPG
MVC-003X.JPG	file:///F:/Disc%2027/MVC-003X.JPG
MVC-004X.JPG	file:///F:/Disc%2027/MVC-004X.JPG

TI-NHTSA 013295


Unable to print document.

The document could not be found.


TI-NHTSA 013286



TI-NHTSA 013297



TI-NHTSA 013298



TI-NHTSA 013299

1999 4 13 12:37:27 PM MVC-FD91

Digital Mavica Images

5 mavica images 434 Kbytes free

<u>MVC-002X.JPG</u>	1999	4	13	12:27:40	PM
<u>MVC-003X.JPG</u>	1999	4	13	12:28:28	PM
<u>MVC-004X.JPG</u>	1999	4	13	12:28:40	PM
<u>MVC-005X.JPG</u>	1999	4	13	12:31:02	PM
<u>MVC-006X.JPG</u>	1999	4	13	12:37:26	PM

This document contains the following shortcuts:

Shortcut Text	Internet Address
MVC-002X.JPG	file:///F:/Disc%2028/MVC-002X.JPG
MVC-003X.JPG	file:///F:/Disc%2028/MVC-003X.JPG
MVC-004X.JPG	file:///F:/Disc%2028/MVC-004X.JPG
MVC-005X.JPG	file:///F:/Disc%2028/MVC-005X.JPG
MVC-006X.JPG	file:///F:/Disc%2028/MVC-006X.JPG

TI-NHTSA 013300

Thermal Cycle Fluid Ingress Test

Purpose : To determine if fluid (water) will ingress into a sealed device after exposure to thermal cycling .


Test : Devices will undergo a 72hr thermal cycle with temperatures ranging from 125c to -40c . Each cycle will have a 4 hr soak at temp and a ½ hr . transition time between temperature excursions .

Post thermal cycling devices will be submitted to a soak of 125c and immersed into a cold water bath of 0c . A small percentage of salt will be added to the water for tracing purposes . Devices will be submerged to the top of the connector only and wires will remain exposed to the air . A 30 minute temperature soak and 5 minute immersion time will be considered 1 cycle . This will be repeated for 10 cycles and after all 10 cycles the device will be submitted to a high voltage current leak test from wire leads to ground . After a 24 hr set at room temperature .


Results : All ten samples passed current leak test at 1500 volts . No arcing or leakage to ground was observed .




TI-NHTSA 013302




TI-NHTSA 013303



TI-NHTSA 013304



TI-NHTSA 013305



TI-NHTSA 013308

77PS Ford



Tests

TI-NHTSA 013307




2

TI-NHTSA 013308



TI-NHTSA 013309



TI-NHTSA 013310



TI-NHTSA 013311



TI-NHTSA 013312




TI-NHT8A 013313




TI-NHTSA 013314



TI-NHTSA 013315




TI-NHTSA 013318



TI-NHTSA 013317



TI-NHTSA 013318



TI-NHTSA 013319

Brake Pressure Switch Test Log, Updated 4/29/99

Category	Test	Location	Test Parameters	Results Update
no Strain	1	TI	Vary water concentrations in 'new' Brake Fluid	250+ hours, Current draw in the 0.5mA to 5mA range
4 Potential Ignition			14Vdc to one terminal, hezport grounded	Fluid has discolored.
1 Switch			Water Conc: 4%, 8%, 10%, 76%	No Significant Temperature Rise. Test Suspended.
				Internal Analysis suspended.
	2	TI	New Brake Fluid	250+ hours. Constant temperature.
			1 Amp through switch terminals	No significant temperature rise with time
			14Vdc to one terminal, hezport grounded	Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Hezport Grounded	> 300 hours into test, max current 7mA
				No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Hezport Grounded, Ambient at 100 C	18 hours into test max current 5mA
				No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp
				Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition
				Test suspended.
	6	TI	Build heater elements into Switch. Heat till failure, include spitting. With Fluid & Dry	2 tested. Smoke observed, ignition observed on part wheater
				See attachment
				Test complete
				Brake fluid in cavity slows down heat build-up
				Smoke observed at 675 F, Base melts and falls off at 800 F
	6a	TI	Create heater by corroding spring arm Salt water solution, 14V between spring and hezport	One out of 15 devices increased resistance to 5 ohms.
				Others either vary low resistance or megohms
				It took about 100 hours to reach the 5 ohm stage.
				The 5 ohm device ignited under conditions similar to test 5.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 6% water solution into switch
				Current path is through hezport.
				See plots and video.

TI-NHTSA 013320

Brake Pressure Switch Test Log, Updated 4/29/00

				Additional test include tap water, old BF, new BF and other.
	6c	TI	Pure 'new' brake fluid with metal shavings	Metal shavings do not contribute significantly to brake fluid conductivity
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psi pressure pulses at 135C per EB	First leak observed at 720,000 cycles. Test Completed. See attached Weibull Chart
High Cycle Wear	8	TI	0-1400 psi pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Conditions	9	Central Labs	Field returns, from dealer lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors Effecting Diaphragm Wear rupture test	10	TI	Very water combinations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0 % water in BF 12 snap + 12 quiet switches w/ 5 % water in BF	Test Report being written. Investigation continues Suspended at 1.3 million cycles with no leaks observed Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess wiring intricacies.
In-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT.....see Ford charts...>600k in car?
Brake fluid analysis Lead fluid at master cylinder.	11a	TI	Analyses used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEB) for metal and water content.	Test complete. UMC: Cu = 415 (ug/ml), Fe = 5.8 (ug/ml), Cr = 0.08 (ug/ml), 1.1 %H2O. UCA: Cu = 682 (ug/ml), Fe = 8.5 (ug/ml), Cr = 1.9 (ug/ml), 1.1 %H2O. NEB: Cu = <0.01 (ug/ml), Fe = 0.92 (ug/ml), Cr = <0.01 (ug/ml), 0.3 %H2O.
Spark Plug Study	12	Central Labs	Determine if arcing/spark forms in switch using splash tests and high speed video Use dry switches as well as switches with varying brake fluid water ratios	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field vehicles & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete Analysis of switches in progress
Salt Ingress Tests	13a	TI	Repeat ignition simulation with different fluids 100 hour tests	Test complete 5% NaCl sample resulted in an ignition

TI-NHTSA 013321

Brake Pressure Switch Test Log, Updated 4/29/88

			5% NaCl in tap water	All brake fluid samples draw less than 3 mAmps. No corrosion
			rain water	Visible on brake fluid samples.
			(24) hour tests:	Rain water and tap water samples draw <10 mAmps and showed
			tap water	some signs of corrosion.
			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H ₂ O	
			new brake fluid	
			new brake fluid w/ 5% H ₂ O	
Design Of Experiments (2)	13b	TI	Very water concentrations in 'new' Brake Fluid	Test suspended. Analysis in process to assess test fixating.
Repeat of test 10			10 amp + 20 quiet switches w/ 0 % water in BF	
			10 amp + 20 quiet switches w/ 6 % water in BF	
Compatibility of Kapton with Oxalic Acid	14	D/S&H	Characterize change in properties of Kapton with various % oxalic acid in brake fluid.	Report expected from Dupont by 5/2/88.
Evaluation of Plastic Materials with Improved Parameters	18	TI	Assess properties and moldability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcones and Noryl ignited 3/5 and 2/5 trials ZYTEL samples tested 1/5 ignitions
Long duration brake fluid exposure test	14a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test in progress. (15) days to date. Used brake fluid current dropped off to <1/10 mAmps. New brake fluid hasport current remains low
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity in switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. circulated switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit test	18	TI	Repeat test 12a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (16) Amp circuit then place in relay circuit for (18) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or move toward ignition in lab Heater element was warm to the touch.

TI-NHTSA 013322