

**EA02-025**

**TEXAS INSTRUMENTS,  
INC.'S 9/10/03  
ATTACHMENT**

**REQUEST NO. 7**

**BOX 8**

**PART A-U**

**PART U**

**Currey, Pat**


---

**From:** Mulligan, Sean [smulligan@email.mc.tl.com]  
**Sent:** Sunday, April 25, 1999 11:50 AM  
**To:** McGuirk, Andy  
**Subject:** Document3



doc1.doc

<<Doc3.doc>>



**Currey, Pat**

---

**From:** Mulligan, Sean [smulligan@email.mc.ti.com]  
**Sent:** Sunday, April 25, 1999 6:19 PM  
**To:** McGuirk, Andy




7798flow\_2.ppt

<<7798flow\_2.ppt>>


All the best,

Sean P. Mulligan

Phone (508) 236-2535  
Fax (508) 238-3586



TI-NHTSA 013378



71-NHTSA 013379

D E V I C E #	GROUP NUMBER						# C Y C L E S
	G1	G2	G3	G4	G5	G6	
1			*A 44503		297283	243000	
2					297348	281012	
3						286712	
4						297283	
5						305241	
6							
7							
8							
9							
10							

\*A=Estimated total cycles are indicated number plus 425000

Note:

G1=77PSL2-1 IN 100% BRAKE FLUID  
 G2=77PLS3-1 IN 100% BRAKE FLUID  
 G3=77PSL4-1 IN 100% BRAKE FLUID  
 G4=77PSL2-1 IN 5% WATER/ 95% BRAKE FLUID SOLUTION  
 G5=77PSL3-1 IN 5% WATER/ 95% BRAKE FLUID SOLUTION  
 G6=77PSL4-1 IN 5% WATER/ 95% BRAKE FLUID SOLUTION

TI-NHTSA 013380

4/25/99 Sr

Long duration Brake Fluid Test. Passed

To date:

(6) Samples

2 Used Brake fluid → < 10 mAmp

4 New Brake Fluid → 1.3 - 17 mAmps steady

No sampls required refilling

50 SHEETS  
100 SHEETS  
200 SHEETS

20-141  
20-142  
20-144





Converter / Washer Measurements

From line today

Washer

± D  
.2960 ± 5/1000 same washer different place  
.2965 + 5/1000 same washer  
.2965 acceptable

Converter

.2890 ± 5/1000  
~~0.2890~~ ± 5/1000  
.2890 ± 5/1000  
.2890 ± 0


converter .2905

20-143  
20-143  
20-143

20-143  
20-143  
20-143




11:22AM to 12:30AM Temperature



TI-NHTSA 013383

11:22AM to 12:39PM



TI-NHTSA 013384

**Curry, Pat**

---

**From:** Mulligan, Sean [smulligan@email.mn.ti.com]  
**Sent:** Sunday, April 25, 1992 6:49 PM  
**To:** McGuirk, Andy



77P9flow\_2.ppt




TESTLOG 4-25.xls

<<77P9flow\_2.ppt>> <<TESTLOG 4-25.xls>>


All the best,

Sean P. Mulligan

Phone (508) 236-2535  
Fax (508) 236-3586



TI-NHTSA 013386



TI-NHTSA 013367

Brake Pressure Switch Test Log, Updated 3/10/89

Category	Yard	Location	Test Procedures	Results Update
Leak Classification of Fuel/air System in Switch	1	TI	Very water concentrations in "near" Brake Field 100% to one terminal (wired) suspended Water Comp. 0%, 0%, 0%, 10%, 20%	200+ hours. Current draw in the 4 Amp to 5A range Fuel log discontinued No significant Temperature Rise. Test Suspended Internal Analysis suspended
	2	TI	Very water concentrations in "near" Brake Field 1 Amp through switch terminals	200+ hours. Constant temperature No significant temperature rise with log Test Suspended
	3	AVT	"near" Brake Field in Switch 24 VDC to one terminal. Internal Suspended	> 200 hours with 20A, 20A current 7mA No significant change with time. Test ongoing
	4	AVT	"near" Brake Field in Switch, 24 VDC to one terminal. Internal Suspended. Ambient at 100 C	10 hours into test with current 60A No significant temperature rise with log. Test suspended
	5	AVT	"near" Brake Field in Switch, 16 Amps through switch terminals	Temperature rise of 20 C above room temp Data T recorded every 10 min at 20 C. Test suspended
	14	AVT	"near" Brake Field in Switch approx 60 Amps through switch terminals	Temperature rose to approx 270 F. No smoke. No sparks. Test suspended
	15	TI	Small amount electrolyte into Switch 100% full battery, electrolyte applied Wash fluid in the Clean "near" brake field with metal shavings 0% water that remains	Internal Battery electrical analysis observed on next delivery No attention Test complete Smoke that is coming from "near" field Smoke observed at 25 F, 30A current and later at 100 F
	16	TI	Current loading by operating spring with full water electrolyte. 100% between spring and terminal	One out of 15 devices passed minimum to 5 amps Current other very low resistance or resistance It took about 100 hours to reach the 5 amp stage The 5 amp device stopped every 10 minutes under 100 A
	17	TI	20-amp system that is unregulated capacitance and current log	Switch opened with repeated 20A, 20A current into switch Current path is through terminal Dry glass and metal Additional log records temperature 100 F, 100 F and other
Leak Classification of Pressure Switch	7	TI	10-1000 psi pressure system at 120C see 15	Test log suspended at 700,000 cycles Test Complete. See attached Visual Chart
Changeover Valve	8	TI	10-1000 psi pressure system at 120C	Test with 1000 cycle 2000 cycles, 1000000 cycles
100 psi on 1 gal Fuel Filter	9	Control Logic	Peak returns, from 1000 psi, 1000psi	Pass in Control Logic, see Fuel spreadsheet
100 psi on 1 gal Fuel Filter (10)	10	TI	Very water concentrations in "near" Brake Field 12 amp + 12 amp constant at 5% water in 100 12 amp + 12 amp constant at 5% water in 100	Test began heavy water concentrations system Suspended at 1.5 million cycles with no leaks observed Temp spikes suspended at 1.5 million cycles with 2 tests observed at 1.5M. Chart complete suspended at 100k cycles to assess battery alternative

TI-NHTSA 013388

Brake Pressure Switch Test Log, Updated 9/10/88

On-Board Diagnostics of Pressure & Temperature Profile in Test Car	11	NYT	Monitor Pressure and Temperature of Switch (warning for ABS and non-ABS) leading events	Test at NYT - see Test sheet - SWK in car?
Brake fluid available	12a	YI	Verify total brake fluid in test pump cylinder (MTC) and brake fluid in test pump (MCA) and also brake fluid (MCA) in wheel and water supply	Test complete MTC: C1 = 0.18 gpm, F = 0.58 gpm, C = 0.00 gpm, 11.000 MCA: C1 = 0.00 gpm, F = 0.58 gpm, C = 1.00 gpm, 11.000 MTC: C1 = 0.01 gpm, F = 0.58 gpm, C = 0.01 gpm, 11.000
Check the Study	13	Control Logic	Examine if necessary event in switch (switch logic and logic speed value) and dry switches as well as such has high voltage being sent out	Equipment set up as program at Control Logic YI Examined with no "dry switch" signal detected
Characteristics of switches captured from data (switch & other signals)	13	Control Logic	Characterize observed switch and chemical nature of electrical system	Done per 4-26 program procedure set up previously Analysis of switches in progress
Field Inspect Yacht	14a	YI	Inspect general situation with different levels 1000 bar tank 5% MTC in top water 5% water 1000 bar tank 1000 bar tank 1000 bar tank of 5% MTC 1000 bar tank 1000 bar tank of 0.5% MTC	Test complete 5% MTC sample (0.001) 11.000 All water level samples show 1000 bar tank. No concern water in 1000 bar tank 1000 bar tank for water samples show 0.5% MTC and showed some level of concern Check all entries in program
Design of Equipment (2) Report of test 10	14b	YI	Verify water concentrations in test Brake fluid 10 gpm + 20 gpm samples of 0.5% water @ 10 10 gpm + 20 gpm samples of 0.5% water @ 10	Test suspended - Analysis in progress to assess test strategy
Compatibility of System with Owner's Plan	14	Report	Characterize change in properties of System with various % usually 0.5% to 10% water	Report prepared (also Report by 1/2/88)
Evaluation of Plans (Mainline with Electrical) Purpose	15	YI	Assess program and capability of different levels of design (also with addition to improve safety and performance)	Test suspended Complete data from system 100 and 200 tests YI will complete test 100 system
Long duration tests that require test	16a	YI		Test in progress - 400 days by date 1000 bar tank current (logged off to 4000 testing) 1000 bar tank (current) current system for
Characteristics of Switch (Mainline)	16b	YI	Assess system capability in terms of pressure 1000 bar tank (0.5% water) 0.5% design 1000 bar tank (0.5% water)	Test complete - Analysis in progress of system capabilities 1000 bar tank (0.5% water) 0.5% design 1000 bar tank (0.5% water) 0.5% design 1000 bar tank (0.5% water) 0.5% design
Water Circuit	16	T2	Report 1000 bar tank (0.5% water) 0.5% design	Test complete - No problem - Continue with 1000 bar tank

TI-NHTSA 013389



Brake Pressure Switch Test Log, Updated 3/10/08

Test		Using switch to illuminate parking lights in (15) Amp	Insufficient voltage in circuit to operate or cause tested switch to fail
		Check three wires in relay circuit for (15) Amp.	Ampere obtained was lower in (30) Amp.
		Upon test, check power into terminal on switch.	

TI-NHTSA 013390

**Currey, Pat**

---

**From:** McGuirk, Andy [a-mcguirk@emsil.mc.tl.com]  
**Sent:** Monday, April 26, 1999 6:05 AM  
**To:** Warner, Pam  
**Subject:** FW:



77PSflow\_2.ppt



TESTLOG 4-25.xls


AUTOMOTIVE SENSORS AND CONTROLS QRA MANAGER  
34 FOREST ST W/S 23-05  
ATTLEBORO, MA 02703  
TEL : (508) 236-3080  
FAX : (508) 236-3745  
MOBILE: (508) 208-6119  
PAGE: (800) 467-3700 PIN 604-2044

-----  
**From:** Mulligan, Sean  
**Sent:** Sunday, April 25, 1999 7:49 PM  
**To:** McGuirk, Andy


<<77PSflow 2.ppt>> <<TESTLOG 4-25.xls>>  
All the best,

Sean P. Mulligan

Phone (508) 236-2535  
Fax (508) 236-3586



TI-NHTSA 013882



TI-NHTSA 013393


Grain Pressure Switch Test Log, Updated 3/16/99

Category	Test	Location	Test Description	Results Update
Lab Identification of Functional Location in Switch	1	II	Very minor overpressure in 'low' Strain Field 100% to one channel, impact prevented Water Cont: 0% 0% 0% 0% 0% 0%	200+ hours. Current data in the 1.5M to 2M range Field has deteriorated No significant temperature rise. Test suspended. Internal Analysis suspended.
	2	II	Very minor overpressure in 'low' Strain Field 1.5M through switch elements	200+ hours. Current temperature No significant temperature rise with time Test suspended
	3	AVI	'low' Strain Field in Switch, 24 VOC to cryo Temperature: 100K/100K	• 200+ hours with test, approx 100K/100K No significant change with time. Test ongoing.
	4	AVI	'low' Strain Field in Switch, 24 VOC to cryo (Temperature: 100K/100K, Ambient at 100C)	200+ hours. 200+ hours. 200+ hours. No significant temperature rise with time. Test suspended.
	5	AVI	'low' Strain Field in Switch, 10 VOC Temperature: 100K/100K	Temperature rise of 20 C above water temp No significant change with time at 20 C. Test suspended.
	6a	AVI	'low' Strain Field in Switch, approx 24 VOC Temperature: 100K/100K	Temperature rise of 20 C above water temp No significant change with time at 20 C. Test suspended.
	6	II	Minor leakage observed, system stopped at 100K/100K 200+ hours. 200+ hours. 200+ hours.	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.
	6b	II	Minor leakage observed, system stopped at 100K/100K 200+ hours. 200+ hours. 200+ hours.	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.
	6c	II	Minor leakage observed, system stopped at 100K/100K 200+ hours. 200+ hours. 200+ hours.	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.
	6d	II	Minor leakage observed, system stopped at 100K/100K 200+ hours. 200+ hours. 200+ hours.	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.
7	II	0-100% rate pressure, ambient at 100C	Test has returned to 100% rate pressure Test completed. See attached White Paper.	
8	II	0-100% rate pressure, ambient at 100C	Test has returned to 100% rate pressure Test completed. See attached White Paper.	
9	Control Lab	Field calibrations, 100% rate pressure	Field at Control Lab, 100% rate pressure	
10	II	Very minor overpressure in 'low' Strain Field 100% to one channel, impact prevented Water Cont: 0% 0% 0% 0% 0% 0%	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.	
11	AVI	Minor pressure rise, 100% rate pressure 100% to one channel, impact prevented Water Cont: 0% 0% 0% 0% 0% 0%	200+ hours. 200+ hours. 200+ hours. No significant change with time. Test ongoing.	

TI-NHTBA 013304



# Brake Pressure Switch Potential Thermal Event Theory Profile 4/26/99




TI-NHTSA 013306

© McQuay-Norris

CONFIDENTIAL

# Brake Pressure Switch Potential Thermal Event Theory Profile 4/26/99



CONFIDENTIAL

7-NHTBA 013397



Brake Pressure Switch Test Log, Updated 4/28/99

Category	Test	Location	Test Parameters	Results Update
Category: Ignition Switch	1	TI	Very water concentrations in 'new' Brake Fluid 140mic to one terminal, terminal grounded	250+ hours, Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended.
#10	2	TI	Water Conc 0%, 5%, 10%, 75% 2 on 2	Internet Analysis suspended.
	3	AVT	Very water concentrations in 'new' Brake Fluid 1 Amp through switch terminals	250+ hours, Constant temperature. No significant temperature rise with time Test Suspended.
	4	AVT	'new' Brake Fluid in Switch, 24VDC to one terminal, terminal Grounded	> 300 hours into test, test current 7mA No significant change with time. Test ongoing
	5	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal, terminal Grounded, Ambient at 100 C	18 hours into test with current 5mA No significant temperature rise with time. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch, 10 Amps through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
#1	6	TI	'new' Brake Fluid in Switch approx. 30 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	3es.		Build heater elements into Switch. Heat till failure, bubble sparking. Wipe Fluid & Dry	2 tested, Smoke observed, ignition observed on part whatever See attachment Test complete
#2	6a	TI	Pure 'new' brake fluid with metal shavings 5% brake fluid solution	Brake fluid in cavity stress down heat build-up Smoke observed at 375 F. Base melts and falls off at 800 F
			Create heater by corroding spring arm Salt water solution, 14V between spring and terminal	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or negative It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test d.
#3	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through terminal See plots and video Additional test in...

TMHTBA 013908

Brake Pressure Switch Test Log, Updated 4/26/90

			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2)	13b	TI	Vary water concentrations in 'new' Brake Fluid 10 amp + 20 quiet switches w/ 0% water in BF 10 amp + 20 quiet switches w/ 5% water in BF	Test suspended. Analysis in process to assess test failure.  DOE
Compatibility of Kepton in Oxalic Acid	14	Dupont	Characterize change in properties of Kepton with various % oxalic acid in brake fluid.	Report expected from Dupont by 5/2/90.
Corrosion of Plastic Materials with Improved Sealants	15	TI	Assess properties and suitability of different types of plastic resin with sealants to improve plastic part performance.	Test suspended. Chelator and Moly tested 3/5 and 2/5 days ZYTEL samples tested 1/5 ignition
Corrosion of Plastic in Duran Brake Fluid Case Test	15a	TI		Test in progress. (15) days to date. Used brake fluid current dropped off to <1/10 mAmp. New brake fluid current remains low
Orientation of Switch Position	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity.	Test complete. Ignition is independent of switch orientation. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit	16	TI	Repeat test 13a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (15) hrs. Repeat step, circuit power into heater on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Heater element was worn to the track.

TI-NHTBA 013389

Brake Pressure Switch Test Log, Updated 4/26/99

Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per LS	First leak observed at 726,000 cycles. <span style="float: right;">DOE</span>
Diaphragm Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear <span style="float: right;">CAR</span>
Field vs Lab Correlation	9	Central Labs	Field returns, from dealer lots, junkyards	Parts in Central Labs, see Ford spreadsheet
Design Of Experiments (1) Evaluating Factors	10	TI	Very water concentrations in 'new' Brake Fluid 12 snap + 12 quiet switches w/ 0 % water in BF	Test Report being written investigation continues. <span style="float: right;">DOE</span>
Effecting Diaphragm Wear Impulse test			12 snap + 12 quiet switches w/ 5 % water in BF	Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.3M. Quiet samples suspended at 500k cycles to assess flaring anomalies.
On-Vehicle Characterization of Pressure & Temperature Profile in Toss Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test of AVT...see Ford charts...>500k in car?
Brake fluid analysis Used fluid at master cylinder.	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. UMC: Cu = 415 (ppm), Fe = 5.6 (ppm), Cr = 0.08 (ppm), 1.1 %H2O. UCA: Cu = 582 (ppm), Fe = 5.7 (ppm), Cr = 1.9 (ppm), 1.1 %H2O. NEW: Cu = <0.01 (ppm), Fe = 0.92 (ppm), Cr = <0.01 (ppm), 0.3 %H2O.
Spark Arc Study	12	Central Labs	Determine if arcing occurs in switch using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water mores.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches retrieved from field junkyards & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Fluid Ingress Tests	13a	TI	Repeat ignition simulation with different fluids. (3) hour tests: 5% NaCl in tap water Tap water rain water (4) hour tests: used brake fluid	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mAmps and showed some signs of corrosion. Chemical analysis in process.

TI-NHTSA 013400

Spence, Bob

---

From: Mulligan, Sean [mailto:smulligan@nhtsa.nhtsa.gov]  
Sent: Wednesday, April 29, 2009 12:45 PM  
To: Sharpe, Robert  
Subject: For Andy McGuirk

W

objective\_results\_conclusions\_2.doc  
All the best,

Sean P. Mulligan

Phone (508) 236-2535  
Fax (508) 236-3586

TI-NHTSA 013401

## TI 77PS Test Synopsis Draft 4/28/99

This document is a synopsis of tests conducted by Texas Instruments during the 77PS investigation. The intent of this document is to highlight test findings which drove the investigation to its current state. Throughout the investigation, several tests were conducted with the same objective. When each objective was met, efforts were refocused to obtain a new level of understanding and to establish a new set of objectives. As such, tests have been categorized into (5) levels, representing the level of knowledge obtained from the group of tests conducted. Each level is listed below with a short description of the objective:

- Level 1: Create a switch ignition without any restrictions on methods.
- Level 2: Create a switch ignition using only items found in the switch operating environment.
- Level 3: Understand the ignition mechanism.
- Level 4: Compare factors contributing to ignition.
- Level 5: Evaluate recommendations.

Refer to Brake Pressure Switch Test Log.

**Level 1 Objective:** Determine if a switch ignition can occur in the laboratory and what conditions are required to create an ignition.

- Test 1

**Objective:** Determine if switch ignition can occur under the following conditions:

Switch contact flooded with brake fluid mixed with varying amounts of % H<sub>2</sub>O.  
14 volts applied to one terminal, second terminal electrically floating. (No electrical load across switch terminals).  
Switch housing electrically grounded.

**Results:**

- (8) samples were tested total:
- (2) with 4% H<sub>2</sub>O in brake fluid.
- (2) with 6% H<sub>2</sub>O in brake fluid.
- (2) with 10% H<sub>2</sub>O in brake fluid.
- (2) with 75% H<sub>2</sub>O in brake fluid.

No ignition occurred. No significant temperature rise observed in all samples. Current draw ranged from 0.5 mAmps to 5 mAmps over a period greater than (250) hours.

TI-NHTSA 013402

• Test 2

**Objective:** Determine if switch ignition can occur under the following laboratory conditions:

Switch contact flooded with brake fluid.

14 volts applied to one terminal, second terminal connected to a 14  $\Omega$  resistor tied to ground. (1 Amp load across switch terminals).

Switch hexport electrically grounded.

**Results:** (2) samples were tested. No ignition occurred. No significant temperature rise observed for a period over (250) hours.

**Conclusion:** A one amp load through switch terminals can not ignite brake fluid in the contact cavity of switches.

• Test 6

**Objective:** Determine if switch ignition can occur under the following conditions:

Heater element installed in contact cavity of the switch.

Power applied to the heating element until plastic base melts.

External spark applied to fumes.

Brake fluid present in the contact cavity (wet device) and not present in the contact cavity (dry device).

**Results:** (2) dry devices were tested and (1) wet device was tested. Ignition occurred in all devices.

**Wet device:** The internal temperature of a wet device reached 660°F. A hole burned through the base of the switch (close to the heating element). The externally applied spark ignited the fumes which engulfed the switch.

**Dry device:** The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The externally applied spark ignited the fumes which engulfed the switch.

**Conclusion:** A switch ignition can occur under the following laboratory conditions:

A heating element is installed in the switch contact cavity.

5 watts of power is applied to the heating element.

An external spark is applied to fumes.

Brake fluid does not contribute to the ignition process

TI-NHTSA 013403

**Level 2: Objective:** Determine if an ignition can occur using only switch components and elements found in the switch environment.

• **Test 6a**

**Objective:** Determine if corrosive degradation of switch electrical components can cause an increase in electrical resistance (and thus a source of heat) in the switch which may lead to an ignition.

**Results:** (1) out of (15) samples tested increased resistance to 5Ω. A 5% NaCl in H<sub>2</sub>O solution can corrode switch electrical components and cause an increase in electrical resistance. Repeated injections of the NaCl in H<sub>2</sub>O solution, with the switch powered, can cause a switch ignition.

**Conclusion:** A switch ignition can occur under the following conditions:  
5% NaCl in H<sub>2</sub>O solution is injected into contact cavity of a switch.  
14 Volts is applied to the switch.  
Hazport is grounded.  
Current is limited at 15 Amps.

• **Test 6c**

**Objective:** Determine if brake fluid with metal shavings is conductive enough to create an ignition.

**Results:** (3) devices with various size metal particles were tested. No significant current increase detected.

**Conclusion:** Metal shavings did not significantly increase conductivity brake fluid. Current levels measured were well below levels necessary to create an ignition.

• **Test 7**

**Objective:** Determine if switch meets cycle life specification.

**Results:** Tests made first quarter of 1999 show that switches exceed cycle life specification.  
In the first quarter of 1999, a total of (42) 77PSL2-1 snap switches were impulse tested to over 1,000,000 cycles with only (1) leak below 1,000,000 cycles which occurred at 728,000 cycles. A Weibull analysis of first quarter, 1999 tests showed 99.9% reliability at 500,000 cycles at 95% confidence level.

**Conclusions:** First quarter, 1999 tests confirm findings of impulse tests made during the period between 1991 and 1992. During that period, (6) impulse tests on 144 devices of 57PS and 77PS construction, had no leaks when tested to

500,000 cycles. A Weibull analysis of first quarter, 1999 tests, showed 99.9% reliability at 500,000 cycles at 95% confidence level. Switches meets cycle life specification.

• Test 15a

**Objective:** Determine if long time switch exposure to brake fluid can lead to an ignition.

**Results:** Test is ongoing. (6) samples are being tested. (4) samples contain new brake fluid and (2) samples contain old brake fluid. Results to date show no increase in conductivity of both new and used brake fluid. After more than 350 hours of testing, current draw on each device is less than 20 mAmps.

**Conclusion:** Long duration switch exposure to brake fluid has had no measurable effect on switches. After more than (350) hours of testing, current draw remains orders of magnitude below the levels needed to create ignition as simulated in laboratory experiments.

**Level 3: Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

• Test 6b

**Objective:** Understand the ignition process, determine the current path and establish a repeatable ignition method.

**Results:** Multiple attempts at ignition, via injection of a 5% NaCl in H<sub>2</sub>O into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current verses time show an increase in current until the point of ignition.

**Conclusion:** A repeatable laboratory method for switch ignition has been established. Based on hexport current measurements, the current path is from switch terminals to hexport body.

When a NaCl in H<sub>2</sub>O solution is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminals results in an increase in terminal resistance. When sufficient power is drawn through the corrosive resistance, switch elements heat up and begin to glow red hot. A hole burns through the switch base and ignition occurs. There is arcing visible throughout the corrosion process which may provide the spark necessary for ignition.

**Level 4: Objective:** Compare and contrast variables influencing ignition using the established laboratory ignition method.



• Test 13a

**Objective:** Compare various fluids in the established ignition method.

**Results:** The following fluids were tested.

- (1) NaCl in H<sub>2</sub>O.
- (1) tap water
- (1) rain water
- (1) used brake fluid
- (1) used brake fluid with 5% H<sub>2</sub>O
- (1) new brake fluid
- (1) new brake fluid with 5% H<sub>2</sub>O

The switch filled with 5% NaCl in H<sub>2</sub>O resulted in an ignition when average hexport current exceeded 2.5 Amps. Switches that were filled with tap water and rain water drew less than 10 mAmps over a (3) hour test and showed little signs of corrosion. Switches filled with a matrix of new and used brake fluids, with water and without water, all drew less than 3 mAmps hexport current draw and showed no signs of corrosion.

**Conclusion:** Brake fluid is not conductive enough to cause the electrolytic corrosion and necessary current draw to create an ignition. Because of its' significantly higher conductivity, an ionic rich fluid such as NaCl in H<sub>2</sub>O is necessary to cause an ignition.

• Test 15

**Objective:** Compare the burn characteristics of various plastics as switch base material.

**Results:** When 5% NaCl in H<sub>2</sub>O was injected into switches with different base materials, the following results were obtained: Cellanex 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

**Conclusions:** All plastics tested can ignite using the established laboratory ignition method.

• Test 15b

**Objective:** Determine if switch ignition can occur in the vertical position and 45° orientation. Determine if switch ignition can occur and at different rotational angles in the 45° orientation.

**Results:** Switch ignitions can occur in both the vertical and 45° orientation using the established laboratory ignition method.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation versus 45° orientation nor to rotational angle in the 45° orientation.

**Level 5 Objective:**

**Test 16**

- Objective: Test proposed relay circuit.

Results: (1) switch was injected with 5%NaCl in H<sub>2</sub>O solution and placed in the proposed current limiting circuit for (48) hours. The current draw remained constant at 180 mAmps throughout the test. There was no activity observed and the contact arm remained intact.

(1) switch was brought to an impending burn condition using the established burn method. An impending burn is a condition where a corrosive resistance has built up in the switch and an ignition is imminent. The switch was then placed in the proposed relay circuit for(18) hours where it drew 160 mAmps, showed no visible activity and did not result in an ignition.

Because the proposed relay circuit acts as a resistor which limits current to the switch, the maximum power to the switch is limited to .75 Watts. A resistive wire was wrapped around the base of (1) switch and 0.75 Watts of power was dumped into the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is not enough power to cause electrolytic corrosion or significant switch terminal heating, which is necessary for ignition. In previous tests, using a resistor as the heating element, approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

Brake Pressure Switch Test Log, Updated 4/29/99

Category	Test	Location	Test Parameters	Results Update
Job Description of Potential Ignition in Switch	1	TI	Vary water concentrations in 'new' Brake Fluid	250+ hours. Current draw in the 0.5mA to 6mA range
			14Vdc to one terminal, heaport grounded	Fluid has discolored.
			Water Conc: 4%, 8%, 10%, 75%	No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	Near Brake Field	250+ hours. Constant temperature.
			1 Amp through switch terminals	No significant temperature rise with time
			14Vdc to one terminal, heaport grounded	Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Heaport Grounded	> 500 hours into test, max current 7mA No significant change with time. Test ongoing
			4	AVT
	5	AVT	'new' Brake Fluid in Switch, 16 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	6a	AVT	'new' Brake Fluid in Switch approx. 60 Amps through Switch Terminals	Temperature rise to approx. 270 F. No smoke. No ignition Test suspended.
	8	TI	Build heater elements into Switch.	2 tested. Smoke observed, Ignition observed on part w/heater
			Heat 16 failure, include sparking.	See attachment.
			With Fluid & Dry	Test complete Brake fluid in cavity slows down heat build-up Smoke observed at 676 F, Base melts and falls off at 600 F
	8a	TI	Create heater by corroding spring arm Belt under solution, 14V between spring and heaport	One out of 16 devices increased resistance to 5 ohms. Others either very low resistance or megohmic It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 8.
	8b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through heaport. See plots and video.

TI-NHTSA 013408

Brake Pressure Switch Test Log, Updated 4/28/09

	6c	TI	Pure 'new' brake fluid with metal shavings	Additional test include tap water, old BF, new BF and other. Metal shavings do not contribute significantly to brake fluid conductivity
In Cycle Reliability of Pressure Switch	7	TI	5-1450 poly pressure pulses at 1000 per ES	First leak observed at 725,000 cycles. Test Completed. See attached Visual Chart
Accelerated Wear	8	TI	5-1450 poly pressure pulses at 1000	Parts withdrawn every 200k cycles, characterized for wear
MSL vs Lab Capabilities	9	Central Labs	Field returns, both donor and subject	Parts in Central Labs, see Ford spreadsheet
Leakage of Electrolyte (1) - Evaluating Failure	10	TI	Vary water concentrations in 'new' Brake Fluid	Test Report being written Investigation continues.
Electrolyte Degradation Wear - impulse test			12 amp + 12 quiet switches w/ 0 % water in BF	Suspended at 1.3 million cycles with no leaks observed.
			12 amp + 12 quiet switches w/ 5 % water in BF	3 amp samples suspended at 1.3 million cycles with 2 leaks observed at 1.5M. Quiet samples suspended at 500k cycles to assess spring anomalies.
In Vehicle Characterization of Pressure & Temperature Profile in 7000 Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS loading events.	Test at AVT... see Ford chart... >600k in car?
Seals Fluid Analysis - Lead Seal at master cylinder.	11a	TI	Sample 220 ml brake fluid at the master cylinder (LMC), used brake fluid at the output (UCA) and new brake fluid (NEW) for metal and water content.	Test complete. LMC: Cu = 415 (ppm), Fe = 6.8 (ppm), Cr = 0.08 (ppm), 1.1 %H2O. UCA: Cu = 882 (ppm), Fe = 6.3 (ppm), Cr = 1.9 (ppm), 1.1 %H2O. NEW: Cu = <0.01 (ppm), Fe = 0.32 (ppm), Cr = <0.01 (ppm), 0.5 %H2O.
Spark Plug Study	12	Central Labs	Determine if different forms in which using clutch loads and high speed video. Use dry switches as well as switches with various brake fluid water ratios.	Equipment set-up in progress at Central Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches returned from field vehicles & other sources	13	Central Labs	Characterize electrical, mechanical and chemical aspects of returned switches	Test log and analysis processing set up complete. Analysis of switches in progress.
Field Ignition Tests	13a	TI	Repeat ignition stimulation with different fluids.	Test complete. 5% NaCl sample resulted in an ignition.

TI-NHTSA 013409

Brake Pressure Switch Test Log, Updated 4/29/99

			5% NaCl in tap water	All brake fluid samples draw less than 3 mAmps. No corrosion visible on brake fluid samples.
			rain water	
			(24) hour tests:	Rain water and tap water samples draw <10 mAmps and showed some signs of corrosion.
			tap water	
			used brake fluid	Chemical analysis in process.
			used brake fluid w/ 5% H <sub>2</sub> O	
			new brake fluid	
			new brake fluid w/ 5% H <sub>2</sub> O	
Design Of Experiments (2) Repeat of test 10	13b	TI	Very water concentrations in 'new' Brake Fluid 10 snap + 20 quiet switches w/ 0 % water in BF 10 snap + 20 quiet switches w/ 5 % water in BF	Test suspended. Analysis in process to assess test fixturing.
Compatibility of Kevlar with Oxalic Acid	14	Dupont	Characterize change in properties of Kevlar with various % oxalic acid in brake fluid.	Report expected from Dupont by 6/2/99.
Evaluation of Plastic Materials with Improved Parameters	15	TI	Assess properties and reliability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl Ignited 8/5 and 2/5 trials ZYTEL samples tested 1/8 ignitions
Long duration brake fluid ingress test.	16a	TI	(4) samples with new brake fluid (2) samples with used brake fluid	Test in progress. (15) days to date. Used brake fluid current dropped off to <1/10 mAmp. New brake fluid testpost current remains low
Evaluation of Switch Orientation	16b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity in 45 deg. orientation.	Test complete. Ignition is independent of switch orientation. Simulated switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	10	TI	Repeat test 13a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (18) hrs. Input max. circuit power into heater on switch.	Test complete. No ignition. Corrosion rate dramatically reduced. Insufficient power in circuit to create or move toward ignition in lab Heater element was warm to the touch.

TI-NHTSA 013410

**77PS FORD**

**TEST**

**DISKS**

Disc

photos

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32
- 33
- 34
- 35

5% NaCl H<sub>2</sub>O Test  
 5% NaCl H<sub>2</sub>O Burn Internal/External  
 Rain water 24 hr Tap water Burned  
 Used Brake Fluid Test  
 Excel USED Brake Ingress Test  
 Excel New Brake w/ 5% H<sub>2</sub>O Ingress  
 Excel Clean Brake Ingress  
 Excel Tap water Test  
 photos 5% H<sub>2</sub>O, Clean BF Clean BF, Tap water  
 Excel Used Brake w/ 5%  
 Photos Used Brake w/ 5%  
 Excel FR 5% Salt Data  
 Excel FR 5% Salt Data  
 Photos FR 5% No Burn, but Corrosion  
 Photos FR 5%  
 Noryl Burn Test 1 HP - DAD Data  
 Noryl Burn Test 1 Fluke DAD Data  
 Noryl Burn Test 2 photos  
 Noryl Burn Test 3 photos  
 Noryl Burn Test 4 HP DAD Data  
 Noryl Burn Test 2 Fluke DAD Data  
 Vertical Burn photos Disk  
 Vertical Burn photos Disk-2  
 48 hour delay photos  
 Impending Burn photos  
 Pumping Tests (?) photos  
 Thermocycle Burn Test photos Disk-1  
 Zytel - Burn Test photos Disk-2  
 Zytel - Burn Test Data-1 Excel  
 Zytel - Burn Test Data-2 Excel  
 Zytel - Burn Test photos Disk-3  
 Long duration M1 #5 photos  
 Long duration M2 #5 photos



APT pressure sensors  
PN 3CP2-1

4/29/97

$$\text{Pressure} = \frac{(\text{Volts} - .3)}{.00199}$$

For Impulse test

$$\text{Low pressure} = 0 - 40 \text{ psi}$$

$$\text{High pressure} = 1450 \pm 50 \text{ psi}$$

$$\therefore \text{Lower Voltage Range} = \underline{.30 - .372}$$

$$V = (40)(.00199) + .3 = .372$$

$$\text{Higher Voltage Range} = \underline{2.932 \rightarrow 3.120}$$

$$(1400)(.00199) + .3 = 2.932$$

$$(1500)(.00199) + .3 = 3.120$$



Man. Serial # 1


4-29-99

1040 HPS

59% H<sub>2</sub>O in Brake Fluid

ART PN: 3CP2-1

Actual Pressure =  $\frac{(Volts - .3)}{.00189}$   
± 5%




5s Full screen = 1/2 sec/div

TI-NHTSA 013414

Manifold #2  
4-29-99  
1041 HES

APT 9W 3CPa-1




TI-NHTSA 013415

A-

Man J #3  
4-29-99  
1043489

APT PN: 3CP2-1




TIANTSA 013410

Manifold #4

4-29-99  
1046 HRS

APT PN: 3C72-1

A-




TNHTSA 013417

#1  
4/29  
1620 HRS

10

RANGES: 5.000V 14.00V 14.00V  
OFFSETS: 0.0V 0.0V 0.0V  
TOTAL TIME: 5.00S  
PRE-TRIG: 0.100S  
TRIGGER: 0.50V 0.0V +LEVEL



3.08V, 0.2555


SOFT 0.1578

TI-NHTSA 013418

#2

4/29/94  
1623HRS

RANGES: 5.000V 14.00V 14.00V  
OFFSETS: 0.0V 0.0V 0.0V  
TOTAL TIME: 5.00S  
PRE-TRIG: 0.100S  
TRIGGER: 0.50V 0.0V  $\leftarrow$ LEVEL




TI-NHT8A 013419

73

B


4-29-99  
1625 HRS



TI-NHTSA 013420

#4  
4-28-99  
1624HRS

B-1




TI-NHTSA 013421



#1

4/30/99  
1035 ARS


RANGES: 5.000V | 14.00V | 14.00V  
OFFSETS: 0.0V | 0.0V | 0.0V  
TOTAL TIME: 5.00S  
PRE-TRIG: 0.100S  
TRIGGER: 0.50V | 0.0V | +LEVEL



TI-NHTSA 013422

2  
4/30/89  
10 37 R3

C




TI-NHTBA 013423

4:3

4/30/99

1040 HRS


C-



TI-NHT8A 013424

#  
4/7/79  
1043 HRJ

C




TI-NHT8A 013425

#1  
4/20/74

D

1950 NR/S


RANGES: 5.000V 14.00V 14.00V  
OFFSETS: 0.0V 0.0V 0.0V  
TOTAL TIME: 5.00S  
PRE-TRIG: 0.100S  
TRIGGER: 0.90V 0.0V +LEVEL



TI-NHTSA 013428

#2  
4/20/99  
1452 HRP


D



TI-NHT9A 013427

3  
4-30-99  
1454ARS


D.



TI-NHTSA 013428

7  
4-30-99  
1457WRS

0



TI-NHTBA 013429