

**EA02-025**

**FORD 10/27/03**

**APPENDIX N**

**BOOK 16 OF 61**

**PART 1 OF 4**

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 17:02:20 \*  
\*\*\*\*\*

From: I2060623--EXTERNAL Date and time 02/18/99 12:49:21  
To: FPORTER --FORDMAIL 'Fred Porter' | For NLAPOINT--FORDMAIL 'Norm LaPointe' | F  
SLAROUCH--FORDMAIL 'Steve LaRoucha' | SREIMERS--FORDMAIL 'Steve Reimers' | F  
cc: PHE4KJL2--EXTERNAL Beringhause, Steve OTFWOGYK--EXTERNAL Sharpe, Robert  
  
From: Rahman, Aziz  
Subject: Switch Log and Eval. Procedure  
  
cc: "Beringhause, Steven" <aberlinghause@mail.mc.ti.com>,  
"Dague, Bryan" <cdague@mail.mc.ti.com>,  
"Baumann, Russ" <rbaumann@mail.mc.ti.com>,  
"McGuirk, Andy" <a-mcguirk@mail.mc.ti.com>,  
"Sharpe, Robert" <rsharp@mail.mc.ti.com>

Updated as of 2/18/99. There were some switches from the initial 24 switch survey that were opened up at AVT and the tag and switch parts were not kept together. I have noted this in the log.

Since the tag numbers for every incoming shipment start from 1, I suggest we use VIN numbers to track the database. This will uniquely identify the switch.

I suggest that the switch analysis priority be as follows:

- Switches from underhood fires, which have not been severely damaged
- Switches from Town Cars, starting by highest mileage and descending
- Switches from CV and GM, starting by highest mileage and descending
- Severely damaged switches from underhood fires
- Disassembled switches, with suspect paperwork trail

<<SwitchLog>>  
Evaluation Procedure updated as of 2/18/99. Note identification of harness wires by color.

<<EVALPROC>>  
I think we are closing in on finalizing the log format and the evaluation procedures. I believe that these are good enough for us to start using them for data entry.

In order to reduce confusion, I will plan on updating the log once a week. Please delete the earlier versions, so that you have only one latest copy.

Please comment.

Thanks  
Aziz

Attachments sent separately:

Data Type	File Name
BINARY	SWITCHLOG.XLS_PC
BINARY	EVALPROC.XLS_PC

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 17:04:19 \*  
\*\*\*\*\*

From: JJOYCE1 --DRBN007  
To: SRIMERS--DRBN007  
cc: FPORTER --DRBN007

Date and time 02/18/99 19:40:43

FROM: John Joyce  
Subject: (U) Pressure Tests

USAET(UTC -05:00)

Steve,

I got your note and will be on vacation tomorrow through Wednesday. Here's the info.

The more I think about this, the more I think TC activation may be the mechanism.

I am not sure of the order of the things connected and that can influence the low frequency amplitude of the signals. But the short answer is to instrument for 0-250 Bar and sample at 1 kHz or more.

Since I'm not sure of where the pressure switch is hydraulically connected I'll give you pressures at nodes and states I do know. The worst case for the switch would be to be connected between the HCU and the prop valve, which is where I think it is.

This is the low frequency component of the signal, I'll talk about the high-frequency component further down.

#### MC - HCU MODE

Maximum Pressure - ~175 Bar

Achieved by getting maximum vacuum (high revving engine and suddenly close throttle) than standing on the pedal as hard as you can. I don't remember this number very well it might be as low as ~130 or as high as 220. It also depends on your leg strength. This type of pressure is VERY RARE at this node. For this car, the driver will typically apply <20 bar and very rarely exceed 50 bar.

#### HCU - PROP VALVE MODE

Standing Still - Same as MC pressure - see above.

ABS Maximum - ~110 Bar

This is achieved by loading to GVW and performing an ABS stop, you may find that you are pedal effort limited, not limited by ABS control. It's pretty rare to get this high of pressure in this mode.

TCS Maximum - ~180 Bar

This is a good candidate. On this vehicle because the HCU had to pump through the prop valve to do the brakes-only traction control, the pressures coming out of the HCU got very high. The pressure relief valve on the pump VERY OFTEN dictated the peak pressure which could be developed - not the control - put another way, because the pressure at the rear brake had to restrain the entire powertrain (no engine intervention) and push through a prop valve, it was often possible to drive through the TC - the engine could overpower the brakes, even though very high pressures were being generated at the HCU. The noise during TC activation in these applications was very dependent upon the pressure relief valve opening point. So the

pressure relief valve value got changed a few times over the years as performance was sacrificed for NVH. Also the tolerance on the pressure relief valves was fairly large - a total of 40 bar, at that time I believe. The pressure relief valve pressure might be anywhere from 90 to 180 bar depending on part-to-part variation and the design generation that was agreed upon.

You can achieve this easiest by getting the rear wheels off the ground and putting the car in drive. Get into the throttle hard, but not so hard that you drive out of first gear or faster than 15 mph. If you maintain this for a while, the thermal model to protect the rear linings will disable the Traction Control. You will then need to wait for them to cool, before the function will be reenabled. You can dramatically accelerate the cooling time by cruising (without braking) at about 40 mph.

Typical drivers can regularly get high pressures in this mode.

**PROP VALVE - REAR BRAKE MODE**

ABS Maximum Pressure ~70 Bar

Load to GVW and perform an ABS stop at maximum pedal effort.

**TCS Maximum Pressure ~100 Bar**

This pressure level is strongly dependent upon the pressure relief valve level - see above.

**Standing Still**

Same as ABS Maximum Pressure

**High Frequency Content**

The high frequency content has two parts. If you are not in ABS or Traction Control there is practically no high frequency content - the pressure is modulated at <10 Hz. This is basically limited by Booster response times and hydraulic dampening in the ABS orifices.

**High Frequency Content Due To Control**

During ABS/TC events the pressure is changed in quick steps. Typically it will increase by 10 Bar in a few milliseconds, and this type of change occurs about every 100ms. The pressure will decrease by about 20 Bar every 300 ms. There can be quite a bit of variation in these numbers, but those are pretty typical. (Actually the numbers I assigned were for ABS, swap "increase" and "decrease" for TC activation.)

**High Frequency Content Due to Shock Waves**

This is a secondary effect from the control. Generally it is worst right at the outlet of the HCU. It is damped and dissipated the further you get from the HCU. The shock wave is generated from the cyclical pulsing of the pump as well as the sudden changes in pressure when a solenoid valve is snapped open or shut.

The amplitude of this can be really big - I haven't looked at it in this generation unit for a few years, but I think it's about 50 Bar peak-peak right at the HCU. It will fall off as you move further away from the HCU.

The frequency is pretty high and I think some components are above the 1 kHz level, but you can get a very good idea of the disturbances by sampling at 1kHz.

Regards,  
John Joyce

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 16:44:49 \*  
\*\*\*\*\*

FROM: SREIMERS--DRBN007  
To: JBRADLEY--DRBN006  
JLOGEL --DRBN005  
cc: JINEME --DRBN005

Date and time 02/16/99 17:00:16  
RNEVI --DRBN005  
FPORTER --DRBN007 Porter, F.J.

FROM: Steve Reimers  
Subject: Town Car Oasis message  
The proposed wording is below for your approval.

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS sreimers@ford.com fax 39-03286 ;>  
\*\*\* Forwarding note from TMASTERS--DRBN005 02/16/99 14:26 \*\*\*  
To: FPORTER --DRBN007 SREIMERS--DRBN007

FROM: Tom Masters USAET(UTC -05:00)  
Subject: Town Car Oasis message

Oasis looks good. Have no changes or additions. Run with it.

Phone 313-39-08657, Text Pager 313-851-2005, Fax 313-317-9158  
#5-2A024, M.D.-5017 AVT-EHSE-OPD Elect System/EDS Trk/Large Car  
The Road To Success Is Uphill, So -  
Don't Expect To Break Any Speed Records.  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/11/99 18:43 \*\*\*  
To: TMASTERS--DRBN005 Masters, Tom

FROM: Steve Reimers USAET(UTC -05:00)  
Subject: Town Car Oasis message  
Tom, here is the proposed wording for the oasis message. Please comment,  
revise and append. Send your response to FPORTER and cc me. Are there any pa  
rts you want to include in this message? I will be gone on Friday. Back  
Monday. The final word smithered version will be sent to Joe Bradley (FCSD), Ray  
Nevi (ASO), and Jay Logel (OGC) for their approval before sending it out.  
\*\*\*\*\*  
For 1992 and 1993 Town Car: When replacing the Speed Control Deactivation  
switch (-9F924, Brake Pressure Switch on the Brake Proportioning valve) or its  
electrical harness, tag the removed part and return to Ford Dearborn (??????).  
Tag to show VIN, mileage, dealer code, and reason removed.  
\*\*\*\*\*  
thanks.

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS sreimers@ford.com fax 39-03286 ;>

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 16:45:00 \*  
\*\*\*\*\*

From: I2060625--EXTERNAL Date and time 02/16/99 17:09:05  
To: FPORTER --FORDMAIL 'Fred Porter ( For NILAPOINT--FORDMAIL 'Norm LaPointe ( F  
SLAROUCH--FORDMAIL 'Steve LaRouche ( BREIMERS--FORDMAIL 'Steve Reimers ( F  
cc: PHB4K5L2--EXTERNAL Beringhouse, Steve OTFWOGYK--EXTERNAL Sharpe, Robert

From: Rahman, Asiz  
Subject: Brake Pressure Switch Test Log.xls

cc: "Beringhouse, Steven"<sberinghouse@mail.mc.ti.com>,  
"Dague, Bryan"<bdague@mail.mc.ti.com>,  
"McGuirk, Andy"<a-moguirke@mail.mc.ti.com>,  
"Baumann, Russ"<rbaumann@mail.mc.ti.com>,  
"Sharpe, Robert"<rsharpas@mail.mc.ti.com>

<<Brake Pressure Switch Test Log.xls>>

Team,

This is a first pass at the test log we can use to track our tests and to update the core team on Wednesday meetings. Please review/add/edit/comment.

Thanks  
Asiz.

Attachments sent separately:

Data Type	File Name
-----	-----
BINARY	BAKEDRE.XLS_PC

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 16:45:06 \*  
\*\*\*\*\*

From: I2060625--EXTERNAL Date and time 02/17/99 01:48:48  
To: FPORTER --FORDMAIL 'Fred Porter' ( For NLAPPOINT--FORDMAIL 'Norm LaPointe' ( F  
SLAROUCHE--FORDMAIL 'Steve LaRouche' ( SRIMERS--FORDMAIL 'Steve Reimers' ( F

From: Rahman, Aziz  
Subject: Brake Pressure Switch Evaluation Plan.xls

<<Brake Pressure Switch Evaluation Plan.xls>>

Team, please review evaluation plan. It is basically a collation of Steve R. and Norm's inputs. I will add the switch dissection section tomorrow. The pressure calibration station from TI is expected to arrive on Thursday and will probably reside at Central Lab due to availability of high pressure air.

Steve R. will Allan be available to perform the electrical characterizations data collection? I can definitely help with data analysis and maintenance of the database.

Please review the attachment and let's discuss tomorrow.

Thanks  
Aziz.

Attachments sent separately:

Data Type	File Name
-----	-----
BINARY	BRAKEPRE.XLS_PC

3713 1392

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 12:56:42 \*  
\*\*\*\*\*

From: JNEME --DRBN005  
To: TMASTER --DRBN005  
CC: JMCINERW --DRBN005  
JNEME --DRBN005

Date and time 02/15/99 17:22:07  
FPORTER --DRBN007  
RMEVI --DRBN005

FROM: Joseph S. Neme  
SUBJECCT: (C) Questionnaire  
Gentlemen,

USAET(UTC -05:00)

We have a central contact point for underhood fires at FCSD litigation prevention. He will work with EA or design analysis to investigate alleged underhood fires.

What is needed from you tomorrow is:

- 1) list of quastions/info you need to know regarding a fire like
  - where did fire originate
  - was the vehicle running, parked, on/off... if off, how long
  - did you notice brake warning lamp or speed control inop prior to fire
  - VIN #, Miles, location of incident
  - where is the vehicle now
- 2) identify a "flag" to signal a vehicle investigation like
  - underhood fire
  - vehicle available
  - 92-95 Town Car, Crown Victoria, Grand Marquis
  - fires that totaled a vehicle or don't know origin
- 3) identify vehicles we want to have EA have a look at right away (suggest working with A&O on present list of alleged incidents)
- 4) list of special request from the investigators... ie which parts to get

We need all this info tomorrow so that we can kick things off... thanks

Call me if you have questions

Joseph S. Neme  
LVC - Safety  
Phone: 39-68133, Fax: 62-18147, E-Mail: jneme@ford.com  
Location: MD1286/Cube 2M37, Building #2 Textpager: 313-795-7003

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 12:57:00 \*  
\*\*\*\*\*

From: I2060625--EXTERNAL Date and time 02/15/99 20:23:01  
To: FPORTER --FORDMAIL 'Fred Porter ( For NLAPPOINT--FORDMAIL 'Norm LaPointe ( F  
SLAROUCH--FORDMAIL 'Steve LaRouche ( SREIMERS--FORDMAIL 'Steve Reimers ( F

From: Rahman, Aziz  
Subject: Brake Pressure Switch Log

Attached is a log file with information on the devices under review. It also contains switches received today from John McInerney. In addition to Steve L's analysis summary file, I will be using this log to track incoming parts. Please advise if I have missed any data.

<<Brake Pressure Switch Log>>

Please let me know if you cannot open the file. Steve/Norm, can you please e-mail me the last update on your analysis summary file? Thanks.

Regards  
Aziz,

Attachments sent separately:

Data Type	File Name
-----	-----
BINARY	BRAKEPRE.XLS_PC

3713 1394

\*\*\*\*\*  
\* Note printed by FPORTER on 22 Feb 1999 at 13:18:21 \*  
\*\*\*\*\*

From: SCOLEL --DRBN005  
To: FPORTER --DRBN007  
cc: TMASTER --DRBN008  
DGOEL --DRBN005

Date and time 02/16/99 13:41:46  
TDONOVAN--DRBN008

From: Sam L. Cole Date and time USAET(UTC -05:00)  
Subject: (U)

I UNDERSTAND THAT THERE WILL BE A FOLLOW UP MEETING WITH JACK PASKUS THIS FRIDAY ON THE TOWN CAR INVESTIGATION. I MET WITH JACK TODAY FOR A 1 ON 1, AND HE REQUESTED SOME SPECIFIC INFO. AT FRIDAYS MEETING, PLEASE BRING A SAMPLE SWITCH TO SHOW JACK.

ALSO, HE IS INTERESTED IN KNOWING OUR PROGRESS AND INVESTIGATING IF THE PREVIOUS PROBLEM WITH THE INTERNAL COMPONENTS BREAKING LOOSE IS A POTENTIAL CAUSE OF THIS CONCERN. PLEASE BE PREPARED TO DISCUSS THIS ON FRIDAY. THANKS.

Thank You,  
Sam  
Ext. 21959  
BLDG. 2, 22J31 - MD# 1220 - SCOLEL@FORD.COM

3713 1396

\*\*\*\*\*  
\* Note printed by FPORTER on 21 Feb 1999 at 13:19:21 \*  
\*\*\*\*\*

From: TMASTERS--DRBN005  
To: FPORTER --DRBN007

Date and time 02/16/99 14:26:23  
SREIMERS--DRBN007

FROM: Tom Masters  
Subject: Town Car Oasis message

USAET(UTC -05:00)

Oasis looks good. Have no changes or additions. Run with it.

Phone 313-39-08657, Text Pager 313-851-2009, Fax 313-317-9158  
#5-2A024, M.D.-5017 AVT-KBBK-OPD Elect System/RDS Trk/Large Car  
The Road To Success Is Uphill, So -

Don't Expect To Break Any Speed Records.

\*\*\* Forwarding note from SREIMERS--DRBN007 02/11/99 18:43 \*\*\*  
To: TMASTERS--DRBN005 Masters, Tom

FROM: Steve Reimers

USAET(UTC -05:00)

Subject: Town Car Oasis message

Tom, here is the proposed wording for the oasis message. Please comment,  
revise and expand. Send your response to FPORTER and cc me. Are there any pa-  
rts you want to include in this message? I will be gone on Friday. Back  
Monday. The final word smithed version will be sent to Joe Bradley (FCSD), Ray  
Nevi (ASO), and Jay Logel (OGC) for their approval before sending it out.  
\*\*\*\*\*

For 1992 and 1993 Town Car: When replacing the Speed Control Deactivation  
switch (-9F924, Brake Pressure Switch on the Brake Proportioning valve) or its  
electrical harness, tag the removed part and return to Ford Dearborn (??????).  
Tag to show VIN, mileage, dealer code, and reason removed.

\*\*\*\*\*  
thanks,

Steve Reimers  
AVT Chassis E/E System Applications  
39-03286 SREIMERS sreimers@ford.com

building 5 3C043  
mail drop 5011  
fax 39-03286 />

PRESENT

BRAKE  
LAMP  
CIRCUIT  
(V<sub>BAT</sub>)

NC  
BRAKE SWITCH

EM  
CLUTCH

CRUISE  
CONTROLLER

PROPOSED

BRAKE (V<sub>BAT</sub>)  
LAMP  
CIRCUIT

N/O  
RELAY

CRUISE  
CONTROL  
INPUT

NC  
BRAKE SWITCH


EM  
CLUTCH


CRUISE  
CONTROLLER

37181367



## Memphis Switch





H7005-A

2/10/99

4-511 Brazeau when

- Get Dow on Team

~~ASK~~ THEM HOW FIRE STARTS  
WITHIN CONSTRAINTS [140, Black Substance,  
15 AMP MAX current, Veh. TEMPERATURES.]

- Char's Real Veh Brake Pressure.

- " " " " " in ABS<sup>2</sup> EVENT.

- Thermo-couple Brk Pr switch after  
Veh. Driven & turned off.

- Take Rate of ABS

" " " ABS w/TC

- Are Leaks/Fires common to ~~the~~ traction loss.

- Black Substance: Copper, Zinc, Silver, Sulfur,  
Brake Fluid.

- Understand TC/ABS Pressure Pulse/

- HISTORY OF ELECTROLYSIS IN Brake Fluid.

8

87

ID	PART NUMBER	PIA	ACT	CPC	S RELEASE	FUN RELEASE	VL	ARMED	IN IN:	CORE	SWATCH	DUT	CORE	NOTICE	IPC		
39	F2VC 99324	AA	F2VC	2C128	CA	NC00	60605	0	NC00811611672328802	H P R	91/07/02	PP F	92 R	IN:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-42
70	F2VC 99324	AA	F2VC	2B091	DA	NC00	60605	0	NC00811611672328802	H P R	91/07/02	PP F	92 R	IN:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-42
261	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00811610192328802	H P R	91/07/02	PP F	92 R	IN:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-42
37	F2VC 99324	AA	F2VC	2C128	CA	NC00	60605	0	NC008112486000001	R P R	91/07/31	PP F	92 R	X:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-45
66	F2VC 99324	AA	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	R P R	91/07/31	PP F	92 R	IN:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-45
97	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	R P R	91/07/31	PP F	92 R	IN:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-47
148	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	R P R	91/07/31	PP F	92 R	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-49
187	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC008112486000001	H P R	91/07/31	PP F	92 R	IN:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-49
187	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	H P R	91/08/29	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-50
148	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	H P R	91/08/29	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-51
198	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC008112486000001	R P R	91/08/29	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-51
200	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC008112486000001	R P R	91/08/29	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-53
206	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC008112486000001	R P R	91/08/29	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-54
130	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	H P R	91/09/31	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-55
134	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	R P R	92/03/24	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-56
153	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	R P R	92/04/25	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-57
1	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/05/02	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-58
116	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/05/02	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-59
243	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/05/02	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-59
158	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC008112486000001	R P R	92/05/26	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-60
129	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	R P R	92/07/21	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-61
184	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	R P R	92/08/13	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-63
149	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	R P R	92/08/21	PP F	92	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-64
3	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/08/21	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-65
118	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/08/21	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-66
7	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/12/17	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-67
9	F2VC 99324	AB	F2VC	2C128	CC	NC00	60605	0	NC00810444499251	R P R	92/10/27	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-68
36	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC00810444499251	H P R	92/08/17	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-69
61	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/17	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-69
79	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/17	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-70
33	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-72
34	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-73
52	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-74
53	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-75
83	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-76
84	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992A	NC008101280844001	PPFAA CTDRM CRDM VDC-76
85	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/08/23	PP F	92 X	X:	24992C	NC008101280844001	PPFAA CTDRM CRDM VDC-77
87	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/10/05	PP F	92	X:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-79
60	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/10/05	PP F	92	X:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-79
91	F2VC 99324	AB	F2VC	2B091	AA	NC00	60605	0	NC00810444499251	H P R	92/10/05	PP F	92	X:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-81
36	F2VC 99324	AB	F2VC	2C128	CA	NC00	60605	0	NC00810444499251	H P R	92/01/18	PP F	92	X:	24992C	NC008100289154001	PPFAA CTDRM CRDM VDC-82

## Sheet 1

#	PART NUMBER	P/L	ACT	CPS/C	S RELEASE	LINK RELEASE	VL	M/N	A/TM	CODE	NOTICE	OUT/CODE	NOTICE	MPN
64	F2MC 3F924 AA F2MC 28891	AA MC98 64605	G	MC00810444499336	H	P R 91/01/18	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN103
64	F2MC 3F924 AA F2MC 28891	AA MC98 64605	G	MC00810444499336	H	P R 91/01/18	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN104
75	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810444499336	H	P R 91/01/18	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN105
95	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101120804000	H	P R 91/01/18	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN106
46	F2MC 3F924 AB F2MC 2C120	CA MC98 64605	G	MC008104472320002	H	P R 91/01/03	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN107
71	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101072320002	H	P R 91/07/02	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN107
162	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101072320002	H	P R 91/07/02	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN108
38	F2MC 3F924 AB F2MC 2C320	CA MC98 64605	G	MC008101280040001	H	P R 91/07/11	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN109
97	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 91/07/11	PP	P 92	IM:	54P92C	MC00810028915981	OUT:		TPRAB OTDAB OTDAB MPN110
88	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 91/07/11	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN111
145	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 91/07/11	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN112
138	F2MC 3F924 AB F2MC 2C320	CD MC98 64605	G	MC008101280040001	H	P R 91/07/11	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN113
149	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 91/08/29	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN114
150	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 91/08/29	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN115
281	F2MC 3F924 AB F2MC 2C320	CD MC98 64605	G	MC008101280040001	H	P R 91/08/29	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN116
282	F2MC 3F924 AB F2MC 2C320	CD MC98 64605	G	MC008101280040001	H	P R 91/08/29	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN117
286	F2MC 3F924 AB F2MC 2C320	CA MC98 64605	G	MC008101072320032	H	P R 91/08/31	PP	P 92	IM:	54P92C	MC008101072320032	OUT:		TPRAB OTDAB OTDAB MPN118
131	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810444499332	H	P R 92/01/21	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN119
135	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810444499332	H	P R 92/01/21	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN120
134	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 92/04/25	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN121
2	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC00810206101000	H	P R 92/05/03	PP	P 92	IM:	54P92C	MC00810206101000	OUT:		TPRAB OTDAB OTDAB MPN122
117	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC00810206101000	H	P R 92/05/03	PP	P 92	IM:	54P92C	MC00810206101000	OUT:		TPRAB OTDAB OTDAB MPN123
234	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC00810206101000	H	P R 92/05/03	PP	P 92	IM:	54P92C	MC00810206101000	OUT:		TPRAB OTDAB OTDAB MPN124
151	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101280040001	H	P R 92/05/26	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN125
168	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810444499335	H	P R 92/07/21	PP	P 92	IM:	54P92C	MC008101280040001	OUT:		TPRAB OTDAB OTDAB MPN126
155	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810210010000	H	P R 92/08/23	PP	P 92	IM:	54P92C	MC00810210010000	OUT:		TPRAB OTDAB OTDAB MPN127
170	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC00810210010000	H	P R 92/08/23	PP	P 92	IM:	54P92C	MC00810210010000	OUT:		TPRAB OTDAB OTDAB MPN128
4	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC008102107213195	H	P R 93/03/09	PP	P 92	IM:	54P92C	MC008102107213195	OUT:		TPRAB OTDAB OTDAB MPN129
115	F2MC 3F924 AB F2MC 2C320	CC MC98 64605	G	MC008102107213195	H	P R 93/03/09	PP	P 92	IM:	54P92C	MC008102107213195	OUT:		TPRAB OTDAB OTDAB MPN130
8	F2MC 3F924 AB F2MC 3C320	SD MC98 64605	G	MC00810361050000	H	P R 93/12/17	PP	P 92	IM:	54P92A	MC00810361050000	OUT:		TPRAB OTDAB OTDAB MPN131
10	F2MC 3F924 AB F2MC 3C320	SD MC98 64605	G	MC00810370000000	H	P R 95/10/27	PP	P 92	IM:	54P92A	MC00810370000000	OUT:		TPRAB OTDAB OTDAB MPN132
41	F2MC 3F924 AB F2MC 3C320	CA MC98 64605	G	MC0081031212000000	H	P R 93/03/27	PP	P 92	IM:	54P92B	MC0081031212000000	OUT:		OTRAB GM 100001114
42	F2MC 3F924 AB F2MC 3C320	CA MC98 64605	G	MC008101622750000	H	P R 93/08/08	PP	P 92	IM:	54P92B	MC008101622750000	OUT:		OTRAB GM 100001115
207	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC008101333750000	H	P R 93/08/08	PP	P 92	IM:	54P92B	MC008101333750000	OUT:		TPRAB GM 100001116
5	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC008102170000000	H	P R 92/05/27	PP	P 92	IM:	54P92A	MC008102170000000	OUT:		TPRAB GM 100001117
124	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC008102170000000	H	P R 92/05/27	PP	P 92	IM:	54P92B	MC008102170000000	OUT:		TPRAB GM 100001118
208	F2MC 3F924 AB F2MC 3C320	CA MC98 64605	G	MC008102170000000	H	P R 94/03/29	PP	P 93	IM:	54P92A	MC008102170000000	OUT:		TPRAB GM 100001119
6	F2MC 3F924 AB F2MC 3C320	CC MC98 64605	G	MC008103910000000	H	P R 94/03/29	PP	P 93	IM:	54P92A	MC008103910000000	OUT:		TPRAB GM 100001120
122	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008103910000000	H	P R 93/04/30	LP	P 93	IM:	54P92A	MC008103910000000	OUT:		OTRAB GM 100001121
123	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101273200000	H	P R 91/01/17	LP	P 92	IM:	54P92A	MC008101273200000	OUT:		TPRAB VIII122
122	F2MC 3F924 AB F2MC 28891	AA MC98 64605	G	MC008101273200000	H	P R 91/01/17	LP	P 92	IM:	54P92A	MC008101273200000	OUT:		TPRAB VIII123

30

#	PART NUMBER	PLA	ACT	CPLC	A RELEASE	SHIPPING RELEASE	VL	ALRT	AC	IN	CODE	NOTICE	OPT	CODE	NOTICE	INC			
161	F2VC 9F924 AB F1LC 2B001	AA	NC00	60405	0	NC00E10137323000	H	P	R	91/07/17	LB	P	53	A	IN	64P93A	NC00E10137323000	GPT	WORK VIII124
182	F2VC 9F924 AB F1LC 2B001	AA	NC00	60405	0	NC00E10157876000	H	P	R	91/11/05	LB	P	53	A	IN	64P93A	NC00E10157876000	GPT	WORK VIII125
183	F2VC 9F924 AB F1LC 2B001	AA	NC00	60405	0	NC00E10157876000	H	P	R	91/11/05	LB	P	53	A	IN	64P93A	NC00E10157876000	GPT	WORK VIII126
195	F2VC 9F924 AB F1LC 2B001	AA	NC00	60405	0	NC00E10168510003	H	P	R	92/01/16	LB	P	53	A	IN	64P93A	NC00E10168510003	GPT	WORK VIII127
73	F2VC 9F924 AB F1LC 3B001	AA	NC00	60405	0	NC00E10204620000	H	P	R	90/04/15	LB	P	51	A	IN	64P93A	NC00E10204620000	GPT	WORK VIII128
184	F2VC 9F924 AB F1LC 2B001	BB	NC00	60405	0	NC00E10204620000	H	P	R	92/04/15	LB	P	53	B	IN	64P93A	NC00E10204620000	GPT	WORK VIII129
213	F2VC 9F924 AB F1LC 2C320	AA	NC00	60403	0	NC00E10161813000	H	P	R	92/05/06	LB	P	54	A	IN	64P94A	NC00E10161813000	GPT	WORK VIII130
214	F2VC 9F924 AB F1LC 2C320	AA	NC00	60403	0	NC00E10152467121	H	P	R	92/08/10	LB	P	54	A	IN	64P94A	NC00E10152467121	GPT	WORK VIII131
216	F2VC 9F924 AB F1LC 2C320	AA	NC00	60403	0	NC00E10152467121	H	P	R	92/08/10	LB	P	54	A	IN	64P94A	NC00E10152467125	GPT	WORK VIII132
221	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10152467125	H	P	R	92/08/10	LB	P	54	A	IN	64P94A	NC00E10152467125	GPT	WORK VIII133
219	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10246733000	H	P	R	92/11/30	LB	P	54	B	IN	64P94A	NC00E10246733000	GPT	WORK VIII134
218	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10246733000	H	P	R	92/12/10	LB	P	54	B	IN	64P94A	NC00E10246733000	GPT	WORK VIII135
224	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10224678000	H	P	R	92/12/10	LB	P	54	A	IN	64P94A	NC00E10224678000	GPT	WORK VIII136
223	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10279779036	H	P	R	93/06/05	LB	P	54	A	IN	64P94A	NC00E10279779036	GPT	WORK VIII137
229	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10293436037	H	P	R	93/10/29	LB	P	54	A	IN	64P94A	NC00E10293436037	GPT	WORK VIII138
231	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10243485045	H	P	R	93/11/12	LB	P	54	A	IN	64P94A	NC00E10243485045	GPT	WORK VIII139
229	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10351398011	H	P	R	94/04/27	LB	P	54	A	IN	64P94A	NC00E10351398011	GPT	WORK VIII140
227	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10413891008	H	P	R	94/08/10	LB	P	54	A	IN	64P94A	NC00E10413891008	GPT	WORK VIII141
228	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10409636000	H	P	R	94/10/21	LB	P	54	A	IN	64P94A	NC00E10409636000	GPT	WORK VIII142
230	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10293446037	H	P	R	93/10/29	LB	Q	55	A	IN	64P94A	NC00E10293446037	GPT	WORK VIII143
234	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10283446045	H	P	R	93/11/12	LB	Q	55	B	IN	64P94A	NC00E10283446045	GPT	WORK VIII144
226	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E1031398011	H	P	R	94/06/27	LB	Q	55	B	IN	64P94A	NC00E1031398011	GPT	WORK VIII145
26	F2VC 9F924 AB F1LC 2C320	AA	NC00	60405	0	NC00E10140630008	H	P	R	90/05/24	VB	P	52	A	IN	64P92A	NC00E10140630008	GPT	ANALY PERIOD TW115
63	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10140630008	H	P	R	90/05/24	VB	P	52	A	IN	64P92A	NC00E10140630008	GPT	PERIOD TW115
100	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10140630008	H	P	R	90/05/24	VB	P	52	A	IN	64P92A	NC00E10140630008	GPT	PERIOD TW115
34	F2VC 9F924 AB F1VC 2C320	AA	NC00	60405	0	NC00E10157876000	H	P	R	90/08/17	VB	P	52	B	IN	64P92A	NC00E10157876000	GPT	ANALY PERIOD TW116
45	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E1016851000	H	P	R	90/08/17	VB	P	52	B	IN	64P92A	NC00E1016851000	GPT	PERIOD TW116
46	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E1016851000	H	P	R	90/08/17	VB	P	52	B	IN	64P92A	NC00E1016851000	GPT	PERIOD TW116
51	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E1016851000	H	P	R	90/08/23	VB	P	52	B	IN	64P92A	NC00E1016851000	GPT	PERIOD TW116
25	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E1016851000	H	P	R	90/08/23	VB	P	52	B	IN	64P92A	NC00E1016851000	GPT	PERIOD TW116
233	F2VC 9F924 AB F1VC 2C320	BB	NC00	60405	0	NC00E10179646000	H	P	R	90/08/24	VB	P	52	B	IN	64P92A	NC00E10179646000	GPT	PERIOD TW116
243	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646000	H	P	R	90/08/24	VB	P	52	A	IN	64P92A	NC00E10179646000	GPT	PERIOD TW116
26	F2VC 9F924 AB F1VC 2C320	AA	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646001	GPT	64P92A NC00E10179646001 ANALY PERIOD TW116
25	F2VC 9F924 AB F1VC 2C320	AB	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	A	IN	64P92A	NC00E10179646001	GPT	ANALY PERIOD TW116
57	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646001	GPT	PERIOD TW116
58	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646001	GPT	PERIOD TW116
59	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646001	GPT	PERIOD TW116
60	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646001	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646001	GPT	PERIOD TW116
234	F2VC 9F924 AB F1VC 2C320	AA	NC00	60405	0	NC00E10179646003	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646003	GPT	PERIOD TW116
235	F2VC 9F924 AB F1VC 2C320	AA	NC00	60405	0	NC00E10179646003	H	P	R	90/10/25	VB	P	52	A	IN	64P92A	NC00E10179646003	GPT	PERIOD TW116
244	F2VC 9F924 AB F1VC 2B001	AA	NC00	60405	0	NC00E10179646003	H	P	R	90/10/25	VB	P	52	B	IN	64P92A	NC00E10179646003	GPT	PERIOD TW116

3

89

Sheet

#	PART NUMBER	PIA	ACT	CPRC	S RELEASE	FUR RELEASE	VL R/WY M IN: CODE	NOTICE	OPT: CODE	NOTICE	REC
15	F2MC 8F924 AB F2MC 2C220 AC NC00 60280 S MC00010467567013	E P R 95/06/24	VC P 98 A IN:	24P90A	MC00010467567013	Q07			PEPAJ J09A5 P0145		247
17	F2MC 8F924 AB F2MC 2C320 AC NC00 60280 S MC00010467567015	H Y R 95/10/18	VC P 98	107 24P90A	MC00010467567000	Q07			PEPAJ M0145		248
18	F2MC 8F924 AB F2MC 2C320 AC NC00 60280 S MC00010467567015	H P R 95/10/18	VC P 98 R IN:	24P90A	MC00010467567013	Q07: 04195A	MC00010467567025	PEPAJ J09A5 P0145		249	
20	F2MC 8F924 AB F2MC 2C320 AC NC00 60280 S MC00010467567000	H P R 95/10/18	VC P 98 R IN:	24P90A	MC00010467555400	Q07:		PEPAJ P0145		250	
21	F2MC 8F924 AB F2MC 2C320 AC NC00 60280 S MC00010467555400	H P R 95/10/18	VC P 98 R IN:	24P90A	MC00010467555400	Q07: 04195A	MC00010467555400	PEPAJ P0145		251	
126	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/06/21				LIND CONVERSION					252
127	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/06/21				LIND CONVERSION					253
128	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					254
129	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					255
130	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					256
131	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					257
132	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					258
133	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					259
134	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					260
135	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					261
136	F2MC 8F924 AB F2MC 2M001 AC NC00 60280 S MC00010467555400	H P R 95/10/07				LIND CONVERSION					262

3713 1407

\*\*\*\*\*  
\* Note printed by FPORTER on 30 Mar 1999 at 17:30:19 \*  
\*\*\*\*\*

From: JHEIME --DRBN005  
To: JKAFATI --DRBN004  
FPORTER --DRBN007  
RNEVI --DRBN005  
RENGLIBI--DRBN005  
cc: JMCINTERN--DRBN005

Date and time 03/30/99 14:22:40  
TMASTERS--DRBN005  
NABRAMC8--DRBN005  
TBASIL --DRBN005  
SKINNERS--DRBN007

FROM: Joseph S. Name USAET(UTC -05:00)  
SUBJECT: got another inspection report  
Stop by and check it out... it is in the green folder on my desk... fuse #12 blown...

John... while I am out of the office... please check my desk for other reports and send out a similar notice if required... thanks

Joseph S. Name  
LVC - Safety  
Phone: 39-08133, Fax:62-18147, E-Mail:jname@ford.com  
Location: MD1255/Cube 2M37, Building #2 Textpager: 313-792-7003

## Low Cost Automotive Hydraulic Line Mount Pressure Switches

TI's pressure switches provide low cost, on/off controls for many automotive systems. The snap action diac reacts to changing pressure by reversing its curvature and activating electrical switch contacts.




### Key Features Include:

- Designed for underhood environment
- Low weight
- Custom packaging for specific application needs
- Automotive temperature range of -40 to 135°C
- Normally open and normally closed contact logic
- Industry proven since 1984

### Typical Applications

- Power Steering Systems
- Cruise Control Systems
- Brake Systems
- Transmissions
- Suspension

### Dimensions (typical examples, other styles available)






## Technical Specifications

Electrical		Durability	
Supply Voltage	6 - 16 V	Cycle Life	
Supply Current	5 - 35 mA	Low/Mid Pressure Range	up to $1 \times 10^6$ cycles
Response Time <sup>1</sup>	10 ms maximum	High Pressure Range	up to $15 \times 10^4$ cycles
Environmental		Proof Pressure	
Operating Temperature	-40 to 135°C	Burst Pressure	1400 to 3000 psi
Full Scale Pressure Range		Low Pressure Range	7000 psi
Low Pressure Range	0 to 300 psi	Mid Pressure Range	4000 psi
Mid Pressure Range	0 to 800 psi	High Pressure Range	2500 psi
High Pressure Range	0 to 1600 psi		

<sup>1</sup>Applies to some devices.

## Pressure Switch Characteristics



**Important Notice:** Texas Instruments (TI) reserves the right to make changes to or to discontinue any product or service identified in this publication without notice. TI advises its customers to obtain the latest version of the relevant information to verify, before placing orders, that the information being relied upon is current.

Texas Instruments assumes no responsibility for infringement of patents or rights of others based on Texas Instruments applications knowledge or product specifications, since TI does not possess full access concerning the use or application of customers' products. TI also assumes no responsibility for customers' product designs.

For further information please write or call:

Texas Instruments Incorporated  
Pressure Switch Marketing MS 23-01  
P.O. Box 3964  
Attleboro, MA 02703-0964  
Phone: 508 236-1910  
Fax: 508 236-1998

### International Offices:

**Japan**  
Texas Instruments Japan Ltd.  
308 Tsurumi-cho, Oyama-Chu  
Saitama-City, Saitama-Ken 310-11  
Oyama, Japan  
Phone: (041) 550-78-1211  
Fax: (041) 550-78-0331

**Korea**  
Texas Instruments Holland N.V.  
Automotive Marketing  
P.O. Box 43  
NL-7600 AA Almelo  
Holland  
Phone: (31) 544-079462  
Fax: (31) 546-364429

**South America**  
Texas Instruments Eletronica do Brasil Ltda.  
Rua Azarias de Melo, 6-48 - Taquaril  
Campinas - SP - Brazil  
CEP 13490-001  
Phone: (55) 192-541146  
Fax: (55) 192-518023

Texas Instruments Incorporated  
S-D Problem Resolution Report # PS/CAR/93-3

CLOSED 12/1/93

Original Report: July 29, 1993

Update Report: October 18, 1993

Ford Part Number: P3TA-9F924-AA/BA/CA

Part Description: Speed Control Deactivation Switch

**(STEP 1) PRODUCT TEAM**

Manufacturing Engineering:	Matt Sellars
Quality Assurance Engineering:	Jim Watt
Product Marketing:	Charlie Douglas
Design Engineering:	Asif Rahman (Champion)

**(STEP 2) PROBLEM DESCRIPTION**

Ford Light Truck Division Brake Engineering reported a noticeable increase in warranty returns, related to inoperative speed control systems for 1993 Econoline models during 4QTR '92 and 1QTR '93 time frame. Detailed breakdown of warranty data showed that a number of these claims were reported to be pressure switch related. Attachment "A" shows R/1000 date as collated from Ford warranty data. Texas Instruments and Ford started on 7/22/93 to call dealerships from the Master Claim list contacting over 150 dealerships. As of 10/18/93, (14) switches have been received, analyzed, and characterized.

The following table details the field data on these switches:

VID	Vehicle type	Switch date code
A84662	'93 Econoline	2316 (November '92)
A35294	'93 Econoline	2294
A40855	'93 Econoline	3078
A70382	'93 Econoline	2345
A61611	'93 Econoline	2345
A34137	'93 Econoline	2243
A32248	'93 Econoline	2286
A47374	'93 Econoline	2307
A50451	'93 Econoline	2316
A49359	'93 Econoline	2338
A57954	'93 Econoline	2345
A92609	'93 Econoline	3037
B15536	'93 Econoline	3078
A40855	'93 Econoline	3175

3713-141

(13) switches were confirmed to be inoperative switches due to liquid ingress resulting in severe corrosion. Switch with date code 2307 was operating normally.

To: Ford  
From: TEC

Program Manager Name: TEC	Page No.: 14

(STEP 3)

**INTERIM CONTAINMENT ACTION**

We have completed the following actions in assessing the integrity of our current product:

1. Verified environmental seal integrity and proper function.
2. Verified switch connector base dimensions that could affect the mating connector sealing ability to be within specification.  
Based upon Texas Instruments' verification of the critical connector base dimensions, the functionality of the environmental seal, and observation of fluid ingress into the switch cavity through the terminal blades, an analysis/investigation of the mating connector sealing system is warranted.
3. Texas Instruments, in cooperation with Ford Light Truck Engineering, conducted a water ingress test with various component combinations of the mating connector, to determine relative susceptibility of each combination. The following combinations were tested:

Current Light Truck	Light Truck Before 11/92	Current Pass Car
-----	-----	-----
Black UTA shell	Black EPC shell	Black UTA shell
Gray Grommet	Gray Grommet	Gray Grommet
Red Silicon Seal	Red Sponge Seal	Red Sponge Seal

The matrix of components tested and the test sequence is outlined in attached charts. Preliminary data analysis did not show significant differences amongst various matrix elements. It has been concluded that the switches need extended exposure under shower to initiate water ingress. In addition to the above combination of components, 50% of the switches were tested with a "rocked" connector.

The shower test was halted on 10/6/93, when non-normal insulation resistance readings were observed on rocked switches. Upon removal of the connectors, water ingress was observed on all switches with rocked connectors. There was no ingress on correctly latched switches. The attached Table 1 summarizes the matrix of parts and visual observations. The ingress in vertical switches was of a magnitude higher than in horizontal switches. Photographs of the switches were sent to Ford Light Truck Engineering for review. The switches were calibrated for functionality. The attached Table 2 confirms the effect of ingress as seen in the reduction of insulation resistance and intermittent operation of the switches. The switches were then disassembled for internal inspection. It was observed that the ingress had proceeded through the connector cavity into the contact zone. Photographs are attached.

The ingress activity on the rocked switches was similar to that observed on parts returned from the field, albeit of a lesser magnitude. It is believed that, given sufficient time (to allow current to pass through the contacts), the ingress on the rocked switches would exhibit exactly the same failure as that observed on the warranty parts.

(STEP 4)            ROOT CAUSE  
-----

The switches analyzed were inoperative since there was no electrical continuity between the terminals. Attachment "B" shows the fishbone diagram for a stuck open switch. The lack of continuity was due to presence of large amounts of corrosion products inside the switch cavity and, in some cases, failure of contact elements due to corrosion. The large quantity of corrosion products is due to fluid that entered the switch cavity. Because of the severe amount of corrosion observed, it is believed that the corrosion is accelerated by the potential difference between the grounded body of the switch and current carrying members.

Thorough visual observation concluded the fluid entry to be through the mating connector end of the switch as evidenced by brass corrosion products along the terminal blades in the connector cavity (see attached photographs). Two of the switches exhibited blue/green corrosion by-products covering more than one half of the connector cavity. The others showed similar corrosion products but in lesser amounts. None of the switches showed any evidence of fluid ingress by the environmental seal.

The snap acting disc in all the returned switches was functioning normally.

The following observations were made by Texas Instruments on '83 Econoline and F-Series Trucks at a local Ford dealership:

1. Econoline: The wire leads coming out of the switch were routed below and touching the rear A/C line. This will create a propensity for water/condensation traveling along the line to flow along the wire leads to the grommet.

2. F-Series: The observed vehicles had a Red Sponge seal inside the mating connector, as opposed to the expected Red Silicone seal.

Additional observations regarding face seal variations:

1. The target zone for pressure switch sealing surface is smaller on the sponge seal, than the silicone seal. The smaller target zone, may lead to a sub-optimal sealing condition under worst case dimensional stack-up.

2. It has been seen that during the mating connector assembly process, there is an opportunity for the silicone seal to be rolled over. This can happen during insertion of the plastic terminal separator. The insertion is done after the silicone seal is placed in the plastic shell. A rolled over silicone seal would not provide protection against water ingress.

3. The silicone seal, by design, has a lower percent compression than the sponge seal. The design limits for the silicone seal are 10 - 15%, whereas the limits for the sponge seal are 38 - 50%. The reduction in percent compression was intended to maintain similar loading forces. It has been observed that there is a tendency for the mating connector to 'rock' in the latched position. The rocking tendency would lead to a higher percent change in the level of compression of the silicone seal than on the sponge seal.

The shower test detailed above, leads to the conclusion that a 'rocked' connector was the most probable root cause of the observed problem. The impact of the problem is magnified in the Econoline platform due to the mounting location and vertical mounting position, both of which are unfavorable from a ingress point of view.

(STEP 5) PERMANENT CORRECTIVE ACTION

---

No corrective action is required from Texas Instruments at this point.

(STEP 6) VERIFY CORRECTIVE ACTION


---

(STEP 7) PREVENT RECURRANCE

---

WARR3\_U.XLC

## 93 ECONOLINE






A4F855 DC3078A



- A4F855 DC3078A



A4F855 DC3078A

9713 1416

JAN 21 '98 11:11 FR MUSTANG - PROGRAM CTR 313 621 8147 TO 04145

P.07/09



A35294




A35294



A35294

3713 1417

ATTACHMENT "B"



3713 1418

connecting synapse matrix for shower head		W178C					
		a	b	c	d	e	f
shell	sil	sil	sil	sil	sil	apo	apo
movement	gray	gray	gray	gray	gray	gray	gray
face seed	sponge	sponge	silicone	silicone	sponge	sponge	
edge length	black	medium	black	medium	black	medium	
orientation	horizontal	horizontal	vertical	vertical	vertical	vertical	
component	pass-conference	pass-cad/breco	scandline	scandline	scandline	scandline	
# of switches	2	2	2	2	2	2	

3713 1419

= TOTAL PAGE: 20 OF 20

60 image 1024x768 pixels

ULLA CASSEL 408 136

file:///C:/My%20Documents/Programs/EN/EN%20Picture/4.jpg



9713 1420



3713 1421

Image 1024x768 pixels

ULLA CASSEL 403 134

Src: C:\My Documents\Program\EN\EN\PC00002.jpg



3713 1422

ULLA CASSER 403 136



3719 1423

VILLA CASSEL 408 136

S7131424



Vera Casser 408 136



3713-1425

Villa Cassa 408 136



3718 1428

ULLA CASSER 4OB 136

3719 1427




ECI image 1024x768 pixels

CASSEL  
Vera 408 136


C:\My Documents\Programm EN\EN PIC0004.jpg




9713 1429



3713 1429



3713 1430



3713 1431

Sharpe, Robert

From: Douglas, Charles  
Sent: Friday, December 18, 1998 10:37 AM  
To: Porter, Fred (Ford)  
Cc: Sharpe, Robert  
Subject: Usage Matrix - Speed Control Deactivation Pressure Switch

Fred,

The following represents a rough usage matrix over time:

MY92	MY93	MY94	MY95	MY96	MY97	MY98
Econoline						
Club Wagon						
Town Car						
Crown Vic						
Grand Marquis						
F Series						
Bronco						
SHO Taurus	SHO Taurus	SHO Taurus??	SHO Taurus??	Capri??	Win88	Win88
		Capri	Capri	Win88	Falcon	Falcon
		Win88		Falcon	Explorer??	Explorer
				Ranger??	Ranger	Ranger
					Expedition	Expedition
					Navigator	Navigator

To be quite honest, I think we actually have more of a grasp on the application matrix in the MY92 - MY95 timeframe than MY96 on. Where you see ??, this means the actual starting or ending model year for a program may be +/- 1 model year. Also, it is conceivable that as of the MY98 timeframe, we are actually released on more platforms than what is shown above. I say this because our actual shipped volumes which are in the 2MU range, would indicate either 100% penetration for cruise control on all of the platforms listed or we are on more than the listed platforms.

One additional note, during our discussion yesterday, you talked about the switch being hot on the Town Car. I think I misunderstood the context of your statement. At the time of our discussion, I was thinking thermal hot but upon further reflection believe you may have meant wired hot. If this is the case, I am pretty sure the switch is wired hot in virtually all of the above applications. This issue can be discussed further on Tuesday as we will be prepared to provide a brief overview on our understanding of how the switch is electrically plumbed into the system.

Any additional questions, please let me know me at your convenience. Also, if the above application matrix does not come across legible, please let me know and I will have this faxed to your attention.

Regards,

Charlie

Charlie Douglas  
(608) 236-3657 (P)  
(608) 236-1598 (F)  
c-douglas2@vti.com

12/21 (from C. Douglas)

Prod.

I believe that your list includes some service part numbers, older rev levels, as well as pre-production or prototype part numbers. Overall, including Ford Australia, there are eight different production parts. Differences from part to part are fairly minor and include, actuation calibration, release pressure, housing style, position tab / color of connector base, thread style, and snap noise associated with the pressure disc. The following matrix, helps summarize this information:

Part Number	Action	Release Base	Mount	Thread	Snap
F2VC 9F924 AB 90-160	(1)	20 min Brown / pos 2	J512	3/8-24M	Snap
P5LC 9F924 AA 200-300	(2)	40 min Black / pos 1	J512	3/8-24M	Snap
F2AC 9F924 AA 90-160	(3)	20 min Natural / pos 2	J512	3/8-24M	Quiet
F58A 9F924 AA 90-160	(4)	20 min Grey / pos 1	J512	3/8-24M	Quiet
P3TA 9F924 CA 200-300	(5)	40 min Red / pos 1	J512	3/8-24M	Snap
94DA 9F924 AA 90-160	(6)	20 min Natural / pos 2	o-ring	M10x1.0M	Quiet
F3DC 9F924 AA 90-160	(7)	20 min Natural / pos 2	Smaller	3/8-24M	Quiet
94JA 9F924 AB 90-160	(8)	20 min Grey / pos 1	o-ring	3/8-24M	Quiet

Vehicle - Part Number Correlation

- (1) Crown Vic, Grand Marquis, Mark, Town Car
- (2) Econoline, Club Wagon
- (3) Crown Vic, Grand Marquis, Mark, Town Car
- (4) Windstar
- (5) Bronco, F-Series, Ranger, Explorer, Navigator, Expedition, Econoline, Club Wagon
- (6) Falcon
- (7) SHO Taurus
- (8) Capri

3713 1433

*Chetelka  
Douglas  
23-C1*

TEXAS INSTRUMENTS INC.

MATERIALS & CONTROLS GROUP

SITE

PARTS LIST : PROJECT  
EXPLOSION : NUM: 3423

PART NUMBER: 77PSL2-1  
DWG PFX: NUM: 77PSL2-1

REV LTR: L CLS: 650  
ECN INC.DT: 98/02/24

TITLE: PRESSURE SWITCH

(CUST P/N F2VC-91-924-AB)

LV: CNT	QTY/UM	ITEM	PART/DRAWING NUMBER	REV	NOMENCLATURE/PARM DATA
01	1	REF	36952-1		FINAL ASSEMBLY
			36952-1	A	
01	2	1	27759-10		BASE ASSEMBLY
			27759SH1	L	
02	3	1	46515-2		BASE (BROWN)
			46515	N	
02	4	1	36888-1		STATIONARY TERMINAL
			36888	D	
02	5	1	36897-2		MOVABLE TERMINAL ASM
			36897SH1	H	
03	6	1	36887-1		MOVABLE TERMINAL
			36887	D	
03	7	1	74916-1		RIVET
			74916	G	
03	8	1	36889-1		SPRING ARM
			36889	B	
04	9	AK	27716-1		KAPTON MAT'L STR SPEC (.216 LBS/KI)
			27716SH1	D	
03	10	1	28744-1		MOVABLE CONTACT
			28744	D	
01	11	1	27293-13		SENSOR ASSEMBLY
			27293SH2	W	
02	12	1	36900-1		MOD SAE J312 HEXPORT
			36900	H	
02	13	1	74353-1		GASKET
			74353	H	
02	14	1	27713-1		CUP
			27713	F	
02	15	3	74176-1		SEAL
			74176	L	
03	16	HR	27225-1		KAPTON STRIP SPEC (.175 LBS/KI)
			27225	MB	
02	17	4	27639-1		WASHER
			27639	F	
02	18	1	27406-1		CONVERTER
			27406	F	
02	19	1	73958-2		SPACER
			73958	J	
02	20	OR	73958-3		SPACER
			73958	J	
03	21	AK	74224-1		KAPTUN TAPE (.100 LBS/KI)
			74224	F	
02	22	1	36656-27		3/4" FORMED DISC
			36656SH1	BM	
02	23	DR	36656-28		3/4" FORMED DISC
			36656SH1	BM	
			34797-1		CRIMP RING

3718 1434

31	26	1	21	74875 74247-4 74247	G! ENVIRONMENTAL SEAL
			22	74888-1 74888	L! THREAD CAP H!
	28	AK		27318-1 27318	CARTON ASM. D!
	29	1	21	74219-1 74219	CARTON D!
	30	3	31	74218-1 74218	ROW SEPARATOR D!
	31	2	41	27317-1 27317	DEVICE SEPARATION D!
	32	AK	51	13608-4 13608-4	ENCLOSURE TAPE D!

NOTES, REV. DATA, DISTRIBUTION, OPERATING CHARACTERISTICS, SPECIAL REQUIREMENTS

EV DESC: CHG 74408-1 TO 28744-1      ! CCB APPROVAL DATE: 98/02/24

FTG WORK GROUP: PRECISION CONTROLS      ! ECN ORIGINATOR: DI T MA

OTES:

- 1 - ACTUATION PRESSURE ----- 90 -160 PSIG
- 2 - RELEASE PRESSURE----- 20 PSIG MIN.
- 3 - DEVICE TO BE MARKED PER CODING SPECIFICATION 75871-1

TAILED REVISION DESCRIPTION:

99 CR M39209, 28744-1 CONTACT (MOV) WAS 74408-1  
 STOCK DISPOSITION  
 FINISHED DEVICES - USE  
 PARTS & SUB ASMS - USE SUBS, HOLD PARTS

**DRAWINGS AVAILABLE UPON REQUEST**

PROJ. # 3500

TITLE  
ATPS-DISC PROCEDUREREV  
A

75755 SH.1

75755 SH.1

## INITIAL SYSTEM LOGON:

FROM A BLANK IMS SCREEN TYPE IN  
 TSSON ATPSDA <USERID> <PASSWORD>  
 WHERE <USERID> IS YOUR IMS USER ID  
 AND <PASSWORD> IS YOUR IMS PASSWORD.

EX. TSSON ATPSDA A99999 PPPP

THEN PRESS THE ENTER KEY

THE RETURN SCREEN SHOULD BE THE ROUTE CARD SYSTEM MENU

AFTER INITIAL LOGON, YOU MAY ACCESS THE MENU FROM A BLANK IMS SCREEN BY  
 TYPING IN

ATPS000

THEN HIT ENTER

FOR REFERENCE ONLY  
 CHECK LATEST REVISION  
 BEFORE USE  
 Parts Made To This Print Must Conform To  
 ENG. STD. E9398 REV. E  
 DDB JAN 19 1990  
 RETAIN THIS PRINT FOR THE INFORMATION CON-  
 TAINTED THEREIN. IT MAY NOT BE COPIED, RE-  
 DUCED OR USED IN WHOLE OR IN PART, IN  
 ANY FORM, WITHOUT THE WRITTEN CONSENT OF  
 KLEIXON CONTROL PRODUCTS DIVISION OR ITS  
 AFFILIATED COMPANIES OR UNLAWFUL LIABILITY  
 SHALL BE ASSUMED.

## OPTION 20:

OPTION 20 OF THE MENU (OR ATPS020 FROM A BLANK SCREEN) WILL  
 ALLOW YOU TO DISPLAY A LIST OF DISC PARTS FOR A GIVEN DRAWING NUMBER.

FOR QUICK ACCESS TO THIS INFORMATION YOU MAY ENTER THE FOLLOWING  
 ON A BLANK IMS SCREEN:

ATPS020 <DRAWING\_NUMBER>  
 WHERE <DRAWING\_Number> IS THE PART II DRAWING THAT YOU WANT TO DISPLAY.

EX. ATPS020 9789SH245

THEN HIT ENTER

## OPTION 30:

OPTION 30 OF THE MENU (OR ATPS030 FROM A BLANK SCREEN) WILL ALLOW YOU TO  
 ACCESS CHARACTERISTIC DATA FOR A SPECIFIED DISC PART NUMBER.

FOR QUICK ACCESS TO THIS INFORMATION YOU MAY ENTER THE FOLLOWING  
 ON A BLANK IMS SCREEN:

ATPS030 <PART\_Number>  
 WHERE <PART\_Number> IS THE DISC PART THAT YOU WANT TO DISPLAY

EX. ATPS030 9769-6-900

THEN HIT ENTER

IF YOU HAVE ANY QUESTIONS OR PROBLEMS, PLEASE CONTACT DRAFTING

A LISTING OF PEOPLE TO CONTACT FOR HELP OR INFORMATION ON THIS SYSTEM  
 WILL BE MAINTAINED ON T10LR AND CAN BE ACCESSED AS FOLLOWS:

T.DA;RCS;USERDOC;CONTACTS

373-1448

1ST ISSUE / 1A  
 9-13-93, CFT / 1A  
 CR14298, J.H.G.

REV  
A

CHAS. FLEURANT 9-13-93  
 S. [Signature] 9-14-93  
 ENCL. 1A, 1B, 1C, 1D



TEXAS INSTRUMENTS  
 ATTLEBORO, MASSACHUSETTS 02703

KLEIXON  
 CONTROL PRODUCTS  
 DIVISION

REV  
B12  
SER. NO.  
A

75755 SH.1

AMERICAN STANDARDS ASSOCIATION

DEVICE # 77PSL  
PROJ. # 3355

TITLE

THREAD CAP

REV  
A


74888

74888

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 19 1999

NOTWITHSTANDING THIS PRINT CONTAINS THE INFORMATION CON-  
TAINED HEREIN IS TO BE USED AGAINST THE  
INTERESTS OF TEXAS INSTRUMENTS, INCORPORATED  
OR AGAINST THE INTERESTS OF ANY OF ITS AFFILIATES  
OR COMPANIES OR WHOLLY OWNED SUBSIDIARIES.



NOTE:

1. GATE MARK AND MANUFACTURER IDENTIFICATION IN RAISED LETTERS ON THIS SURFACE.

3713 1447

1ST ISSUE  
1-30-92, CF  
CRA07B57

74888-1	CAPPLUGS	EC-6	LOPE	RED
PART NO.	VENDOR	STOCK NO.	MATERIAL	COLOR

R	E	V	1	RS	A	3	032	1/2	037-2	LFB
BY	CHAS. FLEURANT	1-30-82	CH.	TEXAS INSTRUMENTS	KLIXON	RE	000	000	000	000



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

KLIXON  
CONTROL PRODUCTS  
DIVISION

A

74888

74224


## KAPTON TAPE

REV.  
F

74224

## NOTE:

1. ROLLS SLITTED FROM ENDS OF MASTER COIL NOT ACCEPTABLE.
2. BUCKLING OF THE CORE ALLOWED UP TO 1/4" MEASURED RADIALLY AWAY FROM THE CORE.
3. DENTS, RIPS, OR JAGGED EDGES ON MATERIAL NOT ALLOWED.
4. ROLLS ARE TO BE SHIPPED WITH PROTECTIVE INSERT CORES IN THE PACKING BOX.



3719 1448

ADDED MATERIAL BOX OF  
CR. 150-371-10-12-00

DEW 21

PART NUMBER	DUPONT'S, KAPTON 200H	.0017/.0023	
	MATERIAL	THICKNESS	

THIS DWG. SUPERSEDES 74224 REV. "E" DATED 10-14-88

BY TOM DAIL 10-14-88  
CH.  
ENG. 10-14-88 10-16-88



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

KODAK  
CONTROL PRODUCTS  
DIVISION

DWG. NO.  
A

74224

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E


Date JAN 19 1999

NEITHER THIS PRINT NOR ANY INFORMATION CONTAINED THEREIN IS TO BE USED AGAINST THE UNITED STATES INSTRUMENTS INC., OR AGAINST THE INTERESTS OF ANY OF ITS ASSOCIATED COMPANIES OR PARTLY OWNED SUBSIDIARIES.

## CRIMP RING

74797

74797



## NOTES:

1. PINCH OFF RADIUS ALLOWED.
2. .002 MAX. BURR ALLOWED.
3. PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.
4. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

3713-149

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E  
Date JAN 19 1999


NOTWITH THIS PRINT MAY NOT BE USED AGAINST THE  
INTEREST OF SEMI-INSTRUMENTS INCORPORATED  
OR AGAINST THE INTERESTS OF ANY OF ITS ASSOCIATED  
COMPANIES OR SUBSIDIARY ENTITIES SUBSIDIARIES.

SUPERSEDES DWG. 74797 REV. A DATED 11-2-90

74797-1	ALUMINUM 5052	
PART NO.	MATERIAL	FINISH

REV'D	ITSP	Q13	Q1	Q2	Q3
BY: DWG-PERIOD: 11-2-90					
CH: <i>J. S. S.</i> 1-30-90	TEXAS INSTRUMENTS	KLIKON	DWG. NO.		
ENG: <i>T. J. S.</i> 11-2-90	ATTLEBORO, MASSACHUSETTS 02703	GENERAL PRODUCTS DIVISION	A	74797	CODE: DRAFT - NO. 000000

73958



## NOTES:

- ◆ 1. .001 MAX. BURR ALLOWABLE.  
 2. PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.  
 3. ALL CONTAINERS OF PARTS MUST BE DATE CODED. DATE CODE IS TO REFLECT ANY MATERIAL LOT, TOOL OR PROCESS CHANGE.  
 4. MATERIAL CERTIFICATION REQUIRED WITH EACH LOT.

3713 1460

CHANGED THE SECOND NOTE THREE TO NOTE FOUR.  
J-30-93  
CRW/12792. D.P. /JPS

73958-4	KAPTON .0017 - .0023 THICK (FORD RCS)	.260/.270
73958-3	MADE FROM 74224-1 (KAPTON TAPE)	NO HOLE
73958-2	DUPONTS, KAPTON 200H, .0017 - .0023 THICK	NO HOLE
73958-1	KAPTON .0017 - .0023 THICK	.260/.270
PART NO.	MATERIAL	DIM "A"

THIS DWG. SUPERSEDES 73958 REV. "H" DATED 3-02-83.

DWG&gt;

BY TOM DAIL 10-10-88

DR.

*[Signature]*TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703KODAK  
CONTROL PRODUCTS  
DIVISIONREV. B  
A

73958

DEV. # 52PSL  
PROJ. # 3365

TITLE

SEAL

REV  
C

74176

74176

ADD SAME NOTE AS DN 74075  
03/17/98 MF  
ECON#39730 D.H.  
27225 WAS. 27287  
04/24/98 H.H.  
CR#9732 S.L.

151 151RF 57551  
02/01/84 H.H.  
CR#27286 D.S.

74176-1

MAKE FROM 27225-1 (STRIP)

PART NO.

MATERIAL

R E D I G  
SIGNATURES ON FILE, REFER TO  
ELECTRONIC CHANGE NOTICE.

THIS IS A CAD DRAWING. THE GEOMETRY IN THE ASSOCIATED CAD COMPUTER FILE IS DIMENSIONALLY ACCURATE.  
WHEN DRAWING IS BEING REVISED, THE GEOMETRY MUST BE UPDATED IN ALL VIEWS AND ON ALL SHEETS.




TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

KLIKON  
CONTROL PRODUCTS  
DIVISION

REV  
A

74176

3713-1461



FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENGL. STD. E9898 REV. E

Date JAN 19 1999

REMEMBER THIS PRINT AND THE INFORMATION CONTAINED THEREIN IS TO BE USED AGAINST THE  
LATEST OF THESE SPECIFICATIONS INCORPORATED OR AS AMENDED IN THE INTERESTS OF ANY OF THE APPLICABLE  
COMPONENTS OR MANUFACTURER'S SPECIFICATIONS.

NOTES:

1. .001 MAX. BURR ALLOWED.
2. ALL CONTAINERS OF PARTS MUST BE DATE CODED. DATE CODE IS TO REFLECT ANY MATERIAL LOT, TOOL OR PROCESS CHANGE.
3. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

74353


GASKET

H 74353

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 19 1999

NOTWITHSTANDING THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTEREST OF TEXAS INSTRUMENTS PREMISED UPON ACCEPTANCE THE STATEMENT OF FACTS IN THIS DRAWING CONCERNING COMPLIANCE OR NONCOMPLIANCE IS WHOLLY OWNED BY TEXAS.



3719 1452

## NOTES:

1. PARTS MUST BE PURCHASED FROM T.I. ENGINEERING APPROVED VENDORS, LISTED BELOW.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.
3. MATERIALS TO BE COMPATIBLE WITH FREON-12 & REFRIGERANT OIL.
4. PARTS TO BE SHIPPED, ISSUED, AND STORED ON 4 FOOT  $\frac{1}{4}$  X 6 INCH MANDRELS, SEALED IN PLASTIC BAGS AND SHIPPED IN CARDBOARD TUBES.
5. ALL CONTAINERS OF PARTS MUST BE MARKED TO REFLECT ANY MATERIAL LOT, TOOL OR PROCESS CHANGE.
6. DASH 1(-1) AND DASH 4(-4) GASKET MUST HAVE FOUR(4) WHITE STRIPING INK MARKS, EQUALLY SPACED AROUND THE CIRCUMFERENCE, AND NOT LESS THAN  $\frac{1}{8}$  INCH WIDE. NO INK IS ALLOWED ON ANY OTHER SURFACE.

**M**

C	D	E	F	G	H	I	J	K
ADDED-3 CROSSREFS ADDED	ADDED-4 CROSSREFS ADDED	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94	SEE C1-1-30-94 E 1-21-93-94
ADDED-3 CROSSREFS ADDED	ADDED-4 CROSSREFS ADDED	74353-4 TEL COMPOUND E-7104-70 TEL PART NO. 6197E	70	BLACK	.670-.662	.030-.036	.003	
ADDED-3 CROSSREFS ADDED	ADDED-4 CROSSREFS ADDED	74353-3 ETHYLENE PROPYLENE TEL COMPOUND E-7054	70	WHITE	.670-.662	.030-.036	.003	
ADDED-3 CROSSREFS ADDED	ADDED-4 CROSSREFS ADDED	74353-2 ETHYLENE PROPYLENE TEL COMPOUND E-7054	70	WHITE	.599-.591	.030-.036	.003	
ADDED-3 CROSSREFS ADDED	ADDED-4 CROSSREFS ADDED	74353-1 ETHYLENE PROPYLENE TEL COMPOUND E-7104-70 TEL PART NO. 6157E	70	BLACK	.599-.591	.030-.036	.003	

A	B	C
Part No.	Material	Dimension Color A H B M C

DIM.	125	Q131	Q1-1	M1-1	T5	P32	P35	P38
BY T. Dail S. Babb CH. S. J. M. J. ENG. J. J. M. J.	TEXAS INSTRUMENTS INCORPORATED ATTLEBORO, MASS., U.S.A.	KODAK CONTROL PRODUCTS DIVISION	A	74353				

DEVICE # 77/87PS  
PROJ.# 3423


TITLE

SWITCH RIVET

G

74916

74916



NOTES:

1. MATERIAL CERTIFICATION REQUIRED, TO BE KEPT BY SUPPLIER AND PROVIDED UPON TI'S REQUEST.
2. TAPERED HOLE IS ALLOWED.
3. PARTS MUST BE PACKAGED CLEAN AND DRY.

74916

SEE ECR # MARK UP FOR CHG.  
8/21/98 L.B.M. J.G.  
CR442191

74916-2	OBSOLETE PER CRM:5079	
74916-1	CDA 260 BRASS	NONE
PART NO.	MATERIAL	FINISH


SUPERSEDES DMG. 74916 REV. "F", DATED 9-30-93

G	SIGNATURES ON FILE, REFER TO ELECTRONIC CHANGE NOTICE.	THIS IS A CAD DRAWING. THE GEOMETRY IN THE ASSOCIATED CAD COMPUTER FILE IS DIMENSIONALLY ACCURATE. WHEN DRAWING IS BEING REVISED, THE GEOMETRY MUST BE UPDATED IN ALL VIEWS AND ON ALL SHEETS.
EW>		Q2-3 M5-3 013 Q3B M21 P37 P35
BRADEN CHAS. FLUENTANT 8-30-93	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	KLIXON CONTROL PRODUCTS DIVISION Dwg. No. A 74916

## TRANSFER PIN

74078

74078



S7131454

"L" LENGTH IS DETERMINED BY THE SUFFIX OF THE PART NUMBER IN THOUSANDTHS OF AN INCH. I.E.; PART NO. "L"  
 74078-155 .155  
 74078-210 .210

VENDOR WILL BE PREPARED TO FURNISH PINS .130 - .250 LONG.

## NOTES:

1. FINISHED PARTS TO BE SHIPPED, ISSUED AND STORED IN SEALED PLASTIC BAGS. SEALED PLASTIC BAGS TO CONTAIN 20,000 PINS( OR LESS FOR PARTIAL BAGS). BAGS MUST BE CLEARLY LABELED WITH THE PART NO. AND THE QUANTITY OF PARTS IDENTIFIED ON THE OUTSIDE OF EACH BAG.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

MATERIAL: L-3 GRADE STEATITE (DC-16E5) OR  
 L-3 GRADE STEATITE (DC-144E)

CURE PER SPEC. — 50502-2

SHTWINKAGE SPEC. — 50501-1

FOR REFERENCE ONLY  
 CHECK LATEST REVISION  
 BEFORE USE  
 Parts Made To This Print Must Conform To  
 ENG. STD. E9898 REV. E

Date JAN 19 1999

NOTWITHSTANDING THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE  
 MFTLSTY OF TEXAS INSTRUMENTS INCORPORATED  
 OR AGAINST THE INTERESTS OF ANY OF ITS AFFILIATED  
 COMPANIES OR SOLELY OWNED SUBSIDIARIES.

G THIS DWG. SUPERSEDES 74078 REV. "E" DATED 8-4-86

REWD		TS#	013	W1	MP2/P42-1/34
BY TOM DAIL 10-17-86	TEXAS INSTRUMENTS	KODAK	Dwg. No.		
CH.	ATTLEBORO, MASSACHUSETTS 02703	CONTROL PRODUCTS DIVISION	A		74078
ENG. 11/20/86					

13608-4

CLOSURE TAPE

13608-4

3" 60# TAPE  
COLOR NATURAL  
WATER ACTIVATED ADHESIVE  
NON-ASPHALTIC

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 19 1999

NEITHER THIS PRINT NOR THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE  
UNITED STATES OF AMERICA OR ITS INCORPORATED  
OR ASSOCIATE INTERESTS, OR ANY OF ITS AFFILIATED  
COMPANIES OR INBILLY OWN SUBSIDIARIES.

PRINT DATE 2/20/72  
C.R. 47187

Q.W.D.	3RT	146	TS-1 III-S T-1	US NIS V-1	V-1	M-1	D-1	P-1
BY BOARDMAN 2-15-72			TEXAS INSTRUMENTS INCORPORATED			KELIXON		
CH.	ATTLEBORO, MASS., U.S.A.			CONTROL RESPONSE DIVISION			OWS. NO. A	13608
ENG.	4-14	2-2-72						
PRINT ALIGNMENT: F-L-M INC								

DEV. # 82/5793  
PROJ. # 335

CARTON

REV.  
D

74219

74219

CONSTRUCTION TO BE RSC FROM 275 LB. CORRUGATED CARDBOARD  
WITH TAPE CLOSURE, TAPE OTHER THAN ASPHALTIC TYPE.

INSIDE DIMENSIONS

LENGTH 22 9/16" MIN.  
WIDTH 10 9/16" MIN.  
HEIGHT 6 5/16" MIN.

OUTSIDE DIMENSIONS

LENGTH 23" MAX.  
WIDTH 11" MAX.  
HEIGHT 7 1/2" MAX.

LENGTH 22 1/2  
WIDTH 10 1/2  
HEIGHT 6 5/16  
DATE 1-16-81

D

R

E

M

S

A

T

U

V

W

X

Y

Z

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 19 1999

NOTICE THIS PRINT IS FOR INFORMATION ONLY.  
CHANGES HEREIN ARE TO BE MADE AGAINST THE  
LATEST BY TEXAS INSTRUMENTS INCORPORATED  
OR AGAINST THE LATEST EDITION OF ANY OF ITS APPROVED  
COMPONENTS OR WHOLELY OWNED SUBSIDIARIES.

THIS DMO. SUPERSEDES 74219 REV. "C" DATED 10-16-80



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

BY TEC-SAL 10-11-80  
CH. ENG. John Howell 4/2/91

KODAK  
CONTROL PRODUCTS  
DIVISION

DMG.  
SIZE  
REV.  
NO.  
A

74219

74219  
9591


REV. # 82/57PS  
EROL. # 5358

ROW SEPARATOR

REV.  
D

74218

74218



3713 1467

MATERIAL: 200 LB. CORRUGATED CARDBOARD

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 19 1999

NEITHER THIS PRINT NOR THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTEREST OF TEXAS INSTRUMENTS INCORPORATED OR AGAINST THE INTERESTS OF ANY OF ITS AFFILIATED COMPANIES OR DIVISIONS OR THEIR EMPLOYEES.

THIS DWG. SUPERSEDES 74218 REV. "C" DATED 10-16-90

PAGE 15

REV. C

BY

CH.

ENG.

10-16-90

4 1/2

4 1/2



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

KODAK  
KODAK PHOTOGRAPHIC  
DIVISION

103

D1

A

DRAW. NO.

74218

F2VLC-9F 529

**1992/93 LINCOLN TOWN CAR/CROWN VIC/GRAND MARQUIS  
BRAKE PRESSURE SWITCH FIELD AUDIT**

VEHICLE TYPE	BUILD DATE	VIN	MILEAGE
Town Car	May-93	1LNMB82W4PY	42621
Town Car	Jun-92	1LNMB82WXNY	53237
Town Car	Jan-93	1LNMB81W3PY6	unknown
Grand Marquis	Nov-92	2MELM74W3PX	68302
Town Car	Oct-92	1LNLM83W7PY	72114
Grand Marquis	Dec-92	2MELM74W4PX	55333
Grand Marquis	Apr-93	2MELM74W5PX	66689
Grand Marquis	Dec-92	2MELM74W9PX	43531
Grand Marquis	Oct-92	2MELM75W4PX	94145
Town Car	Jan-93	1LMLM82W5PY	unknown
Grand Marquis	Jul-92	2MELM75WONX	57600
Town Car	Sep-93	1LNLM81WXBY	97199

PART #  
 /AB F422#  
 AB  
 AA  
 AB  
 AA  
 AB  
 AA  
 AA  
 AB  
 AB  
 AA  
 AB  
 AB

3713-1469

01/15/1999

7/16/99

OF 48 ~~ENTHIS~~ VEHICLES, I IDENTIFIED A BRAKE  
PRESSURE SWITCH.

T1 INVESTIGATION. PERFORATION OF ~~THE~~ ALL THREE  
DIAPHRAMS

CAN

CONTAMINATED REACH TEMPERATURE FOR BRAKE FLUID?


CAN T1 RUN THE TEST?

3713 1469

92-93 TOWN CAR  
JAN 15, 1999


NAME	Area	Phone	Props
TODD PORTER	RVT Chassis/Elec	84-53722	PORTER
BARRY EGAN	AVT Chassis-Breaks	32-39512	BEGAN
William Williams	AVT Chassis-Electronics		
ROB ENGLISH	AVT-202-503	33-73225	ENGLISH
CLARK THOMAS	AVT MATERIALS	59-41313	CTHOMAS
Steve L. Rovner	Concord Lab	84-54176	JLAROVNER
PETE KLAIB		32-2103	PKLAIB
GREG STEVENS	AVT MATERIALS	32-36686	GSTEVEN
Ken Bribble	" "	32-39657	KBRIBBLE
TOM BAZIL	LVC OPO Chassis	59-47547	TBAZIL
JOE ERIS	RVT Chassis-Breaks	32-23122	JEERIS
ZANDRA DEERING	" "	41062	ZDEERING

Hydraulic Pressure Switch Cross Section



3713 1481

### Hydraulic Pressure Switch Cross Section



3713 1462



Central Laboratory  
16000 Century Drive  
Dearborn, MI 48120-1267

January 15, 1989

Preliminary Findings:

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 360 brass, which is highly susceptible to SCC.

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the hex port and on the cup, converter, and disc appear to be compounds which may have formed from a reaction between decomposition products (acids) of the polyester base, the brake fluid, and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any melting parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragm.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (surfaces bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.

The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (tin plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus)

Steve LaRouche

3713 1463



Central Laboratory  
15000 Century Drive  
Dearborn, MI 48120-1297

January 15, 1999

**Preliminary Findings:**

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 360 brass, which is highly susceptible to SCC.

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the hex port and on the cup, converter, and disc appear to be compounds which may have formed from a reaction between decomposition products (acids) of the polyester base, the brake fluid, and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any mating parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragms.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (all facets bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.

The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (tin plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus).

Steve LaRoucha

3713 1464



Central Laboratory  
15000 Century Drive  
Dearborn, MI 48120-1267

January 15, 1989

Preliminary Findings:

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 360 brass, which is highly susceptible to SCC.

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the hex port and on the cup, converter, and disc appear to be compounds which may have formed from a reaction between decomposition products (acids) of the polyester base, the brake fluid, and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any mating parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragms.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (surfaces bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.


The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (tin plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus)

Steve LaRouche

3713 1466

37191486




**Switch D**  
**F2VC-9F924-AA 6329A**

11/19/05  
LGH 44 SWITCH

2FALP71W1VX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20 PE 98-055



3713 1487



**Switch D**  
**F2VC-9F924-AA 6329A**

2FALP71W1VX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20


3713 1469



**Switch D  
F2VC-9F924-AA 6329A**

2FALP71W1VX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20

3713 1469





**Switch D**  
**F2VC-9F924-AA 6329A**

WALKAWAY  
CONY SWITCH

2FALP71W1VX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20 DE 98-055


97131470




**Switch D**  
**F2VC-9F924-AA 6329A**

2FALP71WIVX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20

87431471




2FALP71W1VX [REDACTED] 1997 Crown Victoria - Police - Vero Beach, FL 99-Jan-20



**Switch D**  
**F2VC-9F924-AA 6329A**

8713 1472



ILNLM92WXNY

1992 Lincoln Town Car - Dallas, TX, 99-Jan-13

1648-055



3713 1473

1LNLM92WXNY

1992 Lincoln Town Car - Dallas, TX, 99-Jan-13

PE 98-055

3719 1474



1LNLM92WXNY

1992 Lincoln Town Car - Dallas, TX, 99-Jan-13

ME 98-055

3713 1476






Switch A

1LNLM92W1PY

1993 Lincoln Town Car - Houston, Tx 99-Jan-14 PE98-055


3713 1476



1LNLM92W1PY

1993 Lincoln Town Car - Houston, Tx 99-Jan-14 PE98-055

3713-1477



**Switch A**

**F2VC-9F924-AB 2281**



**1LNLM92W1PY**

**1993 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055**

3713 1478




Switch B



1LNLM83W5NY745119 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

37131478





1LNLM83W5NY [REDACTED] 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

37131480

ILNLM83W5NY

1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 1481





**Switch B**

**F2VC-9F924-AB 2114**

**1LNLM83W5NY**

**1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055**


3713 1482



**Switch B**

**F2VC-9F924-AB 2114**

**ILNLM83W5NY** [REDACTED] 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055






Switch C

3713 1483

1LNLM81W2NY

1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 1484



**Switch C**

**F2VC-9F924-AB 2003**

1LNLM81W2NY

1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 1485



1LNLM82W7NY

1992 Lincoln Town Car - Houston, TX 99-Jan-14

PE98-055

12/16/78

IS SWITCH STILL IN USE?

WHAT OTHER VEHICLES USE THIS SWITCH

- ① BRAKE FLUID LEAK - HIGH RESISTANCE TO GROUND
- ② TABS CORRODED - INNER LEAK — "
- ③ EXTERNAL LEAK INTO

- \* 21 INITIALLY SITED ON 20 NOV 98
- \* 20 ADDITIONAL CLAIMS SINCE REPORT

SOUTHERN STATES

9F924

FAULT CODES? ARE THERE ANY WHEN FAILURE OCCURS?

CAN THIS AFFECT BRAKE LAMPS

TI PWT? NORM FREON

Buyer?



3713 1486

BRAKE PRESSURE SWITCH MTG 12-16-98

ROB ENGLISH	AVT-EES-EOS	73225	ENGLISH
NORM LAPORTE	AVT-DES-FVAL	42686	N LAPORT
JIM GREGOIRE	AVT EEE OPE	39962	J GREGOIR
FRED PORTER	AVT-EESSE	53722	F PORTER
WILLIAM ADAMCZEK	ASO	23284	WADAMCZE
RON WILSON	---	03133	WILSON
WILLIE MCKEELEY	L.C. SAFETY	32 2 276	MCKEELEY

RAY NEVI

CENTRAL LAB  
ASR — X-RAY

KEN GRIBBLE AVT-MATL  
CLARK THOMAS




3713 1487

9713 1488





PE98-055  
98-Dec-14

3713 1499



PB98-055  
98-Dec-14


**F. BY FORD MOTOR CO. IN U.S.A.**  
MFG. 11/92      6000 S/N 17/27449  
FRONT GEAR 2800 LB. - 141524  
REAR GEAR 2741 LB. - 141524  
MOTOR 100 HP 12V 2400 RPM  
GEAR 1000 RPM  
MOTOR 100 HP 12V 2400 RPM  
GEAR 1000 RPM



9719 1480



TE98-055  
98-Dec-14

9713 1491




PE98-055  
98-Dec-14

3713 1492




PI98-055  
98-Dec-14



3719 1483

PE98-055  
98-Dec-14

3713-1494



PE98-055  
98-Dec-14



3713 1465

PE98-055  
98-Dec-14

Page: 01

## CQIS DETAIL REPORT

12/07/98 15:14:14

CQIS Report Number: WJIAA135 Program Type: Q  
Report Source: MBS - FCSD - QSPSOrig Rpt #: 223931-98  
Report Date: 10/09/1998

## ----- R E P O R T S U M M A R Y -----

VEHICLE:	1993 TOWN CAR, SIGN, SEDAN	VIN :	1LMLM82W0FY622977
Engine :	4.6L ROMEO BASE ZFI	Odometer:	51,500 MILES
Operating Environs:		MCC :	3D05
Vehicle Use :		Rep. Act.:	
SYMPTOM:	3 01 0 00 CHASSIS OTHER (CODE NOT AVAILABLE)	SERVICE BRAKE SYSTEM OTHER (CODE NOT AVAILABLE)	
Additional Symptom:			
Other Veh. With Concern:		Severity Rating - Customer:	Engineering:
Causal Component:	2B264	SWITCH BRAKE PRES WORN L	
Causal Factor:		Feature:	Loc:
Causal Condition:		Photo:	Image#:
Component Test Status:		---- Return Loc:	
Vehicle Fixed?: YES	Customer satisfied?:	Repair Effectiveness (%):	100

## ----- C O M M E N T S -----

--TYPE-- COMMENT TEXT

**CONCER** INITIALLY THE CUSTOMERS CONCERN WAS THAT THE VEHICLE WOULD NOT COME OUT OF PARK. WHILE IN THE DEALERSHIP, AN UNEXPLAINED FIRE STARTED, CAUSED BY A LEAKING BRAKE FLUID THROUGH THE SWITCH INTO THE CONNECTOR.

**REPAIR** REPLACED THE SPEED CONTROL SWITCH AND CONNECTOR. REPLACED THE STOP LAMP SWITCH FOR THE ORIGINAL CUSTOMERS CONCERN. PER TECHNICIAN, THIS IS THE THIRD UNIT THAT HAD AN UNEXPLAINED FIRE THAT APPEARED TO ORIGINATE FROM THIS AREA. THE OTHER TWO WERE TOO DAMAGED TO DETERMINE THE SPECIFIC LOCATION OF THE POINT OF THE ORIGIN. THE SWITCH AND CONNECTOR ARE PRESENTLY IN MY POSSESSION IN THE MEMPHIS REGIONAL OFFICE.

**AUDIT** 10/14/1998 09:56AM FRENDA WENDEL MBS - FCSD - QSPS  
- DEALER ID 68523 CHANGED TO 12098 BY FRENDA WENDEL

## ----- C O N C E R N D E T A I L S -----

----- D I A G N O S T I C I N F O R M A T I O N -----

Symp. Verif?:	Ease of Diagnosis:	Level of Assistance:	
Comp. Timing:	Base Timing	NIL light on?	
Test Stand:	Road Test	SD Number:	
Prior Repair Attempts:		Repair Prior to Call: NO	
DTCs Read:	K03C:		
CODE:	CB1:		
Equipment/Procedure Used	Effective?	Equipment/Procedure Used	Effective?

## ----- S E R V I C E A C T I O N S -----

Repair	Type	Component Number	Number	Description	Causal Comp.
Type	Component Number				
RPL	2B264		SERVICE	SWITCH BRAKE PRES WORN L	YES

## ----- V E H I C L E D E T A I L S -----

Vehicle Build Date:	09/10/1992	Warranty Start Date:	02/08/1993
Date of Sale:	02/08/1993	Billing Dlr (Mkt.Dlr,Sub):	12098
Dealer Special Order:		Gross Vehicle Weight:	
LH/RH Drive:			

## ----- 2 N G I N E -----

Engine: 4.6L ROMEO BASE ZFI	Calb: 318J810 A	Tag: 30	812 AA
Std Cc:			
		Serial #: W	

REDACTED

3713 1496M

Page: 02

CQIS DETAIL REPORT

12/07/98 18:14:14

CQIS Report Number: WJ11A135 Program Type: Q Orig Rpt #: 225951-98  
Report Source: M55 - FCSD - QSPS Report Date: 10/09/1998

- - - T R A N S M I S S I O N - - -

Trans: AOD-E 4SP 4LSC O/D Part #:  
Bld Dt: Serial #:

Model: Plt: Shift:

Axle: 6.0 3.08 CONVENTIONAL Id Tag Code: Bld Dt: Plt:  
Serial #: - - - A X L E - - -

Tire : P215/70R15 WSW Brand :  
Radio : ELECTR PREMIUM AM/FM STRO/CSTZ A/C : ATC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY ----- AQUAMARINE FROST C/C

- - - - A F T E R M A R K E T M O D I F I C A T I O N S - - - -

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

- - - - R E P O R T O R I G I N A T O R - R E P A I R F A C I L I T Y - C U S T O M E R I N F O R M A T I O N - - - -

Orig/Caller : Title: OTHER

Repair Dlr: 12098 - SCHILLING L-M/MENDENHALL INC Phs:(901) 794-4000  
City: Memphis State : Tennessee  
Country: UNITED STATES Region : Memphis - 23

Claim #: 07/19/1998

Customer name [REDACTED] City :

- - - - C Q I S V . I N H I S T O R Y - - - -

NO CQIS VIN HISTORY AVAILABLE FOR THIS VEHICLE

- - - S U P P L E M E N T A L S U R V E Y : N O N E - - -

- - - - V E H I C L E ' S W A R R A N T Y H I S T O R Y ( 3 6 5 d a y s o n l y ) - - - -

NO VEHICLE WARRANTY HISTORY AVAILABLE FOR THIS VEHICLE

3713 1497M

CQIS Report Number: VDUA322 Program Type: Q  
 Report Source: MSS - FCSD - QSPS

Orig Rpt #: 134596-97  
 Report Date: 04/21/1997

## ----- REPORT SUMMARY -----

VEHICLE:	1992 TOWN CAR, STAND, SEDAN	VIN :	1LXLM61W8NY714787
Engine :	4.6L ROMEO BASE EFI	Odometer:	56,802 MILES
Operating Environ:		WCC :	5F07
Vehicle Use :		Rsp. Act:	
SYMPOTM:	7 04 2 45 UNKNOWN SOURCE CONCERN'S SMOKE	FIRE/SMOKE UNDERHOOD	
Additional Symptom:			
Other Veh. With Concern:		Severity Rating - Customer:	Engineering:
Causal Component:	2A574	SWITCH ASY LOW AIR P	
Causal Factor:		Feature:	Loc:
Causal Condition:		Photo:	Images: 0
Component Test Status:		---- Return Loc:	
Vehicle Fixed?: YES	Customer satisfied?:	Repair Effectiveness (%):	100

## ----- COMMENTS -----

--TYPE-- **COMMENT TEXT**  
**CONCER** THERE WAS SMOKE FROM UNDER THE HOOD.  
**REPAIR** THE BRAKE PRESSURE SWITCH CAUGHT ON FIRE AND BURNED THE WIRING WITH THE KEY OFF. PREVIOUS VEHICLES WITH FIRES STARTING IN THIS AREA WERE BURNED TO THE DEGREE THAT WE COULD ONLY GUESS WHAT CAUSED THE FIRE. THIS VEHICLE FIRE STOPPED SOON ENOUGH. WE REPLACED THE BRAKE PRESSURE SWITCH.  
**AUDIT** 04/23/1997 10:25AM DATA ENTRY'S MSS - FCSD - QSPS  
**SYMPOTM** 3 01 0 00 CHANGED TO 7 04 2 45 BY MBAKER6

## ----- CONCERN DETAILS -----

----- DIAGNOSTIC INFORMATION -----  
 Symp. Verif?: Ease of Diagnosis: Level of Assistance:  
 Comp. Timing: Base Timing : MIL light on? :  
 Test Stand : Road Test : SD Number:  
 Prior Repair Attempts: NO  
 DTCs KOEO: KOEC: Repair Prior to Call: NO  
 KOER: CB:  
 Equipment/Procedure Used: Effective? Equipment/Procedure Used Effective?

## ----- SERVICE ACTIONS -----

Repair Type	Component Number	Number	Description	Causal Comp.
RPL	2A574	TYPE SERVICE	SWITCH ASY LOW AIR P	YES

## ----- VEHICLE DETAILS -----

Vehicle Build Date:	04/07/1992	Warranty Start Date:	10/02/1992
Date of Sale:	10/02/1992	Selling Dlr (Mkt,Dlr,Sub):	11627
Dealer Special Order:		Gross Vehicle Weight:	
LH/RH Drive:			

## --- ENGINE ---

Engine: 4.6L ROMEO BASE EFI	Tag: 2G	812 MA
Bld Dt:	Calib: 218JRC3 A	Serial #: N

## --- TRANSMISSION ---

Trans: AOD-E 4SP ELEC O/D	Part #:	
Bld Dt:	Serial #:	
Model:	Plt:	Shift:

Page: 02

## CQIS DETAIL REPORT

12/07/98 18:14:12

CQIS Report Number: VDVARA322 Program Type: Q  
Report Source: MSS - FCSD - Q6FSOrig Rpt #: 134596-97  
Report Date: 04/21/1997Axle: 8.8 3.05 CONVENTIONAL Id Tag Code: Mid Dr: Plt:  
Serial #:Tire : P215/70R15 M/SW Brand :  
Radio : ELECTR PREMIUM AM/FM STER/CSTR A/C : ATC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY ----- CLEAR CRYSTAL BLUE FROST C/C

## ----- A F T E R M A R K E T M O D I F I C A T I O N S -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- R E P O R T O R I G I N A T O R - R E P A I R F A C I L I T Y - C U S T O M E R I N F O R M A T I O N -----  
Orig/Caller : GEORGE TAYLOR Title: OTHERRepair Dir: 11627 - Ft Lauderdale L-M Inc Ph#: (954) 779-2060  
City: Ft Lauderdale State : Florida  
Country: UNITED STATES Region : Orlando - 24

Claim #: Date :

Customer name : City :

## ----- C Q I S V I N H I S T O R Y -----

Date	CQIS	Prog	Report #	Type	Synd Cat	Causal Part Description	Dealer Id
04/22/1997	VDVARA114	EDSR	ELECT.		VALVE-FRT DISC BRAK P		11627

## --- S U P P L E M E N T A L S U R V E Y : N O W E

----- VEHICLE'S WARRANTY HISTORY (365 days only)  

Repair Dealer ID	Repair Date	Odometer Order	Rpr Causal Service	Part Number	Labor

11627 04/21/1997 56802

\*\* TOTAL PAGE.02 \*\*

3713 1498

AMERICAN (500 EAST)

29 DATE TIME TO/FROM  
12/18 15:28 313-398-6882MODE MIN/SEC POS CDRN STATUS  
EC-5 62'67" 000 018 OKFord Motor Company  
Environmental and  
Safety Engineering139 Town Center Dr.  
Dearborn, Michigan 481263M IDT™ 9163 TRANSMISSION  
TELEPHONE: (313) 594-2284AUTOMOTIVE SAFETY OFFICE  
PRODUCTION VEHICLE SAFETY  
AND COMPLIANCE  
FAIRLANE PLAZA SOUTH, SUITE 300  
DEARBORN, MI 48126DATE: 98-DEC-10TIME: 3:12 PM EST

Please deliver to:

Name: STEW MULVENNEY / JOE NEMEOrganization: CPO

Room # and Building: \_\_\_\_\_

Telephone: \_\_\_\_\_

FAX: 06002Number of Sheets being Transmited (including this one): 5

Special Instructions/Notes:

I TALKED TO JAMES FARRELL, SERVICE TECH AT SCHILLING U/H REGARDING THE 3 FILES. HE INDICATED DIRECT SHIP TO EXIMCO. TOM MESSERLY 401-777-7077 HAS THE PARTS. PLEASE ASSIST ME IN OBTAINING THESE PARTS.


Transmission sent by (Name/Telephone):

W.M. ADAMCZYK

x 23784

3713 1600

3713 1601



60 image 1024x768 pixels

Sheet A PIC00084.jpg



379 1502

HQ image 1024x768 pixels

File: A\_PIC0000013.jpg




3713 1503

80 image: 8024x768 pixels

File: A:\PIC00002.jpg



3719 1604



3743 1605

✓ 3:60  
3:30

## SPECIFICATIONS AND NOTES

DEVICE MUST CONFORM TO FORD MOTOR CO. SPEC. NO. ▽ ES-F2VC-BF924-AA

ACTUATION PRESSURE ----- 862 ±241 kPag (125 ±35 psi<sub>f</sub>)

RELEASE PRESSURE ----- 138 kPag MIN. (20 psi<sub>f</sub>)

CONTACT ARRANGEMENT ----- SPST NORMALLY CLOSED, OPEN ON PRESSURE RISE

HYDRAULIC SEAL ----- ETHYLENE PROPYLENE


PROOF PRESSURE ----- 20.7 MPa (3000 psi)

PROTECTIVE COVER ON THREADS REQUIRED FOR SHIPMENT.

3713-1626

FINISHING AND TOLERANCING IN  
ANCE WITH ANSI Y14.5M-1982





3713 1607

#### **Engineering Specification**

FRAME 1 OF 18

▼ 35-2010-99904-14

**DET PD 5047-47** *anywhere in the state may be used*

3713 1508

## Engineering Specification

### STEERING ANGLE - SPEED CONTROL MECHANISM

#### I. General

This specification covers the test requirements for the speed control deactivate switch -99924- used in the electronic speed control system. Design changes on the switch assembly or its components shall not be made without compliance to Section V of this specification and written approval from the releasing Productive Engineering Office.

This engineering specification is a supplement to the released drawing of the above part, and all requirements herein must be met in addition to all other requirements of the part drawing. Minimum measures necessary for demonstrating compliance to these requirements are given in each section.

The engineering tests, sample sizes, and test frequencies contained within this engineering specification reflect the minimum requirements established to provide a regular evaluation of conformance to design intent. The engineering test program is intended as a supplement to normal material inspections, dimensional checking and in-process controls, and should in no way adversely influence other inspection operations.

QI suppliers may implement different test sample sizes and frequencies providing these changes have been included in an alternate Control Plan approved by the design responsible Product Engineering Office and concurred in by QG.

#### II. PRODUCTION VALIDATION AND IN-PROCESS TESTS

- Production Validation (PV) Tests must be completed satisfactorily with parts free production tooling (and processes where possible) before IAE approval and authorization for shipment of production parts can be effected. Parts must be revalidated completely, or per Section V whenever any change is made which could possibly affect part function or performance.
- In-Process Test Phase 1 (IP-1) - IP-1 tests are used to demonstrate process capability and must be completed using initial production parts from production tooling and processes prior to final production shipment approval. IP-1 tests are to continue in effect until process capability is demonstrated.
- In-Process Tests Phase 2 (IP-2) - IP-2 test programs may be implemented only after process capability has been established. Tests must be completed with production parts on a continuing basis. Samples for these tests must be selected on a random basis to represent the entire production population as much as possible. In the event that any of the requirements in these tests is not met, the reaction plan specified in Ford Q141 Sect. 3.3, "Engineering Specifications (ES) Test Performance Requirements" shall be invoked.

2	18	REVIEWED	REVISION	V ES-PVTC-99924-AA
NAME	OF	REVIEWED	REVISION	

ME PD 3947-02 Revision edition use MEB to issue

SECTION III. TESTS AND TESTS

Item	Test Name Functional Criteria	PRODUCTION VALIDATION			IN-PROCESS IP-1			IN-PROCESS IP-2		
		Minimum Sample Size	Statistical Acceptance Criteria	Test	Minimum Sample Size	Statistical Acceptance Criteria	Test	Minimum Sample Size	Statistical Acceptance Criteria	Test
<b>III.</b>										
A	Calibration	72	P90-.96	100%	All Test Pass	100%	All Test Pass	100%	All Test Pass	
B	Voltage Drop	72	P90-.96	12/lot	P90-.96	4/Lot				
C	Current Leaks	72	P90-.96	3/lot	P90-.96	4/Lot				
D	Proof Test	72	P90-.96	12/lot	P90-.96	4/Lot				
F	Burst	6	P90-.72	3/lot	P90-.96	4/Lot				
I	Vibration	6	P90-.72	3/lot	P90-.96	6/6 lot	P90-.72			
J	Terminal Strength	12	P90-.96	6/lot	P90-.72	4/Lot	All Test Pass			
K	Vacuum	6	P90-.72	3/lot	P90-.96	6/6 lot	P90-.72			
L	Temperature Cycle	6	P90-.72	3/lot	P90-.96	6/6 lot	P90-.72			
M	Fluid Resistance	36	P90-.96	36/1200	P90-.96	36/1200	P90-.96			
<b>IV.</b>										
<u>Reliability Tests</u>										
E	Impulse	24	P90-.96	12/lot	P90-.96	3/3 lot	P90-.96			
G	Humidity	6	P90-.72	3/lot	P90-.96	6/6 lot	P90-.72			
H	Salt Spray	6	P90-.72	3/lot	P90-.96	6/6 lot	P90-.72			

3713 1510

Engineering Specification								
<u>TESTS FOR VIBROGRAPHIC TEST CEMENT</u>								
72. TEST SAMPLES								
III. A. CALCULATION B. VIBRATING TEST C. CEMENT TESTS D. FROST TEST								
72								
36								
76								
III. B. TESTS FOR CEMENT								
36								
6	6	6	6	12	12	12	6	6
III. C. TEST	III. D. VIBRATION	III. E. TEST	III. F. TESTING STICK	III. G. TEST	III. H. TESTING STICK	III. I. TESTING STICK	III. J. TEST	III. K. TEST
6	6	6	6	6	12	12	6	6
ALL TEST PENS								
64								
III. A. CALCULATION B. VIBRATING TEST C. CEMENT TESTS D. FROST TEST								
64								
ALL TEST PENS								
4	16	REVIEWED	NUMBER	VIB-TEST-SP-20-A				
PRINTED	OF	REVISED	NUMBER					

NAL PD 3947-02 Previous editions are NOT to use

3713-1511

## Engineering Specification

### III. TEST REQUIREMENTS

#### ▽ A. Calibration

##### 1. Test Requirements

- a. Switch calibration is to be checked at room temperatures ( $15^{\circ}\text{C}$ - $35^{\circ}\text{C}$ ) using ambient air or equivalent.
- b. Calibration settings shall be specified on the part drawing with the settings checked after 2 or more pressure cycles with ambient air, or equivalent. Pressure cycle range is to be determined by the manufacturer to insure switch calibration stability. The cut-in and differential set points are to be measured while conducting  $730 \pm 50$  millibars while  $13.0 \pm 1.0$  volts D.C. is applied. The cut-in point is to be checked with increasing pressure.
- c. The cut-out point is to be checked with decreasing pressure, and the differential set point is to be calculated using the cut-in pressure minus the cut-out pressure.

##### 2. Acceptance Requirements

- a. Nonconformance is defined as any switch point which falls outside the tolerance band specified on the part drawing.

#### B. Voltage Drop

##### 1. Test Requirements

- a. Voltage drop is to be measured after 2 or more cycles with ambient air or equivalent from 0 to  $10,000 \pm 172$  KPa ( $1450 \pm 25$  PSI) while conducting  $730 \pm 50$  millibars and  $13.0 \pm 1.0$  volts D.C. is applied to the switch. Under these conditions with the switch closed the voltage drop is to be measured. Millivolt connection interface at terminals to be less than 10 millivolts.

##### 2. Acceptance Requirements

- a. Nonconformance is defined as a voltage drop in excess of 200 millivolts.

5	18		▽ 10-1730-99924-AA
PRINTED	REVISED		NUMBER

EN PD 5947-62 (version 2000) may be used

3713 1612

## **Engineering Specification**

### **III. TEST PROCEDURES AND REQUIREMENTS (cont'd)**

#### **C. Current Leakage**

##### **1. Test Requirements**

- a. Current leakage is to be checked with 500 volts, 60 Hz alternating current.
- b. Current leakage is to be checked:
  - (1) Between the switch leads with the contacts open.
  - (2) Between the lead and the switch housing with contacts closed.
  - (3) Between either lead and switch housing with the contacts open.

##### **2. Acceptance Requirements**

- a. Nonconformance is defined as any leakage current in excess of one hundred (100) microamperes.

#### **D. Proof Test**

##### **1. Test Requirements**

- a. Subject sample switches to Section A to establish their initial switching pressures.
- b. Proof test is to be conducted using brake fluid or equivalent as the pressure medium. Test pressure shall be as specified on the part drawing. Test pressure shall be isolated from pressure source and held for not less than 30 seconds.
- c. Redoak the switches to Section A.

##### **2. Acceptance Requirements**

- a. No evidence of fluid leakage, seepage, or drop in test pressure greater than 430 KPa (42 PSI) is permitted.
- b. A change in cut-in and cut-out pressures greater than  $\pm 3\%$  from the initial value is not permitted.
- c. The test samples must be destroyed after testing.

6	10	REVIEWED	NUMBER	V 10-2200-97924-Aa
NAME	CR			

TM PD 3247-62 Revision edition November 1969

3713 1513

## Engineering Specification

### III. TEST REQUIREMENTS (cont'd)

#### B. Impulse

##### 1. Test Requirements

- a. Test the switch for a total of 500,000 cycles.  
Cycle pressure between (low) 0-275 KPa (0-40 psi)  
and (high) 10,000 ± 345 KPa (1450 ± 50 psi).
  - 1) 0 - 475,000 cycles: 13 ± 1 volts, current to  
switch function.
  - 2) 475,001 - 500,000 cycles: 13 ± 1 volts D.C., 750  
± 50 mA., per Figure 4.
- b. Brake fluid temperature to be  $115 \pm 14^\circ\text{C}$  and ambient  
temperature to be  $107^\circ\text{C}$  min.
- c. Cycle rate is to be 110-130 cycles per minute.
- d. Switch must open and close each cycle.

##### 2. Acceptance Requirements

- a. After impulse test check to sections A, B, C, & D  
using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting  
the criteria in sections A, B, C, & D.
- c. Samples used for this test must be destroyed after  
all testing is completed.

#### C. Impact

##### 1. Test Requirements

- a. Impact strength is to be checked using brake fluid or  
equivalent as the pressure medium.
- b. Pressurize the switch to 48.3 KPa (7000 psi) minimum  
and hold for 30 seconds minimum.

##### 2. Acceptance Requirements

- a. Nonconformance is defined as any evidence of fluid  
leakage or escape from the switch or threads.  
Samples used for this test must be destroyed after  
testing is completed.

7	10			▽ 66-J2WC-97924-24
FRAME	OF	REVISED		NUMBER

SAFETY DATA SHEET

3713 1514

## Engineering Specification

### C. Humidity

#### 1. Test Requirements

- a. Mount the switch in the test port in a humidity chamber. Currently released mating electrical connector must be installed before start of test.
- b. Subject the switch to ten (10) continuous humidity cycles as follows:
  - (1) Raise temperature to 65 +10/-2 °C over 2.5 hours; at 90-95% relative humidity.
  - (2) Hold 3 hours at 65 +10/-2 °C at 90-95% relative humidity.
  - (3) Lower temperature to 25 +10/-2 °C over 2.5 hours; at 50-55% relative humidity.

#### 2. Acceptance Requirements

- a. Within 15 minutes after completion of the tenth humidity cycle, check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D.

### D. Salt Spray

#### 1. Test Requirements

- a. Mount the switch in the test port in a salt spray chamber. The currently released mating electrical connector and wiring must be installed prior to start of test.
- b. Expose the switch assembly to 72 hours of salt spray per ASTM B-117.

#### 2. Acceptance Requirements

- a. After exposure, check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

0	15			✓ MIL-PRF-97024-AA
PHASE	OF	REVISED		REVISION

MIL PD 2947-62 Revision 00 08/06/00

3719 1515

## **Engineering Specification**

### **III. TEST METHODS AND PROCEDURES (cont'd)**

#### **1. Vibration**

##### **1. Test Environment.**

- a. Mount the switch in the test part and attach the currently balanced acting electrical connector before start of test.
- b. Switches are to be vibrated in all 3 planes with electrical continuity being monitored during the entire test. See Figure 1 for switch orientation in the 3 planes. Vibration tests are to be conducted at room temperature using brake fluid, ambient air, or equivalent as the pressure medium.
- c. Internal pressure shall be maintained at 0 KPa g. when the switch is in the closed position and 1.1 times max actuation pressure shown on print when the switch is in the open position.
- d. Vibrate the switch at 1.5 mm displacement (peak-to-peak) while varying the frequency uniformly from 2 to 50 to 3 Hz over a 3 minute period.
- e. Vibrate the switch in alternate one-hour periods in the open and closed positions for a total of 8 hours in each plane. (Total test time is 16 hours).

##### **2. Acceptance Requirements.**

- a. After the entire vibration sequence check the switches to sections A, B, C, or D using the procedure established in each section.
- b. Nonconformance is defined as any evidence of leakage or any change in electrical continuity/discontinuity during the vibration cycles, or any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

9	10			V 22-FW02-9P024-AA
REVISION	CP	REVISED		RELEASER

ML PD 2047-a2 (Rev. dated 06/06/88)

3713 1516

## **Engineering Specification**

III. ~~Test Requirements~~ (00000-0)

### **A. Thermal Strength**

#### **1. Test Requirements**

- a. Mount the switch in the test part.

(1) Apply a 54 ± 9 N axial force to each terminal.

(2) With a pendulum apply a 41 ± 3 N impact force to the switch housing or the connector end, perpendicular to the centerline axis of the switch. See Figure 1 for force application point and direction.

#### **2. Acceptance Requirements**

- a. Check the switch to sections A, B, C, and D using the procedure established in each section.
- b. Nonconformance is defined as any terminal or housing fracture, or any switch not meeting the criteria in sections A, B, C, or D.

### **B. Vacuum**

#### **1. Test Requirements**

- a. Mount the switch in the test part. Vacuum tests are to be conducted at room temperature using ambient air as the pressure medium.
- b. Subject the switch to 5 cycles of vacuum from atmospheric pressure (760 mm Hg) to an absolute pressure of 3-4 mm Hg. Minimum the vacuum for a minimum of 60 seconds.

#### **2. Acceptance Requirements**

- a. Check the switch to sections A, B, C, and D using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, and D.

10	18	REVISION	NUMBER	▽ 20-T2VC-97934-AE
FRAME	OF			

TM PD 3847-62 Revision edition now in effect

3719 1517

## Engineering Specification

### III. TEST PROCEDURE AND REQUIREMENTS (cont'd)

#### A. Temperature Cycle

##### 1. Test Requirements

- a. Mount switches in test ports; test to be run using currently released brake fluid.
- b. Repeat the following procedure 25 times.
  - (1) Lower the switch and fluid temperature to at least -40°C.
  - (2) Cycle the switches ten times at 10 seconds/cycle. One cycle consists of a pressure variation from 0 ± 276 KPa.G (0-40 psi) to 10,000 ± 345 KPa.G (1450 ± 50 PSI).  
Note: Switch must open and close each cycle.
  - (3) Raise switch and fluid temperature to 55°C minimum.
  - (4) Repeat Step 2.

c. At completion of Step b, check switches per sections A, B, C, and D.

##### 2. Acceptance Requirements

- a. Nonconformance is defined as any evidence of switch fluid leakage, seepage, or not meeting the criteria of sections A, B, C, and D.

#### B. Fluid Endurance

##### 1. Test Requirements

- a. Mount the switch in the test port and orient as installed in the vehicle.
- b. Install the currently released mating electrical connector (with wire leads) to the switch.
- c. Sequentially, immerse the switch into each of the specified fluids; at a temperature of 23 ± 2 °C, for 3 ± 1 second. Remove the switch and drain and store the switch for the specified time at room temperature, prior to immersing into the next fluid.

11	16	REMOVED	NUMBER
FRAME	OF		✓ 1A-PVOC-SP934-AA

MS PD 3947-e2, Previous version may not be used

3713 1518

## **Engineering Specification**

### **III. TEST PROCEDURE AND REQUIREMENTS (cont'd)**

<u>Fluid</u>	<u>Soak Time</u>	<u>Immersion Time</u>
Reference Fuel C ASTM D471	60 ± 3 min.	none
10W40 Engine Oil	24 ± 1 hour	14 days
Polyethylene Glycol/ Water 50/50 by Volume	24 ± 1 hour	24 ± 1 hour
Brake Fluid DOT 3	24 ± 1 hour	48 ± 1 hour
Automatic Transmission/ Power Steering Fluid (same) SAE-SAEGL-01	24 ± 1 hour	14 days
Isopropyl Alcohol/ Water 50/50 by Volume	24 ± 1 hour	none
Reference Fuel C, ASTM D471, with Methyl Alcohol 85/15 by Volume	24 ± 1 hour	none

4. Per the Flow Chart, subject the prescribed number of immersed switches to the post immersion tests specified below:

- III. E. Impulse
- III. G. Minimacy
- III. H. Salt Spray
- III. J. Terminal Strength

#### Acceptance Requirements

- a. Switches must fully meet the requirements of the specified post immersion test.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test may be destroyed after all testing is completed.

12	18			▽ ES-P2WG-1P92A-AA
FRAME	OF	REVISED		NUMBER

ES-PD 3847-62 (Revised edition only valid to 09/07/00)

3713 1519

## Engineering Specification

### IV. STATISTICAL ANALYSIS REQUIREMENTS

- A. For PW, LP-1 and LP-2 tests, all samples tested must pass. Having all the required sample size pass will provide data to support the conclusion that the switch has a minimum reliability R, at a given confidence of C. The notation  $R_{C=0.95}$  is interpreted as minimum reliability equal to R, at a confidence C; thus 99.9% means a minimum reliability of 99.9 at 99.9% confidence.
- B. All samples must pass in the statistical test acceptance criteria stated for cases with 100% frequency; or samples from lots; which could have a variable size.

### V. VALIDATION REQUIREMENTS

- C. No change in design, material, process or component supplier shall be made without prior approval from the retaining Product Engineering Office. As part of approving a change, the retaining Product Engineering office will establish the portion of the Product Validation tests required to be run to validate the switch. The following table is to be used as a guide in determining the type of tests required for validation requirements.

### PRODUCT DESIGN VALIDATION

Component	Process or Material Change or New Supplier
1. Terminal, Contacts, or Connectors	III, A, C, E, G, H,I, J, L, M
2. Case or Housing	All Tests
3. Diaphragm	III, A,D,E,F,I,K,L
4. Fitting or Fluid Connection	III, D, E, F, H, I, K
5. Annual revalidation is not required on carryover switches.	

### VI. LOT REQUIREMENTS

A lot is defined as no more than eight (8) hours of production up to 4,000 pieces. If shifts extend beyond eight (8) hours, or more than 4,000 pieces are produced in a shift, the product must be separated into at least two lots.

T3 FRAME	10 OF	SHIPPED	RECEIVED	▽ MS-EVAC-55924-A
-------------	----------	---------	----------	-------------------

MS PD 5947-02 Revision edition may apply to work

3713 1520

## Engineering Specification

### VII. TESTING REQUIREMENTS

- A. Recording and traceable rechecks shall conform with Ford Q-101.
- B. Production Validation test results and analysis are to be forwarded to the releasing Product Engineering Office before approval for shipment of production parts can be granted.
- C. In-Process test results shall be available at the supplier's manufacturing facility for the releasing Product Engineering Office and Ford SQD or its representatives to review on request.

### VIII. MANUFACTURING REQUIREMENTS

All switches are to be identified with the Ford part number, supplier identification, and a date code indicating final assembly.

All test equipment and test procedures for testing to this specification must be approved by the releasing Product Engineering Office and no change in equipment or procedure may be made without their written consent.

Test port configuration is shown in Figure 5.

O-rings, if used in the design, shall be free from cuts, nicks, abrasions or any other damage which would result in a fluid leak.

All switches must have a shipping cap installed over the port threads to prevent contamination. All shipping caps must be approved by the releasing Product Engineering Office prior to production incorporation.

All switches that do not pass the validation test are to either be readjusted and rechecked, or scrapped. (Salvage of component parts permitted with 100% reinspection).

If product nonconformance occurs for test Sections III, A, C, D, E, F, and J, production shall be stopped and the problems corrected. All production lots shall be sorted 100% prior to shipment. Suspected nonconformance of any shipped parts shall be reported immediately to the releasing Product Engineering Office.

If nonconformance of the statistical acceptance criteria occurs for test Sections III, G, H, I, K, L and M, a cause to recall the subject units production and to stop production may result.

14	18	STANDARD		NUMBER V MS-FWU-99924-A
NAME	OF	STANDARD		

MS-PD 3847-02 Revision A, dated 04/07/97

3713 1521

## Engineering Specification

### IX. APPLICABILITY OF SPECIFICATION DOCUMENTS


ASME B-117, Salt Spray Testing  
FED Q-101, Quality System Standard - 1990 Revision

BS-7000-5A4464-AA, Specification - GJB Army - Wire Connectors  
BS-7277-9C735-AA, Specification - Servo Assembly Speed Control

15	18	REVISED	RELEASER	▼ BS-7277C-9C735-AA
----	----	---------	----------	---------------------



AMM PD 3047-02 Previous edition may still be used

3713 1522



VIBRATION TEST - SWITCH ORIENTATION

FIGURE 1.



TERMINAL STRENGTH - LOAD ORIENTATION

FIGURE 2


NAME: [REDACTED] DATE: [REDACTED] APPROVED: [REDACTED]

16	16			$\nabla$ 20-0070-00004-00
FRAME	OF	REVISED		NUMBER

AM PD 5947-02 (Previous edition may still be used)

3713 1523

Engineering Specification



Reference  
SAB J512 OCT 80  
Figure 5A

TEST FIXTURE PORT CONFIGURATION


FIGURE 3

17	18	REVISED	V 38-220-97201-4A
17	18	REVISED	V 38-220-97201-4A

WIPD 3847-62

3713 1524

Engineering Specification



DEACTIVATE SWITCH  
TEST SET UP

FIGURE 4

18	18			$\nabla$ 2B-220-2030-A
REVISED	OF	REVISION		NUMBER

NET PD 3947-62, PAGES 100-101 OF 100-101

3713 1525

Brake Pressure Switch  
Review

12/22/98

NAME	ORGANIZATION	PHONE
FRED PORTER	FORD AVT EEE	(313) 84-53722
JOLA LOTT	AVT MGR'S ENGINEERING	(313) 24-88641
ZANDRA DEERING	LIC - SAFETY EEE	(313) 97-41663
Jim Gregoire	AVT EEE OPD	(313) 33-79962
Steve LeRouvre	Ford Control Lines	313 8454876
Norman Lapointe	AVT - Des. Div.	313 59/42686
Robert Sharpe	Field Sales - TI	(218) 305-5729
Bryan Dague	Design Eng. Sup	(508) 236-3234

9713 1526

12/10/98

Switch current?

- speed control deactivation switch

Brake fluid ignition?

Service Parts Involved?

Was cruise control standard in Town Car


Reports are ambiguous

Is speed control standard  
option on CVGM

Contact for future NHTSA Meetings

Cars on road

WARM STATES





- Communications
- Journal Entry
- Thoughts & Ideas
- Agendas
- Conversations

December 1998  
Daily Record of Events

92 Town Car MTG - Mike Dennis invited

Jim Ferguson & TOM MASTERS

Joe Auger

Rick Rodger

Fred Porter

3 P.M.

→ Prepared an early program in 6.7.98

Create learning justify called Speed control deactivation switch  
located in P.D.A. the prop valve  
Bubbles = Surfaces

QUESTIONS

- Is brake fluid magnetite brake pressure build up
- will brake fluid equalize when hot at all times speed control deactivation
- Is a speed control ETD on Town car
- How similar is Town car to GM per GM, packaging, etc.
- Are Town car V8's with safety wires had previous service repair.
- New single point control for classic brake master.
- Why is the just 93 MPH

IS SPEED CONTROL SWITCH HOT ON ALL VEHICLES



• Communications  
• Journal Entry  
• Thoughts & Ideas  
• Agenda  
• Conversations

A good conscience is a constant feast.  
—Robert Burton

December 1986  
Daily Record of Events

10

Thursday  
34th Day 31 left  
Week 48

92 Town Car Mtg - Brake issues raised  
John DiPietro of TOM MASTERS  
Jeff Pugay  
Mike Fedore  
Fred Porter  
JESFN

→ Received an brake problem in 87 GM  
Brake lining bushed called speed control deactivation switch  
coach in P.E.R. the prop dealid  
Supplier = Brembo

QUESTIONS

- Is brake fluid magnetic
- will brake fluid liquify under heat at all times and under what conditions
- Is speed control STD on Town Car
- How similar is Town Car + GM per GM, packaging, etc.
- Does Town Car V-6 with safety issue had previous repair/repair
- Had single point contact for claims brake related
- Why in this just 92 mth

IS SPEED CONTROL SWITCH HOT ON ALL VEHICLES

12/10/98

Switch current?

- Speed control deactivation switch

Brake fluid ignition?

Are Service Parts Involved?

Was cruise control standard in Town Cars


Reports are ambiguous

Is speed control standard  
optional on CVGM

Contact for future NHTSA Meetings

Cars on road

warm engines



\*\*\*\*\*  
\* Note printed by FPORTER on 17 Dec 1998 at 08:48:16 \*  
\*\*\*\*\*

FROM: FPORTER --DRBN007  
To: LBROWN --DRBN005

Date and time 12/17/98 08:46:37

FROM: F. J. Porter  
Subject: (U)

USAEST (UTC -05:00)

FYI.

Regards,

Fred Porter CV - fporter fporter@ford.com  
Chassis E/E Systems Applications (313) 845-3722  
Bldg 5 - Mail Drop 8030 - Cubicle 3B004 fax: 390-4145  
\*\*\* Forwarding note from FPORTER --DRBN007 12/17/98 00:48 \*\*\*  
To: WABRAMCE --DRBN005 RCLAYTON --DRBN005  
BEGEN --DRBN007 RENGILISI --DRBN005  
JEVANS8 --DRBN005 JGREGOIR --DRBN005  
KGRIEBEL --DRBN005 MLAPPOINT --DRBN005  
JMCINERN --DRBN005 JNEME --DRBN005  
RNEVI --DRBN005 GSTAVEN1 --DRBN005  
CTHOMASS5 --DRBN005 DGCEL --DRBN005  
HWELFER3 --DRBN006

FROM: F. J. Porter  
Subject: (U)

USAEST (UTC -05:00)

#### 1992-1993 Town Car P2VC-9F924-A Brake Pressure Switch Investigation

TEAM:

AVT BESE Chassis Electronics:	Fred Porter	x84-53722	fporter
AVT Chassis Engineering:	Joe Evans	x32-23832	jevans8
AVT BESE EDS:	Barry Egan	x32-39512	began
AVT Design Analysis:	Rob English	x33-73225	rengilis
AVT BESE OPE:	Norm LePointe	x59-42686	mlapoint
EASE Prod. Veh. Safety:	Jim Gregoire	x33-79952	jgregoir
Large Luxury VC:	William Abramczyk	x32-23284	wabramca
Large Luxury VC Safety:	Ray Navi	x59-47688	rnavi
AVT Materials Engineering:	Joe Neme	x39-08133	jneme
	Ron Clayton	x32-24025	rclayton
	John McInerney	x32-20276	jmcinern
	Ken Gribble	x32-38658	kgribble
	Clark Thomas	x59-41313	cthomas5
	Greg Stevens	x32-36686	gstaven1

INFORMATION:

NHTSA letter: PH98-055

Vehicles identified: 21 initially identified.  
20 additional vehicles reported since publication of the investigation.

Warranty: A total of 89 warranty claims are identified in ANS on the P2VY-9F924-A for 1992 and 1993 Town Cars.

Two CQIS reports [REDACTED] mention underhood fire

3713 1531

in connection with the brake pressure switch.  
WJIAA135 occurred at 51,360 miles.  
VXHAA322 occurred at 56,802 miles.

Supplier: The pressure switch was manufactured by Texas Instruments. The switch was purchased in assembly with the brake proportioning valve bought from Surfaces.

Contacts: Surfaces - Mike Thomas (248)543-6520 [HILITE Industries]  
TI - Andy McGuirk (508)236-3080.

Function: The brake pressure switch is a redundant switch for turning off the speed control function.

ON-GOING ACTIVITY:

Norm LaPointe and Clark Thomas will meet with engineers from Central Laboratory to x-ray one part on 12/17/1998.

QUESTIONS: (in no particular order)

- 1) What is the normal current in the brake pressure switch?
- 2) Was cruise control standard on Town Car in 1992 and 1993?
- 3) Under what circumstances is brake fluid flammable?
- 4) What is the repair history for vehicles that have exhibited a problem? ~~?~~
- 5) What other vehicles use this brake pressure switch? What are their electrical configurations?
- 6) Is this switch still in use? If not, why not? If so, what design changes have been implemented since 1992/1993?
- 7) What fault codes are stored if the brake pressure switch fails?

Regards,  
Fred Porter OV - fporter fportar@ford.com  
Chassis E/E Systems Applications (313)843-3722  
Bldg 5 - Mail Drop 5030 - Cubicle 3E004 fax: 390-4145

TODAY





3713 1636