

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 16 OF 61

PART 4 OF 4

CAN A REPLACEMENT CONNECTOR
BE CAUSING EXCESS LEAKAGE?

~~THE~~
- take Warranty Data for ?
ASIC Bill

Junkyard connector evaluation

E-MAIL WARRANTY DATA TO ANDY.

BP Switch Mtg Notes

3/17/99

Mc Connector changes since MY 92/93 (Service Parts).

- In-line relay

- IDEA (ERCO KOTL)

Use BP Switch as relay control that provides power ~~to~~ to Speed Control clutch.

IDEA Stone

- ABS Pedal Travel Switch signal to activate a disconnect device.

Don't understand

- Why aren't we seeing fires in Michigan (Bill)?
Opinion - It's not road salt & we don't have heat & humidity like SOUTH COAST

A - Old Brake Fluid analysis by TI

What does Ford want?

Conductivity, Content metals (iron)

TI test steps

- Use with ¹² Brake Fluid test
Add perforated diaphragm and pulsing pressurized brake fluid.
HEAT THE ... TO ACCELERATE CORROSION.

? Is wire seal, brake fluid compatible? Greg?

? Does ~~an~~ arc drive chemical reactions in brake fluid? (DOW & FRL)

* How does Weibull compare Quiet v Snap Disc?

- Kick-off in-line fuse action. (Bill?)

BP Team Meeting
SWITCH

2/2
3/17/99

Steve Reimers	03286	JREIMERS	RV7/EESE
John Shore	69789	JShore	PS&L / FCSD
Al Loeck	08877	ALLOES	FCSD/Recall
FRED FORTER	53122	FPORTER	RV7/EESE
WILLIAM M. ABRAMCZYK	23204	WILLIAMCZ	ASO
GREG STEWENS	36686	GSTEWENS	EVT MNT 2
TOM BABIL	47587	TBABIL	LVC OPD BRAKES
JOE EVANS	23832	JEVANS8	R-VT-CHASSIS
FRED KOHL	21801	FKOHL	VISTCON SPD CONTROL
ANDY M. QUIRK	508 236 3080	A-MQUIRK @ FI.COM	TEST LAB

BP Team Mtg

'C

-- HARDY, Mike QUALITY OFFICE 3/19/99

HELP FACILITATE IS/IS NOT
SEARCH FOR ROOT CAUSE.

- John McInerney any more parts from field

- TI

- Brake Switch Relocation

- Brake Fluid w/o inhibitor

3/10/99 43

- ~~Brake Pressure Switch with Harness~~ ^{from Prop. Valve}
- ~~Speed control Servo with Harness~~
- ~~STOP LAMP Fuse~~

A - Contact FCSD to gear-up Field Service reps to the OASIS (Zone Managers)

(Dealerships may not pull-up OASIS for out-of-warranty cars.)

A - Go to Shilling

? - Brake Fluid compatible with the plastics, etc in connector and wire. Greg Stevens

A - Copy of questionnaire

? - Erosion lock-up of Transfer

PIN IS RELIABILITY ISSUE FOR

No. ∇ component (Abrasive) is for brake fluid pressure seal (opinion).

3713 1782

BP SWITCH TRAV Mtg

3/10/99 3/3

Steve Reiners

RVT EEEZ

03276 SREINER

FRED PORTER
 JOE NEME
 STEVE LAROUX
 TOM BABIL
 BARRY EGAN
 JOE EVANS
 Mike Hardie
 WILLIAM M. ABRAMCZYK
 Rob Shappe
 Jerry Andritsis
 JOE KAFATI
 ANDY M'Guire

RVT EEEZ
 LVC Safety
 Cen. Labs
 LVC-OPD BRAKES
 RVT-CHASSIS
 RVT-CORE BRAKES
 Quality Center
 ASD
 Texas Instruments
 RVT-Application Engineer
 AVT-EEEZ
 TEXAS INSTRUMENTS

83722 FPORTER
 08133 JNEME
 54876 SLAROUX
 47547 TBABIL
 39812 BEGAN
 23832 JEVANS
 57279 M HARDIE
 27284 WABRAMCZ
 (214) 205-5729 rshappe@ti.com
 248-9524 JANDRITS
 (313) 390-5379 JKAFATI
 508 236 3080 amguire@ti.com

NHTSA Session - 2 months to make decision. 2/19/99

Randy McClure Litigation contact

Brake issues rising LB

A When did SNAP to Quiet Change
accut?

2/23/99 Fiber optic measure for are
* Loose metal in Switch Cavity
Accelerated corrosion of APG
MATE

Inconeri Performance test group.
Road Load group

Vehicle Purchase Bill Pfeiffer?

* Monitor Brake Pressure Switch
actuations during vehicle testing.
Power Steering Switch Usage
92/93 had ABS ~~excessive~~ action.

OWNER MANUALS Bill Abranczyk

DOE VARIABLE Pube Pressure 180
1450

* What Brake Pressure to Turn-on Brake Lamp
for car with dot combination

2/19/77

ID COMBUSTIBLES

- Brake Fluid

DOW reviewing mat'l list
Meet next Tuesday morning

ID Contaminants
~~Source~~

- Copper, Zinc, Sulfur, Silver,
Brake Fluid.

ID Source

- Electrical Terminals +
Sulfur TBD

ID CAUSE OF LEAK

- TI Life Testing
Kepton Diaphragm

ID Heat Source

- not yet
DOW help

Create Event

- 55 AMP HEATING

Collect Parts

- 13 more from Junkyard
(= five)

Structured Evaluation Process

TI Test Station on-site

OASIS Message by CAB.

LOOSE TERMINAL

- 1 return unit
Potential Short Circuit
~~15 AMP not~~

2/19/99

- Speed Controls functional
flyback circuit analysis by Tuesday

~~OASIS Message out by Monday~~

- Test Vehicle Procurement
" Vehicle type IDENTIFIED

- Tests In-Progress
• FATIGUE WEAR-OUT 900K 727K link
• Leakage current growth 3-5 mA
• FATIGUE AGING :
• FIELD RETURN ANALYSIS ON-GOING
JUNYAC SPEED CONTROLS - OK

- DCE @ TI . START MONDAY AFTER FATIGUE TEST
BRAKE FLUID
" " " WATER completion 3/3/99
QUIET DISC
SNAP DISC
CLUTCH LOAD

- CGIS Variations BRAKE = 47
NOT UH 5
UH 17 - 5 Brake Psw
U car 12
UNKNOWN 13

GIVE

TI Telcar

2/19/98

fatigue

93 CONNECTOR UF

#7

728 K →

~~30~~ ONE

Complete
Monday

30 parts total

SNAP every 200K ES ~~30~~ Life Condition

Preparing IOE Brake fluid

LIFE TEST

4 SIZES OR 10

Brake fluid & water

IOE

FLAC-9F929-AA

Quiet Disc N MY
+ CONNECTOR

F2VC-9F

SNAP Disc

10 DAYS from Monday

+ CLUTCH LOAD

Will all on Quiet Disc typ 750K

Function of test

Stress Strain

Pressures

Vacuum

Temp

ENVIRONMENT

WATER

CONNECTOR
6-8K
BRAKE
FLUID
CORR

~~Per~~
~~Greg~~ Greg Stevens

Mike Kit DSW (LOUISIANA)

2/18/99

Water in Brake Fluid

- ~~an effect on~~ conductivity?

- no effect on Flash point

-oo about Salt Water?

FAX 78256

181 TC BASE EXEC

ILNL

M82 TC Sign

M83 TC Capt

M84 TC LTS

ORIGINAL
MASTER CYCLING

after Nov '91

06-09-1 BRAKES

WITH T/C

Performance Test group

2/18/99

Dow ~~Engineer~~ Chem rep is looking
at our ~~the~~ materials list and
questions. ~~then~~ He will be
here by Wed next week.

Brake fluid 312°F flash med spark
600°F auto ignite.

Celorex housing

- Has identified contaminants - need to understand source of sulfur - Do
- Cause

Team Mtg
ATTENDEES

Brake Pressure Switch Mtg 2/17/99

Steve Reimers	ESE/Chassis	SREIMERS
ROB ENGLISH	ESE-205 7325	RENGLIS
WILLIAM ADAMCZEK	ASO 23207	WADAMCZ
Rob Sharpe	TI (410) 305-5729	rsharpe@ti.com
Steve LaRoche	CS 59076	JLAROCHE
LEN BROWN	AVI Chassis 23252	L BROWN
GREG STEVENS	AUT MTL 36676	GSTEVENS
MARTY M. P. REESE	OPD LIKE 77142	MREESE
AZIZ Rahman	TI 248 305-5729	
FRED KOHL	VISION 21801	FKOHL
Joe Neme		

DOW no-response

2/17/99

Brass & Copper Electrode

- ~~Re~~ Give 200 hour unit to Labouch for Analysis
- Flush 212°C Auto Ignition 600°C
- Do these
- VP DOW to Len
- IGNITION Transition Transients
- What is the lowest mileage reported?
TOM MASTERS
- June 95 earliest reports
- 92 vehicle ^{took car after Nov '91} 25317 ^{NO-WIRING MAPS AFTER ABS/TC} Dennis Clark
- ~~Process~~ Process for Speed Control examination.
- Pressure Profile @ HCU Teves.
- J.G. Joyce Chuck Bannon for ABS Data
- Tom & Joe come to meeting
- ~~Tom~~ Chris to ABRAMCZYK

9713 1791

- 2/17/99
- DEALER CANVAS IN SOUTHERN AREA
BILL REQUESTED OF TOM MASTERS.
 - SOUTHERN AREA MAY JUST BE WORST
WEAROUT ENVIRONMENT. OTHERS TO
FOLLOW.
 - BRAKE FLUID samples
 - T.C. 92 93 ABS/TC PARTY
PRIMO from Phoenix Las Vegas
Signature LM

FRISKUS Tech Review

2/11/99

OPTIONS
HOT ENGINE'S

- MATRIX OF WHAT IT IS / IS NOT
- Is Brake Shift Interlock ~~signal part of~~ using BOO signal. CAN'T SHIFT OUT OF PARK.
- Geo of Service Replace Parts Sales.
- Success of Kepton in this application
- Cycle test in Humidity
- ^{92%} Town Car 100% ABS (option TA)
(CV GM ^{option} ABS/TC together only)
- IS ^{stick} Test False? Fluid pure or water contaminated?
- Measure ^{injection} current flow.
- ^{broken switch} ^{faulty parking}
- ^{EXTENSION}
- 2 months to act
- ^{include} ^{for melted, smoked}

Brake Pressure Switch Meeting 1/3

3/3/99

	EMAIL		
Steve Rainers	SRAINERS	X03286	AVT/EESE
Fred Porter	FPORTER	X55722	AVT/EESE
M. P. Reese	MREESE	X77172	OPD LVC
Rob Sharpe	rsharpe@ti.com	(218) 385-8729	Time Instruments
GREG STEVENS	GSTEVEN2	X 36686	AVT MAT'L
NORM LAPINTE	NLAPINT	X42686	AVT/DES. ANAL
Steve LaRouche	SLAROUCH	54876	CENTRAL LABS
Andy McGwire	A-MCGWIRE@TI.COM	506 2303000	TI QRA

WILLIAM M. ABRAMCZYK WABRAMCE 313 32 25284 ASO

* Steve Beringhouse / Bryan Dague from TI on conference call speaker phone.

3/3/99

Test with Oxalic acid. - TI

Oxalic sources

DOE with Old Brake Fluid

Conclusion? - o Corrosion from Water intrusion creates an event

o Brake Fluid leakage creates a cell that causes corrosion.

o Somehow corrosion will occur.

IS THERE A NON-CONDUCTIVE HYDRAULIC CONNECTION TO PUT BETWEEN BP SWITCH & PROP-VALVE.

? ELS n Improved connector seal available.

- Constant Feed of Brake fluid to switch under test,

AA Slo-Blo good enough to limit power?

- Marker that survives a fire

- Different concentrations of ions. 3/3/99
- Test with clutch load limiting current thru contacts.
- Test with clutch load & Hex Port isolated from ground.

O.S. Other solns - plugging the switch cavity with silicon Grease (a temporary seal only?)

- TI - Test with old brake fluid that is corrosive to metal.
- Fuse / current limit to establish

1 e: 2-5 amps, peaks to 10 AMP (TE SALT WATER TEST)

O.S. - Consider the effect of the fuse blowing just because of water - results in customer complaint

- O.S. - ADD A BOOT OVER CONNECTOR TO KEEP WATER OUT OF SWITCH CAVITY.
- ADD Grease to connector to seal.

Torque Pressure Switch Mtg =/29/98

Steve Reimers	SREIMERS	X03286	AVT/EESE
Shawn McCarthy	SMCCARTY	X 21355	FRL
Boe Carter	RCARTER	X31733	FRL
Dave Bauer	DBAUERS	X 41756	FRL
Tom Sweeney	TSCHADY	X 27595	Visual Spec. for
Greg Stevens	GSTEVENI	X 36686	AVT MAT L
Norm LaPointe	NLAPINT	X42686	AVT-DES. Area
Steve LaRouch	SLAROUCH	54876	CENTRAL LAB
Pete Klaas	P KLAAS	21613	CENTRAL LAB
Mike Kitt (DOW)	MK.TT@DOW.COM	225 553-6945	FF REV M. 16
Ken Gribble	KGribble	38658	REV M. 16
AZ = [unclear]	AZERT J. C. M		T =
Rob English	RENGLISH	73225	AVT-EESE
[unclear] [unclear]	[unclear]	X 23284	ASU
[unclear] [unclear]			
Scott Urbina	SURBINA@DOW.COM	248- 357-8857	Dow Automotive
Red Porter	PORTER	(33)84-53722	AVT-EESE

FSW Mtg Notes

2/24/99

Was a brake fluid residue?

EC leakage 5 mA

Did brake fluid cause ignition

or ... from outside?

... reverse current path

... mfr process (sintering vs ?)

... base metal ...

... Disc ...

CAE ... Improved corrosion inhibitor in Brake Fluid (Curex & Dolphi)

... corrosion with ...

92-94 ... in SW ...

2/24/77

MA-9 HORRIS & ALLBERG

↳ samples off Memphis Switch

Are these slow-blow fuses? NO ATO

Does trailer pkg increase fuses??

Mixture in switch as built?

Even Fluid - no S-or S Poly S/est

Is not from Brake Fluid" Dist.

Heat curing process uses sulfur.

Switch to Carter what

happens - insulation resistance

2/24/99
3/3

Look into fire retardant case
mtl?

New Tests

Introduce Chlorine as corrosive
or late as corrosive

Continue 300 hour Test

~~Some new tests~~
more tests to see
if it works

1992/3 Towncar Underhood Fire NHTSA Inquiry — Draft 2/10/99

Background

- On 11/24/98 NHTSA submitted inquiry PE98-055 alleging 21 reports of underhood fires in 1992/3 Towncars
- On 1/11/99 NHTSA submitted a supplemental inquiry requesting information on all Ford vehicles using
 - F2VC-9F924 brake pressure switches
 - 12A581 wire harness assemblies with a PIA relay center
 - EDIS 8 modules
- Present searches have identified the following:
 - 149 underhood fires or overheating events on 1992 and 1993 Towncars
 - 36 with engine off/vehicle parked, 9 with engine on, and 104 unidentified
 - 5 appear to be related to the brake pressure switch
 - 17 appear to be related to other components

Status

- ASD is collecting requested data to respond to NHTSA
- Task force established to investigate brake pressure switch... meeting weekly
- EESE person identified to lead the engineering investigation

Next Steps

- Identify potential affected vehicles/trends
 - identify Crown Victoria/Grand Marquis vehicles incidents since similar electrical configuration and vehicle package
 - identify potential trends by comparing incidents to vehicle options
- Identify potential root cause(s)
 - establish links to CAC/OGC/FCSD/NHTSA to quickly identify incidents and establish team to quickly investigate
 - perform tasks on brake pressure switch task force work plan
 - investigate other components as appropriate
- Identify potential interim containment actions for vehicles in the field

Work Plan- Brake Pressure Switch

Root Cause Investigation-

Identify flammability characteristics of switch components

- AVT EESE Materials Engineering

by Thurs

Identify switch contaminants in parts returned from the field

- Central Lab analysis

by Thurs

Identify potential source of contaminants

- Central Lab analysis

by Thurs

Identify potential for and possible sources of internal brake switch leaks

- Central Lab and Texas Instrument

2 wks

Identify potential ignition sources during switch operation/malfunction

- AVT EESE Chassis Electronics

Thurs

Simulate potential switch malfunctions in a laboratory environment to evaluate the potential for ignition

- AVT EESE Chassis Electronics

BU Gaudin

Collect additional field samples (including connectors) for laboratory analysis

- LVC Safety

BU Gaudin

2/5

Recreate event
analysis notes
understand usage

9F924

of course

- 2nd meter from

- 2nd shut-off of clutch

of the 3rd stage

of the 3rd stage

of the 3rd stage

just

Brake Switch Questions 2/4/99

- ✓ Competitive vehicle - How packaged?
- Are they always on?
- ✓ WHAT ARE THE DESCRIPTION FROM AWS?
CRIS?
- ✓ IS THE BASE MATERIAL COMPATIBLE WITH BRAKE FLUID?
- ✓ FRACAS - DAN BURTON - TO GET PARTS MADE
- ✓ T.I. in-process quality indicators
- ✓ DFMEA FROM T.I.
- ✓ ANALYSIS FROM CONTROL LOG
- ✓ WHO SHOULD ANALYZE PIG TAILS - MARK LABRINE 2/12
- ✓ IF SWITCH HAS CONTAMINATION - CAN IT START EVENT?
- ✓ FLASH POINTS FOR ALL MATERIAL
- ✓ WHAT HEAT IS CONDUCTED INTERNALLY
- ✓ COLOR PHOTOS FOR FLOWLINE
- ✓ DIFFERENCES W/ BASE MATERIALS
- ✓ IP TEST FAILURES
- ✓ MEMPHIS REVIEW QUESTIONS
CREAK MARKS
- ✓ MATERIAL CALL OUT FROM 92.93
- ✓ TESTING W/ CORROSION SIMULATION
- ✓ BOLA - DOES IT TAKE TO START A FIRE

3713 1805

Bck P SW 2/9/99
TI - AZIZ RAHMAN, Rob Sharpe

96 Service Manual shows change
From Prop Valve to Booster mount (96)
Master Cylinder?

- See? TI at Tech Review?

- TOM BAZIL
WILL SENSORS
SEE ABS/TA
MODULATION?
AT BOOSTER
AT PROP VALVE

? Pending Failure for
Leak - loss of Brake
Fluid.

? FAILURES OF FETS

? FAILURES OF BOO INA

? What's current to
cause event?

? Why fluid in switch

? Is fluid causing
event

? What contaminants
increase conductivity
of brake fluid.

Fed Kohl

- What about
100 Relay inline
between Fuset BPSW?
- What is the timing
between FET OFF &
BPSW open?

How will you know
if FET has failed
shorted?

INDICATORS OF LIFE

Contact actuations
Arms " "
DIAPHRAGM "

MINI-DIVE
APPLICATION Very old

Phone & ID for Aziz

.....
* Note printed by REIMERS on 11 Feb 1999 at 07:58:08 *
.....

From: TRAIL --DREW005 Date and time 02/10/99 13:58:51
To: REIMERS--DREW007
cc: TRAIL --DREW005

FROM: Tom Basil USANT(UTC -05:00)
Subject: Brake Pressure Switch Question
DRAFT

~~.....~~
~~.....~~ X STANDARD 2/22/99
~~.....~~

Have a good day!

Thomas E. Basil (311) 89-47547 Log & Lax Car OVD Brake/Veh Supv
Drop 1229-LVC, Cube 24-R36, fax 62-16678, pager (888) 378-6449
*** Forwarding note from REIMERS--DREW007 02/09/99 18:13 ***
To: TRAIL --DREW005

FROM: Steve Reimers USANT(UTC -05:00)
Subject: Brake Pressure Switch Question
Does AMB pressure module have a pressure switch?
Was AMB standard on the vehicle?
Were there any other options available on the vehicle?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 8011
19-03286 REIMERS sreimers@ford.com fax 19-03286 12

* Note printed by SREIMERS on 11 Feb 1999 at 07:57:43 *

From: FPORTER --DREH007
To: SREIMERS--DREH007

Date and time 02/09/99 18:27:09

FROM: F. J. Porter
Subject: CONNECTOR F2AB 14A464 ADA

USANT(UTC -05:00)

Regards,
Fred Porter CV - Sporter fporter@ford.com
Chassis E/N Systems Applications (313)845-3792
Bldg 2 - Mail Drop 5030 - Cubicle 3E004 Fax: 390-6145
*** Forwarding note from ELAPOINT--DREH005 02/09/99 14:11 ***
To: JENNE --DREH005 JENKINS--DREH005
PAYNE--DREH007 BLUM --DREH004
FPORTER --DREH007 WILSON--DREH004
TRAYNER--DREH005 KENGLIS--DREH005
cc: JAVAPI --DREH004 ELAPOINT--FORN001
CYRUS--DREH005 ELAPOINT--DREH005
CULLOCH--DREH005

FROM: Norman LaPointe
Subject: CONNECTOR F2AB 14A464 ADA

USANT(UTC -05:00)

Meeting 2-12-1999 w/UTA, 1:00PM at Central Laboratories, Small Conf. Rm.
Agenda:

1. Obtain drawings for F2AB-14A464-ADA connector & components from UTA.
2. Obtain components for above connector (5 sets).
3. Obtain and discuss FMEA.
4. Discuss sealing details & history of above connector.
5. Obtain the visual characteristics of: water, brake fluid, or other materials that could enter the connector or the wires.
6. Discuss assembly difficulties to seal joint.
7. Hand off 6 press. switch assemblies to UTA.
8. Develop game plan to disassemble and examine the submitted connector from Reddick veh.

FAX copy of above sent to Dan Kulkarni-UTA, Dick Radkey-UTA.

Regards,
Norman LaPointe
PHONE 59-42686 FAX 313-237-8256

2/10/99

ONLY FZVC IS ~~AT 1200~~ FOR

149 92, 93' Fire (Thermal Event/
Smoke/Overheated)

36 OFF
9 RUNNING } engine state
104 UNKNOWN }

5 TO IGM Brake Sw

17 OTHER COMPONENTS

— NAMES OFF WORK PLAN

— DAMAGE LIMITED TO SWITCH ?

— OASIS MSG ~ FOR REPLACED Brake P Sw

— WARRANTY Return Parts have been requested

— A → F ANALYSIS

— Thermal Environment

— Orientation

— Pressure Environment

8D ON Console

— Reaction to field occurrence

Wed 2PM
Weekly

2/10/98

NAME PROFS ORG.

Steve Reiners	SREINER?	AVT/EESF
✓ Tom Barr	TBARR	LVC-OPD BRASS
✓ John McInerney	JMCINERN	LVC-SAFETY
Joseph Neme	JNEME	LVC-SAFETY
Rob English	RENGLSI	AVT-EESF-EDS
Norm Lapointe	NLAPINT	DES. ANAL. AVT
Steve LaRoché	SLAROCR	CENTRAL LAB
Dan Buzynski cc	D BUZYNSI	AVT/OPS
Paul Stokes cc	PSTOKES	AVT/OPS
Stuart SALTER	SSALTER	EESF COMPETITIVE AN
Fred Porter	FPORTER	AVT. CHANGING EQUIPMENTS

✓ Tom Schrody T SCHRWDY

✓ Fred Kohl FKOLL 21801

* Note printed by SREINERS on 10 Feb 1999 at 08:51:03 *

From: I2000625--RETURNAL Date and time 02/09/99 19:04:41
To: FORTNER --FORDMAIL 'Fred Forter (For SREINERS--FORDMAIL 'Steve Reimers (F

From: Rahman, Aziz
Subject: Actions from 2/9/99 CEL Visit

To: "Steve LaRouche (Ford)" <slarouch@ford.com>

1. Provide Steve L with 2 switches from 92/93 Town Cars with varying mileage for Kapton wear study - Aziz
2. Complete subjective "Brittleness" evaluation for above two parts + Memphis part + parts D & F - Steve L
3. Complete Kapton Topography study with Calyex on all parts above except Memphis part. - Steve L
4. Obtain update on 2 resistivity tests in progress at TI - Aziz
5. Document data to date from Allan Janotik test - Aziz
6. Follow up with Dupont on change in Kapton properties with time/temp in aged Brake Fluid - Aziz
7. Assess revising present Allan J. test to expose switch to high temp. - Aziz

Regards
Aziz

TI testing activity

2/10/99

Ground side switch does not
eliminate the possibility of an
arc induce event.

Brk P.S. J

2/5/99

CV, GM warranty claims 92, 93

↓

50K → 90K → ~~124581~~ RELAY PACK

EDAS BRKFSM
2/4/99

14 D Tech Review

2 → 2.5 M parts per year

pkg orientation? Wiring Differences?

92/93 TC is first application.

? Can the switch act as a fuse?

2/12 - UTA mtg Norm Lapointe

- TI FMEA

- ARE ALL APPLICATIONS HOT IN RUN?

- PART DATE CODES

- Sean McCarthy (Ignition switch)
Investigation experience

- Component $\frac{1}{2}$ is used by competition? How wired?

- DOES TI have any SQA issues?

- How MANY ^{vehicles} USE THE SWITCH?

Tom Dorado
Joe McARNEY

* Note printed by SENDERS on 4 Feb 1999 at 13:21:55 *

From: SENDERS--DSEN007 Date and time 02/04/99 11:28:14
To: ✓ PORTER --DSEN007 Frederick J. Porta DCSL --DSEN005
LAWSON --DSEN005
✓ JENSEN --DSEN005 TO ✓ CRIVELLO --DSEN005
✓ STOKES --VISTECH ✓ BOUDREAU --VLETRON
✓ REAGLE1 --DSEN005 ✓ BLANCHARD --FORDNAI
✓ KLAPPOINT --DSEN005 ✓ SALTER --DSEN005 -LATER
✓ SENDERS --DSEN007 Steve Reimers ✓ WALTERS --DSEN005
JIAFATI --DSEN004 ✓ SCOLEL --DSEN005
✓ ROD SHARPE T.I

cyk

FROM: Steve Reimers USABT (OTC -08:00)
Requester: Steve Reimers
Date to be scheduled: 02/04/99
Starting time: 2:00PM USABT
Ending time: 3:00PM USABT
Location: building 5 conf rm 1A039
Subject: Brake Pressure Switch
Purpose: Kick-off meeting for Investigation of Brake Pressure switch
in response to NHTSA investigation.
1. Develop work plan
2. Identify addition team players — — VO
3. Establish meeting schedule and location.

Steve Reimers building 5 1C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SENDERS sreimers@ford.com Exx 39-03286 12

Introductions
Description '92-'93 TC UNDERHOOD
Problem Statement (TC Focus?)
Work Plan -
Containment Short Term
Long Term
Root Cause
Recreate Fault
FAILURE ANALYSIS

BRAKE PRESS - SW. INVESTIGATION

2/4/99

✓ DR. BUDENSKI
✓ PAUL JEROME

CRAIG STEVENS - MATERIALS

Speed control
Safety off
✓ JOE NEMIE ✓

SALT IN SOLUTION?

✓ Central Lab - STEEL LAB

SECTIONED SWITCH

✓ TI - ROB SHAW - 810 905-5737
✓ ROB ELLISON - CCRG
✓ SU SAITOH - BOWEN MCKENNA
✓ NORM LARSON - DESIGN ANALYSIS
✓ TOM MASTERS
✓ JOE KAPPEL

BRAKE FLUID IN WIRE?

✓ ~~FRID~~ FRID

Sparks from MC of switch

NHTSA INVESTIGATION

CC ✓ D GOEL
✓ H WELFER 3
✓ I BROWN
✓ SCOEL

CCRG
R
O
I
C
S

Immediate Actions

Work files

✓ C STEVEN 7

EWING

- FMEA for shorted switch.
- FMEA for failed BOO function
- What does competition do? SALTER
- Why a P switch? VISTEON
- Immediate action (Containment)
 - Disconnect Switch (Remove & Replace?)
 - Re-wire to low-side
 - ~~short~~ Jumper out switch

- 14 D

- OTHER TEAM MEM
VO - TOWNCE

- Competitive Analysis
of Redundant SW.
DOES COMPET USE IT?
- Is it a Redundant SW?
- FMVSS REQUIRE NOT ALL TIME CRT?
- Cut away of switch
-

TOM ARSTLER

STEP 2: Select Your Activity or CPSC and Input Time Allocated %

Employee: [Name], Job Group: [Code]
 Job Family: [Code]
 FMS Job Description: [Code]
 Self Rating: [Code] Job Title: [Code] Date: [Date]

Click on a radio button to view its description.

Activity	Yes	No	Time Allocated %
[Activity]	<input type="radio"/>	<input type="radio"/>	[Value]
[Activity]	<input type="radio"/>	<input type="radio"/>	[Value]
[Activity]	<input type="radio"/>	<input type="radio"/>	[Value]
[Activity]	<input type="radio"/>	<input type="radio"/>	[Value]

The *Rate Skills for Job* screen allows you to record the percentage of time (or *Time Allocated %*) spent on relevant engineering activities (or CPSC code activities) defined within a work assignment.

- 1 REVIEW the *Engineering Activities* or *CPSC* list and indicate a percentage for **ONLY** those activities that apply to your FMS Job Description.

NOTE: To review the definition of a *Engineering Activities* or *CPSC* code **CLICK** on any skill label. When finished **CLICK** the **OK** button to close the Definition Box.

- 2 **SELECT** each *Engineering Activities* or *CPSC* code that apply to your job by clicking the radio button in the column labeled "YES". For each "YES" indicated.

IMPORTANT: It is not necessary to select "NO" if the *Engineering Activities* or *CPSC* does not apply to your FMS Job Description.

- 3 **ENTER** a *Time Allocated %* value for the *Engineering Activities* or *CPSC* code.

NOTE: The total of all entered %s for *Engineering Activities* or *CPSC* codes on the work assignment **MUST** equal 100%. Remember, only enter a value for the activities that apply to what you do.

IMPORTANT: DO NOT ENTER "0%" FOR ACTIVITIES NOT WORKING ON!

- 4 **Save** Your Work.

You may save your work at any time during this process using the "Save Only" button.

SAVING NOTES

- 1 The *Cancel Changes* button clears/cancels entries.
- 2 The *Save Only* button records all screen information and saves for future updating.
- 3 The *Save and Request Concurrence* button records all screen information and notifies your immediate supervisor that your self-assessment of *Time Allocated %* is ready for their concurrence.

IMPORTANT: You are not finished until the total percentages equal 100%, and you **SELECT** *Save and Request Concurrence*.

Return to Work Assignments Listing

Do Not View by [Code]

Home Logout

- 5 **NOTE:** Repeat the rating process for each *Work Assignment* you have documented by **CLICKING** on the "Return to the Work Assignments Listing" link after saving.



**Brake Pressure Switch
On Vehicle Characterization**

Updated 2/26/99

Vehicle: 1992 Town Car

With ABS
With Traction Control
No Major Modifications
No Issues with Brake System

Parameters to be Measured


Pressure Profile at Brake Pressure Switch Mounting Location on Proportioning Valve
Brake Fluid Temperature at same location
Ambient Temperature at same location
Pressure Profile exiting ABS unit prior to entering Proportioning Valve
Brake Pressure Switch circuit (orange wire) voltage.
Vehicle Speed
Brake Pedal ON/OFF switch Voltage
Brake Pedal Effort
Pressures up to 250 Bar, sampling rate 1000 hz minimum.
Voltage up to 20 Vdc
Temperature -10 to 300 F
Effort 0 to 400 lbs

Driving Conditions

DO NOT USE SPEED CONTROL
Traction surface : Dry Asphalt
Loading = 2 Pass weight

	Speed mph	Pedal effort	decel G	repetitions	rate/ mile
Normal Braking (no ABS)	0	normal		5	
	30		< 0.3	5	1
	40		< 0.3	10	1
Normal Braking + ABS	30		0.7 - 0.85	5	1
	40		0.7 - 0.85	10	1
Panic Braking (No ABS)	40	agressive		10	1
Panic Braking + ABS Traction Control On Other combinations??	40	agressive		10	1

31-1 Speed Control



Component

Connector

Page


Harness

31-2 Speed Control

Measure Voltage on
Orange wire. This
may require a pull-down
resistor to ground. (1k² to 10k²)

Shows when Brake pressure
switch opens & closes.

31-1 Speed Control




⊕ Component

⊕ Connector

⊕ Page

⊕ Harness

31-2 Speed Control



⊕ Component

⊕ Connector

⊕ Ground

⊕ Splice


⊕ Page

⊕ Harness

⊕ How The Circuit Works

Deactivator Switch (Brake Pressure Switch)

The deactivator switch is a normally closed switch and replaces the vacuum dump valve as a redundant safety feature in the system. Normally when the brake pedal is depressed, an electrical signal from the brakelamp circuit to the speed control servo will disengage the system. Under increased brake pedal efforts (5-10 lbs, engine running), the deactivator switch mounted in the brake line will open and remove power to the speed control servo clutch, releasing the throttle independent of the speed control servo control. The deactivator switch is located at the rear brake proportioning valve (ABS brakes) or junction block (Non-ABS brakes) below the brake booster.



Brake Pressure Switch

- 1993 Town Car/Crown Victoria/Grand Marquis Table of Contents
- Group 10: FUEL SYSTEM
- Section 10-03: Speed Control Systems
- REMOVAL AND INSTALLATION

Deactivator Switch


Removal

1. Remove electrical connector from switch.
2. Unscrew switch and remove from brake proportioning valve or junction block.

Installation

1. Screw switch into proportioning valve or junction block. Tighten to 15-20 N-m (12-14 lb-ft).
2. Attach electrical connector.
3. Bleed brake lines as outlined in Section 06-09, ABS brakes, or Section 06-08, non-ABS brakes.

Proportioning Valve Location



Junction Block Location

Just install Pressure Sensors

2.000

Thermostat



BRAKE SYSTEM BLEEDING

The anti-lock brake system must be bled in two steps:

Tools Required:

- Anti-Lock Test Adapter T80P-50-ALA
1. The master cylinder and hydraulic control unit must be bled using Anti-Lock Test Adapter T80P-50-ALA or equivalent. If this procedure is not followed, air will be trapped in the Hydraulic Control Unit which will eventually lead to a spongy brake pedal.

To bleed the master cylinder and HCU, disconnect the 55-pin plug from the Electronic Control Unit and install the Anti-Lock Test Adapter to the wire harness 55-pin plug.
 - a. Place bleed/harness switch in bleed position.
 - b. Turn ignition to ON position. At this point the red OFF indicator should turn on.
 - c. Push motor button on adapter down. This starts the pump motor. The red OFF indicator will turn off and the green ON indicator will turn on. The pump motor will run for 60 seconds once the motor button is pushed. If the pump motor is to be turned off for any reason before this 60 seconds has elapsed, push the abort button and the pump motor will turn off.
 - d. After 20 seconds of pump motor operation, push and hold the valve button down. Hold valve button for 20 seconds then release.
 - e. The pump will continue to run for an additional 20 seconds.
 2. The brake lines can be bled in the conventional manner. Refer to «Section 06-06».

Bleed in the following sequence:

- RH Rear
 - LH Front
 - LH Rear
 - RH Front
-

2/18/97

Additional Tests for Matrix

55 AMP wet & dry completed
~~Isolation Resistance~~
~~Leakage current~~ Dry, BF, BF+salt
H₂O

~~BF~~ Dry > 20 Meg

BF ≈ 2 Meg

BF + H₂O + NaCl 0.5 → 0.8 Meg

Brake Pressure Switch Test Log, Updated 4/26/89

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Vary water concentrations in 'new' Brake Fluid 14Vdc to one terminal, harness grounded Water Conc: 0%, 4%, 6%, 10%, 75%	250+ hours, Current draw in the 0.2mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis suspended.
	2	TI	Vary water concentrations in 'new' Brake Fluid 1 Amp through switch terminals	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Harness Grounded	> 300 hours into test, max current 7mA No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal. Harness Grounded, Ambient at 100 C	30 hours into test max current 6mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 18 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 60 Amps Through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat BF tubes, include sparking With Fluid & Dry Pure 'new' brake fluid with metal shavings 5% brake fluid solution	2 tests. Smoke observed, ignition observed on part whisker See attachment Test complete Brake fluid in cavity shows dense test build-up Smoke observed at 675 F, Base wells and falls off at 800 F
	6a	TI	Create heater by covering spring area Salt water solution, 14V between spring and harness	One out of 16 devices increased resistance to 5 ohms. Others either very low resistance or inoperative It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run ignition test to understand repeatability and current path.	Switch ignition with repeated 5% water solution into switch Current path is through harness. See plots and video. Additional test include top water, old BF, new BF and other.

Brake Pressure Switch Test Log, Updated 4/26/09

Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psig pressure pulses at 135C per ES	First leak observed at 728,000 cycles. Test Completed. See attached Method Chart.
Disturbance Wear	8	TI	0-1400 psig pressure pulses at 135C.	Parts withdrawn every 200k cycles, characterized for wear
Field vs Lab Correlation	9	Control Labs	Field returns, both driver side, judders	Parts in Control Labs, see Field spreadsheet
Design Of Experiments (1)	10	TI	Wear under concentration in 'wear' Brake Field	Test Report being written investigation continues.
Evaluating Factors			12 snap + 12 quiet switches w/ 0 % water in BF	Suspended at 1.3 million cycles with no leaks observed.
Effecting Displacement Wear			12 snap + 12 quiet switches w/ 8 % water in BF	Snap samples suspended at 1.3 million cycles with 2 leaks observed at 1.2M. Quiet samples suspended at 600k cycles to assess failure mechanism.
Impulse test				
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Test at AVT... see Ford charts... >500k in car?
Oil and fluid analysis	11a	TI	Analyze used brake fluid at the master cylinder (UMC), used brake fluid at the caliper (UCA) and rear brake fluid (REVF) for metal and water content.	Test complete. UMC: Cu = 416 (ppm), Fe = 5.8 (ppm), Cr = 0.08 (ppm), 1.1 %H2O. UCA: Cu = 582 (ppm), Fe = 5.8 (ppm), Cr = 1.9 (ppm), 1.1 %H2O. REVF: Cu = 4.91 (ppm), Fe = 0.02 (ppm), Cr = <.01 (ppm), 0.3 %H2O.
Spark Rec Study	12	Control Labs	Determine if arcing/erosion forms in switch using clutch tests and high speed video. Use dry switches as well as switches with various brake fluid water levels.	Equipment set-up in progress at Control Labs. TI Experimented with no 'significant' sparks observed
Characterization of switches received from field, suppliers & other sources	13	Control Labs	Chemical/physical, electrical and chemical aspects of returned switches	Data log and analysis procedure set up complete. Analysis of switches in progress.
Field Impact Tests	13a	TI	Repeat impact simulation with different fluids. CR HOUR TEST: 5% NaCl in tap water tap water rain water 480 hour tests: used brake fluid used brake fluid w/ 5% H ₂ O	Test complete. 5% NaCl sample resulted in an ignition. All brake fluid samples drew less than 3 mAmps. No corrosion visible on brake fluid samples. Rain water and tap water samples drew <10 mAmps and showed some signs of corrosion. Chemical analysis in process.

3713 1829

Brake Pressure Switch Test Log, Updated 4/28/89

			new brake fluid	
			new brake fluid w/ 5% H ₂ O	
Design Of Experiments (2)	13b	TI	Vary water concentrations in 'new' Brake Fluid	Test suspended. Analysis in process to assess test findings.
Repeat of test 9D			10 amp + 20 quiet switches w/ 0 % water in BF	
			10 amp + 20 quiet switches w/ 5 % water in BF	
Compatibility of Kaptan with Oxalic Acid	14	Deposit	Characterize change in properties of Kaptan with various % oxalic acid in brake fluid.	Report expected from Deposit by 5/3/89.
Evaluation of Plastic Materials with Improved Parameters	10	TI	Assess properties and availability of different grades of plastic resin with additives to improve plastic part performance	Test suspended. Celcon and Noryl ignited 3/5 and 2/5 trials ZYTEL samples tested 1/8 ignitions
Long duration brake fluid ingress test.	15a	TI		Test in progress. (15) days to date. Used brake fluid current dropped off to <1/10 mAmp. New brake fluid (repeat current) current low
Evaluation of Switch Orientation	15b	TI	Assess ignition sensitivity to switch orientation. Test vertical versus 45 degree. Test rotational sensitivity.	Test complete. Ignition is independent of switch orientation. classified switch ignition can occur in vertical or 45 degree angle. Ignition appears not sensitive to switch rotational alignment.
Relay Circuit Test	16	TI	Repeat test 15a in Ford relay circuit for (48) hrs. Bring switch to impending ignition in (15) Amp circuit then place in relay circuit for (18) hrs. Input max. circuit power into washer on switch.	Test complete. No ignition. Corrosion rate drastically reduced. Insufficient power in circuit to create or move toward ignition in lab Fleeter element was warm to the touch.

3713 1830

Evaluation Process Brake Pressure switch / Harness

Brake Pressure Switch Plan Updated 2/15/99
Evaluation Plan for Field Returns

Dw #		Date of update	
Mileage		Sw Date Code	
Sw PIN			

Category	Step #	Action	Comments
Field Info	1	Log Field Info into Switch Log.xls	
	2	Photograph Switch	
	3	Record any unusual external visual observations	
	4	Check for Connector engagement	
			If not correct conduct X-Ray to determine fit-up between base lip and red seal
Switch +	5	Wire 1(LGRN) to Wire 2(ORANGE) Resistance	
Connector	6	Wire 1(LGRN) to Hotspot Resistance	
Assembly	7	Wire 2(ORANGE) to Hotspot Resistance	
	8	Separate Harness from Switch 8 TAG	PHOTOGRAPH AS NEEDED
Connector Only	9	Verify Connector Seal	Visual check of Red Seal, Dkt lines, Indentation mark. Indentation mark must be 300 degrees.
	10	Wire 1(LGRN) to Wire 2(ORANGE) resistance	
	11	Current Leakage Wire 1(LGRN) to Wire 2(ORANGE)	
	12	Check for full engagement of connector	Visual check of dkt lines on mated r/oth base
	13	Check wire insulation	
	14	Check wire gray seals	
	15	Cut wire insulation to check for corrosion	Cut insulation longitudinally to check for cracking along wires. If signs of corrosion, identify color, save samples for chem Id.
Switch External Unpressurized	16	Assemble Switch to Calibration Stand	
	17	Spring Terminal to Stationary Terminal Resistance	Stationary Terminal is closest to the outside connector facing tab.
	18	Spring Terminal to Hotspot Resistance	
	19	Stationary Terminal to Hotspot resistance	
	20	Wire to Hotspot Resistance	
	21	Current Leakage Spring Terminal to Hotspot	

CRIMP RING

Slave Railers, 313 280 3295,
swrman@ford.com
file evalpro.xls

page 1 of 2
printed 2/15/99 10:48 AM
uncontrolled document

original 2/15/99
revised 8/0

3713 1831

Evaluation Process Brake Pressure switch / Harness

	22 Current Leakage Stationary Terminal to Housing	
	23 Voltage drop at 750 mA	
<hr/>		
Switch	24 Switch Opening Pressure	Do not perform on parts from underhood lines, as they disturb diaphragm/other condition
External	25 Switch Closing Pressure	Do not perform on parts from underhood lines, as they disturb diaphragm/other condition
Pressurized	26 Proof Test for Leakage	Do not perform on parts from underhood lines, as they disturb diaphragm/other condition
	27 Repeat Steps 17 through 25 at 150 psig	
<hr/>		
Switch	Procedure to remove aluminum clamp ring	
Internal	Use cleanroom kit (or plastic if Ford prefers) to assist the analysis surface. Also create a paperface shield to further reduce chance of contamination during cutting of clamp ring. Place a piece of tape over the area to be cut. Cut clamp ring using jewellers saw or Diamond cutoff wheel. Cut corners of ring at 180 degree orientation. Unfold clamp ring. Optically examine revealed surfaces. Take optical photographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate. Inside surface of clamp ring. Seal area and underside of base. Top of cap	
Analytical Techniques SEM/EDX	Assess Need for Analytical Techniques Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base. Reprotest the top surface and remove the cap. Optically document all revealed surfaces starting with cap. Meanwhile, start SEM-EDX analysis on top side of cap. . Particularly look for evidence of corrosion or arcing. Particularly focus in on the edges of the ceramic pin guide and on the inclined ring that lines up with heater wall of the switch cavity. Particularly look for evidence of corrosion or arcing. Decide if we should try to clean off any of the overlying debris to try to examine the underlying metal surface. Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.	
Data Entry	Log All data from this sheet into Switch Log Photographs, Elemental maps etc must be retained and referenced by Switch #	

3718 1838


Steve Fajness, 313 380 3235,
sfajness@ford.com
Stev.fajness@id

page 2 of 2
printed 2/18/99 10:45 AM
unclassified document

original 2/18/99
revised 8/02

PARK STUDY TEST
ELECTRICAL SCHEMATIC.

AR



- Channel ① = Voltage drop across switch
- ② = Current through switch
- ③ = Pressure transducer on manifold



3713 1834

Summary of Brake Switch Analysis

Sample Information		Switch		Switch at 120 psi				Function		
SN	Condition	Spring Tens. to Stat. Term.	Spring Tens. to Hardest	Stat. Term. to Hardest	Spring Term. to Stat. Term.	Spring Term. to Hardest	Stat. Term. to Hardest	Opening Pressure	Closing Pressure	Foot Tens. at Release
0000077	Probably normal	MP	MP	MP	MP	MP	MP	MP	MP	MP
0000084	Normal	MP	MP	MP	MP	MP	MP	MP	MP	MP
00000810	Normal	MP	MP	MP	MP	MP	MP	MP	MP	MP
00000820	Normal	MP	MP	MP	MP	MP	MP	MP	MP	MP
00000823	Apparent leakage	0.5-1.0M	MP	MP	MP	MP	MP	MP	MP	MP
00000874	No leaks or other apparent problems	0.5-1.0M	MP	MP	MP	MP	MP	MP	MP	MP

MP - Not Pedaled
 TSP - To Be Pedaled
 TC - Touch Up

3713 1835

SM - Ford Mustang
 CV - Vehicle
 C - Color

Summary of Brake Switch Analysis

Veh	Connector/Wires				Switch				
	Engagement	Wires	Red Seal	Gray Seal	Inspect, Washer, Cotter Pin, Spacer, and Disc	Environment Seal	Disassembly Notes	Cap	Steel, Switch Core, Contacts, Terminal
NY08877	Could not determine	Went length (~10 mm) no apparent conductor damage. Chalk-like or brownish brownish residue.	Could not determine		Dark residue consisting of small particles (possibly brake fluid) and a metal particle. No residue of brake fluid on fluid seal which piece of metal.	Intact. Appears to be in good condition.	Control intact; appears to have had good sealing. All Kaptan parts checked and visible little residue which most likely from a leak path. Damage appears to have resulted in fluid contact in weather. Kaptan material had oxidized by unknown means.	Direct deposit on face of cap contains elements from brass contacts, including transfer of contact material to cap, possibly as a result of an electrical spark. Other metal particles (possibly brake fluid) also present.	Steel separated below clamp ring. Appears to be a roller component. Stationary contact visible above/below, but of material due to oxidation, and slight corrosion existing. Other deposit on interior of stationary contact appears to be a roller component.
NY08884	Missing	Missing	Missing	Missing	Elements from contact material detected at lining end of inspect. Silver also detected.	Missing	Control missing. Chopped fragments of Kaptan were present.	Deposits on face of cap contain elements from brass contacts, including transfer of contact material to cap, possibly as an oxide, nitride, or corrosion product.	Steel, stationary contact, movable contact, transfer pin, and terminal missing.
NY24118	Missing	Missing	Missing	Missing	Elements from contact material detected at lining end of inspect.	Not permitted to disassemble switch.	Not permitted to disassemble switch.	Deposits on face of cap contain elements from brass contacts, including transfer of contact material to cap, possibly as an oxide, nitride, or corrosion product.	Transfer pin and movable contact missing. Stationary contact visible; contact in lining position as that in disassembly (Photo) results.
NY24206	Missing	Missing	Missing	Missing	Elements from contact material detected at lining end of inspect. Other residue in early section. Part of hydrocarbon and silver.	Missing	Caplet appears damaged. Kaptan parts present, but not held together. Could not conduct for operation.	Deposits on face of cap contain elements from brass contacts, including transfer of contact material to cap, possibly as an oxide, nitride, or corrosion product.	Steel, stationary contact, movable contact, transfer pin, and terminal missing.
NY18823	Missing	Missing	Missing	Missing	Black residue in inspect cavity, on weather, and resistor outside of cap. Some residue (possibly brake fluid) and a metal particle.	Intact and appears to have had good seal.	Control intact and appears to have had good seal. Kaptan parts visible through weather in that found in through (Photo) sample. All three visible little residue which possibly leaked back path.	Dark green deposits on face of cap contain elements from brass contacts including transfer of contact material to cap, possibly as an oxide, nitride, or corrosion product. Liquid in cavity and on face is glycol based (possibly brake fluid).	Switch core and terminal cavity contain glycol based material (possibly brake fluid). Contacts appear intact. Dark green residue.
NY06874	Missing	Missing	Missing	Missing	Black residue in inspect cavity (possibly brake fluid) and a metal particle. No apparent fluid on component inside cap.	Intact and appears to have had good seal.	Control intact and appears to have had good seal. Kaptan parts visible (Photo) sample. Clamping on rollers suggest a good condition in operation.	Face and interior of cap appear clean and dry.	Switch and terminal cavity appear clean and dry. No apparent deposits or corrosion on terminals.

NP = Not Performed
 WP = To Be Performed
 FC = Towed Car

Summary of Brake Switch Analysis

Sample Information					Condition	Conclusions/Comments
VIN	Sample	SPV/Make	Final Code Code	Condition		
P1900077	Sample P1900077	1988 TC	P1900000	Prohibit Ground	Continuation and subsequent events in Keyless entry system lock path for brake field to enter switch easily. Transfer of brake control control to the cap suggests that an electrical path formed between the hot (+) contacts and the grounded (-) line.	Brake field to switch easily may have acted as electrical path for the call. Electrical path and other contact anything of satisfactory contact indicates that structure and other components may have been exposed with brake field.
P1900004	A	1988 TC	7777000	Ground	Transfer of brake control control to cap suggests that electrical path may have occurred. The body developed to determine if Keyless locked or if brake field was present in switch easily.	
P1700018	B	1988 TC	P1700014	Ground	Transfer of brake control control to cap suggests that electrical path may have occurred. The body developed to determine if Keyless locked or if brake field was present in switch easily.	
P1700008	C	1988 TC	P1700000	Ground	Transfer of brake control control to cap suggests that electrical path may have occurred. The body developed to determine if Keyless locked or if brake field was present in switch easily.	
V2100139	D	1988 CV	P2100000	Approved Seizure	Continuation and subsequent events in Keyless entry system lock path for brake field to enter switch easily. Transfer of brake control control to the cap suggests that an electrical path formed between the hot (+) contacts and the grounded (-) line.	Brake field to switch easily may have acted as electrical path for the call. Police made repairs similar to movable switch.
P0000074	E (H1)	TD	P0000000	No brake or other approved problems	No apparent problem with switch other than inherent damage to brake switch.	

NP = Not Performed
 TSP = To Be Performed
 TC = Total CV

Summary of Brake Switch Analysis

Sample Information	Switch	Switch at 100 psi						Function		
		Spring Term. to Std. Term.	Spring Term. to Hanger	Std. Term. to Hanger	Spring Term. to Std. Term.	Spring Term. to Hanger	Std. Term. to Hanger	Opening Position	Closing Position	Final Test of 0202
VN	Condition									
PY28008	Approved Package	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY28009	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)
PY28010	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	NP	NP	NP (No apparent leak)
PY28011	No leaks or other apparent conditions	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY28012	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)
PY28013	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	NP	NP	NP (No apparent leak)
PY28014	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)
PY28015	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)
PY28016	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)
PY28017	No leaks or other apparent conditions	0.20 (NP)	NP	NP	NP	NP	NP	1.0	NP	NP (No apparent leak)

NP - Not Performed
 NP - To Be Performed
 TC - Test Car

3713 1838

GM - General Motors
 CV - Chevrolet
 10 - Police

Summary of Brain Switch Analysis

VIN	Component				Pitch					
	Engagement	Misc	Red Seal	Grey Seal	Hinge, Washer, Detent, Spacer, and Disc	Endorsement Seal	Control/Washer Seal	Cup	Other, Switch Core, Contact, Terminal	
PY20000	Missing	Missing	Missing	Missing	Black washer in topport cavity, on washer, and coverplate contain glycol based material probably brake fluid and a metal coating.	Seal and appears to have had good seal.	Control intact and appears to have had good seal. Washer seals exhibit damage similar to that found in samples (fractured sample). All three exhibit little cracks which probably formed high pitch.	Dark green deposits on face of cup corolla strongly resemble same corrosion byproduct sample of broken switches in cup probably an oxide, sulfate, or carbonate product. Glycol is observed on all face in glycol based probably brake fluid.	Switch and terminal contain visible glycol based material probably brake fluid. Stationary contact intact, shows some corrosion resulting in pitting in some locations on terminal sample. Movement cannot be reproduced, apparently due to loss of spring.	[40% of Reference]. No evidence of heating or die casting. Dark green deposits on switch contacts resemble those found on metal in other. Two contacts exhibit green deposits that extend to base switch and terminal surfaces, but do not merge.
PY20001	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20002	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20003	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20004	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20005	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20006	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20007	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20008	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20009	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20010	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20011	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20012	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20013	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20014	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20015	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20016	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20017	Missing	Missing	Missing	Missing	MP	MP	MP	MP		
PY20018	Missing	Missing	Missing	Missing	MP	MP	MP	MP		

MP = Not Performed
 TP = To Be Performed
 TC = Test Car

3713 1838

GM - Power Steering
 CV - Vehicle
 AC - Power

Summary of Brake Switch Analysis

Sample Information					Conclusions/Comments
VIN	Sample	MPN/Vehicle	Part/Date Code	Condition	
				Apparent leakage	Establishment and subsequent leakage in Kaplan used limited test path for brake field to water switch cavity. Transfer of tester contact contacts to the cap suggests that an electrical cell formed between the hot (+) terminal and the grounded (-) GND.
NY78895	F	TC	PCPC118	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY29049		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28410		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28380		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28211		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
NY78428		ETC	225	No tests or other apparent problems	Functional testing revealed no apparent problem with switch. No further analysis performed.
PX18223		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28728		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28297		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PY28288		ETC	225	No tests or other apparent problems	Corrosion, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.

MP - Not Performed
 TSP - To Be Performed
 TD - Test Car

Summary of Brake Switch Analysis

Special Information		Switch			Switch at 150 psi			Function		
VMI	Condition	Spring Term. to Dist. Term.	Spring Term. to Hanger	Dist. Term. to Hanger	Spring Term. to Dist. Term.	Spring Term. to Hanger	Dist. Term. to Hanger	Opening Passages	Closing Passages	Final Type of Output
PV72222	No leaks or other apparent conditions	0.1 in./sq.	in./sq.	in./sq.	0.1 in./sq.	in./sq.	in./sq.	120	in./sq.	in./sq.
PV72223	No leaks or other apparent conditions	0.2 in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	120	in./sq.	in./sq.
PV72224	No leaks or other apparent conditions	0.3 in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	120	in./sq.	in./sq.
PV72225	No leaks or other apparent conditions	0.4 in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	120	in./sq.	in./sq.
PV72226	Manufactured Sec.	NP	NP	NP	NP	NP	NP	NP	NP	NP
PV72227	No leaks or other apparent conditions	0.5 in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	in./sq.	120	in./sq.	in./sq.
PV72228	Manufactured Sec.	NP	NP	NP	NP	NP	NP	NP	NP	NP

NP = Not Followed
 NP* = To Be Followed
 TC = Valve Cap

3713 1841

GM - General Motors
 CV - Valve
 PC - Piston

Summary of Bottle Switch Analysis

Chemical Findings

BIN	Connector/Wire				Switch					
	Engagement	Flags	Red Seal	Gray Seal	Report, Number, Converter, Spans, and Date	Environmental Seal	Shield/Wireless Cycle	Cap	Body, Switch Core, Contacts, Tumbler	
NY70000	CPMHD with not fully engaged	TIP	Intact, Supersaturant present and clean	Intact. When not easily clean before used except for trace of oil from seal. Seal still Supersaturant in wire condition.	Black switch in filling end of hopper. Did not analyze. Apparent metal deposits on converter, switch, and wire, as well as on interior surface of cap.	Environmental seal intact, in place, appearing to have good adhesion.	Shield intact and appears to have had good seal. Rightion seal without foreign particles identification and trace of oil, but no apparent cracks or indentations. Other Rightion seals show no trace, cracks, or indentations. No apparent lead cap.	Face of cap covered with and covered deposits coated. In place and also probably converter contact of cap mounted. Therefore, the lower in place by converter contact. No evidence of a real connection.	Some residues what appears to be unknown (suspected epoxy) since suspect is discontinued. Intensity correct observed, but not heavily changed over cap.	Face of contacts and their bases appear clean. No apparent deposits or corrosion on tumbler.
NY70001	Fully engaged	TIP	Intact, Supersaturant none and clean all the way around	Intact. When not easily clean before used except for trace of oil from seal. Seal still Supersaturant in wire condition.	Black switch in filling end of hopper. Did not analyze switch. Did not chemically analyze.	Did not demonstrate	Did not demonstrate	Did not demonstrate	Did not demonstrate. Tumbler clean (no apparent deposits or corrosion).	
NY70002	Cap with side of connector not fully engaged.	TIP	Intact, Supersaturant none and clean all the way around	Intact. When not easily clean before used except for trace of oil from seal. Seal still Supersaturant in wire condition.	Black switch with copper or metal colored glaze on filling end of hopper. Did not analyze switch. Did not chemically analyze.	Did not demonstrate	Did not demonstrate	Did not demonstrate	Did not demonstrate. Tumbler clean (no apparent deposits or corrosion).	
NY70004	Fully engaged	TIP	Intact, Supersaturant none and clean - 80% covered. Witness and some damage to edge of seal.	Intact. When not easily clean before used except for trace of oil from seal. Seal still Supersaturant in wire condition.	First colored deposit in filling end of hopper. Did not analyze deposit. Did not chemically analyze.	Did not demonstrate	Did not demonstrate	Did not demonstrate	Did not demonstrate. Tumbler clean (no apparent deposits or corrosion).	
NY70008	Missing	Missing	Missing	Missing	Black switch in filling end of hopper; did not analyze.	Missing	Did not demonstrate	Expected they covered with red and possibly colored deposits; did not analyze.	Missing.	
NY70017	Fully engaged	TIP	Intact, Supersaturant none and clean all the way around	Intact. When not easily clean before used except for trace of oil from seal. Seal still Supersaturant in wire condition.	Black switch with copper or metal colored glaze on filling end of hopper. Did not analyze switch. Did not chemically analyze.	Did not demonstrate	Did not demonstrate	Did not demonstrate	Did not demonstrate. Tumbler clean (no apparent deposits or corrosion).	
NY70101	Missing	Missing	Missing	Missing	Did not analyze in pump. Intensity did not demonstrate.	Did not demonstrate	Did not demonstrate	Expected face covered with red and possibly colored deposits; did not analyze.	Missing.	

MF - Not Fulfilled
 TEP - To Be Fulfilled
 TC - Test Cit

3713 1842

DM - Found Sample
 CV - as Visited
 CI - Police

Summary of Brake Switch Analysis

Sample Information					
VIN	Sample	MP/Vehicle	Postal Data Code	Classifier	Conclusion/Comments
PV12080		PCV-TC		No tests or other approved procedures	Switch did not open when compressed. Cap appears to have been actuated by motor function. Transfer pin found in place by motor function. No evidence of motor field leakage or formation of electrical arc.
PV12092		TC		No tests or other approved procedures	Construction, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PV12093		PCV-PC		No tests or other approved procedures	Construction, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PV12094		TC		No tests or other approved procedures	Construction, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PV12096		TC	77	Unusable for	Severely damaged by fire. No further analysis performed.
PV12072		TC		No tests or other approved procedures	Construction, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
PV12081		TC		Unusable for	Severely damaged by fire. No further analysis performed.

MP = Not Performed
 TSP = To Be Performed
 TC = Test Car

3713 1843

GM = General Motors
 CV = Control Valve
 PC = Pedal

Summary of Brake Switch Analysis

Sample Information		Switch			Switch at 90 mph			Function		
MSR	Condition	Spring Term. to Dist. Term.	Spring Term. to Hoopst	Dist. Term. to Hoopst	Spring Term. to Dist. Term.	Spring Term. to Hoopst	Dist. Term. to Hoopst	Opening Pressure	Closing Pressure	Power Test at 90 mph
PY72408	No leaks or other apparent malfunctions	1.00-2.00	2.00		0.7-2.0K	-2.0K		100		0.750 approx leak
PY28148	No leaks or other apparent malfunctions	0.6-2.0	2.0		2.0	2.0	2.0	120		1.000 approx leak
PY72409	No leaks or other apparent malfunctions	0.6-2.0	2.0		2.0	2.0	2.0	200		2.000 approx leak
PY72409	No leaks or other apparent malfunctions	0.6-2.0	2.0		2.0	2.0	2.0	100		0.750 approx leak
PY72410	No leaks or other apparent malfunctions	0.6-2.0	2.0		2.0	2.0	2.0	100		2.000 approx leak
PY72410	Overriding return, apparent brake hold leak.	-7.0K	-2.0K	-2.0K	-4.0	-2.0K	-2.0K	100		2.000 approx leak

NP = Not Performed
 TSP = To Be Performed
 TC = Test Car

3713 1844

GM - Grand Marquis
 Co. - in Detroit
 -C - Police

Summary of Scope Search Analysis

PY#	Connector/Wire				Switch				
	Wire	Wire	Red Seal	Gray Seal	Mount, Washer, Connector, Spacer, and Die	Environmental Seal	Switch/Washer Seal	Cap	Base, Switch Body, Contacts, Terminals
PY78208	Fully examined	TSP	Intact. Impression even, but not deep or sharp. Not as pronounced as in other samples.	Intact. Wire and cavity clean below seal except for trace of all from seal. Good bit impression in wire position.	Cell attached to prep wire. Die not disassembled.	Intact and appears to have had good seal.	Good bit and appears to have had good seal. Die not disassembled. Impression not as deep as others, but no apparent cavity in substrate. Other die impressions show no wear, cracks, or deformation. No apparent bit path.	Face of cap covered with rust and white material deposits including iron and zinc. Slightly concave portion of cap missing. Sample plus spacer in place by connector post(s). Appears void (environmental entry). No evidence of a cell opening.	Visible contact observed, but not firmly seated near cap. Feet of contacts and their bases appear clean. Terminals which were examined.
PY78154	Fully examined	TSP	Intact. Impression even and sharp.	Intact. Wire and cavity clean below seal except for trace of all from seal. Good bit impression in wire position.	Cell attached to prep wire. Die not disassembled.	Did not disassemble.	Did not disassemble.	Did not disassemble.	Did not disassemble. Terminals clean for apparent deposits or corrosion.
PY78208	Fully examined	TSP	Intact. Impression even and sharp.	Intact. Wire and cavity clean below seal except for trace of all from seal. Good bit impression in wire position.	Cell attached to prep wire. Die not disassembled.	Did not disassemble.	Did not disassemble.	Did not disassemble.	Did not disassemble. Terminals clean for apparent deposits or corrosion.
PY78209	Fully examined	TSP	Intact. Impression even and sharp.	Intact. Wire and cavity clean below seal except for trace of all from seal. Good bit impression in wire position.	Block matches in filing and of impregnated. Die not analyzed at CL. Disassembled and analyzed by EPA.	Disassembled and analyzed by EPA.	Disassembled and analyzed by EPA.	Disassembled and analyzed by EPA.	Disassembled and analyzed by EPA. Terminals from light deposits on base.
PY78215	Fully examined	TSP	Intact. Impression even and sharp.	Intact. Wire and cavity clean below seal except for trace of all from seal. Good bit impression in wire position.	Block matches in filing and of impregnated. Die not analyzed.	Did not disassemble.	Did not disassemble.	Did not disassemble.	Did not disassemble. Terminals clean for apparent deposits or corrosion.
PY78216	Missing	Missing	Missing	Missing	Block matches in filing and scratches placed after base material (possibly base field, die cavity, and/or wire) possibly a reproduction. No apparent trace on connector, washer, or seal.	Intact and appears to have had good seal.	Block is intact and appears to have had good seal. Impression not as deep as others, but no apparent cavity in substrate. Appears to have formed last path. Damage appears similar to that in sample sample.	Face of cap covered with black residue and copper colored granules. Residue contains silver based material (possibly base field) and possibly a reproduction. Additional analysis of residue pending.	Switch cavity of base contains black residue. Striations around appears to have been covered away. Black residue is present in terminal cavity and at base of contacts. Terminals appear clean otherwise.

NP = Not Performed
TSP = To Be Performed
TC = Taken Care

Summary of Brake Switch Analysis

Vehicle Information					
VIN	Sample	SW/Make	Year/Make Code	Condition	Conclusions/Remarks
2Y720408		8TC	222	No leads or other apparent problems	Switch did not open when accelerated. Shows correct lead path between contacts and ground. Cap lead lower downcast. Transfer pin loose in place by capacitor position. Missing in caply appears to have formed correct lead path. No evidence of material transfer from contacts to cap. No evidence of lead in V-shaped notch. Appears to be different failure mode than Memphis switch.
2Y182408		10CV	222	No leads or other apparent problems	Construction, materials and functional testing revealed no apparent problems with switch. No further analysis performed.
2Y720408		11TC	212	No leads or other apparent problems	Construction, materials and functional testing revealed no apparent problems with switch. No further analysis performed.
2Y720408		10TC	222	No leads or other apparent problems	Switch did not open when accelerated. Shows correct lead path between contacts and ground. Covered by DR.
2Y720408		13TC	222	No leads or other apparent problems	Construction, materials and functional testing revealed no apparent problems with switch. No further analysis performed.
2Y720410	Crash	TC	222	Condition: wires, apparent loose lead lead.	Fieldwork measurements show correct lead path between contacts and between contacts and ground. Switch leads appear to have formed lead path for brake fluid to enter switch cavity. Transfer of contact material to cap suggests significant coil surge occurred between the last (-) contacts and the grounded (+) cap. Switch field very loose when in stoppage. Failure occurs similar to Memphis switch.

NP = Not Performed
 TDF = To Be Performed
 TC = Test Car

3713 1646

GM - Front Wheel
 CV - vs Vehicle
 TC - Test Car

Summary of Drive Switch Analysis

Sample Information		Switch			Switch at 100 psi			Function		
VIN	Condition	Spring Term. to Ref. Term.	Spring Term. to Neutral	Stat. Term. to Neutral	Spring Term. to Ref. Term.	Spring Term. to Neutral	Stat. Term. to Neutral	Opening Program	Closing Program	Prog. Test at 50psi
PY00000	Continuity across apparatus (w/steering lock lock)	>12K	>17K	>20K	>17K	>14K	>15K	No sound	No sound	NO ACCURATE INFO
PY01000	Undrained Ste.	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY02007	Undrained Ste.	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY03001	Undrained Ste.	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY04002	Undrained Ste.	NP	NP	NP	NP	NP	NP	NP	NP	NP
PY05000	No leaks or other apparent problems	CL	NP	NP	NP	NP	NP	NP	NP	NO APPROPRIATE INFO

NP - Not Performed
 TRP - To Be Performed
 TC - Test Car

Summary of Beal's Switch Analysis

P#	Connectors				Observations				
	Engagement	Wire	Red Seal	Gray Seal	Thermostat, Washer, Converter, Spacer, and Disc	Emergency Stop	On/Off/Repeat Beak	Cup	Base, Switch Cavity, Contacts, Terminals
PY20168	Missing	Missing	Missing	Missing	Black welding in fitting end of thermostat. Washer, converter, spacer, and disc. Metal at cup are covered with rust colored deposits.	Black and appears to have had good seal.	Cracked in throat and appears to have had good seal. Kapton seals exhibit circumferential wear in Teller with spalls and circumferential cracking in insulation. Appears to have formed leak path. Damage appears similar to that in Memphis sample.	Face of cup covered with black residue and copper colored deposits. Residue appears glycol based material (possibly brake fluid) and possibly a hydrocarbon. Additional evidence of residue spraying.	Switch cavity of base contains black sludge with copper colored deposits. Movable contact appears to have been corroded away. Black residue is present in terminal cavity and on the terminals.
PY21400	Missing	Missing	Missing	Missing	Black welding in fitting end of thermostat. Washer, converter, disc, and spacer at cup are covered with rust colored deposits.	Missing	Cracked wiring. Charred fragments of Kapton seals visible.	Face of cup covered with rust colored deposits. Analysis pending.	Missing
PY22847	Missing	Missing	Missing	Missing	Black welding in fitting end of thermostat. Washer, converter, disc, and spacer at cup are covered with rust colored deposits.	Missing	Cracked wiring. Charred fragments of Kapton seals visible.	Face of cup covered with rust colored deposits. Analysis pending.	Missing
PY20841	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing
PY21400	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing
PY20880	Fully engaged	TSP	Black. Insulation torn and deep all the way around.	Black. Wire and cavity clean before seal except for trace of oil from seal. Seal felt supersonic in wire analysis.	Black residue in fitting end of thermostat. Oil not analyzed.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminal clean but apparent deposits or corrosion.

NP = Not Performed
 TSP = To the Personnel
 TC = Team Car

3713 1848

GM - Grand Marquis
 CV - in Vehicle
 /CI - Police

Summary of Brake Switch Analysis

Sample Information					Conclusions/Comments
MSI	Sample	Alt/Vehicle	Police Date Code	Condition	
9712888	Car	TC	218	Ownership value, apparent brake fluid leak.	Resistance measurements show correct path between contacts and between contacts and ground. Negative results appear to have followed test path for brake fluid in entire switch cavity. Transfer of contact material to cap suggests electrical cell may occurred between the test (+) contacts and the grounded (-) cap. Brake fluid may have acted as electrolyte. Follow track studies to determine cause.
9712889	CAA	TD	2000	Undersized pin.	Analysis in progress.
9712890	CAA	TC	2000	Undersized pin.	Analysis in progress.
9712891	CAA	TC	?	Undersized pin.	Analysis in progress.
9712892	CAA	TC	?	Undersized pin.	Analysis in progress.
9712893		TC	2000	No tests or other apparent problems.	Observative, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.

NP - Not Performed
 TUP - To Be Performed
 TC - Towed Car

9713 1849

GM - Grand Marais
 CV - in Vehicle
 C - Police

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TEST BEING PERFORMED

Brake Switch Testing Checklist

NF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCL = NOT RECD AT CEN LAB.

		MODEL PY8022/7	A PY8022/8	B NY74511M	C NY7032705	D VK145273	E NK758774	F NY700025	G NK700026
Field Info	1. Log Part into the System Log in	C	C	C	O	C	C	C	O
	2. Condition	FIRE	FIRE	FIRE	FIRE	BP LEAK	NO FIRE/LEAK	BP LEAK	NO FIRE/LEAK
	3. Damage Score	C	C	C	C	C	C	C	NP
	4. Check the manual manual test PMS/notes	C	C	C	C	C	C	C	C
	5. Check for Connector engagement	C	NA	NA	NR	NA	NA	NA	NA
Switch + Connector Assembly	6. Plug it if applicable	C	NA	NA	NR	NR	NA	NA	NA
	7. Check for proper fit	C	NA	NA	NR	NR	NA	NA	NA
	8. Check for proper fit	C	NA	NA	NR	NR	NA	NA	NA
	9. Check for proper fit	C	NA	NA	NR	NR	NA	NA	NA
Connector Only	10. Check for proper fit	O	NA	NR	C	NR	NA	NA	NR
	11. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	12. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	13. Check for proper fit	C	NA	NR	NR	NR	NR	NR	NR
	14. Check for proper fit	C	NA	NR	NR	NR	NR	NR	NR
Switch Internal Inspection	15. Check for proper fit	C	NA	NR	NR	NR	NR	NR	NR
	16. Check for proper fit	C	NA	NR	NR	NR	NR	NR	NR
	17. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	18. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	19. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	20. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
Switch External Inspection	21. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	22. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	23. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	24. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
Switch Internal Inspection	25. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	26. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	27. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	28. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
Switch Internal Inspection	29. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	30. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	31. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
	32. Check for proper fit	NA	NA	NA	NR	NR	NR	NR	NR
Switch Internal Inspection	33. Check for proper fit	C	C	NP	C	O	O	C	NP
	34. Check for proper fit	C	C	NP	C	C	C	C	NP
	35. Check for proper fit	C	C	NP	C	C	C	C	NP
	36. Check for proper fit	C	C	NP	C	C	C	C	NP
Technique	37. Check for proper fit	C	C	NP	C	C	O	C	NP
	38. Check for proper fit	C	C	C	O	C	O	C	NP
	39. Check for proper fit	C	NA	NP	C	C	C	C	NP
	40. Check for proper fit	C	NA	NP	C	C	C	C	NP

8713-1893

C = COMPLETE
 NA = NOT APPLICABLE
 NP = NOT PERFORMED

Brake Switch Testing Checklist

NP = NOT PERFORMED
 NA = NOT APPLICABLE
 NO CLR = NOT RECD AT CSK. LAB.

		3	4	5	6	7	8	9	10
		PY720A3	PY82170	PY82220	PY720B11	NO720A36	PA180223	PY82705	PY82070
Field Info	1 Log Part No into Switch Log etc	C	C	C	C	C	C	C	C
	2 Check for NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK
	3 Pushdown Switch	NP	NP	NP	NP	NP	NP	NP	NP
	4 Check for correct adjustment/alignment	C	C	C	C	C	C	C	C
	5 Check for correct engagement	NA	NA	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	6 Check if it operates	NA	NA	NA	NA	NA	NA	NA	NA
	7 Check to follow the adjustability instructions	NA	NA	NA	NA	NA	NA	NA	NA
	8 Check wiring to correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	9 Check wiring to correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	10 Check for correct wire gauge	NA	NA	NA	NA	NA	NA	NA	NA
Connector Only	11 Check for correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	12 Check for correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	13 Check for correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	14 Check for correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
	15 Check for correct terminals	NA	NA	NA	NA	NA	NA	NA	NA
Switch Dependent Measurement	16 Resistance Switch to Chassis Ground	0	C	NA	NA	0	C	0	0
	17 Spring Resistance to Chassis Ground	0.2	0.2	NA	NA	0.2	0.2	0.2	0.2
	18 Spring Resistance to Chassis Ground	NP	NP	NP	NP	NP	NP	NP	NP
	19 Spring Resistance to Chassis Ground	NP	NP	NP	NP	NP	NP	NP	NP
	20 Spring Resistance to Chassis Ground	11.6	1.84	NA	NA	7.24	6.8	7.24	1.84
Switch External Pressure/Load	21 Switch Spring Pressure	134	100	NA	NA	147	130	140	100
	22 Switch Spring Pressure	60	60	NA	NA	70	60	110	60
	23 Load Test for Leakage	NO LEAK	NO LEAK	NA	NA	NO LEAK	NO LEAK	NO LEAK	NO LEAK
	24 Load Test for Leakage	C	C	NA	NA	C	C	C	C
	25 Load Test for Leakage	NP	NP	NA	NA	NP	NP	NP	NP
Switch	26 Check for correct terminals	NP	NP	NA	NA	NP	NP	NP	NP
	27 Check for correct terminals	NP	NP	NA	NA	NP	NP	NP	NP
	28 Check for correct terminals	NP	NP	NA	NA	NP	NP	NP	NP
	29 Check for correct terminals	NP	NP	NA	NA	NP	NP	NP	NP
	30 Check for correct terminals	NP	NP	NA	NA	NP	NP	NP	NP
Thermostat	31 Check for correct terminals	NP	NP	C	C	NP	NP	NP	NP
	32 Check for correct terminals	NP	NP	C	C	NP	NP	NP	NP
	33 Check for correct terminals	NP	NP	C	C	NP	NP	NP	NP
	34 Check for correct terminals	NP	NP	C	C	NP	NP	NP	NP
	35 Check for correct terminals	NP	NP	C	C	NP	NP	NP	NP

3719 1001

C = COMPLETE
 NA = NOT APPLICABLE
 TSP = TEST PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NFLEAK = NOT TESTED AT GEN. LAB.

		11	12	13	14	15	16	17	18
		PY728085	PX885270	NY748388	PX823072	PT688304	DT688304	PY888305	PT888305
Field Info	1 Log Part Info into Switch Log file	C	C	C	C	C	C	C	C
	2 Inspect	NO FIRELEAK							
	3 Photograph Switch	NP							
	4 Check for unusual electrical clearances	C							
Switch + Connector Assembly	5 Check for Ground-to-ground shorts	NA							
	6 Check for Ground-to-ground shorts	NA							
	7 Check for Ground-to-ground shorts	NA							
	8 Check for Ground-to-ground shorts	NA							
Connector Only	9 Check for Ground-to-ground shorts	NA							
	10 Check for Ground-to-ground shorts	NA							
	11 Check for Ground-to-ground shorts	NA							
	12 Check for Ground-to-ground shorts	NA							
Switch External	13 Check for loose connections	NA							
	14 Check for loose connections	NA							
	15 Check for loose connections	NA							
	16 Check for loose connections	NA							
Switch Internal	17 Inspect Terminal in Emergency Control Assembly	C							
	18 Inspect Terminal in Emergency Control Assembly	0.3							
	19 Inspect Terminal in Emergency Control Assembly	NP							
	20 Inspect Terminal in Emergency Control Assembly	NP							
Switch External	21 Inspect Terminal in Emergency Control Assembly	NP							
	22 Inspect Terminal in Emergency Control Assembly	NP							
	23 Inspect Terminal in Emergency Control Assembly	NP							
	24 Inspect Terminal in Emergency Control Assembly	NP							
Switch Internal	25 Inspect Terminal in Emergency Control Assembly	NP							
	26 Inspect Terminal in Emergency Control Assembly	NP							
	27 Inspect Terminal in Emergency Control Assembly	NP							
	28 Inspect Terminal in Emergency Control Assembly	NP							
Switch External	29 Inspect Terminal in Emergency Control Assembly	NP							
	30 Inspect Terminal in Emergency Control Assembly	NP							
	31 Inspect Terminal in Emergency Control Assembly	NP							
	32 Inspect Terminal in Emergency Control Assembly	NP							

PX633K-7

0.3
 INF
 INF
 INF

3713 1882

C = COMPLETE
 NA = NOT APPLICABLE
 TSP = TEST PERFORMED

Brake Switch Testing Checklist

MF = MIFITY OPEN
 NF = NOT PERFORMED
 NRDU = NOT RECD AT CER, LAB

		19	20	21	22	23	1	2	3
		PY774298	PY754576	P0873576	77	P0873574	PY838801	PAT838201	F0847885
Field Info	1. Log Book Number Switch Log on						C	C	C
	2. Location						NO FIRELEAK	NO FIRELEAK	NO FIRELEAK
	3. Photograph taken						C	C	C
	4. Record any unusual vehicle or road observations						C	C	C
	5. Police Case Number assigned						C	C	C
	6. Log # if assigned						NA	0	NA
Switch + Connector Assembly	7. Brake Switches and 200VDC/24VDC connections						EA	EA	EA
	8. Wire (4/16) Size Used for Connections						MF	MF	MF
	9. Wire (20/24) Size for Connections						MF	MF	MF
	10. Wire Size for Terminals						C	C	C
Connector Only	11. Quality Quantity, Size						C	C	C
	12. Wire attached over 200VDC/24VDC connections						MF	MF	MF
	13. Check for full engagement of connector						C	C	C
	14. Check wire condition						C	C	C
Switch Installed Unoperated	15. Check wire size						C	C	C
	16. Check wire size per code						C	C	C
	17. Check wire size to check for connector						TSP	TSP	TSP
	18. Check wire size to check for connector						C	C	C
	19. Check wire size to check for connector						EA	EA	EA
	20. Check wire size to check for connector						MF	MF	MF
	21. Check wire size to check for connector						MF	MF	MF
	22. Check wire size to check for connector						EA	EA	EA
Switch Operated Prescribed	23. Check wire size to check for connector						TSP	TSP	TSP
	24. Check wire size to check for connector						EA	EA	EA
	25. Check wire size to check for connector						NO LEAK	NO LEAK	NO LEAK
	26. Check wire size to check for connector						C	C	C
	27. Check wire size to check for connector						MF	EA	MF
Switch	28. Check wire size to check for connector						MF	MF	MF
	29. Check wire size to check for connector						MF	MF	MF
	30. Check wire size to check for connector						MF	MF	MF
	31. Check wire size to check for connector						MF	C	MF
	32. Check wire size to check for connector						MF	C	MF
	33. Check wire size to check for connector						MF	C	MF
	34. Check wire size to check for connector						MF	C	MF
Technique	35. Check wire size to check for connector						MF	C	MF
	36. Check wire size to check for connector						MF	C	MF
	37. Check wire size to check for connector						MF	C	MF
	38. Check wire size to check for connector						MF	C	MF

2712 1853

C = COMPLETE
 NA = NOT APPLICABLE
 TSP = TEST PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NR000 = NOT RECD AT GEN. LAB.

Item No.	Description	A	B	S	7	8	9	10	11
		PX18312	PT61328	NY72405	PT76172	NY735191	PT736185	PX18140	NY75202
1	Lighted Brake Switch Light	C	C	C	C	C	C	C	C
	Operation	NO FIRELEAK	NO FIRELEAK	FIRE	NO FIRELEAK	FIRE	NO FIRELEAK	NO FIRELEAK	NO FIRELEAK
	2 Pedal Stroke	C	C	C	C	C	C	C	C
	3 Pedal Operated Internal Resistance	C	C	C	C	C	C	C	C
4	Check for Corrosion/engraving	C	C	NA	C	NA	C	NA	C
	4a Corrosion/engraving	C	NA	NA	NA	NA	C	NA	NA
	5 Line of Self-cleaning Accessibility Restricted	NP	0.2	NA	NP	NA	2	0.4	NP
	6 Line of Self-cleaning Accessibility Restricted	NP	INF	NA	NP	NA	0.2	INF	NP
7	Accessibility to Regain Position	NP	NP	NA	NP	NA	0.2	NP	NP
	8 Hydraulic Reservoir Level	C	C	NA	C	NA	C	C	C
9	Check Operation	C	C	NA	C	NA	C	C	C
	10 Line of Self-cleaning Accessibility Restricted	NP	C	NA	NP	NA	C	C	C
11	Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
	12 Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
	13 Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
	14 Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
15	Check for Corrosion/engraving	TSP	TSP	NA	TSP	NA	TSP	TSP	TSP
	16 Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
	17 Check for Corrosion/engraving	0.1	0.2	NA	0.3	NA	1.5	0.4	0.1
	18 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
19	Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	20 Check for Corrosion/engraving	NP	100K	NA	200K	NA	0.4	0.4	NP
	21 Check for Corrosion/engraving	0.2	1.5	NA	1.0	NA	1.0	1.0	0.2
	22 Check for Corrosion/engraving	0.2	0.2	NA	0.2	NA	0.2	0.2	0.2
23	Check for Corrosion/engraving	NO LEAK	NO LEAK	NA	NO LEAK	NA	NO LEAK	NO LEAK	NO LEAK
	24 Check for Corrosion/engraving	C	C	NA	C	NA	C	C	C
	25 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.1	NP	NP
	26 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
27	Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	28 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	29 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	30 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
31	Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	32 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	33 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP
	34 Check for Corrosion/engraving	NP	NP	NA	NP	NA	0.2	NP	NP

3713 1824

C = COMPLETE
 NA = NOT APPLICABLE
 TSP = TEST PERFORMED

Brake Switch Testing Checklist

BP = BATTERY (OPEN)
 NP = NOT PERFORMED
 NRCLO = NOT TESTED AT COR. LAB.

Field No.	Description	12	13	QAS1	QAS2	EAA	EAA	EAA	EAA
		PY743808	PY743813	NY738710	PT80828	PT80805	NY73887	NY73891	NY74389
Field No.	1. Up Ped Vehicle Brake Lights	C	C	C	C	D	C	C	C
	2. Pedal Switch	NO FIRELEAK	NO FIRELEAK	BP LEAK	BP LEAK	FIRE	FIRE	FIRE	FIRE
	3. Pedal Switch	C	C	C	C	C	C	NA	TSP
	4. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	5. Switch for Chassis Engagement	C	NA	NA	NA	NA	NA	NA	NA
	6. Switch for Chassis Engagement	0.5	0.2	NA	NA	NA	NA	NA	NA
	7. Switch for Chassis Engagement	0.25M	0.1M	NA	NA	NA	NA	NA	NA
	8. Switch for Chassis Engagement	0.15M	0.05M	NA	NA	NA	NA	NA	NA
Connector Only	9. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
	10. Switch for Chassis Engagement	BP	BP	NA	NA	NA	NA	NA	NA
	11. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
	12. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
Switch (Internal Unoperated)	13. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
	14. Switch for Chassis Engagement	C	C	NA	NA	NA	NA	NA	NA
	15. Switch for Chassis Engagement	TSP	TSP	NA	NA	NA	NA	NA	NA
	16. Switch for Chassis Engagement	C	C	D	C	NA	NA	NA	NA
Switch (Internal Unoperated)	17. Switch for Chassis Engagement	0.2	0.1	>100K	>100K	NA	NA	NA	NA
	18. Switch for Chassis Engagement	0.1M	0.05M	>100K	>100K	NA	NA	NA	NA
	19. Switch for Chassis Engagement	0.05M	0.02M	>100K	>100K	NA	NA	NA	NA
	20. Switch for Chassis Engagement	0.02M	0.01M	BP	BP	NA	NA	NA	NA
Switch (Internal Unoperated)	21. Switch for Chassis Engagement	0.1	0.05	NO SIGNAL	NO SIGNAL	NA	NA	NA	NA
	22. Switch for Chassis Engagement	0.05	0.02	BP	NO SIGNAL	NA	NA	NA	NA
	23. Switch for Chassis Engagement	NO LEAK	NO LEAK	NO LEAK	NO LEAK	NA	NA	NA	NA
	24. Switch for Chassis Engagement	C	C	C	C	NA	NA	NA	NA
Switch (Internal Unoperated)	25. Switch for Chassis Engagement	0.1	0.05	>100K	170K	NA	NA	NA	NA
	26. Switch for Chassis Engagement	0.05	0.02	>100K	>100K	NA	NA	NA	NA
	27. Switch for Chassis Engagement	0.02	0.01	>100K	>100K	NA	NA	NA	NA
	28. Switch for Chassis Engagement	0.01	0.005	BP	BP	NA	NA	NA	NA
Switch (Internal Unoperated)	29. Switch for Chassis Engagement	NO LAB	NP	C	C	C	C	NA	TSP
	30. Switch for Chassis Engagement	NO LAB	NP	C	C	D	D	NA	TSP
	31. Switch for Chassis Engagement	NO LAB	NP	C	C	C	C	NA	TSP
	32. Switch for Chassis Engagement	NO LAB	NP	C	C	C	C	NA	TSP
Technique	33. Switch for Chassis Engagement	NO LAB	NP	TSP	TSP	TSP	TSP	NA	TSP
	34. Switch for Chassis Engagement	NO LAB	NP	TSP	TSP	TSP	TSP	NA	TSP
	35. Switch for Chassis Engagement	NO LAB	NP	NA	NA	NA	NA	NA	TSP
	36. Switch for Chassis Engagement	NO LAB	NP	C	C	C	C	NA	TSP

Data Log Brake Pressure Switch

Log Updated 8/18/2008

Seq #	Site Data Code	Vehicle	VIN	Event	Mileage	Temp-Header Resistance	Leakoff?	Kapton #1	Kapton #2	Kapton #3	Present Status
Managers	2008	Town Car	PY82287	Oil. Fil				crack	crack	crack	Analysis Complete
A	2004	Town Car	PY88884	Underhood Fil				no info	no info	no info	Analysis Complete
B	2114	Town Car	NY748119	Underhood Fil							Oil. not available
C	2008	Town Car	NY788706	Underhood Fil							Analysis In Progress
D		Crown V PCar	VX1-88378	Cruise Inop		4.8MESH	yes	crack	crack	crack	Analysis Complete
E	2157	Town Car	NY788774	Reference		OPEN	no	worn, no crack	worn, no crack	worn, no crack	Analysis Complete
F	2158	Town Car	NY788838	Cruise Inop		4MEGA	yes	crack	crack	crack	Analysis Complete
1	2008	Town Car	NY788888	Reference	70184	OPEN					
2	2015	Town Car	PY728442	Reference	71327	OPEN					
4	2048	Town Car	PY888178	Reference	88857	OPEN					
5	2004	Town Car	py888888	Reference	88848						Analysis In Progress
6	2005	Town Car	py788841	Reference	47325						Analysis In Progress
7	2008	Town Car	NY728828	Reference	88882	OPEN					
8	2005	Town Car	PX188822	Reference	88814	OPEN					
9	2000	Town Car	P888788	Reference	??	OPEN					
10	2004	Town Car	PY888875	Reference	88824	OPEN					
11	2008	Town Car	PY728888	Reference	88888	OPEN					
12	2000	Town Car	PY888870	Reference	88888	OPEN					
13	2000	Town Car	NY748888	Reference	88827	OPEN					
14	2071	Town Car	P2882872	Reference	84148	OPEN					
15	2001	Town Car	PY888874	Reference	??	OPEN					
16	??	Town Car	NY888884	Reference	87188	OPEN					
17	??	Town Car	PY888826	Reference	72114	OPEN					
18	2008	Town Car	PY888878	Reference		OPEN					
19	??	Town Car	PY778888	Reference	87848	OPEN					
20	??	Town Car	PY788875	Reference	48821	OPEN					
21	??	Town Car	P8848818	Reference	48831	OPEN					
22	2074	??	??	Reference	??						
23	??	Town Car	P8888874	Reference	88802	OPEN					
to 2152, John McFarney Group											
1	2008	Town Car	PY888888	Reference							
2	2000	Crown V PCar	PX188888	Reference	88888						
3	2008	Crown Mustang	P8841888	Reference	??						
4	2006	Crown V8	PX188812	Reference	48842						
5	2000	Town Car	PY888888	Reference	73115						
6	??	Town Car	NY788888	Underhood Fil	??						
7	2001	Town Car	PY788878	Reference	??						

Black Network, 313 59 8226,
blacknet@black.com,
file_black_log.xls

page 1 of 2
printed 2/18/08 12:08 PM
uncontrolled document

3713 1667

revised 2/18/08

Data Log
Brake Pressure Switch

Car #	Dr Date Code	Vehicle	VIN	Event	Mileage	Tech-Report	Leak?7	Kapton #1	Kapton #2	Kapton #3	Present Status
8	2085	Team Car	NY782191	Uncontrolled Flip	108810						
9	2086	Team Car	PY789109	Reference	??						
10	2222	Crown Vic	P2161140	Reference	72814						
11	2115	Team Car	NY787408	Reference	??						
12	2085	Team Car	PY742899	Reference	??						
13	2089	Team Car	PY743913	Reference	92814						

Steve Palmer, 303 38 8280,
spalmer@tsc.com,
No Dutchies!

page 2 of 2
printed 2/19/93 12:08 Pjt
uncontrolled download

3713 1858

revised 2/1/93

NGSC

* Note printed by SREINERS on 22 Feb 1999 at 14:01:49 *

From: DPORTER1--VISTEON Date and time 02/22/99 13:45:46
To: SREINERS--FORDMAIL Steve Reimers
cc: FKOHL --FORDMAIL Fred Kohl (E-mail)

From: Porter, David (D.L.)
Subject: RE: Speed Control Report

The failure of part #318 was a functional failure, that is, speed control would not function. The clutch function was OK, but pulley and clutch rotation was locked at the zero throttle position by the (melted) pulley cover. Once the melted pulley cover was removed, the actuator function was normal, although the motor was almost rusted enough to fail to function, due to water entry. Presumably fire extinguisher entered through the partially melted amplifier. Part #318 failed due to water entry, but the clutch was not engaged, and clutch coil resistance was normal. Note that coil resistance is the same whether the clutch is engaged or not.

Dave Porter dporter1@vistecon.com Phone: 313-390-8674 Fax
313-322-3529

> -----Original Message-----

> From: Steve Reimers SMTP:sreiners@fw.ford.com
> Sent: Monday, February 22, 1999 12:42 PM
> To: dporter1@vistecon.com
> Subject: Speed Control Report

> Thanks for the quick response. Did any of the FAILED units have a clutch
> stuck
> in the energized state? What does FAIL mean for this test?
> thanks,

> Steve Reimers building 5 1C043
> AVT Chassis E/E System Applications mail drop 8011
> 39-03286 SREINERS sreiners@ford.com fax 39-03286 ;>

* Note printed by SREINERS on 17 Feb 1999 at 09:55:50 *

From: SLAROUCH--FORDMAIL Date and time 02/17/99 09:51:51
To: SREINERS--FORDMAIL Reimers, Steve (S.)

From: LaRouche, Steve (S.)
Subject: RE: (U)

We detected the same elements in the corrosion products in switch F as in the other switches. Right now, our best guess is that a cell has been set up between the contacts and the steel cup, with the brake fluid and possible contamination (source unknown) acting as the electrolyte. I gave Norm and Fred a spreadsheet summarizing our findings to date at the last meeting, but I don't think they have distributed it yet.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers mailto:sreimers@gw.ford.com
Sent: Wednesday, February 17, 1999 9:45 AM
To: slarouch@mail.ford.com
Subject: RE: (U)

What caused the corrosion?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREINERS sreimers@ford.com fax 39-03286 ;>
*** Forwarding note from SLAROUCH--FORDMAIL 02/17/99 08:18 ***
To: SREINERS--FORDMAIL Reimers, Steve (S.)

From: LaRouche, Steve (S.)
Subject: RE: (U)

Steve: The switch in question is switch F. The copper-beryllium arm of the movable contact separated from the brass base. Now that we have had a chance to look at it in closer detail, it appears that the arm separated due to a loss of material thickness from corrosion. We have also found evidence of stress corrosion cracking in the stationary contact. We did not see any evidence of heat or arc damage in this switch. It looked like the arm separated, fell away, and stuck to the wall of the switch cavity.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers mailto:sreimers@gw.ford.com
Sent: Tuesday, February 16, 1999 6:13 PM
To: jname@gw.ford.com; nlapoint@gw.ford.com; rnevi@gw.ford.com;
slarouch@mail.ford.com; Aziz Rahman, Texas
Subject: (U)

Can you help me get smart regarding the "LOOSE METAL PART" mentioned above?

Steve Rainers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREINERS sreiners@ford.com fax 39-03286 ;>
*** Forwarding note from SCOLE1 --DREN005 02/16/99 18:04 ***
To: SREINERS--DREN007
cc: DGOEL --DREN005

From: Sam L. Cole USAET(UTC -05:00)
Subject: (U)
THE PREVIOUS CONCERN OF THE "LOOSE METAL PART" WAS MENTIONED IN THE LAST MEETING WITH JACK. HE WILL WANT A FOLLOW UP ON THIS AT THIS FRIDAY'S MEETING. PLEASE GET UP TO SPEED ON THE HISTORY OF THIS CONCERN. IF IT TURNS OUT THAT THIS MAY BE A CAUSE, THEN WE WILL NEED TO KNOW WHEN THE ISSUE WAS IN THE FIELD, WHEN IT WAS FIXED AND HOW MANY ARE OUT THERE TO BE CONCERNED ABOUT. THANKS.

Thank You,
Sam
Ext. 21959
BLDG. 2, 22J31 - MD# 1320 - SCOLE1@FORD.COM
*** Forwarding note from SREINERS--DREN007 02/16/99 16:52 ***
To: SCOLE1 --DREN005 DGOEL --DREN005

FROM: Steve Rainers USAET(UTC -05:00)
Subject: (U)
I have the part to show and a take-apart version too. I am not familiar with the previous problem but a loose metal part in the switch cavity is definitely a potential cause of this concern.

Steve Rainers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREINERS sreiners@ford.com fax 39-03286 ;>
*** Forwarding note from DB7AWAYR--DREN007 02/16/99 13:41 ***
Subject: ANAY Facility/VM messages
This note was generated by the ANAY Facility/VM 5799-FLP (c)IBM Corp.
DO NOT REPLY TO THIS NOTE

ANA1101 This mail item is being routed to you from SCOLE1 at DREN005 on behalf of FPORTER at DREN007.

To: FPORTER --DREN007
cc: TMASTERS--DREN005 TDOMOVAN--DREN005
DGOEL --DREN005

From: Sam L. Cole USAET(UTC -05:00)
Subject: (U)
I UNDERSTAND THAT THERE WILL BE A FOLLOW UP MEETING WITH JACK PASKUS THIS FRIDAY ON THE TOWN CAR INVESTIGATION. I MET WITH JACK TODAY FOR A 1 ON 1, AND HE REQUESTED SOME SPECIFIC INFO. AT FRIDAY'S MEETING, PLEASE BRING A SAMPLE SWITCH TO SHOW JACK.

ALSO, HE IS INTERESTED IN KNOWING OUR PROGRESS AND INVESTIGATING IF THE PREVIOUS PROBLEM WITH THE INTERNAL COMPONENTS BREAKING LOOSE IS A POTENTIAL CAUSE OF THIS CONCERN. PLEASE BE PREPARED TO DISCUSS THIS ON FRIDAY. THANKS.

Thank You,
S&S
Ext. 21959
BLDG. 2, 22J31 - ND# 1220_- SCOLE1@FORD.COM

3713 1863