

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 17 OF 61

PART 3 OF 4

P

3713 2101

- [Action](#) • [Comment History](#) • [Process Details](#) • [Process Status](#)
- [Back to Agenda](#)

OASIS Technical Message Request**Instructions**[Top](#)

1. Fields marked with * are required.

OASIS Message Request[Top](#)

Title: 1992-93 Town Car - Brake Pressure Switch
Activity Code: 00 Miscellaneous
QSF/Non-QSF Status: non-QSF_item_generated
Tracking Number: 97-0255
Does this request supersede an active SSM? No
SSM to supersede:
Are Parts required? No
Message Type: Final
Model Year(s): 1992, 1993
Vehicle Line(s): Town Car
Build Dates: from: 01-Nov-1991 to: 01-Nov-1993
Engine(s):
Calibration(s):
Transmission(s):
Broadcast Message: Yes
SSM Distribution: NA: United States
OASIS Service Codes: 203000 301000 607600
Repair Verification:

none

Original Text: (Author: *scottmrs*)

OASIS Modified Text: (Author: *ldallane*)

ASO Modified Text: (Author: *guy*)

OGC Modified Text: (Author:)

PSL Modified Text: (Author: *gunkert*)

VEE Modified Text: (Author: *machlog*)

Final Version of Text (Author: *nooshell*)

When replacing a Speed Control Deactivation switch on a 1992-93 Town Car (-9F914- Brake Pressure Switch on the Brake Proportioning valve) or the switch electrical harness, tag the removed part and return to Ford Motor Company for analysis. Please include VIN #, mileage, dealer code, and reason removed on the tag. Ship to:

Ford Motor Company
Central Laboratory
15000 Century Drive
Commerce Park North
Dearborn, MI 48120
Attn: DEPT. T118

SSM Number:

12492

Transaction Information

Top

Comments:



* Action:

-- Select Action --



Submit

Comment History[Top](#)

mrvanhall on 24-Feb-1999 10:15:55:

Workflow Name: SSM OASIS2 IMS, Action Taken: Final/Complete (summary sent to: techbot@ford.com, sreimers@ford.com, ldallape@ford.com):
THIS SSM IS NOW ACTIVE.

mrvanhall on 24-Feb-1999 09:27:35:

Workflow Name: SSM OASIS2 Review, Action Taken: Final/Enter into Global Oasis:
(no comment)

dyu on 23-Feb-1999 15:38:31:

Workflow Name: SSM Approval ASO, Action Taken: Approve and submit to OASIS:
last time: no notes; use dept no.;
mschlott on 23-Feb-1999 14:26:58:

Workflow Name: SSM Approval VEE, Action Taken: Approve and submit to OASIS:
(no comment)

dplinkert on 23-Feb-1999 13:27:24:

Workflow Name: SSM Approval PSL, Action Taken: Approve and submit to OASIS:
Ok to publish - parts not required

ldallape on 23-Feb-1999 13:22:57:

Workflow Name: SSM OASIS1 Review, Action Taken: Accept/Submit to Approving Activities (summary sent to: sreimers@ford.com, mrvanhall@ford.com, msaylor3@ford.com, ldallape@ford.com):
Please expedite.

sreimers on 23-Feb-1999 12:58:40:

Workflow Name: SSM Preparation, Action Taken: Submit to OASIS (summary sent to: fporter@ford.com, joetee@ford.com, maevi@ford.com, jbradley@ford.com, tmasters@ford.com, sreimers@ford.com, fporter@ford.com, nlspoint@ford.com, starouch@ford.com, wstramcz@ford.com, lbrown@ford.com, dgoet@ford.com, bweilfer3@ford.com, jlogal@ford.com):
(no comment)

sreimers on 23-Feb-1999 12:12:30:

Workflow Name: FCSD Onsite SSM, Action Taken: Save for later:
The text was approved by Ray Novi (ASO), Jay Logal (OGC), Joe Bradley (FCSD), Tom Masters (AVT).

Process Details[Top](#)

Instance Name:	97-0255 1992-93 Town Car - Brake Pressure Switch	Current User:	sreimers
Business Process:		Customer:	sreimers
Tracking Number:	97-0255	Performer:	ldallape
Title:	1992-93 Town Car - Brake Pressure Switch	Author:	sreimers
Activity Code:	00 Miscellaneous	Author Supervisor:	fporter
Workflow:	SSM OASIS1 Review	Respond By:	No time
Status:	Closed/satisfied	Complete By:	No time

Copyright © 1999 Ford Motor Co. All rights reserved.

Vehicle/Customer Information

Model Year: Make: VIN#: Mileage:
Build Date: Present Vehicle Location: Who owns vehicle now:
Customer Name: Phone: Is it ok for engineering to contact customer:

Incident Info/Vehicle History

Where did fire originate? (engine compartment quadrant, suspect location, or suspect component(s))

What was the vehicle circumstances when the fire was noticed? Was the vehicle running, parked, engine on/off... if off, how long?

Did customer notice anything unusual prior to fire? (specifically... difficulty getting the vehicle out of park, speed control not working, brake warning lamp illuminated, stop lamp inoperative)

Do any underhood relays show evidence of overheating?

Were the underhood fuse links blown?

Were there any fuses that were blown or show evidence of other damage?

Is the correct fuse for the stop lamp switch in the fuse box?

Was there any damage to any wiring in the area where the fire was suspected to start?

Does the air suspension pump show evidence of overheating?

Was there any aftermarket modifications to the vehicle? (specifically car alarm, trailer tow, or remote start)

Was the vehicle involved in a natural disaster/accident that required significant vehicle clean up? If so where was cleanup performed?

What was vehicle repair history?

Parts that we would like from vehicle if possible to provide

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 3 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay, solenoids, module service switch,

Other suspect parts

ECU, Switch

Vehicle/Customer Information

Model Year: Make: VIN#: Mileage:
Build Date: Present Vehicle Location: Who owns vehicle now:
Customer Name: Phone: Is it ok for engineering to contact customer:

Incident Info

Where did fire originate? (engine compartment, quadram, suspect location, or suspect component(s))

What was the vehicle circumstances when the fire was noticed? Was the vehicle running, parked, engine on/off...
If off, how long?

Did customer notice anything unusual prior to fire? (specifically... difficulty getting the vehicle out of park, speed
control not working, brake warning lamp illuminated, stop lamp inoperative)

Do any underhood relays show evidence of overheating?

Were the underhood fuse links blown?

Were there any fuses that were blown or show evidence of other damage?

Was there any damage to any wiring in the area where the fire was suspected to start?

Does the air suspension pump show evidence of overheating?

Is there any evidence of aftermarket component installation? (specifically car alarm or remote start)

Parts that we would like from vehicle if possible to acquire

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS # module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

Which vehicles to look at

Any new incident of 1992-1995 Towacar, Crown Victoria, or Grand Marquis alleged to have an underhood fire

Specific prior incidents... vinn will be provided by ASO forwarded



3713 2108

Prevent corrosion leak paths from starting a fire

3/11/99

Objects

St. Terminal

Sp. "


Cup

Pin


Disc

Fluid

Kapton




Prob.
of
Fire




Seal deterioration, Amount of current, Length of path from term. to ground

Ray's
defect



Prob
of
Fail



Prob
of
Fail



Uniqueness

There is always V on terminal
Small or very ^{large} current is OK


Major prob. is with system off
Brake fluid burn

Plus.

Drains

Dristail

1.)



- 2.) Ground fault interrupter
- 3.) Reverse polarity of terminals
- 4.) Turn upside down so fluids ~~run~~ away from ground & objects fall away from ground.
- 5.) Plastic diaphragm b/w. pin & spring arm (close off switch cavity)
- 6.) Coat all of terminals with plastic except for contacts
- 7.) Put switch after coil
- 8.) O-ring sliding seal
- 9.) Thermal fuse in circuit that melts below ign. temp. & plastic
- 10.) Fill most left of cavity with gel

? Dow ~ Corrosive to brake tubing 3/11/99

GFI type device/

Ranking

Leak fix 2nd

Desc 3rd

Fire Starter 1st

- Fill Switch Cavity below rivet
- Prevent Corrosion leak paths from Starting a fire
- Fuse integrated in terminals (a circuit interrupter)
- Cup of non-conducting Mat?
- Cup coated with non-conducting
- Non-Flexing Seal
- Sudden change from Hi Insulation Resistance to low to force fuse to blow before fire can start. Neg (TC Device?)
- Thermal Breaker(?)
- Plastic Insulator/Seal above Spring arm and transfer pin
- Coat electrical parts with plastic
- Put switch between coil & ground
- Change surface of flexing area to distribute stress (?)

If Military/Aerospace specified devices are required, please contact the National Semiconductor Sales Office/Distributors for availability and specifications.

Supply Current	18 mA
Power Dissipation (Note 1)	1200 mW
Operating Temperature Range	-40°C to +70°C
Storage Temperature Range	-55°C to +125°C

Background

Double-Line Packings (30 mm.)	200°C
Small O-Ring Packings	
Vapor Phase (30 sec.)	210°C
Immersed (15 sec.)	200°C

See AIA-400 "Surface Blasting and Their Effects on Product Reliability" for other methods of reducing surface stress corrosion.

DC Electrical Characteristics $T_A = 25^\circ\text{C}$, $I_{BQ} = 0\text{ mA}$

Parameter	Conditions	Min	Typ	Max	Units
Power Supply Shield Regulator Voltage	Pin 8, Average Value	20	20	20	V
Leakage Trigger Voltage	Pin 7	15	17.5	20	V
Sensitivity Set Voltage	Pin 8 to Pin 9	6	7	8.5	V
Output Drive Current	Pin 1, With Load	0.5	1	2.4	mA
Output Saturation Voltage	Pin 1, Without Load		100	200	mV
Output Saturation Resistance	Pin 1, Without Load		100		Ω
Output External Current Sinking Capability	Pin 1, Without Load, V_{EE} Held to 0.5V (Note 4)	0.5	6		mA
Noise Integration Sink Current Ratio	Pin 7, Ratio of Discharge Currents Between No Load and Peak Conditions	0.0	0.0	0.0	$\mu A/\mu A$

AC Electrical Characteristics $T_A = 25^\circ\text{C}$, $I_{\text{BQ}} = 0\text{ mA}$

Parameter	Condition	Wye	Type	Item	Units
Normal Fault Current Sensitivity	Figure 1 (Note 3)	3	3	7	mA
Normal Fault Trip Time	500N Fault, Figure 2 (Note 2)		15		ms
Normal Fault with Grounded Neutral Fault Trip Time	500N Normal Fault, 50N Neutral, Figure 2 (Note 2)		15		ms

Maint 10°F for operation in ambient temperatures above 35°F. See dealer manual for detailed listing of a 35°F maximum jacket temperature and a thermal resistance of 35°C/W (2000°F in for 1000°F out) for the RS Package.

Notes in Amount of 10 Yrds.

Made in Thailand U.S. customs clearance is not required. U.S. customs clearance is not required.

Make It This *seminars are held at the offices of the National "Make It This" Center.*





FIGURE 1. Standard Push-Brooming Test Circuit


Internal Schematic Diagram



TL40177-2

Typical Performance Characteristics

Temperature: 25°C



TL06077-4

Circuit Description

(Refer to Block and Connection Diagram)

The LM2601 operates from 50V as set by an internal short regulator, Q3. In the absence of a fault ($I_L = 0$) the feedback path drives signal (V_B) to correspondingly zero. Under these conditions the capacitor discharge current, I_{D1} , also correspondingly at three times its threshold value, I_{TH} , so that noise induced charge on the timing capacitor will be rapidly removed. When a fault current, I_L , is induced in the secondary of the external power transformer, the operational amplifier, A1, mass feedback to force a virtual ground at the input on it

output I_L . The presence of I_L during either half-cycle will cause V_B to go high, which in turn charges I_L from I_{TH} to I_{TL} . Although I_{TL} discharges the timing capacitor during both half-cycles of the line, I_L only charges the capacitor during the half-cycle in which I_L enters pin 2. Thus during one half-cycle I_L charges the timing capacitor, while during the other half-cycle I_{TL} discharges it. When the capacitor voltage reaches 17.5V, the latch engages and turns off Q3 permitting I_L to drive the gate of an SCR.

Application Circuits

A typical general fault interrupter circuit is shown in Figure 2. It is designed to operate on 120 V_{AC} line voltage with 8 mA normal fault sensitivity.

A full-wave rectifier bridge and a 1000/25W resistor are used to supply the DC power required by the IC. A 1 μ F capacitor at pin 8 used to filter the ripple of the supply voltage and is also connected across the ICPI to allow ringing of the ICPI on either half-cycle. When a fault causes the ICPI to stop, the circuit breaker is engaged and line voltage is removed from the load. At this time no fault current flows and the IC discharge current increases from I_{TH} to I_{TR} (see Circuit Description and Block Diagram). This quickly resets both the timing capacitor and the output latch. At this time the circuit breaker can be reset and the line voltage again supplied to the load, assuming the fault has been removed. A 1000:1 current transformer is used to detect the normal fault. The fault current, which is basically the difference current between the hot and neutral lines, is stepped down by 1000 and fed into the input pin of the operational amplifier through a 10 μ F capacitor. The 0.001 μ F capacitor between pin 8 and pin 3 and the 100 pF between pins 3 and 4 are added to obtain better noise immunity. The normal fault sensitivity is determined by the timing capacitor discharging current, I_{TH} . I_{TH} can be calculated by:

$$I_{TH} = \frac{TV}{R_{FET}} \rightarrow 8 \quad (1)$$

At the decision point, the average fault current just equals the threshold current, I_{TH} .

$$I_{TH} = \frac{I_{FET}}{2} \times 0.91 \quad (2)$$

where I_{FET} is the avg input fault current to the operational amp and the factor of 2 is due to the fact that I_{FET} charges the timing capacitor only during one half-cycle, while I_{TH} discharges the capacitor continuously. The factor 0.91 converts the rms value to an average value. Combining equations (1) and (2) we have

$$R_{FET} = \frac{TV}{I_{FET} \times 0.91} \quad (3)$$

For example, to obtain 8 mA (rms) sensitivity for the circuit in Figure 2 we have


$$R_{FET} = \frac{TV}{8 \text{ mA} \times 0.91} = 1.66 \text{ k}\Omega \quad (4)$$

The correct value for R_{FET} can also be determined from the characteristic curve that plots equation (3). Note that this is an approximate calculation; the exact value of R_{FET} depends on the specific current transformer used and UL1001 tolerances. Interim as UL548 specifies a sensitivity "window" of 4 mA–8 mA, provision should be made to adjust R_{FET} on a pre-preset basis.

Independent of setting sensitivity, the desired integration time can be obtained through proper selection of the timing capacitor, C_T . Due to the large number of variables involved, proper selection of C_T is best done empirically. The following design example, then, should only be used as a guideline.

Assume the goal is to meet UL548 timing requirements. Also assume that worst case timing occurs during QPI

start-up (QPI closed) with both a heavy normal fault and a QPI grounded-neutral present. This situation is shown schematically below.



UL548 specifies 120 ms average trip time under these conditions. Calculation of C_T based upon charging current due to normal fault only is as follows:

UL548 Specification

- 3 ms QPI has-on time (10k and 1 μ F)
- 3 ms Potential loss of one half-cycle due to fault current cause of half-cycle only
- 4 ms Time required to open a sluggish circuit breaker
- 200 ms Maximum integration time that could be allowed
- 8 ms Value of integration time that encompasses current transformer and other variables

$$C_T = \frac{I \times T}{V} \quad (5)$$

where T = integration time

V = threshold voltage

I = average fault current into C_T

$$I = \left(\frac{120 \text{ V}_{AC} \text{ rms}}{R_F} \right) \times \left(\frac{R_F}{R_F + R_{LN}} \right) \quad (6)$$

heavy fault current generated (average I_{FET}) portion of fault current shunted around QPI

$$\times \left(\frac{1 \text{ rms}}{1000 \text{ turns}} \right) \times \left(\frac{1}{2} \right) \times (0.91) \quad (7)$$

current division of input across transformer C_T charging on half-cycle only rms to average conversion

Therefore:

$$C_T = \frac{\left[\left(\frac{120}{1000} \right) \times \left(\frac{1}{1000} \right) \times \left(\frac{1}{2} \right) \times (0.91) \right] \times 0.0008}{1000} = 0.01 \mu\text{F} \quad (7)$$

Application Circuits (Continued)

In practice, the actual value of $C1$ will have to be modified to include the effects of the neutral loop upon the net charging current. The effect of neutral loop inductance currents is difficult to quantify, but typically they come with several fault currents, thus allowing a larger value of $C1$.

For UL843 requirements, 0.015 μF has been found to be the best compromise between sizing and rating.

For those GFL standards not requiring grounded neutral detection, a still larger value capacitor can be used and better noise immunity obtained. This larger capacitor can be accommodated because R_{N1} and R_{N2} are not present, allowing the full fault current, I , to enter the GFL.

In Figure 2, grounded neutral detection is accomplished by loading the neutral rail with 100 Hz energy continuously and allowing some of the energy to couple into the sense transformer during conditions of neutral fault.

Typical Application




FIGURE 2. 120 Hz Neutral Transformer Approach

Definition of Terms


Normal Fault An unintentional electrical path, R_{NF} , between the load terminal of the hot line and the ground, as shown by the dashed line.



Normal Fault plus Grounded Neutral Fault The combination of the normal fault and the grounded neutral fault, as shown by the dashed lines.




Grounded Neutral Fault An unintentional electrical path between the load terminal of the neutral line and the ground, as shown by the dashed line.



7.00007-4

LM1051 Ground Fault Interrupter

Physical Dimensions: inches indicated



LIVE SUPPORT POLICY

NATIONAL'S PRODUCTS ARE NOT AUTHORIZED FOR USE AS CRITICAL COMPONENTS IN LIFE SUPPORT DEVICES OR SYSTEMS WITHOUT THE EXPRESS WRITTEN APPROVAL OF THE PRESIDENT OF NATIONAL SEMICONDUCTOR CORPORATION. As used herein:

1. The support device or system is a device or system which, (a) is intended for constant contact with the body, or (b) support or sustain life, and whose failure to perform, when properly used in accordance with instructions for use provided in the labeling, can be reasonably expected to result in a significant injury to the user.
2. A critical component in any component of a life support device or system whose failure to perform can be reasonably expected to cause the failure of the life support device or system, or to affect its safety or effectiveness.

2. A critical component is any component of a life support device or system whose failure to perform could be reasonably expected to compromise the ability of the life support device or system, or to affect its safety or effectiveness.

**2 National Environmental
Services
1114 Ridge Road, Forest
Spring, MD 21050
Tel: (301) 424-9600
Fax: (301) 727-3723**

THE

[illegible]

2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	2403	2404	2405	2406	2407	2408</
------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	--------



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

ODI RESUME

INVESTIGATION: EA99-006
SUBJECT: Under Hood Fires
PROMPTED BY: PE98-055
PRINCIPAL INVESTIGATOR: John Abbott

DATE OPENED: 11-MAR-99

MANUFACTURER: Ford Motor Co. (Ford)
MODELS: Lincoln Town Car
MODEL YEARS: 1992 and 1993
POPULATION: 222,500

PROBLEM DESCRIPTION: Engine compartment fires on the driver's side in the area of the left front wheel well and the brake master cylinder.

FAILURE REPORT SUMMARY

	ODI	MANUFACTURER	TOTAL
COMPLAINTS:	47	64	111
CRASHES:	0	0	0
INI CRASHES:	0	0	0
# INJURIES:	0	0	0
FAT CRASHES:	0	0	0
# FATALS:	0	0	0
OTHER:	7	13	20

DESCRIPTION OF OTHER: 20 of the reports indicate some level of fire damage to the vehicle owner's carport, garage or home.

ACTION: Open Engineering Analysis

INVESTIGATOR: *[Signature]*

DIV CH: *[Signature]*

OFC DIR: *[Signature]*

3/6/99

3/11/99

3/11/99

DATE

DATE

DATE

SUMMARY: The Office of Defects Investigation has received 47 reports indicating the vehicles caught on fire while parked and the engines not running. The reports that contain specific information generally indicate the area of fire origin to be on the driver's side in an area between the left front wheel and the brake master cylinder (see photograph on page 2). In the PE response, Ford provided 64 additional reports that could be relevant to this investigation.

This investigation has been upgraded for further study


(CONTINUED)

3/15/99

PAGE 07

TOTAL PAGE 02

3713 2123



Ford Motor Company
Environmental and
Safety Engineering

330 Town Center Drive
Dearborn, Michigan 48126

3M EMT™ 9165 TRANSMISSION
TELEPHONE: (313) 594-2266

AUTOMOTIVE SAFETY OFFICE
PRODUCTION VEHICLE SAFETY
AND COMPLIANCE
FAIRLANE PLAZA SOUTH, Suite 800
DEARBORN, MI 48126

DATE: 99-MAR-15

TIME: 9:45 AM

Please deliver to:

JOE NEME
FRED PORTER

Name: TOM MASTERS

Organization: _____

Room # and Building: _____

Telephone: _____

FAX: _____

06002
04145
77158

Number of Sheets being Transmitted (including this one): 1

Special Instructions/Notes:

PE98-055 HAS BEEN UPGRADED TO AN
ENGINEERING ANALYSIS EA99-006

Transmission sent by (Name/Telephone):


WILLIAM M. ABRAMCZYK
x 23284

3713 2125

DOES CONTROL LINE NEED
PULL-UP?

DOES OUTPUT SHUT-OFF IF
GROUND IS DISCONNECTED?

DOES IT REQUIRE HEATSINK FOR
CONTINUOUS OPERATION?



DOES NOT DETECT GROUND SHORT,
MALFUNCTIONS FOR LEAKAGE > Ω
FUNCTIONS FOR LEAKAGE ACROSS
TERMINALS > Ω

FUNCTIONS WITH CONTACT RESISTANCE
< Ω

LIMITS BP SWITCH CURRENT
TO _____ MA

New Parts:

SSR

HARNESS

SSR CONNECTOR

BPS

TERMINALS - 8

GROUND LUG - 1

GROUND SCREW

TWO WAY CONNECTOR

SHIELD

1 AMP IN-LINE FUSE

TWO WAY MATE

SSR SCREWS

HARNESS TIE DOWNS

John Hayden
79577 memo
Iso Relays


Talbot
Tawanda Allen
51680

SSR
Bill Gardner
25876
26023



16a2

DOES NOT DETECT GROUND SHORTS.



New Parts

EL/Mech Relay

HARNESS

RELAY CONNECTOR

BP CONNECTOR

GROUND LUG

IN-LINE FUSE

TWO WAY

TERMINALS X 8

WIRE

SHIELD

Two way mate

SCREWS x 2

TIZ DOWNS

3/19/99

3713 2129

ALWAYS USE 901-22
 ALWAYS USE 201-22
 ALWAYS USE 101-22



3/19/99

RELAY

SWITCH Requirements

MUST

- Operate in underhood environment
- Operate continuous (Normally energized when battery is connected, turns off when brake is applied.)
- Low control current draw ($< 10 \text{ mA?}$)
- Operate on Battery voltage
- ONE Normal-Open Circuit
- Switch Battery Voltage to Inductive load.
typ: 0.5 amps 0.8 amps @ -40°
inductance 5.3-112 mH
flyback clamped thru 82 ohms

WANT

- Opens circuit when $\geq 1 \text{ amp}$.
- ~~Control current $< 5 \text{ mA}$~~
- FORD QUALIFIED part
- Stand-alone mount
- AVAILABLE IN LARGE QUANTITIES
(500K ~~in~~ in 30 days)

$$E < \left[\frac{B}{A} - \left(1 + \frac{1}{k} \right) \right] R$$

$$R_L = 1200$$

$$R_{10} = 120$$

$$k = 10 \text{ for } \frac{R}{10}$$

RECEIVED
FEB 21 1999



V_t	R_c	R_p	R_1	R_g	V_g	B_+
4	3.3mA	2882	OPEN	OPEN	0	14
4	"	OPEN	2882	"	0	}
4	"	OPEN	OPEN	2882	0	
4	3.3mA	OPEN	5762	5762	0	
4	3.3mA	0	OPEN	OPEN	2882	0
4	3.3mA	0	"	"	↓	9.6V
*12.7	10.5	.01	10M	10M	1	0
4	3.3					4.4
2	1.7mA	7100				14
2		.01	7100			
2		.01	14100	14100		
2			10M	10M	1	11.8V

3/20/99


~~3/20/99~~

Conclusions

$R_L = 1200 \quad R_{10} = 120$

When the contacts are closed.

The switch will appear open when



V_T	B	V_g	$R_{ct} R_g$
4	14	0	> 2882
4	14	2	> 2280
4	14	-2	> 3481
4	16	0	> 3481
4	12	0	> 2280
@ $V_T = 2$	12	0	> 5886
@ $V_T = 6$	12	0	> 1079
6	12	2	> 679
2	16	-2	> 9497
2	14	2	> 5886
2	14	0	> 7089
2	16	0	> 8293

$R_C + R_a$ will exceed these when an open switch contact opens or an open circuit fault occurs or contact corrosion becomes severe.

3/20/99

Conclusion (could) $R_L = 1200$ $R_{T0} = 120$

Switch will appear closed when $R_L = 1200$ $R_{T0} = 120$ and switch contacts are open and

V_T B V_g $R_1 // (R_p + R_2 // R_g)$ Leak
4 14 0 < 2882 > 3.3 mA

4 14 2 < 2280

4 14 -2 < 3480

4 16 0 < 3480

4 12 0 < 2280

2 12 0 < 5886 > 1.7 mA

6 12 0 < 1079 > 5 mA

6 12 2 < 679 "

2 14 2 < 5886 > 1.7 mA

$R_1 // (R_p + R_2 // R_g)$ will go less than these values when a short to ground occurs at R_1 or corrosion/contaminants inside the switch cause R_p to decrease.

3/20/99

To decrease sensitivity to

Desire switch to function for ~~as~~ as long as possible & not burn.

When malfunctioning, ~~it~~ ^{should} cause an obvious symptom (not smoke).
(ie. Speed control in op.)
= SWITCH OPEN

If ~~any~~ leak path is occurring switch function will be ok down to ~~6000~~ 6000Ω but may be ok down to 600Ω .
Below 6000 switch may not open when desired without warning.

If corrosion increases the R_c to above 600Ω the speed control may not function.
Above 9500Ω SC will not function.

3/20/99

MAR 19 '68 09:30 AM

CRF Requires 5 Connections

Includes SMA Wet Castnet 70 SW



P. 22/22

ALAN GALE



WE1.1.1 voltage reference is supplied by Cherry Semiconductor.

Microfilm Corporation
30 Fairbanks
Irwin, CA 92718
714-778-3222

Page Five

Break Switch System Control
File #97-2-Breaking of SCS
by Gary A. Furr


Revision: _____ March 22, 1900 Page: 1 of 1

3713 2139



22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS


Speed Control ^{2nd Act} Desc USING ABS Pedal Position Switch Signal



	<u>V_{OUT}</u>
Pedal Released	B+
PEDAL PRESSED	OPEN CKT
15 AMP OPEN	OPEN

3/24/99

ABS



42-4 Anti-Lock Brake System, With Or Without Traction Assist

37132141


ABS pedal position

Signal is ~~not~~ square wave
at 72 Hz.

CANNOT ROUTE CLUTCH CURRENT THRU THIS SW.
COULD USE SIGNAL FROM CLUTCH POSITION

72 Hz
PULS


31-2 Speed Control



2 How The Circuit Works

3713 2142

42-1 Anti-Lock Brake System, With Or Without Traction Assist



➔ Component

➔ Connector

➔ Ground

➔ Splice

➔ Page



ENGINEERING SPECIFICATION

II. PRODUCTION VALIDATION AND IN-PROCESS TEST (continued)

3. Connector Performance Characterization and Functional Requirements

The following requirements shall be met by a random sample of 12 switches at a temperature of $27 \pm 3^\circ \text{C}$ ($80 \pm 10^\circ \text{F}$) and a square wave input voltage with a peak of 11.5 ± 0.3 volts and a frequency of 72 Hz, unless otherwise specified.

1. Electrical Requirements

- a. Current: The switch contacts must accommodate a resistive load of 5.0 milliamperes at 5.2 volts D.C.
- b. Millivolt Drop: The voltage drop across the closed contacts shall not exceed 100 millivolts at a rated load of 5.0 milliamperes at 11.5 volts D.C. initially, during and after durability tests. (This measurement to be taken at the wire harness connector terminals).
- c. Open Circuit Resistance: The switch contacts when open shall provide a minimum open circuit resistance of 1.0 megohms.
- d. Calibration: The switch shall change status from closed circuit to open circuit and from open circuit to closed circuit within the print specified range before, during and after durability.

2. Mechanical Requirements

- a. Operating Force: The force required to operate the switch actuating rod through its complete stroke (as defined on the released drawing) shall not exceed 350 grams at any point during the stroke.
- b. Wire Retention: The switch wire harness (two wires) shall withstand a pull force of 110 Newtons (24.2 lbs.) in a direction parallel to the harness exit from the switch housing without wire movement with respect to the housing. Each terminal shall also withstand an axial pull test relative to the wire of 110 Newton (24.2 lbs.) without terminal movement on the wire.
- c. Adjustment: The breakaway force required to adjust the hook on the plunger shall be between 17.8 and 66.7 Newtons (4.0 and 15.0 lbs.). The adjusted hook shall retain its initial setting throughout the entire durability cycle test. The adjustment locknut shall withstand 72.0 Newtons (16.2 lbs.) axial pull force without releasing or breaking and must be capable of relocking with the application of 17.8 to 71.0 Newtons (4.0 to 16.0 lbs.) axial push force.
- d. Hook Mounting: The switch hook shall require no more than 44.0 Newtons (9.9 lbs.) force to engage a 6.43/6.38 mm (.254/.249 inch) diameter shaft. The hook shall require a minimum of 11.5 Newtons (2.59 lbs.) force (applied to the hook, not the lift tab) to disengage the hook from the shaft.

CHARACTERISTICS MARKED  ARE FOR INSPECTION AND THE REPORTING DATA. SEE THE CONTROL PLAN

C2

abs. sw

7

DET 22 3247-22

GP

3713 2144

NUMBER
ES-POM-22308-22

REVISED C2

26
OF
FRAME

LOCKOUT

ENGINEERING SPECIFICATION

PART NAME
SPECIFICATION - 28. ASST-MAINE AMT/LX FINAL POSITION NUMBER

PART NUMBER
28-Y003-1C309-AB

LET.	B1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1	L1	M1	N1	O1	P1	Q1	R1	S1	T1	U1	V1	W1	X1	Y1	Z1
PR.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18								
LET.	B1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1	L1	M1	N1	O1	P1	Q1	R1	S1	T1	U1	V1	W1	X1	Y1	Z1
PR.	19	20	21	22	23	24	25	26	27																	

DATE	LET.	PR.	REVISIONS	DR.	CL.	REFERENCE
11/10/77	B1	24	REMOVED FRAME 24			REMOVED FRAME 24
11/10/77	B1	25	REMOVED FRAME 25			REMOVED FRAME 25
11/10/77	B1	26	REMOVED FRAME 26			REMOVED FRAME 26
11/10/77	B1	27	REMOVED FRAME 27			REMOVED FRAME 27
11/10/77	B1	28	REMOVED FRAME 28			REMOVED FRAME 28
11/10/77	B1	29	REMOVED FRAME 29			REMOVED FRAME 29
11/10/77	B1	30	REMOVED FRAME 30			REMOVED FRAME 30
11/10/77	B1	31	REMOVED FRAME 31			REMOVED FRAME 31
11/10/77	B1	32	REMOVED FRAME 32			REMOVED FRAME 32
11/10/77	B1	33	REMOVED FRAME 33			REMOVED FRAME 33
11/10/77	B1	34	REMOVED FRAME 34			REMOVED FRAME 34
11/10/77	B1	35	REMOVED FRAME 35			REMOVED FRAME 35
11/10/77	B1	36	REMOVED FRAME 36			REMOVED FRAME 36
11/10/77	B1	37	REMOVED FRAME 37			REMOVED FRAME 37
11/10/77	B1	38	REMOVED FRAME 38			REMOVED FRAME 38
11/10/77	B1	39	REMOVED FRAME 39			REMOVED FRAME 39
11/10/77	B1	40	REMOVED FRAME 40			REMOVED FRAME 40
11/10/77	B1	41	REMOVED FRAME 41			REMOVED FRAME 41
11/10/77	B1	42	REMOVED FRAME 42			REMOVED FRAME 42
11/10/77	B1	43	REMOVED FRAME 43			REMOVED FRAME 43
11/10/77	B1	44	REMOVED FRAME 44			REMOVED FRAME 44
11/10/77	B1	45	REMOVED FRAME 45			REMOVED FRAME 45
11/10/77	B1	46	REMOVED FRAME 46			REMOVED FRAME 46
11/10/77	B1	47	REMOVED FRAME 47			REMOVED FRAME 47
11/10/77	B1	48	REMOVED FRAME 48			REMOVED FRAME 48
11/10/77	B1	49	REMOVED FRAME 49			REMOVED FRAME 49
11/10/77	B1	50	REMOVED FRAME 50			REMOVED FRAME 50
11/10/77	B1	51	REMOVED FRAME 51			REMOVED FRAME 51
11/10/77	B1	52	REMOVED FRAME 52			REMOVED FRAME 52
11/10/77	B1	53	REMOVED FRAME 53			REMOVED FRAME 53
11/10/77	B1	54	REMOVED FRAME 54			REMOVED FRAME 54
11/10/77	B1	55	REMOVED FRAME 55			REMOVED FRAME 55
11/10/77	B1	56	REMOVED FRAME 56			REMOVED FRAME 56
11/10/77	B1	57	REMOVED FRAME 57			REMOVED FRAME 57
11/10/77	B1	58	REMOVED FRAME 58			REMOVED FRAME 58
11/10/77	B1	59	REMOVED FRAME 59			REMOVED FRAME 59
11/10/77	B1	60	REMOVED FRAME 60			REMOVED FRAME 60
11/10/77	B1	61	REMOVED FRAME 61			REMOVED FRAME 61
11/10/77	B1	62	REMOVED FRAME 62			REMOVED FRAME 62
11/10/77	B1	63	REMOVED FRAME 63			REMOVED FRAME 63
11/10/77	B1	64	REMOVED FRAME 64			REMOVED FRAME 64
11/10/77	B1	65	REMOVED FRAME 65			REMOVED FRAME 65
11/10/77	B1	66	REMOVED FRAME 66			REMOVED FRAME 66
11/10/77	B1	67	REMOVED FRAME 67			REMOVED FRAME 67
11/10/77	B1	68	REMOVED FRAME 68			REMOVED FRAME 68
11/10/77	B1	69	REMOVED FRAME 69			REMOVED FRAME 69
11/10/77	B1	70	REMOVED FRAME 70			REMOVED FRAME 70
11/10/77	B1	71	REMOVED FRAME 71			REMOVED FRAME 71
11/10/77	B1	72	REMOVED FRAME 72			REMOVED FRAME 72
11/10/77	B1	73	REMOVED FRAME 73			REMOVED FRAME 73
11/10/77	B1	74	REMOVED FRAME 74			REMOVED FRAME 74
11/10/77	B1	75	REMOVED FRAME 75			REMOVED FRAME 75
11/10/77	B1	76	REMOVED FRAME 76			REMOVED FRAME 76
11/10/77	B1	77	REMOVED FRAME 77			REMOVED FRAME 77
11/10/77	B1	78	REMOVED FRAME 78			REMOVED FRAME 78
11/10/77	B1	79	REMOVED FRAME 79			REMOVED FRAME 79
11/10/77	B1	80	REMOVED FRAME 80			REMOVED FRAME 80
11/10/77	B1	81	REMOVED FRAME 81			REMOVED FRAME 81
11/10/77	B1	82	REMOVED FRAME 82			REMOVED FRAME 82
11/10/77	B1	83	REMOVED FRAME 83			REMOVED FRAME 83
11/10/77	B1	84	REMOVED FRAME 84			REMOVED FRAME 84
11/10/77	B1	85	REMOVED FRAME 85			REMOVED FRAME 85
11/10/77	B1	86	REMOVED FRAME 86			REMOVED FRAME 86
11/10/77	B1	87	REMOVED FRAME 87			REMOVED FRAME 87
11/10/77	B1	88	REMOVED FRAME 88			REMOVED FRAME 88
11/10/77	B1	89	REMOVED FRAME 89			REMOVED FRAME 89
11/10/77	B1	90	REMOVED FRAME 90			REMOVED FRAME 90
11/10/77	B1	91	REMOVED FRAME 91			REMOVED FRAME 91
11/10/77	B1	92	REMOVED FRAME 92			REMOVED FRAME 92
11/10/77	B1	93	REMOVED FRAME 93			REMOVED FRAME 93
11/10/77	B1	94	REMOVED FRAME 94			REMOVED FRAME 94
11/10/77	B1	95	REMOVED FRAME 95			REMOVED FRAME 95
11/10/77	B1	96	REMOVED FRAME 96			REMOVED FRAME 96
11/10/77	B1	97	REMOVED FRAME 97			REMOVED FRAME 97
11/10/77	B1	98	REMOVED FRAME 98			REMOVED FRAME 98
11/10/77	B1	99	REMOVED FRAME 99			REMOVED FRAME 99
11/10/77	B1	100	REMOVED FRAME 100			REMOVED FRAME 100

REMOVED FRAME 24
REMOVED FRAME 25
REMOVED FRAME 26
REMOVED FRAME 27
REMOVED FRAME 28
REMOVED FRAME 29
REMOVED FRAME 30
REMOVED FRAME 31
REMOVED FRAME 32
REMOVED FRAME 33
REMOVED FRAME 34
REMOVED FRAME 35
REMOVED FRAME 36
REMOVED FRAME 37
REMOVED FRAME 38
REMOVED FRAME 39
REMOVED FRAME 40
REMOVED FRAME 41
REMOVED FRAME 42
REMOVED FRAME 43
REMOVED FRAME 44
REMOVED FRAME 45
REMOVED FRAME 46
REMOVED FRAME 47
REMOVED FRAME 48
REMOVED FRAME 49
REMOVED FRAME 50
REMOVED FRAME 51
REMOVED FRAME 52
REMOVED FRAME 53
REMOVED FRAME 54
REMOVED FRAME 55
REMOVED FRAME 56
REMOVED FRAME 57
REMOVED FRAME 58
REMOVED FRAME 59
REMOVED FRAME 60
REMOVED FRAME 61
REMOVED FRAME 62
REMOVED FRAME 63
REMOVED FRAME 64
REMOVED FRAME 65
REMOVED FRAME 66
REMOVED FRAME 67
REMOVED FRAME 68
REMOVED FRAME 69
REMOVED FRAME 70
REMOVED FRAME 71
REMOVED FRAME 72
REMOVED FRAME 73
REMOVED FRAME 74
REMOVED FRAME 75
REMOVED FRAME 76
REMOVED FRAME 77
REMOVED FRAME 78
REMOVED FRAME 79
REMOVED FRAME 80
REMOVED FRAME 81
REMOVED FRAME 82
REMOVED FRAME 83
REMOVED FRAME 84
REMOVED FRAME 85
REMOVED FRAME 86
REMOVED FRAME 87
REMOVED FRAME 88
REMOVED FRAME 89
REMOVED FRAME 90
REMOVED FRAME 91
REMOVED FRAME 92
REMOVED FRAME 93
REMOVED FRAME 94
REMOVED FRAME 95
REMOVED FRAME 96
REMOVED FRAME 97
REMOVED FRAME 98
REMOVED FRAME 99
REMOVED FRAME 100

28-Y003-1C309-AB	1	OF	26	REV B1
------------------	---	----	----	--------

3947-01 (Previous edition may not be used)

Anti-Lock Brake System (With Or Without Traction Assist)

How The Circuit Works

Anti-lock Brake System

With the Ignition Switch in RUN, current flows through Fuse 18 to the Anti-lock Brake Module and the Anti-lock Brake Relay coil. The Anti-lock Brake Module grounds the relay coil, the coil energizes and the relay contacts change position. Current now flows through Fusible Link Cartridge 3 and the Anti-lock Brake Relay to the Anti-lock Brake Module, the Anti-lock Brake Motor Relay and the ABS Hydraulic Control Unit.

The Anti-lock Brake Module grounds pin 62 to illuminate the ANTI-LOCK BRAKES indicator until a self-check of the entire Anti-lock System has been completed.

If brake pedal travel reaches approximately 2 inches during an Anti-lock stop, the Anti-lock Brake Pedal Travel Switch contacts open. The Anti-lock Brake Module then grounds pin 15 to energize the Anti-lock Brake Motor Relay coil and close the Relay contacts. Current flows through Fusible Link Cartridge 3 and the Anti-lock Brake Motor Relay to the pump motor on the ABS Hydraulic Control Unit. The pump motor runs to build up pressure in the brake master cylinder, forcing the brake pedal back up. When the pedal returns enough to close the Anti-lock Brake Pedal Travel Switch contacts, the Anti-lock Brake Module removes ground from pin 15 and the pump motor stops.

The brake master cylinder fluid reservoir contains a fluid level switch, which opens with fluid level above a predetermined level. If brake fluid level drops too low, the switch contacts close, turning on the red BRAKE warning indicator in the instrument cluster. The Anti-lock Brake System is not affected by this condition.


The ABS Hydraulic Control Unit fluid reservoir also contains a fluid level switch, which is closed with fluid level above a predetermined level. If brake fluid level in the reservoir drops too low, the switch contacts open. The Anti-lock Brake Module responds to this input by turning on the amber ANTI-LOCK warning indicator and disabling the anti-lock functions of the brake system.

Four individual wheel sensors and toothed sensor rings indicate to the Anti-lock Brake Module the speed of each wheel. Each wheel has a sensor and toothed sensor ring. As the wheel rotates, the teeth on the sensor ring make and break the magnetic field in the wheel sensor, generating a pulsing voltage. The Anti-lock Brake Module monitors these signals and senses impending wheel lockups.


Traction Assist

Vehicles equipped with the Anti-lock Brake System may also be equipped with the Traction Assist System. With this system, the Anti-lock Brake Module detects rear wheel spin and pulses the spinning wheel's brake until traction is reestablished.

REFERENCE :For further diagnostic information, refer to «Section 08-06 » of the Service Manual.



3713 2147



➡ Component

➡ Connector

➡ Splice

➡ Page

➡ Harness

2 How The Circuit Works

U

3713 2149

Ford Concept

Effectiveness Rank

Prevents Corrosion

Increases Fuel from 14 to Ground

Reduces Power in Switch

Features

• **Connector Seal**
Ingress of moisture causes ground path

Kapton Seal
Ingress of moisture causes ground path

• **Continuous Power**
To ground circuit
To Load circuit

• **Switch Orientation**
Internal path to ground
Susceptibility to EMI ingress
Transmits from coil to ground

• **Current Capability**

• **Grounded Mount**

Plastic Potting
Hot Wire Ignition
Coils Add

27 Relocates to Pedal	27 Jumper Switch Out	11 ABS Switch (DVT)	16 Pilot Relay	12 Move to NGND load ground	13 Break NGND ground	14 Isolate from Prop Valve	17 Plug Down	15 On Master Cyl	13 RUN Circuit Power	15 GFI circuit	16 Negative TWC Device	12 In-Line Fuse	11 Seal	11 Drop Loop
1000	1000	1000	200	250	120	20	25	20	12	0	0	0	4	4
10	10	10	2	2	2	4	0	5	5	1	1	1	4	4
10	10	10	10	10	10	0	5	5	1	1	1	1	1	1
10	10	10	0	7	0	1	1	1	4	0	0	0	1	1
X	X	X					X	X						
X	X	X												
X	X	X	X	X	X	X			X	X	X	X		
X	X	X	X	X	X				X	X	X	X		
X	X	X	X			X	X						X	X
X	X	X	X	X	X	X				X		X		
X	X	X	X			X								
X	X	X												
X	X	X												

**Prostate Cancer
Increases Risk Even If No Growth
Detected From PSA**

[illegible]

Committer David

X

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1

1
 2
 3
 4
 5
 6
 7
 8
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200
 201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300
 301
 302
 303
 304
 305
 306
 307
 308
 309
 310
 311
 312
 313
 314
 315
 316
 317
 318
 319
 320
 321
 322
 323
 324
 325
 326
 327
 328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348
 349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364
 365
 366
 367
 368
 369
 370
 371
 372
 373
 374
 375
 376
 377
 378
 379
 380
 381
 382
 383
 384
 385
 386
 387
 388
 389
 390
 391
 392
 393
 394
 395
 396
 397
 398
 399
 400
 401
 402
 403
 404
 405
 406
 407
 408
 409
 410
 411
 412
 413
 414
 415
 416
 417
 418
 419
 420
 421
 422
 423
 424
 425
 426
 427
 428
 429
 430
 431
 432
 433
 434
 435
 436
 437
 438
 439
 440
 441
 442
 443
 444
 445
 446
 447
 448
 449
 450
 451
 452
 453
 454
 455
 456
 457
 458
 459
 460
 461
 462
 463
 464
 465
 466
 467
 468
 469
 470
 471
 472
 473
 474
 475
 476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505
 506
 507
 508
 509
 510
 511
 512
 513
 514
 515
 516
 517
 518
 519
 520
 521
 522
 523
 524
 525

其	其	其	其	其
	其	其	其	

TABLE I

2 3 4 5 6 7 8 9 10 11 12

3713 2181

Efficiency Rank
Prevents Corrosion
Increases Path from E+ to Ground
Reduces Power in Switch

Environ

Converter Seal
Ingress of moisture causes ground path

Flapjack Seal
Ingress of moisture causes ground path

Continuous Power
To ground about
To Load about

Switch Orientation
Internal path to ground
Susceptibility to field ingress
Terminal lead will to ground

Current Capability

Grounded Hinge

Flexible Pannure
Not Wire Ignition
Durable Acid

7th Col. - New failure modes introduced
 Ease of implementation
 Speed of implementation

FMEA of Re-work Process

WITH ANY FIX THAT LZAIVES BRAKE PRESSURE SWITCH
CONNECTED ALSO ADD POLARITY CHANGE + DRAIN LOOP + NOAKYL.



3713 2154

CONCERN DETAIL

PRINT DATE/TIME: 99/05/10 10:01
PAGE: 1CONCERN NUMBER
C10971850ORIGIN ACTIVITY
ORIGINATOR:AR00 AVT CORN (ELECTRICAL
KAFATI, JOE W.DATE: 99/05/06
PHONE: 313-39-05389P MNT AUTH: I
STATUS: A

CONCERN DESC:

92/93 MODEL YEAR SERVICE ACTION ON TORN CAR AND CROWN VIC/
GRAND MARQUIS. THIS CONCERN IS FOR A SERVICE KIT THAT WILL
INCLUDE A EPS (F2VC-99224-AA) AND CONNECTOR (F5VB-14A464-AA)LOCAL: W
LOCATION: SLD002, 23C30
FIX PNM: N

DESCRIPTION:

SOLUTION:
PRODUCTS AFFECTED:
MODEL CODES: ORIG

WIRE HARNESSES AND BRAKE PRESSURE SWITCH.

MODEL YEAR: 99
MCC MODEL YEAR: 99
MCC:
MCC: NV01PLANTS AFFECTED: MA22 W017
PRIMARY ENG ACTY: MB00

OTHER ENG ACTY: AR00 MB00 MC00

BUILD EVENT:
CNSC:
PSO:
REQUIR BY:
SUPPORTING DOCUMENTS:
AUTHORIZED DATE: 00/00/00

CONDITION CODES:

PACK:
PRIORITY CODES: 3

CONCURRED DATE: 00/00/00

CONCURE:
CAUSAL FACTORS:
%:
NOTICE NO:
OVERALL AGE DATE:
REJECTED DATE: 00/00/00

ORIGINATOR'S ESTIMATES:

VEHICLE COST:
WARRANTY COST:
TUM:TOOLING COST:
VEN WOT:
ASSEMBLY MIN:ASSEMBLY LABOR:
UNIT OF MEASURE:FACILITY COST:
R/1000:

-----AFFECTED PARTS-----

AFF PART NO:
CNSC:
SUPPLY/LOCAL:AFF PART DESC:
NOTICE:
DAMAGE AVAIL:

-----FURTHER DESCRIPTION/CONCERN RESOLUTION/REASON FOR REJECTION ETC.-----

DESCRIPTION:

92/93 MODEL YEAR SERVICE ACTION ON TORN CAR AND CROWN VIC/
GRAND MARQUIS. THIS CONCERN IS FOR A SERVICE KIT THAT WILL
INCLUDE A EPS (F2VC-99224-AA) AND CONNECTOR (F5VB-14A464-AA)
UTL. CAN YOU PLEASE PROVIDE TIMING OF THIS CONNECTOR. WE ARE LOOKING FOR
ROUGHLY ABOUT 150,000 OF THE F5VB 14A464 AA. THIS WAS URGENT. CHARLES,
LET ME KNOW IF THIS CONNECTOR HAS THE NEW SILICONE PACK SEAL. ALSO, I
THINK THAT THE OUTER SILICONE SEAL IS FOR THE WAL, NOT SURE BUT, COULD
THIS APPLICATION BE USED FOR STANDARD WAL THICKNESS.

KAFATI, JOE W. 313-39-05389 N AVTH JUK0053 AR00 99/05/06
THIS IS FOR TORN CARS BUILT FROM 11/4/91 THRU 11/30/92 (122,338 VEHICLES)
AND CROWN VIC / GRAND MARQUIS BUILT FROM 2/5/92 THRU 11/30/92
(155,335 VEHICLES).
KIMMERS, STEVE 313-390-3286 N AVTH BJR0293 AR00 99/05/06
TO MIKE PATTISON FOR PH145 REVIEW.
PACZYNSKI, SHERR 810-344-5150 N K6700 SPACT003 NV1A 99/05/07

(CONTINUED)

-PINE-

97192185

CONCERN DETAIL

PRINT DATE/TIME: 99/05/10 10:01
PAGE: 2

CONCERN NUMBER
C10971850

ORIGIN ACTIVITY
ORIGINATOR: AS80 AVT CORE (ELECTRICAL
KAPATI, JOE W.

DATE: 99/05/06
PHONE: 313-39-05389

P MNT AUTH: I
STATUS: A

*****FURTHER DESCRIPTION/CONCERN RESOLUTION/REASON FOR REJECTION ETC.*****

DESCRIPTION:

WITH ORDERING CONNECTOR F5VB-14A464-AA WE ALSO WASH TO INCLUDE THE WEDGE THAT LOCKS IN THE TERMINALS. THE WEDGE PART NUMBER IS 8928-14A464-DA. I SPOKE WITH BILL TUTTLE FROM UTA AND HE SAID THAT AT UTA CAN PRODUCE 25,000 CONNECTORS PER DAY. RIGHT NOW THEY HAVE 26,000 PARTS AVAILABLE WITH AN ADDITIONAL 9888 ON ORDER READY TO SHIP. THEY CAN PRODUCE 25K PER DAY AND IN MAXIMUMLY TEN DAYS THEY WILL HAVE 180,000 CONNECTORS.

KAPATI, JOE W. 313-39-05389 M AVTE JWD0813 AS80 99/05/07
BENNY PACTENSKI, APPROVED 99-87 SERVICE, -0- COSTS/WT. FOR 91/92 SERVICE PARTS.
PACTENSKI, BENNY 248-34-45040 M KS840 MLD0621 AS80 99/05/08
FW145 APPROVED FOR 99-87 SERVICE ONLY, -0- COSTS/WT FOR 91/92 SERVICE PARTS.
PACTENSKI, BENNY 810-344-5150 M KS700 SPACTENSK NW1A 99/05/10
JOE KAPATI, NEED WORKSHEET AND PARTS SCREEN COMPLETED BEFORE I CAN TAKE THIS CONCERN TO APPROVED STATUS.
PACTENSKI, BENNY 810-344-5150 M KS700 SPACTENSK NW1A 99/05/10
JACK MULLER, FW145 HAS APPROVED. WHAT IS BENNY'S STATUS?
PACTENSKI, BENNY 810-344-5150 M KS700 SPACTENSK NW1A 99/05/10

*****RESOLUTION OF CONCERN*****

ACTIVITY: AS80
AGE DATE: 99/05/10
REMARKS:
MODEL CODE:
NOTICE:
EFFECTIVE IN:

RESPONSE CODE:
MODULE LEADER NAME: ELECTRICAL PNT LEADER

SCHEDULED DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:

ACTUAL DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:
REJECTED:

LISTING OF CALIBRATION NUMBER:

LISTING OF EFFECTIVE TYPE/POINT:

LISTING OF PROGRAM ID/SEGMENT:

*****MANUFACTURING ACTIVITIES AFFECTED*****
MFG ACT: REQUEST: FEAR: LEAD:
ASSEMBLY COST: PAC COST:

VEN COST:
VEN WGT:

TOOLING COST:
UNIT OF MEASURE:

ACTIVITY: AS80
AGE DATE: 99/05/10
REMARKS:

RESPONSE CODE:
MODULE LEADER NAME: BOOY PRO

-NONE-

3713 2186

CONCERN DETAIL

PRINT DATE/TIME: 99/05/10 10:01
PAGE: 3

CONCERN NUMBER
C10971050

ORIGIN ACTIVITY: AEGG AVT CORE (ELECTRICAL
ORIGINATOR: KAPATI, JOE W.

DATE: 99/05/06
PHONE: 313-39-85389

P NEXT NOTE: I
STATUS: A

-----RESOLUTION OF CONCERN-----

ACTIVITY: HB00
MODEL CODES:
NOTICE:
EFFECTIVE IN:

SCHEDULED DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:

RESPONSE CODE:

ACTUAL DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:
REJECTED:

LISTING OF CALIBRATION NUMBER:

LISTING OF EFFECTIVE TYPE/POINT:

LISTING OF PROGRAM ID/SEGMENT:

*****MANUFACTURING ACTIVITIES AFFECTED*****
MFG ACTY: REQUEST: PRAS: LEAD:
ASSEMBLY COST: FAC COST:

VEH COST:
VEH WGT:

TOOLING COST:
UNIT OF MEASURE:

ACTIVITY: HB00
AGE DATE: 99/05/10
REMARKS:
MODEL CODES:
NOTICE:
EFFECTIVE IN:

SCHEDULED DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:

RESPONSE CODE:
MODULE LEADER NAME: CHASSIS PRO

ACTUAL DATES- APPROVED:
COMPLETE:
DISTRIBUTED:
INCORPORATED:
REJECTED:

LISTING OF CALIBRATION NUMBER:

LISTING OF EFFECTIVE TYPE/POINT:

LISTING OF PROGRAM ID/SEGMENT:

*****MANUFACTURING ACTIVITIES AFFECTED*****
MFG ACTY: REQUEST: PRAS: LEAD:
ASSEMBLY COST: FAC COST:

VEH COST:
VEH WGT:

TOOLING COST:
UNIT OF MEASURE:

-MORE-

37132157

CONCERN DETAIL

PRINT DATE/TIME: 99/05/10 10:01

PAGE: 4

CONCERN NUMBER
C10971850ORIGIN ACTIVITY
ORIGINATOR:AB00 AVT CORR (ELECTRICAL
KAPATI, JOE W.DATE:
PHONE:99/05/06
313-39-05389P NET AUTH: I
STATUS: A

PROPOSED RESOLUTION

ACTIVITY

DATE

RESOLUTION

REGION	DEPARTMENT	USERID	ACTIVITY	APPROVER'S NAME	DATE APPROVED	APPROVAL	STATUS
N	AVTE	JWK0053	AB00	KAPATI, JOE W.	99/05/06		N
N	AVTE	SJRS293	AB00	BRIMMER, STEVE	99/05/06	R	
N	AVTE	FJP9198	AB00	PORTER, FRED	99/05/07	R	
C	7039	UEAFN74	G039	UEA WIKING (JN74) DE	00/00/00		
N	KE654	JON9081	BC00	NEHE, J.S.	00/00/00		
N	SP971	JCB4647	W1A	SHORE, JOHN	00/00/00		
N	AVTE	TG04788	AB00	MARTINEZ, TOM	00/00/00		
N	AVTE	JWK0053	AB00	KAPATI, JOE W.	99/05/06		A
N	K5840	NLP0621	AB00	FETTERMAN, MIKE-VC RE	99/05/08	Y	
N	K5700	DJA4509	WV1A	AMERSON, DONALD J.	00/00/00		
N	K645	GRT1042	WC00	THORNTON, GEORGE	00/00/00		
N	5330	CVC2000	KEG3	SAA LINCOLN PROGRAM	00/00/00		
N	VC1000	KLINKE	AB00	KLINKE, PATTY P.	00/00/00		
N	K5700	NLS4671	WV1J	KLEBOWITZ, MIKE L.	00/00/00		
N	K5840	APT0980	AB00	TRANSIS, MARTIN WIX	00/00/00		
N	K5700	SPACT001	WV1A	PACTUSKI, SHERRY	99/05/10	Y	

3713 2168

WERS HARDCOPY PARAMETER RECAP

BASIC PARAMETERS

REQUESTOR: MALHOTRA, AMITA
 REQUEST DATE/TIME: 99/05/10 10:01:15
 REPORTS REQUESTED FOR: MALHOTRA, AMITA
 DESTINATION DEVICE: R02043W1
 PRINT DATE/TIME: 99/05/10 10:01:15
 DATA EXTRACT DATE/TIME: 99/05/10 10:01:14

REPORT OPTIONS

HARD-COPY REQUEST-TYPE: ON-LINE REQUEST (LATEST DATA)
 LANGUAGE: ENGLISH
 PART DATA RESTRICTIONS:
 NONE

SELECTION CRITERIA

NOTICE NUMBER:
 PART NUMBER:
 PART FUNCTION:
 CONCERN NUMBER: C10971850

REPORTS REQUESTED

RELEASE / CONCERN COVER
 RELEASE SUMMARY
 RELEASE CHANGE SUMMARY
 PART FUNCTION RELEASE
 MULTI-FUNCTION RELEASE

DOUGH TRANSLATION ALERT
 CONTENTS OF ASSEMBLY SAR ONLY:
 X CONCERN DETAIL
 ALERT DETAIL

3713 2159



Service Recall Bulletin

May, 1999

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 99S15: Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control - Speed Control Deactivation Switch

AFFECTED VEHICLES

Certain 1992 and 1993 Crown Victoria and Grand Marquis with Speed Control built at the St. Thomas assembly plant from February 5, 1992 through November 30, 1992. Also, certain 1992 and 1993 Town Cars built at the Wixom Assembly plant from November 4, 1991 through November 30, 1992.

REASON FOR RECALL

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause a fuse to open.

SERVICE ACTION

Repair parts will not be available until mid-June, 1999. Until parts are available, the interim repair described in Attachment III should be used. When parts are available the permanent repair must be completed to close this recall.

Interim Repair: This repair should be performed immediately to eliminate the possibility of a fire. This interim repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch, taping the connector end to protect it from contamination and securing the connector with a tie-strap. The speed control system will be inoperative until the permanent repair is performed.

Permanent Repair: The parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

Concur: *Steve Reimers*
5/17/99

For your approval,

Post-it brand fax transmittal memo 7891		10
Steve Reimers	Gary Belant	
Dept.	Phone 3	72790
Fax 3	Phone 1	51024

3713 2180

ATTACHMENTS

Attachment I: Administrative Information

Attachment II: Labor Allowances, Parts Ordering Information, Disposition of Removed Parts

Attachment III: Technical Information

QUESTIONS?

Claims Information: 1-800-423-8851

Other Recall Questions: 1-800-325-5821

Sincerely,

A. R. O'Neill

Director

Vehicle Service and Programs

ATTACHMENT I

Page 1 of 1

Safety Recall 98B16

Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars
with Speed Control - Speed Control Deactivation Switch

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

Please note that the Interim Repair will not remove the VIN from OASIS.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.
- After performing the Permanent Repair, the replaced parts must be returned to the Warranty Parts Return Center for inspection (See Attachment II page 2). FCS 700 tags will be sent as soon as the claim is submitted.

OWNER REFUND

Ford Motor will only refund for owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII Manual for Refund Information.

ATTACHMENT II
Page 1 of 2

Safety Recall 98815
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch

LABOR ALLOWANCES**Interim Repair**

Description	Labor Operation	Labor Time
Remove, Tape and Secure the Speed Control Deactivation Switch *	98815E*	0.3 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

* Labor Operation 98815E will NOT close the Recall.

Permanent Repair

Description	Labor Operation	Labor Time
Replace Speed Control Deactivation Switch and Hard-shell Connector	98815B	0.5 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS**Parts Ordering Information**

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	31 days after launch	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-6621

Part Number	Description	Quantity
XW7Z-8G652-AA	Speed Control Deactivation Switch Kit	1

3713 2163

ATTACHMENT II
Page 2 of 2**Safety Recall 99818**
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch**DEALER PRICE**

For latest prices, check or call your:

- Order Processing Center
- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

DISPOSITION OF REMOVED PARTS**Parts Return Requested (after completion of Permanent Repair):**

We are requesting that the removed parts be returned to Ford Motor Company:


- Speed Control Deactivation Switch
- Switch Hardshell Connector

Packaging and Shipping:

- Speed Control Deactivation Switch
 - Do not drain the brake fluid from inside the Speed Control Deactivation Switch.
 - Use the plastic cap from the new switch to trap and seal as much oil inside the switch as possible.
- Switch Hardshell Connector
 - Connect the hardshell connector to the Speed Control Deactivation Switch.
 - Attach the FCS 700 tag to the part.
- Shipping Instructions
 - Follow direction on FCS 700 tag
 - See Section 3 of the ACES II manual for more details

ATTACHMENT III
PAGE 1 OF 2
SAFETY RECALL 99E16**INTERIM REPAIR****DISABLE SPEED CONTROL DEACTIVATION SWITCH****SERVICE PROCEDURE**

1. Disconnect the electrical connector from the speed control deactivation switch. See Figure 1.

**FIGURE 1**

2. Tape the end of the connector to prevent contamination from entering the end of the connector.
3. Tie strap the connector to the wiring harness located on the left splash shield.

*Concur:
Steve Reimers
5/17/99*GM © 1999 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
5/99

PERMANENT REPAIR

SPEED CONTROL DEACTIVATION SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES: CERTAIN 1992 AND 1993 CROWN VICTORIA, GRAND MARQUIS AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the speed control deactivation switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the new connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the speed control deactivation switch. See Figure 2.





FIGURE 2

Concur: Steve Reimers
5/17/99

ATTACHMENT 18
PAGE 3 OF 3
SAFETY RECALL 99019

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 3.




4. Obtain the new connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully seated in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the speed control deactivation switch from the parts kit.
7. Remove the old speed control deactivation switch.
8. Fill the new speed control deactivation switch with High Performance DOT 3 Brake Fluid and install the speed control deactivation switch. Tighten the switch to 18 Nm (13 lb-ft).
9. Attach the electrical connector to the speed control deactivation switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
- Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.

Concur: Steve Rainard
5/17/99

© 1999 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
200

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division



Ford Motor Company
P. O. Box 1804
Dearborn, Michigan 48121

May, 1999

Safety Recall 99B15

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control.

SAFETY DEFECT

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause the brake light fuse to open.

REPAIRS

Repair parts may not be available until mid-June, 1999. If your dealer is not able to obtain the parts needed for this recall, an Interim Repair can be performed at no charge to you. However a second visit to your dealer will be required at a later date to have the permanent repair performed. We regret this inconvenience, but your safety is our primary concern.

Interim Repair: If parts are not available, the Interim Repair should be performed immediately. This repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch and protecting the connector end from contamination. The Speed Control system will be inoperative until the Permanent Repair is performed.

Permanent Repair: Parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

3713 2168

HOW LONG WILL IT TAKE?

The time needed for either of the repairs is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 99S15.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. If available, parts would be expected to arrive within a week after ordering. If parts are not available, your dealer can perform the Interior Repair free of charge. When parts are available, your dealer will perform the Permanent Repair free of charge.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

REFUNDS

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your Ford or Lincoln Mercury dealer. To avoid delays, do not send receipts to Ford Motor Company.

CHANGED ADDRESS OR SOLD THE VEHICLE?

Please fill out the enclosed prepaid postcard and mail it to us if you have changed your address or sold the vehicle.

If the dealer doesn't make the repair promptly and without charge, you may contact the Ford Customer Assistance Center, P. O. Box 6248, Dearborn, Michigan 48121. You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 305-0123).

We regret the inconvenience this service may cause you, but we want you to have the work done for your safety and satisfaction with your Ford or Lincoln-built vehicle.

Sincerely,

A. R. O'Neill
Director
Vehicle Service and Programs



3713 2170

3713 2171

Percentage of Fires Based On Production Volumes with Engine off/Unknown

1992 Model Year			
	Production volumes	Number of fires	% fire
Town car	109,120	40	0.04
CV/GM	283,393	*20	0.01
Econoline	155,450	N/A	N/A
F-series	507,105	N/A	N/A

1993 Model Year			
	Production volumes	Number of fires	% fire
Town car	90,784	5	0.01
CV/GM	203,307	12	0.01
Econoline	155,335	N/A	N/A
F-series	493,549	N/A	N/A

1993 Model Year			
	Production volumes	Number of fires	% fire
Town car	113,554	7	0.01
CV/GM	183,148	2	0.001
Econoline	188,452	32	0.02
F-series	542,480	55	0.01

1997 Model Year			
	Production volumes	Number of fires	% fire
Town car	104,977	1	0.001
CV/GM	251,795	7	0.003
Econoline	185,185	N/A	N/A
F-series	341,930	N/A	N/A

1994 Model Year			
	Production volumes	Number of fires	% fire
Town car	113,028	3	0.003
CV/GM	198,072	15	0.01
Econoline	199,725	34	0.02
F-series	508,672	47	0.01

* Note:

Of the 20 1992 CV/GM, there are 6 vehicles equipped with ABS.
Of the 1992 CV/GM without ABS there are 3 that are identified as the brake pressure switch as the probable cause.

1995 Model Year			
	Production volumes	Number of fires	% fire
Town car	107,595	7	0.01
CV/GM	192,591	4	0.002
Econoline	205,595	15	0.01
F-series	555,117	48	0.01

Originator: JKafati
File: volumes2
Date issued: 4/12/99
Date revised: 4/9/99

3713-2172

**THIS PAGE ACCOUNTS FOR PAGE(S) REMOVED FOR CONFIDENTIAL FILE.
DOCUMENTS CONTAINED IN FILE ROOM.**

BOX 3713 **PAGE(S)** 2173-2175 **DATE** 10-20-99.

Note printed by WARRANCE on 5 Jan 1989 at 13:03:31

FROM: FPORTER --DRN007
TO: WARRANCE--DRN005
RANGLIST--DRN005
DOCKEL --DRN005
KGRIBBLE--DRN005
SLAROUCH--FORN01
JNAME --DRN005
GSTEVENS--DRN005
THOMAS5--DRN005

Date and time 12/18/88 17:04:06
BEGEN --DRN007
JEVANS --DRN005
JGREGOIR--DRN005
NLAPPOINT--DRN005
JMCINERN--DRN005
RNEVI --DRN005
CTHOMAS5--DRN005

FROM: F. J. Porter
Subject: 8F924 Update (19921212)

USABY(UTC -05:00)

1992-1993 Town Car F2VC-8F924-A Brake Pressure Switch Investigation

TEAM:

AVT ESE Chassis Electronics:	Fred Porter	x84-53722	fporter
AVT Chassis Engineering:	Joe Evans	x32-23832	jevans
	Barry Egan	x32-39512	began
AVT ESE EOS:	Rob English	x33-72228	ranglist
AVT Design Analysis:	Mora LaPointe	x39-42688	nlapoint
AVT ESE OPE:	Jim Gregoire	x32-79962	jgregoir
ESE Prod. Veh. Safety:	William Abramozyk	x32-21284	wahranca
	Ray Nevi	x39-47688	rnevi
Large Luxury VC Safety:	John McInerney	x32-20278	jmcinern
	Joe Name	x39-08133	jname
AVT Materials Engineering:	Greg Stevens	x32-36688	gstevens
	Ken Gribble	x32-38688	kgribble
	Clark Thomas	x39-41113	cthomas5
Central Lab Services:	Steve LaRouche	x84-54878	slarouch

INFORMATION:

NHTSA letter: PE98-058

Vehicles identified: 21 initially identified.
20 additional vehicles reported since publication of
the investigation.

Warranty: A total of 89 warranty claims are identified in AMS on the
F2VY-8F924-A for 1992 and 1993 Town Cars.

Two QJIS reports (WJIAA135 & VJIAA122) mention underhood fire
in connection with the brake pressure switch.
WJIAA135 occurred at 51,800 miles.
VJIAA122 occurred at 56,892 miles.

Supplier: The pressure switch was manufactured by Texas Instruments. The
switch was purchased in assembly with the brake proportioning
valve bought from Surfaces.

Contacts: Surfaces - Mike Thomas (248)543-6520 [MILITE Industries]
TI - Bob Sharp (248)305-5725

TI - Russ Baumann (508) 236-1314
 TI - Charlie Douglas (508) 236-3687

Function: The brake pressure switch is a redundant switch for turning off the speed control function.

X-Rays: Taken by Steve LaRouche, Norm LaPointe & Clark Thomas on 12/17/1998. Original photographs and part are in Steve LaRouche's possession.

ON-GOING ACTIVITY:

2 service parts have been ordered from Fairlane Ford for X-ray and other testing by Central Lab Services.

Meeting with representatives of TI is planned for 12/22/1998 to discuss intended operation of the switch. The meeting will be at the Central Laboratory Conference room off of the lobby.

QUESTIONS: (in no particular order)

- 1) What is the normal current in the brake pressure switch?
- 2) Was cruise control standard on Town Car in 1992 and 1993?
- 3) Under what circumstances is brake fluid flammable?

According to Clark Thomas & Mary Mags, brake fluid is flammable approximately 300 degrees F.

- 4) What is the repair history for vehicles that have exhibited a problem? Repair history for the two CQIS vehicles are being gathered by F. Porter.
- 5) What other vehicles use this brake pressure switch? What are their electrical configurations?

MODEL YEAR	92	93	94	95	96	97	98
Town Car	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Crown Vic	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Grand Marquis	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Econoline	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
Club Wagon	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
F-Series		XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
Bronco		XXXX	XXXX	XXXX	XXXX		
Taurus SHO		XXXX	XXXX	----			
Capri			XXXX	XXXX	----		
Mustang			XXXX	XXXX	XXXX	XXXX	XXXX
Falcon				XXXX	XXXX	XXXX	XXXX
Explorer					----	XXXX	XXXX
Ranger					----	XXXX	XXXX
Expedition						XXXX	XXXX
Navigator							XXXX

XXXX = used in model year

---- = may have been used in model year

6) Is this switch still in use? If not, why not? If so, what design changes have been implemented since 1992/1997?

Charlie Douglas of TI is investigating the design changes that may have been implemented on the brake pressure switch beginning in 1992.

7) What fault codes are stored if the brake pressure switch fails?

Regards,

Fred Porter

OV - Sporter

spporter@ford.com

Chassis E/E Systems Applications

(313) 945-3722

Bldg 6 - Mail Drop 9030 - Cubicle 3E004

Fax: 390-4145

.....
Note printed by WARRAMCZ on 5 Jan 1998 at 13:03:21
.....

FROM: FPORTER --DREN007
TO: WARRAMCZ--DREN005
RENGLIST--DREN005
DGOEL --DREN005
KGRIBBLE--DREN005
SLAROUCH--FORDNA1
JNAME --DREN005
GSTEVEN1--DREN005
KWELFER3--DREN006

Date and time 12/18/98 17:04:04
BEGEN --DREN007
JEVAMES --DREN005
JUREGOIR--DREN005
NLAPPOINT--DREN005
JMCINERN--DREN005
RNEVI --DREN005
CTHOMAS5--DREN005

FROM: F. J. Porter
Subject: 9F924 Update (19981218)

UNAKT(UTC -05:00)

1992-1993 Town Car F2VC-9F924-A Brake Pressure Switch Investigation

TEAM:

.....
AVT ESE Chassis Electronics: Fred Porter x84-53722 fporter
AVT Chassis Engineering: Joe Evans x32-23832 jevames
Harry Egen x32-39812 begen
AVT ESE SOS: Rob English x33-73225 renglist
AVT Design Analysis: Norm LaPointe x59-42686 nlapoint
AVT ESE OVE: Jim Gregoire x32-79962 jgregoir
ESE Prod. Veh. Safety: William Abramczyk x32-23284 wabramcz
Ray Nevi x59-47888 rnevi
Large Luxury VC Safety: John McInernay x33-30276 jmcinern
Joe Name x39-08123 jname
AVT Materials Engineering: Greg Stevens x32-36686 gsteven1
Ken Gribble x32-38698 kgribble
Clark Thomas x59-41313 cthomas5
Central Lab Services: Steve LaRouche x84-54876 slarouch
.....

INFORMATION:

.....
NHTSA letter: 9898-035

Vehicles identified: 21 initially identified.
20 additional vehicles reported since publication of
the investigation.

Warranty: A total of 88 warranty claims are identified in AMS on the
F2VY-9F924-A for 1992 and 1993 Town Cars.

Two CQIS reports (WJYAL135 & VDUAJ322) mention underhood fire
in connection with the brake pressure switch.
WJYAL135 occurred at 51,500 miles.
VDUAJ322 occurred at 54,802 miles.

Supplier: The pressure switch was manufactured by Texas Instruments. The
switch was purchased in assembly with the brake proportioning
valve bought from Surfaces.

Contacts: Surfaces - Mike Thomas (248) 543-6520 (MILITE Industries)
TI - Rob Sharp (248) 305-5725

TI - Russ Baumann (508)236-3314
 TI - Charlie Douglas (508)236-3637

Function: The brake pressure switch is a redundant switch for turning off the speed control function.

X-Rays: Taken by Steve LaBouche, Norm LaPointe & Clark Thomas on 12/17/1998. Original photographs and part are in Steve LaBouche's possession.

ON-GOING ACTIVITY:

2 service parts have been ordered from Fairlane Ford for X-ray and other testing by Central Lab Services.

Meeting with representatives of TI is planned for 12/22/1998 to discuss intended operation of the switch. The meeting will be at the Central Laboratory Conference room off of the lobby.

QUESTIONS: (in no particular order)

- 1) What is the normal current in the brake pressure switch?
- 2) Was cruise control standard on Town Car in 1992 and 1993?
- 3) Under what circumstances is brake fluid flammable?

According to Clark Thomas & Mary Hays, brake fluid is flammable approximately 100 degrees F.

- 4) What is the repair history for vehicles that have exhibited a problem? Repair history for the two QGIS vehicles are being gathered by P. Porter.
- 5) What other vehicles use this brake pressure switch? What are their electrical configurations?

MODEL YEAR	92	93	94	95	96	97	98
Town Car	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Crown Vic	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Grand Marquis	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	
Econoline	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
Club Wagon	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
F-Series		XXXX	XXXX	XXXX	XXXX	XXXX	XXXX
Bronco		XXXX	XXXX	XXXX	XXXX		
Taurus SHO		XXXX	XXXX	----			
Capri			XXXX	XXXX	----		
Windstar			XXXX	XXXX	XXXX	XXXX	XXXX
Falcon				XXXX	XXXX	XXXX	XXXX
Explorer					----	XXXX	XXXX
Ranger					----	XXXX	XXXX
Expedition						XXXX	XXXX
Navigator							XXXX

XXXX = used in model year

---- = may have been used in model year

- 6) Is this switch still in use? If not, why not? If so, what design changes have been implemented since 1992/1993?

Charlie Douglas of TI is investigating the design changes that may have been implemented on the brake pressure switch beginning in 1992.

- 7) What fault codes are stored if the brake pressure switch fails?

Regards,

Fred Porter OV - Sporter sportersford.com
Chassis E/E Systems Applications (313) 845-3722
Bldg 5 - Mail Drop 5030 - Cubicle 3E004 Fax: 390-4145

SUMMARY

Reviewed 83-85 Econoline reports which included:

Owner Reports (MORS)

Field Reports (CQIS)

There were 81 reports categorized engine off/unknown and underhood based on the information available.

28 out of 81 are reported engine off.

53 out of 81 are reported unknown.

Of the 28 vehicles reported with the engine off:

14 are reported to be unknown probable cause.

5 are reported to be electrical as a probable cause.

2 are reported as having after market conversions.

1 is reported as having started in the left front wheel area.

1 is reported as the brake pressure switch as the probable cause.

1 is reported to be a gas leak.

1 is reported to be the battery.

1 is reported to be the A/C unit.

1 is reported to be transmission.

1 is reported to be the catalytic converter.

Of the 53 vehicles reported with the engine unknown:

24 are reported to be unknown probable cause.

6 are reported to be electrical as a probable cause.

5 are reported to be the ignition switch.

3 are reported to be the left side of vehicle.

3 are reported to be the battery.

2 are reported to be at the front end of the vehicle.

2 are reported to be the fuel pump.

1 is reported to be the A/C relay.

1 is reported as part of a conversion with the heater A/C area.

1 is reported as the vacuum hose.

1 is reported to be the computer module.

1 is reported to be a ground wire melted.

1 is reported to be the transmission.

1 is reported to be the alternator.

1 is reported to be the power distribution fuse panel burnt.

Originator: JKafali
File: summary3.xls
Date issued: 2/15/99
Date revised: 2/12/99

3713 2182

SUMMARY

Reviewed 65 92/93 Crown Vio/Grand Marquis reports of which 46 were categorized engine unknown, engine off and underhood.

Of the 46 reports:

30 out of 46 are reported engine unknown.

16 out of 46 are reported engine off.

Of the 30 vehicles reported with the engine unknown:

9 are reported to be unknown probable cause.

4 are reported to be the alternator as a probable cause.

3 are reported to have started in the front of the car.

2 are reported to have started in the left front of the vehicle.

2 are reported to be the brake booster as a probable cause

1 is reported as brake light wiring touching brake fluid.

1 electrical short.

1 heating system

1 cowl area

1 master cylinder

1 would not shift out of park.

1 rupture hose.

1 starting system.

1 delta PFE hose burned.

1 air compressor

Of the 16 vehicles reported with the engine off:

7 are reported to be unknown probable cause.

2 are reported to have started in the left front of the vehicle.

2 are reported electrical as a probable cause.

2 are reported fuel lines as a probable cause.

1 is reported as the fuel pump relay.

1 is reported as the starter.

1 is reported as the brake pressure switch.

1992 & 1993 Town Car Underhood Fires**FIELD REVIEW COMMITTEE**

To: (North America)
Secretary, FRC
Suite 785
Diagnostic Service Center II
Ford Customer Service Division — North America

To: (Europe)
Secretary, FRC
Room GB-1/329,
Ford Customer Service Division — Europe

The attached Evaluation Paper is being forwarded for review by the Field Review Committee. Copies have been submitted for review to:

Office of the General Counsel: YES ☐ NO ☐

Vehicle Environmental Engineering: YES ☐ NO ☐

Automotive Safety Office: YES ☐ NO ☐

VC Purchasing Director YES ☐ NO ☐

Subject: 1992 & 1993 Town Car Underhood Fires

Vehicle Line Director

Vehicle Center Engineering Director

Date

Date

Note: Both signatures are required prior to Review by the Field Review Committee

1992 & 1993 Town Car Underhood Fires

1. **PROBLEM DESCRIPTION (what/when/extent)**

- A. NHTSA opened PE 98-035, dated November 24, 1998, into "... 21 reports of engine compartment fires in 1992 and 1993 Lincoln Town Cars." Our investigation into these reports indicates the brake pressure switch may be involved in some of the reports.

The brake pressure switch was introduced on the 1992 Town Car in November 1991, as part of the Electronic Speed Control system. The same brake pressure switch was introduced on the 1992 Crown Victoria and Grand Marquis in February 1992. The switch wiring and packaging location are similar on all three vehicles.

Internal brake fluid leakage is one of the reasons service technicians remove brake pressure switches. Internal corrosion of the electrical switch components is observed in brake pressure switches with brake fluid leakage. Chlorine is not evident in these switches.

- B. The brake pressure switch, F2VC-9F924-AB (service part F2VY-9F924-A) is the redundant speed control deactivation switch (CPSC 060605) for the Electronic Speed Control that is standard on all Town Cars built between November 1991 and Job #1 MY1998 and is an option on Crown Victoria and Grand Marquis.

C. **Vehicles Affected —**

Model Year (s)	Vehicle Lines	Vehicle Volume	Variants	Other Limiting Factors
1992, 1993	Town Car	123,310	all	none
1992, 1993	CV/GM	155,335	all	With Electronic Speed Control

D. **Markets Affected: All markets.**E. **Corporate Product Systems Classification (CPSC) code(s): 06.06.05**

2. DEFINE ROOT CAUSE

- A. Though we have not definitively identified the root cause, the brake pressure switch appears to be susceptible to brake fluid leaks and corrosion that may create a conductive path in the switch resulting in overheating. Analysis performed on field samples of the brake pressure switches involved in underhood fires has not allowed us to conclude that the brake pressure switch was the cause of the fires. Analysis performed on brake pressure switch field samples not involved in fires suggests brake fluid enters some of the switch cavities through cracks in localized brittle portions of the internal Kapton diaphragm or other contaminants through the electrical connector seals. This contamination in the presence of a continuous electrical potential is favorable to causing corrosion. Corrosion products inside the brake pressure switch cavity could create a conductive path between the uninterrupted battery power and ground. During lab testing, intended to create internal corrosion, it was observed that a conductive path to ground carried an increasing leakage current of 1 to 2 amps average at 14 volts, with transients of 10 amps at 14 volts. These lab conditions were capable of melting or igniting the brake pressure switch plastic bases in a 3 hour controlled environment (see chart #1).

In normal operation, the switch leakage current is expected not to exceed 0.0001 amps. The switch contacts normally conduct up to 0.75 amps to the speed control clutch when speed control is engaged and 0.005 amps when not engaged. The current into the switch is limited by a 15 amp fuse and is supplied by a circuit that is always energized.

- B. The Ford process intended to prevent the diaphragm leakage and connector seal contamination is the engineering specification (ES-F2VC-9F924-AA) which requires:

- electrical current leakage to the housing (ground) not to exceed 0.0001 amps;
- proof test... no evidence of fluid leakage, seepage, or drop in test pressure greater than 62 psi (in 30 seconds) is permitted;
- 500,000 Impulse cycles at 224° F ambient using 275° F brake fluid;
- 80 hours of humidity cycling;
- 72 hours of Salt spray; and
- in-process testing to control the quality of the component.

- C. The design process did not prevent this issue because DV testing did not evidence any leaking diaphragm or connector seal leakage or internal switch corrosion. The potential effect of creating a conductive path caused by contaminants on the internal switch metallic components was not anticipated in the brake pressure switch design FMEA. ES durability testing did not evidence a leaking diaphragm nor connector seal leakage nor internal switch corrosion.

1992 & 1993 Town Car Underhood Fires

D. Please check the applicable item(s) in each category:

- Type: ☐ Design ☐ Manufacturing ☐ Vehicle Assembly
☐ Other (If other, specify __)
- System: ☐ Body ☒ Chassis ☐ Cooling ☐ Fuel ☒ Electrical ☐ Engine
☐ Glass ☐ Restraints ☐ Transmission/Axle
☐ Vehicle Label/Publications ☐ Emissions Control
☐ OBD ☐ Other (If other, specify __)
- Symptom: ☐ Brake Control ☐ Emission Compliance
☐ Other Regulatory Compliance ☐ Driveability/No Start
☐ Engine Speed Control/Unexpected Movement ☒ Fire
☐ Steering Control ☐ Occupant Restraint ☐ Personal Injury
☐ Visibility ☐ Warranty Avoidance/Customer Satisfaction
☒ Other (If other, specify Speed Control Inoperative)

3. PROBLEM INVESTIGATION/VERIFICATION DATA

A. Lab Test

Lab experiments were performed to reproduce ignition or melting as suggested by analysis of field returns and data. (see Attachment 4) These tests were done with a variation of brake fluid concentrations, water and salt to develop a model to understand the factors contributing to thermal events. These tests did not result in a melting or ignition with brake fluid or water. A salt water solution procedure reliably produced melted switches and some ignited plastic switch bases. This is shown in attachment 4 test 6b.

The test parameters used to create melting or ignition in an accelerated lab environment are:

Voltage: 14 volts dc
 Current Limit: 15 amps
 Solution: 5% NaCl and tap water
 Orientation: connector 45° from vertical (in-vehicle orientation)

1992 & 1993 Town Car Underhood Fires

Procedure: Apply voltage between the switch contact components and the switch metallic base (normal operating condition). Inject salt water solution into the pressure switch cavity through the connector body. Repeat injection as water is boiled away. In 2 to 3 hours, the plastic switch bases will begin to melt and some will ignite drawing 1 to 10 amps of switch leakage current to ground.

This model was used to verify that the proposed relay and wire harness overlay is a robust modification for this concern.

Attachment 4 below lists tests that shows test details.

Include a summary of all of the paths we have investigated. Include the chart.

Include a discussion of change history—looked and found no pattern?

B. Vehicle tests: Vehicle tests were performed on a 1992 Town Car to determine the pressure applied to the brake pressure switch. Maximum pressure seen in these tests did not exceed the maximum test pressure of the engineering specification for the part. No fire or smoke was observed.

C. Plant/Supplier Reports: The Town Car, Crown Victoria and Grand Marquis assembly plants no longer used this part after mm/dd/ 1997. There were no plant or supplier reports..

D. Quality Indicators: 13 of 47 engine off-or-unknown fire incidents reported in MORS and CQIS on 1992 and 1993 Town Cars mention the brake pressure switch or a symptom related to a brake pressure switch failure. (See attachment 1)

Fire allegations on Town Car, Crown Victoria and Grand Marquis declined for vehicles built after November 1992. (see attachments 1 & 2) Based on a review of fire allegations potentially related to the brake pressure switch, the trend demonstrates that the affected vehicle population was built between November 1991 and November 1992.

The mileage at the time of the fire, of the vehicles involved, is 60,000 to 100,000 miles and the average time-in-service is 48 to 72 months (see attachment 3). Vehicles built after the affected population, predictably have reached this mileage and time-in-service for build dates up to BBBBBBB and do not show a similar fire incident rate.

E. Field Reports: Two separate incidents of observed flames on the brake pressure switch were reported by mechanics servicing Town Cars.

Additionally, 48 switches from U.S. vehicles have been collected.

The results of examining these follow:

- 30 functioned correctly with no fluid leakage evident.
- 10 are alleged to be involved in fires.

1992 & 1993 Town Car Underhood Fires

- 6 leaked brake fluid through the Kapton diaphragm. These had black or dark green residue (containing Brake Fluid, Zinc, Copper, Sulfur) on the terminals and/or cup. 4 due to brittle cracks.
- 3 would not open the switch contact
- 1 had high switch contact resistance
- 8 showed transfer of brass contact material to cup (4 fire / 4 leakers)
- 2 missing movable contacts appear corroded away (2 leakers)
- 1 separated movable contact (leaker)

F. Part Sales: The service part is used for multiple model years and 4 vehicle lines. Sales for the affected vehicles cannot be segregated for comparison to other vehicle usage.

G. *List number of accidents... attributed to this condition.*

4. ACTIONS TAKEN IN PRODUCTION; INTERIM (CONTAINMENT) AND/OR PERMANENT

The affected production material were built in the 1992 and 1993 model years. No action is required to be taken in production as these parts are no longer used on Town Car and Crown Victoria and Grand Marquis built after the 1997 model year.

5. VERIFY EFFECTIVENESS OF CORRECTIVE ACTIONS

No corrective action has been implemented in production as this part is no longer used on the Town Car, Crown Victoria or Grand Marquis built after the 1997 model year.

1992 & 1993 Town Car Underhood Fires

6. ESTIMATED PRODUCTION AND PROBLEM STATISTICS (MAGNITUDE OF CONCERN)

A.

VEHICLES AFFECTED (BY MODEL AND MODEL YEAR)	ASSEMBLY PLANTS (INCLUDING KNOCK DOWN OPERATIONS)	VEHICLE PRODUCTION DATES		POTENTIALLY AFFECTED UNITS	
		FROM	UP TO AND INCLUDING	NUMBER OF UNITS	ESTIMATED PERCENTAGE OF VEHICLES THAT CONTAIN THE CONDITION
Town Car	Wixom AP	11/4/1991	11/30/1992	123,310	unknown
CV/GM	St Thomas AP	2/5/1992	11/30/1992	155,335	unknown

B. The source of the data is a NAVIS report.

7. AFTERMARKET PARTS

A. The brake pressure switch is released as an individual service part and as part of assembly P2VY-2B091-B.

B. The affected service stock is usable with the proposed field service action below.

8. ASSESSMENT OF EFFECT ON VEHICLE OPERATION

Customers may experience inoperative speed control, difficulty shifting out of park (fuse #12 blown), dead battery, brake warning lamp ON, excessive brake pedal travel and/or smoke or fire on the left hand side of engine compartment.

9. DESCRIPTION OF CONCERN SOLUTION AND PARTS REQUIREMENTS (FIELD SERVICE ACTIONS)

A. Field Modification: The modification will be accomplished in two visits to the dealership. The first visit will cut the two wires at the brake pressure switch connector to remove power from the switch and prevent potential heating of the switch. The connector and wire stubs will be wrapped with tape to protect the switch until the next visit. The harness wires will be individually wrapped in tape and tied back to the harness to prevent a short to ground. This will disable speed control.

Return vehicles to dealerships a second time for installation of a wire harness overlay rework kit which includes a relay that limits power to the brake pressure switch to 200 milliamps. No power is applied to the brake pressure switch when the ignition is off in contrast to with the unmodified circuit which is always energized.

1992 & 1993 Town Car Underhood Fires**B. Assessment of procedure**

- This modification procedure has been installed on a 1992 Town Car and a 1993 Crown Victoria. The speed control system functioned normally.
- The 200 milliamp current limit successfully prevented melting and ignition as demonstrated in lab testing (see attachment 4 test 16).
- The modification effects the electrical distribution system by adding a 200 milliamp load to the vehicle electrical system when the key is in the RUN or ACC position. There is no additional load and there is no power applied to the brake pressure switch when the key is in the OFF position.
- This modification changes the effect of a short to ground on the brake pressure switch. The unmodified effect disabled speed control. The modified effect disables the secondary deactivation function of the brake pressure switch. The speed control has 3 additional redundant deactivation functions. . No corrective action is necessary as this is a redundant function.
- Validation by FMEA process for other vehicles is not applicable.
- The modification procedure was evaluated by FCSD using appropriate tools, equipment, and a representative vehicle.

C.

- Kit name Relay Jumper.
- 150,000 rework kits will be ready for service by 6/25/99 (8 weeks). WERS concern C10965448 will be released with the completion of the rework kit design and procedure scheduled for TBD.
- production part number is not applicable
- service kit part number is F3VB-9A839-AA
- 1 kit is required per vehicle.

D. ... Other parts????**E. Driveability and Emissions not affected.****10. PROGRAM PARTS SIGN OFF/AVAILABILITY**

EESE OPD is working with FCSD and wiring harness supplier to complete the design of the service kit.

30,000 kits will be available 5 weeks after supplier is started.

30,000 kits per week will be available thereafter.

(150,000 kits can be supplied in 8 weeks.)

1992 & 1993 Town Car Underhood Fires

11. SUPPLIER INVOLVEMENT

- A. TBD
- B.
- C.
- D.
- E.
- F.

1992 & 1993 Town Car Underhood Fires

12. FINANCIAL IMPLICATIONS

	Vehicle Volume	Cost Per Unit	Total Cost (\$00)
A Program Administration Costs	278,645	\$1.20	\$334
B Inspection Costs (Units to be Inspected but Not Modified)	0		0
C Part I Modification Costs (Units to be Inspected and Modified) • Parts (priced at dealer price plus ___%) (\$1.00 (e)) Labor (0.3 hours x \$58.34 labor rate)	278,645	\$18.50	5,155
C Part II Modification Costs (Units to be Inspected and Modified) • Parts (priced at dealer price plus 40%) (\$11.75 (e)) • Labor (0.9 hours x \$58.34 labor rate) \$52.50	278,645	\$64.25	17,900
D Dealer Administration Allowance (for safety and emissions recalls only) [0.1 hours x \$58.34 labor rate - N.A.]	278,645	\$5.83	1,625
E Total Cost (total A through D)			25,014
F Percentage of Recommended Supplier Recovery (if applicable or TBD if unknown)			0%
G Supplier Impact (E * F, if applicable)			0
H Net FORD Exposure (E-G)			0
I Potential Warranty Offset			0

13. PREVENT ACTIONS

- A. Review SDS, WCR Brake System Durability and Bench Testing (DVP&R) to examine the effect of contaminated, or aged, or incorrect brake fluid. Update FMEAs and FTAs.
- B.generic items or processes impacted.....
- C. ... corporate memory updates ...

1992 & 1993 Town Car Underhood Fires

14. REFERENCE DATA**A. Attachments**

- 1 Pareto of 92/93 Town Car Underhood Fire Allegations With Engine On/Off/Unknown.
- 2 Pareto of 92/93 Crown Vic/Grand Marquis Underhood Fire Allegations With Engine On/Off/Unknown.
- 3 92 Lincoln Town Car Reported Incidents Of 40 Vehicles with Engine Off/Unknown.
- 4 9F924 De-activation Switch Test Synopsis
- 5 Hexport Current vs. Time , Fluid Ingress Experiment
- 6 Hydraulic Pressure Switch Cross Section


B. T. F. Donovan, Manager

Phone: (313)390-7420

E/E Systems, LVC/TVC OPD & Core Quality

Building 5, 1A043

Parade of 92/93 Town Car Underhood Fire Allegations With Engine On/Off/Unknown



Note:

- The shaded region represents vehicles with engine off/unknown.
- The unshaded region represents vehicles with engine on.
- 1 Represents BPS symptoms


There were 11 vehicles in the unknown category.
3 engine off/unknown, 1 relates to a BPS symptom.

8 engine on.

Originator: JKell
File: Bulldozer.xls
Date issued: 4/12/99
Date revised: 4/16/99

3713 2195

Parade of 92/93 CV/GM Underhood Fire Allegations With Engine On/Off/Unknown



Note:



- The shaded region represents vehicles with engine off/unknown.
- The unshaded region represents vehicles with engine on.
- 1 Represents BPS symptoms

There were 4 vehicles in the unknown category.
 3 engine off/unknown, 2 relate to BPS symptoms.
 1 engine on, 1 relate to a BPS symptom.

Originator: JKabali
 File: Buldoch.xls
 Date issued: 4/19/99
 Date revised: 4/16/99

3713 2196

92 Lincoln Town Car Reported Incidents Of 40 Vehicles with Engine Off/Unknown



Note:

There were 5 vehicles with unknown vms, therefore, years in service were undetermined.
There were 8 vehicles with unknown miles.

Attachment 3

3713 2197

Attachment 4

9F924 De-activation Switch Test Synopsis

This document is a synopsis of tests conducted during the investigation of the 9F924 brake pressure switch manufactured by Texas Instruments (P/N 77PS). These tests attempt to reconcile the parameters of the system with alleged field events. The following are the system parameters around the application of the brake pressure switch.

1. The switch components are exposed to battery potential continuously after the vehicle is manufactured.
 - A. The hexport of the switch is screwed into the brake proportioning valve that is mounted to the vehicle frame. The vehicle frame is a ground potential.
 - B. Battery voltage is continuously connected to moveable contact. The ignition switch does not modify battery voltage to the brake pressure switch.

The intent of this document is to highlight test findings.

Test 1

- Objective:** Determine if switch ignition can occur under the following conditions:
- Switch contact flooded with brake fluid mixed with varying amounts of % tap water.
 - 14 volts applied to one terminal, second terminal electrically floating. (No electrical load across switch terminals).
 - Switch hexport electrically grounded.
- Test eight samples with the following mixtures:
- 2 with 4% tap water in brake fluid
 - 2 with 6% tap water in brake fluid
 - 2 with 10% tap water in brake fluid
 - 2 with 75% tap water in brake fluid

Results: No ignition occurred. No significant temperature rise observed. Leakage current to ground ranged from 0.5 mAmps to 5 mAmps over the 250-hour test duration.

Conclusion: While degradation in performance is observed, brake fluid does not develop corrosion or a leakage current path quickly enough to use for laboratory validation testing.

Test 2

- Objective:** Determine if switch ignition can occur under the following conditions:
- Switch contact flooded with brake fluid mixed with varying amounts of % tap water.
 - 14 volts applied to one terminal, second terminal connected to a 14-ohm resistor tied to ground. (1 Amp load across switch terminals).
 - Switch hexport electrically grounded.

Results: No ignition occurred. The temperature rise was less than 10°F over the 250-hour duration of the test.

Conclusion: Heat generated by the switch contacts is not sufficient to ignite the plastic base or brake fluid.

1992 & 1993 Town Car Underhood Fires

Attachment 4

Test 6

- Objective:** Determine if switch ignition can occur under the following conditions:
- A heater element installed in contact cavity of the switch.
 - Apply power to the heating element until plastic base ignites.
 - Apply an external spark to the fumes from the plastic.
 - Brake fluid present in the contact cavity (wet device) and not present in the contact cavity (dry device).

Results: Ignition occurred in both wet and dry devices.

Wet device: The internal temperature of a wet device reached 650°F. A hole melted through the base of the switch (close to the heating element). The externally applied spark ignited the fumes and flames engulfed the switch.

Dry device: The internal temperature of a dry switch reached over 1000°F. The switch base flopped over. The externally applied spark ignited the fumes and flames engulfed the switch.

Conclusion: The plastic base with brake fluid can be ignited when 5 Watts of electrical power are dissipated as heat in the switch for 15 minutes, followed by a spark.

Test A

Objective: Identify the interactions of the materials found in the switch returned from the Reddick report by placing a brass and copper electrode in a pool of brake fluid with a 12 volt potential between them.

Results: After 24 hours, a black residue formed on both electrodes. The brake fluid did not ignite.

Conclusion: The material found in the switch returned from the Reddick report was a result of an interaction between brake fluid, the internal switch components and the continuous electrical field present in the vehicle.

Test B

Objective: Show that the brake pressure switch is capable of supporting the maximum design current load by applying 15 Ampe through the switch contacts until they reach a stable temperature.

Results: The temperature rise stabilized at 36°F after 10 minutes. Vehicle test results show a maximum temperature of 250°F at the left-hand engine mount. This mount is near the brake pressure switch. With the temperature rise observed, the maximum temperature the brake pressure switch is exposed to is 286°F. This is less than the 433°F melting point of the plastics used in the switch base.

Conclusion: The brake pressure switch will not ignite under extreme vehicle environmental conditions. Heat to cause an ignition must come from a source outside of the normal design of the switch. To ignite a switch, either an external source, or an internal short to ground must provide heat.

Test 6a

1992 & 1993 Town Car Underhood Fires**Attachment 4**

Objective: Determine if corrosive degradation of switch electrical components can cause a decrease in electrical isolation (and thus a source of heat) in the switch that may lead to an ignition. Subject the switch to the following conditions:

- 5% NaCl in tap water solution is injected into contact cavity of a switch.
- 14 Volts is applied to the switch.
- Hexport is grounded.
- Current is limited at 15 Amps.

Results: Of 4 samples tested, over a 2 - 3 hour period, the switch leakage current averaged 1 Amp while reaching peaks of 10 Amps. Near the end of the experiment with leakage current greater than 2 Amps, the switch bases started to melt. 2 of the switches continued to heat until the plastic ignited. The other 2 continued to melt until electrical connection was broken.

Conclusion: Corrosion materials can create a conductive path that may lead to ignition. In this experiment, NaCl was used to accelerate the corrosion in the switch. Other corrosive processes may yield the same results.

Test 7

Objective: Determine if switches meet cycle life specification by running the life cycle test beyond specification until the switch performance is degraded.

Results: The first sample developed a leak in the kapton seal after 728,000 cycles. The mean time to developing leaks was determined to be 1,200,000 cycles.

Conclusion: The kapton seal exceeds design specification of 500,000 cycles.

Test 15a

Objective: Determine if long time switch exposure to brake fluid can lead to an ignition.

Results: Test is ongoing. Results to date show no increase in conductivity of both new and used brake fluid. At 350 hours of testing, current draw on each device is less than 20 mAmps.

Conclusion: 350 hours of brake fluid exposure is not sufficient to cause ignition. At 350 hours of testing, current draw remains below the levels needed to create ignition as simulated in laboratory experiments.

1992 & 1993 Town Car Underhood Fires

Attachment 4

Test 8b

Objective: Understand the ignition process, determine the current path and establish a repeatable ignition method.

Results: Multiple attempts at ignition, via injection of a 5% NaCl in tap water into the contact cavity of switches, has resulted in a repeatability rate of approximately 50%. Plots of hexport current vs. time show an increase in leakage current until the point of ignition in 2 to 3 hours.

Conclusion: A repeatable laboratory method for switch ignition has been established. Based on hexport current measurements, the current path is from switch terminals to hexport body. When a NaCl in tap water solution is repeatedly injected into the contact cavity of powered switches, electrolytic corrosion of the switch terminals results in an increase in terminal resistance and a conductive path to the sensor housing. When sufficient power is drawn through the terminal and conductive path, the materials inside the switch heat. These materials may begin to glow red hot. A hole melts through the switch base and ignition occurs. There is arcing visible throughout the corrosion process that may provide the spark necessary for ignition.

Test 13a

Objective: Compare various fluids in the established ignition method.

Results: A switch filled with 5% NaCl in tap water resulted in an ignition when average hexport leakage current exceeded 2.5 Amps during a 9 hour test. Switches that were filled with tap water and rainwater drew less than 10 mAmps during a 3-hour test and showed little signs of corrosion. Switches filled with new and used brake fluids, with water and without water, all had less than 3 mAmps leakage current and showed no signs of accelerated corrosion.

Conclusion: NaCl in tap water is the most effective method for creating a short-term corrosion to produce heat in the switch. While brake fluid is not as effective in producing corrosion for a lab test, it does produce corrosion when introduced into the switch cavity.

Test 15

Objective: Compare the burn characteristics of various plastics that have the potential to be used as switch base materials. Plastics tested have melting and flowing characteristics compatible with the molding process of the switch base.

Results: When 5% NaCl in tap water was injected into switches with different base materials, the following results were obtained: Gallenax 4300 ignited 3 out of 5 attempts. Noryl ignited 2 out of 5 attempts. Zytel ignited 1 out of 5 attempts.

Conclusion: Different plastics exhibit different ignition characteristics. None of the plastics tested guaranteed protection against ignition.

1992 & 1993 Town Car Underhood Fires

Attachment 4

Test 15b

Objective: Compare: 1) the probability of switch ignition in the vertical position (connector up) versus a 45° orientation and 2) the probability of switch ignition as a function of rotational angle (about the switches length axis) in the 45° orientation.

Results: Switch ignitions in the lab occurred with the switches mounted both vertically and 45° from vertical. In addition, switch ignitions in the lab occurred at various rotational angles.

Conclusion: Switch ignition does not appear to be sensitive to vertical orientation vs. 45° orientation nor to rotational angle in the 45° orientation.

Test 16



Objective: To test proposed relay circuit.

Results: A switch was injected with 5% NaCl in tap water solution and placed in a proposed current limiting circuit for 48 hours. The current draw remained constant at 180 mAmps throughout the test. There was no thermal activity observed and the contact arm remained intact.


A switch was brought to a high leakage current condition using the established ignition method. An impending burn is a condition where a corrosive resistance has built up in the switch and an ignition is imminent as determined by observing leakage current. The switch was placed in the proposed relay circuit for 18 hours where it drew 180 mAmps, showed no visible thermal activity and did not result in a burn. Because the proposed relay circuit acts as a resistor that limits current to the switch, the maximum power to the switch is limited to 0.75 Watts. A resistive wire was wrapped around the base of the switch and 0.75 Watts of power was applied to the wire. The wire became warm to the touch but had no effect on the switch.

Conclusion: 0.75 Watts, the maximum power in the proposed circuit design, is not enough power to cause switch terminal heating sufficient for ignition. In previous tests, using a resistor as the heating element, approximately 5 Watts of power was necessary to create an ignition. There is not enough power in the proposed circuit to create ignition.

Hexport Current vs. Time Fluid Ingress Experiment



Hydraulic Pressure Switch Cross Section



FAX COVER SHEET

DRAFT REVIEW OF SAFETY RECALL 99S15

6/13/99

FAX

TO: R. Wheelock - ESE (Legal/OGC)
A. Martin - P&L
R. Wooten - Claims/Adj
T. Day - CLOIS
J. Kafati - AVT
N. Vert - Owner Relations
D. Welter WDMO
T. Lusardi - Tech Hotline

42268
61166
54338
06727
81288 ✓
88288 ✓
53817
54501 ✓

03887

FROM: Al Lasse - FCSD/Recall PH 39-08877 FAX 84-81024

Please respond to this review promptly by phone or FAX.


Approved: _____

Approved With Changes: _____

Not Approved: _____

Name and Date of Reviewer: _____

Date: _____

DRAFT

To: All FCSD Regional Managers

cc: All Regional Sales Managers
Ford Division
All PDC Managers

Subject: Safety Recall 99015: Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control - Brake Pressure Switch

See the Dealer Bulletin for program details.

REGIONAL/DEALER ACTION

Federal law requires that dealer stock vehicles must be corrected before delivery.

Advise FCSD, using Form 7256, if a dealer reports that an affected vehicle is not at the location shown in our records.

Make sure regional personnel understand the service procedures before assisting dealers or customers.

QUESTIONS?

Claims Information	1-800-423-8851
Other Recall Questions	1-800-325-8821

A. R. O'Neil
Director
Vehicle Service and Programs

DRAFT

Service Recall Bulletin

May, 1999

TO: All Ford and Lincoln Mercury Dealers**SUBJECT:** Safety Recall 99015: Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control - Brake Pressure Switch**AFFECTED VEHICLES**

Certain 1992 and 1993 Crown Victoria and Grand Marquis with Speed Control built at the St. Thomas assembly plant from February 5, 1992 through November 30, 1992. Also, certain 1992 and 1993 Town Cars built at the Wixom Assembly plant from November 4, 1991 through November 30, 1992.

REASON FOR RECALL

Some brake pressure switches that were installed on the affected vehicles may have been improperly crimped. Over time, these switches may develop a resistive short in the electrical circuit. This short may cause the fuse to open and disable the cruise control circuit. It is also possible for the switch to short without opening the fuse. This could cause the switch to generate sufficient heat to cause a fire, even while the vehicle is not running.

SERVICE ACTION

The dealer will replace the brake pressure switch with a current production switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

ATTACHMENTS

Attachment I: Administrative Information

Attachment II: Labor Allowances and Parts Ordering Information

Attachment III: Technical Information

QUESTIONS?

Claims Information: 1-800-423-8851

Other Recall Questions: 1-800-325-8821

Sincerely,

A. R. O'Neill
Director
Vehicle Service and Programs

3713 2207

DRAFT**ATTACHMENT I****Page 1 of 1****Safety Recall 99016**

**Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars
with Speed Control - Brake Pressure Switch**

QAS19

You must use QAS19 to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.

OWNER REFUND

Ford Motor will only refund for owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII Manual for Refund information.

ATTACHMENT II
Page 1 of 1**Safety Recall 99016**
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Brake Pressure Switch**LABOR ALLOWANCES**

DESCRIPTION	LABOR OPERATION	LABOR TIME
Replace Brake Pressure Switch and Hard-shell Connector	99815B	0.5 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS**Parts Ordering Information**

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	31 days after launch	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-6821

Part Number	Description	Quantity
TBD	Brake Pressure Switch Kit	1

DEALER PRICE

For latest prices, check or call your:

- Order Processing Center
- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

JOB #31041 88515 Part D THIRD DRAFT 5/10/99

ATTACHMENT B
PAGE 1 OF 2
SAFETY RECALL 88515

BRAKE PRESSURE SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES:

CERTAIN 1992 AND 1993 CROWN VICTORIA, GRAND MARQUIS
AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the brake pressure switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the new connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the brake pressure switch. See Figure 1




FIGURE 1

OPR © 1999 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
600

I.S. XXXX

SHEET 1 OF 2

BRAKE PRESSURE SWITCH AND
CONNECTOR REPLACEMENT

RYS

△DRAFT △DRAFT △DRAFT △DRAFT

3713 2210

△DRAFT △DRAFT △DRAFT △DRAFT △DRAFT

JOB #31041 99815 Part D THIRD DRAFT 8/10/99

ATTACHMENT W
PAGE 2 OF 2
SAFETY RECALL 99815

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 2.




FIGURE 2

4. Obtain the new connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully sealed in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the brake pressure switch from the parts kit.
7. Remove the old brake pressure switch.
8. Fill the new brake pressure switch with High Performance DOT 3 Brake Fluid and install the brake pressure switch. Tighten the switch to 18 Nm (13 lb-ft).
9. Attach the electrical connector to the brake pressure switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
 - Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.

© 1999 FORD MOTOR COMPANY
 CLARKSON, MICHIGAN 48121
 500

I.S. XXXX

SHEET 2 OF 2

BRAKE PRESSURE SWITCH AND
CONNECTOR REPLACEMENT

JTB

ADRAFT ADRAFT ADRAFT ADRAFT

3713 2211

ADRAFT ADRAFT ADRAFT ADRAFT ADRAFT

DRAFT

A. R. O'Neil
Director
Vehicle Service and Programs
Ford Customer Service Division



Ford Motor Company
P. O. Box 1804
Dearborn, Michigan 48121

May, 1999

Safety Recall 99S16

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control.

SAFETY DEFECT

Some brake pressure switches that were installed on the affected vehicles may have been improperly crimped. Over time, these switches may develop a resistive short in the electrical circuit. This short may cause the fuse to open and disable the cruise control circuit. It is also possible for the switch to short without opening the fuse. This could cause the switch to generate sufficient heat to cause a fire, even while the vehicle is not running.

REPAIRS

The dealer will replace the brake pressure switch with a current production switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

Dealers currently have instructions and parts ordering information.

3713 2212

HOW LONG WILL IT TAKE?

The time needed for this repair is less than 1/2 day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 99B15.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

REFUND

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your Ford or Lincoln Mercury dealer. To avoid delays, do not send receipts to Ford Motor Company.

CHANGED ADDRESS OR SOLD THE VEHICLE?

Please fill out the enclosed prepaid postcard and mail it to us if you have changed your address or sold the vehicle.


If the dealer doesn't make the repair promptly and without charge, you may contact the Ford Customer Assistance Center, P. O. Box 5248, Dearborn, Michigan 48121. You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 305-0123).

We regret the inconvenience this service may cause you, but we want you to have the work done for your safety and satisfaction with your Ford or Lincoln-built vehicle.

Sincerely,

A. R. O'Neill
Director
Vehicle Service and Programs

Town Car Issue Rates



TC Issue Rates (percentages)

■	0.263 to 0.71	(8)
■	0.167 to 0.263	(5)
■	0.104 to 0.167	(2)
□	0.08 to 0.104	(4)
□	0.032 to 0.08	(7)

92 sales per state
Worst Louisiana
South east States

5300

3713 2214



BUILDCHT, KLS

Page 1 of 1

Date Issued: 16 March 1999
Date Revised: 3/18/99

code for what the customer comment is

All Brake Pressure Switch Replacements on Panther Vehicles 92/93 by Concern

MDL_YR	(All)
--------	-------

Customer Concern Code	Data	
	Sum of COSTS	Sum of REPAIRS
A25 - ENGAGEMENT TROUBLES (SPRFB CONTROL)	\$20,925	149
N17 - BRAKES NOISY	\$5,852	60
A26 - DISENGAGEMENT TROUBLES (SPRFB CONTROL)	\$8,409	44
A99 - ADMINISTRATIVE (PARTS RETURN/ETC.)	\$2,076	27
A27 - DOES NOT MAINTAIN A CONSISTENT SPEED	\$3,191	22
A86 - OTHER ELECTRICAL ACCESSORY TROUBLES	\$4,887	22
N11 - UNUSUAL ENGINE NOISE AT IDLE	\$1,274	18
N58 - OTHER SQUEAK/RATTLE (EXCLUDING WIND NOISE)	\$2,121	15
H05 - EXCESSIVE "BRAKE PEDAL EFFORT" REQUIRED	\$1,026	12
H10 - BRAKE-ABS WARNING LIGHT TROUBLES	\$547	7
L83 - BRAKE FLUID LEAK	\$246	6
N27 - VIBRATION OR SHUDDER WHILE BRAKING	\$888	4
H02 - BRAKES GRAB OR LOCK-UP	\$474	3
C05 - A/C DOES NOT WORK	\$336	2
N22 - VEHICLE VIBRATES WHEN DRIVING BELOW 45 MPH	\$128	2
S25 - SEAT BELT COIL/UNCOIL TROUBLES	\$123	2
P59 - OTHER AUTOMATIC TRANSMISSION TROUBLES	\$423	2
P87 - SHIFTS OCCUR TOO EARLY, TOO LATE, TOO OFTEN	\$1,120	2
P61 - DIFFICULT TO OPERATE SHIFT LEVER	\$150	1
H04 - PARKING BRAKE TROUBLES	\$64	1
N18 - UNUSUAL TRANSMISSION NOISE	\$64	1
C60 - OTHER STEERING/HANDLING AND RIDE TROUBLES	\$55	1
L26 - LIGHTS NOT WORKING-INTERIOR	\$25	1
B05 - BODY PANELS HARD TO OPEN	\$23	1
A88 - WIRING TROUBLES	\$75	1
L68 - POWER STEERING FLUID LEAK	\$52	1
P82 - AUTOMATIC - 4-WHEEL/ALL -WHEEL DRIVE TROUBLES	\$180	1
Grand Total	\$52,485	407

3713 2215

3713 2218



Brake Pressure
Switch

TIS 35

State Code	Sum of R1000	Vehicle Line AWS	Crown Victoria	Grand Marquis	Town Car
AK			0	0	0
AL			1.08	0	0.94
AR			0	0	0
AZ			0.75	1.41	1.29
CA			0.24	0	0.28
CO			2.2	0	0
CT			0.84	1.02	0
DE			3.11	1.98	0
FL			0.73	1.08	0.29
GA			0.4	0.81	0.8
HI			0	0	0
IA			0	0.57	0
ID			0	0	0
IL			0.83	0.88	0
IN			0.68	0.31	0
KS			0.82	0	1.83
KY			0.37	0.6	0
LA			0	0.41	0
MA			0.49	1.5	0.72
MD			0.48	0.61	0
ME			0	0	0
MN			0.62	0.32	0.87
MO			0	0	0
MS			0.31	0.69	0
MT			0	0	0
NC			0	0	0
ND			0.28	0.78	0
NE			0	0	0
NH			0	0	0
NJ			0	1.21	0.41
NM			0	0	1.17
NV			0	0	0
NY			0.14	0.24	0.14
OH			0.85	0.89	0.44
OK			0.88	0	0
ON			0	0	0
OR			0	0	0
PA			1.08	0.77	0.33
RI			0	0	0
SC			0	1.24	0
SD			0	0	0
TN			0	0.41	1.87
TX			0.81	0.72	0.37
UT			0	0	0
VA			0.19	1.03	0.98
VT			0	0	0
WA			1.09	0	0.59
WI			0.48	0.88	1.34
WV			0	0	0
WY			0	0	0

SUM TOTAL
Switch
repairs

T18 38

Sum of REPAIRS	Vehicle Line AWS		
State Code	Crown Victoria	Grand Marquis	Town Car
AK	0	0	0
AL	3	0	1
AR	0	0	0
AZ	1	2	1
CA	3	0	2
CO	2	0	0
CT	2	1	0
DE	1	1	0
FL	7	23	7
GA	2	3	1
HI	0	0	0
IA	0	1	0
ID	0	0	0
IL	8	8	0
IN	3	1	0
KS	1	0	1
KY	1	1	0
LA	0	1	0
MA	1	8	2
MD	1	1	0
ME	0	0	0
MI	3	3	2
MN	0	0	0
MO	1	2	0
MS	0	0	0
MT	0	0	0
NC	1	2	0
ND	0	0	0
NE	0	0	0
NH	0	0	0
NJ	0	10	2
NM	0	0	1
NV	0	0	0
NY	1	2	1
OH	4	8	2
OK	1	0	0
ON	0	0	0
OR	0	0	0
PA	8	8	1
RI	0	0	0
SC	0	2	0
SD	0	0	0
TN	0	1	2
TX	8	7	3
UT	0	0	0
VA	1	3	2
VT	0	0	0
WA	1	0	1
WI	1	8	2
WV	0	0	0
WY	0	0	0

TIS 38

Volumes
1992 MY

State Code	Sum of VEHICLES	Vehicle Line AWS	Grand Marquis	Town Car
AK	129	0	0	0
AL	2829	1972	1089	0
AR	1774	1250	889	0
AZ	1330	1422	777	0
CA	12488	5282	7754	0
CO	908	583	205	0
CT	3110	981	709	0
DE	322	508	285	0
FL	9530	21290	24517	0
GA	4958	3895	1907	0
HI	159	0	0	0
IA	1503	1758	307	0
ID	210	293	0	0
IL	6090	9101	3232	0
IN	4685	3195	1484	0
KS	1225	1338	616	0
KY	2580	1677	1254	0
LA	3585	2428	1832	0
MA	2055	5348	2787	0
MD	2200	1898	1200	0
ME	1842	481	0	0
MI	4575	9482	2987	0
MN	1808	1898	333	0
MO	3258	3417	1928	0
MS	1573	1021	529	0
MT	224	181	0	0
NC	3851	2537	1409	0
ND	355	358	0	0
NE	578	738	197	0
NH	520	508	177	0
NJ	2806	5291	4941	0
NM	551	728	558	0
NV	551	352	288	0
NY	7257	8371	7308	0
OH	7234	7225	4552	0
OK	1799	1539	1103	0
ON	374	0	0	0
OR	858	544	153	0
PA	5854	6479	3051	0
RI	357	0	0	0
SC	3229	1608	844	0
SD	390	275	0	0
TN	1830	2454	1195	0
TX	9863	9882	8122	0
UT	212	282	0	0
VA	5145	2599	2075	0
VT	212	121	0	0
WA	917	551	1508	0
WI	2053	3540	1482	0
WV	716	558	155	0
WY	427	145	0	0

* Note printed by TMASTERS on 9 Apr 1999 at 07:27:58 *

From: JNEME --DRBN005
To: TMASTERS--DRBN005
FPORTER --DRBN007
cc: SCOLEL --DRBN005

Date and time 04/08/99 15:13:23
TDONOVAN--DRBN005

FROM: Joseph E. Neme USAET(UTC -04:00)
SUBJECT: Town Car Underhood Fires
See notes below... please let me know when we can have a 14D to review
with Jack Paskus and Bill Bohan...thanks

Joseph E. Neme
LVC - Safety
Phone: 39-08133, Fax:62-18147, E-Mail:jneme@ford.com
Location: MD1255/Cube 2M37, Building #2 Textpager:313-795-7003
*** Forwarding note from JMCINERN--DRBN005 04/08/99 15:10 ***
To: JNEME --DRBN005

FROM: John McInerney USAET(UTC -04:00)
Subject: Town Car Underhood Fires

Regards,
John McInerney:Tech Specialist-Safety,LVC-OPD Safety and Police
Engineering. 313-322-0276, Pager:313-795-9243 or TEXTPAGE "Cel"
phone:734-765-7534,"FORD-Building the Safest Cars in the World"
*** Forwarding note from JPASKUS --DRBN005 04/08/99 13:17 ***
To: JMCINERN--DRBN005
cc: JPASKUS --DRBN005

FROM: Jack Paskus USAET(UTC -04:00)
Subject: Town Car Underhood Fires

I agree with Bill. Please organize a session to make it happen. Thanks

Regards,
Jack Paskus, Engineering Director, LVC
Room 13G112, MD 1131, Building 1
32-22530 FAX: 84-50078
*** Forwarding note from WBOHAN --DRBN005 04/08/99 09:02 ***
To: JPASKUS --DRBN005
cc: LCAMP --DRBN005 WBOHAN --DRBN005

FROM: Bill Bohan USAET(UTC -04:00)
Subject: Town Car Underhood Fires
This note is in reference to the message I left asking you to give me a call.

You'll recall that back in February, I mentioned that we had about 2 months to
investigate the alleged Town Car underhood fires and come to some kind of
decision. Next week will be April 15 and the two months will be up. I
recommend that LVC schedule a Tech Review next week with the possibility of
turning it in to an FRC.

For the meeting, I recommend that the subjects of potential short term field
action, potential permanent field action, potential involvement of other
vehicle lines and all information that can help us determine if we have a
defect be reviewed (in other words, an updated 14d white paper).

Your continuing efforts on this subject are really appreciated.

Regards,
Bill Bohan, Production Vehicle Safety & Compliance Manager
Automotive Safety Office, ESE, Suite 500, Fairlane Plaza South
Phone (313)322-9115;Fax(313)594-2268;email wbohan@ford.com

*given = silicone
 free
 part = from
 front
 end*
*given = silicone
 cannot
 be tested*

BRONCO

F3TB-12A581-AC	F4TB-12A581-AN	F5TB-12A581-AZ	F6TB-12A581-AJ	F7TB-12A581-BJ		
92	93	94	95	96	97	98
E9EB-14A464-AA	F4ZB-14A464-MA	F4ZB-14A464-MA	F4ZB-14A464-MA	F4ZB-14A464-MA		
18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ		
	SHORTING BAR	SHORTING BAR				

CAPRI

92	93	94	95	96	97	98	99
----	----	----	----	----	----	----	----

CROWN VICTORIA/ GRAND MARQUIS

F3AB-14401-AS	F4AB-14401-AE	F5AB-14401-AZ	F6AB-14401-AL	F7AB-14401-AL		XW3T-14401-
92	93	94	95	96	97	98
F2AB-14A464-ADA	F2AB-14A464-ADA	F2AB-14A464-ADA	F2AB-14A464-ADA	F2AB-14A464-ADA	F6OB-14A464-AA	F8OB-14A464-AA
18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ	18Ga . AZ

ECONOLINE

F3UB-12A581-CB	F4UB-12A581-GZ	F5UB-12A581-BZ	F6UB-12A581-CZ	F7UB-12A581-LY		
92	93	94	95	96	97	98
E9EB-14A464-AA	F4ZB-14A464-MA	F4ZB-14A464-MA	F4ZB-14A464-MA	F4ZB-14A464-MA		
SHORTING BAR	SHORTING BAR	SHORTING BAR	SHORTING BAR	SHORTING BAR		

EXPEDITION

92	93	94	95	96	97	98	99
						XL14-12A581-AT	
						F4ZB-14A464-MA	
						16Ga . AZ	

5718 2222