

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 18 OF 61

PART 2 OF 4



WOLK & GENTER

ATTORNEYS AT LAW



DEFECTIVE WIRING IS HIGH ON THE LIST OF POTENTIAL SOURCES OF THE SMOKE THAT BEFELL SWISSAIR 111

Aviation attorney, Arthur Alan Wolk, who has done substantial research in the field of aircraft fires, notes that the United States Navy refused to allow the continued use of Kapton in Navy fighters because of its poor performance, specifically its propensity for arcing and the propagation of dangerous fire-producing sparks.

Long before the MD-11 was manufactured, McDonnell Douglas, one of the largest manufacturers of Navy fighters, was prohibited from using Kapton encased wiring in Navy fighters, yet it chose to use that kind of wiring in the MD-11.

The FAA was made aware long before this crash that Kapton was a hazardous wiring for use in aircraft, yet did not mandate more stringent inspections of aircraft in which Kapton was used as electrical insulation.

Kapton was described by DuPont, its manufacturer, as having "outstanding thermal, mechanical, chemical and electrical properties." In fact, Boeing engineers concluded that Kapton was completely unsuitable because when wires arced within the Kapton insulation, Kapton became a carbon track, allowing further propagation of the electrical arcing, much like a dynamite fuse.

This clearly made Kapton a bomb waiting to go off in any aircraft in which it was utilized.

It is indefensible that both the FAA and the manufacturer of this aircraft would permit the use of electrical wiring in a civilian, passenger carrying airliner, knowing that in an aircraft in which the crew is equipped with an ejection seat, the material was found to be unsuitable because of its fire and arcing propagation characteristics, says Wolk.

This will be undoubtedly a very ugly and embarrassing investigation for the industry and a further embarrassment to the FAA, which already has thousands of lives etched on its tombstone of ineptitude, says Wolk.

For more information about Swissair Flight 111, call Arthur Alan Wolk, Esq. at (215) 545-4220.

1992-93 LINCOLN TOWN CAR UNDERHOOD FIRES

FE98-005

OWNER NAME	ADDRESS	CITY	STATE	ZIP CODE	TELEPHONE NUMBER	VIN	MODEL YEAR	MODEL	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	MILEAGE	ISSUE REPORTED	POSSIBLE PROBLEM DESCRIPTION
		Hugo	OK	744	744	1LNLMB1W1V1	1992	Town Car	02/12/92	03/03/92	08/17/94	COIS/ MOIS	84,863	Fire	Arson linked on exhaust manifold and spread to fire.
		Evergreen Park	IL	604	604	1LNLMB1W1V1	1992	Town Car	10/08/91	02/27/92	06/29/94	COIS	228,248	Fire	Exhaust.
		Spokane	IL	604	604	1LNLMB1W1V1	1992	Town Car	12/19/91	01/04/92	07/30/93	COIS	21,230	Motor	Brake lines.
		Los Angeles	CA	900	900	1LNLMB1W1V1	1992	Town Car	01/15/92	03/03/92	08/20/95	COIS	37,442	Fire	Brake lines.
		Dearborn	MI	481	518 543-0161	1LNLMB1W1V1	1992	Town Car	06/27/91	08/23/91	04/25/96	COIS/ MOIS	317,008	Fire	Motorcycle mail-down issue
		Cincinnati	FL	331	331	1LNLMB1W1V1	1992	Town Car	12/19/91	01/03/92	06/04/93	COIS	15,772	Hydroplaned	Overheated, drive belt broke, A/C broken, derelict.
		Memphis	TN	381	381	1LNLMB1W1V1	1992	Town Car	09/10/92	03/08/93	04/08/96	COIS	51,560	Fire	Brake lines.
		Pt. Limestone	FL	331	331	1LNLMB1W1V1	1992	Town Car	04/07/92	10/02/92	04/21/97	COIS	50,802	Smoke	Master pressure switch caught on fire and burned the wiring.
		San Jose	CA	951	951	1LNLMB1W1V1	1992	Town Car	07/23/92	08/23/93	12/27/94	COIS	25,837	Motor	Overheated, motor unit.
		Potomac	MD	208	208	1LNLMB1W1V1	1992	Town Car	08/23/92	09/22/92	01/05/95	COIS	40,115	Overheated	Spark plug wires melted.
		Evry	OH	441	441	1LNLMB1W1V1	1993	Town Car	07/28/93	11/23/93	08/23/94	COIS	14,532	Fire	Exhaust.
		Northbrook	IL	600	600	1LNLMB1W1V1	1993	Town Car	08/05/92	11/05/92	03/28/93	MOIS	40,000	General	Electrical wiring.
		Wapahville	IL	600	600	1LNLMB1W1V1	1993	Town Car	08/27/92	09/15/92	08/14/96	MOIS	83,508	Fire	Unknown.
		Englewood	ND	580	580	1LNLMB1W1V1	1993	Town Car	08/18/92	12/18/92	07/25/94	MOIS	12,000	Fire	Unknown.
		New Orleans	LA	701	701	1LNLMB1W1V1	1993	Town Car	08/25/93	09/10/93	08/08/95	MOIS	4,808	Fire	Unknown.
		Iron Station	NC	281	281	1LNLMB1W1V1	1993	Town Car	04/01/93	04/16/93	08/24/94	MOIS	25,811	Fire	Unknown.
		Pittsburgh	PA	152	152	1LNLMB1W1V1	1993	Town Car	12/04/92	01/03/93	03/23/95	MOIS	12,880	Fire	Wiring harness.
		Rochester	NY	146	146	1LNLMB1W1V1	1993	Town Car	03/10/92	06/03/92	09/04/95	MOIS	20,000	Fire	Unknown.
		Mount Laurel	FL	331	331	1LNLMB1W1V1	1992	Town Car	11/25/91	12/21/91	08/27/98	MOIS	46,800	Fire	Unknown.
		Myrtle Beach	FL	295	295	1LNLMB1W1V1	1992	Town Car	07/08/92	09/14/92	06/28/97	MOIS/ VOO	80,000	Fire	Unknown.
		Staten Island	LA	701	701	1LNLMB1W1V1	1992	Unknown	Unknown	Unknown	08/16/95	MOIS	84,508	Fire	Unknown.
		Indianapolis	IN	462	462	1LNLMB1W1V1	1992	Town Car	05/11/92	07/08/92	08/22/93	MOIS	80,000	Fire	Unknown.
		Jackson	MS	392	392	1LNLMB1W1V1	1992	Town Car	08/25/92	08/21/92	07/01/98	MOIS	84,888	Fire	Unknown.
		St. Matthews	LA	701	701	1LNLMB1W1V1	1992	Town Car	05/14/92	01/01/93	09/11/97	MOIS	95,800	Fire	Unknown.
		Fort St. Louis	FL	331	331	1LNLMB1W1V1	1992	Town Car	07/21/92	10/08/92	01/08/98	MOIS/ VOO	81,000	Fire	Unknown.
		Stuart	FL	331	331	1LNLMB1W1V1	1992	Town Car	04/08/92	04/17/92	12/03/97	MOIS	1	Fire	Unknown.

3713 2512

1992-93 LINCOLN TOWN CAR
UNDERHOOD FIRES

PE95-056

NO.	DRIVER NAME	ADDRESS	CITY	STATE	ZIP	TELEPHONE	VIN	MODEL	YEAR	MODEL	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	MILEAGE	MILEAGE REPORTED	POSSIBLE PROBLEM DESCRIPTION
2			Dayton	TX			1LNLMB2VWNY	1992	Town Car	1992	03/03/92	03/03/92	03/17/94	MORE	37,000	File	Unknown.
2			Seelye Hills	CA			1LNLMB2VWNY	1992	Town Car	1992	03/03/92	03/03/92	03/17/94	MORE	125	File	Unknown.
2			San Ramon	LA			1LNLMB2VWNY	1992	Town Car	1992	10/11/91	11/14/91	01/12/93	MORE	16,800	File	Unknown.
3			Womansville	TX			1LNLMB2VWNY	1992	Town Car	1992	03/18/92	03/24/92	04/30/92	MORE	88,800	File	Unknown.
3			Apex	FL			1LNLMB2VWNY	1992	Town Car	1992	05/09/92	05/10/92	12/22/92	MORE	82,800	File	Engine compartment, gas leak.
3			Topwell	GA			1LNLMB2VWNY	1992	Town Car	1992	03/28/92	04/10/92	05/28/92	MORE	20,000	File	Unknown.
3			Alpharetta	IL			1LNLMB2VWNY	1992	Town Car	1992	07/23/92	08/17/92	10/12/92	MORE	60,212	File	Brakes.
3			Regina	NY			1LNLMB2VWNY	1992	Town Car	1992	09/23/92	09/30/92	07/03/93	MORE	11,089	File	Brakes.
3			Credley	TX			1LNLMB2VWNY	1992	Town Car	1992	08/04/92	08/20/92	12/22/92	MORE	72,088	File	Unknown.
3			Apex	TX			1LNLMB2VWNY	1992	Town Car	1992	05/08/92	05/22/92	08/01/92	MORE	38,089	File	Fire starting above the fuel tank fire.
3			Summit Hill	NY			1LNLMB2VWNY	1992	Town Car	1992	07/18/92	07/24/92	08/24/92	MORE	1	File	Engine compartment.
3			Greenwood	MS			1LNLMB2VWNY	1992	Town Car	1992	05/25/92	06/14/92	06/04/92	MORE/VOO	47,594	File	Wiring harness in engine compartment.
3			Wading	FL			1LNLMB2VWNY	1992	Town Car	1992	07/27/92	08/03/92	07/28/92	MORE	47,800	File	Brakes.
4			Sanford	TX			1LNLMB2VWNY	1992	Town Car	1992	03/05/92	03/21/92	12/07/92	MORE	128,000	File	Under the hood - oil leak, pressure sensor for the ABS.
4			Remondine	FL			1LNLMB2VWNY	1992	Town Car	1992	03/18/92	04/18/92	08/03/92	MORE	1	File	Unknown.
4			E. Ashburn	NY			1LNLMB2VWNY	1992	Town Car	1992	10/21/92	05/11/93	09/21/92	MORE	60,800	File	Under the hood.
4			Albany	NC			Unknown	1993	Unknown	Unknown	Unknown	Unknown	12/08/92	MORE	88,800	File	Under the hood.
4			Blair	FL			1LNLMB2VWNY	1992	Town Car	1992	11/19/92	12/05/92	01/02/93	MORE	40,800	File	Under the car.
4			Local Police	FL			1LNLMB2VWNY	1992	Town Car	1992	07/23/92	08/14/92	12/05/92	MORE	47,800	File	Under the engine.
4			Farm Hill	NY			1LNLMB2VWNY	1992	Town Car	1992	12/04/91	13/24/91	07/12/92	MORE	1	File	Electrical short.
4			Chickadee	NC			1LNLMB2VWNY	1992	Town Car	1992	09/27/91	09/28/91	02/28/92	MORE	88,000	File	Front suspension.
4			Johnson	OH			1LNLMB2VWNY	1992	Town Car	1992	04/14/92	04/24/92	11/01/92	MORE/VOO	100,000	File	Ignition or electrical system.
4			Quana	GA			1LNLMB2VWNY	1992	Town Car	1992	08/21/92	03/10/93	04/28/93	MORE	83,000	File	Unknown.
5			Spring City	MO			1LNLMB2VWNY	1992	Town Car	1992	05/03/92	09/18/92	10/08/92	MORE	72,800	File	Electrical system.
5			Houston	TX			1LNLMB2VWNY	1992	Town Car	1992	08/27/91	11/02/91	04/28/92	MORE	65,000	File	Electrical.
5			Lee's Summit	MO			1LNLMB2VWNY	1992	Town Car	1992	10/22/91	12/14/91	05/28/92	MORE	71,000	File	Brake system safety.

3713 2513

1992-93 LINCOLN TOWN CAR UNDERHOOD FIRES

PE98-055

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP	TELEPHONE	VIN	YEAR	MODEL	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	MILEAGE	MI/RE REPORTED	POSSIBLE PROBLEM DESCRIPTION
			San Juan Beach	FL			1LNLM81PWN	1992	Town Car	12/11/91	8/15/92	8/11/92	MORE	70,800	Fire	Electrical.
			Westlake	LA			1LNLM81PWN	1992	Town Car	8/25/92	8/11/92	8/11/92	MORE/VOO	65,700	Fire	Unknown.
			West	LA			1LNLM82V5A	1992	Town Car	8/15/92	8/8/92	12/20/92	MORE/VOO	80,800	Fire	Electrical short.
			West Palm Beach	FL			1LNLM82W7W	1992	Town Car	8/4/2/92	12/11/92	10/14/92	MORE	75,000	Fire	Electrical.
			Wylton	TX			1LNLM81W2N	1992	Town Car	8/14/92	8/4/92	8/2/92	MORE/VOO	67,800	Fire	Electrical system.
			Wynon	TX			1LNLM82W4W	1992	Town Car	9/4/92	8/8/92	8/2/92	MORE	53,800	Fire	Engine.
			Wynon	TX			1LNLM82V5A	1992	Town Car	12/17/91	9/4/2/92	8/11/92	MORE	103,800	Fire	Unknown.
			Wynon Park	IL			1LNLM82W4W	1992	Town Car	12/20/91	10/20/92	8/2/92	MORE	85,000	Fire	Low level fire.
			Wynon	TX			1LNLM82W7W	1992	Town Car	8/4/92	1/8/92	8/2/92	MORE	88,800	Fire	Unknown.
			Wynon	FL			1LNLM82W3N	1992	Town Car	8/20/92	8/2/92	8/2/92	MORE	28,000	Fire	Unknown.
			Wynon Beach	FL			1LNLM82W3N	1992	Town Car	8/11/91	8/20/91	8/11/92	MORE/VOO	70,800	Fire	Low level, wheel drive.
			Wynon	TX			1LNLM81W3N	1992	Town Car	8/4/92	8/2/92	8/2/92	MORE	60,800	Fire	Engine.
			Wynon	VA			1LNLM81W3N	1992	Town Car	8/4/92	8/2/92	8/2/92	MORE	111,300	Fire	Unknown.
			Wynon	TX			1LNLM81W3N	1992	Town Car	8/4/92	8/2/92	8/2/92	MORE	108,000	Fire	Under the hood.
			Wynon	VA			1LNLM81W3N	1992	Town Car	8/4/92	11/20/91	8/11/92	MORE	78,000	Fire	Unknown.
			Wynon	TX			1LNLM81W3N	1992	Unknown	Unknown	Unknown	8/2/92	MORE	1	Fire	Under the hood.
			Wynon	MA			1LNLM81W3N	1992	Town Car	8/4/92	8/2/92	8/2/92	MORE	67,000	Fire	Electrical short.
			Wynon	LA			1LNLM82W4W	1992	Town Car	8/15/92	8/8/92	10/20/92	MORE	48,000	Fire	Electrical.
			Wynon Holly	MA			1LNLM81W4P	1992	Town Car	10/13/92	12/20/92	8/2/92	MORE	88,000	Fire	Electrical.
			Wynon Columbia	SC			Unknown	1992	Unknown	Unknown	Unknown	8/2/92	MORE	8,000	Garage	Engine.
			Wynon	GA			1LNLM81W7W	1992	Town Car	8/2/92	8/2/92	8/2/92	MORE	84,000	Fire	Catalytic converter.
			Wynon	UK			1LNLM81W3N	1992	Town Car	8/2/92	8/2/92	8/2/92	MORE/VOO	118,000	Fire	Spark plug/wire.
			Wynon Bristol	FL			1LNLM81W3N	1992	Town Car	8/4/92	8/8/92	8/11/92	COE	48,000	Fire	Overhead switch.
			Wynon	MA			1LNLM82W3N	1992	Town Car	11/25/91	11/22/91	Unknown	VOO	Unknown	Fire	Unknown.
			Wynon	MA			1LNLM82W3N	1992	Town Car	8/20/92	8/20/92	Unknown	VOO	Unknown	Fire	Unknown.
			Wynon	MA			1LNLM81W3N	1992	Town Car	8/2/92	8/2/92	Unknown	VOO	Unknown	Fire	Unknown.

3713 2014

1992-93 LINCOLN TOWN CAR UNDERHOOD FIRES

FEB-94

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP CODE	TELEPHONE NUMBER	VIN	MODEL YEAR	MODEL	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	RELEASE	ISSUE REPORTED	POSSIBLE PROBLEM DESCRIPTION
19	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/07/92	08/28/92	Unknown	VOG	Unknown	Fire	Unknown
20	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	03/05/92	02/18/92	Unknown	VOG	Unknown	Fire	Unknown
21	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/12/92	03/21/92	Unknown	VOG	Unknown	Fire	Unknown
22	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/27/92	05/12/92	Unknown	VOG	Unknown	Fire	Unknown
23	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	03/20/92	04/23/92	Unknown	VOG	Unknown	Fire	Unknown
24	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/18/92	07/19/92	Unknown	VOG	Unknown	Fire	Unknown
25	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	05/20/92	05/20/92	Unknown	VOG	Unknown	Fire	Unknown
26	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/23/92	05/15/92	Unknown	VOG	Unknown	Fire	Unknown
27	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	05/20/92	11/25/92	Unknown	VOG	Unknown	Fire	Unknown
28	Unknown	Unknown	Unknown	FL	MA	Unknown	1LNLM0700N	1992	Town Car	04/02/92	05/11/92	04/02/92	VOG	Unknown	Fire	Engine
29	Unknown	Unknown	Unknown	MD	MA	Unknown	1LNLM0700N	1992	Town Car	05/14/92	05/23/92	05/14/92	VOG	Unknown	Fire	Unknown
30	Unknown	Unknown	Unknown	TX	MA	Unknown	1LNLM0700N	1992	Town Car	04/23/92	05/20/92	Unknown	VOG	Unknown	Fire	Engine compartment
31	Unknown	Unknown	Unknown	TX	MA	Unknown	1LNLM0700N	1992	Town Car	05/14/92	05/14/92	11/25/92	VOG	Unknown	Fire	Engine compartment
32	Unknown	Unknown	Unknown	TX	MA	Unknown	1LNLM0700N	1992	Town Car	11/24/92	12/07/92	12/06/92	VOG	Unknown	Fire	Engine compartment
33	Unknown	Unknown	Unknown	NY	MA	Unknown	1LNLM0700N	1991	Town Car	11/03/92	11/20/92	05/01/93	VOG	Unknown	Fire	Engine compartment
34	Unknown	Unknown	Unknown	CA	MA	Unknown	1LNLM0700N	1992	Town Car	07/12/92	10/20/92	02/01/93	VOG	Unknown	Fire	Unknown
35	Unknown	Unknown	Unknown	FL	MA	Unknown	1LNLM0700N	1992	Town Car	01/12/92	11/20/92	11/20/92	VOG	Unknown	Fire	Unknown
36	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	02/24/92	04/23/92	05/01/93	VOG	Unknown	Fire	Unknown
37	Unknown	Unknown	Unknown	TX	MA	Unknown	1LNLM0700N	1992	Town Car	05/24/92	07/12/92	10/11/92	VOG	Unknown	Fire	Engine compartment
38	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/18/92	03/27/92	04/24/92	VOG	Unknown	Fire	Engine
39	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/04/92	03/28/92	03/28/92	VOG	Unknown	Fire	Engine
40	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	05/13/92	07/28/92	01/18/93	VOG	Unknown	Fire	Engine compartment
41	Unknown	Unknown	Unknown	MA	MA	Unknown	1LNLM0700N	1992	Town Car	04/24/92	04/23/92	05/01/93	VOG	Unknown	Fire	Left front under area
42	Unknown	Unknown	Unknown	TX	MA	Unknown	1LNLM0700N	1992	Town Car	11/23/92	03/20/92	05/01/93	VOG	Unknown	Fire	Engine compartment
43	Unknown	Unknown	Unknown	FL	MA	Unknown	1LNLM0700N	1992	Town Car	04/08/92	05/01/92	04/14/92	VOG	Unknown	Fire	Engine compartment
44	Unknown	Unknown	Unknown	MA	MA	Unknown	2LSCM0700N	1993	Gr. Mtrg	05/27/93	05/24/93	05/01/93	VOG	Unknown	Fire	Grake hood

3713 2516

1992-93 LINCOLN TOWN CAR
UNDERHOOD FIRES

PE9-056

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP CODE	TELEPHONE NUMBER	VIN	YEAR	MODEL	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	MILEAGE	ISSUE REPORTED	POSSIBLE PROBLEM DESCRIPTION
185	Unknown	Unknown	Unknown	FL	32A	Unknown	2UECMT4M80	1992	Gr. Lim.	05/00/92	05/02/92	08/01/98	VOO	Unknown	Fire	Under hood.
186	Unknown	Unknown	Unknown	FL	NA	Unknown	1NLM82VWYM	1992	Town Car	05/04/92	10/29/92	08/01/98	VOO	Unknown	Fire	Engine compartment.
187	Unknown	Unknown	Unknown	FL	32A	Unknown	1NLM82VWYM	1992	Town Car	04/29/92	05/18/92	07/01/97	VOO	Unknown	Fire	Engine compartment.
188	Unknown	Unknown	Unknown	FL	32A	Unknown	1NLM82VWYM	1992	Town Car	03/28/92	04/18/92	12/01/97	VOO	Unknown	Fire	Left edge of hood and fender.
189	Unknown	Unknown	Unknown	NC	28A	Unknown	1NLM82VWYM	1992	Town Car	05/04/92	06/29/92	08/01/98	VOO	Unknown	Fire	Under hood.
190	Unknown	Unknown	Unknown	FL	32A	Unknown	1NLM82VWYM	1992	Town Car	05/18/92	07/02/92	11/01/98	VOO	Unknown	Fire	Under hood.
191	Unknown	Unknown	Unknown	FL	32A	Unknown	1NLM82VWYM	1992	Town Car	04/15/92	04/29/92	08/01/98	VOO	Unknown	Fire	Under hood.

3713 2518

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 00800807

Date of Request: 02/22/1999 08:17:31 AM

Print Date: 05/28/1999 03:48:36 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006

Phone: (313) 323-6886

PROFS ID: GSTEVEN1

Fax: (313) 390-7224

Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 584-2886

PROFS ID: NLAPONT

Fax: (313) 337-8258

Send Report to:

MD 5006/23086, RVT MATERIALS, BLDG. #5

Bill to:

Acctg Location: 5100

Dept: T113

Work Task: XQ304

Sample Information:

Total Number of Containers: 21

Sample Handling: Return after test

Source: Not specified

Supplier Code: Not specified

Part/Material Name

SPEED CONTROL
CUTOFF SWITCH

Qty

21

Sample Identification

SEE ATTACHED SH
EET

Part Number

F2VY-9F824-A

Material Spec

NA

CPSC Code

00.00.00

Supplier

TEXAS
INST
RUMEN
TS

Investigation Information:

Nature of Investigation:

Failure Analysis

Long Term Project

Requester Info. Box:

Mail typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPOINTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would file report: 04/01/1999

Date customer must have report: 04/01/1999

Report Format(s):

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouche, Blaise

Phone: 84-54876

View your test status at: [HTTP://rd4web.pd7.ford.com/jails](http://rd4web.pd7.ford.com/jails)

Program Name: KALISLab Engr Module

Program Version: 3.0.0

3713 2517

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009900225

Date of Request: 01/29/1999 11:18:53 AM

Print Date: 05/25/1999 03:49:02 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10008

Phone: (813) 323-8888

PROFS ID: GSTEVEN1

Fax: (813) 980-7224

Secondary Contact: LA POINTE, NORM - 10075

Phone: (813) 684-2888

PROFS ID: MLAPONT

Fax: (813) 837-8258

Send Report to:

MD 50082G086, RVY MATERIALS, BLDG. #5

Bill to:

Acctg. Location: 5106

Dept: T113

Work Task: XQG04

Sample Information:

Total Number of Containers: 8

Sample Handling: Dispose after 30 days

Source: Not specified

Supplier Code: Not specified

Part/Material Name

Qty

Sample Identification

Part Number

Material Spec

CPSC Code

Supplier

SPEED CONTROL
CUTOFF SWITCH

8

A,B,C,D,11(E),
AND F

FZY-9F324-A

NA

00.00.00

TEXAS
INST
RUMENTS

Investigation Information:

Nature of Investigation:

Failure Analysis

Long Term Project

Requester Info. Box:

Mail typed report

Additional Sample Information/Testing Requirements:

DISASSEMBLE SWITCHES IN PRESENCE OF PERSONNEL FROM TEXAS INSTRUMENTS. PERFORM ANALYSES TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE.

Reporting Directions:

Date customer would like report: 02/11/1999

Date customer must have report: 02/11/1999

Report Format(s):

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouchie, Steve

Phone: 84-54878

View your test status at: [HTTP://bd4web.pdf7.ford.com/kafar](http://bd4web.pdf7.ford.com/kafar)

Program Name: KALISLab Engr Module

Program Version: 3.0.0

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 00801571

Date of Request: 05/12/1999 03:37:40 PM

Print Date: 05/28/1999 03:49:22 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10000

Phone: (313) 323-8080

PROFS ID: GSTEVEN1

Fax: (313) 380-7224

Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 894-2555

PROFS ID: MLAPOINT

Fax: (313) 387-8258

Send Report to:

MD 80062G066, FVT MATERIALS, BLDG. #6

Bill to:

Acctg Location: 8100

Dept: T113

Work Task: XQ904

Sample Information:

Total Number of Containers: 17

Sample Handling: Return after test

Source: Not specified

Supplier Code: Not specified

Part/Material Name

Qty

Sample Identification

Part Number

Material Spec

CPSC Code

Supplier

SPEED CONTROL

17

SEE ATTACHED SH

F2VY-9F024-A

NA

00.00.00

TEXAS

CUTOFF SWITCH

EET

INST

FLUMEN

TS

Investigation Information:

Nature of Investigation: Requestor Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

Perform Tests as in Lab Number: 9900607

PERFORM TESTS AS IN 9900607 TO ASSIST IN DETERMINING CAUSE OF POSSIBLE LEAKAGE/FIRE. ADDITIONAL SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would like report: 07/01/1999

Date customer must have report: 07/01/1999

Report Format(s):

Log-in Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouche, Steve

Phone: 84-54878

View your test results at: [HTTP://bd4web.pdf.ford.com/kalis](http://bd4web.pdf.ford.com/kalis)

Program Name: KALISLab Eng Module

Program Version: 3.0.0

3713 2519

DEPUEN & EAA
FIELD REPORTS ETC

SCHILLING
LINCOLN/MERCURY

James Farris
Service Manager

Schilling Lincoln-Mercury
2660 South Main
Memphis, TN 38115
(901) 794-4000

Schilling's Guiding Principles

- Practice honesty, integrity and fairness in everything we do.
 - Assess every decision, review value, quality and satisfaction.
 - Create an environment in which our employees can succeed.
 - Return to the community a share of the success and experience.
 - Consistently promote these principles through our Christian behavior.
-

SCHILLING

LINCOLN/MERCURY

SUPER CENTER

2660 S. Mendenhall
Memphis, TN
(901) 794-4000

NEW DIRECT PHONE NUMBERS:
- SERVICE DEPARTMENT
363-1360
- COLLISION REPAIR DEPARTMENT
363-2870 OR 363-2803
- PARTS DEPARTMENT
796-8223

CUSTOMER NO. 26385	NAME ROBERT GUISEPPE	AGE 6434	MAST NO. 5120	DATE 02/22/99	INVOICE NO. LIC883970
	LABOR RATE	DEBIT NO.	158588	COLOR CRYSTAL BLU	STOCK NO.
	VEHICLE MAKE / MODEL 72/LINCOLN/TOWN CAR, 4DR S			DELIVERY DATE 10/23/92	DELIVERY MILE 7
	VEHICLE TYPE / MAKE / MODEL 1988 HONDA 1.6 Y			DELIVERY DATE 03/27/92	
MEMPHIS, TN	AGE NO.	PG. NO.	PG. DATE 02/22/99		
E# 4.6L EFI V8 ENG					

LABOR & PARTS					
JN 1 00LIZOFL2	LOF/LOF-2	TECH(S):355B3		3.50	
	LUB / OIL & FILTER				
	CHANGE OIL & OIL FILTER / LUB CHASSIS				
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 1	1	PKLSC820		9.40	9.40
JOB # 1	1	FL-820-S	FILTER ASY	***	***
JOB # 1	5	XO-5W30-8P	SUPER PREM HOT	***	***
JOB # 1 TOTAL PARTS				9.40	
JOB # 1 TOTAL LABOR & PARTS				12.90	

LABOR & PARTS					
JN 2 20LIZ	TRIN	TECH(S):19879		64.00	
	CUST STATES WONT COME OUT OF PARK AND BRAKE				
	REPLACE BRAKE LIGHT SWITCH AND WIRING.				
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 2	1	FOAZ-13480-A	SW ASY-STP LP	12.99	12.99
JOB # 2	1	OSP-PISTAIL		7.76	7.76
JOB # 2	1	F2UY-9F924-A	SW ASY-SPD CON	16.08	16.08
JOB # 2 TOTAL PARTS				36.83	
JOB # 2 TOTAL LABOR & PARTS				100.83	

LABOR & PARTS					
JN 3 20LIZINT1	INT. TRIM	TECH(S):19879		96.00	
	CHECK RIGHT REAR DOOR LOCK AND				
	REPLACE RIGHT-REAR DOOR LOCK MOTOR				
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 3	1	F5UY-542659-A	ST ASY-DR LAT	44.41	44.41
JOB # 3	1	-38804-81021	BLIND	0.62	0.62
JOB # 3 TOTAL PARTS				45.03	
JOB # 3 TOTAL LABOR & PARTS				141.03	

LABOR & PARTS					
JN 4 02LIZLIGHT	BRAKE WARNING LIGHT	TECH(S):19879		51.20	
	CHECK RED BRAKE LIGHT BULB AND				
	REPLACE BRAKE PRESURE SWITCH				
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 4 TOTAL PARTS				0.00	
JOB # 4 TOTAL LABOR & PARTS				51.20	

MISC	CODE	DESCRIPTION	CONTROL NO	
JOB # A		MAT SHOP SUPPLIES/DISPDISAL FEE		10.00
JOB # 1	LOF	LSC DISCOUNT		-12.92
TOTAL - MISC				-2.92

COMMENTS
ASAP

FORD MOTOR COMPANY
CENTRAL LABORATORY
15000 CENTURY DRIVE
COMMERCE PARK NORTH
DEARBORN, MI 48120
ATTN: DEPT. T118

5770 DRIVELINE CLUNK/JERK DURING TIP-IN/OUT

SOME 1999 EXPEDITION/NAVIGATOR EQUIPPED WITH 5.4L-2V ENGINES AND 4R100 TRANSMISSIONS MAY EXHIBIT A DRIVELINE CLUNK/JERK DURING TIP-IN FROM CLOSED THROTTLE AT VEHICLE SPEEDS ABOVE 43MPH IN 4TH GEAR AND NORMAL TRANSMISSION OPERATING TEMPERATURES. TO REPAIR THIS CONCERN RE-FLASH THE PCM WITH NEW CALIBRATION LEVEL 9VZA-BEF. NOTE: AFTER RE-FLASHING THE PCM, SOME VEHICLES MAY REQUIRE SOME TIME ON THE HIGHWAY TO LEARN PARAMETERS FOR THE MISFIRE PROFILE CORRECTION. A CLUNK MAY BE HEARD DURING THIS LEARNING PROCESS. THIS IS NORMAL AND WILL GO AWAY AFTER THE CUSTOMER HAS DONE SOME HIGHWAY DRIVING.

5771 FORDSTAR VIDEO ANNOUNCEMENT - RECALL 98S36

A A SHORT VIDEO DETAILING THE PROCEDURES UTILIZED FOR COMPLETING RECALL 98S36 (CERTAIN 1986-1995 TAURUS AND SABLE AND 1988-1994 CONTINENTAL VEHICLES - SUB-FRAME REAR PLATE NUT REPLACEMENT) WILL BE BROADCAST ON FORDSTAR DURING THE WEEK OF MARCH 1, 1999 IMMEDIATELY FOLLOWING THE BROADCAST OF TECH TIME. THE VIDEO PROVIDES TIPS FOR THE COMPLETION OF THE RECALL IN THE ALLOTTED TIME. IT MAY BE ADVANTAGEOUS TO TAPE THE BROADCAST FOR YOUR FUTURE REFERENCE. PLEASE REFER TO YOUR "STARGUIDE" FOR THE EXACT BROADCAST TIMES.

1. The first step in the process is to identify the problem. This involves gathering information about the situation and the people involved.

2. The second step is to analyze the problem. This involves breaking the problem down into smaller parts and identifying the causes.

3. The third step is to develop a plan. This involves deciding on the best way to solve the problem and setting goals.

4. The fourth step is to implement the plan. This involves putting the plan into action and monitoring progress.

5. The fifth step is to evaluate the results. This involves checking to see if the problem has been solved and if the goals have been met.

6. The sixth step is to reflect on the process. This involves thinking about what worked well and what could be improved.

7. The seventh step is to share the results. This involves telling others about what you have learned and how you solved the problem.

8. The eighth step is to continue to learn. This involves staying up-to-date on new information and techniques.

9. The ninth step is to apply the knowledge. This involves using what you have learned to solve other problems.

10. The tenth step is to become a problem solver. This involves developing the skills and mindset to tackle any problem that comes your way.

LINE	CODE	DESCRIPTION	CONTROL NO
000000		99-LEAD MATERIALS	
000000		LEAD EPA DISPOSAL FEE	

AD #
NUMBER
2810

WARRANTY
/ OIL
/ PENNED
BOTTOM
/ NO

WARRANTY
/ OIL
/ PENNED
BOTTOM
/ NO

WARRANTY
/ OIL
/ PENNED
BOTTOM
/ NO

02/24/1999 17:25:33

11/15/1992 17:25:33
1992 TRUCK CDR
4.0L SOHC (INJECT)
318,000 4 SPD BU ACCE
4 BR SEVEN CRITTER
ABLE CURE: JN
NO COMPRESSOR REPAIRS (S) FOUND
ADVERTISING START DATE 09/23/1992 BUILD DATE 08/05/1992 START DOWN
LESS THAN TWO YEARS APPROVED AND REPAIR VISITS PAID TO DATE
NO EEP INFORMATION AVAILABLE

FOR NAME INFO CRNO, N. NEW OR 99. BYE

VEHICLE IDENTIFICATION

--	--	--	--	--	--

CUSTOMER'S NAME

ADDRESS

RELEASE

DATE 8/24/99 TIME 8:00

CUSTOMER SERVICE

CONCERN 1: WHAT?

CONCERN 2: WHAT?

CONCERN 3: WHAT?


May we keep your car? Yes _____ No _____

- | | | | |
|--|--|--|---|
| ☐ L.O.I. | ☐ OIL CHANGE | ☐ FUEL FILTER | ☐ SERVICE TRANSMISSION |
| ☐ ROTATE | ☐ TUNE UP | ☐ PCV VALVE | ☐ FLUSH COOLING SYSTEM |
| ☐ BRAKES | ☐ FRONT END ALIGNMENT | ☐ CHECK BELTS AND HOSES | ☐ STATE INSPECTION |
| ☐ WHEEL BALANCE | | | |

April 6, 1999

Vehicle/Owner Information/Accident Info

Model Year: 1992 Make: Grand Marquis Vin#12MECM74W5NX
Miles: Approx 58,000 to 60,000 miles based on old service records
Inspection Date/Location: 4-5-99 Gibsonton, FL Vehicle Owner:
Incident 3-18-99 Approximate miles at incident: 58 to 60,000 miles
Inspector Name: David Burnett EAA 361-575-4174



Reported Info

Area of fire origination (engine compartment quadrant, component, etc)

Quadrant hard to identify—engine compartment driver side appears to hot spot area
Identify if any underhood relays show evidence of internal overheat.

All parts consumed by fire—see photographs

Identify if any fuses or fuse links were blown or show evidence of other damage

All parts consumed by fire—see photographs

Determine if the correct fuse for the stop lamp switch in the fuse box

All parts consumed by fire—see photographs

Identify if there was any damage to wiring in the area where the fire was started (ie chafing, missing insulation)

All parts consumed by fire—see photographs

Assess whether the air suspension pump shows evidence of internal overheating

All parts consumed by fire—see photographs

Identify if there were any aftermarket modifications to the vehicle? (specifically car alarm, trailer tow, or remote start)

No after market equipment seen on burned vehicle or reported to Ins Co.

If possible, identify if the vehicle was involved in a natural disaster/accident that required significant vehicle cleanup? If so where was cleanup performed?

Do not know

If possible, identify vehicle repair history --no prior service problem reported..

Any other info that may be pertinent to the incident...

Per Bill Buckley car was serviced by Bradenton, FL dealer on US 41 or for oil changes-- at a local quick lube location closer to where he lived.--no prior service problem reported..

Vehicle burned in a garage, which was part of a two story house.

Prior to fire vehicle was driven 10-15 miles, then parked in garage for some 3 to 10 minutes when owner heard noises in garage--per Bill Buckley.

David Burnett EAA
361-575-4174

Page 1 of 2

3713 2528

Vehicle/Customer Information/Incident Info

April 6, 1999

Model Year: 1992 Make: Grand Marquis Vin#: 2MECM74W5NX
 Miles: Approx 58,000 to 60,000 miles based on old service records
 Inspection Date/Location: 4-5-99 Gibsonton, FL Vehicle Owner:
 Incident 3-18-99 Approximate miles at incident: 58 to 60,000 miles
 Inspector Name: David Burnett EAA 561-575-4174

Parts that we would like from vehicle if possible to acquire

Brake pressure switch (preferably with wire riserail/connector attached and still attached to prop valve)

Brake switch removed from prop valve—badly burned no pigtail, connector or fluid.

Sample of brake fluid at prop valve (in sealed glass container)

No brake fluid sample possible—all burned—see photographs

Relay pack located on LH fender apron (with as much wiring as possible)

All parts consumed by fire—see photographs

EDIS 8 module located on LH fender All parts consumed by fire—see photographs

Speed control module located on LH fender All parts consumed by fire—see photographs

Air suspension compressor located under air filter All parts consumed by fire—see photographs

Air suspension relay All parts consumed by fire—see photographs

Photograph of door jam VIN sticker

Door jam VIN sticker burned

Other suspect parts

Remains of master cylinder—with possibly a cross threaded fitting?

Remains of several badly burned under hood wire harnesses—driver side

rev 2.0 — 3/

David Burnett EAA
 561-575-4174

S.E.A. INC.
 An FBI Consulting, Inc. Company
 13930 Lyndon Blvd.
 Tampa, Florida 33626
 813 881-1448 800 881-7324
 FAX 813 814-1716

Bill L. Buckley, C.F.I.

www.seainc.com

Page 2 of 2

3713 2529

Case # 39N

1992-95 Town Car/Crown Vic/Grand Marquis/Under Hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Owner Information

Model Year: 1992 Make: GRAND MARQUIS VIN: 2MECMT4W1X
 Present Vehicle Location: COPHART SALVAGE Who owns vehicle now: CUST/INS. CO
 Customer Name: [REDACTED] Phone: [REDACTED]

BM →
 21779
 21779
 21779

Is it ok for engineering to contact customer: YES

Was the vehicle involved in a natural disaster/accident that required significant vehicle clean up? NO

If so, where was cleanup performed? N/A

What is the general repair history of the vehicle? NO MAJOR REPAIRS OTHER THAN MAINTENANCE

Was it equipped with any aftermarket components? (specifically car alarm, trailer tow, or remote start) NO

Insurance Agency Info. (if applicable)

Agency Name: PREMIER ADJUSTING SVCS CNA INSURANCE
 Agency phone number: [REDACTED]

Claim number: P8034501

Contact: Mr. Bill Buckley Phone number: 800-881-7324
(SEA, Inc)

Incident Info

Date of fire: 3-18-99 Mileage: 58,600 Was the vehicle repaired? NO

If repaired, when and where? N/A

Any idea where the fire started? (engine compartment, quadrant... front, back, left, right) DRIVERS SIDE OF ENGINE
BEHIND REAR

Was the vehicle parked or running? PAUSED If parked, where? garage (carport, parking lot) GARAGE

Was the engine ON or OFF? OFF If OFF, how long was it parked before fire? 5-10 minutes

Did customer notice anything unusual prior to fire? NO

Was there any difficulty getting the vehicle out of park? NO Was speed control not working? NO

Was the brake warning lamp illuminated? NO Were the brake lights inoperative? NO

Any other info that you think may be useful to our investigation?

he has seen very similar
Value cover damage - damage to town cars - he
(near brake master cylinder) sees a pattern
is on pattern he sees

03/22/99 MON 14:28 FAX 2488424888

EA ASSOCIATES

Vehicle/Carrier Information/Incident Info

Model Year: 92 Make: LINCOLN

VIN: 1LUMB1W5N0

Mileage (at inspection):

73925

Inspection Date/Location: JARVIS, FL 34116

Vehicle Owner:

LORETTA GLASS

Incident date: 12/23/98

Approximate mileage at incident:

73925

Inspector Name:

DANIEL BARNETT EA

861-575-4774

Parts that we would like from vehicle if possible to acquire

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

SWITCH WAS REPLACED 12/23/98 SEE ATTACHED WORK ORDER
Sample or orifice fluid at prop valve (in sealed glass container) NO PARTS TAKEN

SAMPLE FROM TOP FLUID IN MASTER CYLINDER

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter


Air suspension relay

Photograph of door jam VIN sticker

Other suspect parts

PRIOR TO FIRE MRS GLASS BROKE WINDSHIELD, LOINARDS,
SEATS IN OPERATIVE. ONE WORK PRIOR TO FIRE - NEVER
REPAIRS - ALL NEW WORK - TEST SAYS HE DID NOT REPLACE
ANY FUSES.

SEE ATTACHED OTHER INFO



REV 2.0 - 3/

Page 1072

3713 2531

Vehicle/Customer Information/Incident Info

Model Year: 92 Make: LINCOLN

VIN#: 1LNLMB1W5NY

Mileage (at inspection):

75405 FIRE 73925

Inspection Date/Location: NAPLES, FL 34116

3084 50th LAKE S.W.

Vehicle Owner:

LORETTA GLASS

Incident date: 12/23/95

Approximate mileage at incident: 73925

Inspector Name: DAVID BURNETT SAA

561 575 4174

Requested Info

Area of fire origination (engine compartment quadrant, component, etc)

BRAKE PRESSURE SWITCH AREA - (BELOW BRAKE BOOSTER CYLINDER)

Identify if any underhood relays show evidence of internal overheat

NO EVIDENCE OF OVER HEATED RELAYS

Identify if any fuses or fuse links were blown or show evidence of other damage

SEE ATTACHED FUSE DRAWING, PLANNED - NO BLOWN FUSE LINKS

Determine if the correct fuse for the stop lamp switch is in the fuse box

SEE ATTACHED FUSE DRAWING

Identify if there was any damage to wiring in the area where the fire was started (is chafing, missing insulation)

NO AFTER MARKET EQUIPMENT NOTICED - NO HITCH

Assess whether the air suspension pump shows evidence of internal overheating

LOOKS NORMAL

Identify if there were any aftermarket modifications to the vehicle? (specifically our alarm, trailer tow, or remote start)

NO AFTER MARKET EQUIPMENT NOTICED - NO TRAILER HITCH

If possible, identify if the vehicle was involved in a natural disaster/accident that required significant vehicle clean up? If so where was cleanup performed?

VEHICLE PURCHASED USED IN 93 - LOOK GOOD FOR 92

If possible, identify vehicle repair history

Any other info that may be pertinent to the incident...

SHE SAID SOMEONE IN WASHINGTON CALLED ABOUT FIRST AND
TALKED 45 MIN.

WALGREENS DRUG STORE PERSONNEL CAME OUT ON STREET AND
QUICKLY PUT OUT FIRE - UNDER BRAKE BOOSTER AREA

IN CAR FUSE COVER WAS YELLOW OLD INSIDE COVER?

Page 2 of 2

LORETTA GLASS
92 LINCOLN

3-24-99
DAVID BURNETT EA.
SGI 575474

OTHER INFO

1. NO PARTS WERE REMOVED BECAUSE CAR HAS BEEN REPAIRED AND IS BEING USED BY OWNER MRS GLASS.
2. ARRANGMENTS CAN BE MADE TO REPLACE ANY OF THE LISTED PARTS IF FORD WANTS SOME OF THE COMPONENTS - JUST CALL ME AND ADVISE YOUR WISHES, DAVID BURNETT - 561 575 474 - I WILL WORK OUT DETAILS.
3. [REDACTED] IS MORE THAN WILLING TO BE TRADED OUT OF HIS '92 INTO A BUICK USED MARK III
4. POSSIBLE BUYBACK MIGHT HELP FORD INVESTIGATION BECAUSE THIS VEHICLE HAD VERY MINOR FIRE DAMAGE.
5. THE ONLY PART REPLACED WAS BRAKE PRESSURE SWITCH AND ITS PIG TAIL - PLUS SOME MINOR HEAT DRAWDGE TO A FEW WIRES - WHICH WERE RETAINED.
6. GERMAIN TOED - MECHANIC THAT WORKS ON VEHICLES IN DEC 98 - REMEMBERS THE REPAIR TO A LEAKING SWITCH - BRACE FLUID BLEW IN AREA AND CAT MANIFOLD, OR GOT HOT SOME OTHERWAY - CAR PARKED 5 MINUTES - TIME TO START FIRE. GLO PART WAS NOT SAID.
7. GERMAIN MECHANIC, #109 JIM PAGATA, SAYS IN RECENT TIMES HE ESTIMATES HE HAS REPLACED ABOUT 10 SWITCHES - ALL LEAKING - USUALLY A CRUISE PROBLEM - ALL ONE FIRE - GUY.
8. SUGGESTION: FORD SHOULD CONSIDER LOOKING A SERVICE PARTS STORES FOR THIS SWITCH P/W & POSSIBLY CONSIDER A BULKY RETURN OF DEFECTIVE SWITCHES FOR REVIEW.




DAVID BOER
56 575 4

NAPLES, FL [REDACTED]

LINCOLN TOWN 92
1 COLUMBIA 5 04 [REDACTED]

UPSIDE DOWN



ALMA -

EXPERIMENTAL

LINCOLN MERCURY

MARK Van BUREN
Service Manager



13329 N. Tamiami Trail • Naples, Florida 341
(941) 597-6011 x 224 • Ft. Myers 334-4255 Hol
Naples, FL 34104

13329 N. Tamiami Trail
Naples, Florida 34110

We give that
extra
mile
for you.

Microsoft **Share**

MAPLE
8411 007-0011

FT. MYERS
(841) 234-4000

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED

STATE OF FLORIDA
REGISTRATION: MV - 21231

[illegible]

OFFICE COPY

3713 2536

CHRYSLER LINCOLN MERCURY

13329 N. Tamiami Trail
Naples, Florida 34110

Motorcraft

HAFL 80
30411 807-0019

PT. MYERS
0247 204-0000

STATE OF FLORIDA
REGISTRATION: NY - 21221

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

PLEASE PRINT NAME ADDRESS CITY STATE ZIP		REPLACED PARTS REQUESTED BY CUSTOMER YES ☐ NO ☐ SEE BACK FOR INFORMATION REGARDING SHOP SUPPLIES AND MAINTENANCE WAIVER CHARGE. SEND STORE 7 SAME DAY AIR ARRANGEMENTS ONLY *I hereby authorize the dealer and transporter to ship to specified store with the necessary product and labor that you are responsible for and to provide it when requested to do so. Dealer will make every effort to ship items to the store within 24 hours of receipt of order or to the nearest store. Dealer will be responsible for shipping charges. I agree that the dealer has the right to refuse to ship items that are not in stock. I agree to pay for shipping charges. I agree to pay for handling charges. I agree to pay for insurance charges. I agree to pay for any other charges that may be incurred. I agree to pay for any other charges that may be incurred. I agree to pay for any other charges that may be incurred.
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL
REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL		REPLACEMENT PARTS PART QUANTITY UNIT PRICE TOTAL

SUMMARY OF CHARGES FOR INVOICE 044992

PARTS	24.33
PARTS DISCOUNT	2.44
SUBLET REPAIRS	32.50
LAB-BOOTH SHOP	202.50
SUB-TOTAL	259.89
FL SALES TAX	15.51
TOTAL CHARGE	275.40

PAYMENT DISTRIBUTION FEE INVOICE 04-1997

TOTAL CHARGE	372.30
CASH PAID	372.30

IF YOU HAVE ANY QUESTIONS:



PAGE 2

OFFICE COPY

3713 2536

AUTO

Primary claim rep: Delago, Jack		primary unit: ST		owning office: Naples	
phone: 941-643-8615		ST & AGT: 59-1934		phone: 941-261-5523	
reporting agent: GRAY					
Insured					
name:	[REDACTED]				
street:	[REDACTED]				
city:	NAPLES				
phone home:	[REDACTED]				
contact:	[REDACTED]				
state/prov:	FL				
zip/postal:	[REDACTED]				
Insured vehicle					
year	1992	make	LINCOLN	model	TOWN CAR
body style	4DR				
vehicle identification number	1LNLM81W5NY706341				
license number	[REDACTED]				
prior damage	N				
principle damage:	ELECTRICAL FIRE UNDER HOOD				
vehicle location:	SANTA BARBARA & RADIO RD, WALGREENS PARKING LOT				
POLICY INFORMATION					
vehicles:	1992	LINCOLN	TOWN CAR	4DR	
vehicle identification number:	1LNLM81W5NY706341				
coverage in force	A 100/300/50, P14 10,000, C 5,000, D, G50, E, R1, U3 100/300				
policy source:	PMR				
insurer or leasing company					
BARNETT BANK OF NAPLES INSURANCE DEPT					
claim history					
claim number	date	type	claim number	date	type
59-7067-573	11-25-98	5	59-7512-900	01-05-96	2
59-0485-101	11-19-93	5	59-7434-344	01-04-93	2
59-7337-007	11-15-90	4	59-7262-814	11-09-90	4
59-7015-837	04-09-87	1			
FACTS					
JES-INSO PARKED VEH 1 IN LOT, WENT INTO STORE, CAME OUT OF STORE 5 MINUTES LATER & SAW CAR SMOKING FROM UNDER HOOD					
date and time of loss: [REDACTED]					
location of loss: SANTA BARBARA & RADIO RD, WALGREENS PARKING LOT					
city: NAPLES					
state/prov: FL					
zip/postal: [REDACTED]					

Turn 3750 73925
L 96 cap

3719 2530

DEALERSHIP'S USING ONLY JOB TICKETS SHOULD
AFFIX THE JOB STICKERS IN THIS AREA.

TECHNICIAN'S COMMENTS
INCLUDE DESCRIPTION OF CAUSE

CURE-
TION
CODE

EMP. NO.

FACTOR SELECTED

PARTS RETURN

DATE
SLIP #

Regat leaky Brake & ss. button &
braided wire harness's

CAUSE:

CAUSE:

CAUSE:

CAUSE:

3713 2638

VIN 1LNLM82W6P

Mileage N/A

The vehicle was inspected 3-17-99 at Insurance Auto Auction in Aurora, Illinois with John Kessler of State Farm Insurance.

The vehicle appeared to be in good condition and there is no evidence of collision damage. Also there is no indication the vehicle was ever used as a tow vehicle. The valve cover had been removed at a prior time.

The fire started on the left side of the engine compartment and burned with such intensity that the hood and all components on the left side of the engine melted. No brake fluid was available for analysis. The brake pressure switch and the #12, 15 amp fuse were removed and forwarded to Ford Motor Co.

In a discussion with the State Farm representative I learned that the original State Farm inspector had determined the fire started as a result of a leaking valve cover gasket and removed the valve cover during the initial inspection. I was also told that the owner of the vehicle is a real estate agent and was showing property when the fire occurred. The owner arrived early for her appointment and left the car idling in the driveway. After a while she noticed smoke, raised the hood and the fire spread. There was no indication of how long the vehicle was left running before the fire occurred.

The enclosed photographs detail the extent of the damage.

Dwelle & Mulford

3719 2540

Vehicle/Customer Information/Inspection Info

Model Year Make Lincoln VIN 1LNLM2W6P4 - Mileage (at inspection): *Could not determine*
 Inspection Date/Location: 3-17-91 Insurance Auto Auction Augusta, GA
 Incident date: Unknown Approximate mileage at incident: Unknown
 Inspector Name: *ORVILLE Mullins*

Inspection Info

Area of fire damage (engine compartment, hood, front end)
Left Side of Engine Compartment
 Identify if any underhood wiring shows evidence of unusual overheating
Could not determine
 Identify if any fuses or fuse links were blown or show evidence of other damage
This 15 AMP Fuse - blown - being returned
 Determine if the correct fuse for the stop lamp circuit is the fuse here
15 AMP
 Identify if there was any damage to wiring in the area where the fire was started (ie chafing, missing insulation)
Could not determine
 Assess whether the air suspension pump shows evidence of unusual overheating
Could not determine
 Identify if there were any aftermarket modifications to the vehicle? (specifically car alarm, water tow, or remote start)
None

If possible, identify if the vehicle was involved in a recent disaster/accident that required significant vehicle clean up? If so, when was cleanup performed?
Could not determine - Doubtful
 If possible, identify vehicle repair history
Could not determine
 Any other info that may be pertinent to the incident...

Parts that we would like from vehicle if possible to identify

Brake pressure switch (preferably with wire signal/connector attached and still attached to prop valve)
Exhausts - being returned
 Sample of brake fluid or prop valve (in sealed glass container)
consumed by Fire
 Relay pack located on LH fender apron (with as much wiring as possible)
consumed by Fire
 ECU & module located on LH fender
consumed by Fire
 Speed sensor module located on LH fender
consumed by Fire
 Air suspension compressor located under air filter
consumed by Fire
 Air suspension relay
consumed by Fire
 Photograph of door jam VIN sticker
attached
 Other suspect parts

was not advised to return prop. valve



rev 2.0 - 1/14/90

DAVID BARNETT EA
JUPITER FL 33458
561-575-4174

INSPECTION DATE
3-19-99

Vehicle/Customer Information

Model Year: 92 Make: LINCOLN VIN#: 1LULMB1W0N4 Mileage: 100,000 plus
per owner
Build Date: 5/92 Present Vehicle Location: DEVAUPT, FL. Who owns vehicle now:
PARKED IN GARAGE 1022 N. BLVD. WEST
Customer Name: Phone: Is it ok for engineering to contact customer:
YES

Parts that we would like from vehicle if possible to acquire

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

REMOVED SWITCH - BUT CONNECTOR & PIG TAIL APPARENTLY BURNED

Sample of brake fluid at prop valve (in sealed glass container)

NO BRAKE FLUID FOUND - RESERVE BURNED - NO FLUID AT BRAKE SWITCH

Relay pack located on LH fender apron (with as much wiring as possible)

BURNED

EDIS 8 module located on LH fender (EDIS 8 =

BURNED OR MISSING

Speed control module located on LH fender

BURNED OR MISSING

Air suspension compressor located under air filter

BURNED OR MISSING

Air suspension relay

BURNED

Other suspect parts

- ALL RUBBER FEEL LINES, BRAKE, VACUUM HOSES, AIR CLEANER ASSY
AND DRIVER SIDE FRONT INNER 1 1/2 HOOD BURNED

- FIRE DEPT PUT OUT FIRE

- HOJ. CAR/TRUCK ALSO BURNED.

- LOCAL FORD DEALER
JARRETT FORD HAINES CITY, FL.



DAVID BURNETT EA
JUPITER FL 33458
561-575-4171

INSPECTION DATE
3-19-99

Vehicle/Customer Information

Model Year: 92 Make: LINCOLN

VIN: 1LWLM81W0N4

Mileage: 100,000 plus
per owner

Build Date: 5/92

Present Vehicle Location: DEVAUFORT, FL. Who owns vehicle now:
PARKED IN GARAGE 1022 N. BLVD. WEST

Customer Name:

Phone:

Is it ok for engineering to contact customer:

441-421-1750

YES

Incident Info/Vehicle History

Where did fire originate? (engine compartment quadrant, suspect location, or suspect component(s))

NOT SPOT APPEARS TO BE BELOW BRAKE VACUUM BOOST CYLINDER AREA

What was the vehicle circumstances when the fire was noticed? Was the vehicle running, parked, engine on/off?

If off, how long? VEHICLE PARKED - ENGINE OFF - APPROX 15-20 MIN. OWNER SAID SHE DROVE TO POST OFFICE AND ONTO A GROCERY SHOPPING CENTER - WHEN RETURNED TO CAR IT WAS ON FIRE

Did customer notice anything unusual prior to fire? (specifically... difficulty getting the vehicle out of park, spe control not working, brake warning lamp illuminated, stop lamp inoperative) CUSTOMER STATES PRIOR EVENING SHE COULD NOT GET SHIFT OUT OF 'PARK' POLICE APPARENTLY CHANGED A FUSE

Do any underhood relays show evidence of overheating? WHICH CORRECTED SHIFT PROBLEM

ALL RELAYS CONSUMED BY FIRE

Were the underhood fuse links blown?

ALL WIRE INSULATION CONSUMED BY FIRE

Were there any fuses that were blown or show evidence of other damage?

NO FUSES UNDER HOOD - ALL BURNED BY FIRE

Is the correct fuse for the stop lamp switch in the fuse box?

SEE ATTACHED DRAWING, - DO NOT KNOW STOP LAMP FUSE POSITION OR AMP.

Was there any damage to any wiring in the area where the fire was suspected to start?

ALL WIRES (INSULATION) CONSUMED BY FIRE

Does the air suspension pump show evidence of overheating?

COULD NOT FIND PUMP?

Was there any aftermarket modifications to the vehicle? (specifically car alarm, trailer tow, or remote start)

NO PER OWNER - I DID NOT NOTICE ANY MODIFICATIONS - NO TRAILER HITCH

Was the vehicle involved in a natural disaster/accident that required significant vehicle clean up? If so where was cleanup performed?


PURCHASED USED 10-18-95?

What was vehicle repair history?

VEHICLE HAS BEEN SERVICED BY MR. F. CROW - THE FATHER IN LAW

42 LINCOLN 12N4M81 WONY.

3-19-99

DRAWING UPSIDE DOWN
UNDER I.P.

MON 14:28 FAX 2486424538

EA ASSOCIATES

Vehicle/Customer Information/Incident InfoModel Year: 1993 Make: CROWN VIN: 1FA1P74W1270000000
VICTORIA

Inspection Date/Location: VEHICLE FL HOME

Incident date: 4-14-93

Inspector Name: D. H. BURGETT

561-575-4174

Damage Info

Area of fire origination (engine compartment, underhood, etc.)

APPEARED TO HAVE OCCURRED UNDERHOOD

Identify if any underhood relays show evidence of damage

BURNED

Identify if any fuses or fuse links were blown or show evidence of damage

BURNED

Determine if the correct fuse for the stop lamp system in the area

BURNED

Identify if there was any damage to wiring in the area where the fire was started (is chafing, missing insulation)

BURNED

Assess whether the air suspension pump shows evidence of internal overheating

BURNED

Identify if there were any aftermarket modifications to the vehicle? (specifically car alarm, trailer tow for remote start)

DO NOT KNOW

If possible, identify if the vehicle was involved in a natural disaster/accident that required significant vehicle tie up? If so where was cleamp performed?

DO NOT KNOW HISTORY

If possible, identify vehicle repair history

IT MAY BE IN FIRM'S WARRANTY DATA

Any other info that may be pertinent to the incident...

PAGE 2/4

NOTE:

VEHICLE PURCHASED USED FROM LEASE-LIN DEALER 3-12-97

WITH 35,000 MI.

NET OWNERS - HAD A NICE CONVERSATION - ONLY PROBLEMS

WITH CAR SINCE PURCHASE WAS A FAULTY A/C COMPRESSOR

ONE LONG CAR TRIP TO CALIFORNIA AFTER PURCHASE

NEW TIRE JUST PURCHASED TWO WEEKS PRIOR TO FIRE

DREW HOME PUT CAR IN GARAGE WENT INTO HOUSE - SHORT

TIME LATER HEARD NOISES IN GARAGE - OPENED SLIDED & CAR ON FIRE

MR. WHITEHALL SAID CRUISE HAD NOT WORKED FOR SOME TIME

PUT NO OTHER PROBLEMS - NO WARNING LIGHTS - THINK BRAKE LITS WERE OK



CASE 54N

03/22/99 MON 14:28 FAX 2488424558

EA ASSOCIATES

Vehicle/Owner Information/Accident Info

Model Year: 43 Make: Cadill

VIN#: ZFALP7H4BPK

Mileage (at inspection):

VICTORIA

75,000 Approx

Inspection Date/Location:

Vehicle Owner:

Incident date: 4-14-99

Approximate mileage at incident:

75,000 mi Approx

Inspector Name:

DAVID BURNETT SAA

561-513-4174

Parts that we would like from vehicle if possible to acquire

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

BURNED SWITCH TERMINAL & PIG TAIL BURNED & SWITCH REMOVED

Sample of brake fluid at prop valve (in sealed glass container)

& SENT TO FOR

CONSUMED BY FIRE -

CENTRAL TESTING

Relay pack located on LH fender apron (with as much wiring as possible)

-5-17-99-

BURNED

EDIS 8 module located on LH fender

BURNED

Speed control module located on LH fender

BURNED

Air suspension compressor located under air filter

BURNED

Air suspension relay

BURNED

Photograph of door jam VIN sticker - VIN PLATE ONLY - STICKER BURNED

Other suspect parts

OWNER, MR. WALTHAM SAID CRUISE HAD NOT WORKED FOR A LONG TIME.

HE SAID NO E.T. WARNING LIGHTS - PRIOR TO FIRE

CAR DROVE NORMAL PRIOR TO FIRE -

HE THINKS BRAKE LIGHTS WERE FUNCTIONING

POWER WINDOWS WERE WORKING

CAR WAS ACTING NORMAL - NO UNUSUAL PROBLEMS

JOINED BY INVESTIGATOR BILL BUCKLEY SAA

CNA INSURANCE CASE # 813-PH-1448

3713 2547



3713 2548

Model Year: 92 Make: Linc VIN: 1LNLM81042 [REDACTED] (at inspection): 54/87
Inspection Date/Location: 5-17-99 101st South Auto Salvage Vehicle Owner: [REDACTED]
Incident date: 4-14-99 Approximate mileage at incident: 54/87
Inspector Name: Doretha D. Mullins CASE # 532

Area of the container: Surface components: surface, components, and

Expend Comparison - 1967-1968

Identify 2 key independent/return data evidence of interest/constant

DATE: 11/11/11

Indicate if any front or rear lights were blown or show evidence of other damage

#15 15 Aug FIVE BROWN

Remember is the second issue for the new issue week in the Fall here

15 AND
I don't want any damage to wiring in the room where the fire was caused (in cheating, wiring installation)

Aspen whether the air purification means shows evidence of internal overloading

Identify if there were any alternative modifications to the vehicle (especially car alarm, trailer tow, or remote start) *none*

If possible, identify if the vehicle was involved in a natural disaster/condition that required significant vehicle abuse and if so, when was climate controlled?

20-4127

4/27 4:44 PM 4/27/4

Secure them as would the gun which it would be possible to remove from weapon system and thereby use the pistol chamber, assisted and still attached to pump valve).

7-10

Amount of tissue fluid at pump valve (in sealed glass syringe)

NOT AVAILABLE

FIGURE 1. *Available*

NOT acceptable

NOT AVAILABLE

NOT Available


Air suspension relay
not available

Photograph of donor
H. J. H. H. H.

Other business items



HENRY SECKEL
20949 BOCA RIDGE DRIVE SOUTH
BOCA RATON, FL. 33428
561 488 3760
FAX 561 853 9444



REF: F002A49C

FORD CENTRAL TESTING LAB / DEPT. T118
15000 CENTURY DRIVE
COMMERCE PARK NORTH
DEARBORN, MI 48120

PAGE 1 OF 2

DATE :04-27-99

CASE # 49

VIN: 2FALP71W9R

NAME

MILEAGE: 87204

ATTACHED PLEASE FIND:

1 BRAKE PRESSURE SWITCH

1 BRAKE PROPORTIONING VALVE

1 BRAKE FLUID SAMPLE FROM PROPORTIONING VALVE MARKED # 1 (1/2 GLASS JAR)

1 BRAKE FLUID SAMPLE FROM MASTER CYLINDER MARKED #2 (3/4 GLASS JAR)

FORD UNDER HOOD FIRE QUESTIONNAIRE

ADDENDUM TO FORD UNDER HOOD INVESTIGATION.

PRIOR TO THE INSPECTION I MET WITH

AND INFORMED HIM THAT AFTER THE INVESTIGATION, THE BRAKE PROPORTIONING VALVE AND THE BRAKE PRESSURE SWITCH WOULD BE REPLACED ON THE CAR AT NO COST TO THE PROVIDED THAT HE GIVES PERMISSION TO PERFORM THIS REPAIR TO THE VEHICLE. HE GAVE HIS PERMISSION. THE INSPECTION AND PARTS REPLACEMENT WAS DONE AT FORT LAUDERDALE LINCOLN MERCURY IN FT. LAUDERDALE FL. THE INSPECTION REVEALED THAT THE BRAKE PRESSURE SWITCH AND WIRE TERMINAL WAS COVERED WITH FLUID WHICH STARTED TO WICK UP THE WIRING HARNESS. THE BRAKE MASTER CYLINDER ASSEMBLY AND BRAKE LINES WERE DRY AND NO OTHER UNDER HOOD BRAKE COMPONENT HAD ANY LEAKS. THE MASTER CYLINDER FLUID LEVEL WAS FULL. THE BRAKE PEDAL HAD A GOOD SOLID FEEL AND THE PEDAL DID NOT DROP UNDER STEADY FOOT PRESSURE OF ABOUT 100 LBS. THE POWER BRAKE ASSIST WHEN THE ENGINE WAS STARTED WAS NORMAL. NONE OF THE ENGINE COMPARTMENT WIRING WAS DAMAGED OR HAD ANY SIGN OF OVERHEATING EXCEPT FOR THE WIRING HARNESS TO THE UNDER HOOD LIGHT. SEE PHOTOGRAPHIC NOTES. WIRING TO THE ENGINE COMPARTMENT FUSE BOX ON THE RIGHT FENDER WAS NOT DAMAGED. ALL FUSES WERE OF PROPER SIZE AND NONE WERE BLOWN. MOST OF THE POLICE WIRING PACKAGE WAS CONNECTED TO THIS LOCATION AND NO WIRE DAMAGE WAS OBSERVED. THERE WAS NO OVERHEATING NOTED ON THE SOLENOIDS. THE UNDER DASH FUSE PANEL ALSO HAD THE PROPER SIZE FUSES AND NONE OF THE FUSES WERE BLOWN. ALL THREE STOP LIGHTS IN THE REAR OPERATED NORMALLY. WIRING TO THE RELAY CENTER ON THE LEFT FENDER WAS UNDAMAGED.

3713 2550

THE WIRING HARNESS TO THE EDIS 8 MODULE WAS NOT DAMAGED. THE ABS PUMP CASTING AND HYDRAULIC LINES ARE TIGHT AND DID NOT SHOW ANY SIGN OF LEAKS. IT SHOULD BE NOTED THAT THE ABS MONITOR LIGHT AT THE INSTRUMENT PANEL STAYS LIT WITH KEY ON. THIS IS A COMPLAINT AND THE VEHICLE WAS BROUGHT IN TO REPAIR THIS CONDITION. THE STEERING GEAR HOUSING HAS A SLIGHT FLUID LEAK. PRIOR TO REMOVING THE BRAKE PRESSURE SWITCH AND PROPORTIONING VALVE AS AN ASSEMBLY THE WIRE HARNESS TO THE SWITCH WAS REMOVED. SOME FLUID WAS STARTING TO WICK UP THE HARNESS BUT AFTER CLEANING THE WIRES THERE WAS NO INSULATION DAMAGE OR OVERHEATING CONDITION OBSERVED. THE PROPORTIONING VALVE AND SWITCH WAS REMOVED AS A UNIT AND WAS SHIPPED WITHOUT ANY CLEANING TO THE TESTING LAB. THE SWITCH WAS FOUND TO BE TIGHT IN THE PROPORTIONING VALVE BLOCK. AFTER COMPLETING THE PARTS REPLACEMENT THE POWER TRAIN WAS CHECKED AND THE SYSTEM PASSED AND NO DTC'S WERE OBSERVED. THE DATA MONITOR ALSO INDICATED NO DTC'S.

Case # 49 X

(2)

1993-94 Town Car Crown Victoria/Mercury Under Hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 94 Make: CROWN VICTORIA VIN: 2FALP71N9R1

Present Vehicle Location: 840 N. 5th Ave. At Cambridge

Customer Name: [REDACTED] Phone: [REDACTED]

Is it ok for engineering to contact customer? OK

Was the vehicle involved in a natural disaster/condition that required significant vehicle cleanup? NO

If so, where was cleanup performed? N/A

What is the general repair history of the vehicle? moderate problems - nothing electrical related

Was it equipped with any aftermarket components? (specifically car alarm, trailer tow, or remote start) Power windows

Insurance Agency Info. (if applicable)

Agency Name: [REDACTED] Agency phone number: [REDACTED]

Claim number: [REDACTED]

Contact: [REDACTED] Phone number: [REDACTED]

Incident Info

Date of fire: N/A 07.20.02 Mileage: [REDACTED] Was the vehicle repaired? IN THE PROCESS

If repaired, when and where? [REDACTED]

See Below Any idea where the fire started? (engine compartment, quarter, front, back, left, right) BRAKE REDUNDANT SWITCH

Was the vehicle parked or running? PARKED If parked, where? (garage, airport, parking lot) SIG. DEPT. BAY

Was the engine ON or OFF? OFF If OFF, how long was it parked before fire? [REDACTED]

Did customer notice anything unusual prior to fire? [REDACTED]

Was there any difficulty getting the vehicle out of park? NO Was speed control not working? NO

Was the brake warning lamp illuminated? NO Were the brake lights inoperative? NO

Any other info that you think may be useful to our investigation? [REDACTED]

* Excessive brake fluid - vehicle had not caught on fire
Brake Switch was SATURATED with leaking brake fluid

CONDOR 3000-FAIR
SERVICE TECHNICIAN
SHALINE FORD



CHRYSLER GROUP LLC
MAY 00

PE 98-055

[REDACTED]
WINDY

TOWN CAR



CHRYSLER GROUP
SALES INC.

CQIS Report Number: WJIAA135 Program Type: Q
Report Source: MSS - PCSD - Q595

Orig Rpt #: 225951-98
Report Date: 10/09/1998

R E P O R T S U M M A R Y

VEHICLE: 1993 TOWN CAR, SIGN, SEDAN
Engine: 4.6L ROMEO BASE EFI
Operating Environ:
Vehicle Use:
VIN: L1N1M82W0FY
Odometer: 51,300 MILES
WCC: SDO5
Rsp. Act:
SYMPTOM: 3 01 0 00 CHASSIS
OTHER (CODE NOT AVAILABLE) SERVICE BRAKE SYSTEM
OTHER (CODE NOT AVAILABLE)
Additional Symptom:
Other Veh. With Concern: Severity Rating - Customer: Engineering:
Causal Component: 2B264
Causal Factor: Feature: SWITCH BRK PRES WRN L
Causal Condition: Loc: Images: 0
Component Test Status: Photo: Return Loc:
Vehicle Fixed?: YES Customer satisfied?: Repair Effectiveness (%): 100

C O M M E N T S

INITIALLY THE CUSTOMER'S CONCERN WAS THAT THE VEHICLE WOULD NOT COME OUT OF PARK. WHILE IN THE DEALERSHIP, AN UNDERHOOD FIRE STARTED, CAUSED BY A LEAKING BRAKE FLUID THROUGH THE SWITCH INTO THE CONNECTOR. REPLACED THE SPEED CONTROL SWITCH AND CONNECTOR. REPLACED THE STOP LAMP SWITCH FOR THE ORIGINAL CUSTOMER'S CONCERN. PER TECHNICIAN, THIS IS THE THIRD UNIT THAT HAD AN UNDERHOOD FIRE THAT APPEARED TO ORIGINATE FROM THIS AREA. THE OTHER TWO WERE TOO DAMAGED TO DETERMINE THE SPECIFIC LOCATION OF THE POINT OF THE ORIGIN. THE SWITCH AND CONNECTOR ARE PRESENTLY IN MY POSSESSION IN THE MEMPHIS REGIONAL OFFICE.
AUDIT 10/14/1998 09:58AM BRENDA WENDEL MSS - PCSD - Q595
DEALER ID 68523 CHANGED TO 12098 BY BWENDEL

C O N C E R N D E T A I L S

D I A G N O S T I C I N F O R M A T I O N

Symp. Verif?: Ease of Diagnosis: Level of Assistance:
Comp. Timing: Base Timing: MIL light on?:
Test Stand: Road Test: SD Number:
Prior Repair Attempts: Repair Prior to Call: NO
DTCs KOD0: KOBC:
KOER: CB:
Equipment/Procedure Used Effective? Equipment/Procedure Used Effective?

S E R V I C E A C T I O N S

Repair Type	Component Number	Number Type	Description	Causal Comp.
RPL	2B264	SERVICE	SWITCH BRK PRES WRN L	YES

V E H I C L E D E T A I L S

Vehicle Build Date:	09/10/1992	Warranty Start Date:	02/08/1993
Date of Sale:	02/08/1993	Selling Dlr (Mkt, Dlr, Sub):	12098
Dealer Special Order:		Gross Vehicle Weight:	
LH/RH Drive:			

E N G I N E

Engine: 4.6L ROMEO BASE EFI Tag: 3G 812 AA
Bld Dt: Calb: 318JR10 A Serial #: W

Post-It Fax Note	7871	Date	12/10	Page	4
To: Bill Abernethy		From:	MARILYN TAILOR		
Co. Code		Co.			
Phone 1		Phone 2	27842		
Fax 1	42268	Fax 2			

CQIS Report Number: WJIAA135 Program Type: Q
Report Source: MSS - PCSD - QSPS

Orig Rpt #: 225951-98
Report Date: 10/09/1998

--- TRANSMISSION ---

Trans: AOD-E 4SP ELEC O/D

Part #:

Bld Dt:

Serial #:

Model:

Plt:

Shft:

--- AXLE ---

Axle: 8.8 3.08 CONVENTIONAL

Id Tag Code:

Bld Dt:

Serial #:

Plt:

--- ADDITIONAL ---

Tire : P215/70R15 WSW

Brand :

Radio : ELITE PREMIUM AM/FM STRO/CSTC

A/C

: ATC AIR CONDITIONER

Paint : BLUE EXTERIOR PAINT FAMILY

AQUAMARINE FROST C/C

----- AFTER MARKET MODIFICATIONS -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- REPORT ORIGINATOR - REPAIR FACILITY - CUSTOMER INFORMATION -----

Orig/Caller : KENNETH DYRE

Title: OTHER

Repair Dir: 12098 - SCHILLING L-H/WENDENHALL INC Ph: (901) 794-4000

City: Memphis

State : Tennessee

Country: UNITED STATES

Region : Memphis - 23

Claim #/Date : LIC5777 07/19/1998

Customer Name :

City :

----- CQIS VIN HISTORY -----

NO CQIS VIN HISTORY AVAILABLE FOR THIS VEHICLE

--- SUPPLEMENTAL SURVEY: NONE ---

----- VEHICLE'S WARRANTY HISTORY (365 days only) -----

NO VEHICLE WARRANTY HISTORY AVAILABLE FOR THIS VEHICLE



2660 S. Mendenhall
Memphis, TN
(901) 794-4000

SCHILLING
LINCOLN/MERCURY
SUPER CENTER

2660 S. Mendenhall
Memphis, TN
[901] 794-4000

NEW SERVICE DEPARTMENT
• SERVICE DEPARTMENT
303-3500
• COLLISION REPAIR DEPARTMENT
303-3574 OR 303-3501
• PAINT DEPARTMENT
303-3501

C. [REDACTED] 34686	WILLIAM BLAKELY 4839 CASH RATE [REDACTED] 93/LINCOLN/TOWN CAR/4DR 1 E N L B 2 M O P Y RTR. NO. 15612	4839 4972 5141 02/08/93 09/18/92 10/06/98	10/07/98 10/08/93 09/18/92 10/06/98	10/07/98 10/08/93 09/18/92 10/06/98
------------------------	--	--	--	--

LABOR & PARTS-----		TECH(S) #7102		64.00
JW 1 25L12		CAR WON'T COME OUT OF PARK. REPLACE BRAKE LIGHT SWITCH AND WIRING.		
PARTS-----	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE
JOB # 1	1	FOAZ-13450-A	SW ASY-GTP LP	12.99
JOB # 1	1	08Z-P1818L		7.76
JOB # 1	1	09Z-14525-G	FUSE	0.87
JOB # 1	2	EDAZ-14487-B	CONN-SWIFT BPLI	0.59
JOB # 1 TOTAL PARTS				22.20
JOB # 1 TOTAL LABOR & PARTS				86.20

SUBJECT	PO#	VEN# IN#	IN# DATE	DESCRIPTION	
JOB # 1	98292	35240	10/05/98	TOW BILL	39.00
				TOTAL - SUBJECT	39.00

COMMENTS
DELETED OPERATION (18)
221723 OTHER SIGMET

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	52
--	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	----


CASHIER ID [3]	TOTAL LABOR..	44.00
	TOTAL PARTS..	22.20
	TOTAL SUBLET..	39.00
	TOTAL S.O.G..	0.00
	TOTAL MISC....	0.00
	TOTAL TAX.....	10.50

CASH []	CHARGE []	CHECK []	CREDIT CARD []	TOTAL INVOICE \$	135.78
----------	------------	-----------	-----------------	------------------	--------

THE AMOUNT OF THIS INVOICE REFLECTS ALL DISCOUNTS *****

WE APPRECIATE YOUR BUSINESS. 10

***** CUSTOMER SIGNATURE ***** DUPLICATE INVOICE *****



SCHILLING

LINCOLN/MERCURY



2660 S. Mendenhall
Memphis, TN
(901) 794-4000

SCHILLING
LINCOLN/MERCURY
SUPER CENTER

2660 S. Mendenhall
Memphis, TN
(901) 794-4000

NEW HAVEN, CT
COLLISION REPAIR DEPARTMENT
788-2222

INVOICE NO. 34486	NAME WILLIAM BLAKELY	AGE 49	SEX M	DOB 10/27/78	DRIVER'S LIC L1C877723
	ADDRESS [REDACTED]	CITY [REDACTED]	STATE TN	ZIP 38104	
	VEHICLE TYPE 93 LINCOLN TOWN CAR/ADR	YEAR 93	MAKE LINCOLN	MODEL TOWN CAR	PRICE 12400
	VEHICLE ID 1C1LN82N0PY	VEHICLE TYPE [REDACTED]	VEHICLE MAKE [REDACTED]	VEHICLE MODEL [REDACTED]	VEHICLE PRICE 67710/92
MEMPHIS, TN	PHONE [REDACTED]	FAX [REDACTED]	ALIAS [REDACTED]	DATE 10/07/98	

LABOR & PARTS				INTERNAL	
JOB # 1 20112					
TRIM WIRING HARNESS REPLACE BRAKE LIGHT SWITCH AND WIRING.					
TECH(S) 17102					
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 1	1	601-9924-A	SW ASY-SPD CON		INTERNAL
JOB # 1	1	602-14487-A	CONN-BUTT SPLI		INTERNAL
JOB # 1	1	08P-HARNESS			INTERNAL
JOB # 1 TOTAL PARTS					0.00
JOB # 1 TOTAL LABOR & PARTS					0.00
TOTALS					
CASHIER ID C	3	TOTAL LABOR..	0.00		
		TOTAL PARTS..	0.00		
		TOTAL SUBLET.	0.00		
		TOTAL G.O.B..	0.00		
		TOTAL WISC..	0.00		
		TOTAL TAX....	0.00		
		TOTAL INVOICE \$	0.00		

THE AMOUNT OF THIS INVOICE REFLECTS ALL WTB/COUNTS *****
WE APPRECIATE YOUR BUSINESS !!

CUSTOMER SIGNATURE

DUPLICATE INVOICE

Terms And Conditions

Definitions On this Airbill, "we," "our" and "us" refer to Federal Express Corporation, its employees, and agents. "You" and "your" refer to the sender, its employees, and agents.

Agreement To Terms By giving us your package to deliver, you agree to all the terms in our current Service Guide, which is available on request. You also agree to these terms on behalf of any third party with an interest in the package. If there is a conflict between the Service Guide and this Airbill, the Service Guide will control. No one is authorized to change the terms of our Agreement.

Responsibility For Packaging And Completing Airbill You are responsible for adequately packaging your goods and properly filling out this Airbill. If you omit the number of packages under weight per package, our billing will be based on our best estimate of the number of packages we received and/or an estimated "default" weight per package as determined by us.

Responsibility For Payment Even if you give us different payment instructions, you will always be primarily responsible for all delivery costs, as well as any cost we incur in either returning your package to you or warehousing it pending disposition.

Limitations On Our Liability And Limitation Not Assumed

- Our liability for loss or damage to your package is limited to your actual damage or \$100, unless you declare a higher value, pay an additional charge, and document your actual loss in a timely manner. You may pay an additional charge for each additional \$100 of declared value. The declared value does not constitute, nor do we provide cargo liability insurance.
- In any event, we will not be liable for any damage, whether direct, incidental, special, or consequential in excess of the declared value of a shipment, whether or not Federal Express had knowledge that such damages might be incurred including but not limited to loss of interest or profits.
- We aren't responsible:

for your acts or omissions including but not limited to improper or insufficient packing, securing, marking, or addressing or those of the recipient or anyone else with an interest in the package.

- If you or the recipient violate any of the terms of our Agreement.
- For loss or damage to shipments of prohibited items.
- For loss, damage, or delay caused by events we cannot control, including but not limited to acts of God, acts of the sea, weather conditions, acts of public enemies, war, strikes, civil commotions, or acts of public authorities with actual or apparent authority.

Declared Value Limits

- The highest declared value allowed for FedEx Letter and FedEx Pak shipments is \$500.
- For other shipments, the highest declared value allowed is \$50,000 unless your package contains items of "extraordinary value," in which case the highest declared value allowed is \$500.
- Items of "extraordinary value" include shipments containing such items as artwork, jewelry, furs, precious metals, negotiable instruments, and other items listed in our Service Guide.
- You may send more than one package on this Airbill and still be the total declared value for all packages, not to exceed the \$500, \$500, or \$50,000 per package limit described above. (Example: 5 packages can have a total declared value of up to \$250,000.) In that case, our liability is limited to the actual value of the package(s) lost or damaged, but may not exceed the maximum allowable declared value(s) or the total declared value, whichever is less. You are responsible for proving the actual loss or damage.

Filing A Claim YOU MUST MAKE ALL CLAIMS IN WRITING and notify us of your claim within strict time limits set out in the current Service Guide.

We'll consider your claim that if you notify our Customer Service Department at 1-800-the-FedEx (363-6338) and make your claim in writing as soon as possible.

Within 90 days after you notify us of your claim, you must send us all the information you have about it. We aren't obligated to act on any claim until you have paid all transportation charges, and you may not deduct the amount of your claim from those charges.

If the incident accepts your package without noting any damage on the delivery record, we will assume the package was delivered in good condition. For us to process your claim, you must make the original shipping document and posting available for inspection.

Right To Inspect We may, at our option, open and inspect your packages before delivery if you give them to us to deliver.

Right Of Refusal We reserve the right to reject a shipment when such shipment would be likely to cause delay or damage to other shipments, equipment, or personnel or if its shipment is prohibited by law, or if the shipment would violate any terms of our Agreement or our current Service Guide.

C.O.D. Shipments C.O.D. SERVICE IS NOT AVAILABLE WITH THIS AIRBILL. M.C.U.B. Service is required, please use a Federal Express C.O.D. Airbill.

Air Transportation Tax Inclusion A federal excise tax when required by the Internal Revenue Code on the air transportation portion of this service, if any, is paid by us.

Money-Back Guarantee In the event of untimely delivery, Federal Express will at your request and with some limitations, refund or credit all transportation charges. See current Service Guide for more information.

Freight Services There are several freight service options, depending on your transit time needs.

- **FedEx Overnight Freight** Next business-day service in all points in the 48 states; rates are based upon the distance shipped.
- **FedEx 2-Day Freight** Second business-day service in all points in the 48 states; rates are based upon the distance shipped.
- **FedEx Express Three Freight** Up to 3 business-day service in all points in the 48 states; rates are based upon the distance shipped.

Form FPM3000000 - Sep. 1999

FedEx. USA Airbill

805580868404

0210

BNA22
FedEx Billing Copy

From
Date 12/10/95 Sender's FedEx Account Number 1035-4324-2
Sender's Name [REDACTED] No. [REDACTED]
Company FORD CUST SVC DIV
Address 8000 CENTERVIEW PKWY #201
City CHATTANOOGA State TN Zip 38018
Tel. [REDACTED]
Fax [REDACTED]
Company [REDACTED]
Address [REDACTED]
City [REDACTED] State [REDACTED] Zip [REDACTED]

For BULK or FedEx Location check box

☐ Bulk/Wholesale ☐ Retail/Consumer

For WEEKEND Delivery check box

☐ Saturday Delivery ☐ Sunday Delivery

805580868404

1. Express Package Service Packages under 100 lbs. Prices indicated per lb. to nearest whole lb.
☐ FedEx Priority Overnight ☐ FedEx Standard Overnight
☐ FedEx First Overnight
☐ FedEx 2Day ☐ FedEx Express Saver
2. Express Freight Service Packages over 100 lbs. Prices indicated only for 100 lb. and over
☐ FedEx Overnight Freight ☐ FedEx 2Day Freight ☐ FedEx Freight ☐ FedEx Freight ☐ FedEx Freight
3. Packaging ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx
4. Special Handling ☐ No ☐ Yes ☐ Yes ☐ Yes
5. Payment ☐ Prepaid ☐ Bill Me ☐ Bill Me ☐ Bill Me
6. Reference Signature

Your signature authorizes FedEx/Express to deliver this bill-
ing without obtaining a signature and accept responsibility
and hold harmless FedEx/Express from any resulting claims.

321

BNA22
Rev. 12/95
Part of 10000
9/95/96 FedEx
Form 1000-10-95

004947714 2

FOR FEDEX USE ONLY - PLEASE DO NOT REMOVE THIS COPY

3713 2561

FedEx. USA Airbill **805580868404**

0210 **FedEx Retrieval Copy**

BNA22

Date 12/10/95 Sender's FedEx Account Number 1035-4524-2

Sender's Name [REDACTED] Phone [REDACTED]

Company FORD CUST SVC DIV

Address 8000 CENTERVIEW PKWY #201 Dept./Floor/Room [REDACTED]

City CORONA State TN Zip 38018

Your Internal Billing Reference Information [REDACTED]

To Recipient's Name [REDACTED] Phone [REDACTED]

Company [REDACTED]

Address [REDACTED] City [REDACTED] State [REDACTED] Zip [REDACTED]

For pickup at FedEx Location check box: ☐ Hold at Location ☐ Hold at Office ☐ Hold at Home ☐ Hold at Business ☐ Hold at Warehouse ☐ Hold at Distribution Center ☐ Hold at Retail Store ☐ Hold at Office ☐ Hold at Home ☐ Hold at Business ☐ Hold at Warehouse ☐ Hold at Distribution Center ☐ Hold at Retail Store



805580868404

☐ Express Package Service Packages under 100 lbs. ☐ FedEx Priority Overnight ☐ FedEx Standard Overnight ☐ FedEx First Overnight

☐ FedEx 2Day ☐ FedEx Overnight ☐ FedEx International Overnight ☐ FedEx International Priority

☐ Express Freight Service Packages over 150 lbs. ☐ FedEx Freight ☐ FedEx Freight ☐ FedEx Freight

Packaging ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx

Special Handling ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes

Payment ☐ Sender ☐ Recipient ☐ Third Party ☐ Credit Card ☐ Cash

Total Packages ☐ Total Weight ☐ Total Charges ☐

Signature ☐ Signature ☐ Signature ☐ Signature

321

004947714 2

3713 2562

FedEx. USA Airbill **805580868404**

0210 **SNA22** **Recipient's Copy**

From **[Redacted]**
 Date **12/10/98**
 Sender's Name **[Redacted]**

Company **FORD CUST SVC DIV**

Address **8000 CENTERVIEW PKWY #201**

City **CORDOVA** State **TM** Zip **36018**

Your Internal Billing Reference Information **[Redacted]**

To **[Redacted]**
 Recipient's Name **[Redacted]**

Company **[Redacted]**

Address **[Redacted]**
 On "WFO" in FedEx header, plus FedEx address label

Day **[Redacted]** Rate **27**
 For **WEEKEND** or **FedEx Location** check here **[Redacted]**
 For **WEEKEND** Delivery check here **[Redacted]**



805580868404

Express Package Service Packages under 100 lbs.
☐ FedEx Priority Overnight ☐ FedEx Standard Overnight
☐ FedEx First Overnight
☐ FedEx 2Day ☐ FedEx Express Saver

Express Freight Service Packages over 100 lbs.
☐ FedEx Standard Freight ☐ FedEx 2Day Freight ☐ FedEx Freight
 *Call for delivery schedule. See back for detailed description of freight services.

Packaging ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx ☐ FedEx

Special Handling
 Fragile, Alcoholic, Perishable, Dangerous, etc. ☐ Yes ☐ No
☐ Dry Ice ☐ Cargo Aircraft Only

Payment
☐ Sender ☐ Shipper ☐ Third Party ☐ Credit Card ☐ Cash

[Redacted Signature Area]

Total Packages **2** Total Weight **30** Total Insurance Value **30** Total Charges **27**

*When delivery is made to you, please inspect. We are not liable for loss or damage to contents unless you sign for it. Signature required for delivery of certain items.

Signature **[Redacted]**

Your signature indicates that you agree to deliver the goods to the carrier and to indemnify the carrier from all liability for loss or damage to the goods. Signature required for delivery of certain items.
 Call 1-800-Go-FedEx® (662-663-3636)

321

004947714 2

3713 2563

Terms And Conditions

Definitions In this Airmail, "we," "our" and "us" refer to Federal Express Corporation, its employees, and agents. "You" and "your" refer to the sender, its employees, and agents.

Agreement To Terms By giving us your package to deliver, you agree to all the terms in our current Service Guide, which is available on request. You also agree to these terms on behalf of any third party with an interest in the package. If there is a conflict between the Service Guide and this Airmail, the Service Guide will control. No one is authorized to change the terms of our Agreement.

Responsibility For Packaging And Completing Airmail You are responsible for adequately packaging your goods and properly filling out this Airmail. If you mark the number of packages and/or weight per package, our billing will be based on our best estimate of the number of packages we received and/or an estimated "declared" weight per package as determined by us.

Responsibility For Payment Even if you give us different payment instructions, you will always be primarily responsible for all delivery costs, as well as any cost we incur in either returning your package to you or warehousing it pending disposition.

Limitations On Our Liability And Limitation On Amount

- Our liability for loss or damage to your package is limited to your actual damage or \$100, unless you declare a higher value, pay an additional charge, and document your actual loss in a timely manner. You may pay an additional charge for each additional \$100 of declared value. The declared value does not constitute, nor does it provide cargo liability insurance.
- In any event, we will not be liable for any damage, whether direct, incidental, special, or consequential in excess of the declared value of a shipment, whether or not Federal Express had knowledge that such damages might be incurred including but not limited to loss of income or profits.
- We won't be liable:
 - for your acts or omissions including but not limited to improper or insufficient packing, securing, marking, or addressing or those of the recipient or anyone else with an interest in the package

- if you or the recipient violate any of the terms of our Agreement.
- for loss or damage to shipments of prohibited items
- for loss, damage, or delay caused by events we cannot control, including but not limited to acts of God, perils of the air, weather conditions, acts of public enemies, war, strikes, civil commotions, or acts of public authorities with actual or apparent authority.

Declared Value Limits

- The highest declared value allowed for FedEx Letter and FedEx Pak shipments is \$500.
- For other shipments, the highest declared value allowed is \$50,000 unless your package contains items of "extraordinary value," in which case the highest declared value allowed is \$250.
- Items of "extraordinary value" include shipments containing such items as artwork, jewelry, furs, precious metals, negotiable instruments, and other items listed in our Service Guide.
- You may send more than one package on this Airmail and still be the total declared value for all packages, not to exceed the \$500, \$500 or \$50,000 per package limit described above. (Example: 5 packages that have a total declared value of up to \$250,000.) In that case, our liability is limited to the actual value of the package(s) lost or damaged, but may not exceed the maximum allowable declared value(s) or the total declared value, whichever is less. You are responsible for proving the actual loss or damage.

Filing A Claim YOU MUST MAKE ALL CLAIMS IN WRITING and notify us of your claim within strict time limits set out in the current Service Guide.

We'll consider your claim that if you notify our Customer Service Department at 1-800-Go-FedEx (662-6633) and make your claim in writing as soon as possible.

Within 90 days after you notify us of your claim, you must send us all the information you have about it. We won't be required to act on any claim until you have paid all transportation charges, and you may not deduct the amount of your claim from those charges.

If the recipient accepts your package without noting any damage on the delivery record, we will assume the package was delivered in good condition. For us to process your claim, you must make the original shipping customs and packing available for inspection.

Right To Inspect We may, at our option, open and inspect your packages before or after you give them to us to deliver.

Right Of Rejection We reserve the right to reject a shipment when such shipment would be likely to cause delay or damage to other shipments, equipment, or personnel or if its shipment is prohibited by law, or if the shipment would violate any terms of our Agreement or our current Service Guide.

C.O.D. Services C.O.D. SERVICE IS NOT AVAILABLE WITH THIS AIRMAIL. If C.O.D. Service is required, please use a Federal Express C.O.D. Airmail.

Air Transportation Tax (checked) A federal excise tax when required by the Internal Revenue Code on the air transportation portion of this service, if any, is paid by us.

Money-Back Guarantee In the event of untimely delivery, Federal Express will at your request and with some limitations, refund or credit all transportation charges. See current Service Guide for more information.

Freight Services There are several freight service options, depending on your transit time needs.

- **FedEx Overnight Freight:** Next business-day service to all points in the 48 states; rates are based upon the distance shipped.
- **FedEx 2-Day Freight:** Second business-day service to all points in the 48 states; rates are based upon the distance shipped.
- **FedEx Express Next Freight:** Up to 3 business-day service to all points in the 48 states; rates are based upon the distance shipped.

Form 9000-00000-000-000

9804105

COMPLETE

FINAL REPORT
ISSUED

PHOTOS
FINAL REPORT
RAW DATA

Request for Central Laboratory Service

13000 Century Dr., Danbury NJ 08120-1267 Phone (313) 32-31676 FAX (313) 32-21614

9804105 12-17-98

Your Name (Send report to): G. STEVEN'S	Telephone: 36686	PROPS ID: G STEVEN I	FAX: 36686
Secondary Contact: N. LAPORTE	Telephone: 42686	PROPS ID: N LAPORT	FAX:

Room No. (Add Drop ID No. if applicable): MD 5006	Building: LABORATORIALS	Location Code: MD	Drop ID: 7-03	Work Task & Date (ISO Loc. Code): Y0000000
---	-----------------------------------	-----------------------------	-------------------------	--

Test & Sample Handling:	Sample Handling:	TOXICAM:	Source:	Supplier Code:
Disposition after test:	Disposition after test:	Disposition after 30 days:		

Part Number (Name):	Sample Identification (Name):	Part Number (ID):	Material Specification (ID):	CPC Code:	Supplier:
SPEED CONTROL	BURNED	F2V1-9F924 A	NA		TEXAS
OUT-DEF SWITCH	CONNECTOR				
	PRESSURE ACTUATOR				
	(REDDICK)				

Reason of Investigation (Specify from Request (Check all that apply)):	Requester Info. Box (For requester use):
☐ Production/Plant problem ☐ Failure/Process in Lab ☒ Failure/Analysis ☐ Legal ☐ Specification Compliance ☐ Other (Specify below):	HIGH PRIORITY - POSSIBLE LEGAL Do you need to know your CL contact and status? ☐ Yes
Do you want your CL contact? ☐ No ☐ Yes Do you want your CL contact? ☐ No ☐ Yes	

Additional Sample Information/Testing Requirements

DETERMINE CAUSE OF BURNED CONNECTOR
RADIATION
PHOTOGRAPH
PRESSURE TEST DIAGRAM

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES
--

ATTN: S. LAPORTE

Sample in Lab

NOTE: ALL COMMUNICATIONS/REQUEST ETC. TO BE DUAL (I.E. LAPORTE)
--

Form (Check all that apply) ☒ FAX preliminary results ☐ FAX final written ☐ FAX typed report ☐ Mail hand written ☐ Mail typed report ☐ Electronically transfer report ☐ Form preliminary results

For information about services or assistance in completing this form please refer to the Central Laboratory WEB page. [www.gsa.fed.com/centralhome.htm]
 Laboratory number and date contact to assign without receipt of samples.
 Samples will be disposed of after 30 days unless otherwise indicated above.



April 22, 1999

To: G. Stevens (313) 32-38886 (313) 39-0724 FAX
From: S. LaRouche (313) 84-54878
Subject: Speed Control Cut-off Switch
Part Number: F2VY-8F924-A
Specification: See Appendix A
Supplier: Texas Instruments

Received: One burned speed control cut-off switch and attached connector were received on December 17, 1998. The switch was identified as Reddick (Memphis).

Object: Determine cause of burned switch and connector.

Conclusion: The switch cavity of the base exhibits the most severe heat damage, which suggests that the fire may have originated in that location.

Although several conditions were discovered in the switch cavity which could contribute to the switch fire, it could not be determined if any of these conditions were the actual cause:

The deposits on the face of the cup contain elements (copper and zinc) from the brass contacts. This indicates transfer of the contact material to the cup, possibly as a result of an electrical cell being set up between the contacts which are electrically hot (+) and the cup which is grounded (-). The face of the cup and switch cavity contain a glycol based material (probably brake fluid) which could have acted with other materials (possibly water or an oxalate) as an electrolyte. If a cell occurred, it would have been a current path between the electrically hot contacts and ground.

The stationary contact is corroded and exhibits dezincification. Dezincification in brass is usually caused by exposure to water. The contact also exhibits cracks which are intergranular and appear to have been caused by stress corrosion cracking. Stress corrosion cracking in copper alloys is usually caused by exposure to ammonia, ammonia compounds, or amines. Portions of the contact have been reduced in cross sectional area by as much as 50 as a result of corrosion. All of these conditions could have increased the resistance of the contact.

The movable contact appears to have been melted back into the bulkhead between the switch and wire cavities of the switch base, most likely due to arcing. The surfaces of the melted area are clean which suggests that this damage may have occurred in the later stages of the fire.

The Kapton seals (diaphragms) exhibit cracks, possible mechanical damage, and embrittlement associated with the cracks. The cause of the cracks could not be determined. The cracks appear to have formed a leak path for the brake fluid to enter the switch cavity.

**Data and Analysis:****Visual Examination**

For reference, the components and internal construction of a typical switch are shown in Appendix 1.

The base and connector of the submitted assembly have a burned and melted appearance. The base separated from the pressure side of the assembly approximately flush with the crimp ring. This left the face of the cup exposed. The face of the cup is partially covered with a greenish deposit and what appears to be some type of liquid. Small samples of the deposit and liquid were removed from locations A and B shown in Figure 1 for subsequent analyses.

The switch cavity contains the stationary contact which has a corroded appearance. The movable contact and its base are missing. The ceramic transfer pin is also missing. The cavity appears to be the most severely burned portion of the base. The plastic appears to have been charred away in this area, with only fibrous filler material remaining. This suggests that the fire may have started in this area. The connector appears to have been bonded to the switch base by heat from the fire. The exterior of the connector is covered with a white deposit.

The switch was examined with a fluoroscope (see Fluoroscopic Examination) and then sent to Texas Instruments (switch supplier, Attleboro, MA) for disassembly and examination (witnessed by N. LaPointe). The disassembled components were photographed by N. LaPointe (Figures 2 through 14). After disassembly and examination by Texas Instruments, the switch components were returned to Central Laboratory.

The Kapton seals are discolored and appear to have been cracked. These were sent to the Polymers section of Central Laboratory for further examination (see Examination of Kapton Seals section of this report).

The interior of the cup, the washer, converter, disc, and spacer are covered with a liquid and black residues (Figures 13 and 14). These were sent to the Organic Section of Central Laboratory for sampling and analysis.

The connector and switch base had been separated during examination by Texas Instruments. After the parts were returned from Texas Instruments, the connector was examined at Central Laboratory in the presence of UTA (connector supplier). The gray seal where the wires enter the connector appears intact (Figure 16). The cavity below the seal contains white deposits similar in appearance to those noted on the exterior (Figure 16). The sealing surface of the red seal is no longer intact and appears to have been partially melted by heat from the fire (Figure 17). Part of the melted seal material appears to have been transferred to the switch base (Figure 18). The insulation was carefully removed from the wires. The wires exhibit some tarnish and greenish discoloration (Figure 19). After this examination was completed, the contact bases and terminals were removed from the switch base.

The stationary contact exhibits cracks in the corners of the window below the contact pad and bridge (Figure 20). One corner away from the pad exhibits what appears to be localized arc damage. Approximately 50% of the bridge cross section has been lost by what appears to be corrosion. Cracks are also present in the base of the contact where it is bent and crimped to the bulkhead in the switch base. The terminal is covered with a black deposit.

The movable contact appears to have been melted back into the bulkhead of the switch base. The contact appears to have been melted into a large globule which has a clean and shiny appearance (Figure 20). The clean surfaces suggest that this damage is fresh and may have occurred in the later stages of the fire. The terminal is covered with olive green deposits.



Fluoroscopic Examination

Fluoroscopic examination revealed the presence of cracks in the stationary contact (Figures 21 and 22). It also shows loss of material in the bridge (Figure 21). The movable contact is missing. The base and terminal of the movable contact terminate in a large globule in the bulkhead of the switch base (Figure 23). The switch base and pressure side of the switch assembly were placed together to show the approximate relative position between the stationary contact and cup (Figures 23 through 26). Close ups of the pressure side of the switch assembly show the washer, converter, and disc in position inside the cup (Figures 27 and 28).

Examination of Kapton Seals

(Reflected Light Microscopy and Scanning Electron Microscopy (SEM))

The switch contains three Kapton seals which were splayed at -45° angle to one another. Each seal has a laminated construction of Kapton between Teflon films. All three Kapton seals exhibit radial and circumferential cracks in the area that conformed over the converter and depression in the washer (Figure 29). The direction of the cracks and appearance of the damage suggest that they were caused by buckling or pinching of the Kapton. The cracking and damage appears to have initiated along the side of the seal which was against the washer. The Teflon appears to have been torn in the crack areas. The cracked areas of the Kapton material have been darkened and embrittled by some unknown mechanism (Figure 29). The cracks in the Kapton occurred in a brittle mode (Figures 30 and 31) and appear to have provided a leak path for brake fluid to enter the switch cavity.

Surface Analysis

(Scanning Electron Microscopy (SEM) and Energy dispersive X-ray Spectroscopy (EDS))

The surfaces and cracks of the stationary contact were examined with the SEM. Most of the surfaces of the contact exhibit damage suggesting corrosive attack (Figure 32). One corner of the contact bridge, away from the contact pad, exhibits what appears to be localized arc damage (Figure 33). The crack surfaces exhibit intergranular features (Figures 34 and 35), indicating stress corrosion cracking. EDS was performed to identify elements present in the following materials:

- Oxide material on side of stationary contact.
- Greenish deposit removed from face of cup.
- Fibrous material on cup.
- Material scraped from new switch base.
- Material scraped from burned switch base.
- White deposits removed from wire cavity in connector.
- Material scraped from pad of stationary contact.
- Material on crack surface.
- Green material on terminal of stationary contact.
- Black material on terminal from movable contact.

Spectra from these analyses are shown in Figures 36 through 47.

The spectrum from the material on the side of the stationary contact exhibits elements from the base metal (brass) as well as a trace amount of sulfur. This suggests that the material on the surface of the stationary contact is most likely an oxide of the base metal with possibly a sulfur compound.



Surface Analysis - continued

The spectrum from the greenish deposit on the cup exhibits mostly copper and zinc with trace amounts of sulfur, potassium, silicon, chromium, and iron. The presence of copper and zinc indicates that the deposit is primarily an oxide of the brass contact material which has transferred to the cup. The presence of sulfur suggests that some of the material may be a sulfate. The chromium and iron are most likely from the cup. The deposit also contains fibers which have spectra similar to those in the switch housing.

Spectra from the switch bases are similar. Aluminum, silicon, and calcium are most likely from the fillers (fibers, etc.) used in the housing material.

Spectra from the white deposit exhibit elements which would be found in dry chemical fire extinguishers, i.e., high phosphorus content material with plates of Si, Al, F - rich material (Muscovite).

The spectrum from the material on the pad of the stationary contact exhibits elements from the base metal (brass) as well as sulfur and traces of potassium and silicon. This suggests that the material on the surface of the pad is most likely an oxide and a sulfur compound of the base metal.

The spectrum from the black deposit on the movable contact terminal exhibits elements from the brass base material and the tin coating with sulfur. The deposit appears to be an oxide and sulfur compound of the terminal materials.

The spectrum from the green deposit on the stationary contact terminal exhibits elements from the base metal as well as sulfur, silicon, potassium, calcium, and aluminum. The deposit is most likely a sulfur compound of the terminal material with possible oxide. The silicon, calcium, potassium, and aluminum could be present from the fillers in the switch base or from a dry chemical fire extinguisher.

Molecular Characterization

(FTIR, Qualitative, Microscopic)

Deposit on Face of Cup

Arrow B in Figure 2 points to area where analysis was performed). Spectra of the fluid noted on the metallic surface (chloroform micro casts - several areas) are characteristic of a glycol ether [spectrally similar to Dow HD 50-4 brake fluid] with evidence of an ester and metal soap.

Spectra of the new, brown base are characteristic of a polyester on the base of terephthalic acid.

Spectra of the burned base are similar to the new base and are characteristic of a polyester on the base of terephthalic acid.



Molecular Characterization
(FTIR, Qualitative, Conventional and Microscopic)

Hexport Deposit

Spectra as received are characteristic of a glycol based material [probably brake fluid] and a metal salt [probably an oxalate].

Spectra of the methanol solubles are characteristic of a glycol based material [probably brake fluid] and ester.

Spectra of the insolubles are characteristic of essentially a metal salt [possibly an oxalate].

Converter Deposit

Spectra as received are characteristic of a glycol based material [probably brake fluid] and a metal salt [probably an oxalate].

Spectra of the methanol solubles are characteristic of a glycol based material [probably brake fluid, ester, and other material].

Spectra of the insolubles are characteristic of essentially a metal salt [probably an oxalate].

Spacer Deposit

Spectra of the deposit [as received] are characteristic of a metal salt [probably an oxalate] and a glycol based material [probably brake fluid].

Washer Deposit

Spectra of the deposit [as received] are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].

Diaphragm #2 Internal Fluid/Deposit

Spectra as removed are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].


Water Content, % by weight¹ -10
(ASTM D 1744)

Metallographic Analysis
(ASTM E 3)


The corroded bridge area of the stationary contact was mounted and polished for metallographic examination. The corroded area exhibits dezincification, suggesting exposure to moisture (Figures 48 and 49).

¹ Accuracy of this result is unknown based on the small sample size and possible interference caused between compounds present in the deposit and the blank.

Concur:


P. Klass, Supervisor
Metallurgy Section

By:


Steven LaRouche (SLAROUCH)

Enclosures: Appendix I
Figures 1 through 49

SL/al

Appendix I




Diagram showing components of switch.



-1.7X


Figure 1: Photograph showing as-received switch and locations where samples were removed from cup face.



-1.4X


Figure 2: Photograph showing cup, Kapton seals, and hexport after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-2X


Figure 3: Photograph showing hexport after disassembly at Texas Instruments (N. LaPointe).



-1.8X


Figure 4: Photograph showing Kapton seals after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-3.5X


Figure 5: Photograph showing gasket after disassembly at Texas Instruments (N. LaPointe).



-3.5X

Figure 6: Photograph showing gasket (opposite side of that shown in Figure 5) after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-3.4X


Figure 7: Photograph showing Kapton seal #1 (closest to hexport) after disassembly at Texas Instruments (N. LaPointe).



-3.4X


Figure 8: Photograph showing Kapton seal #1 (opposite side of that shown in Figure 7) after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-3.4X

Figure 9: Photograph showing Kapton seal #2 after disassembly at Texas Instruments (N. LaPointe).



-3.4X

Figure 10: Photograph showing Kapton seal #2 (opposite side of that shown in Figure 9) after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-3.4X

Figure 11: Photograph showing Kapton seal #3 (close to washer) after disassembly at Texas Instruments (N. LaPointe).



-3.4X


Figure 12: Photograph showing Kapton seal #3 (opposite side of that shown in Figure 11) after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.



-1.9X

Figure 13: Photograph showing face of washer after disassembly at Texas Instruments (N. LaPointe).



-1.4X

Figure 14: Photograph showing internal surfaces of cup, converter/disc, and washer after disassembly at Texas Instruments (N. LaPointe).

Note: Nominal magnifications given for photomicrographs.




Figure 15: Image showing gray seal.




Figure 16: Image showing white deposit in cavity below gray seal.

Note: Nominal magnifications given for photomicrographs.



-4.6X


Figure 17: Image showing condition of red seal.



-6.3X

Figure 18: Image showing transfer of red seal material to switch base.

Note: Nominal magnifications given for photomicrographs.



-8.9X

Figure 19: Image showing tarnished condition of wires below insulation.



-3.7X

Figure 20: Photograph showing contacts, bases, and terminals after removal from switch base.


Note: Nominal magnifications given for photomicrographs.



-8.8X

Figure 21: Fluoroscopic image showing cracks and loss of material in stationary contact.


Note: Nominal magnifications given for photomicrographs.



-4.5X

Figure 22: Fluoroscopic image showing cracks and loss of material in stationary contact.


Note: Nominal magnifications given for photomicrographs.



-1.9X

Figure 23: Fluorescopic image showing switch base and pressure side of switch placed together. Note base of movable contact terminating in large globule.


Note: Nominal magnifications given for photomicrographs.



-1.5X

Figure 24: Fluoroscopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnification given for photomicrographs.



-5.2X

Figure 25: Fluorescopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnifications given for photomicrographs.



-3.7X

Figure 26: Fluoroscopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnifications given for photomicrographs.



-1.9X

Figure 27: Fluoroscopic image of washer, converter, and disc in place.


Note: Nominal magnifications given for photomicrographs.



-19X


Figure 28: Fluorescopic image showing converter and disc in place.

Note: Nominal magnifications given for photomicrographs.



7X

Figure 29: Image showing typical damage to Kapton seals. Kapton Strip (Teflon Layers Removed) Closest to Washer with Concave Side Down



Ntali

253X


Figure 30: SEM photomicrograph showing brittle crack in Kapton seal. Crack appears to have propagated away from the washer. The direction of propagation is perpendicular to the plane of the page

Note: Nominal magnifications given for photomicrographs.




Figure 31: SEM photomicrograph showing brittle crack in Kapton seal. Direction of propagation is perpendicular to plane of page.

Note: Nominal magnifications given for photomicrographs.



200X


Figure 32: SEM photomicrograph showing apparent corrosion damage to surface of stationary contact.



100X


Figure 33: SEM photomicrograph showing what appears to be localized arc damage to corner of stationary contact.

Note: Nominal magnifications given for photomicrographs.



75X

Figure 34: SEM photomicrograph showing intergranular crack in stationary contact.



750X

Figure 35: SEM photomicrograph showing intergranular crack in stationary contact.

Note: Nominal magnifications given for photomicrographs.




Figure 36: EDS X-ray spectrum of material scraped from the side of the stationary contact body.




Figure 37: EDS spectrum of greenish compound scraped from the cup region.




Figure 38: EDS X-ray spectrum of fibrous material scraped from the cup region.

Note: Nominal magnifications given for photomicrographs.




Figure 39: EDS X-ray spectrum of material shaved from a new base.




Figure 40: EDS X-ray spectrum of fibrous material scraped from the old base.

Note: Nominal magnifications given for photomicrographs.




Figure 41: EDS X-ray spectrum of one of three samples of the white powder taken from the connector cavity below the wire seal.




Figure 42: EDS X-ray spectrum of the second of three samples of the white powder.




Figure 43: EDS X-ray spectrum of the third of three samples of the white powder.

Note: Nominal magnifications given for photomicrographs.




Figure 44: EDS X-ray spectrum material from pad of stationary contact.




Figure 45: EDS X-ray spectrum of the crack surface.




Figure 46: EDS X-ray spectrum of the green deposit from terminal of stationary contact.

Note: Nominal magnifications given for photomicrographs.





Figure 47: EDS X-ray spectrum of the black deposit from terminal of movable contact.

Note: Nominal magnifications given for photomicrographs.



As-polished

80X

Figure 48: Photomicrograph showing dezincification in stationary contact.




As-polished

500X

Figure 49: Photomicrograph showing dezincification in stationary contact.

Note: Nominal magnifications given for photomicrographs.



Request for Central Laboratory Service

19000 Canyon Dr., Dearborn MI 48120-1267 Phone (313) 32-2187 FAX (313) 32-3181

All shaded areas must be filled in to process your request

Administrative Use Only

Laboratory Number 9804105	Date 12-17-98
-------------------------------------	-------------------------

Your Name (Send report to) E. STEVENS	Telephone 36686	PROPS ID E STEVEN I	FAX 36686
Secondary Contact A. LAROCHE	Telephone 42456	PROPS ID ALAROCHE	FAX

Room No./Mail Drop/PO Box MD5006	Department/Activity MATERIALS INT	Building BLD 15	Location Code 1110	Dept. # T-113	Work Task # (For 5100 Loc. Only) XQ648
--	---	---------------------------	------------------------------	-------------------------	--

Total # of Samples 1	Sample Handling ☒ Return after test ☐ Dispose after test ☐ Dispose after 30 days	TOX/CAS#	Source	Supplier Code
Part/Material Name	Sample Identification (Continue below if needed)	Part Number (If any)	Material Specification (If any)	CPS Code
SPEED CONTROL	BURNED	FRY-9F924A	NA	TEXAS
CUT-OFF SWITCH	CONNECTOR			
	PRESSURE ACTUATOR			
	(REDDICK)			

Notes of Investigation/Specific Tests Required (Check all that apply)		Requester Info. Box (For requester use)
☐ Production/Plant problem	☐ Perform Tests as in Lab No.	HIGH PRIORITY - POSSIBLE LEGAL
☒ Failure Analysis	☐ Photograph (Describe below)	
☒ Legal	☐ Use Specification _____ as a guide	
☐ Specification Compliance	☐ Other (Describe below)	
Stop testing upon failure?	Does this support CAB testing? (If "Yes", what is the expected outcome?)	Do you need to know your CL contact and timing?
☐ No ☐ Yes	☐ No ☐ Yes	☐ Yes

Additional Sample Information/Testing Requirements

DETERMINE CAUSE OF BURNED CONNECTOR

RADIOGRAPH

PHOTOGRAPH

PRESSURE TEST DIAGNOSIS

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES

ATTN: S. LAROCHE

Sample in Lab

NOTE: ALL COMMUNICATIONS/REPORTS, ETC. TO AC DUAL (I.E. LAROCHE)

Date you would like report 1-13-99	Date you must have report 1-14-99	Format (Check all that apply)	Mail typed report
		☒ FAX preliminary results	☐ Electronically transfer report
		☐ FAX typed report	☐ Photo preliminary results

For information about services or assistance in completing this form please refer to the Central Laboratory WEB page. (www.gm.ford.com/central/home.html)

Laboratory number and date cannot be assigned without receipt of samples.

Samples will be disposed of after 30 days unless otherwise indicated above.



-1.7X

Figure 1: Photograph showing as-received switch and locations where samples were removed from cup face.




-1.4X

Figure 2: Photograph showing cup, Kapton seals, and heatport after disassembly at Texas Instruments (N. LaPointe).



-2X

Figure 3: Photograph showing heqport after disassembly at Texas Instruments (N. LaPointe).



-1.5X

Figure 4: Photograph showing Kapton seals after disassembly at Texas Instruments (N. LaPointe).



~3.5X

Figure 5: Photograph showing gasket after disassembly at Texas Instruments (N. LaPointe).




~3.5X

Figure 6: Photograph showing gasket (opposite side of that shown in Figure 5) after disassembly at Texas Instruments (N. LaPointe).



~3.4X

Figure 7: Photograph showing Kevlar seal #1 (closest to hasport) after disassembly at Texas Instruments (N. LaPointe).



~3.4X

Figure 8: Photograph showing Kevlar seal #1 (opposite side of that shown in Figure 7) after disassembly at Texas Instruments (N. LaPointe).




-3.4X

Figure 9: Photograph showing Kapton seal #2 after disassembly at Texas Instruments (N. LaPointe).



-3.4X

Figure 10: Photograph showing Kapton seal #2 (opposite side of that shown in Figure 9) after disassembly at Texas Instruments (N. LaPointe).



~3.4X

Figure 11: Photograph showing Kaptan seal #3 (closest to washer) after disassembly at Texas Instruments (N. LaPointe).



~3.4X

Figure 12: Photograph showing Kaptan seal #3 (opposite side of that shown in Figure 11) after disassembly at Texas Instruments (N. LaPointe).




-1.5X

Figure 12: Photograph showing face of washer after disassembly at Texas Instruments (N. LePointe).



-1.4X

Figure 14: Photograph showing internal surfaces of cup, converter/disco, and washer after disassembly at Texas Instruments (N. LePointe).




-5.4X

Figure 15: Image showing grey seal.




-5.8X

Figure 16: Image showing white deposit in cavity below grey seal.



-4.5X

Figure 17: Image showing condition of red seal.



-6.5X

Figure 18: Image showing transfer of red seal material to switch base.



~6.8X

Figure 18: Image showing tarnished condition of wires below insulation.



~3.7X

Figure 20: Photograph showing contacts, base, and terminals after removal from switch base.



-8.5X

Figure 21: Fluorescopic image showing cracks and loss of material in stationary contact.


Note: Nominal magnifications given for photomicrographs.



-4.9X

Figure 22: Fluoroscopic image showing cracks and loss of material in stationary contact.


Note: Nominal magnification given for photomicrographs.



-1.8X

Figure 23: Fluoroscopic image showing switch base and pressure side of switch placed together. Note base of movable contact terminating in large globule.


Note: Nominal magnifications given for photostereographs.



-1.8X

Figure 24: Fluoroscopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnifications given for photomicrographs.



-5.2X

Figure 28: Fluorescopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnifications given for photomicrographs.



-3.7X

Figure 26: Fluoroscopic image showing switch base and pressure side of switch placed together.


Note: Nominal magnifications given for photomicrographs.



~5.9X

Figure 27: Fluoroscopic image of washer, converter, and disc in place.

Note: Nominal magnifications given for photomicrographs.



-18X

Figure 28: Fluoroscopic image showing converter and disc in place.

Note: Nominal magnification given for photomicrographs.




Figure 22: Image showing typical damage to Kapton seals. Kapton Strip (Teflon Layers Removed) Chased to Washer with Concave Side Down




Figure 30: SEM photomicrograph showing brittle crack in Kapton seal. Crack appears to have propagated away from the washer. The direction of propagation is perpendicular to the plane of the page




1000X

Figure 31: SEM photomicrograph showing brittle crack in Kapton seal. Direction of propagation is perpendicular to plane of page.



200X

Figure 32: SEM photomicrograph showing apparent corrosion damage to surface of stationary contact.



100X

Figure 33: SEM photomicrograph showing what appears to be localized arc damage to corner of stationary contact.




Figure 34: SEM photomicrograph showing intergranular crack in stationary contact.

75X




Figure 35: SEM photomicrograph showing intergranular crack in stationary contact.

750X




Figure 36: EDS X-ray spectrum of material scraped from the side of the stationary contact body.




Figure 37: EDS spectrum of greenish compound scraped from the cup region.




Figure 38: EDS X-ray spectrum of fibrous material scraped from the cup region.

Note: Nominal magnifications given for photomicrographs.




Figure 39: EDS X-ray spectrum of material shaved from a new base.




Figure 40: EDS X-ray spectrum of fibrous material scraped from the old base.

Note: Nominal magnification given for photomicrographs.




Figure 41: EDS X-ray spectrum of one of three samples of the white powder taken from the connector cavity below the wire seal.




Figure 42: EDS X-ray spectrum of the second of three samples of the white powder.




Figure 43: EDS X-ray spectrum of the third of three samples of the white powder.

Note: Nominal magnifications given for photomicrographs.




Figure 44: EDS X-ray spectrum material from pad of stationary contact.




Figure 45: EDS X-ray spectrum of the crack surface.




Figure 46: EDS X-ray spectrum of the green deposit from terminal of stationary contact.

Note: Nominal magnifications given for photomicrographs.





Figure 47: EDS X-ray spectrum of the black deposit from terminal of movable contact.

Notes: Nominal magnifications given for photomicrographs.



As-polished

500X

Figure 48: Photomicrograph showing dezincification in stationary contact.



As-polished

500X

Figure 49: Photomicrograph showing dezincification in stationary contact.

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 008804105

Date of Request: 12/17/1998 10:50:33 AM

Print Date: 01/04/1999 01:38:52 PM

Request Description: SPEED CONTROL CUT-OFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006

Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-5535

Phone: (313) 594-2885

PROFS ID: GSTEVEN1

PROFS ID: NLAPPOINT

Fax: (313) 390-7224

Fax: (313) 337-5255

Send Report to:

MD 5005/2G085, AVT MATERIALS, BLDG. #6

Bill to:

Acctg. Location: 5100

Dept: T113

Work Task: XQG04

Sample Information:

Total Number of Containers: 1

Source: Not specified

Sample Handling: Return after test

Supplier Code: Not specified

Part/Material Name

Qty

Sample Identification

Part Number

Material Spec

CPSC Code

Supplier

SPEED CONTROL

1

BURNED CONNECTO

F2VY-SF024-A

NA

18.05.00

TEXAS

CUT-OFF SWITCH

R*

INST

RUMEN

TS

Investigation Information:

Nature of Investigation: Requestor Info. Box: Mail typed report

Fax preliminary results

HIGH PRIORITY - POSSIBLE LEGAL

Additional Sample Information/Testing Requirements:

SAMPLE ID: BURNED CONNECTOR & PRESSURE ACTUATOR (REDDICK)

DETERMINE CAUSE

OF BURNED CONNECTOR - RADIOGRAPH, PHOTOGRAPH, PRESSURE TEST

DIAPHRAGM

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES.

ATTN: S LA

ROUCHE - SAMPLE IN LAB

NOTE: ALL COMMUNICATIONS/REPORT, ETC. TO BE DUAL

(JE N LA POINT)

Reporting Directions:

Date customer would like report: 01/13/1999

Date customer must have report: 01/14/1999

Report Format(s)

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: Morton, Jacqueline R.

Phone: 59-47064

View your test status at: [HTTP://bd4web.pd7.ford.com/kals](http://bd4web.pd7.ford.com/kals)

Program Name: KALISLab Engr Module

Program Version: Version: 2.0.5



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1257
FAX (313) 322-1614

Report 8804105

January 6, 1999

To: G. Stevens (313) 32-38886 (313) 39-07224 FAX

From: P. J. Nallo (313) 33-75358

Subject: Speed Control Cut-Off Switch
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: Particle scrapings were taken from four areas of a used switch (contact, cup, base, and a white residue) as well as from a new base on January 5, 1999.

Object: Perform EDS analyses on each of the five areas.

Conclusion: The results are listed below in the Data and Analysis section.

Data and Analysis:

Surface Analysis

(Visual Examination, Scanning Electron Microscopy (SEM),
Energy Dispersive X-ray Spectroscopy (EDS))

Scrapings were taken from the side of the stationary contact body, the cup region, the base and a white residue from the connector cavity below the wire seal on a used speed control cut-off switch. A silver of material was taken from a new base as well. Each sample was examined on a scanning electron microscope (SEM) using Energy Dispersive X-ray Spectroscopy (EDS). The following elements were detected, in decreasing order of elemental concentration (Figures 1 - 8).

Contact	Cup 1	Cup 2	New Base	Old Base
Copper	Copper	Silicon	Silicon	Silicon
Zinc	Zinc	Calcium	Calcium	Calcium
Sulfur	Chromium	Aluminum	Aluminum	Aluminum
Potassium	Sulfur	Titanium		Titanium
	Potassium	Copper		
	Silicon	Iron		
	Iron			
	Aluminum			
White Residue 1	White Residue 2	White Residue 3		
Phosphorus	Silicon	Phosphorus		
Silicon	Aluminum	Silicon		
Calcium	Potassium			
Iron	Phosphorus			
Aluminum	Iron			
Magnesium	Titanium			
	Magnesium			

Surface Analysis (continued)

The material from the stationary contact body is most likely an oxide of a high copper brass (approximately 85% copper) base material with possibly a sulfate.

The material from the cup is blue-green colored, and is probably a combination of oxide of brass contact material, possibly a sulfate, and fibers from the base.

The new base spectrum is similar to the old base spectrum. The old base has fillers (fibers) along with a binder material present.

The white residue is a combination of materials. It is primarily a high phosphorus material, with some plates of Si-Al-K-rich material mixed in. These are typically found in dry chemical fire extinguishers.

By: 

Patrick J. Nailor (PNAILO6)
Laboratory Specialist

Enclosures: Figures 1 - 8
PJN/pjn



Figure 1: EDS X-ray spectrum of material scraped from the side of the stationary contact body.




Figure 2: EDS spectrum of greenish compound scraped from the cup region.




Figure 3: EDS X-ray spectrum of fibrous material scraped from the cup region.

Note: Nominal magnifications given for photomicrographs.




Figure 4: EDS X-ray spectrum of material shaved from a new base.




Figure 5: EDS X-ray spectrum of fibrous material scraped from the old base.

Note: Nominal magnifications given for photomicrographs.




Figure 6: EDS X-ray spectrum of one of three samples of the white powder taken from the connector cavity below the wire seal.




Figure 7: EDS X-ray spectrum of the second of three samples of the white powder.





Figure 8: EDS X-ray spectrum of the third of three samples of the white powder.


Note: Nominal magnifications given for photomicrographs.



EDS X-ray spectrum material from the pad (area 3).




EDS X-ray spectrum of the fracture surface (area 4).




EDS X-ray spectrum of the green deposit from area 5.

Note: Nominal magnifications given for photomicrographs.




EDS X-ray spectrum of the black deposit from area 7.


Note: Nominal magnifications given for photomicrographs.




Operator : Patrick Nallor
 Client : Greg Stevens
 Job : 9804105
 White Powder 1 (1/6/99 08:28)




Operator : Patrick Nallor
 Client : Greg Stevens
 Job : 9804105
 Contact 1 (1/6/99 08:29)




Operator : Patrick Nallor
 Client : Greg Stevens
 Job : 9804105
 Housing New 1 (1/6/99 08:31)




Operator : Patrick Nallor
Client : Greg Stevens
Job : 9804105
Housing Old 1 (1/8/99 08:32)




Operator : Patrick Nallor
Client : Greg Stevens
Job : 9804105
Cup 1 (1/8/99 08:36)




Operator : Patrick Nallor
Client : Greg Stevens
Job : 9804105
Cup 2 (1/8/99 08:37)




Operator : Patrick Nallos
Client : Greg Stevens
Job : 9804105
Housing Old 2 (1/5/98 08:40)




Operator : Patrick Nallos
Client : Greg Stevens
Job : 9804105
Housing Old 3 (1/5/98 08:51)




Operator : Patrick Nallos
Client : Greg Stevens
Job : 9804105
White Powder 2 (1/5/98 09:14)



Operator: Patrick Neilson
 Client: Greg Stevens
 Job: 9804105
 White Powder 3 (1/8/99 09:23)



Operator: Patrick Neilson
 Client: Greg Stevens
 Job: 9804105
 White Powder 4 (1/8/99 09:32)



Operator: Patrick Neilson
 Client: Greg Stevens
 Job: 9804105
 5a (1/14/99 13:03)