


EA02-025

FORD 10/27/03


APPENDIX N

BOOK 18 OF 61


PART 3 OF 4




Operator : Patrick Nelles
Client : Greg Stevens
Job : 9804105
7a (1/14/98 16:27)




Operator : Patrick Nelles
Client : Greg Stevens
Job : 9804105
7b (1/14/98 16:28)



Operator : Patrick Nelles
Client : Greg Stevens
Job : 9804105
7c (1/14/98 16:41)



Operator : Patrick Nelles
Client : Greg Stevens
Job : 9804105
Date (1/14/98 10:51)



Operator : Patrick Nelles
Client : Greg Stevens
Job : 9804105
1a (1/14/98 10:18)

TITLE Spall Control C.t.Off SmithFrom Page No. To: Guy Stevens / General Products

Subject: Spall Control C.t.Off Smith

Priority: P&M 9/27/89

Specimen: U.P. Powell

Equipment: Team Instruments

Reason: Particle erosion was taken from 4 mm at - used 5-16
(carbon, cup, beryllium, 3000 cycles) - will be comparing with other

Object: Particle size analysis to the 5 micrometer

Test Date:

EDS Equipment

Suspicious taken for the categorization of aging beryllium (Al)
which can be measured with, to determine wear debris.

The sample was analyzed on a SEM 4000 at 20 kV, and the
the Al₂O₃ phase was detected in decreasing order of abundance
(constant current, low velocity detector, up to 20 kV with EDS)

Element	Cat	Cat	Cat	Mineral	Mineral	Mineral
Cu	Cu	Cu	Si	Si	Si	Fe
Zn	Zn	Zn	Ca	Ca	Ca	Ca
S	C	C	Al	Al	Al	Si
Al	Si	Ti		Ti	Ti	Ti
K	Cu					
Si	Ca					
Fe						
Al						

To Page No. 20

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

From Page No. 19

SDs description (cont)White PandaWhite PandaWhite Panda

7

3:

?

2:

4:

5:

Ca

K

Ce

P

Cl

F

Mg

Ti

N

A

Cottage on a high Cr. Bank (solid + rolled)Mall the Cr. is a large school, probably visited a house. Land
for the school, along w/ library, long the bank,
Now having grown up under the old house. Old house has floor
+ walls still standing.The white mottled Panda is a smallish catch by about
a high T. tail of the path of S-A-K and until -idea.This is from fire extinguisher.

To Page No. 24

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

11/6/99


From Page No. 24

San Joaquin 2 PDS Coats
P.M. Serial was established 1/19 f. Sh. & S. and

① Document one day, or cause of change or cause

② Same thing, see line 2 - if cause is no change

③ same 2-1 be no change Do PDS of the cause



Better explain the effect no change
is resulting.

Br. No. 2 do not take the one day, or last one day, over
likely, is a cause of change to last one day.


Paid back to have occurring first PDS. for hub & coat
Br. No. = sulfate

④ Determine cause rule - use option, etc., if necessary

⑤ Determine cause rule

⑥ PDS of Deposit

⑦ PDS of Deposit



To Page No. 25

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

TITLE Span Control Shut Off Switch (cont)Project No. 9364105-5
Book No. 27-56From Page No. 25Son & SDS (cont)

(4) Formed side walls of top panel right angle
feature is Preformed Bitube Intake (BKG)
SDS shows you can see SFC on the faces

(5) Cuts in BKG

(6) Details have been omitted at several corners (This may vary)

67ZC4CCZSSS:SCaKKSiA1

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date



Recorded by

9/16/90


3713 2847

804105

- ① Document PDC
Damage Corrosion
or Status now continue
- ② Examining Pictures
is T PDC Damaged
OK Coating
- ③ Examining PDC for
PDC Damage
AS-IS, EDS of coating
- ④ Determine fracture
mode. Clean if
necessary (Rev. tape)



- ⑤ mode of crack if
possible.
- ⑥,7 EDS of Deposits
(scrub - if necessary
to avoid peaks from
base metal.)





Central Laboratory
16000 Century Drive
Dearborn, MI 48120-1267
FAX (313) 322-1814

Report 9804106

Preliminary

January 6, 1999

To: G. Stevens/N. LaPointe (313) 32-36686 07224 FAX

From: S. LaRouche (313) 84-54878

Subject: Speed Control Cut-Off Switch
Part Number: F2VY-BF24-A
Source: Customer Vehicle

Received: One switch which had been involved in a thermal event, one unused switch, and unused switch components were received on December 17, 1998.

Object: Determine cause of thermal event.

Conclusion: Surface analysis indicates that oxide or corrosion product from the brass contacts may have transferred to the cup component of the switch. Deposits on the cup also appear to contain filler materials from the switch base.

The white deposit in the connector cavity below the wire seal appears to be from a dry chemical fire extinguisher.

Data and Analysis:

Surface Analysis

(Visual Examination, Scanning Electron Microscopy (SEM),
Energy Dispersive X-ray Spectroscopy (EDS))

The as-received condition of the switch is shown in Figure 1. The switch is shown after sampling for EDS in Figure 2 (arrow A in photograph points to area where sample was removed). Energy dispersive X-ray spectroscopy was performed on the following materials:

Oxide-like material on side surface of stationary contact body¹

Greenish deposit visible on switch side of cup²

Material scraped from switch base

Material scraped from new switch base

White material in cavity of connector below wire seal

The spectra from these materials are attached.

The spectra from the material on the side of the stationary contact exhibits elements from the base metal (brass) as well as a trace amount of sulfur. This suggests that the material on the surface of the stationary contact is most likely an oxide of the base metal with possibly a sulfate.

¹ Small scraping from side of contact.

² Small scraping from deposit.

Surface Analysis - continued

The spectra from the greenish deposit on the cup exhibits mostly copper and zinc with trace amounts of sulfur, potassium, silicon, chromium, and iron. The presence of copper and zinc indicates that the deposit is primarily an oxide of the brass contact material which has transferred to the cup. The presence of sulfur suggests that some of the material may be a sulfate. The chromium and iron are most likely from the cup. The deposit also contains fibers which have spectra similar to those in the switch housing.

Spectra from the switch bases are similar. Aluminum, silicon, and calcium are most likely from the fillers (fibers, etc.) used in the housing material.

Spectra from the white deposit exhibit elements which would be found in dry chemical fire extinguishers, i.e., high phosphorus content material with plates of Si, Al, P - rich material (Muscovite).

Contributor: P. Nallos

Concur:

P. Kies, Supervisor
Metallurgy Section

By:

Steven LaRouche (SLAROUCH)

Enclosures: Eight EDS spectra
Data sheet on muscovite

SL/ai

11

LE

SWITCH


On Page No. B437 S

Project No. 9804105
Book No. 2697

65

Rec'd 12-17-91

Received one switch from Trans Instruments / Miltel Inc.

Liaison
1-6-92

Received new switch & was switch

connected during testing with Trans Instruments / Miltel Inc.

F. Fokken on 12-22-91

A Zener diode was connected 12-21-91 in parallel to
N.I.R. Power's 3.5V battery.

To Page No.

Received & Understood by me,

Date

Invented by

Date

Guaranteed Inv.

3713 2651



Central Laboratory
16000 Century Drive
Dearborn, MI 48120-1257
FAX (313) 322-1614

Report #804106

January 6, 1989

To: G. Stevens (313) 32-36686 (313) 39-07224 FAX

From: P. J. Naloe (313) 33-75358

Subject: Speed Control Cut-Off Switch
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: Particle scrapings were taken from four areas of a used switch (contact, cup, base, and a white residue) as well as from a new base on January 5, 1989.

Object: Perform EDS analyses on each of the five areas.

Conclusion: The results are listed below in the Data and Analysis section.

Data and Analysis:

Surface Analysis

(Visual Examination, Scanning Electron Microscopy (SEM),
Energy Dispersive X-ray Spectroscopy (EDS))

Scrapings were taken from the side of the stationary contact body, the cup region, the base and a white residue from the connector cavity below the wire seal on a used speed control cut-off switch. A sliver of material was taken from a new base as well. Each sample was examined on a scanning electron microscope (SEM) using Energy Dispersive X-ray Spectroscopy (EDS). The following elements were detected, in decreasing order of elemental concentration (Figures 1 - 8).

Contact	Cup 1	Cup 2	New Base	Old Base
Copper	Copper	Silicon	Silicon	Silicon
Zinc	Zinc	Calcium	Calcium	Calcium
Sulfur	Chromium	Aluminum	Aluminum	Aluminum
Potassium	Sulfur	Titanium		Titanium
	Potassium	Copper		
	Silicon	Iron		
	Iron			
	Aluminum			
White Residue 1	White Residue 2	White Residue 3		
Phosphorus	Silicon	Phosphorus		
Silicon	Aluminum	Silicon		
Calcium	Potassium			
Iron	Phosphorus			
Aluminum	Iron			
Magnesium	Titanium			
	Magnesium			

From Page No. —

CENT COORDINATOR: STEVE
LAROCHE

BY G. STEVENS

RECEIVED: 3 CUT OFF SWITCHES (1 ASSEMBLED,
ASSEMBLED NEW, & 1 DISASSEMBLED FAILED)
WERE RECEIVED ON 12/17/98.

REQUESTED: DETERMINE THE EXTENT/CASE OF
THE DAMAGED RAYTON STRIPS.

SEE THE REPORT FOR DETAILS

To Page No. —

Witnessed & Undersigned by me.	Date	Invented by	Date
Recorded by			



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1267
FAX (313) 322-1614

Report 98D4106

Preliminary Report

January 16, 1998

To: G. Stevens/N. LaPointe (313) 32-36668 07224 FAX

From: V. Beltran (313) 69-47304

Subject: Speed Control Cut Off Switch
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: 3 switches (1 assembled, 1 assembled new, and one disassembled failed) were received on December 17, 1996.


Object: Determine the extent/cause of the damage Kapton Strip.


Conclusion: Damage appears to have been initiated at the Kapton strip closest to the washer prior to assembly of the switch by pinching and/or impact which tore the teflon and deformed the Kapton material. The damaged Kapton material appears to have been darkened and embrittled by an unknown mechanism.

Date and Analysis:

See Attached Photographs.

By:


Vladimir S. Beltran (VBELTRA1)
Laboratory Engineer




3713 2655

CONCAVE SIDE DOWN



#3 CONCAVE DOWN





3719 2668

CONCAVE SIDE DOWN



3713 2868



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1297
FAX (313) 322-1814

Report 9804105

Preliminary Report

February 6, 1999

To: G. Stevens/N. LaPointe (313) 32-36686 39-07224 FAX

From: V. Beltran (313) 39-05018

Subject: Speed Control Cut Off Switch
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: 3 switches (1 assembled, 1 assembled new, and one disassembled failed) were received on December 17, 1998.

Object: Determine the extent/cause of the damage Kapton Strips.

Conclusion: Damage appears to have been initiated at the Kapton strip closest to the washer prior to assembly of the switch. Pinching and/or impact tore the Teflon and deformed the Kapton material. The damaged Kapton material appears to have been darkened and embrittled by an unknown mechanism.

Data and Analysis:

Reflected Light Microscopy




Figure 1.
Kapton Strip (Teflon Layers Removed) Closest to
Washer with Concave Side Down.
7X Magnification



Scanning Electron Microscopy




Figure 2.
SEM Photomicrograph of Brittle Fracture on Kaption Strip.
The fracture appears to propagate away from the washer.
The direction of propagation is perpendicular to the plane of the page.
250X Magnification



Scanning Electron Microscopy, continued



Figure 3.
*Scanning Electron Photomicrograph of Brittle Fracture on Kapton Strip.
The direction of fracture propagation is perpendicular to the plane of the page.
230X Magnification*

By:

Vladimir S. Beltran (VBELTRA1)
Laboratory Engineer, Polymers Section



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1267
FAX (313) 322-1614

Report 9604105
Preliminary Report

February 10, 1998

To: G. Stevens/N. LaPointe (313) 32-36666 39-07224 FAX

From: V. Beltran (313) 39-06018

Subject: Speed Control Cut Off Switch
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: 3 switches (1 assembled, 1 assembled new, and one disassembled failed) were received on December 17, 1998.

Object: Determine the extent/cause of the damage Kapton Stripe.

Conclusion: Damage to the Kapton strips appears to be the result of pinching and/or buckling of the Kapton material. The damaged Kapton material appears to have been darkened and embrittled by an unknown mechanism and fractured in a brittle mode. Torn Teflon material on all three strips of the switch coinciding with the location of the fractured Kapton material provide a leak path.

Data and Analysis:

Reflected Light Microscopy



Figure 1.
Kapton Strip (Teflon Layers Removed) Closet to
Washer with Concave Side Down.
7X Magnification



Scanning Electron Microscopy




Figure 2.
SEM Photomicrograph of Brittle Fracture on Kepton Strip.
The fracture appears to propagate away from the viewer.
The direction of propagation is perpendicular to the plane of the page.
253X Magnification



Scanning Electron Microscopy continued



Figure 3.
*Scanning Electron Photomicrograph of Brittle Fracture on Kapton Strip.
The direction of fracture propagation is perpendicular to the plane of the page.
230X Magnification*

By:

Vladimir S. Beltran (VBELTRA1)
Laboratory Engineer, Polymers Section



Central Laboratory
18000 Century Drive
Dearborn, MI 48120-1287
FAX (313) 322-1514

Report 9804106

January 19, 1999

To: G. Stevens/N. LaPointe/S. LaRouche (313) 32-36886 07224 FAX
From: Gayle D. Gullen (313) 32-27322
Subject: Speed Control Cut-Off Switch
Part Number: F2VY-9F924-A
Source: Customer Vehicle

*Car to show
accord of test
until we found
no signs -*

Received: One opened switch which had undergone a thermal event and one unused switch housing were received on January 4, 1999, from S. LaRouche. The switch was returned on January 11, 1999, after disassembly and preliminary examination by Texas Instruments.

Object: Determine if any fluid is present on the switch base in metallic-exposed area and compare the switch housing material to the unused material. Determine the nature of the black residue in the hexport and converter and determine the type of fluid in the diaphragm squares.

Conclusion/
Discussion: There was spectral evidence of a glycol ether [spectrally similar to Dow HD 50-4 brake fluid] and a metal soap on the metallic-exposed area of the switch cup. The customer base and unused base are spectrally similar and are composed of a polyester material. This is not the 'Noryl' material which was specified. [Noryl is a styrenated PPO (polyphenylene oxide).] The exact nature and source of the noted metal soap could not be conclusively determined. Metal soaps can be utilized as polymeric compounding and/or mold release agents. Metal soaps are also utilized in greases (this glycol ether material does not match known carrier grease fluids) and may also be formed in the presence of acids and metal salts (both perhaps a reaction of the polymeric housing and metallic interference during the event). The black residue in the hexport, converter, and washer are similar and are composed of a glycol based material [probably brake fluid] and a metal salt [probably an oxalate salt]. The black residue on the spacer is composed of a metal salt [probably oxalate salt], and a glycol based fluid [probably brake fluid]. The fluid removed from the #2 diaphragm was glycol based [probably brake fluid] and contained a metal salt [probably oxalate salt]. The hexport deposit appears to contain ~10% water, however, this value may be artificially elevated due to reactions with the salts and other compounds in the deposit. Decomposition of the polyester base causes acid formation, with one of these acids likely being oxalic acid. Reaction with the metals in the system forms oxalate salts. Based on this, it is highly unlikely that the oxalate salts were introduced into the system in this fashion but were likely formed during the thermal decomposition of the housing.

Data and Analysis:

Molecular Characterization

(FTIR, Qualitative, Microscopic)

Arrow B in Figure 2 points to area where analysis was performed. Spectra of the fluid noted on the metallic surface [chloroform micro casts - several areas] are characteristic of a glycol ether [spectrally similar to Dow HD 50-4 brake fluid] with evidence of an ester and metal soap. Spectra of the new, brown base are characteristic of a polyester on the base of terephthalic acid. Spectra of the blackened, customer base are similar to the new base and are characteristic of a polyester on the base of terephthalic acid.



Molecular Characterization
(FTIR, Qualitative, Conventional and Microscopic)

Hearport Deposit

Spectra as received are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].

Spectra of the methanol solubles are characteristic of a glycol based material [probably brake fluid] and ester.

Spectra of the insolubles are characteristic of essentially a metal salt [possibly an oxalate].

Convector Deposit

Spectra as received are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].

Spectra of the methanol solubles are characteristic of a glycol based material [probably brake fluid, ester, and other material].

Spectra of the insolubles are characteristic of essentially a metal salt [possibly an oxalate].

Spacer Deposit

Spectra of the deposit [as received] are characteristic of a metal salt [possibly an oxalate] and a glycol based material [probably brake fluid].

Washer Deposit

Spectra of the deposit [as received] are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].

Drainage #2 Internal Fluid/Coolant

Spectra as removed are characteristic of a glycol based material [probably brake fluid] and a metal salt [possibly an oxalate].

Water Content, % by weight¹ ~10
(ASTM D 1744)

¹ Accuracy of this result is unknown based on the small sample size and possible interferences caused between compounds present in the deposit and the titrant.

INFORMATION²

Chemical Resistance	Polytetrafluoroethylene [Teflon ®] ³	Polyimide [Ultram ®]	Polyester [Valox ®]
Brake Fluid [100% conc./73°F/180 days]	no information listed	no information listed	no observed changes no tensile strength change
Sulfuric Acid	no observed changes -2% tensile change [30% conc/212°F/8hr]	no observed changes -3% tensile change [20% conc/73°F/100 days]	no observed changes -4% tensile change [36% conc/73°F/180 days]
Water Absorption, % [1/8 in thick sample, 24hr]	<0.01	0.24-0.34	0.06-0.08 [30% glass filled]
Environmental Stress Cracking			
Brake Fluid [100% conc/2500 psi stress/72°F]	no information listed	>336 hours - no failure	no information listed

² Information obtained from Modern Plastics Encyclopedia, October 1984, November 1998: Teflon ® manufactured by DuPont, Ultram ® and Valox ® are manufactured by General Electric. Ultram ® is a polyetherimide material similar to Kapton ® polyimide which is manufactured by DuPont. Ultram ® was substituted for informational purposes only since Kapton ® information was not readily available (water absorption information is for Kapton ®, Ultram ® value is 0.25.)

³ "Not known to dissolve in any known solvent and not attacked by highly corrosive acids and caustic materials", Today's Chemist At Work, January 1998

Contributor: V. Cooper, M Haga

Concur:

Mary Haga
Organic Section

By:

Gayle D. Guillen (GGULLEN)
Product Materials Engineer



Central Laboratory
18000 Century Drive
Dearborn, MI 48120-1287
FAX (313) 322-1614

Report #604106

Preliminary

January 6, 1999

To: G. Stevens/N. LaPointe/S. LaRouche (313) 32-36686 07224 FAX
From: Gayle D. Gullen (313) 32-27322
Subject: Speed Control Cut-Off Switch
Part Number: F2VY-9F824-A
Source: Customer Vehicle

Received: One opened switch which had undergone a thermal event and one unused switch housing were received on January 4, 1999, from S. LaRouche.

Object: Determine if any fluid is present on the switch base in metallic-exposed area and compare the switch housing material to the unused material.

Conclusion/ Discussion: There was spectral evidence of a glycol ether [spectrally similar to Dow HD 50-4 brake fluid] and a metal soap on the metallic-exposed area of the switch cup. The customer base and unused base are spectrally similar and are composed of a polyester material. This is not the 'Noryl' material which was specified. [Noryl is a styrenated PPO (polyphenylene oxide).] The exact nature and source of the noted metal soap could not be conclusively determined. Metal soaps can be utilized as polymeric compounding and/or mold release agents. Metal soaps are also utilized in greases [this glycol ether material does not match known carrier grease fluids] and may also be formed in the presence of acids and metal salts [both perhaps a reaction of the polymeric housing and metallic interference during the event].

Data and Analysis:

Molecular Characterization
(FTIR, Qualitative, Microscopic)

Arrow B in Figure 2 points to area where analysis was performed. Spectra of the fluid noted on the metallic surface [chloroform micro casts - several areas] are characteristic of a glycol ether [spectrally similar to Dow HD 50-4 brake fluid] with evidence of an ester and metal soap.

Spectra of the new, brown base are characteristic of a polyester on the base of terephthalic acid. Spectra of the blackened, customer base are similar to the new base and are characteristic of a polyester on the base of terephthalic acid.

Contributor: V. Cooper

Concur:

Mary Haga
Organic Section

By:

Gayle D. Gullen
Gayle D. Gullen (GGULLEN)
Product Materials Engineer

From Page No. 1City, State / Sample Location

Address: 1900 South 1st Street, P.O. Box 9964, San Jose, CA 95140-0964
 Specimen number: 93-24103-1
 Date received: Tuesday, April 11, 1995
 Date issued: Tuesday, April 11, 1995
 Label: "Benthos"

Specimen: Very macroscopic, robust oligochaetid polychaete,
 bright yellow-green at the anterior end becoming
 brownish-orange posteriorly.

Posteriorly about 1/4 of the body is brown,
 but becomes heavily yellow.

Body covered in undulating

longitudinal

ridges produced from a pale mottled

area

1/4/95 AM: Several small white oval structures with
 reflective film covering. I found it difficult to find
 some in the body. The soft tubules in the
 anterior area at the midline of my sample were either
 soft enough to

white when I extracted them - or

4105A Spec

7105B Spec

Several of these having

the internal cellular structure more clearly delineated

by some of the surrounding

4105C Spec

4105D Spec

5

To Page No. 1

Project No. 70005

Book No. 1104 TITLE Spud Solder L-2021-Weldable Metals

On Page No. _____

- Material Characterization
- (Fourier Transform Infrared Spectroscopy)
- Spectra of characterizes metal at the metal surface inside the reactor are characteristic of glycol ether (similar to varnish).
- and exhibit flame standard metal soap.
- Spectra of the thermoplastic bonding material are characteristic of polyester, and/or decapentadiene acid.
- Spectra of the blistered plastic having outside characteristic of polyisobutylene or tetraphenylbenzidine.

Nicki Cooper
1/6/1989

To Page No. _____

Witnessed & Understood by me.

Date

Invented by

Date

7804/05



FIG 2 SAMPLE
REMOVED

3713 2672

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 0008024106
Date of Request: 12/17/1998 10:30:33 AM
Print Date: 01/04/1999 01:36:32 PM

Request Description: SPEED CONTROL CUT-OFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-6888 PROFS ID: GSTEVEN1 Fax: (313) 390-7224
Phone: (313) 594-2656 PROFS ID: NLAPPOINT Fax: (313) 337-8266

Send Report to:
BIR to:
MD 6006/23065, AVT MATERIALS, BLDG. MS
Acctg.Location: 5100
Dept: T113
Work Task: XQ004

Sample Information:

Total Number of Containers: 1
Source: Not specified

Sample Handling: Return after test
Supplier Code: Not specified

Part/Material Name	Qty	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUT-OFF SWITCH	1	BURNED CONNECTO R *	P2VT-SP924-A	NA	18.08.00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requestor info. Box: Mail typed report
Fax preliminary results
HIGH PRIORITY - POSSIBLE LEGAL

Additional Sample Information/Testing Requirements:

SAMPLE ID: BURNED CONNECTOR & PRESSURE ACTUATOR (REDDICK)

DETERMINE CAUSE
OF BURNED CONNECTOR - RADIograph, PHOTOGRAPH, PRESSURE TEST
DIAPHRAGM.

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES.

ATTN: S. LA
ROUCHE - SAMPLE IN LAB

NOTE: ALL COMMUNICATIONS/REPORT, ETC. TO BE DUAL
(I.E. N. LA POINT).

Reporting Directions:

Date customer would like report: 01/13/1999
Date customer must have report: 01/14/1999

Report Format(s):

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: Morton, Jacqueline R.

Phone: 59-47084

[View your lab's status etc. at: HTTP://bd4web.pd7.ford.com/kells/](http://bd4web.pd7.ford.com/kells/)

Program Name: KALISLab Engg Module
Program Version: Version: 2.0.6

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009804104
Date of Request: 12/17/1998 10:50:33 AM
Print Date: 01/04/1999 01:36:52 PM

Request Description: SPEED CONTROL CUT-OFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-6688 PROFS ID: GSTEVEN1 Fax: (313) 390-7224
Phone: (313) 694-2686 PROFS ID: NLAPPOINT Fax: (313) 337-8258

Send Report to: MD 6006/25055, AVT MATERIALS, BLDG. #6
Bill to: Acctg.Location: 5100
Dept: T113
Work Task: XQG04

Sample Information:

Total Number of Containers: 1
Source: Not specified

Sample Handling: Return after test
Supplier Code: Not specified

Part/Material Name	Qty	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUT-OFF SWITCH	1	BURNED CONNECTOR R *	F2VY-SPR24-A	NA	18.00.00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requestor Info. Box. Mail typed report
Fax preliminary results
HIGH PRIORITY - POSSIBLE LEGAL

Additional Sample Information/Testing Requirements:

SAMPLE ID: BURNED CONNECTOR & PRESSURE ACTUATOR (REDDICK)

DETERMINE CAUSE
OF BURNED CONNECTOR - RADIOGRAPH, PHOTOGRAPH, PRESSURE TEST
DIAPHRAGM.

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES.

ATTN: S. LA
ROUCHE - SAMPLE IN LAB

NOTE: ALL COMMUNICATIONS/REPORT, ETC. TO BE DUAL
(I.E. N. LA POINT).

Reporting Directions:

Date customer would like report: 01/13/1999
Date customer must have report: 01/14/1999

Report Format(s):

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: Morton, Jacqueline R.

Phone: 59-47064

View your test status at: '<HTTP://b64web.pdf.Jord.com/kalts>'

Program Name: KALISLab Engr Module
Program Version: Version: 2.03

8:30 AM

except

went to ID lab report, including J. C. Miller's -
try straight LiClO_4 - excess of monomer
solvent to remove polymeric - NaCl - gotten
new solubles + insolubles

Concester

Same as report

Spacem.

Cited LiClO_4 in "Chemical & Indus."

nicer

than LiClO_4 - this however

? conclusion for LiClO_4 ?

Thanks

Leslie

3713 2675

For Central Lab
1-11-99

43040

- Hex port
 - + Sample black sludge id:
water - doubtful to detect by IR or KFT
brake fluid
unknown.
- Kapton (3-diamond squares)
 - + Sample fluids -
 - water -
 - brake fluid -
 - unknown
 - + Assess Kapton's sensitivity to water/brake fluid
- Cup
 - steel convex side
 - + Sample heavy black deposits
- Electrical Soc.
 - id black compound on one blade
 - id gray compound on 2nd blade
- Stationary Terminal
 - Remove 1/2 & ~~other~~ Photo SEM \rightarrow clean
& determine fix mode.

530 ~ 55

Report

went to 1D Nod deposit, including 1 & 2 others
try sharp = 2 ft - green or micro
solvent to remove bedded - mean - filter
run solubles & insoluble

Converter

same as Report

Specie

? C. to? - R in 'Ciliates' ? on bank

water

also see 1000 ft. 1000 ft.

? concentration for H₂O?

Thanks

Kayle

3713 2677

225-05

rept

sent to ID lab report, including 1/2 gitters & 1/2
try cinch = 2 ft - greenish mass;
solvent to remove hydrophilic - 1/2 - filter
non soluble & insoluble

Conceter

Same as herpet

Spacer

Cinch + 2 in 'Cinch' in 10.0 ml

viscous

Same as conceter

? concentration for +, 0?

Thanks

Loyd

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009804106

Date of Request: 12/17/1998 10:50:33 AM

Print Date: 01/12/1999 09:30:44 AM

Request Description: SPEED CONTROL CUT-OFF SWITCH

Customer Information:

Primary Contact: STEVENS, GREG - 10008
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-8696 PROFS ID: GSTEVEN1 Fax: (313) 390-7224
Phone: (313) 594-2566 PROFS ID: NLAPOINT Fax: (313) 337-8256

Send Report to:
Bill to:

MD 8008/23095, AVT MATERIALS, BLDG. #6
Actg.Location: 5100
Dept: T113
Work Task: XQG04

Sample Information:

Total Number of Containers: 1
Source: Not specified

Sample Handling: Return after test.
Supplier Code: Not specified

Part/Material Name	City	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUT-OFF SWITCH	R	BURNED CONNECTOR	P2V7-SP024-A	NA	18.08.00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requestor Info. Box. Mail typed report.
Fax preliminary results
HIGH PRIORITY - POSSIBLE LEGAL

Additional Sample Information/Testing Requirements:

SAMPLE ID: BURNED CONNECTOR & PRESSURE ACTUATOR (REDDICK)

DETERMINE CAUSE
OF BURNED CONNECTOR - RADIograph, PHOTOGRAPH, PRESSURE TEST
DIAPHRAGM.

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES.

ATTN: S. LA
ROUCHE - SAMPLE IN LAB

NOTE: ALL COMMUNICATIONS/REPORT, ETC. TO BE DUAL
(I.E. N. LA POINT).

Reporting Directions:

Date customer would like report: 01/13/1999

Date customer must have report: 01/14/1999

Report Format(s):

Log-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: Morton, Jacqueline R.

Phone: 59-47064

Program Name: KALISLab Engr Module
Program Version: Version: 2.0.6

View your test status at: <HTTP://fd4web.pdf.ford.com/kalis>

Gullen, Gayle (G.D.)

From: Gullen, Gayle (G.D.)
Sent: Thursday, January 14, 1999 11:44 AM
To: LaRouche, Steve (S.)
Cc: Kowalczyk, Richard (R.A.)
Subject: black residue in switch

Steve,

I went back to some basic chemistry information I had available and I believe I know how the black residue is forming inside the switch. We have seen this black residue in the Yuma Police vehicles as I told you yesterday. We had tentatively identified it as an oxalate [a metal salt of an oxalic acid]. What bothered us is that the usage of this material is for cleaning metal parts and that didn't fit. However, based on past experience with polyester materials we knew that acids were formed during the decomposition process. Terephthalic acid [the base acid in the polyester] has a ring structure with side groups. If you take the side groups off and leave the ring structure you form oxalic acid which would make sense if the housing were smoldering. Glycols and glycol ethers [which is what brake fluids are made up of] are highly reactive with this acid. This in turn with contact with any metallic surface would form a metal salt of oxalic acid. This still doesn't tell us what caused the fire to start, however, it indicates that brake fluid had to be present within the area of the housing reaction during the smoldering of the part and that it was not introduced into the part in this reacted form. I'll forward this information to you when I write up my portion of the report; however, I don't have Mary's formal data in order to do that at this time.

Regards,

Gayle Gullen

Gayle Gullen (313) 32-27322 (313) 32-21614 FAX


Gullen, Gayle (G.D.)

From: LaRouche, Steve (S.)
Sent: Wednesday, December 23, 1998 12:31 PM
To: Gullen, Gayle (G.D.); Schumacher, Dan (D.E.); LaRouche, Steve (S.)
Cc: Klass, Pete (P.F.); Kowalczyk, Richard (R.A.); Manor, James (J.R.)
Subject: Brake/Cruise Control Switch Failure Analysis

Gayle and Dan: We are going to have a meeting in the large conference room on January 4 to discuss what types of analyses we could perform on a brake/cruise control switch that was involved in a fire. Specifically we may need to identify corrosion products, brake fluid, and other materials which could have entered the switch. Nonn LaPointe from Design Analysis will most likely attend. Please attend if you can, or let me know if you can send a substitute. ASQ needs to respond to NHTSA by 1/15/99. If asked to perform analyses, we will probably need to respond by 1/7/99. Thanks.

Steve LaRouche (SLAROUCH)
Metallurgy Section
Central Laboratory, Room N410
(313) 845-4878
(313) 322-1614 FAX

Hydraulic Pressure Switch Cross Section



From Page No. _____

E.R.Lower Deposit:

Mineral isolates: essentially metal salts (possibly an oxidate)

Upper Deposit

Metal salts (possibly an oxidate) & glass
basic material (possibly brackish)

Rubber Deposit

Glassy basic material (possibly brackish fluid)
Metal salt (possibly an oxidate)

Pipelines

Glassy basic material (possibly brackish fluid)
Metal salt (possibly an oxidate)

M. C. Hey11/19/99

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

From Page No. _____

Received: Hexpack
 Coagulator
 Spacers
 Washer
 Daphargin

Water of Deposit Fr. Export, 9.6 wt

ASTM D1744

Blanks = 1.255 mg

Tare = 5.6395 mg/ea

Sand weight	0.0089
1.1 point, ml	1.454
g.	13.6855

 $\sim 10\%$

ETC

Hexpack deposit:
 as received: glycol based material (solid, fine floc)
 + metal salts possibly an oxalate

Metal Solubles: glycol based material (probably
 broken floc) + ester

Methanol insolubles: essentially metal salts
 (possibly an oxalate)

Coagulator deposit

as received: glycol based material (probably broken
 floc) + metal salts (possibly an oxalate)

Metal solubles: glycol based material (probably
 broken floc), ester + other material

To Page No. _____

Witnessed & Understood by me,


Date

Invented by

Date

Recorded by

BALL BEARING, CENTER CAVITY



WELL APPLIED TO SURFACE

3713 2686

Project No. _____

Book No. _____

TITLE _____

Page No. _____

9804105

Drey Stevens / D. L. Parke

Types I called and affirmed

WY 10pm mdy with Not Read
designated people due to perform
while waiting for T2 recorded
and Mag. C&X (APD)

from Kaylor

referred to C&X mdy to look
for back/other

returned first & copy of inspection to file

To Page No. _____

Read & Understood by me,

Date

Invented by

Date

M. M. M. M.

1/6/99

3713 2656

Project No. _____
Book No. _____

From Page No. _____

98-4105

They Stevens / J. L. Davis
Speed Credit Unit of Service

Meeting Monday at 9:30-11:30 Single
Book opened account + paid up to date

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date

3713 2687

From Page No.

Copy I want / Single carbon

Because: A gun with F3VCF934 as serial no. came in a
specialized case, but was never in a small power bay
and was sent on Tuesday 2, 1998. The gun is described
"Marked"

Object: Very durable infrared microspectrometer,
large enough not to be connected to the power or
have such screen materials.

Probability stored in gun bay panel,
not required heavy material.

Heavy material is required

Very much

Very probable which would be checked

920

4/3/1998 Believed to analyze what was at continuously
reflected. The reason, I found it reflected most by
some in the way. The first intention with the
captain was not to interfere and my damage to others
drift cannot be cut.

Next object: electronic circuit

4105A-1pa

"145B-1pa

Scanning of beam having

This is electronic, nothing in the body is not easily damaged

by vibration. It is good at moving

4105C-1pa

True to the electronic having

4105D-1pa

To Page No.

Witnessed & Understood by me,

Date

Invented by

Date

From Page No. _____

Molecular Weight Reduction

(Fourier Transform Infrared Spectroscopy)

Spectra of a chloroform extract of the metal surface inside the connector are characteristic of glycerine (similar to water film) and indicate evidence of water and metal soap.

Spectra of the brown plastic housing material are characteristic of polycarbonate or polycarbonate terephthalic acid.

Spectra of the blackened plastic housing material are characteristic of polycarbonate based on terephthalic acid.

Walter L. Jones

4/6/1988

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date

Generated by

3713 2689

On Page No. _____

Received Hex part

Convector

Spacer

Washer

Diaphragm

Date of deposit from Hex part, 2 lbs wt

ASTM D1744

Blanks = 1, 25.9 mg

7.16 = 5.6095 mg/1cc

undeg g 0.084

undeg ml 1.464

or 13.6895

~ 10.2

IIR

Hex part deposit:

as received: glycol based material (probably brake fluid)

+ metal salt (possibly an oxalate)

Methanol solubles: glycol based material (probably
brake fluid) + ester

Methanol insolubles: essentially metal salt
(possibly an oxalate).

Convector deposit

as received: glycol based material (probably brake
fluid) + metal salt (possibly an oxalate)

Methanol solubles: glycol based material (probably
brake fluid), ester + other material

To Page No. _____

Witnessed & Understood by me.

Date

Invented by

Date

From Page No. _____

FTRInverter Deposits

Methanol insolubles; essentially metal salts (probably an oxalate)

Spacer Deposit

Metal salt (probably an oxalate) + glycol
based material (probably brake fluid)

Washer Deposits

Glycol based material (probably brake fluid)
Metal salt (possibly an oxalate)

Diphosphates

Glycol based material (probably brake fluid)
Metal salt (possibly an oxalate)

M. C. Flayor

11/14/69

9804105 SPACER, DEPOSIT

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Origin: *m*

Conc:

Interpretation:

Wed Jan 13 09:51:20 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)


Resolution: 4.00

Detector: MCT[16]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



9804105 WASHER, DEPOSIT

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: BETWEEN NaCL PLATES — MCKEEAN

Exptno: 0015

Interpretation:

Wed Jan 13 09:43:59 1999 Engineer: MCH

Scan: 128 / 256


APOD: Norton-Bear (medium)

Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance X Axis: Wavenumber



9804105 DIAPHRAGM, DEPOSIT

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Detector: MCT
Concen:

Interpretation:

Wed Jan 13 11:19:29 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)



Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



9804105 CONVERTOR

Specification:

Supplier:

Preparation method: INSOLUBLES

IR Technique: BETWEEN NaCL PLATES

Engineer: M.K.

Concur:

Interpretation:

Thu Jan 14 10:07:52 1999

Engineer: MCH

Scans: 32 / 64

APOD: Norton-Bear (medium)


Resolution: 4.00

Detector: TGS(0)

Gain: 4 / 4

Y Axis: % Transmittance

X Axis: Wavenumber



37182696

9804105 CONVERTOR

Specification:

Supplier:

Preparation method: MEOH SOLUBLES

IR Technique: BETWEEN NACL PLATES

Thu Jan 14 09:19:01 1999

Engineer: MCH

Scan: 32 / 64

APOD: Norton-Beer (medium)

Resolution: 4.00

Detector: TGS[0]

Gain: 2 / 2

Y Axis: % Transmittance


X Axis: Wavenumber

Engineer: MCH

Comment:

Interpretation:

glutaric acid + Al powder, melt, cool, + after material



9804105 CONVERTOR, DEPOSIT

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: BETWEEN NaCl PLATES

Explorer: 201

Conc:

Interpretation:

altered bentonite? (possibly kaolinite) - initial (and possibly kaolinite)

Wed Jan 13 09:30:16 1999 Engineer: MCN

Scans: 32 / 64

APOD: Norton-Beer (medium)


Resolution: 4.00

Detector: TGS[0]

Gain: 2 / 2

Y Axis: % Transmittance

X Axis: Wavenumber



37132697

9804105 HEXPORT

Specification:

Supplier:

Preparation method: INSOLUBLES

IR Technique: BETWEEN NaCl PLATES

Thu Jan 14 09:58:28 1999

Engineer: mch

Scans: 32 / 64

APOD: Norton-Bear (medium)

Resolution: 4.00

Detector: TGS[0]

Gain: 474

Y Axis: % Transmittance


X Axis: Wavenumber

Engineer: mch

Comment:

Interpretation:

anhydrous salt (possibly manganite)



9804105 HEXPORT

Specification:

Supplier:

Preparation method: MEOH SOLUBLES

IR Technique: BETWEEN MAGL PLATES

Thu Jan 14 09:31:35 1999

Engineer: MCH

Scans: 32 / 64

APOD: Norton-Beer (medium)

Resolution: 4.00

Detector: TGS[0]

Gain: 2 / 2

Y Axis: % Transmittance


X Axis: Wavelength

Engineer: MCH

Comment:

Interpretation:

glycol and malonate (probably brata (1,3)) + water



9804105 HEXPORT, DEPOSIT

Specification:

Wed Jan 13 09:02:05 1999 Engineer: MCH

Supplier:

Scans: 32 / 64

APOD: Norton-Bear (medium)

Preparation method: AS RECEIVED

Resolution: 4.00

Detector: TGS(0)

IR Technique: BETWEEN IRACE PLATES

Gain: 2 / 2


Y Axis: % Transmittance X Axis: Wavenumber

Sample: *TMU*

Conc:

Interpretation:

Slight broad mband (possibly antifreeze) - metal salt (possibly oxalate)



9804105



Date: Tue Jun 06 12:00:29 1995

Power: 100

Resolution: 0.008

Tue Jun 06 12:02:10 1995 9804105: CONNECTOR SPEED CONTROL SWITCH


Chloroform/Mono-Cast of Metal Surface Infrared Connector

VC

Atmospheric Correction for Scale (None)
Integration Time: 4 sec. at 100% Transp. 20.000

3719 2701

980410.5



Date: Tue Jan 05 13:46:30 1999

Blank: 128

Resolution: 1.000

Tue Jan 05 13:46:44 1999 980410.5 CONNECTOR SPEED CONTROL SWITCH


Chlorophore Micro-Chip of Mixed Surface Infiltrate Connector

VC

Glycol Ether (Conductivity water blank)

Calibration of 0.000 & 1.000 mV

9804105



Date: Tue Jan 05 14:17:23 1999

Score: 120

Resolution: 8.000

Tue Jan 05 14:18:22 1999 9804105 CONNECTOR SPEED CONTROL SWITCH


Options: Mute-Crossed Metal Surface Guide Connector

VC

91 peak labeled: C=O in carbonyl group
Evaluations: 11, RMS: 0.0000, S/N: 13.3, %R: 0.00

3719 2703

9804105



Date: Tue Jan 05 14:32:28 1999

Scans: 128

Resolution: 8.000

Tue Jan 05 14:32:28 1999 9804105 CONNECTOR SPEED CONTROL SWITCH


Brown Plastic Housing Material As Received Micro-FIR

VC

Transmittance vs. Wavenumber (cm⁻¹)

3719204

98041105



Date: Tue Jan 05 15:07:46 1999

Tue Jan 05 15:08:22 1999 98041105 CONNECTORY SPEED CONTROL SWITCH

Source: 128

Blackened Plastic Housing Material As Received Micro-FTIR

Resolution: 6.000

VG

* Angles: Units in Degrees Radians Arcsin

ABG + LC

3713 2705

Dague, Bryan

From: Hopkins, AL
Sent: Wednesday, January 20, 1999 11:21 AM
To: Dague, Bryan; Baumern, Russell
Cc: McGuirk, Andrew; Andree, Amy
Subject: 99-032: TSL #150700: ANALYSIS OF MATERIAL REMOVED FROM 77P6 THERMAL EVENT

INTRODUCTION

OBJECTIVE:

Determine nature of deposit; in particular, determine if it is consistent with the results from Ford's analysis.

SUMMARY:

The results were very similar to those found by Ford. The main difference is that our EDX detector has a much better low energy cutoff than did the Ford detector. Their detector is unable to detect carbon and oxygen. Our analysis showed large amounts of carbon and oxygen on all three samples.

SAMPLES AND DESCRIPTION:

All of the samples were comprised of a mixture of different phases that had agglomerated together. A description of our findings is shown below:

BLACK FLAKE FROM TROUGH: We found the following elements which are listed in a very approximate decreasing order of preponderance: copper, oxygen, carbon, chrome, zinc, potassium, sulfur, and silver.

MATERIAL SCRAPPED FROM CUP ASSEMBLY: There were a very large number of glass fibers present which had the composition that is typically used in plastics for reinforcing purposes. In other words, this is almost certainly from thermal decomposition of the plastic base. The EDX detectable elements in these fibers are calcium, aluminum, silicon and oxygen. The rest of the material was very similar in composition to that reported for the above sample although we also detected some phosphorous in this sample.

GREEN MATERIAL ON CUP: This material was similar to that found on the first sample although the amount of chrome was much less.

The data was collected under the guidelines of TSL-S-71, Rev A which can be accessed at <http://www-mcd.mg.tj.com/tsl/>. SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis was used in the above described analysis. The data will be sent through the internal mail.

AL HOPKINS


MSG ID: AHOP

PHONE: 509/236-3040

ALTERNATE STACKING ORDER
(PIECES SEEM TO FIT EACH OTHER BETTER)



CONCAVE SIDE Down



3713 2708



3713 2709



2



3

3713 2710

CONCAVE SIDE DOWN



3713 2711

CONCAVE SIDE DOWN



1 2 3



3713 2712

CONCAVE SIDE UP



4 1



4 2



4 3

3713 2713



M

3713 2714

CONCAVE SIDE DOWN



2



3

3713 2715

CONCAVE SIDE UP




3



3

3713 2716

CONCAVE SIDE UP



3



3

3713 2717

CONCAVE SIDE DOWN



2



3

3713 2718

Direction of Deformation/Tension

CONCAVE SIDE UP



INITIAL SIDE OF CONTACT/
DEFORMATION


3713 2719

ALTERNATE STACKING ORDER (PIECES SEEM TO FIT BETTER)



Orientation
of
jasper.





3713 2721

REDDICK




3713 2722

3713 2723




3713 2724


REEDICK




3713 2725




3713 2726






3713 2727




3713 2728



3713 2728

REDDICK



3713 2730




3713 2731





3713 2732

REDDICK



3719 2733



3713 2734




3713 2735

3713 2736



3713 2737



3713 2738



3713 2739




FIG 2

SAMPLE
REMOVED



3713 2741

9900226
IN PROGRESS
FINAL REPORT
NOT ISSUED

RAW DATA
PRELIM. REPORTS

All divided areas must be filled in to process your request.

Administrative Use Only

Laboratory Number	Date
0900226	1-26-99 sc

Request for Central Laboratory Service

15000 Century Dr., Dearborn MI 48120-1267 Phone (313) 32-21674 FAX (313) 32-21614

Your Name [Read report to]:

G. Stevens

Secondary Contact:

N LaPrairie

Room No./Lab Drop-off Box:

MD 5006

Department/Activity:

Materials AYT

Building:

BLDG #3

Location Code:

S1013

Dept. #:

T113

Work Task # (For 3100 Loc. Only):

X00544

Total # of Samples:

Sample Handling:

After hours after test _____

Dispose after test _____

Dispose after 30 days _____

TOX/CALM

Source

Supplier Code

Perfected Name	Sample Identification [Continue below if needed]	Part Number [If any]	Material Specification [If any]	CPTC Code	Supplier
Spores, Cantharidin Cutting Surface	A, B, C, D, E, F, G	FZYY 947347	NA	-----	TEXAS LUMBER
				-----	-----
				-----	-----
				-----	-----

Instructions

Nature of Investigation/Specific Test Required (Check all that apply)

 Protection from pollution Perform Test as in Lab No. _____

Requester Info. Box (For requester use):

 Failure Analysis Photograph [Describe below] _____ Legal Use Specification _____ as a guide Specifications Compliance Other [Describe below] _____

Stop testing upon failure?

Does the support Call cost? [If "Yes", what is the expected expense?]

 No Yes

Do you need to know your CL contact and

name? _____ Yes

Additional Sample Submission/Testing Requirements

DISASSORTED SAMPLES IN REASONABLE PLACEMENT FOR
TESTINGREASONABLE EFFORTS TO PERFORM ALL DETERMINED TESTS ON POSSIBLE
SAMPLES THAT ARE SUBMITTED.

Notes

Please [Check off the apply]

Date you would like report: 7-11-99 Fax preliminary results Fax hand written Mail typed report Electronically transfer reportDate you want hard copy: 7-11-99 Fax typed report Mail hand written Fax preliminary results

For information about services or assistance in completing this form, please refer to the Central Laboratory WEB page.

[www.ges.foods.com/central/forms.html]

Laboratory supplier and date report to assigned within receipt of sample.

Samples will be disposed of after 30 days unless otherwise indicated above.

From Page No.

Switches

Page No. 1-26-49

Rec'd. Six switches A, B, C, D, 116(E), & F

PRO-SHOT	PRO-LINE	NO	LOM
ARMED	ARMED	DEAL	NO
		DEAL	DEAL

Six switches were disassembled for presence of
Telltac Inst. Personnel

A. Switch mounted in base

Holding switch contacts - contacts in front face of housing
Came from - after press contacts & housing made
base, contacts, terminals missing, terminal pin was held
by metal crimped in contacts by firm.

Face of cut switch - switch - face popular

Round cut switch - environment seal missing
Cut open cut

Face of housing, insulator cut switch

Material used in switch is contacts
insulator missing

Washer, contacts, one contact
one switch - contacts missing

B. Switch mounted in case

Holding switch contacts - contacts popular in front face
Came from - after press contacts & housing made

One switch from base switch

Statement contact possible, switch at rear of
housing in base

Material contact missing - X-ray film missing
terminal wires present

Statement of fact above is true - true

& that contacts - part number or name please
to be stated base switch

Contact not required to determine switch

To Page No.

Witnessed & Understood by me,

Date

Invented by

Date

Signed and initialed by

3713 2744

LE San Geron Concrete Services

On Page No.

2
3C. Surface involved in dust.

HEAVY DUSTING - NOT ENOUGH DUST IN PAVING AREA.

CROWN DUSTING CROWN IS PAVING AREA.

SOIL, OAK LEAVES, TRASHES, & TRASHED IN MULCH.

DUST ON THE GROUND - NOT A LOT OF DUST.

PARKING AREA - PAVING AREA MULCH.

CUT ORN. CUE.

DUST ON PAVING, IN LINE OF CUE, INVESTIGATE, CONCRETE,

& DUST CUE DUSTED & DUST.

KODAK SHOT IN PAVING - PAVING CLEANED & CLEARED.

SHOOTER A STRONG POSITION.

D. Surface involved in TOL-BOX - NO. 1008.

EXPLANATION OF SURFACE MOST LIKELY WHAT APPARELS

TO BE DUSTED DUE TO EXPOSED SOIL NOT WITH

LAYER MATERIALS TO BE DUSTED DUE TO EXPOSED SOIL.

BLACK POLYURETHANE APPLIED IN PAVING AREA OF HAMMERS

PARKING AREA PARK.

ENVIRONMENTAL DUST INHIBIT IN PAVING, & PAVEMENT

TO PAVING SURFACE - DOES NOT INHIBIT DUST DUST.

DUST DUSTED.

SURFACE CONCRETE CONTAINS DARK SPOTS WHICH - APPEARS
TO HAVE BEEN DUSTED DUSTED CONCRETE DUST. SURFACE IS FRICTION
ON CONCRETE SURFACE HAD DUST, BUT NOT DUSTED OR
DUSTED AS CONCRETE.

DUST DUSTED DUSTED IS PRESENT ON PAVING AREAS. (Area ~4x7).

TO DUST DUSTED DUSTED DUST. REST OF THIS IS CLEAN.

OAK LEAVES.

Hammers CONCRETE CONTAINS BLACK DUST. GROUT DUST - 30% METAL
KODAK SHOT SHOT TO POLYURETHANE PAVING CONCRETE.

IN LINE OF CUE, WASHING, CONCRETE, & DUST. EXHIBIT BLACK DUSTED.

THERE CONCRETE HAS CONCRETE DUST DUST.

To Page No.

Received & Understood by me,

Date

Invented by

Date

Reviewed by

From Page No.

No LHM, No Fins

U(E)

Exterior of switch box

Terminal cover box - Terminal box

Some box exterior contains black residue.

Terminal cover box

Switch box intact, insulation missing, insulation

does NOT appear to have been tampered

General quality, contacts, face on top clean & dry.

Grounded box

Insulated box top clean

Some black residue on contacts, bottom face

general interior metal good

However contact contains black residue

Kester solder used to prevent foil insulation

F

Switch terminal to box, no fins

Exterior & terminal quality intact with white residue to be seen fine.

Terminal break box intact

Bottom clean face

Switch box intact, insulation, terminals, the housing surface does not appear to have been tampered

Switch box contains dark green residue on contacts

Residue contact insulation is loose in bottom of

box

Field box and cover intact, clean, shows no soil

Clean outside

CFC clean box

Residue on faces - appears to have been tampered

Interior shows signs of tampering. No insulation

inside of box, insulation, contacts, and face, parts

black & dry

cut insulation & box to reduce insulation

General debris system like other terminal box

Power connection & contact good, but do NOT solder.

To Page No

Witnessed & Understood by me,

1-2-78

Date

Invented By

Date

Recorded by

3713 2746



Central Laboratory
16000 Century Drive
Dearborn, MI 48120-1267
FAX (313) 322-1614

Report 9800228

February 11, 1999

To: G. Stevens / S. LaRouche (313) 32-38888 (313) 39-07224 FAX

From: Gayle D. Gußen (313) 32-27322

Subject: Speed Control Cut Off Switch
Part Number: F2VY-9F924-A
Supplier: Texas Instruments

Received: Various components from 5 cut off switches were received on January 29, 1999.

Object: Determine presence of brake fluid in materials.

Conclusion/ Discussion: Switches A and C showed no evidence of brake fluid. Switches A and C appeared to mostly contain rust with traces of silicone. Sample C contained on both the material on switch side of cup and on the disc material something which appeared to be zinc carbonate. Switches D, F, and 11 showed glycol based material [most areas] as well as a metal salt, probably an oxalate [some areas]. A metal salt [not an oxalate but perhaps an intermediate material] was noted in some areas. The oxalate salt may be formed in a reaction from degraded polyester and metal components.

Areas on D, F, and 11 where no brake fluid was noted include only: D - base material seal 2 and brown/black on seal 3. Areas which did not exhibit the oxalate metal salt include: D - seal 1 material, base material of seal 2, converter, interior and switch side of the cup, contact, and base connector cavity; F - seal 2, seal 3, material on spacer, interior and switch side of cup, and base connector cavity; - Sample 11: None on any of the 3 seals. Areas on D, F, and 11 where a metal salt [not an oxalate-type] was detected: D - material on the contact; - Sample F - material on the contact; No areas on Sample 11.

Data and Analysis:

Molecular Characterization (FTIR, Qualitative, Microscopic)

Sample A

Spectra of the material in the fitting end of the hexport are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the black material in the cavity of the hexport are show a trace of silicone.

Spectra of the brown material in the cavity of the hexport are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material in the interior of the cup are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the grey material on the switch side of the cup are characteristic of essentially inorganic material.

Spectra of the brown material on the switch side of the cup are characteristic of essentially inorganic material with a trace of silicone.



Spectra of the material on the washer are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the brown material on the converter are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the black material on the converter are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the black material on the disc are characteristic of a trace of silicone.

Spectra of the brown material on the disc are characteristic of essentially inorganic material with a trace of silicone.

Sample C

Spectra of the material in the fitting end of the hexport are characteristic of inorganic material, probably containing yellow Iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the black material in the cavity of the hexport are show a trace of hydrocarbon (possibly mineral oil) and a trace of silicone.

Spectra of the brown material in the cavity of the hexport are characteristic of inorganic material, and a trace of hydrocarbon (possibly mineral oil).

Spectra of the material in the interior of the cup are characteristic of inorganic material, probably containing yellow Iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material on the switch side of the cup are characteristic of an inorganic carbonate [probably zinc carbonate] and possibly a trace of a metal soap.

Spectra of the material on the washer are show evidence of inorganic material.

Spectra of the material on the converter are characteristic of inorganic material probably containing yellow Iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material on the disc are characteristic of an inorganic carbonate [probably zinc carbonate] and other..

Sample D

Spectra of the material in the fitting end of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on Seal 1 are characteristic of a glycol based material, probably brake fluid.

Spectra of the material on Seal 2 are characteristic of metal salt (possibly an oxalate) and glycol based material (probably brake fluid) and polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).

Spectra of the base material of Seal 2 are characteristic polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).

Spectra of the liquid material on Seal 3 are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).

Spectra of the brown/black material on Seal 3 are characteristic of metal salt (possibly an oxalate) and polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).



Spectra of the material on the washer are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on the converter are characteristic of essentially glycol based material (probably brake fluid).

Spectra of the material on the spacer are characteristic of metal salt (probably an oxalate) and glycol based material (probably brake fluid).

Spectra of the material on the disc are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).

Sample D

Spectra of the material in the interior of the cup are characteristic of glycol based material (probably brake fluid).

Spectra of the material on the switch side of the cup are characteristic of glycol based material (probably brake fluid) and other hydrocarbon.

Spectra of the material on the contact are characteristic of metal salt and glycol based material (probably brake fluid).

Spectra of the material on the base, connector cavity are characteristic of essentially glycol based material (probably brake fluid).

Sample E

Spectra of the material in the fitting end of the hexport are characteristic of metal salt (probably an oxalate) and glycol based material (probably brake fluid).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on Seal 1 are characteristic of metal salt (possibly an oxalate) and glycol based material (probably brake fluid).

Spectra of the material on Seal 2 are characteristic essentially glycol based material (probably brake fluid).

Spectra of the material on Seal 3 are characteristic of glycol based material and other material.

Spectra of the material on the washer are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on the converter are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on the spacer are essentially characteristic of glycol based material (probably brake fluid).

Spectra of the material on the disc are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).

Spectra of the material in the interior of the cup are essentially characteristic of glycol based material (probably brake fluid).

Spectra of the material on the switch side of the cup are characteristic of glycol based material (probably brake fluid) and other material.

Spectra of the material on the contact are characteristic of glycol based material (possibly brake fluid) and other material, possibly a metal salt.



Spectra of the material on the base, connector cavity are characteristic of essentially glycol based material (probably brake fluid).

Sample 11

Spectra of the material in the fitting end of the hexport are characteristic of metal salt (probably an oxalate) and glycol based material (probably brake fluid).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on Seal 1 are characteristic essentially glycol based material (probably brake fluid).

Spectra of the material on Seal 2 are characteristic glycol based material (probably brake fluid) and silicone.

Spectra of the material on Seal 3 are characteristic of glycol based material and other material, possibly silicone.

Contributor: M. Haga

By:

Gayle Guillen

Gayle B. Guillen (GGUILLEN)
Product Materials Engineer



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1267
FAX (313) 322-1614

Report 9800226

February 10, 1999

To: G. Stevens / S. LaRouche / G. Gullen (313) 32-38686 (313) 39-07224 FAX

From: M. C. Haga (313) 33-78388

Subject: Speed Control Cut Off Switch
Part Number: F2VY-9F924-A
Supplier: Texas Instruments

Received: Various components from 5 cut off switches were received on January 29, 1999.

Object: Determine presence of brake fluid in materials.

Discussion: Switches A and C showed no evidence of fluid. Switches D, F and 11 showed glycol based material as well as a metal salt, probably an oxalate. The salt may be formed in a reaction from degraded polyester and metal components.

Data and Analysis:

Molecular Characterization
(FTIR, Qualitative, Microscopic)

Sample A

Spectra of the material in the fitting end of the hexport are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the black material in the cavity of the hexport are show a trace of silicone.

Spectra of the brown material in the cavity of the hexport are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material in the interior of the cup are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the grey material on the switch side of the cup are characteristic of essentially inorganic material.

Spectra of the brown material on the switch side of the cup are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the material on the washer are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the brown material on the converter are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the black material on the converter are characteristic of essentially inorganic material with a trace of silicone.

Spectra of the black material on the disc are characteristic of a trace of silicone.

Spectra of the brown material on the disc are characteristic of essentially inorganic material with a trace of silicone.



Molecular Characterization
(FTIR, Qualitative, Microscopic)

Sample C

Spectra of the material in the fitting end of the hexport are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the black material in the cavity of the hexport are show a trace of hydrocarbon (possibly mineral oil) and a trace of silicone.

Spectra of the brown material in the cavity of the hexport are characteristic of inorganic material, and a trace of hydrocarbon (possibly mineral oil).

Spectra of the material in the interior of the cup are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material on the switch side of the cup are characteristic of metal-soap-and-other material.

Spectra of the material on the washer are show evidence of inorganic material.

Spectra of the material on the converter are characteristic of inorganic material, probably containing yellow iron oxide ($Fe_2O_3 \cdot H_2O$), and a trace of silicone.

Spectra of the material on the disc are characteristic of metal-soap-and-inorganic material.

Sample D

Spectra of the material in the fitting end of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on Seal 1 are characteristic of a glycol based material, probably brake fluid.

Spectra of the material on Seal 2 are characteristic of metal salt (possibly an oxalate) and glycol based material (probably brake fluid) and polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).

Spectra of the base material of Seal 2 are characteristic polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).

Spectra of the liquid material on Seal 3 are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).

Spectra of the brown/black material on Seal 3 are characteristic of metal salt (possibly an oxalate) and polytetrafluoroethylene (PTFE) and/or Fluorinated Ethylene Propylene (FEP).

Spectra of the material on the washer are, characteristic of glycol based material (probably brake fluid) and metal salt (possibly an oxalate).

Spectra of the material on the converter are characteristic of essentially glycol based material (probably brake fluid).

Spectra of the material on the spacer are characteristic of metal salt (probably an oxalate) and glycol based material (probably brake fluid).

Spectra of the material on the disc are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).



Molecular Characterization
(FTIR, Qualitative, Microscopic)

Sample D

Spectra of the material in the interior of the cup are characteristic of glycol based material (probably brake fluid).

Spectra of the material on the switch side of the cup are characteristic of glycol based material (probably brake fluid) and other hydrocarbon.

Spectra of the material on the contact are characteristic of metal salt and glycol based material (probably brake fluid).

Spectra of the material on the base, connector cavity are characteristic of essentially glycol based material (probably brake fluid).

Sample E

Spectra of the material in the fitting end of the hexport are characteristic of metal salt (possibly an oxalate) and glycol based material (probably brake fluid).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (possibly an oxalate).

Spectra of the material on Seal 1 are characteristic of metal salt (possibly an oxalate) and glycol based material (probably brake fluid).

Spectra of the material on Seal 2 are characteristic essentially glycol based material (probably brake fluid).

Spectra of the material on Seal 3 are characteristic of glycol based material and other material.

Spectra of the material on the washer are, characteristic of glycol based material (probably brake fluid) and metal salt (possibly an oxalate).

Spectra of the material on the converter are characteristic of glycol based material (probably brake fluid) and metal salt (possibly an oxalate).

Spectra of the material on the spacer are essentially characteristic of glycol based material (probably brake fluid).

Spectra of the material on the disc are characteristic of metal salt (possibly an oxalate) and a glycol based material (probably brake fluid).

Spectra of the material in the interior of the cup are essentially characteristic of glycol based material (probably brake fluid).

Spectra of the material on the switch side of the cup are characteristic of glycol based material (probably brake fluid) and other material.

Spectra of the material on the contact are characteristic of glycol based material (possibly brake fluid) and other material, possibly a metal salt.

Spectra of the material on the base, connector cavity are characteristic of essentially glycol based material (probably brake fluid).



Molecular Characterization
(FTIR, Qualitative, Microscopic)

Sample 11

Spectra of the material in the fitting end of the hexport are characteristic of metal salt (probably an oxalate) and glycol based material (probably brake fluid).

Spectra of the material in the cavity of the hexport are characteristic of glycol based material (probably brake fluid) and metal salt (probably an oxalate).

Spectra of the material on Seal 1 are characteristic essentially glycol based material (probably brake fluid).


Spectra of the material on Seal 2 are characteristic glycol based material (probably brake fluid) and silicone.

Spectra of the material on Seal 3 are characteristic of glycol based material and other material, possibly silicone.

Concur: _____

G. Guillen
Organic Section

By:


Mary C. Haga (MHAGA)
Laboratory Development Analyst

From Page No. _____

A

Hex nut

Fitting End: irregularly cutting yellow oxide
(Fig. B) material atCavity: black - has silicous
brown - see B.H., redCaps

Interior - see file.

Solder side edges - possibly irregular
brown - irregularly cutting silicousWasher: ~~black~~ - orange & trace silicousConcentric rings of washer
blocksDisc with trace silicous
brown see washerB

Hex nut

Fitting End : see "A"

Cavity: basic trace of red iron - possibly grey & brown
brown - orange - trace by, dark blue (possibly)

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

Project No. 222226
Book No.

TITLE Seal Cont. 5.6.6

From Page No.

F-1A

2

Cup ~~metal~~ ~~aluminum~~
Tin ~~tin~~ ~~lead~~ ~~nickel~~ fitting end

Spherical metal soap holder

Wear evidence of abrasives

Crater see Report fitting end

Disc metal support bearings

1

B

Hexnut

Fitting End spherical part (possibly Break Fluid)
almost ~~not~~ ~~variable~~ ~~variable~~ in ex(alt)

cavity spherical material (possibly Break Fluid)
metal part (possibly an exalt)

See 17 gbm TBE

Seal 2 m³⁶⁰ 50m by SP + PTFE & FC6

Seal 2 (Seal min.) PTFE & FC6

Seal 2 (Seal max.) PTFE & FC6

bowl black regular M.S (rod) + PTFE & FC6

To Page No.

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

3713 2756

From Page No. _____

PICWasher gbrn(pBF) + m.s.(p.O.)cover : essentially gbrn(pBF)spacer m.s.(p.O.) + gbrnbase m.s.(p.O.) + gbrnInt'l gbrn(pBF)switch side gbrn(pBF) ~ other by Assemblycontact m.s. gbrn(pBF)base : essentially gbrn(pBF)P

Hex part

Fitting End m.s.(p.O.) + gbrn(pBF)cavity gbrn(pBF) + m.s.(p.O.)

To Page No. _____

Witnessed & Understood by me,

Date _____

Invented by _____

Date _____

Recorded by _____

From Page No. _____

FTC

Seq. 1 : m.s.(p.o) + gbm (pBF)

Seq. 2 : essentially Sbm (pBF)

Seq. 3 : gbm + other

Wester : Sbm (pBF) / 2 m.s.(p.o)

Converter see work

Speaker : essentially Sbm (pBF)

Disc : m.s.(p.o) + gbm (pBF)

Cup : Teflon -> gbm (pBF)

switch side : Sbm + other

Contact : Sbm (possibly BP) + other
possibly amorphous

Base : essential gbm (pBF)

To Page No. _____

Witnessed & Understood by me.

Date

Invented by

Date

Recorded by

From Page No.

F75A11textbookFitting End = m.s.(p-w) & gbm (BC)carrying gbm (p, B2) + m.s (p-w)sec 1 1 egg gbm (B2)sec 2 gbm + s.licorsec 3 gbm 1, possib's s.licorM.C. Hagan2/10/99

To Page No.

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 006900225
Date of Request: 01/26/1999 11:18:53 AM
Print Date: 01/26/1999 02:13:51 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-6888 PROFS ID: GSTEVEN1 Fax: (313) 390-7224
Phone: (313) 594-2888 PROFS ID: NLAPPOINT Fax: (313) 337-8258

Send Report to:
Bill to:

MD 5008/2G06S, AVT MATERIALS, BLDG. #6
Addrg.Location: 6100
Dept: T113
Work Task: XQG04

Sample Information:

Total Number of Containers: 6
Source: Not specified

Sample Handling: Dispose after 30 days
Supplier Code: Not specified

Part/Material Name	Gly	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	8	A,B,C,D,T1(E), AND F	F2VY-SP924-A	NA	00.00.00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requestor Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

DISASSEMBLE SWITCHES IN PRESENCE OF PERSONNEL FROM TEXAS INSTRUMENTS. PERFORM ANALYSES TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE.

Reporting Directions:

Date customer would like report: 02/11/1999

Date customer must have report: 02/11/1999

Report Format(s):

Lead-In Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouche, Steve

Phone: 84-54876

View your test status at: <HTTP://bd4web.pd7.ford.com/kalif>

Program Name: KALISLab Engr Module
Program Version: Version 2.0.6

PLEEOSE DETERMINE PRESENCE OF
 BRAKE FLUOD IN LOCATONS SPECIFISES) UN
 ATTACHED SHEET. ALSO IDENTIFY ANY OTHER
 MATERIALS, ESPECIALLT IN DARKENED AREAS OF
 INTERIOR COMPONENTS. PLEASE RETURN PATS
 AFTER YOU FINISH JAMPSUNS SO ICAN ROUTE THEN
 THANKS, FOR OTHER ANALYSES

S. LaRouche

3713 2780

990226 Test Locations

Sample	Component	Location
A,C	Hexport	Fitting End Cavity
	Cup	Interior Switch Side
	Washer, Converter, Disc	Anywhere
D,F	Hexport	Fitting End Cavity
	Seal	Dark Areas
	Washer, Converter, Spacer and Disc	Dark Areas
	Cup	Interior Switch Side
	Contact	Anywhere ¹
	Base	Connector Cavity
11	Hexport	Fitting End Cavity
	Seal	Dark Areas

¹ Sample already collected prior to further disassembly. Placed in Gelman dish or in vial.

990226 Test Locations

Sample	Component	Location
A, C	Hexport	Fitting End ✓ Cavity
	Cup	Interior Switch Side
	Washer, Converter, Disc	Anywhere
D,F	Hexport	Fitting End ✓ Cavity
	Seal	Dark Areas
	Washer/Converter/Spacer and Disc	Dark Areas
	Cup	Interior Switch Side
	Contact	Anywhere
	Base	Connector Cavity
11	Hexport	Fitting End ✓ Cavity
	Seal	Dark Areas

11 - is in service - no problem
 fluid in exterior (of hexport) probably
 came from interior during handling -
 situated in ID of black deposit

It's quick method to determine presence
 of black fluid &/or debris - avoid for method for
 Hexport cavity - just look behind elastomeric seal
 fitting end - just might be large of debris.

Thank
Steve

* Sample already collected prior to further disassembly. Placed in Gelman dish or in vial

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009800376
Date of Request: 01/28/1999 11:13:53 AM
Print Date: 01/28/1999 02:13:51 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 323-8688 PROFS ID: GSTEVEN1 Fax: (313) 390-7224
Phone: (313) 594-2688 PROFS ID: NLAPPOINT Fax: (313) 337-6256

Send Report to: MD 500B/2G085, AVT MATERIALS, BLDG. #5
Bill to: Addg. Location: 5100
Dept: T113
Work Task: XQG04

Sample Information:

Total Number of Containers: 8
Source: Not specified

Sample Handling: Dispose after 30 days
Supplier Code: Not specified

Part/Material Name	City	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	8	A,B,C,D,11(2), AND F	FZVT-#PB24A	NA	00 00 00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requester Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

DISASSEMBLE SWITCHES IN PRESENCE OF PERSONNEL FROM TEXAS INSTRUMENTS. PERFORM ANALYSES TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE

Reporting Directions:

Date customer would like report: 02/11/1999

Date customer must have report: 02/11/1999

Report Format(s):

Log-in Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouche, Steve

Phone: 84-54875

Program Name: KALISLab Engg Module
Program Version: Version 2.03

View your test status at: [HTTP://ed4web.pd7.ford.com/kalis](http://ed4web.pd7.ford.com/kalis)

PLEASE DETERMINE PRESENCE OF
BRAKE FLUID IN LOCATIONS SPECIFIED ON
ATTACHED SHEET. ALSO IDENTIFY ANY OTHER
MATERIALS, ESPECIALLY IN DARKENED AREAS OF
INTERIOR COMPONENTS. PLEASE RETURN PARTS
AFTER YOU FINISH SAMPLING SO I CAN ROUTE THEM.
THANKS, FOR OTHER ANALYSES

S. LaRouche

3713 2763

TITLE _____

From Page No.

49010226 They started 1/2 in. back to back
5 pieces total sample

in service with no seal - not
in use. This was their press
in other ways - time contacts -
certain black deposit however

990226 Test Locations

Sample	Component	Location
A.C	Hexport	Fitting End
		Cavity
	Cup	Interior
		Switch Side
D.F	Washer, Converter, Disc	Anywhere
	Hexport	Fitting End
		Cavity
	Seal	Dark Areas
	Washer, Converter, Spacer and Disc	Dark Areas
	Cup	Interior
		Switch Side
11	Contact	Anywhere ¹
	Base	Connector Cavity
	Hexport	Fitting End
		Cavity
	Seal	Dark Areas

¹ Sample already collected prior to further disassembly. Placed in Gilmont class C n.v.s.

To Page No.

Witnessed & Understood by me,

John J. ...

Date

2/1/09

Invented by

Date

3713 2764

9900226 HEXPORT A, FITTING END, BROWN MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Interpretation:

Engineer: *MH*
Code: 201.0

Thu Feb 04 10:27:45 1999

Engineer: MCH

Scans: 128 / 268

APOD: Norton-Bear (medium)


Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

V Axis: % Transmittance

X Axis: Wavenumber



9900226 HEXPORT A, CAVITY, BLACK MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Interpretation:

Thu Feb 04 10:14:00 1989

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Beer (medium)


Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



9900226 HEXPORT A, CAVITY, BROWN MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: MICROSCOPE

Element:

Compound:

Interpretation:

Thu Feb 04 10:08:48 1999

Engineer: MCH

Scene: 128 / 256

APOD: Norton-Bear (medium)



Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



9743 2767

9900226 "A", CUP, INTERIOR

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Engineer: jmj

Interpretation:

Chemist:

monomeric possibly carbonized yellow iron oxide + trace organic

Thu Feb 04 11:00:10 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)


Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



9900226

9900226 "A", CUP, SWITCH SIDE, GREY MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: MICROSCOPE

Engineer: MCH

Interpretation: *synthetic
material*

Comment: _____

Thu Feb 04 11:08:25 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Beer (medium)


Resolution: 4.00

Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



3713 2783

9900226 "A", CUP, SWITCH SIDE, BROWN MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Interpretation:

Engineer: *[Signature]*

Owner: _____

Thu Feb 04 11:12:01 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)



Resolution: 4.00

Detector: MCT[16]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber



0719270

9900226 "A", WASHER

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: MICROSCOPE

Interpretation:

Inorganic, trace silicon

Thu Feb 04 11:25:26 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)

Resolution: 4.00



Detector: MCT[15]

Gain: 4R / 4R

Y Axis: % Transmittance

X Axis: Wavenumber

9900226



9900226 "A" CONVERTER, BROWN MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Engineer:

1997

Conc:

Interpretation:

marginally functional

Fri Feb 05 13:26:12 1999

Engineer: mch

Scans: 128 / 256

APOD: Norton-Bear (medium)



Resolution: 4.00

Detector: MCT[15]

Gain: 4 / 4

Y Axis: % Transmittance

X Axis: Wavenumber



9900226 "A" CONVERTER, BLACK MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Interpretation:

Sample: *mp*

Center:

track

silica

Fri Feb 05 13:30:50 1999

Engineer: mch

Scans: 128 / 256

APOD: Norton-Bear (medium)



Resolution: 4.00

Detector: MCT[15]

Gain: 4 / 4

Y Axis: % Transmittance

X Axis: Wavenumber



3719 2773

9900226 "A" CONVERTER,DISC, BLACK MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: microscope

Fri Feb 05 13:37:54 1999

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Bear (medium)

Resolution: 4.00

Detector: MCT[15]

Gain: 4 / 4

Y Axis: % Transmittance

X Axis: Wavenumber


Engineer:

MCH

Comment:

Interpretation:

true of silicones



9900226

9900226 "A" CONVERTER,DISC, BROWN MATERIAL

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: MICROSCOPE

Interpretation:

Fri Feb 05 13:34:33 1998

Engineer: MCH

Scans: 128 / 256

APOD: Norton-Beer (medium)

Resolution: 4.00

Detector: MCT[15]

Gain: 4 / 4


Y Axis: % Transmittance

X Axis: Wavenumber

Figure:

101

Conc:



3713 2776

9900226 "C" HEXPORT, FITTING END

Specification:

Supplier:

Preparation method: AS RECEIVED

IR Technique: MICROSCOPE

Engineer: MCH

Conc:

Interpretation:

Mon Feb 08 14:31:03 1999

Engineer: MCH

Scan#: 128 / 256

APOD: Norton-Bear (medium)

Resolution: 4.00

Detector: MCT[15]

Gain: 2R / 2R

Y Axis: % Transmittance

X Axis: Wavenumber

