

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 25 OF 61

PART 2 OF 5

View previous calendar View next calendar PostScript Compact PostScript

Calendar for SREIMERS

SREIMERS

February 1999

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>1</p> <p>1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-04T</p> <p>3:15PM - 5:15PM C3P Commodity Reviews w/C Wilson & ERSE Mgrs. Bldg 5, Conf Rm 1B010</p>	<p>2</p> <p>07:00AM - 5:00PM U152 RAS Design Review for IPP FIDC 245</p>	<p>3</p> <p>07:00AM - 5:00PM U152 RAS FMEA FTDC rm 169</p>	<p>4</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>NOON - 2:00PM U222/228 Air Suspension System FMEA development & review. Bldg.#5, 3A-039</p> <p>2:00PM - 3:00PM Brake Pressure Switch building 5 conf rm 3A039</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bld 5, CR# 2C062</p>	<p>5</p> <p>08:00AM - 10:00AM U222/228 Air Suspension System FMEA. Bldg.#5, 3A-039</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>2:00PM - 3:00PM Brake Pressure Switch building 5 3A059</p>	<p>6</p>	
<p>7</p>	<p>8</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>10:00AM - 11:00AM Pantech Chassis PMT LVC, CR 24G14A</p> <p>11:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-04T</p> <p>2:30PM - 3:30PM Air Suspension On/Off Switch Elimination BLI Team Meeting BL53A019</p>	<p>9</p> <p>08:15AM - 09:00AM Don Robertson, Speed Control @ my desk</p> <p>09:00AM - 10:00AM FN145 Steering Systems. BL53A079</p> <p>10:00AM - 11:00AM Meet Aziz Rehman from TI Fred's Desk</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PC52</p>	<p>10</p> <p>11:00AM - NOON CVSA Status on U231 PDC</p> <p>2:00PM - 3:00PM Brake Pressure Switch bldg 5 3A017</p> <p>2:30PM - 3:30PM 4WAS build 3a019 floors</p>	<p>11</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>11:00AM - NOON Section Lunch Cafe HAWAII</p> <p>4:00PM - 5:00PM Technical Review Meeting Building #1, Executive Conf. Rm. 13E112</p>	<p>12</p> <p>07:00AM - 5:00PM pers</p> <p>09:00AM - 10:00AM U152 Freezer Track Testing Overview PDC2DM10</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>1:00PM - 2:30PM V-184 Air Suspension S/W Design specification BL53A019</p>	<p>13</p> <p>08:00AM - 6:00PM Reviewed Town car, Grand Marquis, Crown Vic and Continental Owner manuals for MY2000 and submitted changes.</p>
<p>14</p>	<p>15</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p>	<p>16</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PC52</p> <p>2:00PM - 4:00PM Dash Switch, Alternative</p>	<p>17</p> <p>11:30AM - NOON 2c062 D-Good staff mtg</p> <p>1:00PM - 2:00PM Chassis E/E SDR BL53A019</p>	<p>18</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>NOON - 2:30PM</p>	<p>19</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>1:00PM - 2:30PM V-184 (Air Suspension) S/W Design</p>	<p>20</p>

3713 6433

	<p>10:00AM - 11:00AM Paulina Chassis PMT LVC, CR 24G14A</p> <p>1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT Bldg #5 3A-047</p> <p>2:30PM - 4:00PM U152 FMEA</p>	<p>3a017, bldg 5</p>	<p>2:00PM - 4:00PM Brake Pressure Switch building 5 3A039</p> <p>3:00PM - 5:00PM videocon frw process 3a019</p>	<p>u222 strategy 3a019</p> <p>1:00PM - 1:30PM Town Car Investigation #5, 2A019</p> <p>3:00PM - 5:00PM C3P (S) Methods Meeting Bld 5, CR# 2C062</p>	<p>Specification development BL53A019</p> <p>4:00PM - 5:00PM 1992-93 Linc. Town Car Underhood Fires (NHTSA Inq. PE98-055) Bldg. #1 ECR 13F112</p>	
21	<p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>11:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT Bldg #5 3A-047</p> <p>2:30PM - 3:30PM Air Suspension On/Off Switch Ebramson HJL Team Meeting TW 53A019</p>	<p>09:00AM - 11:00AM DOW Rep Meeting Hldg 5 3A017</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2FC52</p>	<p>12:30PM - 3:00PM U222/U228 Air Suspension Strategy BR5, 3A017</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>3:00PM - 4:00PM Deepak and Fred</p> <p>3:00PM - 5:00PM C3P (S) Methods Meeting Hld 5, CR# 2C062</p>	<p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>1:00PM - 2:30PM V-184 Air Suspension SW Design specification BL53A019</p>	27
28						

[View previous calendar](#) [View next calendar](#) [PostScript](#) [Compact PostScript](#)

WEB Calendar Interface to PROFS
Copyright © 1996, 1997, 1998 Ford Motor Company. All Rights Reserved.

3713 6434

View previous calendar
 View next calendar
 PostScript
 Compact PostScript

Calendar for SREIMERS

SREIMERS

March 1999

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
	1 06:45AM - 5:00PM MPG Joe Gwisdalla 09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019 10:00AM - 11:00AM Panther Chassis PMT LVC, CR 24G14A 1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg #5 3A-047 3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 ECR 13R112	2 08:00AM - 5:00PM nrg town car testing Joe Gwisdalla 2:00PM - 3:30PM U152/U231 Air PDC2FC52	3 10:30AM - 11:30AM Profit Sharing Celebration BLS2C062 12:30PM - 3:00PM U222/U228 Air Suspension Strategy BM5, 3A017 1:00PM - 2:00PM Chassis E/E SDS BL53A019 2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039	4 09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01 12:30PM - 2:00PM Air Suspension Sub-System FMEA My Desk 3:00PM - 5:00PM C3P EE Methods Meeting Bldg 5, CRa 2C062	5 10:00AM - 11:00AM Section Mtg BL53A019 NOON - 2:00PM U222 System PMFA review. Bldg. #5, 3A-039 1:00PM - 2:30PM V-184 (Air Suspension) S/W Design Specification development BL53A019		
	7 09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019 09:15AM - 4:45PM U152/U231 Chassis Design Review PDC GH-A32 1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-047 2:30PM - 3:30PM Air Suspension On/Off Switch Elimination BL1 Team Meeting BL53A019 3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 ECR 13R112	8 09:00AM - 10:45AM Brake Pressure Switch Connector Bldg 5 3A017 1:30PM - 3:00PM Air Snap Voltage Drop Simulation -Rescheduled Tuyen's desk 2:00PM - 3:30PM U152/U231 Air PDC2FC52	9 09:00AM - 10:45AM Brake Pressure Switch Connector Bldg 5 3A017 1:30PM - 3:00PM Air Snap Voltage Drop Simulation -Rescheduled Tuyen's desk 2:00PM - 3:30PM U152/U231 Air PDC2FC52	10 10:00AM - 11:00AM SIT and brake switch overheating SRL-1513 (Ed Siskafus office) 12:30PM - 3:00PM U222/U228 Air Suspension Strategy BM5, 3A017 2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039	11 09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01 2:00PM - 4:00PM SIT and brake switch overheating SRL-1529 (near Ed Siskafus office) 3:00PM - 4:00PM RA5 Module Relocation (2002 FN145) 11B045	12 09:00AM - 10:00AM Brake Pressure Switch Connector bldg 5 3a017 (tentative) 10:00AM - 11:00AM 3a017 H khaki 2002 EN114 RAS mtg	13

3713 6435

<p>14</p>	<p>15</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BLS3A019</p> <p>10:00AM - 11:00AM Panther Chassis PMT LVC, CR 24G14A</p> <p>3:30PM - 4:00PM 1992 93 Town Car Underhood Fires (NETSA Inquiry PE98-055) Bldg. #1 ECR 13E112</p>	<p>16</p> <p>12:30PM - 2:30PM 2001 / 2002 Panther Design Aid Meeting LVC</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2FC52</p>	<p>17</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>1:00PM - 2:00PM Chassis E/E SDS BLS3A019</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>18</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>12:30PM - 1:30PM Ground Fault Circuit Interruptor bldg 5 3A019 (west end of bldg) or FLL</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bld 5, CR# 2C062</p>	<p>19</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BLS3A019</p>	<p>20</p>
<p>21</p>	<p>22</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BLS3A019</p> <p>1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-047</p> <p>2:30PM - 3:30PM Air Suspension On/Off Switch Elimination R.I.J Team Meeting BLS3A019</p>	<p>23</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2FC52</p>	<p>24</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>11:15AM - 12:45PM Group Lunch Mongolian Barbecue</p> <p>1:00PM - 1:30PM BL1 - Replace gold plated wheel speed sensor terminals Bldg #5, 3A019</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>25</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>09:30AM - 11:00AM Program review for UN93 Height Sensor Bldg 5, CR 3A017</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bld 5, CR# 2A055</p>	<p>26</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>08:40AM - 5:00PM Spirit of Ford FITMC, Room 262 (South)</p>	<p>27</p>
<p>28</p>	<p>29</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BLS3A019</p> <p>10:00AM - 11:00AM Panther Chassis PMT LVC, CR 24G14A</p> <p>1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-047</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NETSA Inquiry PE98-055) Bldg. #1 ECR 13E112</p>	<p>30</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM U152 Rear Air Suspension Voltage Drop Analysis PDC Conference Table @ 1DF60</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2FC52</p>	<p>31</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>			

View previous calendar View next calendar PostScript Compact PostScript

Calendar for SREIMERS

<http://hub.ford.com:8082/calendar.cgi?user=SREIMERS&from=3%2F01%2F1999&to=3%2F01%2F1999&month=month>

WEB Calendar Interface to PROFS
Copyright © 1996, 1997, 1998 Ford Motor Company. All Rights Reserved.

3719 6437

View previous calendar View next calendar PostScript Compact PostScript

Calendar for SREIMERS

SREIMERS

April 1999

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				<p>1</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>08:30AM - 10:00AM Tukios, Thermal Brake</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bld 5, CR# 2C062</p>	<p>2</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BLS3A019</p> <p>1:00PM - 2:30PM V-184 (Air Suspension) S/W Design Specification development BLS3A019</p>	<p>3</p>
<p>4</p>	<p>5</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Mallon BLS3A019</p> <p>10:00AM - 11:00AM Further Chassis PMT 1.VC, CR 24G14A</p> <p>1:00PM - 2:00PM U222/222# Chassis E/E Subsystem PAT</p> <p>Bldg #5 3A-047</p> <p>2:30PM - 3:30PM Air Suspension On/OE Switch Elimination BLI Team Meeting BLS3A019</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry #E98-055) Bldg. #1 CR 13E112</p>	<p>6</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM U152/U231 Air PDC 2FC52</p>	<p>7</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>07:30AM - 08:30AM Speed Control Deact. switch CCRG Update T. Donovan's Office</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>8</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bld 5, CR# 2C062</p>	<p>9</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BLS3A019</p> <p>1:00PM - 2:30PM V-184 Air Suspension S/W Design Specification BLS3A019</p>	<p>10</p>
<p>11</p>	<p>12</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p>	<p>13</p> <p>07:00AM - 6:00PM Brake Pressure Switch</p>	<p>14</p> <p>07:00AM - 6:00PM Brake Pressure Switch</p>	<p>15</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p>	<p>16</p> <p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p>	<p>17</p>

3713 6438

	<p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry FE98-055) Bldg. #1 ECR 13E112</p>	<p>Investigation 2:00PM - 3:30PM U152/U231 Air PDC2PC52</p>	<p>Investigation 10:00AM - NOON Speed Control De-Activation Switch T. Donovan's Office #5 Rm. 1A043</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>10:00AM - NOON Speed Control De-Activation Switch T. Donovan's Office #5 Rm 1A043</p>	<p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>10:00AM - NOON Speed Control De-Activation Switch Concern T. Donovan's Office #5 Rm. 1A043</p> <p>2:20PM - 3:40PM MY2002 EN114/PN145 Air suspension VISTHON 22A01</p>	
18	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>10:00AM - 11:00AM Speed Control De-Activation Switch Concern T. Donovan's Office #5 Rm. 1A043</p> <p>2:30PM - 3:30PM Air Suspension On/Off Switch Elimination BLI Team Meeting BL53A019</p> <p>3:30PM - 4:30PM Technical Review Meeting Bldg. #1, Executive Conference Room 13E112</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PC52</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>11:15AM - 12:15PM BTR Compressor thermo TRIP BLDG#5</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bldg 5, CRW 2C062</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>07:30AM - NOON All Hands Meeting World Headquarter Auditorium</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>10:00AM - NOON Rear Air Suspension Voltage Drop PDC, ID-J58 or Conf desk ID-P60</p> <p>1:00PM - 2:30PM V-184 Air Suspension S/W Design specification BL53A019</p>	24
25	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>1:00PM - 2:00PM U222/U228 Chassis E/E Subsystem PAT. Bldg #5 3A-047</p> <p>1:00PM - 2:00PM Proposed Revisions to CE-SDS Details 8772 8785 BL53A039</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry FE98-055) Bldg. #1 ECR 13E112</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PC52</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>1:00PM - 2:00PM Chassis R/P SDS BL53A019</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>3:00PM - 5:00PM C3P EE Methods Meeting Bldg 5, CRW 2C062</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>08:30AM - 09:30AM 92-93 Underhood TownCar Deact Switch Bldg#5</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p>	30

[View previous calendar](#)
[View next calendar](#)
[PostScript](#)
[Compact PostScript](#)

Calendar for SREIMERS

<http://hub.ford.com:8082/calendar.cgi?user=SREIMERS&from=4%2F01%2F1999&to=4%2F01%2F1999&month=month>

Copyright © 1996, 1997, 1998 Ford Motor Company. All Rights Reserved.

3713 6440

[View previous calendar](#) [View next calendar](#) [PostScript](#) [Compact PostScript](#)

Calendar for SREIMERS

SREIMERS

May 1999

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1						1
2	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>1:00PM - 2:00PM U122/U228 Chassis E/E Subsystem PAT. Bldg.#5 3A-047</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 BCR 13E112</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>12:30PM - 2:30PM 2001 / 2002 Panther Design Aid Meeting LVC</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PCS2</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/FN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>11:00AM - NOON Notice of a meeting La Riviera (Tullio's)</p> <p>3:00PM - 5:00PM CSP EL Methods Meeting Bld 5, CR# 20062</p> <p>3:30PM - 4:30PM Technical Review Meeting Bldg. #1, Executive Conference Room 13E112</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p> <p>3:00PM - 4:30PM Contingency Action Team Meeting - Brake Pressure Switch DSCI-A</p>	8
9	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019</p> <p>3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 BCR 13E112</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM U152/U231 Air PDC2PCS2</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>1:00PM - 2:00PM Chassis E/E SDS BL53A019</p> <p>2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:30AM - 11:00AM FN145/FN114 Electrical PMT Meeting Building #2, Conference Room 24E01</p> <p>3:00PM - 5:00PM CSP EL Methods Meeting Bld 5, CR# 20062</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p>	15
16	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>09:00AM - 10:00AM CHASSIS E/E SDS</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 3:30PM</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>2:00PM - 4:00PM</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>11:00AM - NOON **Rescheduled**</p>	<p>07:00AM - 6:00PM Brake Pressure Switch Investigation</p> <p>10:00AM - 11:00AM Section Mtg BL53A019</p>	22

3713 6441

	Anita Malhotra BL53A019 3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 ECR 13E112	U152/U231 Air PDK 2R052	Brake Pressure Switch Bldg 5 3A039	Tullio's	1:00PM - 2:00PM Notice of a meeting QMP-555	
23	07:00AM - 6:00PM Brake Pressure Switch Investigation 1:00PM - 2:00PM U222/U228 Chassis E/B Subsystem PAT. Bldg.#5 3A-047 1:30PM - 2:30PM 3a017, U231 CVSA, Windsor 3:30PM - 4:00PM 1992-93 Town Car Underhood Fires (NHTSA Inquiry PE98-055) Bldg. #1 ECR 13E112	07:00AM - 6:00PM Brake Pressure Switch Investigation 2:00PM - 3:30PM U152/U231 Air PDK 2R052	07:00AM - 6:00PM Brake Pressure Switch Investigation 1:00PM - 2:00PM Chassis E/B SDS BL53A019 2:00PM - 4:00PM Brake Pressure Switch Bldg 5 3A039	07:00AM - 6:00PM Brake Pressure Switch Investigation 09:30AM - 11:00AM FN145/EN114 Electrical PMT Meeting Building #2, Conference Room 24ED1 3:00PM - 5:00PM CSP EE Methods Meeting Bld 5, CR# 21062	07:00AM - 6:00PM Brake Pressure Switch Investigation 10:00AM - 11:00AM Section Mtg BL53A019	29
30	07:00AM - 6:00PM Brake Pressure Switch Investigation 09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019 10:00AM - 11:00AM Panther Chassis PMT LVC, CK 24G14A 1:00PM - 2:00PM U222/U228 Chassis E/B Subsystem PAT. Bldg.#5 3A-047					
	07:00AM - 6:00PM Brake Pressure Switch Investigation 09:00AM - 10:00AM CHASSIS E/E SDS Anita Malhotra BL53A019 10:00AM - 11:00AM Panther Chassis PMT LVC, CK 24G14A 1:00PM - 2:00PM U222/U228 Chassis E/B Subsystem PAT. Bldg.#5 3A-047					

View previous calendar
 View next calendar
 PostScript
 Compact PostScript

WFB Calendar interface to PROPS
 Copyright © 1996, 1997, 1998 Ford Motor Company. All Rights Reserved.

Evaluation Process Brake Pressure switch / Harness

Brake Pressure Switch Plan Updated 2/18/99
Evaluation Plan for Field Returns

Sw #		Date of update	
Mileage		Sw Date Code	
Sw P/N			

Category	Step #	Action	Notes/Data	Comments
Field Info	1	Log Field Info into Switch Log.xls		
	2	Photograph Switch		
	3	Record any unusual external visual observations		
	4	Check for Connector engagement		If not correct conduct X-Ray to determine fit-up between base lip and red seal
Switch + Connector Assembly	5	Wire 1(LG/R) to Wire 2(ORANGE) Resistance		
	6	Wire 1(LG/R) to Hexport Resistance		
	7	Wire 2(ORANGE) to Hexport Resistance		
	8	Separate Harness from Switch		
Connector Only	9	Verify Connector Seal		Visual check of Red Seal, Dirt lines, Indentation mark.. Indentation mark must be 360 degrees.
	10	Wire 1(LG/R) to Wire 2(ORANGE) resistance		
	11	Current Leakage Wire 1(LG/R) to Wire 2(ORANGE)		
	12	Check for full engagement of connector		Visual check of dirt lines on mated switch base
	13	Check wire insulation		
	14	Check wire gray seals		
	15	Cut wire insulation to check for corrosion		Cut insulation longitudinally to check for wicking along wires. If signs of corrosion, identify color, save samples for chem Id.
Switch External Unpressurized	16	Assemble Switch to Calibration Stand		
	17	Spring Terminal to Stationary Terminal Resistance		Stationary Terminal is closest to the outside connector keying tab.
	18	Spring Terminal to Hexport Resistance		
	19	Stationary Terminal to Hexport resistance		

3713 6443

Steve Reimers, 313 390 3286,
sreimers@ford.com
file evalproc.xls

page 1 of 2
printed 6/1/99 3:23 PM
uncontrolled document

original 2/18/99
revised tbd

Evaluation Process Brake Pressure switch / Harness

- 20 Base to Hexport Resistance
- 21 Current Leakage Spring Terminal to Hexport
- 22 Current Leakage Stationary Terminal to Hexport
- 23 Voltage drop at 750 mA

Switch	24 Switch Opening Pressure	Do not perform on parts from underhood fires, as may disturb diaphragm/other condition
External	25 Switch Closing Pressure	Do not perform on parts from underhood fires, as may disturb diaphragm/other condition
Pressurized	26 Proof Test for Leakage	Do not perform on parts from underhood fires, as may disturb diaphragm/other condition
	27 Repeat Steps 17 through 23 at 180 psig	

Switch Internal	<p>Procedure to remove aluminum crimp ring</p> <p>Use aluminum foil (or plastic if Ford prefers) to mask the analysis surface.</p> <p>Also create a paper/tape shield to further reduce chance of contamination during cutting of crimp ring.</p> <p>Place a piece of tape over the area to be cut.</p> <p>Cut crimp ring using jewelers saw or Dremel cutoff wheel</p> <p>Cut corners of ring at 180 degree orientation</p> <p>Unfold crimp ring</p> <p>Optically examine revealed surfaces. Take optical photographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate.</p> <p>Inside surface of crimp ring.</p> <p>Seal area and underside of base</p> <p>Top of cup</p>
Analytical Techniques SEM/EDX/IR	<p>Assess Need for Analytical Techniques</p> <p>Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.</p> <p>Reprotect the top surface and remove the cup</p> <p>Optically document all revealed surfaces starting with cup.</p> <p>Meanwhile, start SEM-EDX analysis on top side of cup. . Particularly look for evidence of corrosion or arcing</p> <p>Particularly focus in on the edges of the ceramic pin guide and on the indented ring that lines up with interior wall of the switch cavity</p> <p>Particularly look for evidence of corrosion or arcing</p> <p>Decide if we should try to flake off any of the overlaying debris to try to examine the underlying metal surface.</p> <p>Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cup.</p>

Data Entry	<p>Log All data from this sheet into Switch Log</p> <p>Photographs, Elemental maps etc must be retained and referenced by Switch #</p>
------------	--

3713 6444

Steve Reimers, 313 390 3286,
sreimers@ford.com
file evalproc.xls

page 2 of 2
printed 6/1/99 3:23 PM
uncontrolled document

original 2/18/99
revised tbd

**Data Log
Brake Pressure Switch**

20 ??
18 ??
Swr ID Sw Data Code
D leak
Log Updated 3/30/1999

PY754575 Reference
PY774256 Reference
VIN Event
VX145373 Cruise Inop
build data

42921	OPEN								
87549	OPEN								
Mileage	Tam-Header	Leaker?	Kapton #1	Kapton #2	Kapton #3	Present Status	Parts Received		
	4.8MEGACHMS	yes	crack	crack	crack	Analysis Complete			

Resistance

From TX trip of 2/10 to 2/12, John McInerney Group
OASIS

EAA

3713 6446

Steve Reimers, 313 39 03288,
sreimers@ford.com,
file SwitchLog.xls

page 2 of 2
Printed 8/1/99 3:22 PM
uncontrolled document

revised 2/18/99

Summary of Brake Switch Analysis

Sample Information					Conclusion/Comments
VIN	Sample	MY/Vehicle	Profile Data Code	Condition	
	Memphis (Reddit)	1993 TC	F2VC2298	Partially burned	Extrusion and subsequent cracks in Kapton seal formed leak path for brake fluid to enter switch cavity. Transfer of brass contact material to the cup suggests that an electrical cell formed between the hot (+) contacts and the grounded (-) cup. Brake fluid in switch cavity may have acted as electrolyte for the cell. Deterioration and stress corrosion cracking of stationary contact indicates that moisture and other contaminants may have been present with brake fluid.
	A	1993 TC	????2281	Burned	Transfer of brass contact material to cup suggests that electrical cell may have occurred. Too badly damaged to determine if Kapton leaked or if brake fluid was present in switch cavity.
	B	1992 TC	F2VC2114	Burned	Transfer of brass contact material to cup suggests that electrical cell may have occurred. Too badly damaged to determine if Kapton leaked or if brake fluid was present in switch cavity.
	C	1992 TC	F2VC2203	Burned	Transfer of brass contact material to cup suggests that electrical cell may have occurred. Too badly damaged to determine if Kapton leaked or if brake fluid was present in switch cavity.
	D	1993 CV	F2AC????	Apparent leakage	Extrusion and subsequent cracks in Kapton seal formed leak path for brake fluid to enter switch cavity. Transfer of brass contact material to the cup suggests that an electrical cell formed between the hot (+) contacts and the grounded (-) cup. Brake fluid in switch cavity may have acted as electrolyte for the cell. Failure mode appears similar to Memphis switch.
	E (#11)	TC	F2AC2137	No leaks or other apparent problems	No apparent problem with switch other than hypot damage to Kapton seals.

3713 6447

NP = Not Packaged
 TBP = To Be Performed
 TC = Town Car

GM = Grand Marquis
 CV = Crown Victoria
 PG = Polaris

Summary of Brake Switch Analysis

Sample Information					Conclusion/Comments
Y/N	Sample	MF/Vehicle	Prob# Date Code	Condition	
	F	TC	F2V22128	Apparent leakage	Examination and subsequent analysis in Kington seal forced leak tests for brake fluid to enter switch cavity. Transfer of brass contact material to the cup suggests that an electrical cell formed between the hot (+) contacts and the grounded (-) cup. Brake fluid in switch cavity may have acted as electrolyte for the cell. Stress corrosion cracking of stationary contact indicates that moisture and other contaminants may have been present with brake fluid. Failure mode appears similar to Mustang switch.
		3TC	3015	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		4TC	2048	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		6TC	2084	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		8TC	3025	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		7TC	2080	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		8TC	3028	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		8TC	2280	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		10TC	2281	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.
		11TC	3028	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problems with switch. No further analysis performed.

3713 8448

NP = Not Performed
TBP = To Be Performed
TC = Town Car

Summary of Brake Switch Analysis

Sample Information					
VIN	Sample	MY/Vehicle	Photo/Date Code	Condition	Conclusion/Comments
		2CV-PC	3063	No leaks or other apparent problems	Switch did not open when pressurized. Cup appears to have been corroded by water intrusion. Tensioner pin frozen in place by corrosion product. No evidence of brake fluid leakage or formation of electrical cell.
		3GM	3225	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		4CV-PC	3028	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		8TC	2055	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		8TC	77	Underhood fire	Severely damaged by fire. No further analysis performed.
		7TC	3063	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		8TC	2046	Underhood fire	Severely damaged by fire. No further analysis performed.

3713 8449

NP - Not Performed
 TBP - To Be Performed
 TC - Town Car

Summary of Brake Switch Analysis

Sample Information					Conclusion/Comments
VIN	Sample	MY/Vehicle	Printed Date Code	Condition	
		8 TC	3008	No leaks or other apparent problems	Switch did not open when pressurized. Shows correct leak path between contacts and ground. Cup has been corroded. Transfer pins frozen in place by corrosion products. Moisture in cavity appears to have formed current leak path. No evidence of material transfer from contacts to cup. No evidence of leak in Kaptan seals. Appears to be different failure mode than Memphis switch.
		10 CV	2272	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		11 TC	2116	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		12 TC	3068	No leaks or other apparent problems	Switch did not open when pressurized. Shows correct leak path between contacts and ground. Analyzed by SRL.
		13 TC	3068	No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
	Cash	TC	2002	Closeup return, apparent brake fluid leak.	Resistance measurements show current leak path between contacts and between contacts and ground. Kaptan seals appear to have formed leak path for brake fluid to enter switch cavity. Transfer of contact material to cup suggests electrical cell may have occurred between the hot (+) contacts and the grounded (-) cup. Brake fluid may have acted as electrolyte. Failure mode similar to Memphis switch.

3713 B460

NP = Not Performed
 TSP = To Be Performed
 TC = Town Car

GM = Grand Marquis
 CV = Crown Victoria
 PC = Police

Summary of Brake Switch Analysis

Sample Information					Conclusion/Comments
VIN	Sample	MY/Vehicle	Prob./Date Code	Condition	
					Resistance measurements show current leak path between contacts and between contacts and ground. Kaptan leads appear to have formed leak path for brake fluid to enter switch cavity. Transfer of contact material to cup suggests electrical cell may
	Deals	TC	2128	Dealship return, apparent brake fluid leak.	occurred between the hot (+) contacts and the grounded (-) cup. Brake fluid may have acted as electrolyte. Failure mode similar to Memphis switch.
	EAA	TC	2088	Underhood fire.	Analysis in progress.
	EAA	TC	2080	Underhood fire.	Analysis in progress.
	EAA	Lincoln	?	Underhood fire.	Brake fluid only. No switch to analyze.
	EAA	GM	?	Underhood fire.	Analysis in progress.
				No leaks or other apparent problems	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		TC	2028		

3718 8451

NP = Not Performed
 TBP = To Be Performed
 TC = Team Car

GM = Grand Marquis
 CV = Crown Victoria
 PC = Police

Summary of Brake Switch Analysis

Sample Information				Resistance Measurement, (1)														Function		
VIN	Sample	M/V/Vehicle #	Part#/Date Code	Condition #	Switch and Connector				Switch				Switch at 180 psi				Opening Pressure	Closing Pressure	Proof Test at 500psi	
					GRN/FO to OR	GRN/FO to Hsgport	OR to Hsgport	GRN/FO to OR	Spring Term. to Stat. Term.	Spring Term. to Hsgport	Stat. Term. to Hsgport	Base to Hsgport	Spring Term. to Stat. Term.	Spring Term. to Hsgport	Stat. Term. to Hsgport	Base to Hsgport				
	Memphis (Redick)	1993 TC	F2VC2065	Partially Burned	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	A	1993 TC	77772281	Burned	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	B	1992 TC	F2VC2114	Burned	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	C	1992 TC	F2VC2003	Burned	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	D	1997 CV	F2VC7777	Appears to be leaking	NP	NP	NP	NP	0.4-0.6M	NP	1.3M	NP	NP	NP	NP	NP	NP	NP	NP	
	E (P11)	TC	F2VC2137	No leaks or other apparent problems	NP	NP	NP	NP	0.2 mV only	NP	0.2M	NP	NP	NP	NP	NP	NP	NP	NP	

3713 8462

NP = Not Performed
 TBP = To Be Performed
 TC = Town Car

GM = Grand Marquis
 CV = Crown Victoria
 PC = Police

Summary of Brake Switch Analysis

Sample Information					Switch and Connector			Connector	Switch				Switch at 150 psi			Function			
VIN	Sample	MYA/Model #	Printed Date Code	Condition	GROUND to OR	GROUND to Hoopart	OR to Hoopart	Connector to OR	Spring Tens. to Stat. Tens.	Spring Tens. to Hoopart	Stat. Tens. to Hoopart	Base to Hoopart	Spring Tens. to Stat. Tens.	Spring Tens. to Hoopart	Stat. Tens. to Hoopart	Spec to Hoopart	Opening Pressure	Closing Pressure	Proof Test at 500psi
		TC	F2YC2125	Apparent if leaking	NP	NP	NP	NP	NP	234	NP	NP	NP	NP	NP	NP	NP	NP	NP
		2TC	3018	No leaks or other apparent	NP	NP	NP	NP	0.2	Infinity	Infinity	11.4	Infinity	Infinity	Infinity	Infinity	124	66	No apparent leak
		4TC	2545	No leaks or other apparent	NP	NP	NP	NP	0.3	Infinity	Infinity	1.0M	Infinity	Infinity	Infinity	Infinity	190	85	No apparent leak
		6TC	2904	No leaks or other apparent	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP
		8TC	3025	No leaks or other apparent	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP
		7TC	2088	No leaks or other apparent	NP	NP	NP	NP	0.2	Infinity	Infinity	7.0M	Infinity	Infinity	Infinity	Infinity	147	70	No apparent leak
		9TC	3028	No leaks or other apparent	NP	NP	NP	NP	0.2	Infinity	Infinity	16.0	Infinity	Infinity	Infinity	Infinity	132	65	No apparent leak
		8TC	2280	No leaks or other apparent	NP	NP	NP	NP	6.2	Infinity	Infinity	7.5M	Infinity	Infinity	Infinity	Infinity	140	112	No apparent leak
		10TC	2281	No leaks or other apparent	NP	NP	NP	NP	2.3	Infinity	Infinity	1.4M	Infinity	Infinity	Infinity	Infinity	137	65	No apparent leak
		11TC	3025	No leaks or other apparent	NP	NP	NP	NP	0.2	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	134	73	No apparent leak

9713 6453

NP = Not Performed
TBP = To Be Performed
TC = Town Car

GM - Grand Marquis
CV - Crown Victoria
PC - Police

Summary of Brake Switch Analysis

Sample Information					Switch and Connector				Resistance Measurement, Ω				Function						
VIN	Sample	Model	Part/Date Code	Condition	GROUND to OR	GROUND to Heaport	OR to Heaport	Connector Only	Switch				Switch at 150 psi						
									Spring Term. to Stat. Term.	Spring Term. to Heaport	Stat. Term. to Heaport	Base to Heaport	Spring Term. to Stat. Term.	Spring Term. to Heaport	Stat. Term. to Heaport	Base to Heaport	Opening Pressure	Closing Pressure	Proof Test at 500psi
		2CV-PC	3055	No leaks or other apparent problems	0.4	Infinity	Infinity	Infinity	0.1	Infinity	Infinity	Infinity	0.1	Infinity	Infinity	Infinity	127	62	No apparent leak
		3GM	3295	No leaks or other apparent problems	0.2	Infinity	Infinity	Infinity	0.2	Infinity	Infinity	17.7K	Infinity	Infinity	Infinity	Infinity	126	64	No apparent leak
		4CV-PC	3026	No leaks or other apparent problems	NP	NP	NP	NP	0.1	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	135	63	No apparent leak
		BTC	2053	No leaks or other apparent problems	0.2	Infinity	Infinity	NP	0.2	Infinity	Infinity	160K	Infinity	Infinity	Infinity	Infinity	151	62	No apparent leak
		BTC	77	Underhood	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP
		7TC	2087	No leaks or other apparent problems	Infinity	Infinity	Infinity	Infinity	0.3	Infinity	Infinity	453K	Infinity	Infinity	Infinity	Infinity	130	66	No apparent leak
		BTC	2046	Underhood	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP

3713 6454

NP = Not Performed
 TBP = To Be Performed
 TC = Town Car

GM = Grand Marquis
 CV = Crown Victoria
 PC = Police

Summary of Brake Switch Analysis

Sample Information					Resistance Measurement, Ω								Function							
VIN	Sample	MY/Metric	Part/Date Code	Condition	Switch and Connector			Opened Only	Switch				Switch at 180 psi				Opening Pressure	Closing Pressure	Proof Test at 600psi	
					GRND to OR	GRND to Heaport	OR to Heaport	GRND to OR	Spring Term. to Stat. Term.	Spring Term. to Heaport	Stat. Term. to Heaport	Base to Heaport	Spring Term. to Stat. Term.	Spring Term. to Heaport	Stat. Term. to Heaport	Base to Heaport				
	8TC		3088	No leaks or other apparent problems		26.0M	8.1M	Infinity		1.0-1.3M	8.4M	0.4		0.1	~970K	~970K	Infinity	154	89	No apparent leak
	10CV		2272	No leaks or other apparent problems		0.4	Infinity	Infinity		0.4	Infinity	Infinity	6.8	Infinity	Infinity	Infinity	Infinity	136	108	No apparent leak
	11TC		2118	No leaks or other apparent problems	NP	NP	NP	NP		0.1	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	Infinity	136	74	No apparent leak
	12TC		3088	No leaks or other apparent problems		0.3-20.2M	21.5M	Infinity		0.2-9M	38M	63.4K		0.1	Infinity	Infinity	Infinity	148	81	No apparent leak
	13TC		3088	No leaks or other apparent problems		0.3	Infinity	Infinity		0.3	Infinity	Infinity	7.5M	Infinity	Infinity	Infinity	Infinity	160	70	No apparent leak
	Dash TC		2082	Dash tip returns, apparent brake fluid leak.	NP	NP	NP	NP		>750K	>250K	>380K	Infinity	>1M	>800K	>400K	Infinity	152	82	No apparent leak

3713 6465

NP = Not Performed
 TBP = To Be Performed
 TC = Town Car

GM = Grand Marquis
 CV = Capri Vehicle
 PC = Police

Summary of Brake Switch Analysis

Sample Information					Conclusions/Comments
VIN	Sample	MY/Vehicle	Prob/Date Code	Condition	
		STC	3008	No leaks or other apparent problems.	Switch did not open when pressurized. Shows current leak path between contacts and ground. Cap has been covered. Transfer pin float is placed by corrosion products. Moisture in cavity appears to have formed current leak path. No evidence of material transfer from contacts to cap. No evidence of leak in Kapton seals. Appears to be different failure mode than Memphis switch.
		10 CV	2272	No leaks or other apparent problems.	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		15 TC	2115	No leaks or other apparent problems.	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
		15 TC	2005	No leaks or other apparent problems.	Switch did not open when pressurized. Shows current leak path between contacts and ground. Analyzed by SRL.
		15 TC	2000	No leaks or other apparent problems.	Examination, resistance and functional testing revealed no apparent problem with switch. No further analysis performed.
	Osaka	TC	2002	Dealership return, apparent brake fluid leak.	Resistance measurements show current leak path between contacts and between contacts and ground. Kapton seals appear to have formed leak path for brake fluid to enter switch cavity. Transfer of conductive material to cup suggests electrical cell may occur between the hot (+) contacts and the grounded (-) cup. Brake fluid may have acted as electrolyte. Failure mode similar to Memphis switch.

9713 0450

NP = Not Performed
 TBP = To Be Performed
 TC = Town Car

Summary of Brake Switch Analysis

Sample Information				Resistance Measurement, Ω													Function			
VIN	Sample	M/V Vehicle	Field Data Code	Condition	Switch and Connector			Connector Only	Switch				Switch at 180 psi				Opening Pressure	Closing Pressure	Proof Test at 550psi	
					GRNWD to OR	GRNWD to Hoopst	OR to Hoopst		GRNWD to OR	Spring Term. to Stat. Term.	Spring Term. to Hoopst	Stat. Term. to Hoopst	Base to Hoopst	Spring Term. to Stat. Term.	Spring Term. to Hoopst	Stat. Term. to Hoopst				Base to Hoopst
	Deals	TC	2128	Deals No return, apparent 1 brake fluid leak.	NP	NP	NP	NP	>130K	>17K	>350K	Infinity	175K	>140K	>16K	Infinity	No sound	No sound	No apparent leak	
	EAA	TC	2089	Underhood of fire.	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	EAA	TC	2089	Underhood of fire.	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	EAA	Miracle	?	Underhood of fire.	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	EAA	GM	?	Underhood of fire.	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	NP	
	1TC		2028	No leaks or other apparent problems					0.3	Infinity	Infinity	Infinity	6.0	Infinity	Infinity	Infinity	Infinity	150	80	No apparent leak

3719 8456

NP = Not Performed
 TBP = To Be Performed
 TC = Team Car

GM = Grand Marquis
 CV = Crown Victoria
 PC = Police

Summary of Brake Switch Analysis

VIN	Observations/Findings								
	Components/Wires				Switch				
	Engage ment	Wires	Red Seal	Gray Seal	Hasport, Washer, Converter, Spacer, and Disc	Environmental Seal	Gasket/Kapton Seals	Cup	Base, Switch Cavity, Contacts, Terminals
	Could not determine.	Short length (~10 mm) no apparent exterior damage. Oxidation or tarnish beneath insulation.	Could not determine.	Appears intact. White residue in cavity contains elements typically found in dry chemical fire extinguishers.	Black residue containing glycol based material (probably brake fluid) and a metal particle. Indicates presence of brake fluid on disc and switch sides of seals.	Intact. Appears to have had good sealing.	Gasket intact; appears to have had good sealing. All Kapton seals beaded and exhibit brittle cracks which most likely formed a leak path. Damage appears to have initiated in seal closest to washer. Kapton charred and embrittled by unknown mechanism.	Green deposits on face of cup contain elements from brass contacts, indicating transfer of contact material to cup, possibly as a result of an electrical arc. Glycol based material (probably brake fluid) also present.	Base separated below spring ring. Transfer pin and movable are contact missing. Movable contact melted back into switch (possibly due to arcing); appears to have occurred in later stages of event. Black deposit on terminal of movable contact appears to be a sulfur compound. Stationary contact exhibits discoloration, loss of material due to corrosion, and stress corrosion cracking. Green deposit on terminal of stationary contact appears to be a sulfur compound.
Missing	Missing	Missing	Missing	Elements from contact material detected at filling end of hasport. Silicone also detected.	Missing	Gasket missing. Charred fragments of Kapton seals remain.	Deposits on face of cup contain elements from brass contacts, indicating transfer of contact material to cup probably as an oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, transfer pin, and terminals missing.	
Missing	Missing	Missing	Missing	Elements from contact material detected at filling end of hasport.	Not permitted to disassemble switch.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts, indicating transfer of contact material to cup probably as an oxide, sulfide, or corrosion product.	Transfer pin and movable contact missing. Stationary contact exhibits crack in similar location as that in Memphis (Redick) sample.	
Missing	Missing	Missing	Missing	Elements from contact material detected at filling end of hasport. Black residue in cavity contains traces of hydrocarbon and silicone.	Missing	Gasket appears charred. Kapton seals present, but melted together. Could not evaluate for cracks/leaks.	Deposits on face of cup contain elements from brass contacts, indicating transfer of contact material to cup probably as an oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, transfer pin, and terminals missing.	
Missing	Missing	Missing	Missing	Black residue in hasport cavity, on washer, and converter contain glycol based material (probably brake fluid) and a metal particle.	Intact and appears to have had good seal.	Gasket intact and appears to have had good seal. Kapton seals exhibit damage similar to that found in Memphis (Redick) sample. All three exhibit brittle cracks which probably formed leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. (Liquid in interior and on face is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Contacts appear intact. Dark green deposits on movable and stationary contact contain elements from brass contact material. Terminals are clean (no apparent deposits or corrosion).	
Missing	Missing	Missing	Missing	Black residue in hasport contains glycol based material (probably brake fluid) and a metal particle. No apparent fluid on components inside cup.	Intact and appears to have had good seal.	Gasket intact and appears to have had good seal. Kapton seals exhibit deformation and beading similar to that found in Memphis (Redick) sample. Cracking on surfaces suggest friction cracking is occurring.	Face and interior of cup appear clean and dry.	Switch and terminal cavities appear clean and dry. No apparent deposits or corrosion on terminals.	

3718 8457

NP = Not Performed
TBP = To Be Performed
TC = Town Car

GM = Grand Marquis
CV = Crown Victoria
PC = Police

Summary of Brake Switch Analysis

VIN	Observational Findings								
	Connectors/Wires				Switch				
	Engage circuit	Wires	Red Seal	Gray Seal	Hoopet, Washer, Converter, Spacer, and Disc	Environment Seal	Gasket/Kapton Seals	Cup	Base, Switch Cavity, Contacts, Terminals
	Missing	Missing	Missing	Missing	Black sealant in hoopet cavity, on washer, and converter contains glycol based material (probably brake fluid) and a metal particle.	Intact and appears to have had good seal.	Gasket intact and appears to have had good seal. Kapton seals exhibit damage similar to that found in Memphis (Residual) samples. All three exhibit little cracks which probably formed leak paths.	Dark green deposits on face of cup contain elements from brake contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid in interior and on face is glycol based (probably brake fluid).	Switch and terminal cavities contain glycol based material (probably brake fluid). Shallow contact intact; shows stress corrosion cracking in progress in same location as Memphis sample. Movable contact separated, apparently due to loss of material.
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP
	Missing	Missing	Missing	Missing	NP	NP	NP	NP	NP

3713 8458

NP = Not Performed
 TBP = To Be Performed
 TC = Town Car

GM - Grand Marais
 CV - Crown Victoria
 PC - Police

Summary of Brake Switch Analysis

VIN	Observation/Findings								
	Connector/Wires				Switch				
	Engage Point	Wires	Red Seal	Gray Seal	Hesport, Washer, Converter, Spacer, and Disc	Environmental Seal	Gasket/Kapton Seals	Cup	Base, Gasket Cavity, Contacts, Terminals
	ORWR O side not fully engaged	TBP	Intact. Impression viewed and off-center	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in wire insulation.	Black residue in filling end of hesport. Did not analyze. Apparent wet deposits on converter, washer, and disc, as well as on interior surface of cup.	Environmental seal intact, in place, appears to have good adhesion.	Gasket intact and appears to have had good seal. Kapton seal nearest hesport exhibits deterioration and tears in seal, but no apparent cracks in substrate. Other Kapton seals show no tears, cracks, or deterioration. No apparent leak path.	Face of cap covered with rust colored deposits containing iron and zinc (probably corrosion product of cap material). Transfer pin frozen in place by corrosion product. No evidence of a call occurring.	Base contains what appears to be sealure (evaporated quickly once exposed to atmosphere). Movable contact discolored, but not heavily discolored near cup.
	Fully engaged OR wire side of connect or not fully engaged	TBP	Intact. Impression even and deep all the way around	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Black residue in filling end of hesport. Did not analyze residue. Did not disassemble switch.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
		TBP	Intact. Impression viewed and deep all the way around	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Black residue with copper or rust colored globules in filling end of hesport. Did not analyze residue. Did not disassemble switch.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Fully engaged	TBP	Intact. Impression even and deep -80% around. Witness mark from damage to edge of	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in wire insulation.	Pink colored deposit in filling end of hesport. Did not analyze deposit. Did not disassemble switch.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Missing	Missing	Missing	Missing	Black residue in filling end of hesport; did not analyze.	Missing	Did not disassemble	Exposed face covered with rust and greenish colored deposits; did not analyze.	Missing.
	Fully engaged	TBP	Intact. Impression even and deep all the way around	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Black residue with copper or rust colored globules in filling end of hesport. Did not analyze residue. Did not disassemble switch. Still attached in prop. value did not disassemble.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Missing	Missing	Missing	Missing		Did not disassemble	Did not disassemble	Exposed face covered with rust and greenish colored deposits; did not analyze.	Missing.

9713 6459

NP = Not Performed
TBP = To Be Performed
TC = Torn Car

Summary of Brake Switch Analysis

Connections/Wires					Observations/Findings				
VIN	Engage meal	Wires	Red Seal	Gray Seal	Switch				
					Haspot, Washer, Converter, Spacer, and Disc	Environmental Seal	Gasket/Kapton Seals	Cap	Base, Switch Cavity, Contacts, Terminals
PY78R15B	Fully engaged	TSP	Intact. Impression even, but not deep or sharp. Not as compressed as in other	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in wire insulation.	Still attached to prop. valve. Black residue in haspot cavity; did not analyze. White deposits on washer, converter, disc, and interior of cup; did not analyze - probably corrosion product of zinc plating.	Intact and appears to have had good seal.	Gasket intact and appears to have had good seal. Kapton seal around haspot exhibits deterioration and possible tear in left, but no apparent cracks in substrate. Other Kapton seals show no tears, cracks, or deterioration. No apparent leak path.	Face of cup covered with rust and white colored deposits containing iron and zinc (probably corrosion product of cup material). Transfer pin frozen in place by corrosion product. Appears moist (evaporated quickly). No evidence of a seal occurring.	Movable contact floored, but not heavily corroded near cup. Feet of contacts and their bases appear clean. Terminals exhibit some corrosion.
	Fully engaged	TSP	Intact. Impression even and deep.	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Still attached to prop. valve. Did not disassemble.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Fully engaged	TSP	Intact. Impression even and deep.	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Still attached to prop. valve. Did not disassemble.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Fully engaged	TSP	Intact. Impression even and deep.	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Black residue in filling end of haspot; did not analyze at CL. Disassembled and analyzed by SRL.	Disassembled and analyzed by SRL.	Disassembled and analyzed by SRL.	Disassembled and analyzed by SRL.	Disassembled and analyzed by SRL. Terminals have light deposits on them.
	Fully engaged	TSP	Intact. Impression even and deep.	Intact. Wires and cavity clean below seal except for trace of oil from seal. Seal left impressions in	Black residue in filling end of haspot; did not analyze.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).
	Missing	Missing	Missing	Missing	Black residue in filling end and contains glycol ether based material (probably brake fluid), oil, carbon, and other material; possibly a hydrocarbon. No apparent bars on converter, washer, or haspot.	Intact and appears to have had good seal.	Gasket is intact and appears to have had good seal. Kapton seals exhibit circumferential tears in Teflon with radial and circumferential cracking in substrate. Appears to have followed leak path. Damage appears similar to that in Memphis sample.	Face of cup covered with black residue and copper colored glazes. Residue contains glycol based material (probably brake fluid) and possibly a hydrocarbon. Additional analysis of rubber padding.	Switch cavity of base contains black sludge. Movable contact appears to have been corroded away. Black residue is present in terminal cavity and at bases of terminals. Terminals appear clean otherwise.

3713 6460

NP = Not Performed
TSP = To Be Performed
TC = Town Car

Summary of Brain Switch Analysis

Observational Findings									
FY758158	Covered/Misc				Switch				
VSN	Engage ment	Wires	Red Seal	Gray Seal	Hasport, Washer, Converter, Spacer, and Disc	Environmentel Seal	Gasket/Kapton Seal	Cup	Base, Switch Cavity, Contacts, Terminals
	Missing	Missing	Missing	Missing	Black residue in filling end of hasport contains glycol based material (probably brake fluid) and an oxide. Copper colored globules also present. No apparent burn on converter, washer, or hasport.	Intact and appears to have had good seal.	Gasket is intact and appears to have had good seal. Kapton seals exhibit circumferential tears in Teflon with radial and circumferential cracking in substrate. Appears to have formed leak path. Damage appears similar to that in Memphis sample.	Face of cup covered with black residue and copper colored globules. Residuum contains glycol based material (probably brake fluid) and possibly a hydrocarbon. Additional analyses of residue pending.	Switch cavity of base contains black sludge with copper colored globules. Movable contact appears to have been corroded away. Black residue is present in terminal cavity and on the terminals.
	Missing	Missing	Missing	Missing	Black residue in filling end of hasport. Washer, converter, disc, and interior of cup are covered with rust colored deposits.	Missing	Gasket missing. Charred fragments of Kapton seals remain.	Face of cup covered with rust colored deposits. Analysis pending.	Missing
	Missing	Missing	Missing	Missing	Black residue in filling end of hasport. Washer, converter, disc, and interior of cup are covered with rust colored deposits.	Missing	Gasket missing. Charred fragments of Kapton seals remain.	Face of cup covered with rust colored deposits. Analysis pending.	Missing
	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing	Missing
	Missing	Missing	Missing	Missing	TBP	TBP	TBP	TBP	Missing
	Fully engaged	TBP	Intact. Impression even and deep all the way around	scaly clean below seal except for trace of oil from seal. Seal left impressions in wire insulation.	Black residue in filling end of hasport. Did not analyze.	Did not disassemble	Did not disassemble	Did not disassemble	Did not disassemble. Terminals clean (no apparent deposits or corrosion).

3713 6461

NP = Not Performed
TBP = To Be Performed
TC = Toon Car

GM = Grand Marquis
CV = Crown Victoria
PC = Police

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT REC'D AT GEN. LAB.

		Memphis	A	B	C	D	E	F	T
		PY622877	PY885224	NY745119	NY703705	VX145373	NX768774	NY760055	NX762858
Field Info	1 Log Field Info into Switch Logfile	C	C	C	C	C	C	C	C
	Condition	FIRE	FIRE	FIRE	FIRE	BF LEAK	NO FIRE/LEAK	BF LEAK	NO FIRE/LEAK
	2 Photograph Switch	C	C	C	C	C	C	C	NP
	3 Record any unusual external visual observations	C	C	C	C	C	C	C	C
	4 Check for Connector engagement X-ray if appropriate	C	NA	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	5 Wire 1(LBR) to Wire 2(ORANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	6 Wire 1(LBR) to Heapsort Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	7 Wire 2(ORANGE) to Heapsort Resistance	NA	NA	NA	NA	NA	NA	NA	NA
Connector Only	8 Separate Harness from Switch	C	NA	NA	C	NA	NA	NA	NA
	9 Verify Connector Seal	C	NA	NA	C	NA	NA	NA	NA
	10 Wire 1(LBR) to Wire 2(ORANGE) resistance	NA	NA	NA	NA	NA	NA	NA	NA
	12 Check for full engagement of distributor	NA	NA	NA	NA	NA	NA	NA	NA
	13 Check wire insulation	C	NA	NA	NA	NA	NA	NA	NA
Switch External Unpressurized	14 Check wire gray seals	C	NA	NA	NA	NA	NA	NA	NA
	15 Cut wire insulation to check for corrosion	C	NA	NA	NA	NA	NA	NA	NA
	16 Assemble Switch to Calibration Stand	NA	NA	NA	NA	NA	NA	NA	C
	17 Spring Terminal to Stationary Terminal Resistance	NA	NA	NA	NA	0.4	0.2	NP	0.3
	18 Spring Terminal to Heapsort Resistance	NA	NA	NA	NA	4.8M	INF	2M	INF
	19 Stationary Terminal to Heapsort resistance	NA	NA	NA	NA	NP	NP	NP	INF
	20 Seal to Heapsort Resistance	NA	NA	NA	NA	1.1	6.8M	NP	3.3M
	24 Switch Opening Pressure	NA	NA	NA	NA	NA	NA	NA	122
Switch External Pressurized	25 Switch Closing Pressure	NA	NA	NA	NA	NA	NA	NA	59
	26 Final Test for Leakage	NA	NA	NA	NA	NA	NA	NA	NO LEAK
	27 Repeat Steps 17 through 20 at 100 psi	NA	NA	NA	NA	NA	NA	NA	C
		NA	NA	NA	NA	NA	NA	NA	INF
Switch	28 Remove aluminum drive ring	C	C	NP	C	C	C	C	NP
	29 Examine revealed surfaces. Photograph	C	C	NP	C	C	C	C	NP
	30 Remove cap	C	C	NP	C	C	C	C	NP
	31 Examine revealed surfaces. Photograph	C	C	NP	C	C	C	C	NP
Techniques	31 SEM-EDX /FTIR base, contacts, terminals	C	C	NP	C	C	C	C	NP
	32 SEM-EDX /FTIR cup, heapsort, weather seals, etc.	C	C	C	C	C	C	C	NP
	33 Microphotographic analysis of contacts. Look for evidence of corrosion or wiring	C	NA	NP	C	C	C	C	NP

2713 6482

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT GEN. LAB.

		3	4	5	6	7	8	9	10
		PY72404S	PY82817U	PY632329	PY728811	DX728439	PX180223	PX637766	PY889375
Field Info	1 Log Field Info into Switch Log file	C	C	C	C	C	C	C	C
	Condition	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK
	2 Photograph Switch	NP	NP	NP	NP	NP	NP	NP	NP
	3 Record any unusual external visual observations	C	C	C	C	C	C	C	C
Switch + Connector Assembly	4 Check for Connector engagement	NA	NA	NA	NA	NA	NA	NA	NA
	5-Tag if appropriate	NA	NA	NA	NA	NA	NA	NA	NA
	6 Wire 1 (LGR) to Wire 2 (ORANGE) Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	6 Wire 1 (LGR) to Heapt Resistance	NA	NA	NA	NA	NA	NA	NA	NA
	7 Wire 2 (ORANGE) to Heapt Resistance	NA	NA	NA	NA	NA	NA	NA	NA
Connector Only	8 Separate Heapt from Switch	NA	NA	NA	NA	NA	NA	NA	NA
	9 Visually Check Connector Seal	NA	NA	NA	NA	NA	NA	NA	NA
	10 Wire 1 (LGR) to Wire 2 (ORANGE) resistance	NA	NA	NA	NA	NA	NA	NA	NA
	12 Check for full engagement of connector	NA	NA	NA	NA	NA	NA	NA	NA
	13 Check wire insertion	NA	NA	NA	NA	NA	NA	NA	NA
Switch External Unpressurized	14 Check wire grom seal	NA	NA	NA	NA	NA	NA	NA	NA
	15 Cut wire insulation to check for corrosion	NA	NA	NA	NA	NA	NA	NA	NA
	16 Assemble Switch to Collector Head	C	C	NA	NA	C	C	C	C
	17 Spring Terminal to Stationary Terminal Resistance	0.2	0.3	NA	NA	0.2	0.2	0.2	2.2
	18 Spring Terminal to Heapt Resistance	INF	INF	NA	NA	INF	INF	INF	INF
Switch External Pressurized	19 Stationary Terminal to Heapt resistance	INF	INF	NA	NA	INF	INF	INF	INF
	20 Wire to Heapt Resistance	11.4	1.6M	NA	NA	7.8M	18.6	7.9M	1.4M
	24 Switch Operating Pressure	134	180	NA	NA	147	132	140	137
	25 Switch Closing Pressure	50	86	NA	NA	70	85	112	66
	26 Proof Test for Leakage	NO LEAK	NO LEAK	NA	NA	NO LEAK	NO LEAK	NO LEAK	NO LEAK
Switch	27 Repeat Steps 17 through 20 at 100 psi	C	C	NA	NA	C	C	C	C
		INF	INF	NA	NA	INF	INF	INF	INF
		INF	INF	NA	NA	INF	INF	INF	INF
		INF	INF	NA	NA	INF	INF	INF	INF
		INF	INF	NA	NA	INF	INF	INF	INF
Switch	28 Remove aluminum clasp ring	NP	NP	C	C	NP	NP	NP	NP
	29 Examine revealed surfaces. Photograph	NP	NP	C	C	NP	NP	NP	NP
	30 Remove cap	NP	NP	C	C	NP	NP	NP	NP
	31 Examine revealed surfaces. Photograph	NP	NP	C	C	NP	NP	NP	NP
Techniques	31 SEM-EDX /FTIR case, contacts, terminals	NP	NP	NP	NP	NP	NP	NP	NP
	32 SEM-EDX /FTIR cap, heapt, wiper seats, etc.	NP	NP	NP	NP	NP	NP	NP	NP
	33 Microscopic analysis of contacts	NP	NP	NP	NP	NP	NP	NP	NP
	Look for evidence of corrosion or arcing	NP	NP	NP	NP	NP	NP	NP	

3713 8483

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT GEN. LAB.

		11	12	13	14	15	16	17	18
		PY728088	PX885270	NY740208	PX823672	PY685374	BY639884	PY680225	PY688795
Field Info	1 Log Field Info into Switch Log.xls	C	C	C	C	C	C	C	C
	Condition	NO FIRE/LEAK							
	2 Photograph Switch	NP							
	3 Record any unusual external visual observations	C							
	4 Check for Connector engagement	NA							
	Stay if it appropriate	NA							
Switch + Connector Assembly	5 Wire 1(L.GND) to Wire 2(ORANGE) Resistance	NA							
	6 Wire 1(L.GND) to Harport Resistance	NA							
	7 Wire 2(ORANGE) to Harport Resistance	NA							
	8 Separate Harness from Switch	NA							
Connector Only	9 Verify Connector Seal	NA							
	10 Wire 1(L.GND) to Wire 2(ORANGE) resistance	NA							
	12 Check for full engagement of connector	NA							
	13 Check wire insulation	NA							
	14 Check wire gray seats	NA							
	16 Cut wire insulation to check for corrosion	NA							
Switch External Unpressurized	16 Assemble Switch to Calibration Stand	C							
	17 Spring Terminal to Stationary Terminal Resistance	0.2							
	18 Spring Terminal to Harport Resistance	INF							
	19 Stationary Terminal to Harport Resistance	INF							
	20 Seal to Harport Resistance	INF							
Switch External Pressurized	24 Switch Opening Pressure	139							
	25 Switch Closing Pressure	71							
	26 Proof Test for Leaks	NO LEAK							
	27 Repeat Steps 17 through 26 at 180 psig	C							
		INF							
		INF							
		INF							
		INF							
Switch	28 Remove aluminum crimp ring	NP							
	29 Examine revealed surfaces. Photograph	NP							
	30 Remove cap	NP							
	31 Examine revealed surfaces. Photograph	NP							
Techniques	31 SEM-EDX AFTER cap, contacts, terminals	NP							
	32 SEM-EDX AFTER cap, harport, weather seals, etc.	NP							
	32 Micrographic analysis of contacts.	NP							
	Look for evidence of corrosion or wiring	NP							

3719 6484

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT GEN. LAB.

		19	20	21	22	23	1	2	3
		PY774268	PY764676	PX643615	71	PX628834	PY638860	PX163820	ROK81585
Field Info	1 Log Field Info into Switch Lognote						C	C	C
	2 Condition						NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK
	3 Photograph Switch						C	C	C
	3a) Record any unusual external visual observations						C	C	C
	4 Check for Connector engagement						C	C	C
	5 Key if appropriate						NA	G	NA
Switch + Connector Assembly	6 Wire 1 (Orange Wire 2 (ORANGE)) Resistance						0.3	0.4	0.2
	6 Wire 1 (GRN) to Harport Resistance						INF	INF	INF
	7 Wire 2 (ORANGE) to Harport Resistance						INF	INF	INF
	8 Separate Harness from Switch						C	C	C
Connector Only	9 Verify Connector Type						C	C	C
	10 Wire 1 (GRN) to wire 2 (ORANGE) resistance						INF	INF	INF
	11								
	12 Check for full engagement of connector						C	C	C
	13 Check wire insulation						C	C	C
	14 Check wire grey seals						C	C	
	15 Cut wire insulation to check for corrosion						TBP	TBP	
Switch External Unpressurized	16 Assemble Switch to Calibration Stand						C	C	C
	17 Spring Terminal to Stationary Terminal Resistance						0.3	0.1	0.2
	18 Spring Terminal to Harport Resistance						INF	INF	INF
	19 Stationary Terminal to Harport resistance						INF	INF	INF
	20 Wire to Harport Resistance						6.5	INF	17.7K
	21								
Switch External Pressurized	24 Switch Opening Pressure						158	127	126
	25 Switch Closing Pressure						88	82	84
	26 Proof Test for Leakage						NO LEAK	NO LEAK	NO LEAK
	27 Repeat Steps 17 through 20 at 188 psig						C	C	C
	28					INF	0.1	INF	
	29					INF	INF	INF	
	30					INF	INF	INF	
	31					INF	INF	INF	
Switch	28 Remove adjustment or top ring						NP	C	NP
	29 Examine exposed surfaces. Photograph						NP	C	NP
	30 Remove top						NP	C	NP
	31 Examine revealed surfaces. Photograph						NP	C	NP
	32						NP	C	NP
Techniques	31 SEM-EDX /FTIR lens, contacts, terminals						NP	C	NP
	32 SEM-EDX /FTIR cup, harport, weather seals, etc.						NP	C	NP
	33 Metallographic analysis of contacts.						NP	NP	NP
	Look for evidence of abrasion or scoring						NP	C	NP

3713 8465

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLB = NOT RECD AT DEN. LAB.

		4	5	6	7	8	9	10	11
		PX163312	PY610384	NY724368	PY750172	NY733181	PY758168	PX151140	NY757408
Field Info	1 Log Field Info into Switch Log-Log	C	C	C	C	C	C	C	C
	2 Condition	NO FIRE/LEAK	NO FIRE/LEAK	FIRE	NO FIRE/LEAK	FIRE	NO FIRE/LEAK	NO FIRE/LEAK	NO FIRE/LEAK
	3 Photograph Switch	C	C	C	C	C	C	C	C
	4 Record any unusual external visual observations	C	C	C	C	C	C	C	C
	5 Check for Connector engagement	C	C	NA	C	NA	C	NA	C
Switch + Connector Assembly	6 Wire 1 (LBRG) Wire 2 (ORANGE) Resistance	NP	0.2	NA	INF	NA	2	0.4	NP
	8 Wire 1 (LBRG) to Heapsat Resistance	NP	INF	NA	INF	NA	8.0M	INF	NP
	7 Wire 2 (ORANGE) to Heapsat Resistance	NP	INF	NA	INF	NA	6.1M	INF	NP
	9 Measure Heapsat Side Switch	C	C	NA	C	NA	C	C	C
	10 Verify Connector Seal	C	C	NA	C	NA	C	C	C
Connector Only	10 Wire 1 (LBRG) to Wire 2 (ORANGE) resistance	NP	NA	NA	INF	NA	INF	INF	NP
	12 Check for full engagement of connector	C	C	NA	C	NA	C	C	C
	13 Check wire installation	C	C	NA	C	NA	C	C	C
	14 Check wire gray mark	C	C	NA	C	NA	C	C	C
	15 Cut wire insulation to check for corrosion	TBP	TBP	NA	TBP	NA	TBP	TBP	TBP
Switch External Unpressurized	16 Reverse Switch in Calibration Stand	C	C	NA	C	NA	C	C	C
	17 Spring Terminal to Stationary Terminal Resistance	0.1	0.2	NA	0.3	NA	1.5	0.4	0.1
	18 Spring Terminal to Heapsat Resistance	INF	INF	NA	INF	NA	6.3M	INF	INF
	19 Stationary Terminal to Heapsat resistance	INF	INF	NA	INF	NA	6.4M	INF	INF
	20 Date to Heapsat Resistance	INF	100K	NA	463K	NA	0.4	8.8	INF
Switch External Pressurized	24 Switch Opening Pressure	139	151	NA	138	NA	184	198	135
	25 Switch Closing Pressure	85	82	NA	88	NA	88	108	74
	26 Proof Test for Leakage	NO LEAK	NO LEAK	NA	NO LEAK	NA	NO LEAK	NO LEAK	NO LEAK
	27 Repeat Steps 17 through 20 at 100 psig	C	C	NA	C	NA	C	C	C
		INF	INF	NA	INF	NA	0.1	INF	INF
Switch		INF	INF	NA	INF	NA	~870K	INF	INF
		INF	INF	NA	INF	NA	~970K	INF	INF
		INF	INF	NA	INF	NA	INF	INF	INF
	28 Remove aluminum clamp ring	NP	NP	NP	NP	NP	C	NP	NP
	29 Examine revealed surfaces. Photograph	NP	NP	NP	NP	NP	C	NP	NP
Techniques	30 Remove cup	NP	NP	NP	NP	NP	C	NP	NP
	31 Examine revealed surfaces. Photograph	NP	NP	NP	NP	NP	C	NP	NP
	31 SEM-EDX/FTIR base, contacts, terminals	NP	NP	NP	NP	NP	C	NP	NP
	32 SEM-EDX/FTIR cup, heapsat, weather seal, etc.	NP	NP	NP	NP	NP	C	NP	NP
	33 Metallographic analysis of contacts	NP	NP	NP	NP	NP	NP	NP	NP
	Look for evidence of corrosion or scoring	NP	NP	NP	NP	NP	C	NP	NP

3713 6455

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT GEN. LAB.

		12	13	OASIS	OASIS	EAA	EAA	EAA	EAA
		PY742858	PY743413	NY734410	PY605826	PY614995	NY738847	NY706341	NY714569
Field Info	1 Log Field Info into Switch Logbook	C	C	C	C	C	C	C	C
	2 Photograph Switch	C	C	C	C	C	C	NA	TBP
	3 Record any unusual external visual observations	C	C	C	C	C	C	NA	TBP
	4 Check for Connector engagement	C	C	NA	NA	NA	NA	NA	NA
	5 Key if appropriate	C	NA	NA	NA	NA	NA	NA	NA
Switch + Connector Assembly	6 Wire 1(LGRN) to Wire 2(ORANGE) Resistance	0.8	0.3	NA	NA	NA	NA	NA	NA
	7 Wire 1(LGRN) to Heapsort Resistance	20.2M	INF	NA	NA	NA	NA	NA	NA
	8 Wire 2(ORANGE) to Heapsort Resistance	21.6M	INF	NA	NA	NA	NA	NA	NA
	9 Separate Harness from Switch	C	C	NA	NA	NA	NA	NA	NA
Connector Only	10 Verify Connector Seal	C	C	NA	NA	NA	NA	NA	NA
	11 Wire 1(LGRN) to Wire 2(ORANGE) resistance	INF	INF	NA	NA	NA	NA	NA	NA
	12 Check for full engagement of connector	C	C	NA	NA	NA	NA	NA	NA
	13 Check wire insulation	C	C	NA	NA	NA	NA	NA	NA
	14 Check wire grommets	C	C	NA	NA	NA	NA	NA	NA
15 Cut wire insulation to check for corrosion	TBP	TBP	NA	NA	NA	NA	NA	NA	
Switch External Unpressurized	16 Assemble Switch to Calibration Stand	C	C	C	C	NA	NA	NA	NA
	17 Spring Terminal to Stationary Terminal Resistance	0.2	0.2	>700K	>180K	NA	NA	NA	NA
	18 Spring Terminal to Heapsort Resistance	34M	INF	>250K	>17K	NA	NA	NA	NA
	19 Stationary Terminal to Heapsort resistance	36M	INF	>550K	>120K	NA	NA	NA	NA
	20 Wire to Heapsort Resistance	63.4K	7.5M	INF	INF	NA	NA	NA	NA
Switch External Pressurized	24 Switch Opening Pressure	148	150	162	NO SOUND	NA	NA	NA	NA
	25 Switch Closing Pressure	61	70	82	NO SOUND	NA	NA	NA	NA
	26 Proof Test for Leakage	NO LEAK	NO LEAK	NO LEAK	NO LEAK	NA	NA	NA	NA
	27 Repeat Steps 17 through 23 at 150 psig	C	C	C	C	NA	NA	NA	NA
Switch	28	0.1	INF	>1.0M	170K	NA	NA	NA	NA
	29	INF	INF	>600K	>140K	NA	NA	NA	NA
	30	INF	INF	>400K	>15K	NA	NA	NA	NA
	31	INF	INF	INF	INF	NA	NA	NA	NA
Switch	28 Remove aluminum crimp ring	SCI LAB	NP	C	C	C	C	NA	TBP
	29 Examine revealed surfaces. Photograph	SCI LAB	NP	C	C	C	C	NA	TBP
	30 Remove cap	SCI LAB	NP	C	C	C	C	NA	TBP
	31 Examine revealed surfaces. Photograph	SCI LAB	NP	C	C	C	C	NA	TBP
Techniques	31 SEM/EDX /FTIR: base, contacts, terminals	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	TBP
	32 SEM/EDX /FTIR: cap, base, contact, wiper, seals, etc.	SCI LAB	NP	TBP	TBP	TBP	TBP	NA	TBP
	33 Microphotographic analysis of contacts	SCI LAB	NP	NA	NA	NA	NA	NA	TBP
	Look for evidence of corrosion or arcing	SCI LAB	NP	C	C	C	C	NA	TBP

3713 6487

C = COMPLETE
 NA = NOT APPLICABLE
 TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
 NP = NOT PERFORMED
 NRCLS = NOT RECD AT CEN. LAB.

Field Info	1	Log Field Info into Switch Log.xls																
	2	Photograph Switch																
	3	Record any unusual external visual observations																
	4	Check for Connector engagement																
Switch + Connector Assembly	5	Verify I/P appropriate																
	6	Wire 1(L/R) to Wire 2(B/RANGE) Resistance																
	7	Wire 1(L/R) to Harport Resistance																
	8	Wire 2(B/RANGE) to Harport Resistance																
Connector Only	9	Separate Harport from Switch																
	10	Verify Connector Seal																
	11	Wire 1(L/R) to Wire 2(B/RANGE) resistance																
	12	Check seal seal for full engagement of connector																
Switch External Unpressurized	13	Check wire insulation																
	14	Check wire girth seals																
	15	Cut wire insulation to check for corrosion																
	16	Moveable Switch to Calibration Stand																
Switch External Pressurized	17	Spring Terminal to Stationary Terminal Resistance																
	18	Spring Terminal to Harport Resistance																
	19	Stationary Terminal to Harport resistance																
	20	Harport to Harport Resistance																
Switch External Pressurized	24	Switch Opening Pressure																
	25	Switch Closing Pressure																
	26	Proof Test for Leakage																
	27	Repeat Steps 17 through 20 at 100 psig																
Switch	28	Remove aluminum strip ring																
	29	Examine revealed surfaces. Photograph																
	30	Reattach cup																
	31	Examine revealed surfaces. Photograph																
Techniques	31	SEM-EDS FTIR base, contact, terminals																
	32	SEM-EDS FTIR cup, harport, washer seals, etc.																
	33	Microscopic analysis of contacts. Look for evidence of operation or wiring																

3713 8488

	PMF2AC-2B091-BA	F2AC-2B091-BA	F2VC-9F924-AB	DANA	Sheet1 PITTS	kh	F2AC-9F924-AA	TE	2B091	9F924
Oct-91	3140							2	3140	0
Nov-91	5390							3	5390	0
Dec-91	8924							3	8924	0
Jan-92	5842		73770	31890	40930			4	5842	146590
Feb-92	1656	14352	110420	67110	43310			5	16008	220840
Mar-92		19596	63850	63380	470			24	19596	127700
Apr-92		12558	31890	0	31890			22	12558	63780
May-92		13294	32360	0	32360		22840	19	13294	87560
Jun-92		13938	3330	0	3330		0	19	13938	6660
Jul-92		12880	35220	0	35220		74730	9	12880	145170
Aug-92		19182	53780	0	53780		39980	7	19182	147540
Sep-92		8280	21880	0	21080		50	7	8280	43810
Oct-92		7841	43790	0	43790		29980	10	7841	117580
Nov-92		7130	44740	0	44740		0	3	7130	89480
Dec-92		4738	18560	0	18560		0	0	4738	37120
Jan-93		4462	20460	0	15470	4990	0	0	4462	40920
Feb-93		5750	19270	0	15230	4040	0	0	5750	38540
Mar-93		8779	28790	0	23560	5230	0	2	8779	57580
Apr-93		9292	25210	0	22610	2600	0	1	9292	50420
May-93		9936	17110	0	14510	2600	0	0	9936	34220
Jun-93		9062	26180	0	22610	3570	0	4	9062	52360
Jul-93										
Aug-93		181070	590840	130490	443320	23030	167580	132	182726	1361260

3713 8469

Brake Pressure Switch Table:

DEFINITIONS:

Resistance Measurement #1 = Resistance reading between connector terminals (NC switch)

Resistance Measurement #2 = Resistance reading between sensor case and threaded fitting.

Resistance Measurement #3 = Resistance reading between both connector pins and sensor case.

Sensor Id Code	Date	Zig Code	Res. #1	Res. #2	Res. #3
PY754575	5-93	42521	0.2 Ohm	167.0 Ohms	Inf. Ohm
NY740208	6-92	53237	0.3 Ohm	0.3 Ohm	Inf. Ohm
PY688795	1-93	NA	0.3 Ohm	4.48 M Ohm	Inf. Ohm
PX629934	11-92	68302	0.2 Ohm	1.5 Ohms	Inf. Ohm
PY650225	10-92	72114	0.2 Ohm	1.7 Ohm	Inf. Ohm
PX638867	12-92	85333	0.3 Ohm	17 K Ohm	Inf. Ohm
PX665270	4-93	66689	0.3 Ohm	2.90 Ohm	Inf. Ohm
PX643515	12-92	43531	0.2 Ohm	0.4 Ohms	Inf. Ohm
PX623672	10-92	94145	0.2 Ohm	24 M Ohm	Inf. Ohm
PY695374	1-93	NA	0.2 Ohm	11.30 M Ohm	Inf. Ohm
NK758774	7-92	97199	0.2 Ohm	6.79 M Ohm	Inf. Ohm
BY639984	9-93	97199	0.2 Ohm	0.2 Ohm	Inf. Ohm
'Leading Sensor' VIN 2FALP71W1VX243573			0.4 Ohm	1.1 Ohms	4.80 M Ohms
New sensor #1			0.2 Ohm	0.4 Ohm	Inf. Resistance
New sensor #2			0.2 Ohm	1.1 Ohm	Inf. Resistance

Brake Pressure Switch Table:

DEFINITIONS:

Resistance Measurement #1 - Resistance reading between connector terminals (NC switch)

Resistance Measurement #2 - Resistance reading between sensor case and threaded fitting

Resistance Measurement #3 - Resistance reading between both connector pins and sensor case.

Sensor ID Code	Date	Zip Code	Res. #1	Res. #2	Res. #3
2MELM75W7NK762858	7-92	79164	0.4 Ohm	11.60 M Ohm	Inf. Ohm
ILNLM03W2FY774256	7-93	67549	0.4 Ohm	1.0 Ohm	Inf. Ohm
ILNLM02W8FY724043	3-93	71337	0.4 Ohm	3.5 Ohm	Inf. Ohm
ILNLM03W8FY628170	9-92	89087	0.4 Ohm	16 M Ohm	Inf. Ohm
ILNLM02W4FY632329	9-92	98349	0.5 Ohm	Inf. Ohm	Inf. Ohm
ILNLM02W0FY729611	3-93	47325	0.4 Ohm	111.9 Ohm	Inf. Ohm
2MECM74WXXC728439	4-92	86922	0.4 Ohm	6.80 Ohm	Inf. Ohm
2FALP74W4PX180223	3-93	69614	0.4 Ohm	3.2 Ohm	Inf. Ohm
2MELM74W4PX637766	12-92	58132	0.6 Ohm	Inf. Ohm	Inf. Ohm
ILNLM01W7FY669375	12-92	82224	0.4 Ohm	Inf. Ohm	Inf. Ohm
ILNLM02W8FY726066	3-93	91358	0.4 Ohm	Inf. Ohm	Inf. Ohm
ILNLM01W3FY727899	3-93	88135	0.4 Ohm	0.6 Ohm	Inf. Ohm

Sample	VIN	Page/Date Code	Condition	Findings			
				Heartport, Washer, Converter, and Spacer	Seals	Cup	Base/Switch Cavity/Terminals
Reddick (Memphis, 1993 Town Car)		F2VCI/2008	Partially burned.	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on bulb and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. All three Kapton seals are bubbled and exhibit brittle cracks which most likely formed leak path. Damage appears to have initiated in seal closest to washer. Damaged Kapton delaminated and embrittled by unknown mechanism.	Green Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.	Base separated below clamp ring. Transfer pin and movable contact missing. Stationary contact exhibits loss of material due to corrosion, evidence of pitting/corrosion, shows corrosion cracking. Base of movable contact melted back into bulkhead between switch and terminal cavities. Appears to have occurred in later stages of event. Surfaces of terminals covered with black and green deposits which appear to be sulfur compounds of the terminal materials.
A (1993 Town Car, Houston)		77792/281	Burned	Elements from contact material detected at filling end of heartport. Indicate possible flow of fluid back through seals. Traces of silicone detected.	Gasket and environmental seal missing. Charred fragments Kapton seals remain.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
B (1992 Town Car, Houston)		F2VCI/2114	Burned	Elements from contact material detected at filling end of heartport. Indicate possible flow of fluid back through seals.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Transfer pin and movable contact missing. Stationary contact exhibits crack in starter location as that in Reddick sample.
C (1992 Town Car, Houston)		F2VCI/2003	Burned	Elements from contact material detected at filling end of heartport. Indicate possible flow of fluid back through seals. Black deposit in cavity contains traces of hydrocarbon and silicone.	Gasket appears charred. Environmental seal missing. Damage to Kapton seals currently being evaluated.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
D (1987 Crown Victoria)		F2VCI/7777	Apparent leakage.	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on bulb and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Deposits appear to have formed a bridge between movable contact and cup. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Contacts appear intact. Dark green deposits on movable and stationary contacts contain elements from brass contact material. Terminals appear clean (no apparent deposits or corrosion).
E (#1 from survey)		F2VCI/2137	No leaks or other apparent problems.	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on bulb and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit delamination and bubbling similar to that found in Reddick sample. Cracking on surfaces suggest incipient damage is occurring.	Face of cup appears clean and dry.	Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
F		F2VCI/2128	Apparent leakage	Black residue containing glycol based material (probably brake fluid) and a metal coating. Indicates presence of brake fluid on bulb and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kapton seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Stationary contact is intact, but does show stress corrosion cracking in progress in bridge area (same location as in Reddick switch). Movable contact appears to have separated as a result of loss of material (~80% of thickness) due to corrosion. No evidence of heating or arc damage. Dark green deposits on movable and stationary contacts contain elements from brass contact material, as well as sulfur. Terminals exhibit green deposits (currently being analyzed). Deposits extend in from both sides of bulkhead between switch and terminal cavities, but do not meet.

Ford	Relocate to Pedal	ABS Switch (DPDT)	Pilot Relay + Drip Loop	Insulate from Prop Valve + Drip Loop + In-Line Fuse
Concept	21	28	18a + 28	24 + 28 + 22
Effectiveness Rank	1000	1000	360	320
Prevents Corrosion	10	10	4	5
Increase Path from B+ to Ground	10	10	10	8
Reduces Power In Switch	10	10	8	8
<u>Factors</u>				
Connector Seal	X	X		
Ingress of corrosives causes ground path				
Kapton Seal	X	X		
Ingress of corrosives causes ground path				
Continuous Power				
To ground circuit	X	X	X	XZ
To Load circuit	X	X	X	Z
Switch Orientation				
Internal path to ground	X	X	X	X
Susceptibility to fluid Ingress	X	X	Y	Y
Terminals form cell to ground	X	X	X	X
Current Capability	X	X	X	X
Grounded Hexport	X	X	X	X
Plastic Params				
Hot Wire Ignition	X	X		
Oxylic Acid	X	X		

Ford Concept

	12 Relocate to Ford	13 Jumper Switch Out	14 ABS Switch (OPDT)	15 Pilot Relay	16 Move to NGSC bed ground	17 Blank NGSC ground	18 Insulate from Prop Valve	19 Pins Down	20 On Member Cyl	21 RUN Circuit Power	22 GFI circuit	23 Negative TIC Device	24 In-Line Fuse	25 Boot	26 Drip Loop	
Effectiveness Rank	1000	1000	1000	270	210	180	32	28	25	12	8	8	8	4	4	
Prevents Corrosion	10	10	10	3	3	3	4	5	5	3	1	1	1	4	4	
Increase Path from B+ to Ground	10	10	10	10	10	10	8	5	6	1	1	1	1	1	1	
Reduces Power in Switch	70	10	10	9	7	6	1	1	1	4	8	8	8	1	1	
Factors																
Connector Seal Ingress of corrosives causes ground path	X	X	X					X	X							
Kapton Seal Ingress of corrosives causes ground path	X	X	X													
Conducts Power To ground circuit	X	X	X	X	X	X	X			X	X	X	X			
To Load circuit	X	X	X	X	X	X				X	X	X	X			
Switch Orientation Internal path to ground	X	X	X	X			X	X								
Susceptibility to fluid ingress	X	X	X					X						X	X	
Terminate force coil to ground	X	X	X	X			X	X								
Current Capability	X	X	X	X	X	X	X				X		X			
Grounded Hazard	X	X	X	X			X									
Plastic Params Hot Wire Ignition	X	X	X													
Oxalic Acid	X	X	X													

**Texas Inst
Concept**

	9 Transducer	11 Coat Arm	1 Coat Cup	2 Non-Conductive cup	10 Diaphragm b/wm cup & arm	4 Insulator b/wm Cup & arm	10 Thermal Link	13 Poring	6 Teflon Diech	6 Siding Seal	7 Converter Topology	16 4th Layer kepton	12 Gold Plate arm	16 Polarity	14 Neryl
Effectiveness Rank	64	24	24	24	24	6	8	7	5	6	5	5	4	3	1
Prevents Corrosion	3	4	3	3	3	1	1	7	3	6	5	5	4	1	1
Increase Path from B+ to Ground	3	5	3	3	3	3	1	1	1	1	1	1	1	3	1
Reduces Power in Switch	1	1	1	1	1	1	6	1	1	1	1	1	1	1	1

Factors

Connector Seal Ingress of corrosives causes ground path		X						X					X		
Kapton Seal Ingress of corrosives causes ground path	X	X			X				X	X	X	X			
Continuous Power To ground circuit	X	X	X	X	X	X	X								X
To Load circuit	X						X								
Switch Orientation Internal path to ground		X	X	X	X	X									
Susceptibility to fluid ingress		X													
Terminates from out to ground			X	X	X										
Current Capability							X								
Grounded Neutral		X	X	X	X	X								X	
Plastic Porams Hot Wire Ignition Cyclic Acid							X								X
															X

Relocate Deactivation Switch to Brake Pedal

#1

Effectiveness Rank	1000	none
Prevents Corrosion	10	
Increase Path from B+ to Ground	10	
Reduces Power In Switch	10	
Factors		
Connector Seal Ingress of corrosives causes ground path	X	Seal no longer needed
Kapton Seal Ingress of corrosives causes ground path	X	Seal no longer needed
Continuous Power		
To ground circuit	X	No ground inside new switch
To Load circuit	X	No corrosion of contacts to cause heating.
Switch Orientation		
Internal path to ground	X	No ground inside new switch
Susceptibility to fluid ingress	X	New switch oriented properly
Terminal leads call to ground	X	No ground inside new switch
Current Capability	X	No corrosion of contacts to cause heating.
Grounded Heqport	X	No Hydraulic interface.
Plastic Parts		
Hot Wire Ignition	X	No corrosion of contacts to cause heating.
Oxalic Acid	X	Not exposed to external cleaning agents
Manufacturing Study		
Service Study		
Part(s) Availability		
Customer Impact	10	Transparent to customer
Rank	10	

Use ABS Pedal Switch DPDT

26

Effectiveness Rank

1000

unknown

Prevents Corrosion

10

Removes SP switch from system

Increases Path from B+ to Ground

10

No ground paths in switch

Reduces Power In Switch

10

No more power thru SP switch.

Factors

Connector Seal

X

Ingress of corrosives causes ground path

Kapton Seal

X

Ingress of corrosives causes ground path

Continuous Power

To ground circuit

X

To Load circuit

X

Switch Orientation

Internal path to ground

X

Susceptibility to fluid ingress

X

Terminals form coil to ground

X

Current Capability

X

Grounded Haxport

X

Plastic Parasite

Hot Wire Ignition

X

Oxylic Acid

X

Manufacturing Study

Must ensure power in new switch does not create new problem.

Service Study

Part(s) Availability

Customer Impact

10

Technical Rank

Total Rank

10

3713 6477

Pilot Relay

18a

Effectiveness Rank	270	atomic
Prevents Corrosion	3	
Increase Path from B+ to Ground	10	
Reduces Power In Switch	9	

Factors

Connector Seal			Ground path current limited to relay control current.
Ingress of corrosives causes ground path			
Kapton Seal			Ground path current limited to relay control current.
Ingress of corrosives causes ground path			
Continuous Power			
To ground circuit	X		Ground path current limited to relay control current.
To Load circuit	X		
Switch Orientation			
Internal path to ground	X		Ground path current limited to relay control current
Susceptibility to fluid ingress			
Terminal form call to ground	X		
Current Capability		X	Ground path current limited to relay control current
Grounded Heatsink		X	Ground path current limited to relay control current.
Plastic Ferrules			
Hot Wire Ignition			
Crylic Acid			
Manufacturing Study			
Service Study			
Part(s) Availability			
Customer Impact	7		If switch shorts to ground the Secondary Speed Control Desc is not functional.
Rank	7		

3713 6478

Isolate Hexport from Ground

	24
Effectiveness Rank	32
Prevents Corrosion	4
Increase Path from B+ to Ground	8
Reduces Power in Circuit	1

Factors

Connector Seal Ingress of corrosives causes ground path		Ground path current limited to Speed Control Clutch current.
Kapton Seal Ingress of corrosives causes ground path		Ground path current limited to Speed Control Clutch current.
Continuous Power To ground circuit To Load circuit	X	Ground current leakage only thru Brake Fluid or Isolator Load circuit power is still continuous and may provide a heat source.
Switch Orientation Internal path to ground Susceptibility to fluid ingress Terminals form seal to ground	X	Ground current leakage only thru Brake Fluid or Isolator
	X	Ground current leakage only thru Brake Fluid or Isolator
Current Capability	X	Limits current to ground but not current thru contacts.
Grounded Hexport	X	Will only be grounded thru conductivity of Brake Fluid and Isolator
Plastic Parts Hot Wire Ignition Chytic Acid		
Manufacturing Study		
Service Study		
Part(s) Availability		
Customer Impact	10	Transparent to customer
Rank	10	

Add Drip loop to Harness at Switch

25

Effectiveness Rank

4

not applicable

Prevents Corrosion

4

Reduces but does not eliminate external fluid ingress only.

Increase Path from B+ to Ground

1

No Effect

Reduces Power in Switch

1

No Effect

Factors**Connector Seal**

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous PowerTo ground circuit
To Load circuit**Switch Orientation**Internal path to ground
Susceptibility to fluid ingress
Terminals form call to ground

X

Current Capability**Grounded Hexport****Plastic Parts**Hot Wire Ignition
Oxylic Acid**Manufacturing Study****Service Study****Part(s) Availability****Customer Impact**

10

Transparent to customer

Technical Rank

10

Total Rank

In-line Fuse between 15amp fuse and switch.

22

Effectiveness Rank	8	adequate
Prevents Corrosion	1	
Increase Path from B+ to Ground	1	
Reduces Power In Switch	8	Removes power if current reaches 1 Amp

Factors

Connector Seal

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit X
To Load circuit X

Switch Orientation

Internal path to ground
Susceptibility to fluid ingress
Terminals form call to ground

Current Capability

X

Grounded Hexport

Plastic Params

Hot Wire Ignition
Oxylo Acid

Manufacturing Study

1 Amp may still cause ignition

Service Study

Part(s) Availability

Customer Impact
Technical Rank
Total Rank

10 Transparent to customer
10

3713 6481

Boat

Add Boot to Harness at Switch

25

Effectiveness Rank

4

optimal

Prevents Corrosion

4

Reduces but does not eliminate ingress from Spill from above.

Increase Path from B+ to Ground

1

Reduces Power In Switch

1

Factors

Connector Seal

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit
To Load circuit

Switch Orientation

Internal path to ground
Susceptibility to fluid ingress
Terminals form cell to ground

X

Current Capability

Grounded Hezport

Plastic Params

Hot Wire Ignition
Oxylic Acid

Manufacturing Study

Service Study

Part(s) Availability

Customer Impact

10

Transparent to customer

Technical Rank

10

Total Rank

3713 6482

Reroute Power Source thru RUN circuit

23

Effectiveness Rank

12

relocate

Prevents Corrosion

3

Reduces time that coil is energized, but does not reduce amount of corrosives.

Increase Path from B+ to Ground

1

No Effect

Reduces Power in Switch

4

Removes power when key is off

Factors

Connector Seal

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit

X

To Load circuit

X

Switch Orientation

Internal path to ground

Susceptibility to fluid ingress

Terminals form coil to ground

Current Capability

Grounded Heepert

Plastic Parame

Hot Wire Ignition

Oxylic Acid

Manufacturing Study

Service Study

Part(s) Availability

Customer Impact

10

Transparent to customer

Technical Rank

Total Rank

10

Move Switch to Master Cylinder to Re-Orient Pins Down

28

Effectiveness Rank

25

rationale

Prevents Corrosion

5

Fluid now pools away from Spring arm. Corrosion can still cause circuit path resistance to increase.

Increase Path from B+ to Ground

6

Coastal starts and debris now collect away from ground

Reduces Power In Switch

1

Factors**Connector Seal**

X

Ingress of corrosives causes ground path

Kepton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit

To Load circuit

Switch Orientation

Internal path to ground

Susceptibility to fluid ingress

Terminal form cell to ground

Current Capability**Grounded Hexport****Plastic Parts**

Hot Wire Ignition

Oxylic Acid

Manufacturing Study**Service Study****Part(s) Availability****Customer Impact**

10

Transparent to customer

Technical Rank**Total Rank**

10

3713 GAB4

Turn Switch to Point Connector Pins Down

17

Effectiveness Rank	25	optimal
Prevents Corrosion	5	
Increase Path from B+ to Ground	5	
Reduces Power in Switch	1	
 Factors		
Connector Seal	X	Seal now needs to let fluid out.
Ingress of corrosives causes ground path		
Kepton Seal		Fluid now pools away from ground
Ingress of corrosives causes ground path		
Continuous Power		Fluid now pools away from ground
To ground circuit		Corrosion can still cause circuit path resistance to increase.
To Load circuit		
Switch Orientation		Contaminants and debris now collect away from ground
Internal path to ground		Fluids can now drain out
Susceptibility to fluid ingress		Contaminants and debris now collect away from ground
Terminate from out to ground		
Current Capability		Current limited to Speed Control Clutch current.
Grounded Hicport		Contaminants and debris now collect away from ground
Plastic Parts		Current limited to Speed Control Clutch current.
Hot Wire Ignition		
Oxylic Acid		
Manufacturing Study		
Service Study		
Part(s) Availability		
Customer Impact	10	Transparent to customer
Rank	10	

Move Switch to Ground circuit of Speed Control-Redesign

19a

Effectiveness Rank	216	<i>estimate</i>
Prevents Corrosion	3	
Increase Path from B+ to Ground	10	
Reduces Power in Switch	7	
 Factors		
Connector Seal		Ground path current limited to Speed Control Clutch current.
Ingress of corrosives causes ground path		
Kapton Seal		Ground path current limited to Speed Control Clutch current.
Ingress of corrosives causes ground path		
Continuous Power		
To ground circuit	X	Power only when Speed Control Engaged
To Load circuit	X	Power only when Speed Control Engaged
Switch Orientation		
Internal path to ground		Ground path current limited to Speed Control Clutch current.
Susceptibility to fluid Ingress		Only while Speed Control is engaged
Terminate from call to ground		
Current Capability	X	Ground path current limited to Speed Control Clutch current.
Grounded Heatport		Ground path current limited to Speed Control Clutch current.
Plastic Penetration		Ground path current limited to Speed Control Clutch current.
Hot Wire Ignition		
Oxylic Acid		
Manufacturing Study	-1000	Requires redesign of Speed Control, etc.
Service Study		
Part(s) Availability	10	
Customer Impact	7	If switch shorts to ground the Secondary Speed Control Diac is not functional.
Rank	-863	

3713 6486

Disconnect Speed Control Ground with Switch.

19

Effectiveness Rank	100	optimal
Prevents Corrosion	3	
Increase Path from B+ to Ground	10	
Reduces Power in Switch	6	

Factors

Connector Seal Ingress of corrosives causes ground path			Ground path current limited to Speed Control Clutch current.
Kepton Seal Ingress of corrosives causes ground path			Ground path current limited to Speed Control Clutch current.
Continuous Power			
To ground circuit	X		Power only when Speed Control Engaged
To Load circuit	X		Power only when Speed Control Engaged
Switch Orientation			
Internal path to ground			Ground path current limited to Speed Control Clutch current.
Susceptibility to fluid ingress			Only while Speed Control is engaged
Terminal form seal to ground			
Current Capability	X		Ground path current limited to Speed Control Clutch current.
Grounded Heupert			Ground path current limited to Speed Control Clutch current.
Plastic Params			
Hot Wire Ignition			Ground path current limited to Speed Control Clutch current.
Chytic Acid			
Manufacturing Study	10		
Service Study			
Part(s) Availability	10		
Customer Impact	-20		Speed Control will shut-off everytime brake is pressed.
Rank	-25		

Ground Fault Interrupter circuit

100

Effectiveness Rank	8	nitrate
Prevents Corrosion	1	
Increase Path from B+ to Ground	1	
Reduces Power In Switch	8	

Factors

Connector Seal			Sealing to prohibit contamination is no longer a factor if current is removed.
Ingress of corrosives causes ground path			
Kapton Seal			Sealing to prohibit contamination is no longer a factor if current is removed.
Ingress of corrosives causes ground path			
Continuous Power			
To ground circuit	X		Continuous power is removed if ground leakage current is detected.
To Load circuit	X		Load circuit power is still continuous and may provide a heat source.
Switch Orientation			Orientation for contamination is no longer an issue if power is removed.
Internal path to ground			Debris providing current path to ground is no longer an issue if power is removed.
Susceptibility to fluid Ingress			
Terminal form call to ground			
Current Capability	X		Limits current to ground but not current thru contacts.
Grounded Hazard			No longer a factor if current is removed.
Plastic Params			
Hot Wire Ignition			
Chrylic Acid			
Manufacturing Study			
Service Study			
Part(s) Availability	-1000		no parts identified
Customer Impact	10		Transparent to customer
Rank	-990		

Use Negative Temp Coef. Device to Blow Fuse

16

Effectiveness Rank	8	rationale
Prevents Corrosion	1	
Increase Path from B+ to Ground	1	
Reduces Power in Switch	8	

Factors

Connector Seal

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit
To Load circuit

X
X

Blows fuse when temp gets high enough. Trip tolerance questionable.
Blows fuse when temp gets high enough. Trip tolerance questionable.

Switch Orientation

Internal path to ground
Susceptibility to fluid ingress
Terminals form cell to ground

Blows fuse when temp gets high enough. Trip tolerance questionable.

Blows fuse when temp gets high enough. Trip tolerance questionable.

Current Capability

Blows fuse when temp gets high enough. Trip tolerance questionable.

Grounded Hexport

Not a factor after fuse blows.

Plastic Params

Hot Wire Ignition
Cyclic Acid

Not a factor if trip temp is low enough.
Not a factor if trip temp is low enough.

Manufacturing Study

Service Study

Part(s) Availability -1000

Customer Impact 10 Transparent to customer

Technical Risk

Total Rank -980

3713 6489

Short Circuit

Put Short circuit in place of Switch

27

Effectiveness Rank	1000	nitrocell
Prevents Corrosion	10	Remove BP switch from system
Increase Path from B+ to Ground	10	No ground paths in switch
Reduce Power In Switch	10	No more power thru BP switch.
 Factors		
Connector Seal Ingress of corrosives causes ground path	X	No longer a factor due to elimination of switch
Kapton Seal Ingress of corrosives causes ground path	X	No longer a factor due to elimination of switch
Continuous Power		
To ground circuit	X	No longer a factor due to elimination of switch
To Load circuit	X	No longer a factor due to elimination of switch
Switch Orientation		
Internal path to ground	X	No longer a factor due to elimination of switch
Susceptibility to fluid ingress	X	No longer a factor due to elimination of switch
Terminates form cell to ground	X	No longer a factor due to elimination of switch
Current Capability	X	No longer a factor due to elimination of switch
Grounded Heqport	X	No longer a factor due to elimination of switch
Plastic Parasite		
Hot Wire Ignition	X	No longer a factor due to elimination of switch
Oxylic Acid	X	No longer a factor due to elimination of switch
Manufacturing Study		
Service Study		
Part(s) Availability		
Customer Impact	-1000	Secondary Speed Control Deactivation disabled
Technical Rank		
Total Rank	-1000	

3713 6490

temp-linked

Concept

Factors

rationale

Connector Seal

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

Continuous Power

To ground circuit
To Load circuit

Switch Orientation

Internal path to ground
Susceptibility to fluid ingress
Terminals form cell to ground

Current Capability

Grounded Hexport

Plastic Params

Hot Wire Ignition
Oxylic Acid

Manufacturing Study

Service Study

Part(s) Availability

Customer Impact

Technical Rank

Total Rank

3713 6491

Add a 4th layer of Kapton to diaphragm

15

Effectiveness Rank

5

critical

Prevents Corrosion

5

May Lengthen life by preventing internal seals fluid leak but no effect on external leak.

Increase Path from B+ to Ground

1

No effect

Reduces Power In Switch

1

No effect

Factors**Connector Seal**

Ingress of corrosives causes ground path

Kapton Seal

Ingress of corrosives causes ground path

X

May improve life of diaphragm

Continuous PowerTo ground circuit
To Load circuit**Switch Orientation**Internal path to ground
Susceptibility to fluid ingress
Terminals form seal to ground**Current Capability****Grounded Heatsort****Plastic Frame**Hot Wire Ignition
Oxylic Acid**Manufacturing Study**

Feasibility Incomplete

Service Study**Part(s) Availability****Customer Impact**

10

Transparent to customer

Technical Rank**Total Rank**

10

Change Switch plastic to improve ignition parameters

14

Effectiveness Rank	1	none
Prevents Corrosion	1	No Effect
Increase Path from B+ to Ground	1	No Effect
Reduces Power In Switch	1	No Effect

Factors**Connector Seal**

Ingress of corrosives causes ground path

Kepton Seal

Ingress of corrosives causes ground path

Continuous PowerTo ground circuit
To Load circuit**Switch Orientation**Internal path to ground
Susceptibility to fluid ingress
Terminates form call to ground**Current Capability****Grounded Hexport****Plastic Param**Hot Wire Ignition
Oxytic AcidX
X

Raise temperature required for ignition

Manufacturing Study

10

Noryl already being used on other Ford vehicles

Service Study**Part(s) Availability****Customer Impact**

10

Transparent to customer

Technical Rank**Total Rank**

20

Fill Switch cavity with Potting to seal terminals

13

Effectiveness Rank	7	rationale
Prevents Corrosion	7	External Fluid Ingress stopped but not Internal brake fluid leak
Increase Path from B+ to Ground	1	No Effect
Reduce Power in Switch	1	No Effect

Factors

Connector Seal X
Ingress of corrosives causes ground path

Kapton Seal
Ingress of corrosives causes ground path

Continuous Power
To ground circuit
To Load circuit

Switch Orientation
Internal path to ground
Susceptibility to fluid ingress
Terminals form cell to ground

Current Capability**Grounded Heqport**

Plastic Parasite
Hot Wire Ignition
Oxylic Acid

Manufacturing Study Feasibility incomplete

Service Study**Part(s) Availability**

Customer Impact 10 Transparent to customer

Technical Rank

Total Rank 10

3713 8494

Gold Plate Spring Contact

	12	
Effectiveness Rank	4	rationale
Prevents Corrosion	4	Makes Spring Arm less susceptible to corrosion but not Rivet & terminals
Increase Path from B+ to Ground	1	No effect
Reduces Power in Switch	1	No effect

Factors

Connector Seal X
Ingress of corrosives causes ground path

Kapton Seal X
Ingress of corrosives causes ground path

Continuous Power
To ground circuit
To Load circuit

Switch Orientation
Internal path to ground
Susceptibility to fluid ingress
Terminal form cell to ground

Current Capability

Grounded Hexport

Plastic Parts
Hot Wire Ignition
Oxylic Acid

Manufacturing Study Feasibility incomplete

Service Study

Part(s) Availability

Customer Impact 10 Transparent to customer

Technical Rank

Total Rank 10

Insulate the Spring arm

	11	
Effectiveness Rank	24	critical
Prevents Corrosion	4	Makes Spring Arm less susceptible to corrosion but not Rivet & terminals
Increase Path from B+ to Ground	6	Reduces probability of short to ground
Reduces Power in Switch	1	No effect

Factors

Connector Seal	X
Ingress of corrosives causes ground path	
Kapton Seal	X
Ingress of corrosives causes ground path	
Continuous Power	
To ground circuit	X
To Load circuit	
Switch Orientation	
Internal path to ground	X
Susceptibility to fluid ingress	X
Terminals form cell to ground	
Current Capability	
Grounded Hazard	X
Plastic Parasite	
Hot Wire Ignition	
Oxylic Acid	
Manufacturing Study	
Service Study	
Part(s) Availability	
Customer Impact	10
Transparent to customer	
Technical Rank	
Total Rank	10