

EA02-025

FORD

10/27/03

BOOK 26 OF 61

PART 4 OF 4

BOX 23 OF 28

Summary of Chemical Properties

3/2/99

The following pages were supplied by Dupont and show chemical and physical properties for Teflon and Kapton. In summary, water will degrade the mechanical properties of Kapton, but Teflon is unaffected by water. This is the reason why the Teflon-Kapton-Teflon system was selected for Texas Instruments switch diaphragm (3 mil thick Kapton layer coated with 1 mil Teflon on both sides). Page 1 (marked with "A") indicates that the Teflon is non-reactive with water. While page 2 shows Teflon has a relatively low vapor transmission rate (marked with "B"). Page 3 shows how the mechanical properties of Kapton degrade with water and temperature exposure (marked with "C").

End of document.

Chemical Properties

DuPont FEP fluorocarbon film is chemically inert and solvent resistant to virtually all chemicals except molten alkali metals, fluorine at elevated temperatures, and certain complex halogenated compounds such as chlorine trifluoride at elevated temperatures and pressures.

In circumstances where end-use temperatures are close to the upper service limit 205°C (400°F), 80% sodium hydroxide, metal hydrides, aluminum chloride, ammonia, and certain amines (R-NH₂) may attack the film in a manner similar to molten alkali metals. Special testing is required when such extreme reducing or oxidizing conditions are evident.

With these exceptions noted, DuPont FEP fluorocarbon films exhibit a very broad range of chemical and thermal serviceability.

Due to the many complex aspects of performance in severe environments, final selection should be based on functional evaluations or experience under actual end-use conditions.

The chemical substances listed in Table I are representative of those with which DuPont FEP film has been found to be nonreactive.

Table I
Typical Chemicals with Which DuPont FEP Film is Nonreactive*

Abietic acid	Cyclohexanone	Hydrofluoric acid	Phthalic acid
Acetic acid	Diisopropyl phthalate	Hydrogen peroxide	Picric acid
Acetic anhydride	Dibutyl sebacate	Lead	Pipridine
Acetone	Diethyl carbonate	Magnesium chloride	Polymers (like)
Acetophenone	Diethyl ether	Mercury	Paracetamol acetate
Acrylic anhydride	Dimethyl formamide	Methyl ethyl ketone	Potassium hydroxide
Allyl acetate	Diisobutyl adipate	Metacrylic acid	Potassium
Allyl methacrylate	Dimethylformamide	Methanol	Formate
Aluminum chloride	Dimethylhydrazine, unsymmetrical	Methyl methacrylate	Pyridine
Ammonia, liquid	Glycerol	Naphthalene	Soda and detergents
Ammonium chloride	Ethyl acetate	Naphthol	Sodium hydroxide
Aniline	Ethyl alcohol	Nitric acid	Sodium hypochlorite
Benzonitrile	Ethyl ether	Nitrobenzene	Sodium peroxide
Benzoyl chloride	Ethyl hexanoate	2-Nitro-2-butanol	Solvents, aliphatic and aromatic**
Benzyl alcohol	Ethylene bromide	Nitromethane	Stearic acid
Borax	Ethylene glycol	Nitrogen tetroxide	Sulfur
Boric acid	Ferric chloride	2-Nitro-2-methyl propanol	Sulfuric acid
Bromine	Ferric phosphate	n-Octadecyl alcohol	Tetrahydrofuran
n-Butyl amine	Fluoranthracene	Oils, animal and vegetable	Tetrachloroethylene
Butyl acetate	Fluorobenzene	Ozone	Trichloroacetic acid
Butyl methacrylate	Formaldehyde	Pentachloroethylene	Trichloroethylene
Calcium chloride	Formic acid	Pentachloro- benzamide	Triethyl phosphate
Carbon disulfide	Purans	Perfluorocyclohexane	Triphenylamine
Cetane	Gasoline	Phenol	Vinyl methacrylate
Chlorine	Hexachlorobenzene	Phosphoric acid	Water
Chloroform	Hexane	Phosphorus pentachloride	Xylene
Chlorosulfonic acid	Hydrazine		Zinc chloride
Chromic acid	Hydrochloric acid		
Cyclohexane			

*Based on experiments conducted up to the boiling points of the liquids tested. FEP films have normal service temperature up to 205°C (400°F). Absence of a specific chemical does not mean that it is reactive with FEP film.

**Some hydrogenated solvents may cause moderate swelling.

TEFLON FEP

Physical Properties

Absorption

Almost all plastics absorb small quantities of certain materials with which they come in contact. Submicroscopic voids between polymer molecules provide space for the material absorbed without chemical reaction. This phenomenon is usually marked by a slight weight increase and sometimes by discoloration.

DuPont FEP fluorocarbon films have unusually low absorption compared with other thermoplastics. They absorb practically no common acids or bases at temperatures as high as 200°C (392°F) and exposure of up to one year. Even the absorption of solvents is extremely small. Weight increases are generally less than 1% when exposed at elevated temperatures for long periods. In general, aqueous solutions are absorbed very little by DuPont FEP film. Moisture absorption is typically less than 0.01% at ambient temperature and pressure.

Permeability


Many gases and vapors permeate FEP films at a much lower rate than for other thermoplastics (see Figure 13). In general, permeation increases with temperature, pressure, and surface contact area and decreases with increased film thickness. Table 6 lists rates at which various gases are transmitted through DuPont FEP fluorocarbon film, while Table 7 lists rates of vapor permeability for some representative substances. Note that the pressure for each material is its vapor pressure at the indicated temperature.

Table 6
Typical Gas Permeability Rates of DuPont FEP
Fluorocarbon Film, 25 μ m (1 mil) Thickness
(Test Method: ASTM D-1434 at 5°C (77°F))

Gas	Permeability Rate cm ³ /in ² ·s·atm
Carbon Dioxide	28.8×10^{-10}
Hydrogen	34.1×10^{-10}
Nitrogen	8.0×10^{-10}
Oxygen	11.8×10^{-10}

*To convert to cm³/100 in² (1 ft²)·day by 1.6548.

Figure 13. Water Vapor Transmission Rate of DuPont FEP Film at 5°C (41°F) to ASTM E-96 (Modified)




Notes: Values are average only and not for specification purposes. To convert the permeation values for 100 in² to those for 1 m², multiply by 15.5.

Table 7
Typical Vapor Transmission Rates of DuPont FEP Fluorocarbon Film, 25 μ m (1 mil) Thickness
(Test Method: Modified ASTM E-96)

Vapor	Temperature		Vapor Transmission Rate	
	°C	°F	SI Units g/m ² ·s	English Units (g/100 in ² ·d)
Acetic Acid	35	95	0.3	0.41
Acetone	35	95	14.7	0.95
Benzene	35	95	2.8	0.54
Carbon Tetrachloride	35	95	4.8	0.31
Ethyl Acetate	35	95	11.7	0.74
Ethyl Alcohol	35	95	19.7	0.09
Freon® F-12	23	73	372.0	27.0
Hexane	35	95	8.7	0.58
Hydrochloric Acid	25	77	<0.2	<0.01
Nitric Acid (Red Fuming)	25	77	180.0	10.8
Sodium Hydroxide, 50%	25	77	<0.2	<0.01
Sulfuric Acid, 98%	25	77	2×10^{-4}	1×10^{-4}
Water	25.5	100	7.6	0.40


Hydraulic Pressure Switch Cross Section



① Look for dirt & contaminants

Low Cost Automotive Hydraulic Line Mount Pressure Switches

TI's pressure switches provide low cost, on/off controls for many automotive systems. The snap action disc reacts to changing pressure by reversing its curvature and activating electrical switch contacts.




Key Features Include:

- Designed for underhood environment
- Low weight
- Custom packaging for specific application needs
- Automotive temperature range of -40 to 135°C
- Normally open and normally closed contact logic
- Industry proven since 1984

Typical Applications

- Power Steering Systems
- Cruise Control Systems
- Brake Systems
- Transmissions
- Suspension

Dimensions (typical examples, other styles available)






Technical Specifications

Electrical		Durability	
Supply Voltage	6 - 16 V	Cycle Life	
Supply Current	5 - 35 mA	Low/Mid Pressure Range	up to 5×10^6 cycles
Response Time ¹	10 ms maximum	High Pressure Range	up to 15×10^4 cycles
Environmental		Proof Pressure	1400 to 3000 psi
Operating Temperature	-40 to 135°C	Burst Pressure	
Full Scale Pressure Range		Low Pressure Range	7000 psi
Low Pressure Range	0 to 300 psi	Mid Pressure Range	4000 psi
Mid Pressure Range	0 to 800 psi	High Pressure Range	2500 psi
High Pressure Range	0 to 1600 psi		

¹Applicable on some devices

Pressure Switch Characteristics



For further information please write or call:

Texas Instruments Incorporated
Pressure Switch Marketing MS 23-01
P.O. Box 2564
Andover, MA 02703-0964
Phone 508 236-3510
Fax 508 236-1598

International Offices:

Japan
Texas Instruments Japan Ltd.
305 Tama-gakko, Oyama-cho
Saitama-City, Saitama-Ken 410-13
Oyama, Japan
Phone (81) 550-72-1211
Fax (81) 550-74-0391


Europe
Texas Instruments Holland B.V.
Automotive Marketing
P.O. Box 43
NL-7800 AA Almere
Holland
Phone (31) 546-879462
Fax (31) 546-864429

South America
Texas Instrumentos Eletrônicos do Brasil S/A
Rua Amélia de Melo, 648 - Taguaçu
Campinas - SP - Brazil
CEP 13090-901
Phone (55) 192-541146
Fax (55) 192-518023

Important Notice: Texas Instruments (TI) reserves the right to make changes to or to discontinue any product or service identified in this publication without notice. TI advises its customers to obtain the latest version of the relevant information to verify, before placing orders, that the information being relied upon is current.

Texas Instruments assumes no responsibility for infringement of patents or rights of others based on Texas Instruments applications assistance or product specifications since TI does not possess full access concerning the use or application of customers' products. TI also assumes no responsibility for customers' product designs.

151-3 COMPONENT LOCATION VIEWS



DESCRIPTION (Continued)


Item	Part Number	Description
1A	N610889-308	Screw
2	—	Actuator Cable Adjuster Fitting
3	9A826	Speed Control Actuator

(Continued)

Item	Part Number	Description
4	—	Accelerator Cable
5	9C735	Speed Control Servo
6	9C809	Speed Control Bracket Plate
A		Tighten to 3-4 Nm (27-35 Lb-in)

Deactivator Switch

The deactivator switch is a normally closed switch and replaces the vacuum dump valve as a redundant safety feature in the system. Normally when the brake pedal is depressed, an electrical signal from the brakelamp circuit to the speed control servo will disengage the system. Under increased brake pedal efforts (5-10 lbs, engine running), the deactivator switch mounted in the brake line will open and remove power to the speed control servo clutch, releasing the throttle independent of the speed control servo control. The deactivator switch is located at the rear brake proportioning valve (ABS brakes) or junction block (Non-ABS brakes) below the brake booster.



L7885-B

Vehicle Speed Sensor (VSS)

The vehicle speed sensor (VSS)(9E731) is mounted to the transmission.

OPERATION

System Activation

To operate the speed control system, the engine must be running and vehicle speed must be greater than 48 km/h (30 mph). The system is activated by pressing the ON switch in the steering wheel. Then the operator must depress and release the SET/ACCEL switch. Current speed will then be maintained until a new speed is set, the brake pedal is depressed or the OFF switch is depressed.

REMOVAL AND INSTALLATION (Continued)

3. Install three screws that retain the contact assembly and tighten to 2-3 N-m (18-26 lb-in). Remove tape from contact assembly.
4. Route the contact assembly harness down the column and connect to main wiring.
NOTE: If a new contact assembly is installed, remove the lock mechanism after assembly is secured to column.
5. Install steering column shroud.
6. Install lower trim panel.
7. Install tilt lever if equipped.
8. Position steering wheel on steering shaft and install new steering wheel retaining bolt. Tighten to 31-46 N-m (23-33 lb-ft).
NOTE: Route contact assembly wiring through steering wheel as wheel is being positioned.

9. Connect speed control/horn connector to clockspring contact assembly connector.
CAUTION: Make sure wires are positioned that no interference is encountered when installing air bag module.
10. Position air bag module on steering wheel and connect clockspring contact connector.
11. Install air bag module on wheel and install four air and washer assemblies. Tighten to 4-5.6 N-m (35-50 lb-in) for Town Car and 2.7-3.7 (24-32 lb-in) for Crown Victoria/Grand Marquis.
12. Connect battery ground cable and air bag back power supply. Refer to Section 01-20B.
13. Verify air bag warning indicator.

Deactivator Switch


Removal

1. Remove electrical connector from switch.
2. Unscrew switch and remove from brake proportioning valve or junction block.


Installation

1. Screw switch into proportioning valve or junction block. Tighten to 15-20 N-m (12-14 lb-ft).
2. Attach electrical connector.
3. Bleed brake lines as outlined in Section 08-09 ABS brakes, or Section 08-06, non-ABS brakes.

Proportioning Valve Location



L7084



Engineering Specification

PART NAME						PART NUMBER					
SWITCH ASSEMBLY - SPEED CONTROL DEACTIVATE						▽ ES-72V0-7F924-AA					
LET											
PR											
LET											
PR											
DATE	LET	PR	REVISIONS			OR	CK	REFERENCE			
			ADDED DATA TO COMPLETE SPEC. & RETYPED					PREPARED/ APPROVED BY			
9/11/80			NEOLEH00TJ779C02					R.J. PUGH JR. 9009 LG			
								DESIGNED BY			
								DETAILS BY			
								CONCURRENCE/APPROVAL SIGNATURES			
								DESIGN ENGINEERING SUPERVISOR			
								<i>R. J. Pugh Jr.</i> 9009 LG			
								DESIGN ENGINEERING MGT.			
								MANUFACTURING ENGNG.			
								QUALITY CONTROL			
								<i>H. F. Baggett</i>			
								SUPERVISOR QUALITY ASSISTANCE			
								<i>E. C. R.</i> 9009 LG			
								ELECTRONICS DIVISION			
								<i>W. D. S.</i> 9009 LG			

▽ CONTROL ITEM - THE ▽ SYMBOL ALSO IDENTIFIES PRODUCT ENGINEERING DESIGNATED CRITICAL CHARACTERISTICS. THESE AND ADDITIONAL CRITICAL CHARACTERISTICS IDENTIFIED BY PROCESS REVIEW MUST APPEAR ON THE Q-M CONTROL PLAN(S) WHICH REQUIRE PRODUCT ENGINEERING APPROVAL.

FRAME 1 OF 18
REV
▽ ES-72V0-7F924-AA

MAY 1964 PD 3947-81

Engineering Specification

SWITCH ASSEMBLY - SPEED CONTROL DEACTIVATE

I. General

This specification covers the test requirements for the speed control deactivate switch -9P924- used in the electronic speed control system. Design changes on the switch assembly or its components shall not be made without compliance to Section V of this specification and written approval from the releasing Production Engineering Office.

This engineering specification is a supplement to the released drawing on the above part, and all requirements herein must be met in addition to all other requirements of the part drawing. Minimum measures necessary for demonstrating compliance to these requirements are given in each section.

The engineering tests, sample sizes, and test frequencies contained within this engineering specification reflect the minimum requirements established to provide a regular evaluation of conformance to design intent. The engineering test program is intended as a supplement to normal material inspections, dimensional checking and in-process controls, and should in no way adversely influence other inspection operations.

Q1 suppliers may implement different test sample sizes and frequencies providing these changes have been included in an alternate Control Plan approved by the design responsible Product Engineering Office and concurred in by SQA.

II. PRODUCTION VALIDATION AND IN-PROCESS TESTS

- Production Validation (PV) Tests must be completed satisfactorily with parts from production tooling (and processes where possible) before ISIL approval and authorization for shipment of production parts can be effected. Parts must be revalidated completely, or per Section V whenever any change is made which could possibly affect part function or performance.
- In-Process Test Phase 1 (IP-1) - IP-1 tests are used to demonstrate process capability and must be completed using initial production parts from production tooling and processes prior to first production shipment approval. IP-1 tests are to continue in effect until process capability is demonstrated.
- In-Process Test Phase 2 (IP-2) - IP-2 test program may be implemented only after process capability has been established. Tests must be completed with production parts on a continuing basis. Samples for these tests must be selected on a random basis to represent the entire production population as much as possible. In the event that any of the requirements in these tests is not met, the reaction plan specified in Ford Q101 Sect. 3.5, "Engineering Specification (ES) Test Performance Requirements" shall be invoked.

2	18		▽ ES-F2VC-9P924-AA
FRAME	OF	REVISED	NUMBER

WV PD 3047-02 (Previous editions may not be used)


SECTION III. TABLE OF TESTS

Item	Test Name Functional Tests	PRODUCTION VALUATION		IN-PROCESS IP-1		IN-PROCESS IP-2	
		Minimum Sample Size	Statistical Test Acceptance Criteria	Minimum Sample Size	Statistical Test Acceptance Criteria	Minimum Sample Size	Statistical Test Acceptance Criteria
III.							
△	A Calibration	72	P90-.96	100%	All Must Pass	100%	All Must Pass
	B Voltage Drop	72	P90-.96	12/No.	P90-.84	4/Lot	" " "
	C Current Leakage	72	P90-.96	3/No.	P90-.56	4/Lot	" " "
	D Proof Test	72	P90-.96	12/No.	P90-.84	4/Lot	" " "
	F Solder	6	P90-.72	3/No.	P90-.56	4/Lot	" " "
	I Vibration	6	P90-.72	3/No.	P90-.56	6/5 No.	P90-.72
	J Terminal Strength	12	P90-.84	6/No.	P90-.72	4/Lot	All Must Pass
	K Vacuum	6	P90-.72	3/No.	P90-.56	6/5 No.	P90-.72
	L Temperature Cycle	6	P90-.72	3/No.	P90-.56	6/5 No.	P90-.72
	M Fluid Resistance	36	P90-.94	36/12No.	P90-.94	36/12No.	P90-.94
	<u>Durability Tests</u>						
III.							
	R Impulse	24	P90-.90	12/No.	P90-.84	3/3 No.	P90-.56
	Q Humidity	6	P90-.72	3/No.	P90-.56	6/6 No.	P90-.72
	H Salt Spray	6	P90-.72	3/No.	P90-.56	6/6 No.	P90-.72

NAME 3 OF 18
 PO 9047-12 (Previous editions may exist)
 REVISIONS
 △ IN-PROCESS-IP-1-1A

Engineering Specification

PRODUCTION VALIDATION FLOW CHART



FRAME	18	REVISED	YES-F2TC-9722A-AA
OF			NUMBER

PD 3947-82 (Previous edition may NOT be used)

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS

▽ A. Calibration

1. Test Requirements

- a. Switch calibration is to be checked at room temperature (16°C - 35°C) using ambient air or equivalent.
- b. Calibration settings shall be specified on the part drawing with the settings checked after 2 or more pressure cycles with ambient air, or equivalent. Pressure cycle range is to be determined by the manufacturer to insure switch calibration stability. The cut-in and differential set points are to be measured while conducting 750 ± 50 milliamperes while 13.0 ± 1.0 volts D.C. is applied. The cut-in point is to be checked with increasing pressure.
- c. The cut-out point is to be checked with decreasing pressure, and the differential set point is to be calculated using the cut-in pressure minus the cut-out pressure.

2. Acceptance Requirements

- a. Nonconformance is defined as any switch point which falls outside the tolerance band specified on the part drawing.

B. Voltage Drop

1. Test Requirements

- a. Voltage drop is to be measured after 2 or more cycles with ambient air or equivalent from 0 to $10,000 \pm 172$ KPa (1450 ± 25 PSI) while conducting 750 ± 50 milliamperes and 13.0 ± 1.0 volts D.C. is applied to the switch. Under these conditions with the switch closed the voltage drop is to be measured. Millivolt connection interface at terminals to be less than 10 millivolts.

2. Acceptance Requirements

- a. Nonconformance is defined as a voltage drop in excess of 200 millivolts.

5	18			▽ ES-F2VC-9F924-AA
FRAME	OF	REVISED		NUMBER

WAI PD 3947-a2 (Previous editions may apply in whole.)

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

G. Current Leakage

1. Test Requirements

- a. Current leakage is to be checked with 500 volts, 60 Hz alternating current.
- b. Current leakage is to be checked:
 - (1) Between the switch leads with the contacts open.
 - (2) Between the lead and the switch housing with contacts closed.
 - (3) Between either lead and switch housing with the contacts open.

2. Acceptance Requirements

- a. Nonconformance is defined as any leakage current in excess of one hundred (100) microamperes.

D. Proof Test

1. Test Requirements

- a. Subject sample switches to Section A to establish their initial switching pressures.
- b. Proof test is to be conducted using brake fluid or equivalent as the pressure medium. Test pressure shall be as specified on the part drawing. Test pressure shall be isolated from pressure source and held for not less than 30 seconds.
- c. Recheck the switches to Section A.

2. Acceptance Requirements

- a. No evidence of fluid leakage, seepage, or drop in test pressure greater than 430 KPa (62 PSI) is permitted.
- b. A change in cut-in and cut-out pressures greater than $\pm 5\%$ from the initial value is not permitted.
- c. The test samples must be destroyed after testing.

6	18		ES-F29C-97924-AA
FRAME	OF	REVISED	NUMBER

MAY PD 3947-22 (Previous editions may NOT be used)

3713 7261

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

E. Impulse

1. Test Requirements

- a. Test the switch for a total of 500,000 cycles.
Cycle pressure between (low) 0-276 KPa (0-40 psi)
and (high) 10,000 $\pm$ 345 KPa (1450 $\pm$ 50 psi).
 - 1) 0 - 475,000 cycles: 13 $\pm$ 1 volts, trace current to monitor function.
 - 2) 475,001 - 500,000 cycles: 13 $\pm$ 1 volts D.C., 750 $\pm$ 50 ma., per Figure 4.
- b. Brake fluid temperature to be 135 $\pm$ 14°C and ambient temperature to be 107°C min.
- c. Cycle rate is to be 110-130 cycles per minute.
- d. Switch must open and close each cycle.

2. Acceptance Requirements

- a. After impulse test check to sections A, B, C, & D using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, & D.
- c. Samples used for this test must be destroyed after all testing is completed.

F. Burst

1. Test Requirement

- a. Burst strength is to be checked using brake fluid or equivalent as the pressure medium.
- b. Pressurize the switch to 48.3 MPa (7000 PSI) minimum and hold for 30 seconds minimum.

2. Acceptance Requirements

- a. Nonconformance is defined as any evidence of fluid leakage or seepage from the switch or threads.
Samples used for this test must be destroyed after testing is completed.

7	18		RS-FIVC-9F924-AA
FRAME	OF	REVISED	NUMBER

MAY PD 3647-B2 (Previous versions may NOT be used)

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

G. Humidity

1. Test Requirements

- a. Mount the switch in the test port in a humidity chamber. Currently released mating electrical connector must be installed before start of test.
- b. Subject the switch to ten (10) continuous humidity cycles as follows:
 - (1) Raise temperature to $65 \pm 10/-2$ °C over 2.5 hours; at 90-98% relative humidity.
 - (2) Hold 3 hours at $65 \pm 10/-2$ °C at 90-98% relative humidity.
 - (3) Lower temperature to $25 \pm 10/-2$ °C over 2.5 hours; at 80-98% relative humidity.

2. Acceptance Requirements

- a. Within 15 minutes after completion of the tenth humidity cycle check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D.

H. Salt Spray

1. Test Requirements

- a. Mount the switch in the test port in a salt spray chamber. The currently released mating electrical connector and wiring must be installed prior to start of test.
- b. Expose the switch assembly to 72 hours of salt spray per ASTM B-117.

2. Acceptance Requirements

- a. After exposure, check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

6	18			ES-F2VC-97924-AA
FRAME	OF	REVISED		NUMBER

MAY 1964 PD 3947-a2 (Portion of Manual only NOT to copy)

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

I. Vibration

1. Test Requirements

- a. Mount the switch in the test port and attach the currently released mating electrical connector before start of test.
- b. Switches are to be vibrated in all 3 planes with electrical continuity being monitored during the entire test. See Figure 1 for switch orientation in the 3 planes. Vibration tests are to be conducted at room temperature using brake fluid, ambient air, or equivalent as the pressure medium.
- c. Internal pressure shall be maintained at 0 KPa G. when the switch is in the closed position and 1.1 times max actuation pressure shown on print when the switch is in the open position.
- d. Vibrate the switch at 1.5 mm displacement (peak-to-peak) while varying the frequency uniformly from 9 to 30 to 1 Hz over a 5 minute period.
- e. Vibrate the switch in alternate one-hour periods in the open and closed positions for a total of 8 hours in each plane. (Total test time is 24 hours).

2. Acceptance Requirements

- a. After the entire vibration sequence check the switches to sections A, B, C, or D using the procedure established in each section.
- b. Nonconformance is defined as any evidence of leakage or any change in electrical continuity/discontinuity during the vibration cycles, or any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

9	18			ES-F2VU-9P424-AA
FRAME	OF	REVISED		NUMBER

PO 3847-82 (Previous editions may NOT be used)

Engineering Specification

III. Test Procedures and Requirements (cont'd)

J. Terminal Strength

1. Test Requirements

- a. Mount the switch in the test port.

(1) Apply a 89 ± 9 N axial force to each terminal.

(2) With a pendulum apply a 43 ± 5 N impact force to the switch housing at the connector and, perpendicular to the centerline axis of the switch. See Figure 2 for force application point and direction.

2. Acceptance Requirements

- a. Check the switch to sections A, B, C, and D using the procedures established in each section.
- b. Nonconformance is defined as any terminal or housing fracture, or any switch not meeting the criteria in sections A, B, C, or D.

K. Vacuum

1. Test Requirements

- a. Mount the switch in the test port. Vacuum tests are to be conducted at room temperature using ambient air as the pressure medium.

b. Subject the switch to 5 cycles of vacuum from atmospheric pressure (760 mm Hg) to an absolute pressure of 3-5 mm Hg. Maintain the vacuum for a minimum of 60 seconds.

2. Acceptance Requirements

- a. Check the switch to sections A, B, C, and D using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, and D.

TO	18			ES-P2VC-9F92A-AA
FRAME	OF	REVISED		NUMBER

PD 3947-82 (Previous editions may not be used)

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

L. Temperature Cycle

1. Test Requirements

- a. Mount switches in test ports; test to be run using currently released brake fluid.
- b. Repeat the following procedure 25 times.
 - (1) Lower the switch and fluid temperature to at least -40°C .
 - (2) Cycle the switches ten times at 10 seconds/cycle. One cycle consists of a pressure variation from 0 - 276 KPa.G (0-40 psi) to $10,000 \pm 345$ KPa.G (1450 ± 50 PSI).
Note: Switch must open and close each cycle.
 - (3) Raise switch and fluid temperature to 38°C minimum.
 - (4) Repeat Step 2.
- c. At completion of Step b, check switches per sections A, B, C, and D.

2. Acceptance Requirements

- a. Nonperformance is defined as any evidence of switch fluid leakage, seepage, or not meeting the criteria of sections A, B, C, and D.

M. Fluid Resistance

1. Test Requirements

- a. Mount the switch in the test port and orient as installed in the vehicle.
- b. Install the currently released mating electrical connector (with wire leads) on the switch.
- c. Sequentially, immerse the switch into each of the specified fluids; at a temperature of $23 \pm 2^{\circ}\text{C}$, for 5 ± 1 second. Remove the switch and drain and store the switch for the specified time at room temperature, prior to immersing into the next fluid.

11	15			▽ ES-F29C-9792A-AA
FRAME	OF	REVISED		NUMBER

MAY 1982 PD 3947-82 previous editions may NOT be used

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

Fluid	Drain Time	Storage Time
Reference Fuel C ASTM D471	60 $\pm$ 5 min.	None
10W40 Engine Oil	24 $\pm$ 1 hour	14 days
Ethylene Glycol/ Water 50/50 by Volume	24 $\pm$ 1 hour	24 $\pm$ 1 hour
Brake Fluid DOT 3	24 $\pm$ 1 hour	48 $\pm$ 1 hour
Automatic Transmission/ Power Steering Fluid (same) ESP-M2GL32-GJ	24 $\pm$ 1 hour	14 days
Isopropyl Alcohol/ Water 50/50 by Volume	24 $\pm$ 1 hour	None
Reference Fuel C, ASTM D471 with Methyl Alcohol 85/15 by Volume	24 $\pm$ 1 hour	None

6. For the Flow Chart, subject the prescribed number of immersed switches to the post immersion tests specified below:

- III. E. Impulse
- III. G. Humidity
- III. H. Salt Spray
- III. J. Tensile Strength

Acceptance Requirements

- a. Switches must fully meet the requirements of the specified post immersion test.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, G, or D. Samples used for this test must be destroyed after all testing is completed.

12	14			33-FZVC-9P924-AA
FRAME	OF	REVISED		NUMBER

SAI PD 3947-82 (Previous editions may apply as noted)

Engineering Specification

IV. STATISTICAL ANALYSIS METHODS

- A. For FV, IP-1 and IP-2 tests, all samples tested must pass. Having all the required sample size pass will provide data to support the conclusion that the switch has a minimum reliability R, at a given confidence of G. The notation P_c-R is interpreted as minimum reliability equal to R, at a confidence G; thus P90-.80 means a minimum reliability of 80% at 90% confidence.
- B. All samples must pass in the statistical test acceptance criteria stated for tests with 100% frequency; or samples from lots which could have a variable size.

V. REVALIDATION REQUIREMENTS

- A. No change in design, material, process or component supplier shall be made without prior approval from the releasing Product Engineering Office. As part of approving a change, the releasing Product Engineering Office will establish the portion of the Product Validation tests required to be run to revalidate the switch. The following table is to be used as a guide in determining the type of tests required for revalidation requirements.

DESIGN CHANGE REVALIDATION

Component	Process or Material Change or New Supplier
1. Terminals, Contacts, or Connector	III, B, C, E, G, H, I, J, L, M.
2. Case or Housing	All Tests
3. Gasket or Diaphragm	III, A, D, E, F, I, K, L.
4. Fitting or Fluid Connection	III, D, E, F, H, I, M.
5. Annual revalidation is not required on carryover switches.	

VI. LOT DEFINITION

A lot is defined as no more than eight (8) hours of production up to 4,000 pieces. If shifts extend beyond eight (8) hours, or more than 4,000 pieces are produced in a shift, the product must be separated into at least two lots.

13	18			▽ 83-P2VC-9T924-AA
FRAME	OF	REVISED		NUMBER

HAZ PD 3947-B2 (Previous editions may NOT be used)

Engineering Specification

VII. RECORD RETENTION

- A. Recording and record retention shall conform with Ford Q-101.
- B. Production Validation test results and analysis are to be forwarded to the releasing Product Engineering Office before approval for shipment of production parts can be granted.
- C. In-Process test results shall be available at the supplier's manufacturing facility for the releasing Product Engineering Office and Ford SQA or its representatives to review on request.

VIII. INSTRUCTIONS AND NOTES

All switches are to be identified with the Ford part number, supplier identification, and a date code indicating final assembly.

All test equipment and test procedures for testing to this specification must be approved by the releasing Product Engineering Office and no change in equipment or procedure may be made without their written concurrence.

Test port configuration is shown in Figure 3.

O-rings, if used in the design, shall be free from cuts, nicks, abrasions or any other damage which would result in a fluid leak.

All switches must have a shipping cap installed over the port threads to prevent contamination. All shipping caps must be approved by the releasing Product Engineering Office prior to production incorporation.

All switches that do not pass the calibration test are to either be readjusted and rechecked, or scrapped. (Salvage of component parts permitted with 100% reinspection).

If product nonperformance occurs for test Sections III. B, C, D, E, F, and J, production shall be stopped and the problems corrected. All production lots shall be sorted 100% prior to shipment. Suspected nonperformance of any shipped parts shall be reported immediately to the releasing Product Engineering Office.

If nonperformance of the statistical acceptance criteria occurs for test Sections III. G, H, I, K, L and M, a cause to recall the subject weeks production and to stop production may result.

14	18			▽ ES-FIVC-9F924-AA
FRAME	OF	REVISED		NUMBER

MAX PD 3947-82 (Previous editions may NOT be used)

Engineering Specification

IX. COMPILATION OF REFERENCE DOCUMENTS

ASTM B-117, Salt Spray Testing

Ford Q-101, Quality System Standard - 1990 Edition


ES-FO2B-14A664-AA, Specification - SILV Assy - Wire Connector

ES-F2V7-9C713-AA, Specification - Servo Assembly Speed Control


FRAME	15	18	OF	REVISED	NUMBER	ES-F2VC-9F924-AA
-------	----	----	----	---------	--------	------------------

MAY 1982 PD 3947-B2 (Previous editions may NOT be used)

Engineering Specification



VIBRATION TEST - SWITCH ORIENTATION
FIGURE 1.




TERMINAL STRENGTH - LOAD ORIENTATION
FIGURE 2.

16	18			▽ 23-3270-9924-1A
FRAME	OF	REVISED		NUMBER

MAY 1966 PD 3947-22 (This form and blank form NOT be used)

Engineering Specification




TEST FIXTURE PORT CONFIGURATION

FIGURE 3

17	18			∇ EN-1200-51724-11
FRAME	OF	REVISED		NUMBER

MAY PD 3947-82 (Previous editions may NOT be used)

Engineering Specification



DEACTIVATE SWITCH
TEST SET UP

FIGURE 4

18	18			▽ 18-7270-9724-11
FRAME	OF	REVISED		NUMBER

NOT PD 3947-82 (Previous editions may NOT be used)

Lubricant Specifications

ITEM	CODE	ITEM NAME	FLUID SPECIFICATION
Wheels, Chocks and Tires	DP42-0004-AA	Multi-Purpose Grease	ESL-MC04-A
Brake Master Cylinder	DP42-0004-AA (ESL-MC04-A)	Red Heavy Duty Brake Fluid	ESL-MC04-A
Front Suspension, Ball joints and Steering Linkage	XS-C	Long Life Grease	ESL-MC04-A
Head Latch and Auxiliary Catches	DP42-0004-AA	Multi-Purpose Grease Spray	ESL-MC04-A
Lock Cylinders	DP42-0004-AA	Red Lock Lubricant	ESL-MC04-A
Door Hinges/Joints	DP42-0004-AA	Silicone Grease	ESL-MC04-A
Rear Axle Chaperonals and Traction-Lock (T)	XS-C or DP42-0004-AA	Fluorinax Rear Axle Lubricant	ESL-MC04-A
Power Steering (Pump Assembly)	XS-C	Motorcraft Auto Trans. Fluid - Type F	ESL-MC04-A
Automatic Overdrive Transmission (AOD)	XS-C	Motorcraft MERCON [®] Auto Trans. Fluid	MERCON [®]
Wiper Motor (TV) Linkage or Wiper Arm Linkage	XS-C	Long Life Grease	ESL-MC04-A
Engine Oil Filter (L.E. Engine)	FL42-0004-A (FL42)	Motorcraft Oil Filter Long Life Type	ESL-MC04-A
Engine Oil - Gasoline Engines	XS-C or XS-C	Motorcraft Motor Oil SAE 5W-30 Super Performance	ESL-MC04-A and API SAE
Engine Coolant	ESL-0004-AA	Red Cooling System Fluid	ESL-0004-A

(1) For Traction-Lock Axle Add a no. of DP42-0004-AA (ESL-MC04-A) to the list of items for complete list of items.

Maintenance Schedule and Record Log

General Maintenance	268
What Maintenance Schedule Do You Follow	269
Maintenance Schedule A	270
Maintenance Schedule B	272
Owner Maintenance Checks	274
Whenever you stop for fuel	274
While operating your vehicle	274
At least monthly	275
At least twice a year	275
At least once a year	276
Maintenance Services and Record Retention ..	277
Maintenance Record Log	277

Maximum Oil Change Interval...
 Schedule A: 3 months or 3,000 miles
 (4,800 km)
 Schedule B: 6 months or 7,500 miles
 (12,000 km) whichever occurs first. See
 appropriate Schedule.

PO TAIL
FAILURE MODE & EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 508788

Page 1

Revision Level C

Revision Date 4-Nov-88

Original (Initial) Date 20-Dec-83

System
Subsystem
X Component Program Switch

Design Responsibility Program Switch Group

Model Year(s)/Vehicle(s)/Version

Key Date 1983

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	C I S V	Potential Cause(s) Mechanism(s) of Failure	O C S F	Current Design Controls	D a t a P N	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Taken	S o l v e	O o f	D e f i n e	R. P. N.
BASE (PB) (48515) Provides a system of slots which guide, locate, and physically support terminals.	Fails to properly locate terminals.	Terminals out of position.	3	Incorrect dimensions and/or tolerances specified between slots and terminals. Inadequate stacking design concept.	1	Comparison with dimensions of similar STPS product.	1	3							
	Fails to properly guide the terminals during insertion.	Device will not assemble properly; yield loss in reg.	5	Incorrect dimensions and/or tolerances specified between slots and terminals. Insufficient lead-in.	1	Review with assembly equipment designers to determine correct clearances and lead in.	1	3							
	Fails to properly support the terminals.	Terminals move relative to each other or the base (such as under physical or thermal loadings).	5	Incorrect material specified. Excessively large dimensions specified on terminal slots.	1	Comparison with design of similar STPS product.	1	6							
Provides features to enhance the effectiveness of terminal stacking.	Terminal stacking is insufficient.	Loose terminals. Disturbance in switch assembly.	5	Incomplete understanding of design of stacking features.	1	Comparison with design of similar STPS product. Stacking evaluations.	1	6							
Provides a dielectric medium for the electrical elements.	Current leakage between terminals or terminal-to- base.	Inproper switching action.	5	Low insulation resistance. Incorrect material specified.	1	Comparison with design of similar STPS product. Material evaluation.	1	6							

3713 7276

POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 603766
Revision Level C
Revision Date 2-Nov-93
Original (Initial) Date 20-Dec-85

Page 2

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s)/Version _____

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Row Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D i s c r i m i n a t i o n	F l a t t e r n a t i v e	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r e	O c c u r r e n c e	D i s c r i m i n a t i o n	R P N	
6A26 (P6) (40313) Provides physical isolation of the switch components.	Fails to physically isolate ingress of fluid from external environment.	High current leakage. High oil/coolant drop. Erratic or insensitive switch action.	6		Incorrect material specified. Poor milled part design i.e. wall sections too thin, etc.	1	Comparison with design of similar 67P6 product. Design review with molder. Mold flow analysis.	1	5								
Provides a reference surface which locates the electrical elements relative to the pressure sensor.	Fails to properly locate the switch elements relative to the pressure sensor.	Shift in setpoints. Erratic or insensitive switch.	5		Warpage of the reference surface. Intrusion of other design elements into the plane of the reference surface. Excessive clearance specified between mating features.	1	Specification of flatness on print. Flatten this surface to prevent intrusion of other elements. Tolerance stackup analysis.	1	5								
Provides a flange to compress the internal environmental seal.	Improper compression of internal environmental seal.	Inadequate compression may lead to ingress of media. Excessive compression may prevent switch from seating correctly to sensor assembly.	7		Incorrect seal gland design. Warpage.	1	Review of standard gland design practice. Comparison to similar products. Flatness specified on print.	1	7								

3713 7277

ROYALTY
FAILURE MODE & EFFECTS ANALYSIS
(OEM/FAE/FMEA)

Document Number: 503789

Page 3

Revision Level: C

Revision Date: 4-Nov-88

System: _____
Subsystem: _____
Component: Pressure Switch

Design Responsibility: Pressure Switch Group

Original (Initial) Date: 85-Dec-88

Model Year(s)/Vehicle(s)/Version: _____

Key Date: 1988

Prepared By: G. Wagner

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Potential Failure Mode	Potential Effect(s) of Failure	S	I	C	Potential Cause(s) Mechanism(s) of Failure	O	Current Design Controls	D	R.	Recommended Action(s)	Responsibility & Target Completion Date	Action Request	S	O	D	R.
Function			Severity	Incidence	Consequence				Effect	P.			Task	Value	Cost	Time	P.
BASE (P8) (48515) Provides interference tube to locate and temporarily hold the base in relation to the crimp ring prior to crimp.	Tube is properly located prior to crimp.	Too large may cause difficulty in assembly, base cracking, or prevent switch from seating to sensor. Too small provides no effect; possibly affecting subsequent assembly operations.	5			Design of interference tube is insufficient.	1	Calculation and experimentation to determine limits of size. Tolerance stacking analysis.	1	5							
Provides a flange surface for the crimp ring.	Flange provides adequate geometry for crimp ring.	Base loose or insufficient torque withstand. Base cracked.	7			Incorrect design of flange for crimp ring.	1	Comparison with design of similar GTPS product.	1	7							
Provides lock tabs, keys, and features which mate to electrical connector.	Mating electrical connector doesn't fit properly.	Connector difficult to install. Connector falls off.	8			Connector geometry improperly specified.	1	Review of dimensions relative to mating connector parts.	1	8							
Provides compression to environmental seal in connector.	Mating connector seal is not properly compressed.	Seepage of water into switch cavity. Connector difficult to install and/or falls off.	7			Connector geometry and/or surface condition/finish is improperly specified. Incorrect material specified.	1	Review of dimensions relative to mating connector parts. Material evaluation.	1	7							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503789
Revision Level 0
Revision Date 28-Nov-90

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (WBS) Date 28-Dec-89

Model Year(s)/Vehicle(s) Year(s) _____

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	O c c u r r e n c e	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	B e n e f i t	O c c u r r e n c e	D e t e r i n i s t	R. P. N.
STATIONARY TERMINAL (20000 & 35729) Provide a brass blade for interconnection.	Poor interconnection.	Device appears oper- ational when connector installed.	7		Contamination of brass blade. Material specified too thin.	1	Review design and dimensions of wiring connector to assure proper interference and wiping action.	1	7							
	Blade geometry improper.	Difficult to install wiring connector.	8		Lead-in channels on terminal are insufficiently specified. Material specified too thick.	1	Review design and dimensions of wiring connector. Compare with design of similar 5718 product.	1	5							
Provide a silver layer surface for electrical contact	Fails to provide adequate electrical contact.	Device appears open- circuited. Intermittent continuity. High millivolt drop.	7		Incorrect contact material specified. Contamination. Silver layer specified too thin.	1	Review of TI proprietary and general contact design info. Eliminate paths for ingress of contamination.	1	7							
	Excessive loss of contact height dimension (mechanical loads).	Shift in set points over life.	7		Silver layer specified too thick.	1	Review of TI proprietary and general contact design info. J.D. Testing.	1	7							
	Erosion of contacts due to electrical loads.	Shift in set points over life. Intermittent or no continuity.	7		Incorrect material specified for particular electrical loading.	1	Review of TI proprietary and general contact design info. Review and testing with actual electrical loads.	1	7							

3718 7279

PO- TIAL
FAILURE MODE A EFFECTS ANALYSIS
(FMEA)

Document Number 603788

Page 2

Revision Level D

Revision Date 25-May-88

System
Subsystem
X Component Primitive Switch

Design Responsibility EGRESS Switch Group

Original (Initial) Date 20-Dec-83

Model Year(s)/Vehicle(s)/Variant(s)

Key Date 1983

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	F L P N	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Actions Taken	S e v e r e	O c c u r r e n c e	D e t e c t i o n	F L P N
STATIONARY TERMINAL (3064 & 3072) Provides feature for device calibration.	Poor calibration	Mfg. yield loss Shift in setpoints over life.	5		Design is excessively stiff. Design has excessive spring back. Material hardness is incorrectly specified. Initial position requires excess deformation to calibrate. Design has inadequate strength to maintain calibration over life.	1	Mechanical (finite FEA) analysis Force deflection springback testing Testing with actual production calibration equipment.	1	5							
Provides feature to ensure adequate sliding into base.	Terminal is inadequately seated into base.	Loose terminals. Short/circuit in switch setpoints.	7		Incomplete understanding of design of sliding features.	1	Comparison of design with similar STPS product. Sliding overlows.	1	7							
Provides feature which mate with slot in base for location of terminal.	Fails to properly locate terminal.	Terminal out of position.	5		Incorrect dimensions and/or tolerances specified between slot and terminal. Adequate sliding design concept.	3	Comparison of design with similar STPS product.	1	5							
Provides electrical path from silver brazing contact to mating connector.	Fails to provide adequate conductivity.	High resistance shown as high milivolt drop.	5		Incorrect material specified. Inadequate cross-section area.	1	Calculations of resistance. Testing.	1	5							

3713 7280

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503780
Revision Level C
Revision Date 4-Nov-98
Original (Initial) Date 28-Dec-95

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Variant _____

Key Date 1998

Prepared By C. Wagner

One Time Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Row Failure	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e s s	C l a s s i f i c a t i o n	Potential Cause(s) Mechanism(s) of Failure	D i s c o n f i r m a n c e	Current Design Controls	D e t e r m i n e	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Required				
												Action Taken	S e v e r e s s	C l a s s i f i c a t i o n	D i s c o n f i r m a n c e	R. P. N.
MOUNTABLE TERMINAL (30057)																
Provides a brass blade for interconnection.	Poor interconnection.	Device appears open- circuit when connector mated.	7		Material specified too thick.	1	Review design and dimensions of mating connector to ensure proper interference and mating action.	1	7							
	Blade geometry improper.	Difficult to install mating connector.	5		Lead-in chamfers on terminal are insufficiently specified. Material specified too thick.	1	Review design and dimensions of mating connector. Comparison with design of similar STPS product.	1	5							
Provides a mounting point for the spring via rivet.	Fails to allow proper spring/rivet installation.	Disturbance in switch actuation (noise, jitter). Inoperative device (rivet falls out completely). Mfg. yield loss.	7		Rivet hole size is specified incorrectly. Rivet hole position is specified incorrectly. Support surface for spring is incorrectly specified. Choice of fastener style incorrect.	1	Comparison with design of similar products. Check with recommendations of rivet manufacturer. Testing.	1	7							
Provides features to ensure adequate sliding into base.	Terminal is inadequately slotted into base.	Loose terminal. Disturbance in switch actuation.	7		Incomplete understanding of design of sliding features.	1	Comparison of design with similar STPS product. Sliding experiments.	1	7							

3713 7281

PC¹ TIAL
FAILURE MODE & EFFECTS ANALYSIS
(DESKTOP FMEA)

Document Number 503780
Revision Level G
Revision Date 4-Nov-88
Original (Initial) Date 20-Dec-85

Page 2

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1988

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item	Potential Failure Mode	Potential Effect(s) of Failure	S	D	Potential Cause(s) Mechanism(s) of Failure	O	Current Design Controls	D	R	Recommended Action(s)	Responsibility & Target Completion Date	Action Results	S	O	D	R
Function			v	e		u		e	P.			Actions Taken	v	e	i	P.
MOVABLE TERMINAL (30067)																
Provides features which mate with slots in base for location of terminal.	Fails to properly locate terminal.	Terminal out of position.	3		Incorrect dimensions and/or tolerances specified between slots and terminals. Inadequate mating design concept.	3	Comparison of design with similar STPG product.	1	9							
Provides electrical path from movable contact via spring to mating connector.	Fails to provide adequate conductivity.	High resistance shown as high voltage drop.	5		Incorrect material specified. Inadequate cross-sectional area.	1	Calculations of resistance Testing	1	5							

3713 7282

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503792
Revision Level 0
Revision Date 4-Nov-85
Original (Initial) Date 20-Dec-85

Page 1

System _____
Subsystem _____
X Component Transfer Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s)/Version _____

Key Date 1985

Prepared By C. Wagner

Core Team Design Engineers, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C r i t i c i t y	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e d	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results Taken	R e v	O c c	D e t	R. P. N.	
SPRING (2244) Provides contact force.	Low contact force.	High millivolt drop across contacts.	5		Incorrect geometry specified. Incorrect material specified.	3	Beam deflection specimens. Force/deflection testing.	1	15								
	High contact force.	SWR in setpoints. Disc cracking over life.	7		Incorrect geometry specified. Incorrect material specified.	3	Beam deflection specimens. Force/deflection testing.	1	21								
Provides electrical path from movable contact to movable terminal.	Fails to provide adequate conductivity.	High resistance shown as high millivolt drop.	5		Incorrect material specified. Inadequate connection area.	1	Calculations of resistance using $R = \frac{\rho(L)}{A}$ Testing	1	5								
Provides tension to interface with transfer pin.	Fails to interface correctly with transfer pin.	Spring failure over life. Shift in setpoints over life. Sliding transfer pin causes intermittent operation.	7		Inadequate height of feature specified. Inadequate shape of feature specified. Improper position of feature specified.	1	Comparison of design with similar product. Dimension and tolerance stackup analysis. Actual measurement. Testing	1	7								
Provides tension for attachment to movable contact.	Fails to provide adequate mounting for movable contact.	Intermittent or erratic operation Open circuit.	6		Hole size/position incorrectly specified. Fit/force inadequate.	1	Fit/force recommendations. Comparison of design with similar product. Testing.	1	6								
Locates movable contact.	Fails to adequately locate movable contact relative to stationary contact.	High millivolt drop over life. Excessive contact erosion over life.	7		Spring geometry incorrectly specified.	1	Dimension and tolerance stackup analysis. Testing	1	7								

3719 7283

POTENTIAL
FAILURE MODE & EFFECTS ANALYSIS
(DESBM FMEA)

Document Number 503792
Revision Level 0
Revision Date 4-Nov-88
Original (Initial) Date 20-Dec-88

Page 2

System
Subsystem
☒ Component Pressure Switch
Model Year(s)/Vehicle(s)/Version

Design Responsibility Pressure Switch Group

Key Date 1988

Prepared By G. Warner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item	Potential Failure Mode	Potential Effect(s) of Failure	S	O	Potential Cause(s) Mechanism(s) of Failure	O	Current Design Controls	D	PL	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S	O	D	PL
Function			v	e		c		e	P.				v	c	1	N.
SP-1542 (20000)	Provides feature for attachment to movable terminal.	Erratic or intermittent operation. Shift in setpoints. Open or short circuit.	6	1	Rivet hole size or position incorrectly specified. Fitment inadequate. Choice of fastener style incorrect.	1	Rivet mfg. recommendations. Comparison of design with similar product. Testing.	1	1							
Allows disc overtravel.	Fails to allow disc overtravel.	Shift in setpoints. Disc cracking. Device inoperative at assembly. Poor calibration.	5	1	Incorrect geometry specified. Incorrect material specified.	3	Bears deflection equations. Force/deflection testing.	1	1							
Provides force to open contacts.	Inadequate force to open contacts.	Insufficient resistance to mechanical vibration. Short circuit.	6	1	Incorrect geometry specified. Incorrect material specified.	1	Bears deflection equations. Force/deflection testing.	1	1							
	Excessive force to open contacts.	Shift in setpoints. Disc cracking. Device inoperative at assembly. Poor calibration.	7	1	Incorrect geometry specified. Incorrect material specified.	3	Bears deflection equations. Force/deflection testing.	1	21							

3718 7284

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 502794

Page 1

Revision Level C

Revision Date 4-Nov-99

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Process Switch Group

Original (Initial) Date 21-Dec-99

Model Year(s)/Vehicle(s) Various

Key Date 1999

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e s s	C a u s e s	P o t e n t i a l C a u s e(s) Mechanism(s) of Failure	O c c u r r e n c e	C u r r e n t D e s i g n C o n t r o l s	D e t e c t i o n	R e c o m m e n d e d A c t i o n(s)	Responsibility & Target Completion Date	Action Results				
											Actions Taken	S e v e r e s s	O c c u r r e n c e	D e t e c t i o n	R e s p o n s i b i l i t y
343821 (74383) Provides fluid and pressure transport and displacement.	Fails to provide adequate fluid seal.	Seals fluid leakage.	2		Insufficient compression specified. Very excessive compression specified, leading to displacement from gland. Incorrect ID and/or OD leading to displacement from gland. Incorrect cross-section shape specified. Incorrect material specified; fluid incompatibility. Incorrect design of sealing mechanism.	1	Review of general seal design principles. Manufacturer's recommendations. Burst, impulse, and thermal cycle tests. Comparison with design of similar products.	1	9						

3713 7285

PRELIMINARY
FAILURE MODE EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503245

Page 1

Revision Level C

Revision Date 4-Nov-85

Original (Initial) Date 30-Dec-83

System
Subsystems
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s)/Version(s)

Key Date 1983

Prepared By C. Wagner

Cow Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effects of Failure	S e v e r e n e s s	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t a b i l i t y	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r e n e s s	O c c u r r e n c e	D e t e c t a b i l i t y	R. P. N.
CLIP (27718 OR 27288) Provides crimpable area which holds pressure sensor together.	Fail to provide a suitable geometry for crimp.	Leakage Low burst	8		Crimp wall thickness incorrectly specified. Crimp wall height incorrectly specified. Incorrect material specified.	1	Burst and leakage testing. Comparison of design with similar product.	1	8							
Locates heater, diaphragm, and washer.	Fail to correctly locate heater, diaphragm, or washer.	Difficult assembly.	5		I.D. specified incorrectly.	1	Tolerance stackup analysis.	1	5							
Provides support and location for disc.	Fail to support and locate the disc/corvette correctly.	Shift in setpoints. Erratic operation. Stack open at assembly. Reduced disc life.	7		Incorrect disc envelope specified. Bump into position incorrectly specified. Poor surface condition of bump, so control specified.	1	Tolerance stackup analysis. Impact testing.	1	7							
Provides guide for heater pin.	Fail to guide heater pin correctly.	Erratic operation. Device stuck short-circuit.	7		Pin guide geometry is incorrectly specified.	1	Tolerance stackup analysis.	1	7							
Provides portion of environmental seal gland.	Fail to allow a proper environmental seal.	Ingress of matter. Switch does not seal correctly to cap.	7		Surface condition required for good seal so understood or not correctly specified. Geometry incorrectly specified.	1	Environmental testing. Switch cavity pressurization testing. Review of standard gland design rules.	1	7							

3713 7286

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 821789

Page 2

Revision Level C

Revision Date 4-Nov-88

Original (Initial) Date 25-Dec-88

System _____
Subsystem _____
X Component Passive Switch

Design Responsibility Passive Switch Group

Model Year(s)/Vehicle(s)/Variation _____

Key Date 1988

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e d	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e r m i n e d
CUP 02713 OR 07209 Provide surface to interface with base/switch assembly.	Fails to properly locate relative to switch.	Shift in sequence. Erratic or inoperative switch.	5		Incorrect geometry of mating surface specified.	1	Tolerance stacking analysis. Cross-section sectioned device for inspection of interface.	1	5						
(Post-assembly check) provides geometry for final assembly with wrap ring.	Fails to allow proper final assembly with wrap ring.	Erratic operation. Ingress of matter. Coated base.	7		Post-assembly geometry is not controlled per design intent. Gap diameter incorrectly specified.	1	Tolerance stacking analysis. Bore torque testing.	1	7						

3719 7287

P
ITAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503786
Revision Level D
Revision Date 4-Nov-88
Original (with) Date 20-Dec-88

Page 1

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s) Various

Key Date 1988

Prepared By C. Wagner

Does Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	B v e n u e	C i n c i d e n t	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	C u r r e n t D e s i g n C o n t r o l s	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r e	O o b s e r v e d	D e t e c t e d	R. P. N.
DIAPHRAGM (OR SEAL) (BT) (74174) Forms flexible element of fluid containment assembly.	Fails to contain fluid.	Fluid leakage.	9		Gradual rupture over life due to improper design of supporting elements. Gradual rupture over life due to excessive flexure/displacement. Gradual rupture over life due to stress concentrations caused by supersonic strain disturbances. Chemical attack due to incorrect material specified. Incorrect thickness (or # of layers) of diaphragm material. Insufficient location/clamping of diaphragm.	1	Burst, impulse, and thermal cycle tests. Mechanical imp. reconstruction. Comparison of design with similar products.	1	2							
Transfer pressure from fluid to pressure- sensing elements.	Change in area of pressure transfer over life. Excessive change of pressure transfer area versus pressure.	Shift in setpoints over life. Excessively high pressure needed to adequately form pressure transfer area; wide spread on setpoints due to unpredictability at lower pressures.	5		Diaphragm too stiff. Incorrect material specified.	1	Life testing w/ characteristics of intermediate points.	1	5							
			9		Diaphragm too stiff. Incorrect material specified.	1	Force and pressure versus deflection leading to calculate effective areas.	1	8							

3713 7288

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 602787
Revision Level C
Revision Date 4-Nov-88

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-83

Model Year(s)/Vehicle(s)/Version _____

Key Date 1989

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e d	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Plan(s)				
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e r m i n e d	P. N.
WASHER (F8) (17038) Provides a portion of the support surface for diaphragm.	Failure to correctly support the diaphragm.	Reduced diaphragm life results in leakage.	8	1	Condition of diaphragm support surface are specified incorrectly. Condition of edges of support surface specified incorrectly. Clearance between washer I.D. and converter bump is specified too small.	1	Burst, impulse, and Thermal Cycle tests. Comparison of design with similar products.	1	6							
Provides support for compression of piston.	Failure to allow proper piston compression.	Leakage.	8	1	Washer thickness is incorrectly specified or unspecified. Washer thickness is specified too small. Washer material and/or heat-treat is incorrectly specified.	1	Burst, impulse, and Thermal Cycle tests. Comparison of design with similar products.	1	6							
Locates and guides converter with respect to cup.	Converter is not properly located relative to cup.	Shift in setpoints. Erratic behavior.	5	1	Incorrectly specified bush ID. Incorrectly specified washer O.D.	1	Comparison of design with similar products. Tolerance stackup analysis.	1	5							
	Converter travel is restricted by washer.	Discontinuous release; device is stuck open- closed.	7	1	Washer thickness is incorrectly specified or unspecified. Washer thickness is specified too small. Washer material and/or heat-treat is incorrectly specified. I.D. of bush guide is too small.	1	Burst, impulse, and Thermal Cycle tests. Comparison of design with similar products. Tolerance stackup analysis.	1	7							

3713 7289

POTENTIAL
FAILURE MODES & EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 003787

Page 2

Revision Level C

Revision Date 4-Nov-88

System
Subsystem
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-81

Model Year(s) Vehicle(s) Year(s)

Key Date 1982

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e r v i c e	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t a b i l i t y	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Priority	S e v e r e n e s s	O c c u r r e n c e	D e t e c t a b i l i t y	R. P. N.
WASHER (F8) (27000) Interface with cup feature and provides a portion of component seal for clamp.	Fails to interface correctly with cup.	Difficult assembly (washer O.D. too large). Poor wash/vertical location relative to cup (washer O.D. too small).	7		Washer O.D. specified incorrectly.	1	Comparison of design with similar products. Tolerance stackup analysis.	1	7							
	Fails to allow proper clamp.	Reduced burst capability leads to leakage. Reduced fatigue resistance leads to leakage.	8		Thickness incorrectly specified. O.D. incorrectly specified. Edge condition incorrectly or unspecified.	1	Tolerance stackup analysis. Burst, Impact, and Thermal Cycle tests.	1	8							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503788
Revision Level E
Revision Date 13-May-95

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-93

Model Year(s)/Vehicle(s)/Version _____

Key Date 1993

Prepared By D/Hs

Core Team: Design Engineers, Manufacturing Engineers, Manufacturing, Quality

Item / Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e r m i n e	R e l i a b i l i t y	Recommended Action(s)	Responsibility & Target Completion Date	Action Results					
												Actions Taken	S e v e r i t y	O c c u r r e n c e	D e t e r m i n e	R e l i a b i l i t y	
CONVERTER (P8) (27408) Transfer pressure from field (via diaphragm) to a force on pressure-sensing disc.	Fail to correctly transfer fluid pressure to force on disc.	Shift in setpoint	5		Bolton O.D. incorrectly specified relative to washer I.D. Converter major O.D. incorrectly specified relative to cup I.D. Converter thickness incorrectly specified. Incorrect material specified.	1	Tolerance stackup analysis. Force/deflection analysis to determine strength and resistance to plastic deformation. Burst, rupture, and Thermal cycle tests.	1	5								
Provide alignment and support to disc.	Fail to properly align and support disc.	Excess tolerances allow misalignment which may cause shift in setpoint or erratic operation. Disc not in place relative to converter may cause erratic operation or inoperative device, check open-circuit.	5		Bolton O.D. incorrectly specified relative to washer I.D. Converter major O.D. incorrectly specified relative to cup I.D. Disc support bump incorrectly specified. Disc retaining wall incorrectly specified.	1	Tolerance stackup analysis. Comparison of design with similar product.	1	5								

3713 7291

F VTAL
FAILURE MODE EFFECTS ANALYSIS
(DEMON PMEA)

Document Number 503786

Page 2

Revision Level E

Revision Date 13-May-98

System
Subsystem
X Component Process Switch

Design Responsibility Program Switch Group

Original (Initial) Date 20-Dec-93

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By DJH

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t a b i l i t y	R. P. M.	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t a b i l i t y	R. P. M.
CONVERTER (Pg 27-406) Provides a portion of the support surface for diaphragm.	Fails to properly support diaphragm.	Reduced diaphragm life results in leakage.	3		Contours of surface in contact with diaphragm are specified incorrectly. Condition of edges in contact with diaphragm are specified incorrectly. Clearance between converter bump and sealer I.D. are specified too wide.	1	Burst, impact, and Thermal cycle tests. Comparison of design with similar product.	1	5							
Provides disc support during over pressure (proofburst).	Fails to properly support disc during over pressure.	Disc deformation results in shift in setpoints. Reduced disc travel if disc motion is restricted prematurely. Reduced disc life.	4		Features which control disc motion during over pressure are incorrectly specified.	3	Pre-and post-proof characterization. Pressure-deflection measurements of disc motion.	1	10							
Used in converter prevents pressure building from exceeding setpoints.	Does not vent properly.	Shift in setpoints over temp. Reduced disc usage.	3		Vent hole incorrectly specified.	1	Comparison of design with similar product. Temperature characterization.	1	5							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 803780
Revision Level 0
Revision Date 4-May-95
Original (Initial) Date 25-Dec-95

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Prepared By C. W. 288

Model Year(s)/Vehicle(s) Variant _____

Key Date 1995

Core Team Design Engineers, Manufacturing Engineering, Manufacturing Quality

Rev. Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e n e s s	C r i t i c i t y	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r e n e s s	D e t e c t i o n	D i a g n o s t i c	R. P. N.
SPACER (72852) Reduce friction between disc and coverplate	Fails to effectively reduce friction.	Shift in sealpoints over life. Reduced disc life.	5		Incorrect material specified. Incorrect dimensions specified.	1	Inputs and Thermal Cycle tests. Pre- and Post-life characterizations. Tolerance stackup analysis.	1	5							
Allow venting of chamber formed by disc and coverplate.	Fails to allow venting.	Shift in sealpoints over temp. Reduced disc action.	5		Vent hole incorrectly specified.	1	Comparison of design with similar product. Temperature characterization.	1	5							

P ITAL
FAILURE MODE & EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 503800
Revision Level C
Revision Date 4-Nov-85
Original (Initial) Date 29-Dec-85

Page 1

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s)/Version _____

Key Date 1985

Prepared By G. Wiegner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r e	O c c u r r e n c e	D e t e c t i o n	R. P. N.
DISC (switch) Controls activation and release set- points of switch relative to applied force.	Fails to activate and/or release at the proper points of assembly.	Mfg. yield loss.	5		Disc material improperly specified. Dimensions and tolerances improperly specified.	1	Characterization aspects. Comparison of design with similar product.	1	5							
Key component in circuiting usable service life of device.	Disc activation and/or release setpoints change excessively over life.	Shift in device setpoints over life.	5		Disc material improperly specified. Disc heat-treat improperly specified. Material thickness improperly specified. Excessive force applied by spring.	1	Impulse testing. Pre- and post- characterizations.	1	5							
	Service life shorter than customer requirements.	Dynamic shift in setpoints over life. Device inoperative - open circuit.	7		Disc material improperly specified. Disc heat-treat improperly specified. Material thickness improperly specified. Excessive force applied by spring.	1	Impulse testing. Pre- and post- characterizations.	1	7							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DFMEA)**

Document Number 609901

Page 1

Revision Level C

Revision Date 4-Nov-88

System

Subsystem

X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Date) Date 20-Dec-85

Model Year(s)/Vehicle(s) Various

Key Date 1993

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S v	O f F	Potential Cause(s) Mechanism(s) of Failure	O f F	Current Design Controls	D e t e r m i n e d F r e q u e n c y	R e c o m m e n d e d A c t i o n (s)	Responsibility & Target Completion Date	Action Results				
											Action Taken	S v	O f F	D e t e r m i n e d F r e q u e n c y	R e c o m m e n d e d A c t i o n (s)
CRIMP (WHS 74787) Hold together base assembly and sensor assembly.	Fails to hold base to sensor correctly.	Erratic switch operation. Cracked base. Shift to setpoints. Low base torque withstand.	5		Incorrect geometry of crimpable area specified. Incorrect geometry at formed rail. Incorrect material specified.	3	Inspection, thermal cycle, base torque, and tensile/rail impact tests.	1	15						
Provide a surface for part identification/date code.	ID character flaking.	Improperly identified parts at assembly plant.	2		Geometry/finish not properly specified. Wrong material specified.	1	Coding tests. Environmental tests.	1	2						
Support environmental protection and weathering in service.	Inability to withstand environment.	Corrosion causes material compression, loss of mechanical properties, switch eventually fails off sensor. Flaking coding.	7		Wrong material specified.	1	Environmental tests.	1	7						
Provide information to keep clear via WHS coding.	Insufficient information.	Missed base/parties on external device various.	6		Incorrect or insufficient war specified.	1	Crimping tests.	1	6						

PC TIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN AREA)

Document Number 508802
Revision Level C
Revision Date 4-Nov-95

Page 1

System
Subsystem
K Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-93

Model Year(s)/Vehicle(s) Valios

Key Date 1995

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Control Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R. P. N.
TRANSFER PIN (74071)	Transfer disc motion to movable electrical contact	Contacts stuck open. Contacts stuck closed. Erratic operation.	7		Dimension incorrectly specified. Chips/debris cause pin to lodge.	1	Tolerances overlap between pin and pin guide in cap. Check with supplier for material properties regarding chips.	1	7							
Transfer disc motion to movable electrical contact	Failure to insulate.	Continuity between movable terminal and housing to ground.	5		Wrong material specified.	1	Check with supplier for material properties. Check with customer for electrical logic of movable terminal.	1	6							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503809
Revision Level C
Revision Date 4-Nov-88
Original (Failure) Date 20-Dec-88

Page 1

System _____
Subsystem _____
☒ Component Pressure Switch

Design Responsibility Pressure Switch Group

Model Year(s)/Vehicle(s)/Version _____

Key Date 1988

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t e d	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t e d	R. P. N.
ENVIRONMENTAL SEAL (74267) Prevents ingress of water to switch cavity. Provides action to aid in preventing water intrusion.	Contributants enter switch cavity.	High current leakage. High self-volt drop. Erratic or inoperative switch operation.	7		Gasket thickness is specified too small. Limits on porosity not specified. Incorrect material.	1	Review of standard practice for gland design. Review with gasket manufacturer. Comparison of design with similar product.	1	7							
	Beam rotates too easily.	Perceived as inadequate by assembly plant and/or service personnel.	5		Gasket thickness improperly specified.	1	Review of standard practice for gland design. Torque-to-rotate testing. Comparison of design with similar product.	1	8							

P R I M A L
FAILURE MODE & EFFECTS ANALYSIS
(DESIGN FMEA)

Document Number 903804

Page 1

Revision Level C

Revision Date 4-Nov-88

System _____
 Subsystem _____
 X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 20-Dec-85

Model Year(s)/Vehicle(s) Variant _____

Key Date 1985

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Actions Taken	S e v e r i t y	C o n s e q u e n c e s	D e t e c t i o n	R. P. N.
THREAD CAP (74884) Protects support threads from damage during shipping and unpack. Prevents dust from entering the load cavity.	Incorrect length.	Does not protect threads sufficiently.	2		Length incorrectly specified.	1	Dimensional analysis study.	1	6							
	Loose Cap.	Allows dust to enter load cavity.	4		Incorrect diameter specified.	1	Dimensional analysis.	1	4							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 533005
Revision Level C
Revision Date 30-Oct-98

Page 1

System _____
Subsystem _____
X Component Passage Switch

Design Responsibility Process Switch Group

Original (Jitter) Date 20-Dec-95

Model Year(s)/Vehicle(s) Various

Key Date 1998

Prepared By G. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing, Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r e	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D i s c o n f o r m a n c e	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Planned	S e v e r e	O c c u r r e n c e	D i s c o n f o r m a n c e	R. P. N.
REPORT (30000)																
Provides a hydraulic sealing surface per SAE J612.	Failure to seal.	Leakage of brake fluid.	8	FF	Incorrect surface finish specification. Incorrect material specification. Incorrectly specified geometry. Excessive pressure.	1	Cross-check of print dimensions vs. SAE standard. Comparative evaluation of design at tolerance limits. Fluid testing to confirm specified limits.	1	8							
Provides external thread for installation into mating port.	Fails to properly install in mating port.	Damage to threads in mating port during installation. Does not allow installation.	7	FF	Threads specified improperly. Threads not gauged per ANSI spec's. Flaring buildup.	3	Cross-check of applicable SAE and ANSI standards.	3	8							
	Apparently installs, but fails to properly seat and seal.	Seals fluid leakage.	9	FF	Threads specified improperly. Threads not gauge per ANSI spec's. Flaring buildup.	1	Cross-check of applicable SAE and ANSI standards.	3	27							
Provides bar feature for 9/16" wrench.	Incorrect bar size.	Damage to bar flats during wrenching. 9/16" wrench does not fit.	5		Bar features improperly specified per established SAE/ANSI spec's.	1	Cross-check of applicable SAE and ANSI standards.	1	6							
Provides fluid passage to pressure-sensing element.	Fluid passage is too small.	Electrical signal from switch is delayed vs. pressure signal especially at very low temp. Subject to blockage by foreign matter.	7	FF	Inadequate size of fluid passage specified. Inadequate review of Ford standard practices.	1	Review of Ford standard practices. Review of industry practices.	1	7							
	Fluid passage is too large.	Fouling film will occlude passage during installation during underhood service operations	7	FF	Fluid passage specified excessively large.	1	Torque testing.	1	7							

3719 7289

**FAILURE MODE & EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 503805
Revision Level C
Revision Date 30-Oct-98

Page 2

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility Pressure Switch Group

Original (Initial) Date 29-Dec-98

Model Year(s)/Vehicle(s)/Variant _____

Key Date 1998

Prepared By C. Wenzel

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing, Quality

S/N Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Current Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Priority			
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n
HEXPORT (20000)															
Provides gland for internal gasket.	Failure to seal internal gasket properly.	Leakage of brake fluid.	9		Gland dimensions improperly specified. Gasket finishes improperly specified. Gland geometry improperly designed.	1	Cross-check with recommendations of gasket supplier. Comprehensive testing.	1	9						
Provides flange which interfaces with other components to form pressure-sensor structure.	Flange fails to mate properly with other components of pressure sensor.	Dis. too large results in assembly difficulty. Clearance too small results in bad component alignment. Flange too thick results in poor seating. Flange too thin results in reduced burst capacity. Improper edge chamfer results in stress concentration which weakens joint. Inadequate burst capacity.	9		Improper or incomplete specification of dimensions and tolerances.	1	Expedite and analyze to determine proper thickness for required strength. Tolerance stack-up analysis. Print review.	1	9						
	Material too soft or weak.	Damage/breakage during installation or subsequent service. Threads prone to damage, leads to assembly difficulties.	9		Improper material selection.	1	Comprehensive evaluation of physical properties.	1	9						
	Material cracks.	Increasing of strain leads to leakage.	9		Improper material selection.	1	Review of material properties.	1	9						
	Material degraded in presence of working fluid(s).	Leakage	9		Improper material selection.	1	Cross-check with similar products.	1	9						
	Inadequate environmental protection.	Long-term effect causes weakening of bay areas which leads to leakage or breakage.	9		Improper or insufficient plating specification.	1	Comprehensive environmental testing.	3	27						

8713 7300

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 803805

Page 3

Revision Level C

Revision Date 20-Oct-88

System _____
Subsystem _____
X Component Pressure Switch

Design Responsibility PRESSURE SWITCH GROUP

Original (Initial) Date 20-Dec-88

Model Year(s)/Vehicle(s) Var(s) _____

Key Date 1988

Prepared By C. Wagner

Core Team Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	C o n s e q u e n c e s	Potential Cause(s) Mechanism(s) of Failure	O c c u r r e n c e	Control Design Controls	D e t e c t i o n	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results				
												Action Taken	S e v e r i t y	O c c u r r e n c e	D e t e c t i o n	R. P. N.
EXPORT (80000) Provides flange which interfaces with other components to form pressure- tight structure.		Casualty problem.	9			1	Failure of plating protection.	3	27							

C of Number: 00072
 E. C. 0
 Revision Date: 10/07/97
 Prepared by: A. Arora/G. Vass

Part/Component: Movable Cartel
 Part No. / Revision: 28741/D, 04/01/98
 Process Name: CRT
 Drawn / Reviewed:

Design Responsibility: A. Arora / J. Pye
 Process/Quality Responsibility: R. Meyer / J. Wall
 Supplier:
 Model Year/Version:

1	Provide electrical wiring	Fail to provide	Cables appear as an open short	2	Correct material specified	1	Review of TI packaging and general
2	Strap with electrical function	substitute electrical	Material continuity		See EIR		product design info
3		control					
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14	Provide electrical path from location	Fail to provide	High resistance shows as high	7	Correct material specified	1	Review with correct manufacturer
15	to control unit	adequate conductivity	critical stop				Departmental verification
16							
17							
18							
19	Provide means of mechanical	Inadequate attachment	Shift in register over life	7	Incorrect geometry specified	1	Manufacturer recommendation
20	attachment to control unit	to control unit					
21							
22							
23							
24							
25							
26	Provide ability to override control	Collision shift	Shift in register	6	Incorrect geometry specified	1	Manufacturer recommendation
27	gap and therefore device self-aligns						
28							
29							
30	Provide a feature to minimize	Inadequate level	High critical stop	7	Incorrect geometry specified	1	Manufacturer recommendation
31	control input in a particular case	compensation					
32							
33							
34							
35	Provide feature to allow feeding	Fail to allow feeding	Manufacturing yield loss	8	Incorrect geometry specified	2	Manufacturing validation
36	material	in direction					
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							

**POTENTIAL
FAILURE MODE AND EFFECTS ANALYSIS
(DESIGN FMEA)**

Document Number 505770 Page 1
 Revision Level B
 Revision Date 5-Nov-95
 Original (Initial) Date 20-Dec-93
 Prepared By D. Ha

System _____
 Subsystem _____
 X Component Pressure Switch

Design Responsibility Pressure Switch Group


Model Year(s)/Vehicle(s) Various

Key Date 1993

Core Team: Design Engineering, Manufacturing Engineering, Manufacturing Quality

Item Function	Potential Failure Mode	Potential Effect(s) of Failure	S e v e r i t y	O c c u r r e n c e	Potential Cause(s) Mechanism(s) of Failure	D e t e r m i n e d	Current Design Controls	D e t e r m i n e d	R. P. N.	Recommended Action(s)	Responsibility & Target Completion Date	Action Results			
												Action Taken	S e v e r i t y	O c c u r r e n c e	R. P. N.
FVVER (74816) Fastens spring to movable terminal.	Fails to adequately fasten spring to movable terminal.	Spring rotates about axis of rivet. Spring falls off movable terminal.	5		Improper rivet diameter for given hole sizes. Improper rivet length for given material thickness. Improper head size. Improper tubular feature. Improper material.	1	Rivet manufacturer recommendations. Comparison with similar products. Testing to determine torque to rotate spring.	1	5						
	Provides a force between movable terminal and spring which causes infeasible contact for current flow.	Inadequate force between spring and movable terminal. High resistance or no continuity at interface of spring and movable terminal.	5		Improper rivet diameter for given hole sizes. Improper rivet length for given material thickness. Improper head size. Improper tubular feature. Improper material.	1	Rivet manufacturer recommendations. Comparison with similar products. Testing to determine torque to rotate spring.	1	5						













FF Analysis SW.
REDICK CAMP

* Note printed by NLAPOINT on 23 Feb 1999 at 16:36:37 *

From: I2060625--EXTERNAL Date and time 02/23/99 12:13:50
To: FPORTER --FORDMAIL 'Fred Porter { For NLAPOINT--FORDMAIL 'Norm LaPointe { F

From: Rahman, Aziz
Subject: FW: (U)Pressure Tests

You may have received this from Steve R. Interesting info on pressure profiles at various nodes. we will try to factor this into our vehicle test.

Regards
Aziz.

From: Steve Raimers SMTP:sraimers@ford.com
Sent: Friday, February 19, 1999 8:11 AM
To: Aziz Rahman, Texas
Subject: (U)Pressure Tests

fyi... I gave him a copy of your test plan and asked what pressure range and frequency we should instrument for.

Steve Raimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sraimers@ford.com fax 39-03286 :>
*** Forwarding note from JJOYCE1 --DREN007 02/18/99 19:40 ***
To: SREIMERS--DREN007
cc: FPORTER --DREN007

FROM: John Joyce USAF(UTC -05:00)
Subject: (U)Pressure Tests

Steve,

I got your note and will be on vacation tomorrow through Wednesday. Here's the info.

The more I think about this, the more I think TC activation may be the mechanism.

I am not sure of the order of the things connected and that can influence the low frequency amplitude of the signals. But the short answer is to instrument for 0-250 Bar and sample at 1 kHz or more.

Since I'm not sure of where the pressure switch is hydraulically connected I'll give you pressures at nodes and states I do know. The worst case for the switch would be to be connected between the HCU and the prop valve, which is where I think it is.

This is the low frequency component of the signal, I'll talk about the high-frequency component further down.

MC - HCU NODE
Maximum Pressure - 175 Bar

3713 7311

Achieved by getting maximum vacuum (high revving engine and suddenly close throttle) then standing on the pedal as hard as you can. I don't remember this number very well it might be as low as 130 or as high as 220. It also depends on your leg strength. This type of pressure is VERY RARE at this mode. For this car, the driver will typically apply <20 bar and very rarely exceed 50 bar.

HCU - PROP VALVE MODE
Standing Still - Same as MC pressure - see above.

ABS Maximum - 110 Bar
This is achieved by loading to GVW and performing an ABS stop, you may find that you are pedal effort limited, not limited by ABS control. It's pretty rare to get this high of pressure in this mode.

TCS Maximum - 180 Bar
This is a good candidate. On this vehicle because the HCU had to pump through the prop valve to do the brakes-only traction control, the pressures coming out of the HCU got very high. The pressure relief valve on the pump VERY OFTEN dictated the peak pressure which could be developed - not the control - put another way, because the pressure at the rear brake had to restrain the entire powertrain (no engine intervention) and push through a prop valve, it was often possible to drive through the TC - the engine could overpower the brakes, even though very high pressures were being generated at the HCU. The noise during TC activation in these applications was very dependant upon the pressure relief valve opening point. So the pressure relief valve value got changed a few times over the years as performance was sacrificed for NVH. Also the tolerance on the pressure relief valves was fairly large - a total of 40 bar, at that time I believe. The pressure relief valve pressure might be anywhere from 90 to 180 bar depending on part-to-part variation and the design generation that was agreed upon.

You can achieve this easiest by getting the rear wheels off the ground and putting the car in drive. Get into the throttle hard, but not so hard that you drive out of first gear or faster than 15 mph. If you maintain this for a while, the thermal model to protect the rear linings will disable the Traction Control. You will then need to wait for them to cool, before the function will be reenabled. You can dramatically accelerate the cooling time by cruising (without braking) at about 40 mph.

Typical drivers can regularly get high pressures in this mode.

PROP VALVE - REAR BRAKE MODE
ABS Maximum Pressure 70 Bar
Load to GVW and perform an ABS stop at maximum pedal effort.

TCS Maximum Pressure 100 Bar
This pressure level is strongly dependant upon the pressure relief valve level - see above.

Standing Still
Same as ABS Maximum Pressure

High Frequency Content
The high frequency content has two parts. If you are not in ABS or Traction Control there is practically no high frequency content - the pressure is modulated at <10 Hz. This is basically limited by Booster response times

and hydraulic dampening in the ABS orifices.

High Frequency Content Due To Control

During ABS/TC events the pressure is changed in quick steps. Typically it will increase by ~10 Bar in a few milliseconds, and this type of change occurs about every 100ms. The pressure will decrease by about 20 Bar every 300 ms. There can be quite a bit of variation in these numbers, but those are pretty typical. (Actually the numbers I assigned were for ABS, swap "increase" and "decrease" for TC activation.)

High Frequency Content Due to Shock Waves

This is a secondary effect from the control. Generally it is worst right at the outlet of the HCU. It is dampened and dissipated the further you get from the HCU. The shock wave is generated from the cyclical pulsing of the pump as well as the sudden changes in pressure when a solenoid valve is snapped open or shut.

The amplitude of this can be really big - I haven't looked at it in this generation unit for a few years, but I think it's about 50 Bar peak-peak right at the HCU. It will fall off as you move further away from the HCU.

The frequency is pretty high and I think some components are above the 1 kHz level, but you can get a very good idea of the disturbances by sampling at ~1kHz.

Regards,
John Joyce

1993 TOWN CAR SIGNATURE 4-DOOR 35494 00 30175 00
 DG CHINA BLUE CLEARCOAT MET NC NC
 DM AQUAMARINE LTHR SEAT SURFACE NC NC
 99H .4.6L EFI V8 ENGINE NC NC
 44P .ELECTRONIC AUTO O/D TRANS NC NC
 T3P .P215/70R15 HSW TIRES NC NC
 153 FRONT LICENSE PLATE BRACKET NC NC
 444 DUAL EXHAUST SYSTEM 83 00 69 00
 D LEATHER SEATING SURFACE T/C 570 00 479 00
 919 TRUNK MOUNTED CD CHANGER 833 00 700 00
 TOTAL VEHICLE & OPTIONS 36980 00 31425 00
 DESTINATION & DELIVERY 590 00 590 00

TOTAL FOR VEHICLE 37570 00

13 U.S. GAL GAS FACTORY 18 20
 PRICE ADJUSTMENT NOTICE APPLIES
 BATCH-ID 3796000001 D TO AA
 SCHEDULE-B LEVEL 00000
 PRICE LEVEL 301010M82 VIN: 1LNLM82N0PY622977
 SHIPPING WEIGHT 3891 LBS.

THIS INVOICE MAY NOT REFLECT THE FINAL COST OF THE VEHICLE IN VIEW OF THE POSSIBILITY OF FUTURE REBATES, ALLOWANCES, CIRCULATING AND PROMOTIVE AWARDS FROM FORD MOTOR COMPANY TO THE DEALER. * THIS PORTION OF THE VEHICLE PRICE WILL BE PROVIDED TO THE APPROPRIATE FORD ALIEN TO SUPPORT REGIONAL/DEALER ADVERTISING.					
REGIONAL ADVERTISING	INVOICE TOTAL	LESS REBATE FOR DEALER ACCOUNT	LESS ADVERTISING COST FOR DEALER ACCOUNT	LESS ADVERTISING COST FOR DEALER ACCOUNT	A PLAN
361.00	32,892.20	1,109.00	360.00	30,923.20	30,923.20

1109.00 44.00 1248.00 ,00 1065.00 29815.00

SOLD TO		FURTHER TERMS ON REVERSE SIDE		PLT RLSE DTE	
Memphis TN		2		09/14/92	
SHIP TO (IF OTHER THAN ABOVE)		22663		RS20	
		09 01 92		22-2077 04 08	

SHIP THROUGH

1LNLM82N0PY622977 HIXON FORD MOTOR CREDIT 000001
 THIS INVOICE TO BE USED FOR THE BILLING OF VEHICLES ONLY DEALER COPY

3713 7314

DEALER

220 663 VIN 1LNLM82H0PY622977

NUMBERED PRICE

AMOUNT

BATCH-ID 9796000001 D TO AA

PRICE LEVEL

301010M82

VIN: 1LNLM82H0PY

REQUEST

CASE: LAPOINTS, N

THIS INVOICE MAY NOT REFLECT THE FINAL COST OF THE VEHICLE IN VIEW OF THE POSSIBILITY OF FUTURE REBATES, ALLOWANCES, DISCOUNTS AND INCENTIVE AWARDS FROM FORD MOTOR COMPANY TO THE DEALER.					
* THIS PORTION OF THE VEHICLE PRICE WILL BE PROVIDED TO THE APPROPRIATE FORD LEAD TO SUPPORT REGIONAL/DEALER ADVERTISING.					
REGIONAL ADVERTISING	INVOICE TOTAL	FOR LEAD FOR LEAD ADJUST	FOR LEAD FOR LEAD ADJUST	FOR LEAD FOR LEAD ADJUST	A PLAN

SOLD TO
Schilling L-M/Mendenhall Inc. 220663
2660 South Mendenhall
Memphis TN 38115

FURTHER TERMS
ON REVERSE
SIDE

PLT RLSE DTE
09/14/92
RS20

SHIP TO (IF OTHER THAN ABOVE)

22663

DATE OF PURCHASE

09/01/92

FIN NUMBER

22-2077

FIN PLAN

SHIP THROUGH

1LNLM82H0PY

WIXOM

FORD MOTOR CREDIT

000001

THIS INVOICE IS TO BE USED FOR THE SELLING OF VEHICLES ONLY

DEALER COPY

3713 7315

3712 7316

PRICE INFORMATION

- [illegible]

➔ **STANDARD VEHICLE PRICE** **\$35499.00**

OPTIONAL EQUIPMENT

FRONT LICENSE PLATE BRACKET	NO CHARGE
DUAL EXHAUST SYSTEM	53.00
LEATHER SEATING SURFACE T/C	578.00
TRUNK MOUNTED CD CHANGER	635.00

TOTAL VEHICLE & OPTIONS	28980.00
DESTINATION & DELIVERY	500.00

SOLD TO
 2nd Floor, 1st Floor, 2nd Floor, 2nd Floor
 2nd Floor, 2nd Floor, 2nd Floor, 2nd Floor

IMP TO construction industry

#MP THROUGH ITEM 22-507

المجلس الأعلى للدراسات الإسلامية

200 643

WILSON

DATE	MS20
------	------

5796 D FD AA 301 00001

Report Created by: nlapoint Report Date: Tue Dec 15 13:45:34 EST 1998

5. BROADCAST MESSAGES

6. E D S R - ELECTRONIC DEALER SERVICE REPORT *

7. SELECT LANGUAGE *

99. DISCONNECT FROM OASIS

* NOTE: OPTION NOT AVAILABLE IN ALL MARKETS

ENTER SELECTION NUMBER <RTN>

2

12/15/1998 13:47:54

ENTER VIN <RTN> FOR VEHICLE WARRANTY HISTORY

M. MENU 1-7. MENU SELECTION NUMBER 99. BYE
1lnlms2w0py622977

12/15/1998 13:48:21

1993 TOWN CAR

4 DR SEDAN SIGNATURE

4.6L SOHC (ROMEO) 318JR10A 4 SPD OD AODE

AXLE CODE: JY

*OPEN CAMPAIGNS

NO CAMPAIGN MESSAGE(S) FOUND

*WARRANTY START DATE 02/08/1993 BUILD DATE 09/10/1992 START ODOM
LESS THAN TWO DEALER APPROVED AWA REPAIR VISITS PAID TO DATE
NO ESP INFORMATION AVAILABLE

12/15/1998 13:48:21

NO REPAIR HISTORY ON VEHICLE

12/15/1998 13:48:22

ENTER VIN <RTN> FOR VEHICLE WARRANTY HISTORY

OR <RTN> FOR 1LNLM82W0PY

M. MENU 1-7. MENU SELECTION NUMBER 99. BYE
99

12/15/98 13:48:35

THANK YOU FOR USING THE OASIS/EDSR MENU SYSTEM

DISCONNECTED FROM FORD COMPUTER #1335

THANK YOU FOR TYPING BYE, THIS HELPS TO REDUCE LOGIN TIME FOR OASIS/EDSR.

PLEASE TURN OFF YOUR TERMINAL...

please log in:

3713 7317

**TEXAS
INSTRUMENTS**

March 21, 1997

FACSIMILE TRANSMITTAL

TO: **Name:** Norman LaPointe
 Location: Design Analysis Department
 Phone Number:
 FAX Number: (313) 337-8256

FROM: Bryan Dague
 TEXAS INSTRUMENTS MS 12-29
 Phone Number: (508) 238-3234
 FAX Number: (508) 238-3586

Total number of pages (including header page): 4

Norm,

Here is the information that we have sent Fred over the past few days.

Let me know if you need anything else.

Regards,
Bry

TEXAS INSTRUMENTS INCORPORATED * 34 FOREST STREET * ATTLEBORO, MA 02703

Daggs, Bryan

From: Douglas, Charles
Sent: Wednesday, January 03, 1999 8:00 AM
To: Daggs, Bryan
Subject: FW: Florida Information

Charlie

Charlie Douglas
(508) 238-3857 (P)
(508) 238-1898 (F)
c-douglas2@t.com

From: Douglas, Charles
Sent: Monday, January 04, 1999 6:23 PM
To: Porter, Fred (Fort)
Subject: FW: Florida Information

Fred,

I was not able to get answers to all of your questions and will pass along what we know right now:

- While the exact melt temperature of the Noryl GTX 830 was not available, we do know that this material is molded in the 540 F - 580 F range.
- Kapton does not melt nor burn. Technically it "chars". While we have not been able to determine the exact char temperature of the Kapton, we do know that it is well above 800 F.
- Our team is working on the information on the gasket -- we need to get this from our supplier.

I have a meeting with Bryan Daggs and Al Hopkins first thing in the morning and will raise these questions again with them (Al is only returning from vacation on Tuesday). My concern is that we may be reliant on our suppliers for some of the information that you are requesting. What I will try to understand from Al and Bryan is if we have the capability to run tests to determine these temperatures ourselves (if this is the best way to generate the information).

Regards,

Charlie

Charlie Douglas
(508) 238-3857 (P)
(508) 238-1898 (F)
c-douglas2@t.com

From: R. Porter [mailto:RPorter@voyager.net]
Sent: Monday, January 04, 1999 12:18 PM
To: c-douglas2@t.com
Cc: Fred Porter
Subject: Florida Information

Dague, Bryan

From: Douglas, Charles
Sent: Wednesday, January 06, 1999 8:59 AM
To: Dague, Bryan
Subject: PW: 99-003: PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM 77PS FROM LINCOLN TOWN CAR

Charlie

Charlie Douglas
(508) 238-9657 (P)
(508) 238-1528 (F)
c-douglas2@t.com

From: Douglas, Charles
Sent: Wednesday, January 06, 1999 8:27 AM
To: Foster, Fred (Fred); Shupe, Robert
Subject: PW: 99-003: PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM 77PS FROM LINCOLN TOWN CAR

Fred,

Attached is the protocol for disassembly and analysis we plan to follow tomorrow. Please feel free to offer your thoughts relative to any additions or modifications your team may desire.

Rob,

Please make sure Norm gets a copy of this at your earliest convenience.

Regards,

Charlie

Charlie Douglas
(508) 238-9657 (P)
(508) 238-1528 (F)
c-douglas2@t.com

From: Hopkins, Al
Sent: Tuesday, January 05, 1999 7:37 PM
To: Dague, Bryan; Frois, Stephen; Douglas, Charles
Cc: Beasman, Russ; Baker, Gary; McQuitt, Andy; Berlinghouse, Steven; Andrus, Arny; Skuzick, Allen; Penco, Joe
Subject: 99-003: PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM 77PS FROM LINCOLN TOWN CAR

Here's a rough pass, what do you guys think?

PROPOSED PROTOCOL FOR DISASSEMBLY AND ANALYSIS OF SWITCH FROM
77PS FROM LINCOLN TOWN CAR

Page 1

- Review Ford's Analysis data that they are bringing in.
- Examine threads and determine if it is OK to just chase the threads to get a good seal or should we remove material for analysis.
- Pressure Leak Test the device (15 minute static-hold, air-pressurized test).
- Decide if we should remove any material or try any other analysis before we start disassembling the device.
- Do a practice decap using the below procedure on a deliberately fractured part (to mimic the condition that the returned device will be in) before performing it on the real sample. Bryan, you and I could do this now.
- Procedure to remove aluminum crimp ring
- Use aluminum foil (or plastic if Ford prefers) to mask the analysis surface.
- Also create a paper/tape shield to further reduce chance of contamination during cutting of crimp ring.
- Place a piece of tape over the area to be cut.
- Cut crimp ring using jeweler's saw or Dremel cutoff wheel in one of the two areas indicated on optical photo.
- Cut corners of ring at 150 degree orientation
- Unfold crimp ring
- Optically examine revealed surfaces. Take optical photographs (digital camera with macro lens plus instant microphotography) and document observations where appropriate. Examine the following areas
 - Inside surface of crimp ring.
 - Seal area and underside of base
 - Top of cap
- Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.
- Reprotect the top surface and remove the cap. Bryan had originally suggested just using an end mill to remove the cap. I wouldn't, however, go all the way through with the end mill. I would leave some material behind as a shield. I would suggest then bending the cap off.
- Optically document all revealed surfaces starting with cap.
- Meanwhile, start SEM-EDX analysis on top side of cap. Particularly focus in on the edges of the ceramic pin guide and on the indented ring that lines up with interior wall of the switch cavity. Particularly look for evidence of corrosion or arcing.
- Decide if we should try to flake off any of the overlying debris to try to examine the underlying metal surface.
- Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.
- Non-destructively probe inside of the grommet to determine its resilience which will give us an indication of the temperature that it saw. Another indication might be the depth of the indentations left by the grommet seal rings in the wire.
- Decide if it makes sense to further examine the mating connector or grommet seal.

Regards,

Al

END-OF-FAX

VIEW THE NOTE

M01

From: PKLAAS --FORDNA1

Date and time

01/05/99 16:19:07

To: NLAPPOINT--FORDMAIL LaPointe, Norman (

From: Klaas, Pete (P.F.)

Subject: RE: (U) Part Analysis

Done, thanks. IR shows brake fluid, according to Gayle, SEM work underway.

P. F. Klaas

Ford Motor Co.

Room 220, Central Laboratory

313-322-1613, fax 313-322-1614

Internet: mailto:pklaas@ford.com

-----Original Message-----

From: Norman Lapointe [mailto:nlapointe@gw.ford.com]

Sent: Tuesday, January 05, 1999 3:28 PM

To: pklaas@mail.ford.com

Subject: (U) Part Analysis

PF1 Alternate PFs PF2 File NOTE

PF3 Keep

PF4 Erase

PF5 Forward Note

PF6 Reply PF7 Resend PF8 Print PF9 Help PF10 Next PF11 Previous PF12 Return

- Review Ford's Analysis data that they are bringing in.
- Examine threads and determine if it is OK to just chase the threads to get a good seal or should we remove material for analysis.
- Pressure Leak Test the device (15 minute static-held, air-pressurized test).
- Decide if we should remove any material or try any other analysis before we start disassembling the device.
- Do a practice decay using the below procedure on a deliberately fractured part (to mimic the condition that the returned device will be in) before performing it on the real sample. Bryan, you and I could do this now.

- Procedure to remove aluminum wiring ring
 - Use aluminum foil (or plastic if Ford prefers) to mask the analysis surface.
 - Also create a paper/tape shield to further reduce chance of contamination during cutting of wiring ring.
 - Place a piece of tape over the area to be cut.
 - Cut wiring ring using jewellers saw or Dremel cutoff wheel in one of the two areas indicated on optical photo.
 - Cut corners of ring at 180 degree orientation
 - Unfold wiring ring
 - Optically examine revealed surfaces. Take optical photographs (digital camera with macro lens plus instant microphotography) and document observations where appropriate. Examine the following areas
 - Inside surface of wiring ring.
 - Seal area and underside of base
 - Top of cap
 - Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic - need to plate?
 - Reprotest the top surface and remove the cap. Bryan had originally suggested just using an end mill to remove the cap. I wouldn't, however, go all the way through with the end mill. I would leave some material behind as a shield. I would suggest then bending the cap off.
 - Optically document all revealed surfaces starting with cap.
 - Meanwhile, start SEM-EDX analysis on top side of cap. Particularly focus in on the edges of the ceramic pin guide and on the indented ring that lines up with interior wall of the switch cavity. Particularly look for evidence of corrosion or arcing.
 - Decide if we should try to flake off any of the overlying debris to try to examine the underlying metal surface.
 - Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.
 - Non-destructively probe inside of the groove to determine its resilience which will give us an indication of the temperature that it saw. Another indication might be the depth of the indentations left by the groove seal rings in the wire.
 - Decide if it makes sense to further examine the mating connector or groove seal.

Regards,

AL

END-OF-FAX

Page 2

JAN 08 '88 08:45

08:45 FAX

MODE MIN-SEC FOR CHW STATUS
LF-8 00:25 001 B44 EX

DATE TIME 01/08/88 10:37
TO/FROM FORD CENTRAL LAB

FORD DES DEPT 0000000000

08 OF JAN 08 '88 10:37 PAGE 01

TX COMPLETION REPORT **

3713 7323

Corrosion of Brass contact surfaces.

Nature of corrosion products

Brake Fluid — *I.R. / Chloroform solvent /*

Water

Unknown

Leakage determination

Internal Leakage

Physical Testing - Blow air at low pressure through the fluid side for a seal check

If no passage- no internal brake fluid issue

If passage- did fire damage the seal

} water bath only ok. not good.

Chemical analysis- determine if brake fluid exists on wrong side of diaphragm.

I.R. all above.

External Leakage

Determine if wires are path:

Internal- along copper strands- need to cut insulation for examination.

External path along insulation surface to contacts.

Connector cavity- Determine white power composition.

Fracture Analysis of internal contact components.

Stationary contact - Two fractures & two cracks.

file/ pressaw.wp.nr.122288

- green residue → *finy sample* → push → SEM
- brass oxides → *scrape small* → " → "
- fire ext. → " → " → " → "

*1/4/99
n*

Corrosion of Brass contact surfaces.

Nature of corrosion products

Brake Fluid- I. R.

Water - Green Oxides, and corrosion oxide - SEM

Unknown- White powder - SEM

Fracture Analysis of internal brass contact components.

Stationary contact - Two fractures & two cracks. Nature of fractures?

Leakage determination

Internal Leakage

Physical Testing - Blow air at low pressure - 125psi through the fluid side for a seal, check:

If no passage- no internal brake fluid issue.

If passage- did fire damage the seal? Cut to determine.

Chemical analysis I.R. - determine if brake fluid exists on wrong side of diaphragm.

Connector Side

External Leakage- Look for contamination path along or in wires.

Determine if wires are path:

Internal- along copper strands- need to cut insulation for examination.

External path along insulation surface to contacts.

Connector cavity- Determine white powder composition. SEM

file/ presssw.wp.nrl.122298

chemical
in
steels
acid
under

steels
con-
crete
rate

the
and
stain-
less
in a
cor-
rosion
steel
in as
s

ures
The
on

liquid

may
ved
dis-
of
be-

STAINLESS AND HEAT-RESISTING STEELS

Alloy	C	Cr	Mo	Other Elements	ASTM Spec.
304	0.08 max.	18.0-20.0	8.0-10.0	—	A 304
304L	0.03 max.	18.0-20.0	8.0-10.0	—	A 304L
316	0.08 max.	16.0-18.0	10.0-12.0	2.0-3.0 Mo	A 316
316L	0.03 max.	16.0-18.0	10.0-12.0	2.0-3.0 Mo	A 316L
321	0.08 max.	17.0-19.0	9.0-11.0	0.5-0.7 Ti	A 321
321L	0.03 max.	17.0-19.0	9.0-11.0	0.5-0.7 Ti	A 321L
347	0.08 max.	17.0-19.0	9.0-11.0	0.5-0.7 Nb	A 347
347L	0.03 max.	17.0-19.0	9.0-11.0	0.5-0.7 Nb	A 347L
309S	0.08 max.	22.0-24.0	12.0-14.0	—	A 309S
310S	0.08 max.	24.0-26.0	14.0-16.0	—	A 310S
314	0.08 max.	24.0-26.0	14.0-16.0	—	A 314
314L	0.03 max.	24.0-26.0	14.0-16.0	—	A 314L
3155	0.08 max.	24.0-26.0	14.0-16.0	—	A 3155
3155L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3155L
3167	0.08 max.	24.0-26.0	14.0-16.0	—	A 3167
3167L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3167L
3168	0.08 max.	24.0-26.0	14.0-16.0	—	A 3168
3168L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3168L
3169	0.08 max.	24.0-26.0	14.0-16.0	—	A 3169
3169L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3169L
3170	0.08 max.	24.0-26.0	14.0-16.0	—	A 3170
3170L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3170L
3171	0.08 max.	24.0-26.0	14.0-16.0	—	A 3171
3171L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3171L
3172	0.08 max.	24.0-26.0	14.0-16.0	—	A 3172
3172L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3172L
3173	0.08 max.	24.0-26.0	14.0-16.0	—	A 3173
3173L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3173L
3174	0.08 max.	24.0-26.0	14.0-16.0	—	A 3174
3174L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3174L
3175	0.08 max.	24.0-26.0	14.0-16.0	—	A 3175
3175L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3175L
3176	0.08 max.	24.0-26.0	14.0-16.0	—	A 3176
3176L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3176L
3177	0.08 max.	24.0-26.0	14.0-16.0	—	A 3177
3177L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3177L
3178	0.08 max.	24.0-26.0	14.0-16.0	—	A 3178
3178L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3178L
3179	0.08 max.	24.0-26.0	14.0-16.0	—	A 3179
3179L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3179L
3180	0.08 max.	24.0-26.0	14.0-16.0	—	A 3180
3180L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3180L
3181	0.08 max.	24.0-26.0	14.0-16.0	—	A 3181
3181L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3181L
3182	0.08 max.	24.0-26.0	14.0-16.0	—	A 3182
3182L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3182L
3183	0.08 max.	24.0-26.0	14.0-16.0	—	A 3183
3183L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3183L
3184	0.08 max.	24.0-26.0	14.0-16.0	—	A 3184
3184L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3184L
3185	0.08 max.	24.0-26.0	14.0-16.0	—	A 3185
3185L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3185L
3186	0.08 max.	24.0-26.0	14.0-16.0	—	A 3186
3186L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3186L
3187	0.08 max.	24.0-26.0	14.0-16.0	—	A 3187
3187L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3187L
3188	0.08 max.	24.0-26.0	14.0-16.0	—	A 3188
3188L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3188L
3189	0.08 max.	24.0-26.0	14.0-16.0	—	A 3189
3189L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3189L
3190	0.08 max.	24.0-26.0	14.0-16.0	—	A 3190
3190L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3190L
3191	0.08 max.	24.0-26.0	14.0-16.0	—	A 3191
3191L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3191L
3192	0.08 max.	24.0-26.0	14.0-16.0	—	A 3192
3192L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3192L
3193	0.08 max.	24.0-26.0	14.0-16.0	—	A 3193
3193L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3193L
3194	0.08 max.	24.0-26.0	14.0-16.0	—	A 3194
3194L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3194L
3195	0.08 max.	24.0-26.0	14.0-16.0	—	A 3195
3195L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3195L
3196	0.08 max.	24.0-26.0	14.0-16.0	—	A 3196
3196L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3196L
3197	0.08 max.	24.0-26.0	14.0-16.0	—	A 3197
3197L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3197L
3198	0.08 max.	24.0-26.0	14.0-16.0	—	A 3198
3198L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3198L
3199	0.08 max.	24.0-26.0	14.0-16.0	—	A 3199
3199L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3199L
3200	0.08 max.	24.0-26.0	14.0-16.0	—	A 3200
3200L	0.03 max.	24.0-26.0	14.0-16.0	—	A 3200L

* All percentages given, reported only when substantially added.
† Elements listed in parentheses are not required for service in
the atmosphere, but may be added for improved performance.

STAINLESS STEELS
GENERAL

GALVANIC AND CONCENTRATION-CELL CORROSION

When two unlike metals are connected in good contact and ex-
posed to a solution capable of carrying an electric current, the more
noble metal will corrode less rapidly, whereas the less noble metal
will corrode more rapidly than normal as a result of the develop-

Table IX
Galvanic Series of Metal Alloys

Metals	Corroded and (Anodic, or least noble)
Magnesium	
Magnesium Alloys	
Zinc	
Aluminum 2 1/2	
Aluminum	
Aluminum 24 ST	
Steel or Iron	
Cast Iron	
18 Per Cent Chromium-Iron (active)	
18 Per Cent Chromium-8 Per Cent Nickel Steel (active)	
18 Per Cent Chromium-8 Per Cent Nickel-3 Per Cent Molybdenum Steel (active)	
Monel	
Lead	
Lead-Aluminum	
Lead	
Tin	
Nickel (active)	
Monel (active)	
Antimony	
Antimony 2	
Bismuth	
Copper	
Brass	
Copper-Nickel Alloys	
Monel	
Mercury	
Nickel (passive)	
Monel (passive)	
Chromium-Iron (passive)	
18 Per Cent Chromium-8 Per Cent Nickel Steel (passive)	
18 Per Cent Chromium-8 Per Cent Nickel-3 Per Cent Molybdenum Steel (passive)	
Silver	
Gold	
Platinum	
	Protected and (Cathodic, or most noble)

ment of an electric current. The simple dry cell, when shorted, is
an excellent example of current generation produced by two dis-
similar metals in contact with an electrolyte. Because corrosion of
this type is associated with the generation of an electrical current,

NHTSA Investigation

93 ~~92~~ ~~TSO~~ contact William Abramczyk X 23284
Towin Car NY 1993
VIN 1Lnln 82 w/ p/ 62 29 77
P/N# F2YC-9F [redacted] Date code 2056
Name Brake Activated pressure sw.

12-15-98 Quick look

- Sw. channel internally @ path where
8-fluid, if weeping, could cause a
high resistance path between LG/R wire &
ground.
 - metal/steel tab corroded
 - wrong side of ~~switch~~ ^{switch} appeared wet.
 - white debris under the weather proof seal.
 - Neither wire appeared overheated.
 - pyrolyzed on inside @ one edge, 8 ^{elec.} connector
 - exterior melted, of elec. connector.
- 12-16 • X-ray - Orange wire side melted @ contact.

Theory Assessment - Brake fluid leak passed
diaphragm in switch caused a high resistance
(weak short) between either wire to ground.

Last cause F2YC-9F924-AB

Need to verify this theory!

Alternate theory - contamination came from wire side
Need to check for water/salt/mechanics.



Request for Central Laboratory Service

15000 Country Dr., Dearborn MI 48120-1367 Phone (313) 32-21676 FAX (313) 32-21614

All shaded areas must be filled in to process your request

Administrative Use Only

Laboratory Number

Date

9804105

12-17-98 Jm

Your Name (Send report to)	Telephone	PROPS ID	FAX
G. STEVENS	36686	GSTEVENI	36686
Secondary Contact	Telephone	PROPS ID	FAX
N. LAPOINTE	42686	NLAPOINT	

Room No./Mail Drop/PO Box	Department/Activity	Building	Location Code	Dept. #	Work Unit # (For 3100 Loc. Only)
MD5006	MATERIALS INT	BLD 45	5100	T-113	XOGEA

Total # of Samples	Sample Handling	TOX/CASE	Source	Supplier Code
1	☒ Return after test ☐ Dispose after test ☐ Dispose after 30 days			

Part/Material Name	Sample Identification (Continued below if needed)	Part Number (if any)	Material Specification (if any)	CPSC Code	Supplier
SPEED CONTROL	BURNED	F2Y1-9F924-A	NA		TEXAS INSTRUMENTS
CUT-OFF SWITCH	CONNECTOR				
	PRESSURE ACTUATOR				
	(REDDICK)				

Nature of Investigation/Specific Tests Requested (Check all that apply)		Investigation	Requester Info. Box (For requester use)
☒ Production/Plant problem	☐ Perform Tests as in Lab No.		HIGH PRIORITY - POSSIBLE LEGAL
☒ Failure Analysis	☐ Photograph (Describe below)		
☒ Legal	☐ Use Specifications as a guide		
☐ Specification Compliance	☐ Other (Describe below)		
Stop delivery upon failure?	Does this support CAE testing? (If "Yes", what is the expected outcome?)		Do you need to know your CL contact and timing?
☐ No ☐ Yes	☐ No ☐ Yes		☐ Yes

Additional Sample Information/Testing Requirements

DETERMINE CAUSE OF BURNED CONNECTOR
RADIOGRAPH
PHOTOGRAPH
PRESSURE TEST DIAGNOSIS

EVALUATE/UNDERSTAND CIRCUITRY OF NEW SWITCHES

ATTN: S. LAROCHE


NOTE: ALL COMMUNICATIONS/REPORT, ETC. TO BE DUAL (I.E. NLAPOINT)
--


Report

Date you would like report	Format (Check all that apply)	Mail typed report
1-13-99	☒ FAX preliminary results ☐ FAX hard written	☐ Electronically transfer report
Date you must have report	☐ FAX typed report ☐ Mail hard written	☐ Phone preliminary results
1-14-99		

For information about services or assistance in completing this form please refer to the Central Laboratory WEB page. [www.gro.ford.com/central/lcna.htm]
 Laboratory number and date cannot be assigned without receipt of samples.
 Samples will be disposed of after 30 days unless otherwise indicated above.


REDDICK






3713 7331

REDDICK




REDDICK




3713 7333

REDDICK




REDDICK




8718 7335




3713 7336





3713 7837





3713 7339

PE98-055
98-Dec-14



PR98-055
98-Dec-14

WFO BY FORD MOTOR CO. IN U.S.A.




DATE: 11/92 CMC: 244127247000

FRONT VIEW: 263113 119310



REAR VIEW: 263113 119310

THIS PART IS NOT TO BE USED IN THE



REAR VIEW OF THE VEHICLE



PE98-055
98-Dec-14




PE98-055
98-Dec-14



PE98-055
98-Dec-14



3713 7343




98-Dec-14
PE98-055



3713 7344



PE98-055
98-Dec-14



3713 7348

PE98-055
98-Dec-14

3713 7347

FIELD RETURN SAMPLES

Brake Pressure Switch Plan Updated 2/10/90
Evaluation Plan for Field Returns

Sw #
Mileage
Sw PIN

Date of update
Sw Date Code

Category	Step #	Action	Notes/Date	Comments
Field Info	1	Log Field info into Switch Log.xls		
	2	Photograph Switch		
	3	Report any unusual external visual observations		
	4	Check for Connector engagement		If not correct conduct X-Ray to determine fit-up between brake flange and seal
Switch + Connector Assembly	5	Wire 1 to Wire 2 Position		
	6	Wire 1 to Harport Resistance		
	7	Wire 2 to Harport Resistance		
	8	Separate Harmon from Switch		
Connector Only	9	Verify Connector Seal		Visual check of Red Seal, Del Seal, Indentation mark. Indentation mark must be 300 degrees.
	10	Wire 1 to Wire 2 resistance		
	11	Current Leakage Wire 1 to Wire 2		
	12	Check for full engagement of connector		Visual check of del trace on spring switch base
	13	Check wire insulation		
	14	Check wire grommets		
	15	Cut wire insulation to check for corrosion		Cut insulation lengthwise to check for cracking along wires. If signs of corrosion, identify color, save samples for chem lab.
Switch Electrical Unpressurized	16	Assemble Switch to Calibration Stand		
	17	Terminal 1 to Terminal 2 Resistance		
	18	Terminal 1 to Harport Resistance		
	19	Terminal 2 to Harport Resistance		
	20	Seal to Harport Resistance		
	21	Current Leakage Terminal 1 to Harport		
	22	Current Leakage Terminal 2 to Harport		
	23	Voltage drop at 700 psi		
Switch Electrical Pressurized	24	Switch Opening Pressure		Do not perform on parts from undischarged line, as may disturb disintegration condition
	25	Switch Closing Pressure		Do not perform on parts from undischarged line, as may disturb disintegration condition
	26	Proof Test for Leakage		Do not perform on parts from undischarged line, as may disturb disintegration condition
	27	Repeat Steps 17 through 23 at 700 psi		
Switch Internal		Procedure to remove sludge from oring Use aluminum foil (or plastic if Ford part) to break the single surface. Also create a pipe tape shield to further reduce chance of contamination during cutting of oring ring. Place a piece of tape over the area to be cut. Cut oring ring using jigsaw saw or Unimol cut-off wheel. Cut oring at 90 degree orientation. Unfold oring ring.		

3713 7348

Optically examine revealed surfaces. Take optical photographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate. Examine the following areas inside surface of strap ring.

Swal area and underside of base

Top of cap

Analytical
Techniques
SEM/EDX/CP

Assess Need for Analytical Techniques

Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.

Reposition the top surface and remove the cap

Optically document all revealed surfaces starting with cap.

Meanwhile, start SEM-EDX analysis on top side of cap. Particularly look for evidence of corrosion or arcing

Particularly focus in on the edges of the ceramic pin guide and on the insulated ring that lines up with interior wall of the switch cavity

Particularly look for evidence of corrosion or arcing

Debris if we should try to take off any of the overlying debris to try to expose the underlying metal surface.

Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.

Data Entry

Log All data from this sheet into Switch Log

Photographs, elemental maps etc must be retained and referenced by Switch #

3713 7849

				Flyings			
Sample	VIN	Field Date	Condition	History, Weather, Corrosion, and Other	Seals	Cup	Notes/Other Comments
Redlich (Mississippi, 1983 Town Car)	1LNLM2W0P	FEV00000	Partially burned.	Black residue containing glycol based material (probably brake fluid) and a metal catalyst. Indication presence of brake fluid on fluid and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. All three Kaptan seals are backed and exhibit little oxide which most likely formed a leak path. Damage appears to have resulted in that closest to window. Damaged Kaptan declared and certified by unknown mechanism.	Green deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.	Three mounted lower wiring ring. Transfer pin and movable contact missing. Stationary contact exhibits loss of material due to corrosion, evidence of disintegration, stress corrosion cracking. Base of movable contact marked with two bolt heads between switch and terminal contacts. Appears to have occurred in later stages of event. Evidence of terminals covered with black and green deposits which appear to be sulfur compounds of the type not available.
A (1983 Town Car, Houston)	1LNLM2W1PY	77720001	Burned	Stainless steel contact material detected at wiring end of support. Indicates possible flow of fluid back through seals. Traces of silicone detected.	Seal and environmental seal missing. Chopped fragments Kaptan seals remain.	Deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
B (1982 Town Car, Houston)	1LNLM2W2N	FEV00014	Burned	Stainless steel contact material detected at wiring end of support. Indicates possible flow of fluid back through seals.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Transfer pin and movable contact missing. Stationary contact exhibits crack in similar location as that in Redlich sample.
C (1982 Town Car, Houston)	1LNLM2W3N	FEV00009	Burned	Stainless steel contact material detected at wiring end of support. Indicates possible flow of fluid back through seals. Black deposit is clearly evidence of hydraulic oil and silicone.	Gasket appears chipped. Environmental seal missing. Damage to Kaptan seals currently being evaluated.	Deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product.	Base, stationary contact, movable contact, and terminals missing.
D (1987 Crown Victoria)	2FAUPT1R1V	FEV00000	Apparent leakage.	Black residue containing glycol based material (probably brake fluid) and a metal catalyst. Indication presence of brake fluid on fluid and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit damage similar to that found in Redlich sample. All three exhibit little oxide which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Deposits appear to have formed a bridge between movable contact and cup. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Corrosion appears intact. Dark green deposits on movable and stationary contacts appear elements from brass contact material. Terminals appear clean (no apparent deposits or corrosion).
E (911 from survey)		FEV00000	No leaks or other apparent problems.	Black residue containing glycol based material (probably brake fluid) and a metal catalyst. Indication presence of brake fluid on fluid and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit deformation and buckling similar to that found in Redlich sample. Cracking on surfaces suggest buckling damage is occurring.	Face of cup appears clean and dry.	Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
F	1LNLM2W1N	FEV00000	Apparent leakage	Black residue containing glycol based material (probably brake fluid) and a metal catalyst. Indication presence of brake fluid on fluid and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit damage similar to that found in Redlich sample. All three exhibit little oxide which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts including transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid in interior and on face of cup is glycol based (probably brake fluid).	Switch cavity and terminal cavity contain glycol based material (probably brake fluid). Stationary contact is intact, but does show stress corrosion, cracking in progress in bridge area (same location as in Redlich switch). Movable contact appears to have separated as a result of loss of material (-50% of thickness) due to corrosion. No evidence of buckling or any damage. Dark green deposits on movable and stationary contacts contain elements from brass contact material, as well as sulfur. Terminals exhibit green deposits (currently being analyzed). Deposits extend in from both sides of subframe (between switch) and terminal cavities, but do not vent.

Copyright © 1994 by Ford Motor Company

Page 10 of 10

Reading Comprehension Practice Test 1

Updated 3/10/04

[illegible]

3713 7361

* Note printed by NLAPOINT on 17 Feb 1999 at 16:26:26 *

From: I2060625--EXTERNAL Date and time: 02/17/99 08:53:37
To: FPORTER--FORDMAIL 'Fred Porter (For NLAPOINT--FORDMAIL 'Norm LaPointe (F
SLAROUCH--FORDMAIL 'Steve LaRoucha (SEEDMERS--FORDMAIL 'Steve Reimers (F

From: Rahman, Aziz
Subject: Switch Dissection Proposal

Please review the attached dissection guidelines. Please add/edit, and I will incorporate them in the process flow.

Thanks
Aziz.

Decide if we should remove any material or try any other analysis before we start disassembling the device.

- * Procedure to remove aluminum crimp ring
- * Use aluminum foil (or plastic if Ford prefers) to mask the analysis surface.
- * Also create a paper/tape shield to further reduce chance of contamination during cutting of crimp ring.
- * Place a piece of tape over the area to be cut.
- * Cut crimp ring using jeweler's saw or Dremel cutoff wheel in one of the two areas indicated on optical photo.
- * Cut corners of ring at 180 degree orientation
- * Unfold crimp ring
- * Optically examine revealed surfaces. Take optical photographs (Digital camera with macro lens plus instant microphotography) and document observations where appropriate. Examine the following areas
 - * Inside surface of crimp ring.
 - * Seal area and underside of base
 - * Top of cap
- * Start SEM-EDX (Scanning Electron Microscope with Energy Dispersive Analysis of X-rays) analysis on the inside of the ring and on various surfaces of the plastic base.
- * Reprotect the top surface and remove the cap.
- * Optically document all revealed surfaces starting with cap.
- * Meanwhile, start SEM-EDX analysis on top side of cap. Particularly focus in on the edges of the ceramic pin guide and on the indented ring that lines up with interior wall of the switch cavity. Particularly look for evidence of corrosion or arcing.
- * Decide if we should try to flake off any of the overlaying debris to try to examine the underlying metal surface.
- * Proceed to perform SEM-EDX analysis on other component surfaces revealed by removal of cap.

8718 7363

FOED LAB RESULTS

Log Updated 2/15/1988

Sw #	Sw Data Code	Vehicle	VIN	Event	Message	Leader?	Kaplan #1	Kaplan #2	Kaplan #3	Team-Hasco Residence	Present Location of Sw.	Present Status	Comments
Masterfile		Town Car		Sw. Pile			Year	Year	Year		Central Lab		
A		Town Car		Underhood Fire							Central Lab	Analysis in Progress	
B		Town Car		Underhood Fire							NA	Sw. not available	
C		Town Car		Underhood Fire							Central Lab	Analysis in Progress	
D		Crown Vic Police Car		Crash Inp			Year?	Year?	Year?		Central Lab	Analysis in Progress	
E		Town Car		Reference							Central Lab	Analysis in Progress	
F		Town Car		Crash Inp			Year?	Year?	Year?		Central Lab	Analysis in Progress	
1	2008	Town Car	MX702090	Reference	79453						AVT		
2	2015	Town Car	FX704048	Reference	71287						AVT		
3	2040	Town Car	FX702070	Reference	30387						AVT		
4		Town Car		Reference	28548						Central Lab	Analysis in Progress	
5		Town Car		Reference	47295						Central Lab	Analysis in Progress	
6	2009	Town Car	MX702430	Reference	80552						AVT		
7	2008	Town Car	FX702028	Reference	68514						AVT		
8	2200	Town Car	FX702770	Reference	??						AVT		
9	2201	Town Car	FX702070	Reference	52254						AVT		
10	2000	Town Car	FX702080	Reference	91528						AVT		
From TX trip of 2/10 to 2/12													
1	2009	Town Car	FX702080	Reference							AVT		With Connector and servo
2	2000	Crown Vic Police Car	FX702020	Reference	19880						AVT		With Connector and servo
3	2000	Grand Marquis	FX702100	Reference	??						AVT		With Connector and servo
4	2000	Crown Vic	FX702110	Reference	40542						AVT		With Connector
5	2000	Town Car	FX702080	Reference	72118						AVT		With Connector
6	??	Town Car	FX702080	Underhood Fire	??						AVT		
7	2004	Town Car	FX702170	Reference	??						AVT		With Connector
8	2045	Town Car	FX702181	Underhood Fire	105510						AVT		With Servo, Prop Valve
9	2000	Town Car	FX702185	Reference	??						AVT		With Connector, Prop Valve, Servo
10	2002	Crown Vic	FX702140	Reference	72314						AVT		With Connector, Prop Valve, Servo
11	2115	Town Car	FX702100	Reference	??						AVT		With Connector
12	2000	Town Car	FX702080	Reference	??						AVT		With Connector
13	2000	Town Car	FX702113	Reference	105048						AVT		With Connector and Servo

3713 7355

BLACK SLUDGE MATL. LOADED CAVITY

REVELED SURF'S COATED W/ BLACK-BROWN
VARNISH LIKE SMOOTH UNIL MATL.

LEAKED

ON CENTER CAVITY FILLED W/
BLACK (CONTAMINATION).

FULL SURF. OF
DISC. CONTAMINATED
W/ BLACK GRIT & VARNISH
LOADING.

FULL FACE OF WASHER. CONTAMINATED
W/ BLACK GRIT & VARNISH LIKE
LOADING.

GREEN OXIDE

LEAKING FROM TO
GREEN OXIDE

NOTES AFTER T.I. DISASSEMBLY

UNLESS
DIM

FRACT

WATER

3713 7356

Sample	VIN	Plate/Date Code	Condition	Findings		
				Exterior, Weather, Corrosion, and Interior	Seals	Cap
Reddick (Mercedes) 43 <i>Thermlac</i>		F2VJ2208	Partially burned.	Black residue containing glycol based material (probably brake fluid) and a metal catalyst. Indicates presence of brake fluid on field and switch sides of seals.	Environmental seal and gasket intact and appear to have had good sealing. All three Kaptan seals are buckled and exhibit brittle cracks which most likely formed leak path. Damage appears to have initiated in seal closest to switch. Damaged Kaptan deformed and entrapped by unknown mechanism.	Green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Glycol based material (probably brake fluid) also detected in this area.
A (1985 Town Car, Houston)	1LHLM82W1	727702081	Burned	Elements from contact catalyst detected at fitting end of transport. Indicates possible flow of fluid back through seals.	Good seal environmental seal missing. Charred fragments Kaptan seals remain.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.
B (1982 Town Car, Houston)	1LHLM82W1	F2VJ2114	Burned	Elements from contact catalyst detected at fitting end of transport. Indicates possible flow of fluid back through seals.	Not permitted to disassemble switch.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.
C (1982 Town Car, Houston)	1LHLM82W1	F2VJ2003	Burned	Elements from contact catalyst detected at fitting end of transport. Indicates possible flow of fluid back through seals. Black deposit is likely definitely being analyzed (possibly charred gasket).	Gasket appears charred. Environmental seal missing. Damage to Kaptan seals currently being evaluated.	Deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product.
D (1987 Crown Victoria)	2FALP7W1 1 - 0.2 2 - 1.1 3 - 1.1 3 - 1.1	F2VJ2117	Apparent leakage.	Black residue currently being analyzed. <i>seems as Reddick</i>	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid on surface currently being analyzed.
E (1911 Ford survey)	1 - 0.2 2 - 0.2 3 - 1.1	F2VJ2197	No leaks or other apparent problems.	Dark residue currently being analyzed. <i>3 dots</i> <i>seems as Reddick</i>	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit deformation and buckling similar to that found in Reddick sample. Cracking on surfaces suggest leakage damage is occurring.	Face of cup appears clean and dry.
F	1LHLM82W1 1 - 0.2 3 - 1.1	F2VJ2126	Apparent leakage.	Black residue currently being analyzed. <i>seems as Reddick</i>	Environmental seal and gasket intact and appear to have had good sealing. Kaptan seals exhibit damage similar to that found in Reddick sample. All three exhibit brittle cracks which most likely formed a leak path.	Dark green deposits on face of cup contain elements from brass contacts indicating transfer of contact material to cup probably as oxide, sulfide, or corrosion product. Liquid on surface currently being analyzed.
						Base separated below crimp ring. Transfer pin and movable contact missing. Stationary contact exhibits loss of material due to corrosion, evidence of demineralization, stress corrosion cracking. Base of movable contact nailed back into ballhead between switch and terminal cavity. Appears to have occurred in later stages of event. Surfaces of terminals covered with black and green deposits which appear to be either compounds of the terminal materials.
						Base, stationary contact, movable contact, and terminals missing.
						Transfer pin and movable contact missing. Stationary contact exhibits crack in similar location as that in Reddick sample.
						Base, stationary contact, movable contact, and terminals missing.
						Switch cavity and terminal cavity contain what appears to be brake fluid (currently being confirmed). Contacts appear intact. Dark green deposits on movable and stationary contacts contain elements from brass contact material. Terminals appear clean (no apparent deposits or corrosion).
						Switch cavity and terminal cavity appear clean and dry. No apparent deposits or corrosion.
						Switch cavity and terminal cavity contain what appears to be brake fluid (currently being confirmed). Stationary contact appears intact. Movable contact appears to have expanded as a result of corrosion. Dark green deposits on movable and stationary contacts contain elements from brass contact material, as well as sulfur. Terminals exhibit green deposits (currently being analyzed).

WIK: OPTIONS? ABS & TRACTION

- 1 - REG. BOWEN CAR, TEXAS
- 2 - REG. 1 BOWEN CAR & THUNDER BOLT
- 3 - REG. BOWEN CAR FOR CASE

3718 7357

Brake Pressure Switch Table:

Definitions:

Resistance Measurement #1 - Resistance reading between connector terminals (NC switch)

Resistance Measurement #2 - Resistance reading between sensor case and threaded fitting.

Resistance Measurement #3 - Resistance reading between both connector pins and sensor case.

Sensor	Id Code	Date	Zip Code	Res. #1	Res. #2	Res. #3
#1	PY754573	5-93	42621	0.2 Ohm	167.0 Ohms	Inf. Resistance
#2	NY740208	6-92	33237	0.3 Ohm	0.3 Ohms	Inf. Resistance
#3	PY688795	1-93	NA	0.3 Ohm	4.48 M Ohms	Inf. Resistance
#4	PX629934	11-92	68302	0.2 Ohm	1.5 Ohms	Inf. Resistance
#5	PY650223	10-92	72114	0.2 Ohm	1.7 Ohms	Inf. Resistance
#6	PX638867	12-92	35333	0.3 Ohm	17 K Ohms	Inf. Resistance
#7	PX665270	4-93	66689	0.3 Ohm	2.9 Ohms	Inf. Resistance
#8	PX643515	12-92	43531	0.2 Ohm	0.4 Ohms	Inf. Resistance
#9	PX623672	10-92	94145	0.2 Ohm	24 M Ohms	Inf. Resistance
#10	PY695374	1-93	NA	0.2 Ohm	11.30 M Ohms	Inf. Resistance
#11	NX758774	7-92	97199	0.2 Ohm	6.79 M Ohms	Inf. Resistance
#12	BY639984	9-93	97199	0.2 Ohm	0.2 Ohms	Inf. Resistance
"E" "D" "Looking sensor" VIN 2FALP71W1V2 [REDACTED]				0.4 Ohm	1.1 Ohms	4.80 M Ohms
CENT. LAB.				0.2 Ohm	0.4 Ohm	Inf. Resistance
New sensor #1				0.2 Ohm	1.1 Ohm	Inf. Resistance
New sensor #2				0.2 Ohm	1.1 Ohm	Inf. Resistance

140K GROUND TO GND
UNSTABLE

2120

1LNLM8ZW1V

4P130

300K - 2M

116117

* Note printed by NLAPPOINT on 17 Feb 1999 at 16:15:06 *

From: FPORTER --DRBN007
To: NLAPPOINT--DRBN005

Date and time 01/22/99 09:51:02

FROM: F. J. Porter
Subject: RE: (U) Brake Fluid Questions

USART(UTC -05:00)

Regards,
Fred Porter OV - fporter fporter@ford.com
Chassis E/E Systems Applications (313)845-3722
Bldg 5 - Mail Drop 5030 - Cubicle 3E004 fax: 390-4145
*** Forwarding note from GGULLEN --FORDMAIL 01/22/99 08:12 ***
To: CTHOMAS5--FORDMAIL Thomas, Clark (C.D) MHAGA --FORDMAIL Haga, Mary (M.C.)
GGULLEN --FORDMAIL Gullen, Gayle (G.D)
cc: FPORTER --FORDMAIL Porter, Fred (F.J.) GSTEVEN1--FORDMAIL Stevens, Gregory (G)
KGRIBBLE--FORDMAIL Kowalczyk, Richard

From: Gullen, Gayle (G.D.)
Subject: RE: (U) Brake Fluid Questions

I just talked to Mike Kitt at Dow and he informed me that Greg Stevens is faxing him a list of questions to answer. The one that Mike can't answer is regarding whether or not brake fluid reacts with copper/brass. The answer to that is yes, under some circumstances. We have seen several instances over the years in various assembly plants where brake fluids have formed an organometallic copper complex. This only occurs after there has been some type of welding repair to the delivery system. Dow does not add anything copper based to their system and they have never been able to assist us in determining the exact nature of the copper complex formed. Eventually this material flushes from the plant system, however, in an enclosed system like a switch I suspect we could have flocculating particulates.

-----Original Message-----

From: Clark Thomas mailto:cthomas5@acorn1.detroit.ford.com
Sent: Thursday, January 21, 1999 5:27 PM
To: mhaga@mail.ford.com; ggullen@mail.ford.com
Cc: fporter@gw.ford.com; gsteven1@gw.ford.com; kgribble@gw.ford.com
Subject: (U) Brake Fluid Questions

Gayle/Mary: Can you comment on this? It is in reference to the issue of fires possibly caused by the Texas Instrument Cruise Control Switch being looked at by NHTSA and our Legal Staff. Thanks.

Regards, Clark Thomas
AVT Materials (Plastics/Elastomers)
313-89-41313 (Bldg); 313-32-23100 (POH)
*** Forwarding note from FPORTER --DRBN007 01/21/99 10:13 ***
To: CTHOMAS5--DRBN005 GSTEVEN1--DRBN005

FROM: F. J. Porter
Subject: (U) Brake Fluid Questions

USART(UTC -05:00)

Two questions:

Is brake fluid conductive? How much?

Will brake fluid react with copper or brass? Will an electric field or current cause a reaction?

Regards,
Fred Porter OV - fporter fporter@ford.com
Chassis E/E Systems Applications (313) 945-3722
Bldg 5 - Mail Drop 9030 - Cubicle 38004 Fax: 390-4145

* Note printed by NLAPOINT on 17 Feb 1999 at 09:08:40 *

From: BREIMERS--DRBN007 Date and time 02/16/99 18:12:29
To: JNENE --DRBN005 NLAPOINT--DRBN005
RNEVI --DRBN005 SLAROUCE--FORDNAL
I2060625--EXTERNAL Axis Rahman, Texas

FROM: Steve Raimers USAET(UTC -05:00)
Subject: (U)
Can you help me get smart regarding the "LOOSE METAL PART" mentioned above?

Steve Raimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 BREIMERS sreimers@ford.com fax 39-03286 />
*** Forwarding note from SCOLE1 --DRBN005 02/16/99 18:04 ***
To: BREIMERS--DRBN007
cc: DGOEL --DRBN005

From: Sam L. Cole USAET(UTC -05:00)
Subject: (U)
THE PREVIOUS CONCERN OF THE "LOOSE METAL PART" WAS MENTIONED IN THE LAST
MEETING WITH JACK. HE WILL WANT A FOLLOW UP ON THIS AT THIS FRIDAY'S
MEETING. PLEASE GET UP TO SPEED ON THE HISTORY OF THIS CONCERN. IF IT
TURNS OUT THAT THIS MAY BE A CAUSE, THEN WE WILL NEED TO KNOW WHEN THE
ISSUE WAS IN THE FIELD, WHEN IT WAS FIXED AND HOW MANY ARE OUT THERE TO
BE CONCERNED ABOUT. THANKS.

Thank You,
Sam
Ext. 21959
BLDG. 2, 22J31 - WD# 1220 - SCOLE1@FORD.COM
*** Forwarding note from BREIMERS--DRBN007 02/16/99 16:52 ***
To: SCOLE1 --DRBN005 DGOEL --DRBN005

FROM: Steve Raimers USAET(UTC -05:00)
Subject: (U)
I have the part to show and a take-apart version too. I am not familiar with the
previous problem but a loose metal part in the switch cavity is definitely a
potential cause of this concern.

Steve Raimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 BREIMERS sreimers@ford.com fax 39-03286 />
*** Forwarding note from DB7AWAYR--DRBN007 02/16/99 13:41 ***
Subject: AWAY Facility/VM messages
This note was generated by the AWAY Facility/VM 5799-FLP (c) IBM Corp.
DO NOT REPLY TO THIS NOTE

AWA1101 This mail item is being routed to you from SCOLE1 at DRBN005
on behalf of FPORTER at DRBN007.

To: FPORTER --DRBN007
cc: TMASTERS--DRBN005 TDOGOVAN--DRBN005
DGOEL --DRBN005

From: Sam L. Cole USAET(UTC -05:00)
Subject: (U)
I UNDERSTAND THAT THERE WILL BE A FOLLOW UP MEETING WITH JACK PASKUS

3713 7361

THIS FRIDAY ON THE TOWN CAR INVESTIGATION. I MET WITH JACK TODAY FOR A 1
ON 1, AND HE REQUESTED SOME SPECIFIC INFO. AT FRIDAYS MEETING, PLEASE
BRING A SAMPLE SWITCH TO SHOW JACK.

ALSO, HE IS INTERESTED IN KNOWING OUR PROGRESS AND INVESTIGATING IF THE
PREVIOUS PROBLEM WITH THE INTERNAL COMPONENTS BREAKING LOOSE IS A
POTENTIAL CAUSE OF THIS CONCERN. PLEASE BE PREPARED TO DISCUSS THIS ON
FRIDAY. THANKS.

Thank You,

Sam

Ext. 21959

BLDG. 2, 22J31 - MD# 1220 - SCOLRI@FORD.COM

Date and time 02/17/99 09:41:08
I2060625--EXTERNAL Aziz Rahman, Texas

USABT (UTC -05:00)

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 :>
*** Forwarding note from SLAROUCH--FORDMAIL 02/17/99 08:18 ***
To: SREIMERS--FORDMAIL Reimers, Steve (2.

From: LaRouche, Steve. (S.)
Subject: RE: (U)

Steve: The switch in question is switch F. The copper-beryllium arm of the movable contact separated from the brass base. Now that we have had a chance to look at it in closer detail, it appears that the arm separated due to a loss of material thickness from corrosion. We have also found evidence of stress corrosion cracking in the stationary contact. We did not see any evidence of heat or arc damage in this switch. It looked like the arm separated, fell away, and stuck to the wall of the switch cavity.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room #410
(313) 845-4876 (313) 322-1614 FAX

-----Original Message-----

From: Steve Reimers mailto: sreimers@gw.ford.com
Sent: Tuesday, February 16, 1999 6:13 PM
To: jneme@gw.ford.com; nlapoint@gw.ford.com; rnsvi@gw.ford.com; alarouch@mail.ford.com; Aziz Rahman, Texas
Subject: (U)

Can you help me get smart regarding the "LOOSE METAL PART" mentioned above?

Steve Reiners building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03285 BREINERS areiners@ford.com fax 39-03285
*** Forwarding note from SCOLE1 --DREND05 02/16/99 18:04 ***
To: BREINERS--DREND07
cc: DGOSL --DREND05

0800Z (UTC -05:00)

THE PREVIOUS CONCERN OF THE "LOOSE METAL PART" WAS MENTIONED IN THE LAST MEETING WITH JACK. HE WILL WANT A FOLLOW UP ON THIS AT THIS FRIDAY'S MEETING. PLEASE GET UP TO SPEED ON THE HISTORY OF THIS CONCERN. IF IT TURNS OUT THAT THIS MAY BE A CAUSE, THEN WE WILL NEED TO KNOW WHEN THE ISSUE WAS IN THE FIELD, WHEN IT WAS FIXED AND HOW MANY ARE OUT THERE TO BE CONCERNED ABOUT. THANKS.

Thank You,
Ben

Ext. 21959

BLDG. 2, 22J31 - MD# 1220 - SCOLE1@FORD.COM

*** Forwarding note from BREIMERS--DRBN007 02/16/99 16:52 ***
To: SCOLE1 --DRBN005 DGOEL --DRBN005

FROM: Steve Reimers

USAST(UTC -05:00)

Subject: (U)

I have the part to show and a take-apart version too. I am not familiar with t

he previous problem but a loose metal part in the switch cavity is definitely a

potential cause of this concern.

Steve Reimers

building 5 3C043

AVT Chassis E/E System Applications

mail drop 5011

39-03286 BREIMERS breimers@ford.com

fax 39-03286

*** Forwarding note from DB7AWAYR--DRBN007 02/16/99 13:41 ***

Subject: AWAY Facility/VM messages

This note was generated by the AWAY Facility/VM 5799-FLP (c) IBM Corp.

DO NOT REPLY TO THIS NOTE

AWA1101 This mail item is being routed to you from SCOLE1 at DRBN005 on behalf of FPORTER at DRBN007.

To: FPORTER --DRBN007

cc: THASTERS--DRBN005

TDKNOVAN--DRBN005

DGOEL --DRBN005

From: Sam L. Cole

USAST(UTC -05:00)

Subject: (U)

I UNDERSTAND THAT THERE WILL BE A FOLLOW UP MEETING WITH JACK PASKUS THIS FRIDAY ON THE TOWN CAR INVESTIGATION. I MET WITH JACK TODAY FOR A 1 ON 1, AND HE REQUESTED SOME SPECIFIC INFO. AT FRIDAYS MEETING, PLEASE BRING A SAMPLE SWITCH TO SHOW JACK.

ALSO, HE IS INTERESTED IN KNOWING OUR PROGRESS AND INVESTIGATING IF THE PREVIOUS PROBLEM WITH THE INTERNAL COMPONENTS BREAKING LOOSE IS A POTENTIAL CAUSE OF THIS CONCERN. PLEASE BE PREPARED TO DISCUSS THIS ON FRIDAY. THANKS.

Thank You,

Sam

Ext. 21959

BLDG. 2, 22J31 - MD# 1220 - SCOLE1@FORD.COM

3713 7354

* Note printed by NLAPOINT on 4 Feb 1999 at 13:17:44 *

From: SLAROUCH--FORDMAIL Date and time 02/02/99 09:51:57
To: FPORTER --FORDMAIL Porter, Fred (F.J. NLAPOINT--FORDMAIL LaPointe, Norman (

From: LaRouche, Steve (S.)
Subject: Status of S/C Switches

Fred/Norm: The SEM portion of the work is pretty much complete. Pat has acquired all the spectra and is interpreting them. Copper and zinc were detected on the cup surfaces of the A, C, D, and F samples, which indicates transfer of oxide or corrosion product from the contacts to the cup. This suggests corrosion of the contacts as a common thread among the leaking and burned switches. The infrared work is in progress. We've given them alot of samples, so it is going to take them awhile to finish their analyses. Apparently, they can't take their sample until just before they analyse it and that has prevented me from routing these samples for further analyses. I asked them to give the seals priority so I can have Vlad in polymers look at them. I hope to have the seals later today.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room M410
(313) 845-4876 (313) 322-1614 FAX



Central Laboratory
16000 Century Drive
Dearborn, MI 48120-1257

January 15, 1999

Preliminary Findings:

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 360 brass, which is highly susceptible to SCC. 260

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the hex port and on the cup, converter, and disc appear to be compounds which may have formed from a reaction between decomposition products (acids) of the polyester base, the brake fluid, and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any mating parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragms.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (surfaces bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.

The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (tin plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus).

Steve LaRouche

MINI-FAX Transmittal		DATE 1/20/99	
TO Steve LaRouche		FROM STEVE LA ROUCHE	
SUBJECT P-1		REMARKS	
TELEPHONE		TELEPHONE	
FAX NO. 78256		FAX NO. 313 322 1514	
TIME 10:00			

** TOTAL PAGE 381 **

3713 7366

Conclusions:

Kepton seals are becoming brittle and cracked, forming leak path for brake fluid to enter switch.

Presence of elements of brass contact material on face of steel cup indicates transfer of contact material to cup. This suggests that a cell may be being formed between the contacts which are positive, and the cup which is ground. The brake fluid may be acting as the electrolyte.

The stationary contact in the Reddick switch exhibits corrosion and dezincification. Dezincification indicates presence of water in switch cavity. The contact also shows evidence of stress corrosion cracking (intergranular cracks), which is most often caused by exposure to ammonia, ammonia compounds, sulfur, or moisture.

$\epsilon = 0.75 A$ normal

TI test $135^{\circ}C$ 24 hr.

$0 \rightarrow 1400$ psi @ 500, ms $N_f = 1.6 \times 10^6$
@ 2 Hz ok leaks

N_f 900,094 @ 2 Hz

1.13×10^6
1.3
1.32
1.34
1.35
1.4
1.41

} leaks

3713 7368



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1257
FAX (313) 322-1614

Report 9804108

January 19, 1999

To: G. Stevens/N. LaPointe/S. LaRouche (313) 32-3888 07224 FAX
From: Gayle D. Gullen (313) 32-27322
Subject: Speed Control Cut-Off Switch
Part Number: F2VY-8F924-A
Source: Customer Vehicle
Received: One opened switch which had undergone a thermal event and one unused switch housing were received on January 4, 1999, from S. LaRouche. The switch was returned on January 11, 1999, after disassembly and preliminary examination by Texas Instruments.

Object: Determine if any fluid is present on the switch base in metallic-exposed area and compare the switch housing material to the unused material. Determine the nature of the black residue in the hexport and converter and determine the type of fluid in the diaphragm squares.

Conclusion: There was spectral evidence of a glycol ether (spectrally similar to Dow HD 50-4 brake fluid) and a metal soap on the metallic-exposed area of the switch cup. The customer base and unused base are spectrally similar and are composed of a polyester material. This is not the Noryl material which was specified. (Noryl is styrenated PPO (polyphenylene oxide)).

The exact nature and source of the noted metal soap could not be conclusively determined. Metal soaps can be utilized as polymeric compounding and/or mold release agents. Metal soaps are also utilized in greases (this glycol ether material does not match known carrier grease fluids) and may also be formed in the presence of acids and metal salts (both perhaps a reaction of the polymeric housing and metallic interference during the event).

The black residue in the hexport, converter, and washer are similar and are composed of a glycol based material (probably brake fluid) and a metal salt (probably an oxalate salt). The black residue on the spacer is composed of a metal salt (probably oxalate salt), and a glycol based fluid (probably brake fluid). The fluid removed from the #2 diaphragm was glycol based (probably brake fluid) and contained a metal salt (probably oxalate salt). The hexport deposit appears to contain ~10% water, however, this value may be artificially elevated due to reactions with the salts and other compounds in the deposit.

Decomposition of the polyester base causes acid formation, with one of these acids likely being oxalic acid. Reaction with the metals in the system forms oxalate salts. Based on this, it is highly unlikely that the oxalate salts were introduced into the system in this fashion but were likely formed during the thermal decomposition of the housing.

Data and Analysis:

Molecular Characterization

(FTIR, Qualitative, Microscopic)

Arrow B in Figure 2 points to area where analysis was performed). Spectra of the fluid noted on the metallic surface (chloroform micro casts - several areas) are characteristic of a glycol ether (spectrally similar to Dow HD 50-4 brake fluid) with evidence of an ester and metal soap.

Spectra of the new, brown base are characteristic of a polyester on the base of terephthalic acid.

Spectra of the blackened, customer base are similar to the new base and are characteristic of a polyester on the base of terephthalic acid.